

Popcorn Machine

Operating Instructions:

1. Turn all switches to the ON position
2. For the first batch only, let the kettle heat about 4 minutes prior to putting anything in the kettle. CAUTION: the kettle and all metal components attached are very hot. Avoid skin contact to prevent burns.
3. Add oil or oil bar, then popcorn.
4. Dump when popping is about 99% completed. Try to get all the popcorn and kernels prior to making a new batch of popcorn to avoid leftover burnt popcorn in the new batch.
5. Repeat steps 3 and 4. Always pop at least 5 batches each time you pop.
6. On the final batch, turn the kettle heat switch OFF as soon as the corn starts popping rapidly. Make sure to keep the kettle switch OFF when not popping.



Cleaning Instructions:

To avoid additional cleaning charges, make sure the unit is returned clean.

- When the unit is completely cooled down, unplug the kettle and remove it from the inside of the popcorn machine. Use a soapy scouring pad or SOS pad to clean the inside of the kettle. Wipe it out with a clean, wet washcloth. Repeat until clean.
- Do not immerse the kettle in water
- Remove all popcorn and unpopped kernels from the base of the popcorn machine. This can be done by removing the inside bottom tray of the machine.