CENTURY 21 Dream Home

CENTURY 21 7500 E Arapahoe Rd., Suite 345 Centennial, CO 80112

Bjorn Quaden

Ph: 720-261-1656 Fax: 303 957-5931

The printed portions of this form, except differentiated additions, have been approved by the Colorado Real Estate

Commission. (NTC43R-6-16) (Mandatory 1-17) 2 THIS FORM HAS IMPORTANT LEGAL CONSEQUENCES AND THE PARTIES SHOULD CONSULT LEGAL 3 AND TAX OR OTHER COUNSEL BEFORE SIGNING. 4 INSPECTION RESOLUTION 5 (Amendment To Contract To Buy And Sell Real Estate) 6 Date: 02/13/2025 7 8 This Inspection Resolution amends to the contract dated 2/1/2025 , between Sample Seller (Seller) and Sample Buyer (Buyer) relating to the sale and purchase of the Property known as: 11010 Highland Oaks PI Place, Colorado Springs, CO 80921 (Contract). 10 Terms used in this document have the same meaning as in the Contract. 11 **RESOLUTION OF UNSATISFACTORY PHYSICAL CONDITION.** Pursuant to the **Inspection** 12 **2.** Resolution provision in the Contract, Buyer and Seller agree that Seller, on or before 2 days prior to **Closing**, will do the following to resolve Buyer's Inspection Objection Notice: 1) Seller shall hire a licensed plumber to address the following items: a) install a pressure regulating valve and lower the water pressure to 50 psi (see page 20, item 17) b) repair the shower faucet handle (see page 68, item 20) c) install a TPR valve pipe and drain (see page 89, item 8) d) replace the galvanized main line (see page 94, item 2) 2) Seller shall hire a licensed electrician to address the following items: a) repair 220v dryer outlet (see page 40, item 11) b) label the electrical panel (see page 72, item 6) 3) Seller shall hire a licensed contractor to address the following items: a) install carbon monoxide detectors within 15 ft of each bedroom (see page 47, item 10) b) level the refrigerator c) install proper ventilation to both crawlspace areas (see pages 96 & 100, items 2 & 11) d) create positive drainage away from the foundation all around the home (see page 18, item 13) 4) Seller shall hire a licensed HVAC contractor to create sufficient combustion air supply and evaluate the orange flames/air fuel mixture issue (see pages 78 & 79, items 7 & 13). 5) Seller shall hire a licensed mold mitigation company to evaluate and treat the potential mold like substance in the crawlspace (see page 103, item 6). 6) Seller shall have the sewer line cleaned, rescoped, and make all recommended repairs (see sewer line inspection report/video).

7) Seller shall deliver to Buyer paid invoices/receipts for all completed work no later than 2

	days prior to Closing.
15	3. SELLER'S COST. Pursuant to the Damage , Liens and Indemnity provision in the Contract, correcting or resolving the unsatisfactory physical condition set forth in this document, will be paid by Seller.
16 17 18	4. SURVIVAL. If any agreed upon correction requires action after Closing, the obligations agreed upon survive Closing.
19	Note: This document amends the Contract. Buyer must provide a copy of this Inspection Resolution to Buyer's Lender.
20	
21	
	Date:
22	Buyer: Sample Buyer
23	
24	
25	Date:
	Seller: Sample Seller
26	
27	Seller: Date:

NTC43R-6-16. INSPECTION RESOLUTION

CTM eContracts - ©2025 MRI Software LLC - All Rights Reserved