



the standard in safety

Underwriters
Laboratories

File E107514

Vol 1

Issued: 1987-04-07

Revised: 2011-04-14

FOLLOW-UP SERVICE PROCEDURE
(TYPE L)

COMPONENT - WIRING HARNESSSES
(ZPFW2,ZPFW8)

Manufacturer: SEASON ELECTRIC LTD
(702238-001) B2 BLDG, A5 REGION
TONGFUYU INDUSTRIAL ESTATE, BUYONG
BAOAN, SHAJING
SHENZHEN
GUANGDONG 518104 CHINA

Applicant: HONG KONG HUNG SHANG ELECTRIC LTD
(870633-002) ROOM 108, 1ST FL
WELL FUNG INDUSTRIAL CTR
68 TA CHUEN PING ST
KWAI CHUNG, N T HONG KONG

Recognized Company: SAME AS APPLICANT
(870633-002)

This Procedure authorizes the above manufacturer to use the marking specified by Underwriters Laboratories Inc. (UL), or any authorized licensee of UL, only on products covered by this Procedure, in accordance with the applicable UL Services Agreement.

The prescribed Mark or Marking shall be used only at the above manufacturing location on such products which comply with this Procedure and any other applicable requirements.

The Procedure contains information for the use of the above named Manufacturer and representatives of Underwriters Laboratories Inc. and is not to be used for any other purpose. It is lent to the Manufacturer with the understanding that it is not to be copied, either wholly or in part, and that it will be returned to Underwriters Laboratories Inc. (UL) or any authorized licensee of UL, upon request.

This PROCEDURE, and any subsequent revision, is the property of Underwriters Laboratories Inc. (UL) and the authorized licensee of UL and is not transferable.

Underwriters Laboratories Inc.

Stephen Hewson
Senior Vice President
Global Follow-Up Service Operations

William R. Carney
Director
North American Certification Program



the standard in safety

Underwriters
Laboratories

MR. S C TAI
SEASON ELECTRIC LTD
B2 BLDG, A5 REGION
TONGFUYU INDUSTRIAL ESTATE, BUYONG
BAOAN, SHAJING
SHENZHEN
GUANGDONG 518104 CHINA

Date: 2011/04/15
Subscriber: 702238001
PartySite: 159409
File No: E107514
Project No: 11SR7571490
PD No: 11015016
Type: L
PO Number:

Subject: **Procedure And/Or Report Material**

The following material resulting from the investigation under the above numbers is enclosed.

Issue

<u>Date</u>	<u>Vol</u>	<u>Sec</u>	<u>Pages</u>	<u>Revised Date</u>
	1		Revised Authorization Page(s)	2011/04/14

NAFT:Address Change for App/Lis (Sub:870633-002) To All Files

Inspections at your plant will be conducted under the supervision of BILL ZHANG, UL INSPECTION CENTER SHENZHEN, CHINA NAT'L IMPORT & EXP COM INSP CORP, 10/F, ANLIAN BLDG, NO 4018 JINTIAN RD, FUTIAN DISTRICT, SHENZHEN, GUANGDONG, China, 518026., PHONE: 755-8828-6188, FAX: 755-8828-6100, EMAIL: bill.zhang@cccicshenzhen.com.cn

Please file revised pages and illustrations in place of material of like identity. New material should be filed in its proper numerical order.

NOTE: Follow-Up Service Procedure revisions DO NOT include Cover Pages, Test Records and Conclusion Pages. Report revisions DO NOT include Authorization Pages, Indices, Section General Pages and Appendixes.

Please review this material and report any inaccuracies to UL's Customer Service Professionals. Contact information for all of UL's global offices can be found at <http://www.ul.com/global/eng/pages/corporate/contactus>.

If you'd like to receive updated materials FASTER, UL offers electronic access and/or delivery of this material. For more details, contact UL's Customer Service Professionals as shown above.

This material is provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL.

CAM File

UL INSPECTION CENTER 750