



HH7

Installation method		Application	
Floor	●	Spot welding	
Ceiling		Arc welding	
Wall surface		Handling	●
		Assembly	●
		Sealing	●
		Painting	




View A: Detailed drawing of the wrist attachment part




View B: Dimensional drawing for the floor installation of the body

View G: Application part mounting




View C: Application cable connection part




※Precaution:When installing robot, please apply positioning pins.(2xØ6)


View D: Application cable connection part



View E: Application part mounting detail



Wrist-axis torque line diagram



** For product improvement, some of the ratings, specifications, dimensions, etc. are subject to changes without notice.