

FIZZ DISPENSE PURITY DEFINITIONS



Purity Definitions

Nitrogen Content	Oxygen Content + N₂ & Ar
95%	5%
98%	2%
99%	1%
99.5%	0.5%
99.9%	0.1%
99.95%	500ppm
99.975	250ppm
99.99%	100ppm
99.995%	50ppm
99.999	10ppm
99.9995	5ppm