


CONNECTION DIAGRAM FOR TACHOMETER CUM MECH. HOUR METER (0-4000RPM)

WITH DIP SWITCH ARRANGEMENT



a. FOR TACHOMETER WHEN SIGNAL IS TAKEN FROM IGNITION COIL:-

DIP SWITCH
1
2
3
ON OFF

DIP SWITCH POSITION
1
2
3
4
6
8

CALIBRATION TABLE			
RPM	4 CYLINDER	6 CYLINDER	8 CYLINDER
1000	33	50	66
2000	66	100	132
3000	99	150	198
4000	132	200	264

b. FOR TACHOMETER IF SIGNAL IS TAKEN FROM ALTERNATOR (PULSES PER REVOLUTION)

DIP SWITCH
1
2
3
ON OFF

DIP SWITCH POSITION
1
2
3
8
12
16