

Machine	Process or Machine Type	Machine Description	Spindles	RPM	X-Axis	Y-Axis	Z-Axis
SN001	Mill, 5-Axis - CNC	Cincinnati 2 Spindle Bridge	2	5000	168	60	24
SN002	Mill, 5-Axis - CNC	Cincinnati 20v (Big Blue)	1	3600	121	30	24
SN003	Mill, 5-Axis - CNC	Cincinnati 20v (950)	1	4000	121	32	24
SN004	Mill, 5-Axis - CNC	Cincinnati 30v Gantry Mill	1	3600	468	68	14
SN006	Mill, 5-Axis - CNC	Cincinnati Bridge Mill	1	10000	168	84	19
SN007	Mill, 5-Axis - CNC	Cincinnati Gantry Mill	1	10000	336	84	24
SN008	Mill, 5-Axis - CNC	Cincinnati Bridge Mill	1	10000	144	84	19
SN018	Mill, 5-Axis - CNC	Cincinnati Bridge Mill	1	10000	144	84	19
SN009	Mill, 5-Axis - CNC	Cincinnati 3 Spindle Gantry	3	10000	864	104	24
SN010	Mill, 5-Axis - CNC	Cincinnati 3 Spindle Gantry	3	10000	864	104	24
SN015	Mill, 5-Axis - CNC	Cincinnati 3 Spindle Gantry	3	10000	118	84	24
SN016	Mill, 5-Axis - CNC	Cincinnati 3 Spindle Gantry	3	10000	118	84	24
SN020	Mill, 5-Axis - CNC	Cincinnati 3 Spindle Gantry	3	10000	60	164	24
SN011	Mill, 5-Axis - CNC	Cincinnati Lancer V5	1	15000	80	30	30
SN012	Mill, 5-Axis - CNC	Cincinnati Lancer V5	1	15000	80	30	30
SN019	Mill, 5-Axis - CNC	Cincinnati Lancer V5	1	15000	80	30	30
SN005	Mill, 3-Axis - CNC	Cincinnati 20v	1	4000	80	30	24
SN017	Mill, 3-Axis - CNC	Cincinnati 3 Axis Lancer	1	6000	60	30	24
SN014	Mill, 3-Axis - CNC	Cincinnati 3 Axis Lancer	1	6000	80	30	24
SN021	Mill, 5-Axis - CNC	Cincinnati 5 Axis Gantry	3	10000	156	124	24

SN022	Mill, 5-Axis - CNC	Cincinnati 5 Axis Hyper Mach	1	18000	840	137.9	29.5
SN023	Mill, 5-Axis - CNC	Cincinnati H5 5 Axis Horiz.	1	24000	72.8	57.1	60
SN024	Mill, 5-Axis - CNC	Cincinnati H5 5 Axis Horiz.	1	24000	72.8	57.1	60
SN025	Mill, 5-Axis - CNC	Cincinnati 3 Spindle Gantry	3	10000	156	124	24
SN026	Mill, 5 Axis - CNC	Cincinnati 5 Axis Hyper Mach	2	18000	636	96	29.5
SN027	Mill, 5 Axis - CNC	Cincinnati 4 Spindle Gantry	4	10000	124	124	24
SN028	Mill, 5 Axis - CNC	Cincinnati 5 Axis Hyper Mach	2	18000	636	96	29.5
SN029	Mill, 5 Axis - CNC	Cincinnati H4000 5 Axis Horizontal	1	30000	158	79	0
SN030	Mill, 5 Axis - CNC	Cincinnati H4000 5 Axis Horizontal	1	30000	158	79	0
SN031	Mill, 5 Axis - CNC	Makino MAG3-EX 5 Axis Horizontal (Makino, MAG3-EX)	1	33000	157.5	59.1	39.4
SN032	Mill, 5 Axis - CNC	Makino MAG3-EX 5 Axis Horizontal (Makino, MAG3-EX)	1	33000	157.5	59.1	39.4
SN033	Mill, 5 Axis - CNC	Zimmermann FZH 400 (Zimmermann, FZH 400)	1	30000	161	61	25
SN034	Mill, 5 Axis - CNC	Zimmermann FZH 400 (Zimmermann, FZH 400)	1	30000	161	61	25

SN035	Mill, 5 Axis - CNC	Makino MAG3-EX 5 Axis Horizontal (Makino, MAG3-EX)	1	33000	157.5	59.1	39.4
SN036	Mill, 5 Axis - CNC	Makino MAG3-EX 5 Axis Horizontal (Makino, MAG3-EX)	1	33000	157.5	59.1	39.4
SN111	Mill, 5 Axis - CNC	3 Spindle Gantry (40 in.) Vertical (Cincinnati)	3	10000	1920	104	28
SN112	Mill, 5 Axis - CNC	3 Spindle Gantry (40 in.) Vertical (Cincinnati)	3	10000	192	104	28
SN113	Mill, 5 Axis - CNC	3 Spindle Gantry (40 in.) Vertical (Cincinnati)	3	3600	816	82	18
SN114	Mill, 5 Axis - CNC	3 Spindle Gantry (40 in.) Vertical (Cincinnati)	3	3600	816	82	18
SN115	Mill, 5 Axis - CNC	3 Spindle Gantry (40 in.) Vertical (Cincinnati)	3	3600	816	82	18
SN116	Mill, 5 Axis - CNC	3 Spindle Gantry (40 in.) Vertical (Cincinnati)	3	3600	816	82	18
SN117	Mill, 5 Axis - CNC	3 Spindle Gantry (40 in.) Vertical (SNK)	3	4000	713	84	28

SN118	Mill, 5 Axis - CNC	3 Spindle Gantry (40 in.) Vertical (Cincinnati)	3	10000	816	82	18
SN119	Mill, 3 Axis - CNC	Single Spindle Vertical (Mori Seiki)	1	4000	50	25	25
SN120	Mill, 5 Axis - CNC	Ecospeed F1540 AB Axis Horizontal (Starrag)	1	30000	169.3	63	14.6
SN121	Mill, 5 Axis - CNC	Ecospeed F1540 AB Axis Horizontal (Starrag)	1	30000	169.3	63	14.6