Proposabid.com



Apartamento De La Esperanza

SB721 Estimations for Inspection RFP

Project Overview

Note:

- <u>Estimates/Bids are to be sent to RoDevia Brigham RoDevia@proposabid.com</u>
- Estimates/Bids are for inspection costs only not for Repairs
- Vendors will be notified by property on moving forward with inspections.

This project involves the assessment of balconies, walkways, and landings at Apartamento De La Esperanza, a condo complex located at 3590 19th Street, San Francisco, CA 94110. The property consists of 39 units spread across 4 stories, with a focus on providing affordable housing for seniors.

Important Consideration for Vendors:

If no repairs are needed, Property is requesting an included detailed explanation of why SB721 does not apply to the scope of this property.

The law primarily focuses on wood-based structures and does not explicitly mention concrete. However, it applies to all buildings with three or more multifamily dwelling units. Local jurisdictions may interpret and enforce the law based on their assessment of potential safety risks.

While concrete structures are generally more durable and less prone to weathering compared to wood, they can still deteriorate over time due to factors such as poor construction, water infiltration, or corrosion of reinforcing steel. Therefore, some local jurisdictions may choose to include concrete Exterior Elevated Elements (EEEs) in their SB721 inspection requirements.

To get a definitive answer for this specific case, vendors are requested to advise the property at Cost and consult with the local building department or a qualified professional familiar with SB721 requirements and their application in this area.

Objectives for Apartamento De La Esperanza Inspection

Ensure Structural Safety:

• Give 100% and 50% estimates that will include conducting thorough inspections of balconies, walkways, and landings to identify any potential structural issues or maintenance needs, ensuring the safety of all residents.

Compliance with Regulations:

• Verify that all structures meet ADA standards and local building codes, particularly concerning SB721 requirements for multifamily dwellings.

Identify Repair Needs:

- Provide a detailed report highlighting areas that require repair or maintenance, focusing on both immediate and long-term safety concerns.
- If no repairs are needed, include a detailed explanation of why SB721 does not apply to the scope of this property.

Maintain Property Value:

• Ensure the longevity and durability of the property's structures through proactive inspections and maintenance recommendations, thereby maintaining and potentially increasing the property value.

Inspection Timeline

• Project Start Date: ASAP

• **Project End Date:** July 31, 2024 (Based on Vendor Availability)

Project Team

Proposabid - Primary Contact: RoDevia Brigham

• Phone: +1 (408) 353-2769

• Email: (rodevia@proposabid.com)

Portfolio Manager: Richelle Page

• Phone: +1 (415) 795-0971

• Email: (rodevia@proposabid.com)

For Scheduling Onsite Visit - Community Director: Matthew Cantor

• Phone: +1 (415) 795-0971

• Email: (rodevia@proposabid.com)

Property Details

• **Property Name:** Apartamento De La Esperanza

• **Property Address:** 3590 19th Street, San Francisco, CA 94110

Building Type: Condo
Year Built: 1975
Number of Units: 39
Number of Stories: 4

• Number of Units with Open Decks: 1

• Number of Closed Balconies: 27

Number of Walkways: 4 (each 150 feet)
 Number of Landings: 6 (each 10 feet)
 Access Codes to Property: 4448

• **Gate Code:** 4448

• Asbestos Materials: Yes

• Special Conditions: ADA-compliant walkways for easy traversal

Project Scope

The scope of this project includes:

1. Inspection of Balconies:

- Assess the condition of 27 closed balconies with closed joists.
- Identify any necessary repairs or maintenance needs.

2. Inspection of Walkways:

- Assess the condition of 4 walkways, each 150 feet long.
- Ensure 3 of the walkways covered underneath are structurally sound.

3. Inspection of Landings:

• Assess the condition of 6 landings, each 10 feet long, and covered underneath.

4. Inspection of Entry Structures:

• Evaluate the single entry structure covered underneath for any potential repairs.

5. Compliance Check:

• Ensure all structures are compliant with ADA standards for senior housing.

6. Reporting:

o Provide a detailed report of findings and recommendations for repairs.

Budget

• Total Budget: Based on Vendor Recommendation

Warranty

• Inspection Warranty: Based on Vendor Recommendation

Project Deliverables

- Detailed inspection report for balconies, walkways, and landings.
- Recommendations for repairs or maintenance.
- Compliance certification for ADA standards.

Access for Property Site Visit

• Access Codes to Property: 4448

• **Gate Code:** 4448

• Contact for Access:

o Matthew Cantor

o Phone: +1 (415) 626-5513

Assumptions

- Access to all areas will be granted as needed.
- No significant structural changes are required beyond repair and maintenance.
- No unforeseen hazardous materials, beyond known asbestos, will be encountered.

Constraints

- All work must be performed with minimal disruption to residents.
- Compliance with ADA standards must be maintained at all times.
- Any asbestos found must be handled according to local and federal regulations.

















