

GREENSHIELDS JCB

SS0810P Page 1 of 1

> Service Direct Cash Sales Braintree Depot

Site Address: Soco Tec Low Street Brickworks Station Road East Tilbury RM18 5QR

Supplying Depot

Farnham GU10 4LG Tel 01420 525917 Fax

Invoice 4913991 Date 15/09/20 Order No

Job No 7451329 Job Code 51 RF

Date Completed 2/09/20

Parts Issue No

Model WARRANTY

Serial No U0242718

CASH CUSTOMER

Fleet No

Reg No

Hours

Customer Instructions

Fault reading SCR inducement. DEF system

Account 980008 104

Work Carried Out

Complaint of machine displaying scr inducement. Found machine to randomly cut out. it is purely a JCB engine fitted & all other components are made by the machine manufacturer. When the machine cuts out p1509 is displayed. Linked to throttle sensor with a can error, & then followed up by u010e-08 & u010e-87. Tested both the ecm & dcu. giving readings indicating connections & both online. Removed & inspected both ecm plugs & dcu plug all ok all dry & no issues found. Tested lives & earths all ok. Tested fuel delivery, approx. 1.3 litres delivered. Unable to trace errors further back due to there being no throttle on the unit. Engine was also run up to temp & scr regen attempted. Unable to do so. Customer liaised with equipment manufacturer. They are expecting phone call back from them, but no time scale could be given. As over allocated time, customer agreed that we should leave site until more information can be supplied

Invoice Summary

	Amount	VAT Code
Labour	515.12	S
Mileage	130.50	S
Parts	.00	
Other	.00	
Environmental Charge	.00	
Sublet	.00	
Goods Total	645.62	
Vat Total 20.00%	129.12	
Invoice Total	774.74	

ANY QUERIES RELATING TO THIS INVOICE MUST BE SUBMITTED WITHIN SEVEN DAYS FROM THE DATE OF THE INVOICE.