



SOCOTEC

Plant Service Record

Dil Serv V

Date: 26.11.2024	Fitter's name: DOM	
Plant Item: DANON 3000	Plant no.: CT-53	
Hour reading: 439		
Description of work carried out	Time taken (hours)	Initials
MAIN WINCH DRUM REPLACEMENT + RETHREADED HOUSING		DT
RE-END ROPE WITH NEW CLAMPS		DT
FABRICATE SPACERS - CLUTCH SIDE X2		
- CHAIN WHEEL SIDE		DT
INSPECT BRAKE CABLES AND REPLACE IT		DT
INSTALL NEW SET-UP ROPE		DT + DT
FABRICATE CHAIN GREASING FLAP		DT
INSTALL NEW FUEL FILTER HOUSING		DT
OIL-SERVICE ENGINE + GB FLUSH		DT
INSTALL NEW STARTER MOTOR		DT
INSTALL NEW BATTERY		DT
INSTALL NEW FUEL FILTER HOUSING		DT
INSTALL NEW R/C + PLUGS		DT
Parts/materials used		Quantity
R/C for SET-UP		1
SET-UP - ROPE W 24600		1
HALFORDS BATT HCB 018		1
OIL FILTER P554770 + FUEL FILTER 550498		1 + 1
AIR FILTER HiFi 6001		
15W-40 Engine Oil		6.5 L
80W90 GEARBOX OIL		2L
FUEL FILTER HOUSING		
Fitter's comments:		
HAVE TO FABRICATE SPACER BETWEEN CLUTCH BOSS AND SLIDING MEMBER TO ELIMINATE CLUTCH PLAY INSIDE DRUM. (STOP MOVEMENT OF CLUTCH BOSS)		
ADD EXTENSIONS TO BRAKE HOLDER CABLE HOLDERS TO KEEP CABLES STRAIGHT		
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> MAIN DRUM No 3DA-BLX-53 </div>		
Fitter's Signature (work complete)	29-11-2024	