

Plant Service Record



Date: 22-X-2021		Fitter's name: JAM	
Plant Item: DANDY 3000		Plant no.: CT-62	
Hour reading: N/A			
Description of work carried out	Time taken (hours)	Initials	
REPLACE CLUTCH ACTUATOR CABLE	8	J	
Parts/materials used	Quantity		
CLUTCH ACTUATOR CABLE	1		
<p>Fitter's comments: BRAKE DOWN IN <u>ST5 OUK</u> HAD TO REMOVE CLUTCH SIDE PILLAR BEARING AND AND RISEUP DRUM.</p>			
Fitter's Signature (work complete)			