

④ R72 T3130

CUSTOMER ORDER No.

FIELD SERVICE REPORT



109910
£ 762.70

DATE-DAY 19 MONTH 04 YEAR 2022	CUSTOMER: Socotec
SERIAL No. 3145 PLANT No. Geo 405.	SITE ADDRESS: Socotec central CV3 2TF
HOURS ENGINE 1611	
HOURS AIR N/A	
DRILL APPEARANCE V. good	
DID PROBLEM MAKE RIG INOPERABLE? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	

SPARES USED ON MACHINE

QTY:	PART No.	DESCRIPTION	TIME ARRIVED ON SITE: 8:30		MILEAGE:	
			SERVICEMAN'S NAME(s)	HOURS WORKED	OUT	RETURN
1	3-3241.02	24V circuit board	J. BANNISTER	4	75	75
1	7-6801.00	Swivel shaft				
1	2-2190.02	Swivel Seal kit				
1	2-2290.02	Swivel Bearing kit				
TOTAL						
TOTAL MILEAGE						
TRAVELLING TIME					1.5 Hrs	1.5 Hrs
TIME LEFT SITE			12:30			
SERVICEMAN'S HOME TELEPHONE No.			07802766112			
CAR REG No.			BN21FK5			

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

Remove swivel from rig strip down and replace shaft, seals and bearings.

Replaced swivel back to rig and test swivel all okay.

Test remote found fault with main circuit board removed and replaced. Tested all okay.

Tested gear change with drive strong all okay no fault found.

New key is in remote control bag. Swivel bar needs welding and re connecting back to rig.

SERVICEMAN'S SIGNATURE

CUSTOMER'S SIGNATURE