

FIELD SERVICE REPORT

CUSTOMER ORDER No.

R75

Wrenfy

*108658
£221.50*



DATE-DAY <i>2</i> MONTH <i>11</i> YEAR <i>2021</i>	CUSTOMER: <i>Soco tee</i>
SERIAL No. <i>3800</i> PLANT No. <i>Geo 305</i>	SITE ADDRESS: <i>Stafford Show Ground ST18 0BD</i>
HOURS ENGINE <i>SGS.</i>	
HOURS AIR <i>N/A</i>	
DRILL APPEARANCE <i>V. good</i>	
DID PROBLEM MAKE RIG INOPERABLE? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	

SPARES USED ON MACHINE

QTY:	PART No.	DESCRIPTION
<i>(Large diagonal line through the table)</i>		

TIME ARRIVED ON SITE: <i>11:30</i>	MILEAGE:		
SERVICEMAN'S NAME(s)	HOURS WORKED	OUT	RETURN
<i>[Redacted]</i>	<i>1</i>	<i>80</i>	<i>80</i>
TOTAL			
TOTAL MILEAGE			
TRAVELLING TIME		<i>1.5 Hrs</i>	<i>1.5 Hrs</i>
TIME LEFT SITE		<i>12:20</i>	
SERVICEMAN'S HOME TELEPHONE No.	<i>[Redacted]</i>		
CAR REG No.	<i>[Redacted]</i>		

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

Remove shims out of water swivel to stop leak.

Set rig up in regeneration.

SERVICEMAN'S SIGNATURE

J.D.

CUSTOMER'S SIGNATURE

[Handwritten Signature]