

FIELD SERVICE REPORT

R70 + fine
Rig
12051.
CUSTOMER ORDER NO. 101507



UK LIMITED

DATE-DAY	17	MONTH	12	YEAR	19
SERIAL No	2979/3389	PLANT No.	Geo 205 / Geo 205		
HOURS ENGINE	1111	/ 352			
HOURS AIR					
DRILL APPEARANCE	Good.				
DID PROBLEM MAKE RIG INOPERABLE?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>				
SPARES USED ON MACHINE					
QTY.	1	PART No.	7-2602.047	Module.	
DESCRIPTION					
TIME ARRIVED ON SITE: 09:20					
MILEAGE:					
HOURS WORKED		1.5		RETURN	
MILEAGE:		322		321	
TOTAL					
TOTAL MILEAGE		643			
TRAVELLING TIME		6.25 Hrs		5.45 Hrs	
TIME LEFT SITE		11:00 AM			
SERVICEMAN'S HOME TELEPHONE No.					
CAR REG No.					

SERVICEMAN'S NAME(S)		[REDACTED]		RETURN	
HOURS WORKED		1.5		322	
MILEAGE:		321		321	
TOTAL					
TOTAL MILEAGE		643			
TRAVELLING TIME		6.25 Hrs		5.45 Hrs	
TIME LEFT SITE		11:00 AM			
SERVICEMAN'S HOME TELEPHONE No.					
CAR REG No.					

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

Geo 205 3389 (rig services)

Reports of drill, ~~setup and bench~~ not working. Green light would not work. Arrived on site everything working ok! Tested machine & left rig drilling for 1 hour. All ok!

Geo 205 2979 (Socket)

All lights enabling for rotation but rig has no rotation. Checked the fuses, found one blown fuse (10AMP) changed fuse everything working ok!

CUSTOMER'S SIGNATURE

SERVICEMAN'S SIGNATURE