

Specifications & Accesories

	WATER LEVEL METER WM-30	WATER LEVEL METER WM-50	WATER LEVEL METER WM-100
Weight	1036 gm	1112 gm	1279 gm
Dimensions	208mm X95mm X95mm	213mm X95mm X95mm	250mm X95mm X95mm
Measuring tape lengths	30 feet	50 feet	100 feet
Colour coded wire	×	×	×
Power Supply	2 x 9 Volt Batteries	2 x 9 Volt Batteries	2 x 9 Volt Batteries
Measuring tape	Flex Silicone with copper	Flex Silicone with copper	Flex Silicone with copper
Measuring Accuracy	1/8 Inch	1/8 Inch	1/8 Inch
Marked Measurements	Marked per foot	Marked per foot	Marked per foot
Probe Dimensions (LxWXH)	20mm x 20mm x 70mm	20mm x 20mm x 70mm	20mm x 20mm x 70mm
On/Off button	✓	✓	✓
3 LED Visual Indicators	✓	✓	✓
Drill Attachment (nut driver)	✓	✓	✓
Wingnut Handle Replacement	✓	✓	✓
Batteries Included	✓	✓	✓
Magnetic Base	80 lb Holding Capacity	80 lb Holding Capacity	80 lb Holding Capacity
Waterproof	✓	✓	✓
Operating Temperature	-18°C to 55°C (0°F to 130°F)	-18°C to 55°C (0°F to 130°F)	-18°C to 55°C (0°F to 130°F)

Power Supply:

2 x 9 Volt Batteries (included)

Measuring Cacle/Wire:

Flex Silicone with Copper

Button:

On/ Off Button

Visual Indicators:

3 LED's

Magnetic Base:

80 lb Holding Capacity

Operating Envirnoment:

Rated for outdoor use and is Water-proof

Battery Life:

20 hours continuously detecting

1 year on, but not detecting

Operating Tempurature:

-18°C to 55°C (0°F to 130°F)

[can be used periodically at lower temperatures, if stored in warmer environment when not in use]

Response time:

<100 milliseconds

Accesories:

Carry Bag

Drill attachment (nut driver)

Wignut (handle replacement when using drill)

