

OWNER: GOLDENEYE LLC		OPERATOR: GOLDENEYE LLC		
ADDRESS: 422 BEECHER ROAD GAHANNA COLUMBUS OH 43230		ADDRESS: 422 BEECHER ROAD GAHANNA COLUMBUS OH 43230		
OFFICE:		OFFICE:		
FAX:		FAX:		
ANALYST: PATRICK VITAMVAS		+1-316-462-2484 (DIRECT)	800-787-9749 (EFAX-CARDS)	PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).
EMAIL: PVITAMVAS@CAMPSYSTEMS.COM		+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)	
		WWW.CAMPSYSTEMS.COM		

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL/REGNO: 60 320/N328AJ	MODEL: LEARJET 60XR	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 22-AUG-2007		LAST ACTUALS:	
		1385 A/C HRS	as of 13-FEB-2025
		1094 AFL	as of 13-FEB-2025
		989.2 APH	as of 16-OCT-2024
		1849 ACH	as of 16-OCT-2024

APU	SERIAL/PART: SP-E060440/4503134	MODEL: T-20G-10C3A (CIMMS)	MANUFACTURER: HAMILTON SUNDSTRAND CORPORATION
INSTALLED ON: 17-AUG-2007		LAST ACTUALS:	
7.5 APU HRS	0 A/C HRS	989.2 APU HRS	as of 16-OCT-2024
98 APUS		1935 APUS	as of 02-OCT-2024

ENGINE NO. 1	SERIAL/PART: PCE-CA0499/31B4067-04	MODEL: PW305A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 10-NOV-2006		LAST ACTUALS:	
0 ENG. HRS	0 A/C HRS	1385 ENG. HRS	as of 13-FEB-2025
0 ENC		1094 ENC	as of 13-FEB-2025

ENGINE NO. 2	SERIAL/PART: PCE-CA0498/31B4067-04	MODEL: PW305A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 11-NOV-2006		LAST ACTUALS:	
0 ENG. HRS	0 A/C HRS	1385 ENG. HRS	as of 13-FEB-2025
0 ENC		1094 ENC	as of 13-FEB-2025

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
CI60-161006	REVIEW LEARJET 60 AMM REVISION A15							Service ATA:00
	MOS/MSC	21-Oct-16	-					REQUIREMENT CHANGE FORMS
	HRS	733.8						
	AFL	566						
PROC. REF: RCF CI60PROC. REF: RCF CI60								
CI60-161011	REVIEW LEARJET 60 EINSPECTOR REVISION 2016.10.11							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI60PROC. REF: RCF CI60								
EC24-151014-1	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 63.0 DATED NOV 24/2014 - CAMP CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-151014-1	NO. 2 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 63.0 DATED NOV 24/2014 - CAMP CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-151014-2	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 64.0 DATED JUN 15/2015 - CAMP CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EC24-151014-2	NO. 2 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 64.0 DATED JUN 15/2015 - CAMP CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-151014-3	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 65.0 DATED JUL 20/2015 - CAMP CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-151014-3	NO. 2 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 65.0 DATED JUL 20/2015 - CAMP CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-160115	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL REV NO. 65.1 DATED DEC 9/2015							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-160115	NO. 2 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL REV NO. 65.1 DATED DEC 9/2015							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EC24-160516	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-160516	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-161024 ^S	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 67.0							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-161024 ^S	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 67.0							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-161220 ^S	NO. 1 ENGINE - REVIEW PW305/305A305B MM REV 67.1							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EC24-161220	^S	NO. 2 ENGINE - REVIEW PW305/305A305B MM REV 67.1						Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-170116		NO. 1 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2						Service ATA:00
	MOS/MSC	20-Feb-17	-					REQUIREMENT CHANGE FORMS
	HRS	734.6						
	ENC	567						
EC24-170116		NO. 2 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2						Service ATA:00
	MOS/MSC	20-Feb-17	-					REQUIREMENT CHANGE FORMS
	HRS	734.6						
	ENC	567						
EC24-180214		NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
EC24-180214		NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC24PROC. REF: RCF EC24								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-A1		PHASE A1-300 HOUR						Package ATA:05
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
	HRS	1375.9	300 (+25/-25)		1675.9	1700.9	290.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-01PROC. REF: AMM 5-10-01								PKG:1
05-10-02-A2	PHASE A2-300 HOUR							Package ATA:05
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	
	HRS	1375.9	300 (+25/-25)		1675.9	1700.9	290.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-02PROC. REF: AMM 5-10-02								PKG:2
05-10-03-A3	PHASE A3-300 HOUR							Package ATA:05
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	
	HRS	1375.9	300 (+25/-25)		1675.9	1700.9	290.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-03PROC. REF: AMM 5-10-03								PKG:3
05-10-04-A4	PHASE A4-300 HOUR							Package ATA:05
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	
	HRS	1375.9	300 (+25/-25)		1675.9	1700.9	290.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-04PROC. REF: AMM 5-10-04								PKG:4
05-10-05-A5	PHASE A5-300 HOUR							Package ATA:05
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	
	HRS	1375.9	300 (+25/-25)		1675.9	1700.9	290.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-05PROC. REF: AMM 5-10-05								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-06-A6	PHASE A6-300 HOUR							Package ATA:05
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	
	HRS	1375.9	300 (+25/-25)		1675.9	1700.9	290.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-06PROC. REF: AMM 5-10-06								PKG:6
05-10-07-B1	PHASE B1-600 HOUR							Package ATA:05
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS	1375.9	600 (+25/-25)		1975.9	2000.9	590.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-07PROC. REF: AMM 5-10-07								PKG:7
05-10-08-B2	PHASE B2-600 HOUR							Package ATA:05
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS	1375.9	600 (+25/-25)		1975.9	2000.9	590.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-08PROC. REF: AMM 5-10-08								PKG:8
05-10-09-B3	PHASE B3-600 HOUR							Package ATA:05
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS	1375.9	600 (+25/-25)		1975.9	2000.9	590.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-09PROC. REF: AMM 5-10-09								PKG:9
05-10-10-B4	PHASE B4-600 HOUR							Package ATA:05
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS	1375.9	600 (+25/-25)		1975.9	2000.9	590.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-10PROC. REF: AMM 5-10-10								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-11-B5	PHASE B5-600 HOUR							Package ATA:05
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS	1375.9	600 (+25/-25)		1975.9	2000.9	590.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-11PROC. REF: AMM 5-10-11								PKG:11
05-10-12-B6	PHASE B6-600 HOUR							Package ATA:05
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS	1375.9	600 (+25/-25)		1975.9	2000.9	590.9 (+25)	
	AFL	1084						
PROC. REF: AMM 5-10-12PROC. REF: AMM 5-10-12								PKG:12
05-10-13-C1	PHASE C1-1200 HOUR							Package ATA:05
	MOS	07-Oct-23	48 (+14d/-14d)	Adj 7d	14-Oct-27	28-Oct-27	953 d (+14)	
	HRS	1309.3	1200 (+25/-25)		2509.3	2534.3	1124.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-13PROC. REF: AMM 5-10-13								PKG:13
05-10-14-C2	PHASE C2-1200 HOUR							Package ATA:05
	MOS	07-Oct-23	48 (+14d/-14d)	Adj 7d	14-Oct-27	28-Oct-27	953 d (+14)	
	HRS	1309.3	1200 (+25/-25)		2509.3	2534.3	1124.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-14PROC. REF: AMM 5-10-14								PKG:14
05-10-15-C3	PHASE C3-1200 HOUR							Package ATA:05
	MOS	07-Oct-23	48 (+14d/-14d)	Adj 7d	14-Oct-27	28-Oct-27	953 d (+14)	
	HRS	1309.3	1200 (+25/-25)		2509.3	2534.3	1124.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-15PROC. REF: AMM 5-10-15								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-16-C4	PHASE C4-1200 HOUR							Package ATA:05
	MOS	07-Oct-23	48 (+14d/-14d)	Adj 7d	14-Oct-27	28-Oct-27	953 d (+14)	
	HRS	1309.3	1200 (+25/-25)		2509.3	2534.3	1124.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-16PROC. REF: AMM 5-10-16								PKG:16
05-10-17-C5	PHASE C5-1200 HOUR							Package ATA:05
	MOS	07-Oct-23	48 (+14d/-14d)	Adj 7d	14-Oct-27	28-Oct-27	953 d (+14)	
	HRS	1309.3	1200 (+25/-25)		2509.3	2534.3	1124.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-17PROC. REF: AMM 5-10-17								PKG:17
05-10-18-C6	PHASE C6-1200 HOUR							Package ATA:05
	MOS	07-Oct-23	48 (+14d/-14d)	Adj 7d	14-Oct-27	28-Oct-27	953 d (+14)	
	HRS	1309.3	1200 (+25/-25)		2509.3	2534.3	1124.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-18PROC. REF: AMM 5-10-18								PKG:18
05-10-19-D1	PHASE D1-2400 HOUR							Package ATA:05
	MOS	07-Oct-23	96 (+14d/-14d)	Adj -45d	23-Aug-31	06-Sep-31	2362 d (+14)	
	HRS	1309.3	2400 (+25/-25)		3709.3	3734.3	2324.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-19PROC. REF: AMM 5-10-19								PKG:19
05-10-20-D2	PHASE D2-2400 HOUR							Package ATA:05
	MOS	07-Oct-23	96 (+14d/-14d)	Adj -45d	23-Aug-31	06-Sep-31	2362 d (+14)	
	HRS	1309.3	2400 (+25/-25)		3709.3	3734.3	2324.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-20PROC. REF: AMM 5-10-20								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-21-D3	PHASE D3-2400 HOUR							Package ATA:05
	MOS	07-Oct-23	96 (+14d/-14d)	Adj -45d	23-Aug-31	06-Sep-31	2362 d (+14)	
	HRS	1309.3	2400 (+25/-25)		3709.3	3734.3	2324.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-21PROC. REF: AMM 5-10-21								PKG:21
05-10-22-D4	PHASE D4-2400 HOUR							Package ATA:05
	MOS	07-Oct-23	96 (+14d/-14d)	Adj -45d	23-Aug-31	06-Sep-31	2362 d (+14)	
	HRS	1309.3	2400 (+25/-25)		3709.3	3734.3	2324.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-22PROC. REF: AMM 5-10-22								PKG:22
05-10-23-D5	PHASE D5-2400 HOUR							Package ATA:05
	MOS	07-Oct-23	96 (+14d/-14d)	Adj -45d	23-Aug-31	06-Sep-31	2362 d (+14)	
	HRS	1309.3	2400 (+25/-25)		3709.3	3734.3	2324.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-23PROC. REF: AMM 5-10-23								PKG:23
05-10-24-D6	PHASE D6 2400 HOUR							Package ATA:05
	MOS	07-Oct-23	96 (+14d/-14d)	Adj -45d	23-Aug-31	06-Sep-31	2362 d (+14)	
	HRS	1309.3	2400 (+25/-25)		3709.3	3734.3	2324.3 (+25)	
	AFL	1026						
PROC. REF: AMM 5-10-24PROC. REF: AMM 5-10-24								PKG:24
05-10-25-3000 LDG	3000 LANDING							Package ATA:05
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)		3000	3025	1906 (+25)	
PROC. REF: AMM 5-10-25PROC. REF: AMM 5-10-25								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-10-26-6000 LDG	MAJOR LANDING GEAR							Package ATA:05
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)		6000	6025	4906 (+25)	
PROC. REF: AMM 5-10-26PROC. REF: AMM 5-10-26								PKG:26
05-10-27-12 YR	12 YEAR AIRFRAME							Package ATA:05
	MOS	14-Oct-19	144 (+14d/-14d)		14-Oct-31	28-Oct-31	2414 d (+14)	
	HRS	976.1						
	AFL	766	6000 (+25/-25)		6766	6791	5672 (+25)	
PROC. REF: AMM 05-10-27, AMM 5-10-27PROC. REF: AMM 05-10-27, AMM 5-10-27								PKG:27
05-10-28-12000 HR	12000 HOUR AIRFRAME							Package ATA:05
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)		12000	12025	10615 (+25)	
	AFL	0						
PROC. REF: AMM 5-10-28PROC. REF: AMM 5-10-28								PKG:28
05-50-02	PERFORM HARD LANDING OR DEPARTURE FROM RUNWAY MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-03	PERFORM OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT) MAINTENANCE CHECKS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-04		PERFORM SEVERE TURBULENCE AND/OR MANEUVERS MAINTENANCE CHECKS (REFER TO 5-50-00)					Service	ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-05 ^S		PERFORM NO. 1 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00)					Service	ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-05		PERFORM NO. 2 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00)					Service	ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-06		PERFORM HIGH ENERGY STOP (LANDING AND REJECTED TAKEOFF) MAINTENANCE CHECKS (REFER TO 5-50-00)					Service	ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-07		PERFORM PERFORM THRUST REVERSER INSPECTION FOR SLAM-STOW OR HIGH THRUST EMERGENCY STOW OPERATION (REFER TO 78-40-00)					Service	ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-08		PERFORM OVERSPEED RECOVERY LANDING GEAR INSPECTION (LANDING GEAR EXTENSION AND RETRACTION AT HIGH SPEED) (REFER TO 5-50-00)					Service ATA:05	
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-09		PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 5-50-00)					Service ATA:05	
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-10		PERFORM HIGH GROUND WIND GUST INSPECTION (REFER TO 5-50-00)					Service ATA:05	
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-11		PERFORM HEAT DAMAGE INSPECTION (REFER TO 5-50-00)					Service ATA:05	
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-12		PERFORM PRESSURE CABIN SKIN THICKNESS MEASUREMENTS (REFER TO 5-50-00)					Service ATA:05	
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-13	PERFORM FLAP INSPECTION AFTER CONTAMINATED RUNWAY TAKEOFF OR LANDING (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-14	PERFORM VOLCANIC ASH INSPECTION AND MAINTENANCE PROCEDURES (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-15	MAINTENANCE PROCEDURES ON AIRCRAFT EXTERIOR SURFACE WITHIN SALT INFLUENCED ENVIRONMENTS (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-16	PERFORM FLAP OVERSPEED INSPECTION AND REPAIR (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC	22-Aug-07	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								
05-50-17	PERFORM FOREIGN OBJECT DAMAGE INSPECTION (REFER TO 5-50-00)							Service ATA:05
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
	AFL							
PROC. REF: AMM 5-50-00PROC. REF: AMM 5-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-PATS-490001	APU - INSPECT APU PER MANUFACTURERS INSTRUCTIONS							Service ATA:05
	MOS	07-Oct-23						
	HRS	937	200		1137		147.8	
	APUS	1862						
PROC. REF: SMM 49-11-03PROC. REF: SMM 49-11-03								
05-PATS-490002	APU - ANNUAL INSPECTION OF APU MOUNTS FOR LOOSENESS & DAMAGE							Service ATA:05
	MOS	18-Apr-24	12		18-Apr-25		44 d	
	HRS							
	APUS							
PROC. REF: SMM 49-11-03PROC. REF: SMM 49-11-03								
05-PATS-490005	VISUALLY INSPECT ALL MOUNT PARTS AND FUSELAGE ATTACHMENT POINTS FOR CRACKS OR DAMAGE							Service ATA:05
	MOS	22-Aug-07						
	HRS	0	3000		3000		1615	
	AFL	0						
	APH	0	3000		3000		2010.8	
PROC. REF: GENERIC NO REF, SMM 49-11-03PROC. REF: GENERIC NO REF, SMM 49-11-03								
05-PATS-490006	PERFORM EXHAUST & INLET DOUBLER FRAMES & STRINGERS							Service ATA:05
	MOS	22-Aug-07						
	HRS	0	10000		10000		8615	
	AFL	0						
PROC. REF: GENERIC NO REF, SMM 49-11-03PROC. REF: GENERIC NO REF, SMM 49-11-03								
05-PATS-490007	APU - DRAIN EPA SUMP							Service ATA:05
	MOS/MSC	25-Aug-06	O/C					
	HRS	0						
	APUS	0						
05-T20G-490001	APU - PERFORM OIL LEVEL CHECK							Service ATA:05
	MOS/MSC	24-Mar-23	PR/C					
	HRS	916.4						
	APUS	1818						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-T20G-490002	APU - CHECK EXTERNAL FUEL AND OIL LEAKAGE, AIR INLET AND EXHAUST DUCTS FOR OBSTRUCTION AND ATTACHING BOLTS AND SCREWS FOR ATTACHMENT AND SECURITY							Service ATA:05
	MOS	15-Apr-19						
	HRS	761	500		1261		271.8	
	APUS	1490						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490003	APU - PERFORM APU OIL & FILTER CHANGE							Service ATA:05
	MOS	24-Mar-23	24		24-Mar-25		19 d	
	HRS	916.4	500		1416.4		427.2	
	APUS	1818						
PROC. REF: MM 49-20-00, MM 49-20-00PROC. REF: MM 49-20-00, MM 49-20-00								
05-T20G-HS-490004	APU - VISUAL INSPECTION ENGINE HARNESS							Service ATA:05
	MOS	30-Apr-18						
	HRS	731	500		1231		241.8	
	APUS	1403						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490005	APU - INSPECT IGNITER PLUG							Service ATA:05
PN:PN	MOS	11-Oct-21						
SN:UNKNOWN	HRS	862	500		1362		372.8	
	APUS	1727						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490006	APU - INSPECT COMBUSTOR FUEL DRAIN LINE							Service ATA:05
	MOS	15-Apr-19						
	HRS	761	500		1261		271.8	
	APUS	1490						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490007	APU - INSPECT OIL OVERFILL TUBE ASSEMBLY FOR CLEANLINESS AND OBSTRUCTIONS							Service ATA:05
	MOS	15-Apr-19						
	HRS	761	500		1261		271.8	
	APUS	1490						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS / MAINTENANCE CHECKS								
05-T20G-HS-490010	APU - INSPECT APU HOUSING, COVERS AND BRACKETS							Service ATA:05
	MOS	15-Apr-19						
	HRS	761	500		1261		271.8	
	APUS	1490						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
05-T20G-HS-490011	APU - REPLACE FUEL INLET FILTER							Service ATA:05
	MOS	24-Mar-23	24		24-Mar-25		19 d	
	HRS	916.4	500		1416.4		427.2	
	APUS	1818						
PROC. REF: MM 49-20-00PROC. REF: MM 49-20-00								
050300 ^U	PERFORM 300 HOUR SUPPLEMENTAL MAINTENANCE CHECKS							Package ATA:05
	MOS	08-Nov-22						SMM
	HRS	1247	300		1547		162	
	AFL	971						
PKG:5								
050600 ^U	PERFORM 600 HOUR SUPPLEMENTAL MAINTENANCE CHECKS							Package ATA:05
	MOS	25-Jan-22						SMM
	HRS	1207.3	600		1807.3		422.3	
	AFL	939						
PKG:6								
052000	NO. 1 ENGINE - MINOR INSPECTION ITEMS							Package ATA:05
	MOS	07-Oct-23	36		07-Oct-26		581 d	
	HRS	1309.3	600 (+40/-9)		(1909.3) 1909.3	1949.3	524.3 (+40)	
	ENC	1026						
PKG:1								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
052000	NO. 2 ENGINE - MINOR INSPECTION ITEMS							Package ATA:05
	MOS	07-Oct-23	36		07-Oct-26		581 d	
	HRS	1309.3	600 (+40/-9)		(1909.3) 1909.3	1949.3	524.3 (+40)	
	ENC	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
054800 ^U	PERFORM 4800 HOUR SUPPLEMENTAL MAINTENANCE CHECKS							Package ATA:05
	MOS	22-Aug-07						SMM
	HRS	0	4800		4800		3415	
	AFL	0						
								PKG:7
055002	NO. 1 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								
055002	NO. 2 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								
055003	NO. 1 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055003	NO. 2 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								
055004	NO. 1 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								
055004	NO. 2 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								
055005	NO. 1 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055005	NO. 2 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055008	NO. 1 ENGINE - ENGINE OPERATION IN VISIBLE, REPORTED OR SUSPECTED VOLCANIC ASH							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								
055008	NO. 2 ENGINE - ENGINE OPERATION IN VISIBLE, REPORTED OR SUSPECTED VOLCANIC ASH							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								
055009	NO. 1 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055009	NO. 2 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055010	NO. 1 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
055010	NO. 2 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055011	NO. 1 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055011	NO. 2 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: EMM 05-50-00PROC. REF: EMM 05-50-00								
055012	NO. 1 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	10-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								
055012	NO. 2 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)							Service ATA:05
	MOS/MSC	11-Nov-06	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REF, EMM 05-50-00PROC. REF: GENERIC NO REF, EMM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 08 - LEVELING AND WEIGHING									
082000	WEIGHT AND BALANCE							Service	ATA:08
	MOS/MSC	22-Aug-07	A/R						
	HRS	0							
	AFL	0							
PROC. REF: AMM 08-20-00PROC. REF: AMM 08-20-00									
ATA 11 - PLACARDS AND MARKINGS									
113000	GENERAL VISUAL INSPECTION OF THE CABIN PLACARDS - INTERNAL							Service	ATA:11
	MOS	08-Nov-22					SMM		
	HRS	1247	300						
	AFL	971							
PKG:5									
T1130001	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS. (REFER TO 11-30-00.)							Service	ATA:11
	MOS	07-Oct-23	96 (+14d/-14d)						
	HRS	1309.3	2400 (+25/-25)						
	AFL	1026							
PKG:20									
PROC. REF: AMM 11-30-00PROC. REF: AMM 11-30-00									
ATA 12 - SERVICING									
121005	PERFORM NOSE AND MAIN TIRE PRESSURE CHECKS							Service	ATA:12
	MOS/MSC	26-Mar-21	A/R						
	HRS	1109.9							
	AFL	869							
PROC. REF: AMM 12-10-05PROC. REF: AMM 12-10-05									
D1221001	LUBRICATE NOSE LANDING GEAR ACTUATOR - LUBRICATE ATTACH FITTING. (REFER TO 12-21-01)							Service	ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)						
	HRS	1375.9	300 (+25/-25)						
	AFL	1084							
PKG:5									
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
D1221002	^S	LUBRICATE NOSE LANDING GEAR ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-01)						Service ATA:12
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:11
D1221006	^S	INSPECT THRUST REVERSERS - LUBRICATE IDLER LINKS AND DRIVE LINKS. (REFER TO 12-21-04)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:3
D1221010	^S	LUBRICATE MAIN LANDING GEAR AFT TRUNNION PIN. (REFER TO 12-21-01)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
D1221011	^S	LUBRICATE MAIN LANDING GEAR FORWARD TRUNNION PIN. (REFER TO 12-21-01)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
D1221012	^S	LUBRICATE MAIN LANDING GEAR TORQUE LINK BUSHINGS. (REFER TO 12-21-01)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
D1221013	^S	LUBRICATE MAIN LANDING GEAR ACTUATOR STRUT ATTACH POINT. (REFER TO 12-21-01)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
F1221008	^S	LUBRICATE MAIN LANDING GEAR DOOR ACTUATOR (48C48608) PISTON ROD FELT WIPER. (REFER TO 12-21-01).						Service ATA:12
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:11
G1221004	^S	LUBRICATE NOSE LANDING GEAR DOORS HINGES. (REFER TO 12-21-01)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
G1221005	^S	LUBRICATE MAIN LANDING GEAR DOORS HINGES. (REFER TO 12-21-01)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
G1221007	^S	LUBRICATE NOSE LANDING GEAR UPLATCH ACTUATOR PISTON ROD FELT WIPERS. (REFER TO 12-21-01).						Service ATA:12
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
G1221019	^S	LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE. (REFER TO 12-21-03)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221020	^S	LUBRICATE SINGLE POINT REFUELING ACCESS DOOR HINGES. (REFER TO 12-21-03)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221021	^S	LUBRICATE EMERGENCY EXIT/BAGGAGE DOOR HINGES AND LATCH PINS. (REFER TO 12-21-03)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221023	^S	LUBRICATE TOILET SERVICING DOOR HINGE. (REFER TO 12-21-03)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221024	^S	LUBRICATE TAILCONE EQUIPMENT DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
G1221025 ^S	LUBRICATE TAILCONE BAGGAGE DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:6
G1221029 ^S	INSPECT LOWER NACELLE - LUBRICATE HINGES. (REFER TO 12-21-03)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:3
G1221030 ^S	LUBRICATE OXYGEN SERVICING ACCESS DOOR HINGE. (REFER TO 12-21-03)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:2
G1230000 ^S	INSPECT ALCOHOL ANTI-ICE TANK - CHECK FOR QUANTITY OF FLUID. (REFER TO 12-10-08)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-10-08PROC. REF: AMM 12-10-08								PKG:2
H1221003 ^S	LUBRICATE NOSE LANDING GEAR ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.)							Service ATA:12
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
H1221028 ^S	LUBRICATE UPPER AND LOWER ENTRY DOORS HINGES AND LATCH PINS. (REFER TO 12-21-03)							Service ATA:12
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:12
L1221017 ^S	LUBRICATE FLAP CAM FOLLOWERS. (REFER TO 12-21-02)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:4
L1221036 ^S	LUBRICATE SPOILER ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-02).							Service ATA:12
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:10
M1221038 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) WING ATTACH POINTS. (REFER TO 12-21-01)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
M1221040 ^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.)							Service ATA:12
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
M1221041 ^S	INSPECT THRUST REVERSERS - LUBRICATE GUIDE RODS. (REFER TO 12-21-04)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								PKG:3
P1210051 ^S	CHECK NOSE GEAR SHOCK STRUT FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-03)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03								PKG:5
P1210052 ^S	CHECK MAIN GEAR SHOCK STRUTS FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-04)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04								PKG:5
P1210053 ^S	INSPECT EMERGENCY AIR PRESSURE GAUGE - CHECK FOR PROPER AIR PRESSURE (1800 TO 3000 PSI). (REFER TO 12-10-07)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-10-07PROC. REF: AMM 12-10-07								PKG:1
P1210054 ^S	INSPECT OXYGEN PRESSURE GAUGE - CHECK FOR PROPER INFLATION (1500 TO 1850 PSI). (REFER TO 12-10-09)							Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-10-09PROC. REF: AMM 12-10-09								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
P1210055	^S	CHECK NOSE AND MAIN TIRES FOR PROPER INFLATION. (REFER TO 12-10-05)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-10-05PROC. REF: AMM 12-10-05								PKG:5
P1210056	^S	INSPECT HYDRAULIC AND THRUST REVERSER ACCUMULATORS - CHECK ACCUMULATOR PRECHARGE (850 PSI). (REFER TO 12-21-04)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-10-01PROC. REF: AMM 12-10-01								PKG:3
P1221043	^S	LUBRICATE NOSE LANDING GEAR TRUNNION PINS. (REFER TO 12-21-01)						Service ATA:12
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
R1221039	^S	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 2327100) PISTON ROD FELT WIPER. (REFER TO 12-21-01).						Service ATA:12
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:11
X1221045	^S	LUBRICATE R/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184)						Service ATA:12
	MOS	08-Nov-22	12 (+14d/-14d)					
	HRS	1247	300 (+25/-25)					
	AFL	971						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
X1221046 ^S	LUBRICATE L/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184)							Service ATA:12
	MOS	08-Nov-22	12 (+14d/-14d)					
	HRS	1247	300 (+25/-25)					
	AFL	971						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:2
ATA 21 - AIR CONDITIONING								
05-10-29-L2150053	FUNCTION TEST REFRIGERATION SYSTEM PRESSURE SWITCH							Service ATA:21
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 21-50-05PROC. REF: AMM 21-50-05								
05-10-29-N2150019	PENETRANT INSPECT AC COMPRESSOR FAN BLADES							Service ATA:21
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
PROC. REF: NDT 21-50-01PROC. REF: NDT 21-50-01								
05-10-29-U2130007	PERFORM CABIN LEAK RATE CHECK							Service ATA:21
	MOS	14-Oct-19						
	HRS	976.1	1200 (+25/-25)		2176.1	2201.1	791.1 (+25)	
	AFL	766						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								
212001	COCKPIT AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01								
212003	LEFT CABIN AIR CHECK VALVE							Component ATA:21
PN:60160-11	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6839AC	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02								
212004	RIGHT CABIN AIR CHECK VALVE							Component ATA:21
PN:60160-11	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6842AC	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02								
212005	LEFT CABIN OVERHEAD DIFFUSER							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03								
212006	RIGHT CABIN OVERHEAD DIFFUSER							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03								
212007	AFT EVAPORATOR BLOWER ASSEMBLY							Component ATA:21
PN:66-0261-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:K22133	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10PROC. REF: AMM 21-51-10								
212007A	INSPECT AFT EVAPORATOR BLOWER ASSEMBLY BRUSHES							Service ATA:21
PN:66-0261-2	MOS/MSC	22-Aug-07	O/C					
SN:K22133	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212008	FWD EVAPORATOR BLOWER ASSEMBLY							Component ATA:21
PN:66-0251-4	MOS/MSC	25-Oct-08	O/C					
SN:6602514-052	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-51-08PROC. REF: AMM 21-51-08								
212101	CABIN EVAPORATOR BLOWER							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01								
212104	COCKPIT EVAPORATOR BLOWER							Component ATA:21
PN:ES7317H	MOS/MSC	03-Apr-20	O/C	TSO 0				
SN:1675AB	HRS	1010.6		TSO 0				
	AFL	792		TSO 0				
PROC. REF: AMM 21-21-04PROC. REF: AMM 21-21-04								
212105	COCKPIT BLOWER CONTROL BOX ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-05PROC. REF: AMM 21-21-05								
212155	LEFT BLEED AIR MUFFLER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212156	RIGHT BLEED AIR MUFFLER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212201	LEFT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-22-01PROC. REF: AMM 21-22-01								
212202	RIGHT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-22-01PROC. REF: AMM 21-22-01								
212205	AVIONICS COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-22-02PROC. REF: AMM 21-22-02								
213001	PRIMARY OUTFLOW VALVE							Component ATA:21
PN:103780-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0220	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01								
213002	SECONDARY OUTFLOW VALVE							Component ATA:21
PN:103782-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-B0350	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02								
213003	CABIN AIR PRESSURE SELECTOR							Component ATA:21
PN:2119828-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:86-B0341	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03								
213004	CABIN PRESSURE CONTROLLER							Component ATA:21
PN:2119830-4	MOS/MSC	17-May-10	O/C	TSR 0				
SN:38-F0129	HRS	506.9		TSR 0				
	AFL	413		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04								
213005	MANUAL PRESSURE CONTROLLER							Component ATA:21
PN:4222152-1001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1282D	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-05PROC. REF: AMM 21-30-05								
213006	AIR FILTER							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06								
213008	PRESSURIZATION MODE SWITCH							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-08PROC. REF: AMM 21-30-08								
213009	EMERGENCY DEPRESSURIZATION SWITCH							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-09PROC. REF: AMM 21-30-09								
213010	CABIN PRESSURE INDICATOR							Component ATA:21
PN:10403N04C00	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:07954	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-10PROC. REF: AMM 21-30-10								
213011	VACUUM REGULATOR							Component ATA:21
PN:131402-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1431D	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-30-11PROC. REF: AMM 21-30-11								
213012	VACUUM PUMP							Component ATA:21
PN:131410-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:76-1690	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-12PROC. REF: AMM 21-30-12								
213013	VACUUM CHECK VALVE							Component ATA:21
PN:130158-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:46-4309	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-13PROC. REF: AMM 21-30-13								
213101	LEFT EMERGENCY PRESSURIZATION VALVE							Component ATA:21
PN:61700-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1078	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01								
213102	RIGHT EMERGENCY PRESSURIZATION VALVE							Component ATA:21
PN:61700-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1076	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01								
213103	LEFT EMERGENCY PRESSURIZATION ANEROID SWITCH							Component ATA:21
PN:2E37C-30	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:839	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02PROC. REF: AMM 21-31-02								
213104	RIGHT EMERGENCY PRESSURIZATION ANEROID SWITCH							Component ATA:21
PN:2E37C-30	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:834	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-31-02PROC. REF: AMM 21-31-02								
213105	LEFT CONDITIONED AIR CHECK VALVE							Component ATA:21
PN:60160-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7364AL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03								
213106	RIGHT CONDITIONED AIR CHECK VALVE							Component ATA:21
PN:60160-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7366AL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03								
213107	POSITIVE VENTILATION CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04								
214001	FLOW CONTROL VALVE							Component ATA:21
PN:320335-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:580	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-40-01PROC. REF: AMM 21-40-01								
214002	HEAT EXCHANGER							Component ATA:21
PN:6608060-009	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:A197	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-40-02PROC. REF: AMM 21-40-02								
214101	COCKPIT HEATER							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-41-01PROC. REF: AMM 21-41-01								
214102	COCKPIT DIVERTER DOOR SOLENOID							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-02PROC. REF: AMM 21-41-02								
214103	COCKPIT DIVERTER DOOR RESISTOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-03PROC. REF: AMM 21-41-03								
214104	COCKPIT DIVERTER DOOR THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-04PROC. REF: AMM 21-41-04								
214201	LEFT AUXILIARY CABIN HEATER							Component ATA:21
PN:7026-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0301	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-42-01PROC. REF: AMM 21-42-01								
214202	RIGHT AUXILIARY CABIN HEATER							Component ATA:21
PN:7026-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0306	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-42-01PROC. REF: AMM 21-42-01								
214203	AUXILIARY HEAT OVERTEMPERATURE MONITOR BOX							Component ATA:21
PN:6018166-004	MOS/MSC	15-Apr-11	O/C					
SN:MRP529738	HRS	510.5						
	AFL	414						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-42-02PROC. REF: AMM 21-42-02								
214301	LEFT OUTBOARD ELECTRIC FOOT WARMER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-43-00PROC. REF: AMM 21-43-00								
214302	LEFT INBOARD ELECTRIC FOOT WARMER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-43-00PROC. REF: AMM 21-43-00								
214303	RIGHT INBOARD ELECTRIC FOOT WARMER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-43-00PROC. REF: AMM 21-43-00								
214304	RIGHT OUTBOARD ELECTRIC FOOT WARMER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-43-00PROC. REF: AMM 21-43-00								
215001	AIR CONDITIONING COMPRESSOR							Component ATA:21
PN:JBS222-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:K20336	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-01, AMM 21-51-01PROC. REF: AMM 21-50-01, AMM 21-51-01								
215003	CONDENSER							Component ATA:21
PN:7608061-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:992	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-50-03, AMM 21-51-04PROC. REF: AMM 21-50-03, AMM 21-51-04								
215004	RECEIVER/DRYER							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-04, AMM 21-51-05PROC. REF: AMM 21-50-04, AMM 21-51-05								
215005	FREON PRESSURE SWITCH							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-05, AMM 21-51-06PROC. REF: AMM 21-50-05, AMM 21-51-06								
215006	COCKPIT EVAPORATOR							Component ATA:21
PN:6009002V2-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:K19935	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-06, AMM 21-51-07PROC. REF: AMM 21-50-06, AMM 21-51-07								
215007	FREON COMPRESSOR DRIVE (R134) MOTOR							Component ATA:21
PN:ES61134-3	MOS	30-May-18		TSO 0				OVERHAUL
SN:629	HRS	843.6		TSO 0				
	AFL	655		TSO 0				
	ACH	927.6	2000 (+25/-25)	TSO 0	2927.6	2952.6	1078.6 (+25)	
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02								
215007A	INSPECT/REPLACE FREON COMPRESSOR DRIVE (R134) MOTOR BRUSHES - 05-10-29-K2150036							Service ATA:21
PN:ES61134-3	MOS	30-May-18						
SN:629	HRS	843.6						
	AFL	655						
	ACH	927.6	1200 (+25/-25)		2127.6	2152.6	278.6 (+25)	
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215008	COCKPIT EVAPORATOR PRESSURE REGULATOR VALVE							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-08PROC. REF: AMM 21-50-08								
215009	CABIN EVAPORATOR							Component ATA:21
PN:6009002V2-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:244A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10, AMM 21-50-09PROC. REF: AMM 21-51-10, AMM 21-50-09								
215010	CABIN EXPANSION VALVE							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-10, AMM 21-51-11PROC. REF: AMM 21-50-10, AMM 21-51-11								
215012	FREON MOTOR CONTROL BOX							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-12, AMM 21-51-13PROC. REF: AMM 21-50-12, AMM 21-51-13								
215013	K61 FREON MOTOR CONTACTOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-13, AMM 21-51-14PROC. REF: AMM 21-50-13, AMM 21-51-14								
215014	K62 FREON MOTOR CONTACTOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-13, AMM 21-51-14PROC. REF: AMM 21-50-13, AMM 21-51-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
215015	K63 FREON MOTOR CONTACTOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-13, AMM 21-51-14PROC. REF: AMM 21-50-13, AMM 21-51-14								
215016	FREON MOTOR DIFFERENTIAL CURRENT SENSOR							Component ATA:21
PN:268-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:206250408	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-14, AMM 21-51-15PROC. REF: AMM 21-50-14, AMM 21-51-15								
215017	COMPRESSOR MOTOR HOURMETER							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-16, AMM 21-51-03PROC. REF: AMM 21-50-16, AMM 21-51-03								
215031	ABSOLUTE PRESSURE SWITCH							Component ATA:21
PN:EC45C-47	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:5431	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215049	COCKPIT EXPANSION VALVE							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-07, AMM 21-51-09PROC. REF: AMM 21-50-07, AMM 21-51-09								
215120	CONDENSER FAN							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216001	REMOTE CABIN TEMPERATURE SETTING BOX							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01								
216002	CREW TEMPERATURE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02								
216003	CABIN TEMPERATURE SELECTOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02								
216004	TEMPERATURE CONTROL INDICATOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-03PROC. REF: AMM 21-60-03								
216005	COCKPIT TEMPERATURE CONTROLLER							Component ATA:21
PN:625734-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:625734-01119	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04								
216006	CABIN TEMPERATURE CONTROLLER							Component ATA:21
PN:625734-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:625734-01120	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216007	COCKPIT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05								
216008	CABIN TEMPERATURE SENSOR							Component ATA:21
PN:627962-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05								
216009	COCKPIT TEMPERATURE SENSOR BLOWER							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05								
216010	CABIN TEMPERATURE SENSOR BLOWER							Component ATA:21
PN:6600231-1	MOS/MSC	17-Dec-07	O/C					
SN:UNKNOWN	HRS	150.5						
	AFL	109						
PROC. REF: AMM 21-60-05PROC. REF: AMM 21-60-05								
216011	COCKPIT SKIN TEMPERATURE SENSOR							Component ATA:21
PN:625704-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0760-6982	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06								
216012	CABIN SKIN TEMPERATURE SENSOR							Component ATA:21
PN:625704-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0960-7001	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216013	COCKPIT TEMPERATURE CONTROL VALVE							Component ATA:21
PN:3291290-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:656	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07								
216014	CABIN TEMPERATURE CONTROL VALVE							Component ATA:21
PN:3291290-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:652	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07								
216015	COCKPIT TEMPERATURE CONTROL VALVE TORQUE MOTOR							Component ATA:21
PN:124904-1-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6604	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08								
216016	CABIN TEMPERATURE CONTROL VALVE TORQUE MOTOR							Component ATA:21
PN:124904-1-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6610	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08								
216017	SERVO AIR PRESSURE REGULATOR							Component ATA:21
PN:60810-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1197	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-09PROC. REF: AMM 21-60-09								
216018	COCKPIT AIR DISTRIBUTION CHECK VALVE							Component ATA:21
PN:3202078-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1340	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216019	CABIN AIR DISTRIBUTION CHECK VALVE							Component ATA:21
PN:3202188-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:728	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10								
216020	COCKPIT DUCT TEMPERATURE SENSOR							Component ATA:21
PN:627962-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:627962-20064	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11								
216021	CABIN DUCT TEMPERATURE SENSOR							Component ATA:21
PN:627962-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:627962-20088	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11								
216022	COCKPIT DUCT OVERHEAT THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-12PROC. REF: AMM 21-60-12								
216023	CABIN DUCT OVERHEAT THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-12PROC. REF: AMM 21-60-12								
216024	CLIMATE CONTROL BOX							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-13PROC. REF: AMM 21-60-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
216025	PILOT ELECTRICAL EQUIPMENT BOX							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-14PROC. REF: AMM 21-60-14								
216050	MEMBRANE, CABIN TEMPERATURE SWITCH							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216101	CABIN TEMPERATURE INDICATOR							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-01PROC. REF: AMM 21-61-01								
216102	CABIN TEMPERATURE INDICATOR SENSOR							Component ATA:21
PN:RTD-1-F3142-48-T	MOS/MSC	17-Dec-07	O/C					
SN:UNKNOWN	HRS	150.5						
	AFL	109						
PROC. REF: AMM 21-61-02PROC. REF: AMM 21-61-02								
218105	LEFT TRANSITION DUCT ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10PROC. REF: AMM 21-51-10								
218106	RIGHT TRANSITION DUCT ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-10PROC. REF: AMM 21-51-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
B2121004 ^S	INSPECT POSITIVE VENTILATION CHECK VALVE. (REFER TO 21-31-04.)							Service ATA:21
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
PROC. REF: AMM 21-31-04PROC. REF: AMM 21-31-04								PKG:25
C2132030 ^S	INSPECT CABIN (PRESSURE) CONDITIONED AIR CHECK VALVES. (REFER TO 21-31-03.)							Service ATA:21
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
PROC. REF: AMM 21-31-03PROC. REF: AMM 21-31-03								PKG:25
C2132031 ^S	INSPECT CABIN AIR AND COCKPIT AIR CHECK VALVES. (REFER TO 21-20-01 AND 21-20-02.)							Service ATA:21
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01								PKG:25
E2130005 ^S	BOREScope INSPECTION PRIMARY AND SECONDARY OUTFLOW VALVE POPPETS AND SEATS FOR CONTAMINATION. (REFER TO 21-30-00).							Service ATA:21
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:13
E2130064 ^S	REMOVE AND REPLACE CABIN AIR FILTER. (REFER TO 21-30-06).							Service ATA:21
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06								PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
H2132004 ^S	PERFORM FUNCTIONAL TEST OF EMERGENCY PRESSURIZATION SYSTEM. (REFER TO 21-31-00)							Service ATA:21
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 21-31-00PROC. REF: AMM 21-31-00								PKG:7
H2150000 ^S	INSPECT REFRIGERATION (AIR CONDITIONING) SYSTEM COMPONENTS INSTALLATION FOR PROPER V-BELT TENSION, SECURITY OF MOUNTING, AND GENERAL CONDITION. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND SHAFT)							Service ATA:21
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 12-10-06, AMM 21-50-01, AMM 21-51-01PROC. REF: AMM 12-10-06, AMM 21-50-01, AMM 21-51-01								PKG:9
K2150006 ^S	PERFORM REFRIGERATION COMPRESSOR MOTOR BRUSH WEAR INSPECTION. (REFER TO 21-50-02)							Service ATA:21
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02								PKG:9
L2150048 ^S	FUNCTIONAL TEST OF REFRIGERATION SYSTEM PRESSURE SWITCH. (REFER TO 21-50-05.)							Service ATA:21
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 21-50-05PROC. REF: AMM 21-50-05								PKG:21
N2131010 ^S	FUNCTIONAL TEST OF CABIN PRESSURE WARNING SYSTEM. (REFER TO 21-30-00.)							Service ATA:21
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
N2144000 ^S	FUNCTIONAL TEST OF TAILCONE BAGGAGE COMPARTMENT HEATING SYSTEM. (REFER TO 21-44-00.)							Service ATA:21
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 21-44-00PROC. REF: AMM 21-44-00								PKG:21
N2150017 ^S	PERFORM A FLUORESCENT PENETRANT INSPECTION OF THE AIR CONDITIONER COMPRESSOR MOTOR FAN BLADES. PARTICULAR ATTENTION SHOULD BE GIVEN TO THE FAN BLADES IN THE AREA OF THE HUB. (REFER TO NDI MANUAL [NDI-2], PART 5, 21-50-01.)							Service ATA:21
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: NDT 21-50-01PROC. REF: NDT 21-50-01								PKG:15
P2130070 ^S	FUNCTIONAL TEST OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00)							Service ATA:21
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:13
T2120001 ^S	INSPECT RAM AIR DUCTING AND HEAT EXCHANGER FRO SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:21
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
T2130012 ^S	PERFORM FUNCTIONAL TEST OF PRESSURIZATION SYSTEM VACUUM PUMP HEATING ELEMENT. (REFER TO 21-30-12)							Service ATA:21
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 21-30-12PROC. REF: AMM 21-30-12								PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
T2130069 ^S		PERFORM OPERATIONAL CHECK OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00)					Service	ATA:21
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:7
T2142002 ^S		FUNCTIONAL TEST OF AUXILIARY CABIN HEAT SYSTEM. (REFER TO 21-42-00.)					Service	ATA:21
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 21-42-00PROC. REF: AMM 21-42-00								PKG:13
T2144010 ^S		VISUALLY INSPECT TAILCONE BAGGAGE COMPARTMENT HEATER BLANKETS. (REFER TO 5-10-00.)					Service	ATA:21
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
ATA 22 - AUTO FLIGHT								
221001		AUTOPILOT CONTROLLER					Component	ATA:22
PN:501-1679-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80008	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01								
221002		AUTOPILOT ELECTRICAL BOX					Component	ATA:22
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221003 PITCH SERVO ACTUATOR								Component ATA:22
PN:622-5027-102	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2HHXC	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03								
221004 PITCH SERVO MOUNT								Component ATA:22
PN:622-5029-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2D61G	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04								
221005 AUTOPITCH TRIM AMPLIFIER BOX ASSEMBLY								Component ATA:22
PN:5418419-009	MOS/MSC	28-Nov-07	O/C					
SN:429080	HRS	135						
	AFL	93						
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05								
221006 ROLL SERVO ACTUATOR								Component ATA:22
PN:622-5027-102	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2D5LR	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06								
221007 ROLL DISCONNECT RELAY BOX								Component ATA:22
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07								
221008 YAW DISCONNECT RELAY BOX								Component ATA:22
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-08PROC. REF: AMM 22-10-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221009 YAW SERVO ACTUATOR								Component ATA:22
PN:622-5027-102	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2056F	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-09PROC. REF: AMM 22-10-09								
221010 YAW SERVO MOUNT								Component ATA:22
PN:622-5029-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2D5TV	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-10PROC. REF: AMM 22-10-10								
221011 ROLL SERVO MOUNT								Component ATA:22
PN:6080014-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2942W	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-11PROC. REF: AMM 22-10-11								
221012 REMOTE TUNING RELAY BOX								Component ATA:22
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-12PROC. REF: AMM 22-10-12								
221013 NO. 1 FLIGHT GUIDANCE COMPUTER								Component ATA:22
PN:822-1108-041	MOS/MSC	21-Jun-21	O/C					
SN:287VK	HRS	1129.3						
	AFL							
PROC. REF: AMM 22-10-14PROC. REF: AMM 22-10-14								
221014 NO. 2 FLIGHT GUIDANCE COMPUTER								Component ATA:22
PN:822-1108-041	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:284TL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-14PROC. REF: AMM 22-10-14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
222001		MACH TRIM COMPUTER					Component	ATA:22
PN:501-1132-04	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80053	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-01PROC. REF: AMM 22-20-01								
222002		MACH TRIM ADAPTER					Component	ATA:22
PN:902-1-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:206380114	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-02PROC. REF: AMM 22-20-02								
222003		MACH TRIM POSITION (FOLLOW UP) SENSOR					Component	ATA:22
PN:6608436-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-20-03PROC. REF: AMM 22-20-03								
225001		YAW FORCE INTERFACE BOX					Component	ATA:22
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01								
225002		PILOT FORCE SENSOR					Component	ATA:22
PN:3454-101-650	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1110037	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02								
225003		COPILLOT FORCE SENSOR					Component	ATA:22
PN:3454-101-650	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1110034	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
B2211016 ^S	CHECK PRIMARY YAW DAMPER SERVO ACTUATOR AND SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-09.)							Service ATA:22
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: AMM 22-10-10PROC. REF: AMM 22-10-10								PKG:28
B2212013 ^S	CHECK PITCH SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-06.)							Service ATA:22
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04								PKG:28
B2213006 ^S	CHECK AUTOPILOT ROLL SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-06.)							Service ATA:22
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: AMM 22-10-11PROC. REF: AMM 22-10-11								PKG:28
H2211034 ^S	CHECK ROLL SERVO CABLE TENSION. (REFER TO 22-10-11.)							Service ATA:22
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 22-10-11PROC. REF: AMM 22-10-11								PKG:17
H2211039 ^S	CHECK PITCH SERVO AND YAW SERVO CABLE TENSION. (REFER TO 22-10-04 AND 22-10-10.)							Service ATA:22
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 22-10-04, AMM 22-10-10PROC. REF: AMM 22-10-04, AMM 22-10-10								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
T2211022 ^S	CHECK YAW SERVO CABLE FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR CONDITION AND SECURITY.							Service ATA:22
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
T2212022 ^S	INSPECT ELEVATOR SERVO CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR GENERAL CONDITION AND SECURITY.							Service ATA:22
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
ATA 23 - COMMUNICATIONS								
231101	NO. 1 VHF TRANSCEIVER							Component ATA:23
PN:822-1115-001	MOS/MSC	21-Oct-08	O/C					
SN:2DGPH	HRS	462.3						
	AFL	362						
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01								
231102	NO. 2 VHF TRANSCEIVER							Component ATA:23
PN:822-1115-001	MOS/MSC	05-Mar-21	O/C					
SN:6033	HRS							
	AFL							
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01								
231103	NO. 1 VHF ANTENNA							Component ATA:23
PN:VF10-347	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:5349	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231104	NO. 2 VHF ANTENNA							Component ATA:23
PN:VF10-347	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:5358	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02								
231121	AERO M SATCOM ANTENNA							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231123	SATCOM PHONE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231180	NO. 1 HF AUDIO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231181	NO. 2 HF AUDIO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231192	HF ANTENNA LEADTHRU INSULATOR							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-03PROC. REF: AMM 23-12-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231201	NO. 1 HF RECEIVER/EXCITER							Component ATA:23
PN:064-01073-0101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1902	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-01PROC. REF: AMM 23-12-01								
231202	NO. 2 HF RECEIVER/EXCITER							Component ATA:23
PN:064-01073-0101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1901	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-01PROC. REF: AMM 23-12-01								
231203	PRIMARY POWER AMPLIFIER/ANTENNA COUPLER							Component ATA:23
PN:064-01074-0101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1977	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02PROC. REF: AMM 23-12-02								
231203A	PERFORM PRIMARY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHF 1050 SYSTEM							Service ATA:23
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	SMM
	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 23-12-08PROC. REF: AMM 23-12-08								
231204	STANDBY POWER AMPLIFIER/ANTENNA COUPLER							Component ATA:23
PN:064-01074-0101	MOS/MSC	17-May-10	O/C					
SN:KAC1052-3381	HRS	506.9						
	AFL	413						
PROC. REF: AMM 23-12-02PROC. REF: AMM 23-12-02								
231204A	PERFORM STANDBY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHF 1050 SYSTEM.							Service ATA:23
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	SMM
	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 23-12-08PROC. REF: AMM 23-12-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231205	HF ANTENNA							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-03PROC. REF: AMM 23-12-03								
231207	NO. 1 HF CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04								
231208	NO. 2 HF CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04								
231209	HF AUDIO ADAPTER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-05PROC. REF: AMM 23-12-05								
231210	HF COMMUNICATION FUSE BOX ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-06PROC. REF: AMM 23-12-06								
231211	(CBR8) HF REMOTE CIRCUIT BREAKER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-07PROC. REF: AMM 23-12-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231212		UPPER HF POWER AMPLIFIER					Component	ATA:23
PN:064-01072-0101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1888	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02PROC. REF: AMM 23-12-02								
231213		LOWER HF POWER AMPLIFIER					Component	ATA:23
PN:064-01072-0101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1811	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02PROC. REF: AMM 23-12-02								
231271		HF GROUND ASSEMBLY					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231301		FLITEFONE TRANSCEIVER					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-13-01PROC. REF: AMM 23-13-01								
231302		FLITEFONE ANTENNA					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-13-02PROC. REF: AMM 23-13-02								
231303		COCKPIT FLITEFONE BASE - CONTROL UNIT					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-13-03PROC. REF: AMM 23-13-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231304	CABIN FLITEFONE BASE - CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-13-03PROC. REF: AMM 23-13-03								
231305	COCKPIT ASSEMBLY PHONE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231306	CABIN ASSEMBLY PHONE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231307	COCKPIT FLIGHT PHONE (TT-3000) HANDSET							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231308	CABIN FLIGHT PHONE (TT-3000) HANDSET							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231310	AIRBORNE RADIO TELECOMMUNICATIONS TRAY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231312		CABIN DISTRIBUTION BUS REPEATER					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231313		LEFT CABIN DISTRIBUTION, FLITEFONE REPEATER					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231314		RIGHT CABIN DISTRIBUTION, FLITEFONE REPEATER					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231315		CALL ALERTER, FLITEFONE SWITCH					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231316		ASSEMBLY, ARTU TRAY					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231317		MAGNASTAR (C-2000/C-750 TMU) ARTU					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231318	MAGNASTAR ANTENNA							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231319	MAGNASTAR ANALOG INTERFACE UNIT							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231320	AIRSAT 1 TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231321	AIRSAT 1 HANDSET							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231335	CELLULAR PHONE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231340	CELL PHONE ANTENNA							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231351	SATELLITE DATA (SDU) UNIT							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231401	SELCAL CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-14-01PROC. REF: AMM 23-14-01								
231402	SELCAL DECODER							Component ATA:23
PN:2800-0012-105	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6415088	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-14-02PROC. REF: AMM 23-14-02								
231403	SELCAL SONALERT							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-14-03PROC. REF: AMM 23-14-03								
231501	PASSENGER BRIEFER CONTROL PANEL							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-01PROC. REF: AMM 23-15-01								
231502	PASSENGER BRIEFER COMPUTER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-02PROC. REF: AMM 23-15-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232001	IRIDIUM SATCOM TRANSCEIVER							Component ATA:23
PN:500617-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:5558	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232005	IRIDIUM SATCOM ANTENNA							Component ATA:23
PN:C1490-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:5015396	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232010	COCKPIT IRIDIUM SATCOM PHONE ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232015	CABIN IRIDIUM SATCOM PHONE ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232020	COCKPIT IRIDIUM SATCOM HANDSET							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232025	CABIN IRIDIUM SATCOM HANDSET							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232030	IRIDIUM SATCOM PHONE CRADLE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232035	IRIDIUM SATCOM PHONE CRADLE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232040	IRIDIUM SATCOM CORDLESS BASE UNIT							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232045	IRIDIUM SATCOM CORDLESS BASE UNIT							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232055	UNILINK (UL-601) PROCESSOR							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232105	VHF DATA LINK TRANSCEIVER							Component ATA:23
PN:822-1468-302	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:29YPL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
232110	COMMUNICATION MANAGEMENT (CMU) UNIT							Component ATA:23
PN:822-1739-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:29YTV	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232111	CMU EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:23
PN:822-1200-997	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2G1KV	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232120	SATPHONE ANTENNA							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233001	LEFT FORWARD CABIN STEREO SPEAKER							Component ATA:23
PN:EN-101M-8-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:020700752	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233002	RIGHT FORWARD CABIN STEREO SPEAKER							Component ATA:23
PN:EN-101M-8-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:020700751	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233003	LEFT AFT CABIN STEREO SPEAKER							Component ATA:23
PN:EN-101M-8-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:010700673	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233004	RIGHT AFT CABIN STEREO SPEAKER							Component ATA:23
PN:EN-101M-8-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:020700749	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233005	PASSENGER SPEAKER AMPLIFIER							Component ATA:23
PN:PA-7501-01-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:120600332	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02								
233007	DVD PLAYER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233023	FORWARD WOOFER, CABIN SPEAKER							Component ATA:23
PN:EN-W-60-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:060600669	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233024	AFT WOOFER, CABIN SPEAKER							Component ATA:23
PN:EN-W-60-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:040600732	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233026	VIDEO CASSETTE PLAYER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233030	CONFIGURATION MODULE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233040	INFRARED REMOTE CONTROL							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233051	CD CHANGER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233052	CONTROL HEAD CD CHANGER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233075	CABIN DISPLAY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233084	FORWARD 15.1 LCD COLOR DISPLAY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233085	FORWARD VIDEO MONITOR-							Component ATA:23
PN:LCD-9151-201-1	MOS/MSC	29-Jul-08	O/C					
SN:040800366	HRS	383.4						
	AFL	298						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233086	AFT VIDEO MONITOR-							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233087	FORWARD 10.4 LCD COLOR DISPLAY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233088	AFT 15.1 LCD COLOR DISPLAY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233101	STEREO ANTENNA							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-01PROC. REF: AMM 23-31-01								
233102	STEREO							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-02PROC. REF: AMM 23-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233103	STEREO BATTERY							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-03PROC. REF: AMM 23-31-03								
233104	STEREO VOLTAGE REGULATOR							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-04PROC. REF: AMM 23-31-04								
233105	AUDIO DISTRIBUTION MODULE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-05PROC. REF: AMM 23-31-05								
233106	LEFT DIGITAL SELECTOR MODULE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-06PROC. REF: AMM 23-31-06								
233107	RIGHT DIGITAL SELECTOR MODULE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-31-06PROC. REF: AMM 23-31-06								
234101	INTERPHONE AUDIO AMPLIFIER							Component ATA:23
PN:MODEL 204	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2818	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-41-01PROC. REF: AMM 23-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
235001		PILOT AUDIO CONTROL PANEL					Component	ATA:23
PN:802-009	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2107	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01								
235002		COPILOT AUDIO CONTROL PANEL					Component	ATA:23
PN:802-009	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2102	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01								
235003		LEFT AUDIO AMPLIFIER					Component	ATA:23
PN:700-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2267	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-02PROC. REF: AMM 23-50-02								
235004		RIGHT AUDIO AMPLIFIER					Component	ATA:23
PN:700-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2269	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-02PROC. REF: AMM 23-50-02								
236005		WEATHER WORX XM RADIO CONTROLLER					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
236010		WEATHER WORX XM DATA PORT					Component	ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
237001	COCKPIT VOICE (CVR) RECORDER							Component ATA:23
PN:1603-02-12	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1577	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01								
237002	CVR REMOTE MICROPHONE AMPLIFIER							Component ATA:23
PN:1635-02	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:359	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03								
237003	CVR REMOTE AREA MICROPHONE							Component ATA:23
PN:16301-01	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2200	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-04PROC. REF: AMM 23-70-04								
237004	CVR INERTIA SWITCH							Component ATA:23
PN:3L0-453/8	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:13831	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-05PROC. REF: AMM 23-70-05								
237021	CVR UNDERWATER LOCATOR (ULB) BEACON							Component ATA:23
PN:DK120	MOS/MSC	30-Apr-18	O/C					
SN:SD37190	HRS	827						
	AFL	646						
PROC. REF: AMM 25-63-00PROC. REF: AMM 25-63-00								
237021A	CLEAN/FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY							Service ATA:23
PN:DK120	MOS	18-Apr-24	24 (+14d/-14d)	18-Apr-26	02-May-26	409 d (+14)		
SN:SD37190	HRS	1336.5						
	AFL	1050						
PROC. REF: AMM 25-63-00PROC. REF: AMM 25-63-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
237021B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000							Service ATA:23
PN:DK120	MOS/MSC	03-Apr-20	DUE		01-Mar-26 (M)		361 d	
SN:SD37190	HRS	1010.3						
	AFL	791						
PROC. REF: AMM 25-63-00PROC. REF: AMM 25-63-00								
237032	AUDIO/VIDEO AMPLIFIER							Component ATA:23
PN:AV-4589-01-1	MOS/MSC	10-May-17	O/C					
SN:010900690	HRS	734.6						
	AFL	567						
PROC. REF: AMM 23-41-01PROC. REF: AMM 23-41-01								
238001	NO. 1 RADIO TUNING (RTU) UNIT							Component ATA:23
PN:822-0730-438	MOS/MSC	19-Oct-21	O/C					
SN:33YWP	HRS							
	AFL							
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01								
238002	NO. 2 RADIO TUNING (RTU) UNIT							Component ATA:23
PN:822-0730-438	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:27JKX	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01								
239007	NO. 1 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
239008	NO. 2 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
239009	NO. 3 SWITCHING MODULE							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
239015	ORDINANCE SIGN SWITCH							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
239016	AUDIO AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-41-01PROC. REF: AMM 23-41-01								
E2360010 ^S	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00)							Service ATA:23
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:6
E2360011 ^S	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00)							Service ATA:23
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:6
H2360021 ^S	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.)							Service ATA:23
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								
P2360022 ^S	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.)							Service ATA:23
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:24
ATA 24 - ELECTRICAL POWER								
05-10-29-B2432010	INSPECT MAIN AIRCRAFT BATTERY INSTALLATION							Service ATA:24
	MOS	12-Nov-24	6 (+14d/-14d)	Adj -44d	29-Mar-25	12-Apr-25	24 d (+14)	
	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
05-10-29-H2431017	PERFORM BATTERY CABLES & RECEPTACLES - BATTERY CONNECTOR INSPECTION							Service ATA:24
	MOS	12-Nov-24						
	HRS	1375.9	300 (+25/-25)		1675.9	1700.9	290.9 (+25)	
	AFL	1084						
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
242001	LEFT PRIMARY AC POWER INVERTER							Component ATA:24
PN:6608483-1	MOS/MSC	14-Feb-11	O/C					
SN:1148	HRS	510.5						
	AFL	414						
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								
242002	RIGHT SECONDARY AC POWER INVERTER							Component ATA:24
PN:501-1666-01	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80096	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242003	POWER MONITOR INDICATOR							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242005	ISOLATION PARALLELING BOX							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242009	NO. 1 GROUND FAULT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4409	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242010	NO. 2 GROUND FAULT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4661	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242016	GENERATOR CONTROL PANEL							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-02PROC. REF: AMM 24-30-02								
242031	DC AMMETER SENSOR							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242032	NO. 1 DC CURRENT SENSOR							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
242033	NO. 2 DC CURRENT SENSOR							Component ATA:24
PN:952-500-C	MOS/MSC	06-Nov-07	O/C					
SN:3727	HRS	108						
	AFL	76						
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
242081	1200 VA, 115 VAC, 60 HZ INVERTER							Component ATA:24
PN:SS120 (C)	MOS/MSC	12-Feb-08	O/C					
SN:165	HRS	223.7						
	AFL	152						
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								
242500 ^{U S}	GENERAL VISUAL INSPECTION OF THE CABIN INVERTER SYSTEM COMPONENTS							Service ATA:24
	MOS	22-Aug-07					SMM	
	HRS	0	4800					
	AFL	0						
PKG:7								
242505	GROUND FAULT INTERRUPTER							Component ATA:24
PN:106072-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:13210207	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242507	60HZ POWER SYSTEM ANEROID SWITCH							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243001	NO. 1 STARTER/GENERATOR							Component ATA:24
PN:400SG138Q-1	MOS/MSC	13-Nov-18	O/C	TSO 0				
SN:3436	HRS	886.4		TSO 0				
	AFL	694		TSO 0				
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01								
243001A	OVERHAUL NO. 1 STARTER/GENERATOR - (Y2431025)							Service ATA:24
PN:400SG138Q-1	MOS	13-Nov-18						OVERHAUL
SN:3436	HRS	886.4	1000 (+25/-25)		1886.4	1911.4	501.4 (+25)	
	AFL	694						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243002	NO. 2 STARTER/GENERATOR							Component ATA:24
PN:400SG138Q-2	MOS/MSC	20-Dec-17	O/C	TSO 0				
SN:3163	HRS	796.1		TSO 0				
	AFL	620		TSO 0				
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01								
243002A	OVERHAUL NO. 2 STARTER/GENERATOR - (Y2431025)							Service ATA:24
PN:400SG138Q-2	MOS	20-Dec-17						OVERHAUL
SN:3163	HRS	796.1	1000 (+25/-25)		1796.1	1821.1	411.1 (+25)	
	AFL	620						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243003	APU STARTER/GENERATOR							Component ATA:24
PN:400SG159Q	MOS/MSC	23-Jan-17	O/C	TSO 0				
SN:5357	HRS	734.6		TSO 0				
	AFL	567		TSO 0				
	APH	702		TSO 0				
PROC. REF: GENERIC NO REF, SMM 49-11-02PROC. REF: GENERIC NO REF, SMM 49-11-02								
243003A	OVERHAUL/REPLACE APU STARTER/GENERATOR BRUSHES							Service ATA:24
PN:400SG159Q	MOS	23-Jan-17						
SN:5357	HRS	734.6						
	AFL	567						
	APH	702	1000		1702		712.8	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243005	LEFT (GCU) GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG505-16B	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1718B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-03PROC. REF: AMM 24-30-03								
243006	RIGHT (GCU) GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG505-16B	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1677B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-03PROC. REF: AMM 24-30-03								
243007	A11 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4407	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04PROC. REF: AMM 24-30-04								
243008	2A11 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4676	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04PROC. REF: AMM 24-30-04								
243009	A12 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4044	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-04PROC. REF: AMM 24-30-04								
243010	2A12 GENERATOR CURRENT TRANSFORMER							Component ATA:24
PN:CTSG700	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4036	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
PROC. REF: AMM 24-30-04PROC. REF: AMM 24-30-04								
243011	LEFT DC AMMETER CURRENT SENSOR							Component ATA:24
PN:256-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:206390253	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
243012	RIGHT DC AMMETER CURRENT SENSOR							Component ATA:24
PN:256-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:206380107	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-30-05PROC. REF: AMM 24-30-05								
243049	UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY							Component ATA:24
PN:RG-380E/60L	MOS/MSC	08-Nov-22	O/C	TSN 6				VENDOR RECOMMENDED
SN:41209090	HRS	1247		TSN 18.5				
	AFL	971		TSN 15				
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
243049B	CAPACITY CHECK UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002							Service ATA:24
PN:RG-380E/60L	MOS	12-Nov-24	6		12-May-25		68 d	
SN:41209090	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 12-22-00PROC. REF: AMM 12-22-00								
243050	LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY							Component ATA:24
PN:RG-380E/60L	MOS/MSC	08-Nov-22	O/C	TSN 6				VENDOR RECOMMENDED
SN:41209129	HRS	1247		TSN 18.5				
	AFL	971		TSN 15				
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
243050B	CAPACITY CHECK LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002							Service ATA:24
PN:RG-380E/60L	MOS	12-Nov-24	6		12-May-25		68 d	
SN:41209129	HRS	1375.9						
	AFL	1084						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
PROC. REF: AMM 12-22-00PROC. REF: AMM 12-22-00								
243051	NO. 1 MAIN - SEALED RECUMBANT BATTERY							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
243051A	SERVICE NO. 1 MAIN - SEALED RECUMBANT BATTERY - 05-10-29-G1222001							Service ATA:24
PN:PN	MOS/MSC	22-Aug-07	N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 12-22-00PROC. REF: AMM 12-22-00								
243052	NO. 2 MAIN - SEALED RECUMBANT BATTERY							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
243052A	SERVICE NO. 2 MAIN - SEALED RECUMBANT BATTERY 05-10-29-G1222001							Service ATA:24
PN:PN	MOS/MSC	22-Aug-07	N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 12-22-00PROC. REF: AMM 12-22-00								
243055	EMERGENCY POWER (24VDC TO 5VDC) CONVERTER							Component ATA:24
PN:MSM2912-01-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:040700184	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243056 ^U	EMERGENCY POWER (24VDC TO 5VDC) CONVERTER							Component ATA:24
PN:RHR18(A)	MOS/MSC	13-May-11	O/C					
SN:133	HRS	512.2						
	AFL	415						
243062	NO. 1 EMERGENCY POWER BATTERY							Component ATA:24
PN:100-2410-06	MOS/MSC	08-Nov-24	O/C	TSO 0				
SN:0705549	HRS	1370.4		TSO 0				
	AFL	1078		TSO 0				
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								
243063	NO. 2 EMERGENCY POWER BATTERY							Component ATA:24
PN:501-1712-02	MOS/MSC	08-Nov-22	O/C	TSR 68				
SN:2633	HRS	1247		TSR 512.4				
	AFL	971		TSR 404				
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								
243063A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010							Service ATA:24
PN:501-1712-02	MOS	12-Nov-24	6 (+14d/-14d)	Adj -44d	29-Mar-25	12-Apr-25	24 d (+14)	
SN:2633	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								
243063B	PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015							Service ATA:24
PN:501-1712-02	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	
SN:2633	HRS	1375.9						
	AFL	1084						
PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170								
243064	NO. 3 EMERGENCY POWER BATTERY							Component ATA:24
PN:501-1712-02	MOS/MSC	08-Nov-22	O/C					
SN:81687	HRS	1247						
	AFL	971						
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243064A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 3 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010							Service ATA:24
PN:501-1712-02	MOS	12-Nov-24	6 (+14d/-14d)	Adj -44d	29-Mar-25	12-Apr-25	24 d (+14)	
SN:81687	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								
243064B	PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 3 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015							Service ATA:24
PN:501-1712-02	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	
SN:81687	HRS	1375.9						
	AFL	1084						
PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170PROC. REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170								
243103	BATTERY TEMPERATURE INDICATOR							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-31-03PROC. REF: AMM 24-31-03								
243200	PERFORM NO. 1 EMERGENCY POWER BATTERY OPERATIONAL CHECK (XL2410) (IRN Y2431061)							Service ATA:24
PN:100-2410-06	MOS	08-Nov-24	12 (+14d/-14d)		08-Nov-25	22-Nov-25	248 d (+14)	
SN:0705549	HRS	1370.4						
	AFL	1078						
PROC. REF: AMM 24-32-01PROC. REF: AMM 24-32-01								
243301	NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK							Component ATA:24
PN:501-1712-02	MOS/MSC	15-May-23	O/C					
SN:81687	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243301A	CHARGE NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030							Service ATA:24
PN:501-1712-02	MOS	18-Apr-24	12 (+14d/-14d)		18-Apr-25	02-May-25	44 d (+14)	
SN:81687	HRS	1336.5						
	AFL	1050						
PROC. REF: AMM 12-23-02PROC. REF: AMM 12-23-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243302	NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK							Component ATA:24
PN:501-1712-02	MOS/MSC	15-May-23	O/C					
SN:2633	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243302A	CHARGE NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030							Service ATA:24
PN:501-1712-02	MOS	18-Apr-24	12 (+14d/-14d)		18-Apr-25	02-May-25	44 d (+14)	
SN:2633	HRS	1336.5						
	AFL	1050						
PROC. REF: AMM 12-23-02PROC. REF: AMM 12-23-02								
244002	GROUND POWER MONITOR-							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-40-02PROC. REF: AMM 24-40-02								
245001	PILOT CIRCUIT BREAKER PANEL							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-01PROC. REF: AMM 24-50-01								
245002	COPILOT CIRCUIT BREAKER PANEL							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-01PROC. REF: AMM 24-50-01								
245003	LEFT OVERLOAD (CBR2) SENSOR							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-03PROC. REF: AMM 24-50-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
245004	RIGHT OVERLOAD (CBR2) SENSOR							Component ATA:24
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-50-03PROC. REF: AMM 24-50-03								
AA2432003 ^S	PERFORM OPERATIONAL CHECK OF AC POWER SYSTEM							Service ATA:24
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 24-20-00PROC. REF: AMM 24-20-00								
H2400004 ^S	INSPECT PEDESTAL INTERIOR WIRING FOR WIRE ROUTING, CLEARANCES, DETERIORATION, AND GENERAL CONDITION.							Service ATA:24
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H2432001 ^S	OPERATIONAL CHECK EMERGENCY DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-51-00.)							Service ATA:24
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 24-51-00PROC. REF: AMM 24-51-00								
H2450021 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.							Service ATA:24
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
P2400008 ^S	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCE, AND GENERAL CONDITION (THAT PORTION VISIBLE THROUGH WHEEL WELLS).						Service	ATA:24
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
Q2400006 ^S	PERFORM INSPECTION OF ALL 4 AWG OR GREATER ELECTRICAL CABLES. VERIFY THERE IS NO HEAT DAMAGE TO THE LARGE GAUGE WIRE TERMINAL CONNECTIONS TO THE POWER DISTRIBUTION ASSEMBLY. INSPECT CONNECTORS AND TERMINAL LUGS FOR CONDITION AND SECURITY. INSPECT CABLE ROUTING TO						Service	ATA:24
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
T2400003 ^S	INSPECT ELECTRICAL WIRING, HYDRAULIC, AND PNEUMATIC LINES UNDER FLOORBOARDS FOR EVIDENCE OF LEAKAGE, SECURITY OF CLAMPS, AND CONDITION. (REFER TO 5-10-00.)						Service	ATA:24
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
T2400009 ^S	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCES SECURITY, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)						Service	ATA:24
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
T2432000 ^S	OPERATIONAL CHECK OF DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-50-00.)						Service	ATA:24
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 24-50-00PROC. REF: AMM 24-50-00								PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
T2450020	^S	CHECK SWITCH AND CIRCUIT BREAKER PANELS FOR GENERAL CONDITION. ENSURE MARKINGS ARE CLEAR AND READABLE.						Service ATA:24
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:13
ATA 25 - EQUIPMENT/FURNISHINGS								
250000		STEREO/PAGE AMPLIFIER						Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
250001	^{U S}	GENERAL VISUAL INSPECTION OF THE PASSENGER AND LAVATORY COMPARTMENT CABINETS, HEADLINER, WINDOW PANELS, BULKHEADS, SLEDGES, TABLES, AND CARPETING						Service ATA:25
	MOS	08-Nov-22					SMM	
	HRS	1247	300					
	AFL	971						
								PKG:5
250002	^U	INSPECT INTERIOR CABINET DRAWER AND DOOR LATCHES FOR WEAR, CONDITION, SECURITY OF ATTACHMENT IN THE STOWED POSITION, AND PROPER OPERATION						Service ATA:25
	MOS	08-Nov-22	36	08-Nov-25		248 d	SMM	
	HRS	1247						
	AFL	971						
250003	^{U S}	INSPECT SIDEEDGE COMPARTMENT DOOR LATCHES FOR WEAR, CONDITION, SECURITY OF ATTACHMENT IN THE STOWED POSITION, AND PROPER OPERATION						Service ATA:25
	MOS	08-Nov-22					SMM	
	HRS	1247	400					
	AFL	971						
								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
250004	U S	INSPECT THE GALLEY, POTTY, AND LAVATORY FOR SPILLAGE						Service ATA:25
	MOS	25-Jan-22					SMM	
	HRS	1207.3	600					
	AFL	939						
PKG:6								
250005	U S	CHECK THE OPERATION, LATCHING AND SEALING OF THE WASTE CONTAINER COMPARTMENTS						Service ATA:25
	MOS	25-Jan-22					SMM	
	HRS	1207.3	600					
	AFL	939						
PKG:6								
250006	U S	CHECK THE OPERATION OF THE AFT PARTITION DOOR HOLD-OPEN LATCH						Service ATA:25
	MOS	08-Nov-22					SMM	
	HRS	1247	300					
	AFL	971						
PKG:5								
251001	PILOT CREW SEAT							Component ATA:25
PN:3A213-0007-01-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:47587	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-10-01PROC. REF: AMM 25-10-01								
251002	COPILOT CREW SEAT							Component ATA:25
PN:3A213-0008-01-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:47226	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-10-01PROC. REF: AMM 25-10-01								
251005	PILOT LIGHTED CHART HOLDER							Component ATA:25
PN:10-62-01	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4948	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-10-05PROC. REF: AMM 25-10-05								
251006 COPILOT LIGHTED CHART HOLDER								Component ATA:25
PN:10-62-01	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4951	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-10-05PROC. REF: AMM 25-10-05								
252001 LEFT FORWARD PASSENGER SEAT								Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252002 RIGHT FORWARD PASSENGER SEAT								Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252003 LEFT MID PASSENGER SEAT								Component ATA:25
PN:3A394-0010-102-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:49365	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252004 RIGHT MID PASSENGER SEAT								Component ATA:25
PN:3A394-0007-102-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:49364	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252005 LEFT AFT PASSENGER SEAT								Component ATA:25
PN:3A394-0007-102-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:49363	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252006	RIGHT AFT PASSENGER SEAT							Component ATA:25
PN:3A394-0010-102-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:49366	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252007	RIGHT PASSENGER DIVAN							Component ATA:25
PN:160201-1R4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:34082	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-05PROC. REF: AMM 25-20-05								
252025	RIGHT LOWER DIFFUSER							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-03PROC. REF: AMM 25-20-03								
252027	LEFT LOWER DIFFUSER							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-03PROC. REF: AMM 25-20-03								
252100 ^{U S}	GENERAL VISUAL INSPECTION OF THE PASSENGER SEAT RESTRAINTS							Service ATA:25
	MOS	08-Nov-22					SMM	
	HRS	1247	300					
	AFL	971						
PKG:5								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
253000	U S	GENERAL VISUAL INSPECTION OF THE GALLEY						Service ATA:25
	MOS	25-Jan-22						SMM
	HRS	1207.3	600					
	AFL	939						
PKG:6								
253001	U S	GENERAL VISUAL INSPECTION OF THE WARMING OVEN						Service ATA:25
	MOS							SMM
	HRS		4800					
	AFL							
PKG:7								
253007		LEFT FORWARD COLD CATHODE LAMP INVERTER						Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253009		LEFT FORWARD COLD CATHODE LAMP INVERTER						Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253010		RIGHT FORWARD COLD CATHODE LAMP INVERTER						Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253012		RIGHT FORWARD COLD CATHODE LAMP INVERTER						Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
253052		VOLTAGE REGULATOR					Component	ATA:25
PN:106090-2	MOS/MSC	12-Feb-08	O/C					
SN:4660706	HRS	223.7						
	AFL	152						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253053 ^U		RH FWD CABIN POWER CONTROLLER					Component	ATA:25
PN:106090-2	MOS/MSC	12-Feb-08	O/C					
SN:4600706	HRS	223.7						
	AFL	152						
253068		WARMER-LIQUID					Component	ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253068A ^{U S}		GENERAL VISUAL INSPECTION WARMER-LIQUID					Service	ATA:25
PN:PN	MOS	22-Aug-07					SMM	
SN:UNKNOWN	HRS	0	4800					
	AFL	0						
								PKG:7
253069		WARMER-LIQUID					Component	ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253069A ^{U S}		GENERAL VISUAL INSPECTION WARMER-LIQUID					Service	ATA:25
PN:PN	MOS	22-Aug-07					SMM	
SN:UNKNOWN	HRS	0	4800					
	AFL	0						
								PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
253090	AM/FM/CASSETTE STEREO							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
254000 ^{U S}	GENERAL VISUAL INSPECTION OF THE LAVATORY							Service ATA:25
	MOS	25-Jan-22					SMM	
	HRS	1207.3	600					
	AFL	939						
PKG:6								
255050B ^{U S}	CHECK MICROWAVE OVEN MICROWAVE OVEN AND BAROMETRIC SWITCH							Service ATA:25
PN:PN	MOS	05-Oct-14					SMM	
SN:UNKNOWN	HRS	578.5	600					
	AFL	480						
PKG:6								
255050C ^{U S}	GENERAL VISUAL INSPECTION MICROWAVE OVEN							Service ATA:25
PN:PN	MOS	22-Aug-07					SMM	
SN:UNKNOWN	HRS	0	4800					
	AFL	0						
PKG:7								
255055	MICROWAVE OVEN							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
255055A	ANNUAL INSPECTION MICROWAVE OVEN M100367ICT-SMM-1 (25-35-13)							Service ATA:25
PN:PN	MOS/MSC	18-Nov-11	N/A					
SN:NOT INSTALLED	HRS	512.2						
	AFL	415						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256001	(ELT) EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:453-5000-(366)	MOS/MSC	08-Nov-22	O/C	TSN 183				
SN:A00028	HRS	1247		TSN 1247, TSR 736.5				
	AFL	971		TSN 971, TSR 557				
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01								
256001A	INSPECT/FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:453-5000-(366)	MOS	12-Nov-24	12 (+14d/-14d)		01-Apr-25 (M)	15-Apr-25	27 d (+14)	
SN:A00028	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 25-62-00PROC. REF: AMM 25-62-00								
256001B	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - 05-11-00-L2564000							Service ATA:25
PN:452-0133	MOS	16-Sep-20	60 (+14d/-14d)		16-Sep-25	30-Sep-25	195 d (+14)	
SN:384725-015	HRS	1050.2						
	AFL	823						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256001D	REGISTRATION RENEWAL (ELT) EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:453-5000-(366)	MOS/MSC	03-Jan-20	N/A					
SN:A00028	HRS	995.5						
	AFL	778						
PROC. REF: GENERIC NO REF, CMM NOAA/SARSATPROC. REF: GENERIC NO REF, CMM NOAA/SARSAT								
256003	ELT CONTROLLER							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256010	ELT/NAV INTERFACE							Component ATA:25
PN:453-6500	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:05969	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256060	U S	DETAILED INSPECTION OF THE LIFE VESTS						Service ATA:25
	MOS	08-Nov-22					SMM	
	HRS	1247	300					
	AFL	971						
PKG:5								
256061	NO. 1 LIFE VEST						Component	ATA:25
PN:D21343-153	MOS/MSC	04-Nov-16	O/C	TSN 4				
SN:L3394566	HRS	733.8		TSN 0				
	AFL	566		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256061A	INSPECT NO. 1 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS						Service	ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394566	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256062	NO. 2 LIFE VEST						Component	ATA:25
PN:D21343-153	MOS/MSC	04-Nov-16	O/C	TSN 0				
SN:L3394567	HRS	733.8		TSN 0				
	AFL	566		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256062A	INSPECT NO. 2 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS						Service	ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394567	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256063	NO. 3 LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	04-Nov-16	O/C	TSN 0				
SN:L3394568	HRS	733.8		TSN 0				
	AFL	566		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256063A	INSPECT NO. 3 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394568	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256064	NO. 4 LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	04-Nov-16	O/C	TSN 0				
SN:L3394564	HRS	733.8		TSN 0				
	AFL	566		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256064A	INSPECT NO. 4 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394564	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256065	NO. 5 LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	04-Nov-16	O/C	TSN 0				
SN:L33945613	HRS	733.8		TSN 0				
	AFL	566		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256065A	INSPECT NO. 5 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L33945613	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256066	NO. 6 LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	04-Nov-16	O/C	TSN 0				
SN:L3394559	HRS	733.8		TSN 0				
	AFL	566		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256066A	INSPECT NO. 6 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394559	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256067	NO. 7 LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	04-Nov-16	O/C	TSN 0				
SN:L3394556	HRS	733.8		TSN 0				
	AFL	566		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256067A	INSPECT NO. 7 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394556	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256068 ^U	LAVATORY LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	11-Oct-21	O/C	TSN 59				
SN:L3394562	HRS	1173.5		TSN 439.7				
	AFL	920		TSN 354				
256068A ^U	INSPECT LAVATORY LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394562	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256069 ^S	NO. 9 LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	01-Sep-12	O/C	TSO 6				
SN:L963920	HRS	532.3		TSO 0				
	AFL	427		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256069A ^S	INSPECT NO. 9 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	23-Oct-17	60					
SN:L963920	HRS	781.7						
	AFL	608						
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256070 ^S	NO. 10 LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	01-Sep-12	O/C	TSO 6				
SN:L96313	HRS	532.3		TSO 0				
	AFL	427		TSO 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256070A ^S	INSPECT NO. 10 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	23-Oct-17	60					
SN:L96313	HRS	781.7						
	AFL	608						
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256071	PILOT LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	11-Oct-21	O/C	TSN 59				
SN:L3394565	HRS	1173.5		TSN 439.7				
	AFL	920		TSN 354				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256071A	INSPECT PILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394565	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00, CMM 25-60-05PROC. REF: AMM 25-61-00, CMM 25-60-05								
256072	COPILOT LIFE VEST							Component ATA:25
PN:D21343-153	MOS/MSC	11-Oct-21	O/C	TSN 59				
SN:L3394569	HRS	1173.5		TSN 439.7				
	AFL	920		TSN 354				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256072A	INSPECT COPILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
PN:D21343-153	MOS	11-Oct-21	60		11-Oct-26		585 d	
SN:L3394569	HRS							
	AFL							
OverHaul Date:: 11-Oct-21								
PROC. REF: AMM 25-61-00PROC. REF: AMM 25-61-00								
256076	FIRST AID KIT							Component ATA:25
PN:FL220-FAKFAA	MOS/MSC	07-Oct-23	O/C	TSN 0				
SN:0923-3468	HRS	1309.3		TSN 0				
	AFL	1026		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256076A	CONDITION CHECK FIRST AID KIT INVENTORY & EXPIRATION DATES							Service ATA:25
PN:FL220-FAKFAA	MOS	12-Nov-24	12		12-Nov-25		252 d	
SN:0923-3468	HRS	1375.9						
	AFL	1084						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256078	EMERGENCY MEDICAL KIT							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256078A	INSPECT EMERGENCY MEDICAL KIT CONTENTS							Service ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256116	ELT REMOTE SWITCH PANEL							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256202	ELT ANTENNA							Component ATA:25
PN:110-337	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:129371	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02PROC. REF: AMM 25-62-02								
256410	(ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY							Component ATA:25
PN:452-0133	MOS/MSC	16-Sep-20	O/C					
SN:384725-015	HRS	1050.2						
	AFL	823						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
257101	NOSE AVIONICS EXHAUST BLOWER							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: AMM 25-71-01PROC. REF: AMM 25-71-01								
258010	AIRSHOW DIGITAL INTERFACE UNIT							Component ATA:25
PN:920055	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:G01001406	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258011	COCKPIT CONTROL - AIRSHOW UNIT							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258012	AIRSHOW FLIGHT DECK CONTROLLER							Component ATA:25
PN:922000-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:H01000924	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258014	FORWARD AIRSHOW COLOR MONITOR-							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258015	AFT AIRSHOW COLOR MONITOR-							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258016	FORWARD 10.4 LCD COLOR, AIRSHOW 400 DISPLAY							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258017	AFT 10.4 LCD COLOR, AIRSHOW 400 DISPLAY							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
258020	AIRSHOW 400 VIDEO SWITCH PANEL							Component ATA:25
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E2510010 ^S	INSPECT CREW SEATS AND SEAT BELTS FOR OPERATION, SECURITY OF MOUNTING, AND GENERAL CONDITION							Service ATA:25
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
N2571002 ^S	PERFORM FUNCTIONAL TEST OF NOSE AVIONICS COMPARTMENT EXHAUST BLOWERS AND THEIR RESPECTIVE CONTROL TEMPERATURE SWITCHES. (REFER TO 25-71-01.)							Service ATA:25
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 25-71-01PROC. REF: AMM 25-71-01								PKG:14
P2520007 ^S	INSPECT CABIN SEATS AND SEAT BELTS FOR CONDITION; BAGGAGE COMPARTMENT, STOWAGE CABINETS, STOWAGE CABINET LATCHES, RUGS, HEADLINER, AND SIDE PANELS FOR SECURITY AND CONDITION.							Service ATA:25
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
U2510005 ^S	GENERAL VISUAL INSPECTION GLARESHIELD, HEADLINER, AND TRIM STRIPS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00)							Service ATA:25
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
U2540004 ^S	INSPECT ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.							Service ATA:25
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
ATA 26 - FIRE PROTECTION								
261001	NO. 1 FIRE DETECTION CONTROL UNIT							Component ATA:26
PN:377-02833	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0729-258	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								
261002	NO. 2 FIRE DETECTION CONTROL UNIT							Component ATA:26
PN:377-02833	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0729-263	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								
261006	TAILCONE BLEED AIR OVERHEAT (E267) CONTROL BOX							Component ATA:26
PN:35009-20	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D3624	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261007	TAILCONE BLEED AIR OVERHEAT (E268) CONTROL BOX							Component ATA:26
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02								
261051	NO. 1 TEE DOUBLE CHECK VALVE							Component ATA:26
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05								
261052	NO. 2 TEE DOUBLE CHECK VALVE							Component ATA:26
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05								
261207	BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY							Component ATA:26
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01								
262013	FORWARD FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:32700004-1	MOS/MSC	08-Nov-22	O/C	TSO 74				
SN:25982C1	HRS	1247		TSO 513.2				
	AFL	971		TSO 405				
PROC. REF: AMM 26-21-03PROC. REF: AMM 26-21-03								
262013A	CHECK FORWARD FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY (REF TO 05-10-00)							Service ATA:26
PN:32700004-1	MOS	12-Nov-24	6 (+14d/-14d)	Adj -44d	29-Mar-25	12-Apr-25	24 d (+14)	
SN:25982C1	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262013C	HYDROSTATIC TEST FORWARD FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:32700004-1	MOS		60 (+14d/-14d)		01-Oct-26 (M)	15-Oct-26	575 d (+14)	
SN:25982C1	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262014	AFT FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:32700004-1	MOS/MSC	08-Nov-22	O/C	TSO 74				
SN:26008C1	HRS	1247		TSO 513.2				
	AFL	971		TSO 405				
PROC. REF: AMM 26-21-03PROC. REF: AMM 26-21-03								
262014A	CHECK AFT FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 05-10-00)							Service ATA:26
PN:32700004-1	MOS	12-Nov-24	6 (+14d/-14d)	Adj -44d	29-Mar-25	12-Apr-25	24 d (+14)	
SN:26008C1	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								
262014C	HYDROSTATIC TEST AFT FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:32700004-1	MOS		60 (+14d/-14d)		01-Oct-26 (M)	15-Oct-26	575 d (+14)	
SN:26008C1	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262036	FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Component ATA:26
PN:AE30903823	MOS	08-Nov-22	72 (+14d/-14d)	TSN 0	08-Nov-28	22-Nov-28	1344 d (+14)	SERVICE LIFE LIMIT
SN:NSN	HRS	1247		TSN 0				
	AFL	971		TSN 0				
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04								
262036A	REPLACE FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Service ATA:26
PN:AE30903823	MOS	08-Nov-22	108 (+14d/-14d)		08-Nov-31	22-Nov-31	2439 d (+14)	LIFE LIMIT
SN:NSN	HRS	1247						
	AFL	971						
Manufacture Date:: 08-Nov-22								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262037	AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Component	ATA:26
PN:AE30903823	MOS	11-Oct-21	72 (+14d/-14d)	TSN 6	11-Apr-27	25-Apr-27	767 d (+14)	SERVICE LIFE LIMIT	
SN:919	HRS	1173.5		TSN 0					
	AFL	920		TSN 0					
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262037A	REPLACE AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB							Service	ATA:26
PN:AE30903823	MOS	01-Apr-21	108 (+14d/-14d)		01-Apr-30	15-Apr-30	1853 d (+14)	LIFE LIMIT	
SN:919	HRS								
	AFL								
		Manufacture Date:: 01-Apr-21							
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262038	FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB							Component	ATA:26
PN:AE30903823	MOS	08-Nov-22	72 (+14d/-14d)	TSN 0	08-Nov-28	22-Nov-28	1344 d (+14)	SERVICE LIFE LIMIT	
SN:NSN	HRS	1247		TSN 0					
	AFL	971		TSN 0					
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262038A	REPLACE FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB							Service	ATA:26
PN:AE30903823	MOS	08-Nov-22	108 (+14d/-14d)		08-Nov-31	22-Nov-31	2439 d (+14)	LIFE LIMIT	
SN:NSN	HRS	1247							
	AFL	971							
		Manufacture Date:: 08-Nov-22							
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262039	AFT ENGINE FIRE EXTINGUISHER AFT SQUIB							Component	ATA:26
PN:AE30903823	MOS	11-Oct-21	72 (+14d/-14d)	TSN 6	11-Apr-27	25-Apr-27	767 d (+14)	SERVICE LIFE LIMIT	
SN:917	HRS	1173.5		TSN 0					
	AFL	920		TSN 0					
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
262039A	REPLACE AFT ENGINE FIRE EXTINGUISHER AFT SQUIB							Service	ATA:26
PN:AE30903823	MOS	01-Apr-21	108 (+14d/-14d)		01-Apr-30	15-Apr-30	1853 d (+14)	LIFE LIMIT	
SN:917	HRS								
	AFL								
		Manufacture Date:: 01-Apr-21							
PROC. REF: AMM 26-21-04PROC. REF: AMM 26-21-04									
262041	PILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:A344	MOS/MSC	13-Feb-25	O/C						
SN:37228711	HRS	1385		TSN 0					
	AFL	1094		TSN 0					
		Manufacture Date:: 01-Aug-24							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service	ATA:26
PN:A344	MOS	13-Feb-25	144 (+14d/-14d)		01-Aug-36	15-Aug-36	4167 d (+14)		
SN:37228711	HRS	1385							
	AFL	1094							
		HydroCheck Date: : 01-Aug-24							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262042	COPILOT PORTABLE FIRE EXTINGUISHER							Component	ATA:26
PN:A344	MOS/MSC	13-Feb-25	O/C						
SN:37228710	HRS	1385		TSN 0					
	AFL	1094		TSN 0					
		Manufacture Date:: 01-Aug-24							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262042B	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service	ATA:26
PN:A344	MOS	13-Feb-25	144 (+14d/-14d)		01-Aug-36	15-Aug-36	4167 d (+14)		
SN:37228710	HRS	1385							
	AFL	1094							
		HydroCheck Date: : 01-Aug-24							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262045	NO. 1 ENGINE FIRE - PULL SWITCH							Component ATA:26
PN:865201-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:768	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01								
262046	NO. 2 ENGINE FIRE - PULL SWITCH							Component ATA:26
PN:865201-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:772	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01								
262050	APU FIRE EXTINGUISHER							Component ATA:26
PN:50-1200	MOS/MSC	15-Apr-19	O/C	TSN 12				
SN:18-1011	HRS	940.3		TSN 0				
	AFL	730		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-61-01PROC. REF: GENERIC NO REF, SMM 49-61-01								
262050C	INSPECT APU FIRE EXTINGUISHER WEIGHT CHECK AND REPLACE AS NECESSARY							Service ATA:26
PN:50-1200	MOS	19-Apr-24	12		19-Apr-25		45 d	
SN:18-1011	HRS	1336.5						
	AFL	1050						
WeightCheck Date : : 19-Apr-24								
PROC. REF: GENERIC NO REF, SMM 49-11-03PROC. REF: GENERIC NO REF, SMM 49-11-03								
262050D	CONTINUITY CHECK APU FIRE EXTINGUISHER PRESSURE SWITCH IAW SAFECRAFT CMM 26-20-02							Service ATA:26
PN:50-1200	MOS	18-Apr-24	12		18-Apr-25		44 d	
SN:18-1011	HRS	1336.5						
	AFL	1050						
PROC. REF: GENERIC NO REF, CMM 26-20-02PROC. REF: GENERIC NO REF, CMM 26-20-02								
262051	CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:352TS	MOS/MSC	10-May-17	O/C	TSN 0				
SN:B-00097981	HRS	734.6		TSN 0				
	AFL	567		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262051B	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030							Service ATA:26
PN:352TS	MOS	10-May-17	144 (+14d/-14d)		10-May-29	24-May-29	1527 d (+14)	
SN:B-00097981	HRS							
	AFL							
HydroCheck Date: : 10-May-17								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262057	APU FIRE BOTTLE SQUIB							Component ATA:26
PN:30900000M	MOS	15-Apr-19	60	TSN 20	01-Aug-27 (M)		879 d	LIFE LIMIT
SN:UNKNOWN	HRS	940.3		TSN 0				
	AFL	730		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-61-04, SMM 49-11-03PROC. REF: GENERIC NO REF, SMM 49-61-04, SMM 49-11-03								
H2610010 ^S	INSPECT FIREWALL AND ACCESSORY GEARBOX FIRE DETECTOR ELEMENTS FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION.							Service ATA:26
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PKG:9								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H2620020 ^S	DISCONNECT PLUMBING FROM THE FIRE EXTINGUISHER TWO-WAY CHECK VALVE ASSEMBLY. INSPECT FOR FREEDOM OF MOVEMENT OF THE TWO-WAY CHECK VALVE, EVIDENCE OF DEFECTS, WEAR, AND CORROSION. REPLACE VALVE CAP O-RING. (REFER TO 26-21-05.)							Service ATA:26
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PKG:21								
PROC. REF: AMM 26-21-05PROC. REF: AMM 26-21-05								
P2620041 ^S	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.							Service ATA:26
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PKG:2								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
Q2620010 ^S	PERFORM WEIGHT CHECK OF FIRE EXTINGUISHER CONTAINERS. AFTER INSTALLATION OF CONTAINERS, PERFORM FUNCTIONAL TEST OF ENGINE FIRE EXTINGUISHER SYSTEM. (REFER TO 26-21-00).							Service ATA:26
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								PKG:9
T2614000 ^S	PERFORM FUNCTIONAL TEST OF BAGGAGE COMPARTMENT SMOKE DETECTOR SYSTEM. (REFER TO 26-12-00)							Service ATA:26
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 26-12-00PROC. REF: AMM 26-12-00								PKG:8
T2620045 ^S	INSPECT COPILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE							Service ATA:26
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
T2620045 ^S	INSPECT PILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.							Service ATA:26
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
U2610020A ^S	INSPECT NO. 1 ENGINE TAILCONE FIRE DETECTION ELEMENT							Service ATA:26
	MOS	22-Aug-07						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:29

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
U2610020B	^S	INSPECT NO. 2 ENGINE TAILCONE FIRE DETECTION ELEMENT						Service ATA:26
	MOS	22-Aug-07						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:30

ATA 27 - FLIGHT CONTROLS								
05-10-29-H2750044L		PERFORM DETAILED INSPECTION OF THE LEFT FLAP CAM FOLLOWER BEARING						Service ATA:27
	MOS	14-Oct-19						
	HRS	976.1	1200 (+25/-25)		2176.1	2201.1	791.1 (+25)	
	AFL	766						
PROC. REF: AMM 5-10-00PROC. REF: AMM 5-10-00								

05-10-29-H2750044R		PERFORM DETAILED INSPECTION OF THE RIGHT FLAP CAM FOLLOWER BEARING						Service ATA:27
	MOS	14-Oct-19						
	HRS	976.1	1200 (+25/-25)		2176.1	2201.1	791.1 (+25)	
	AFL	766						
PROC. REF: AMM 5-10-00PROC. REF: AMM 5-10-00								

05-11-00-E2710010L		REPLACE LEFT * AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)						Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	3600		3600		2215	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

05-11-00-E2710010R		REPLACE RIGHT * AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)						Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	3600		3600		2215	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

05-11-00-E2710013L		* REPLACE LEFT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)						Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	3600		3600		2215	
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710013R	* REPLACE RIGHT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	3600		3600		2215	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710020L	REPLACE LEFT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710020R	REPLACE RIGHT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710022L	* REPLACE LEFT AILERON SECTOR (5425105) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-10PROC. REF: AMM 27-10-10								
05-11-00-E2710022R	* REPLACE RIGHT AILERON SECTOR (5425105) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-10PROC. REF: AMM 27-10-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2710024L	* REPLACE LEFT AILERON CLEVIS (2324517) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710024R	* REPLACE RIGHT AILERON CLEVIS (2324517) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710026L	REPLACE LEFT * AILERON YOKE ASSEMBLY (2324511) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710026R	REPLACE RIGHT * AILERON YOKE ASSEMBLY (2324511) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710028L	REPLACE LEFT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-E2710028R	REPLACE RIGHT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2710031L	REPLACE LEFT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2710031R	REPLACE RIGHT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2720020	REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P5) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								
05-11-00-E2720022	REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-20-09PROC. REF: AMM 27-20-09								
05-11-00-E2720026	REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2730021L	REPLACE LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2730021R	REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
05-11-00-E2730022L	REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
05-11-00-E2730022R	REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
05-11-00-E2730024L	REPLACE LEFT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2730024R	REPLACE RIGHT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-E2740010	REPLACE * HORIZONTAL STABILIZER HINGE PIN (2331028) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2750002L	REPLACE LEFT FLAP NOSE ROLLER BUSHINGS (NAS76A4)							Service ATA:27
	MOS	16-Sep-20						
	HRS	1050.2	1200 (+25/-25)		2250.2	2275.2	865.2 (+25)	
	AFL	823						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-E2750002R	REPLACE RIGHT FLAP NOSE ROLLER BUSHINGS (NAS76A4)							Service ATA:27
	MOS	16-Sep-20						
	HRS	1050.2	1200 (+25/-25)		2250.2	2275.2	865.2 (+25)	
	AFL	823						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-E2750035L	REPLACE LEFT * FLAP SECTOR (2625031) (AWL*)							Service ATA:27
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-E2750035R	REPLACE RIGHT * FLAP SECTOR (2625031) (AWL*)							Service ATA:27
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-E2760059L	REPLACE LEFT * SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
05-11-00-E2760059R	REPLACE RIGHT * SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2760061L	REPLACE LEFT * SPOILER ACTUATOR ARM (2422511) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760061R	REPLACE RIGHT * SPOILER ACTUATOR ARM (2422511) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760062L	REPLACE LEFT * SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760062R	REPLACE RIGHT * SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760063L	REPLACE LEFT * SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760063R	REPLACE RIGHT * SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-E2760064LI	REPLACE LEFT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760064LO	REPLACE LEFT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760064RI	REPLACE RIGHT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-E2760064RO	REPLACE RIGHT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	4500		4500		3115	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
05-11-00-F2710036	REPLACE * PRIMARY AILERON CONTROL CABLES (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	2400		2400		1015	
	AFL	0						
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07								
05-11-00-F2720029	REPLACE PRIMARY RUDDER CONTROL CABLES							Service ATA:27
	MOS	22-Aug-07						
	HRS	0	2400 (+25/-25)		2400	2425	1015 (+25)	
	AFL	0						
PROC. REF: AMM 27-20-10PROC. REF: AMM 27-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-F2730030	REPLACE * PRIMARY ELEVATOR CONTROL SYSTEM CABLES (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	2400		2400		1015	
	AFL	0						
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05								
05-11-00-G2740011	REPLACE * HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS (NAS464P6) (AWL*)							Service ATA:27
	MOS	14-Oct-19	144		14-Oct-31		2414 d	LIFE LIMIT
	HRS	976.1						
	AFL	766	6000		6766		5672	
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								
05-11-00-G2750034L	REPLACE LEFT WING FLAP SECTOR MOUNTING BOLT							Service ATA:27
	MOS	14-Oct-19	144 (+14d/-14d)		14-Oct-31	28-Oct-31	2414 d (+14)	
	HRS	976.1						
	AFL	766	6000 (+25/-25)		6766	6791	5672 (+25)	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-G2750034R	REPLACE RIGHT WING FLAP SECTOR MOUNTING BOLT							Service ATA:27
	MOS	14-Oct-19	144 (+14d/-14d)		14-Oct-31	28-Oct-31	2414 d (+14)	
	HRS	976.1						
	AFL	766	6000 (+25/-25)		6766	6791	5672 (+25)	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750027LI	REPLACE LEFT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750027LO	REPLACE LEFT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-L2750027RI	REPLACE RIGHT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750027RO	REPLACE RIGHT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750028	REPLACE * INBOARD NOSE ROLLER TRACK (2322511) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750029	REPLACE * OUTBOARD NOSE ROLLER TRACK (2322512) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750033L	REPLACE LEFT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	10000		10000		8906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-L2750033R	REPLACE RIGHT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	10000		10000		8906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-M2710021LI	REPLACE LEFT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-M2710021LO	REPLACE LEFT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-M2710021RI	REPLACE RIGHT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-M2710021RO	REPLACE RIGHT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
05-11-00-M2730031	REPLACE * HINGE ASSEMBLIES (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 INBOARD)(LOCATED ON HORIZONTAL STABILIZER ASSEMBLY) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
05-11-00-M2750049LI	REPLACE LEFT INBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-M2750049LO	REPLACE LEFT OUTBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-M2750049RI	REPLACE RIGHT INBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-M2750049RO	REPLACE RIGHT OUTBOARD * FLAP SUPPORT FITTING (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750025	REPLACE * INBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625023) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750026	REPLACE * OUTBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625024) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750031	REPLACE * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-1 THRU-8) (AWL*)							Service ATA:27
	MOS/MSC	22-Aug-07	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-N2750032	REPLACE * UPPER FLAP SECTOR BRACKET ASSEMBLY (6022511-1, -2, -801, AND -802) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	3000		3000		1906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750051	REPLACE * INBOARD FLAP HINGE FITTING (P/N 6025022) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-N2750052	REPLACE * OUTBOARD FLAP HINGE FITTING (P/N 6025021) (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-R2750050L	REPLACE LEFT UPPER * UPPER FLAP SECTOR BRACKET (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-R2750050R	REPLACE RIGHT UPPER * UPPER FLAP SECTOR BRACKET (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
05-11-00-R2760079L	REPLACE LEFT LEFT * SPOILER ACTUATOR ATTACH FITTING AND BOLT (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	10000		10000		8615	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
05-11-00-R2760079R	REPLACE RIGHT RIGHT * SPOILER ACTUATOR ATTACH FITTING AND BOLT (AWL*)							Service ATA:27
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	10000		10000		8615	
	AFL	0						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
27-51-06-082	LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-51-06-082	LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-51-06-082	RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-51-06-082	RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
27-51-06-085	LEFT FLAP LEADING EDGE RIB							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-06-085	RIGHT FLAP LEADING EDGE RIB							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
270505	TRIM SWITCH PANEL ASSEMBLY							Component ATA:27
PN:6027080002-005	MOS/MSC	13-May-11	O/C					
SN:CRT003999-01	HRS	512.2						
	AFL	415						
PROC. REF: AMM 27-00-01PROC. REF: AMM 27-00-01								
271013	AILERON TRIM TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								
271015	LEFT AILERON BALANCE TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-03PROC. REF: AMM 27-10-03								
271016	RIGHT AILERON BALANCE TAB ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-03PROC. REF: AMM 27-10-03								
271019	AILERON TRIM ACTUATOR							Component ATA:27
PN:2R6203B	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:B0180	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-11PROC. REF: AMM 27-10-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271025 PILOT CONTROL WHEEL								Component ATA:27
PN:2415151-017	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2782	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-01PROC. REF: AMM 27-10-01								
271026 COPILOT CONTROL WHEEL								Component ATA:27
PN:2415151-018	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2613	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-01PROC. REF: AMM 27-10-01								
271027 PILOT CONTROL COLUMN								Component ATA:27
PN:5415150-025-625	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:A00766551	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-06PROC. REF: AMM 27-30-06								
271028 COPILOT CONTROL COLUMN								Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-06PROC. REF: AMM 27-30-06								
271031 AILERON TRIM TAB ACTUATOR POTENTIOMETER								Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-12PROC. REF: AMM 27-10-12								
271126 AILERON TRIM POSITION INDICATOR								Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271131	LEFT AILERON POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80473	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-06PROC. REF: AMM 27-10-06								
271132	RIGHT AILERON POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80471	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-06PROC. REF: AMM 27-10-06								
271701	* LEFT AILERON ASSEMBLY (AWL*)							Component ATA:27
PN:2424000-313	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:W777	HRS	0	20000	TSN 0	20000		18615	
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
271702	* RIGHT AILERON ASSEMBLY (AWL*)							Component ATA:27
PN:2424000-314	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:W746	HRS	0	20000	TSN 0	20000		18615	
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
272001	* RUDDER ASSEMBLY (AWL*)							Component ATA:27
PN:5433000-20	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:W545	HRS	0	20000	TSN 0	20000		18615	
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								
272005	AFT RUDDER SECTOR							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-09PROC. REF: AMM 27-20-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272007	RUDDER TRIM TAB							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-02PROC. REF: AMM 27-20-02								
272013	RUDDER TRIM TAB ACTUATOR							Component ATA:27
PN:2R6204B	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:B0133	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03								
272020	RUDDER TRIM TAB POTENTIOMETER							Component ATA:27
PN:P30LS0GJS102KAG222	MOS/MSC	10-May-17	O/C	TSN 21				
SN:UNKNOWN	HRS	734.6		TSN 0				
	AFL	567		TSN 0				
PROC. REF: AMM 27-20-04PROC. REF: AMM 27-20-04								
272026	RUDDER TRIM INDICATOR							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-06PROC. REF: AMM 27-20-06								
272031	PILOT RUDDER PEDAL ACTUATOR							Component ATA:27
PN:EM423-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:817	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-07PROC. REF: AMM 27-20-07								
272032	COPILOT RUDDER PEDAL ACTUATOR							Component ATA:27
PN:EM423-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:822	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-07PROC. REF: AMM 27-20-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273001	* LEFT ELEVATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2434000-177	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:W735	HRS	0	20000	TSN 0	20000		18615	
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
273002	* RIGHT ELEVATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2434000-178	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:W755	HRS	0	20000	TSN 0	20000		18615	
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
2730036	ELEVATOR BELLCRANKS - PERFORM EDDY CURRENT INSPECTION							Service ATA:27
	MOS	29-Sep-21	96		29-Sep-29		1669 d	
	HRS	1173.5	2400		3573.5		2188.5	
	AFL	920						
PROC. REF: NDT 27-30-01PROC. REF: NDT 27-30-01								
273013	STALL WARNING COMPUTER							Component ATA:27
PN:54301-3L MOD A	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:GST02906	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02								
273017	PILOT STICK SHAKER							Component ATA:27
PN:20-7	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1039A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03								
273018	COPILOT STICK SHAKER							Component ATA:27
PN:20-7	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1030A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273101	PILOT STALL WARNING TRANSDUCER							Component ATA:27
PN:25147A-12	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:GST05853	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01								
273102	COPILOT STALL WARNING TRANSDUCER							Component ATA:27
PN:6608263-19	MOS/MSC	29-Jul-08	O/C					
SN:1012	HRS	383.4						
	AFL	298						
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01								
273105	PILOT ANGLE-OF-ATTACK (AOA) INDICATOR							Component ATA:27
PN:N617-9025	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06097782	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04								
273106	COPILOT ANGLE-OF-ATTACK (AOA) INDICATOR							Component ATA:27
PN:N617-9025	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06097781	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04								
273110	ANGLE-OF-ATTACK (AOA) VANE							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-05PROC. REF: AMM 27-31-05								
274001	HORIZONTAL STABILIZER							Component ATA:27
PN:2332000-60	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:W429	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
274003	HORIZONTAL STABILIZER ACTUATOR CONTROLLER							Component ATA:27
PN:EM2079-9	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1307A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-03PROC. REF: AMM 27-40-03								
274010	TRIM-IN-MOTION DETECTOR							Component ATA:27
PN:231-1-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:206360188	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01								
274013	HORIZONTAL STABILIZER ACTUATOR							Component ATA:27
PN:5435005-028	MOS	16-Sep-20		TSO 0				OVERHAUL
SN:371	HRS	1050.2	600 (+25/-25)	TSO 0	1650.2	1675.2	265.2 (+25)	
	AFL	823		TSO 0				
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								
274062	PITCH TRIM INDICATOR							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04								
274070	STABILIZER POSITION SWITCH							Component ATA:27
PN:CS402-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10822	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-06PROC. REF: AMM 27-40-06								
274072	STABILIZER POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80339	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275001	* LEFT FLAP ASSEMBLY (AWL*)							Component ATA:27
PN:6025010-035	MOS	14-Oct-19		TSN 146				LIFE LIMIT
SN:W1541	HRS	976.1		TSN 976.1				
	AFL	766	10000	TSN 766	10000		8906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
275002	* RIGHT FLAP ASSEMBLY (AWL*)							Component ATA:27
PN:6025010-036	MOS	14-Oct-19		TSN 146				LIFE LIMIT
SN:W1533	HRS	976.1		TSN 976.1				
	AFL	766	10000	TSN 766	10000		8906	
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
275005	LEFT LOWER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275005	LEFT UPPER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275005	RIGHT LOWER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275005	RIGHT UPPER FLAP SECTOR BRACKET							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
2750058	* LEFT FLAP LEADING EDGE RIB - REPLACE (AWL*)							Service ATA:27
	MOS/MSC	22-Aug-07	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	22-Aug-07	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	22-Aug-07	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* RIGHT FLAP LEADING EDGE RIB - REPLACE (AWL*)							Service ATA:27
	MOS/MSC	22-Aug-07	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	22-Aug-07	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
2750058	* RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)							Service ATA:27
PN:PN	MOS/MSC	22-Aug-07	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275010	FLAP & ENGINE SYNCHRONIZER RELAY BOX ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275012	FLAP POSITION POTENTIOMETER							Component ATA:27
PN:RV4NAYSD102A	MOS/MSC	07-Oct-23	O/C	TSN 0				
SN:UNKNOWN	HRS	1309.3		TSN 0				
	AFL	1026		TSN 0				
PROC. REF: AMM 27-50-09PROC. REF: AMM 27-50-09								
275019	LEFT LIMIT, INBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:CS402-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10757	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05								
275020	RIGHT LIMIT, INBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:CS402-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10715	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05								
275021	LEFT POSITION, OUTBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:CS402-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10743	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-04PROC. REF: AMM 27-50-04								
275022	RIGHT POSITION, OUTBOARD FLAP/STABILIZER SWITCH							Component ATA:27
PN:CS402-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10759	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-04PROC. REF: AMM 27-50-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275031 FLAP CONTROL (FLAP/SPOILER) VALVE								Component ATA:27
PN:65770	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1161	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07								
275036 FLAP RESTRICTOR VALVE								Component ATA:27
PN:2R1047-0312	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2259	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275037 LEFT FLAP ACTUATOR								Component ATA:27
PN:6600493-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0554	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08								
275038 RIGHT FLAP ACTUATOR								Component ATA:27
PN:6600493-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0555	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08								
275200 FLAP POSITION INDICATOR								Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-10PROC. REF: AMM 27-50-10								
275213 FLAP PRESSURE RELIEF VALVE								Component ATA:27
PN:AN6245A4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:19087	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-13PROC. REF: AMM 27-50-13								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275217	FLAP ACTUATION CHECK VALVE							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-12PROC. REF: AMM 27-50-12								
276001	* LEFT SPOILER ASSEMBLY (AWL*)							Component ATA:27
PN:2422510-131	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:1935	HRS	0	4500	TSN 0	4500		3115	
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
276002	* RIGHT SPOILER ASSEMBLY (AWL*)							Component ATA:27
PN:2422510-130	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:W1959	HRS	0	4500	TSN 0	4500		3115	
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
276005	LEFT SPOILER FLOW CONTROL SERVO VALVE							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								
276006	RIGHT SPOILER FLOW CONTROL SERVO VALVE							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								
276010	SPOILER COMPUTER							Component ATA:27
PN:66008454-3	MOS/MSC	07-Oct-23	O/C	TSR 0				
SN:80072	HRS	1309.3		TSR 0				
	AFL	1026		TSR 0				
PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276013	* LEFT SPOILER ACTUATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2417015-5	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:2371	HRS	0	10000	TSN 0	10000		8615	
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
276014	* RIGHT SPOILER ACTUATOR ASSEMBLY (AWL*)							Component ATA:27
PN:2417015-5	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:2423	HRS	0	10000	TSN 0	10000		8615	
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
276037	LEFT SPOILER POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80469	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07								
276038	RIGHT SPOILER POSITION SENSOR							Component ATA:27
PN:501-1123-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80425	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07								
276043	SPOILER POTENTIOMETER							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09								
276049	SPOILER POSITION INDICATOR							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-10PROC. REF: AMM 27-60-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276128	SPOILER MANIFOLD VALVE							Component ATA:27
PN:2627023-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1148	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								
276265	WHEEL SPEED DETECTION BOX							Component ATA:27
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-12PROC. REF: AMM 27-60-12								
AB2700049 ^S	REMOVE ALL PANELS REQUIRED TO GAIN ACCESS TO CABLES, PULLEYS, SECTORS, AND ASSOCIATED EQUIPMENT. VISUALLY INSPECT ACCESSIBLE PORTIONS OF FLIGHT CONTROLS FOR PROPER CONDITION, CABLE CLEARANCE, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO FLIGHT CONTROL CABLE CLEARANCES AT FUEL CROSSOVER TUBES.							Service ATA:27
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
B2760050 ^S	PERFORM FUNCTIONAL TEST OF SPOILER (UP LIMIT) SWITCH. (REFER TO 27-60-05.)							Service ATA:27
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05								PKG:28
C2700011 ^S	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.							Service ATA:27
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
C2700013	^S	WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (FLAPS, AILERONS, AND SPOILERS), INSPECT ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE						Service ATA:27
	MOS	14-Oct-19	144	(+14d/-14d)				
	HRS	976.1						
	AFL	766	6000	(+25/-25)				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
C2700019	^S	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						Service ATA:27
	MOS	14-Oct-19	144	(+14d/-14d)				
	HRS	976.1						
	AFL	766	6000	(+25/-25)				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
C2700020	^S	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						Service ATA:27
	MOS	14-Oct-19	144	(+14d/-14d)				
	HRS	976.1						
	AFL	766	6000	(+25/-25)				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
C2700022	^S	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						Service ATA:27
	MOS	14-Oct-19	144	(+14d/-14d)				
	HRS	976.1						
	AFL	766	6000	(+25/-25)				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
C2700023	^S	WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (RUDDER AND ELEVATORS), INSPECT ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERF						Service ATA:27
	MOS	14-Oct-19	144	(+14d/-14d)				
	HRS	976.1						
	AFL	766	6000	(+25/-25)				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
E2700031	^S	CHECK ELEVATOR AND RUDDER CONTROL CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEY, PULLEY BRACKETS, AND GUARDS FOR SECURITY AND GENERAL CONDITION.						Service ATA:27
	MOS	12-Nov-24	24	(+14d/-14d)				
	HRS	1375.9	600	(+25/-25)				
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
E2700032	^S	INSPECT CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION.						Service ATA:27
	MOS	12-Nov-24	24	(+14d/-14d)				
	HRS	1375.9	600	(+25/-25)				
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
E2710005	^S	HOLD CONTROL WHEEL INA FIXED POSITION AND APPLY UP AND DOWN LOADS ON THE AILERON TRAILING EDGE. OBSERVE AILERON DRIVE ASSEMBLY AREA FOR WEAR IN SHAFT KEYWAYS, FAILURE OF BEARINGS, AND AILERON YOKE SLIPPAGE.						Service ATA:27
	MOS	07-Oct-23	48	(+14d/-14d)				
	HRS	1309.3	1200	(+25/-25)				
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16
E2730025	^S	INSPECT CONTROL COLUMNS (INCLUDING CONTROL WHEELS AND BOOTS) FOR CONDITION, PROPER OPERATION, AND CLEARANCES.						Service ATA:27
	MOS	12-Nov-24	12	(+14d/-14d)				
	HRS	1375.9	300	(+25/-25)				
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
F2740020	^S	REMOVE STABILIZER ACTUATOR. INSPECT UPPER AND LOWER ATTACHMENT STRUCTURE FOR FATIGUE CRACKS, DISTORTION, WEAR, CORROSION, AND GENERAL SECURITY.						Service ATA:27
	MOS	14-Oct-19	144	(+14d/-14d)				
	HRS	976.1						
	AFL	766	6000	(+25/-25)				
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								PKG:27
H2700018	^S	VISUALLY INSPECT SPOILER, FLAP, AILERON, AND AILERON TRIM TAB ELECTRICAL BONDING JMPERS FRO SECURITY AND GENERAL CONDITION.						Service ATA:27
	MOS	12-Nov-24	24	(+14d/-14d)				
	HRS	1375.9	600	(+25/-25)				
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:10
H2700021	^S	INSPECT THE RUDDER AND ELEVATOR BALANCE WEIGHT INSTALLATIONS AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUC						Service ATA:27
	MOS	07-Oct-23	48	(+14d/-14d)				
	HRS	1309.3	1200	(+25/-25)				
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
H2700024	^S	INSPECT THE AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUCTURE.						Service ATA:27
	MOS	07-Oct-23	48	(+14d/-14d)				
	HRS	1309.3	1200	(+25/-25)				
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
H2710032	^S	CHECK AILERON, RUDDER, AND ELEVATOR CONTROL SYSTEM CABLE TENSIONS. (REFER TO 27-10-00, 27-20-00 AND 27-30-00.)					Service	ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-10-00, AMM 27-20-00, AMM 27-30-00PROC. REF: AMM 27-10-00, AMM 27-20-00, AMM 27-30-00								PKG:14
H2731000	^S	PERFORM STALL WARNING SYSTEM FUNCTIONAL TEST. (REFER TO 27-31-00)					Service	ATA:27
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 27-31-00PROC. REF: AMM 27-31-00								PKG:7
P2700050	^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.					Service	ATA:27
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
P2700055	^S	VISUALLY INSPECT ELEVATOR, RUDDER, AND RUDDER TRIM TAB ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION.					Service	ATA:27
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
P2700057	^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.					Service	ATA:27
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
P2710044	^S	CHECK AILERON AND FLAP SYSTEM CONTROL CABLE TENSIONS. (REFER TO 27-10-00 AND 27-50-00.)						Service ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-10-00, AMM 27-50-00PROC. REF: AMM 27-10-00, AMM 27-50-00								PKG:16
P2710045	^S	REMOVE CONTROL WHEEL SECTOR AND TURNBUCKLE COVERPLATE FROM CONTROL COLUMN. MOVE CONTROL WHEEL TO BOTH EXTREME RIGHT AND LEFT WHILE INSPECTING FOR FRAYED OR DAMAGED CABLES.						Service ATA:27
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
P2710046	^S	DISASSEMBLE CONTROL COLUMN AS REQUIRED TO INSPECT PULLEYS, BEARINGS, ELECTRICAL WIRING FOR PROPER ROUTING AND CHAFING, AND CONTROL COLUMNS FOR GENERAL CONDITION.						Service ATA:27
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:19
P2760003	^S	INSPECT SPOILER ACTUATOR INSTALLATION FOR SECURITY, SUPPORT STRUCTURE CRACKS, AND GENERAL CONDITION.						Service ATA:27
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:10
Q2700051	^S	INSPECT RUDDER AND ELEVATOR CONTROLS (INCLUDING DOWNSPRING INSTALLATION WHEN INSTALLED AND PUSH-PULL TUBES) FOR PROPER OPERATION, GENERAL CONDITION AND SECURITY.						Service ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2700017	^S	INSPECT STRUCTURE, PULLEY BRACKETS, AND CONTROLS UNDER FLOORBOARDS FROM PEDESTAL AND CONTROL COLUMN AFT TO FRAME 24 FOR OPERATION, CLEARANCES, CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO THE ELEVATOR PULLEY BRACKET CUTOUT AREA RADIUS FOR CRACKS. (S					Service	ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
T2700052	^S	USING THE PROPER COCKPIT CONTROLS, CHECK FLAPS, SPOILERS, HORIZONTAL STABILIZER, AND TRIM TABS FOR PROPER OPERATION AND ACCURATE INDICATION.					Service	ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-40-00, AMM 27-50-00, AMM 27-60-00PROC. REF: AMM 27-40-00, AMM 27-50-00, AMM 27-60-00								PKG:13
T2700056	^S	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.					Service	ATA:27
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
T2700058	^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.					Service	ATA:27
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
T2700059	^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.					Service	ATA:27
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2700060 ^S	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.							Service ATA:27
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:22
T2710042 ^S	INSPECT AILERON AND AILERON TABS AND DRIVE MECHANISM FOR SECURITY, OPERATION, AND GENERAL CONDITION.							Service ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								PKG:16
T2720027 ^S	INSPECT RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS FOR SECURITY, PROPER OPERATION, AND CLEARANCES.							Service ATA:27
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
T2730029 ^S	CHECK CONTROL COLUMN ASSEMBLY FREE PLAY. (REFER TO 27-30-06.)							Service ATA:27
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-30-06PROC. REF: AMM 27-30-06								PKG:20
T2731075 ^S	FUNCTIONAL TEST OF STALL WARNING ALTITUDE SWITCHES. (REFER TO 27-31-00.)							Service ATA:27
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-31-00PROC. REF: AMM 27-31-00								PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2760030 ^S	INSPECT SPOILER AND HINGE INSTALLATION FOR SECURITY, CRACKS, AND GENERAL CONDITION.							Service ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16
T2760031 ^S	INSPECT SPOILER CENTER ANGLE BRACKET RIVETS, LOWER SKIN CENTER RIB AND SUBSPAR RIVETS FOR EVIDENCE OF WORKING. WITH SPOILERS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO SPOILER TRAILING EDGE. CHECK MOTION AT CENTER HINGE. INSPECT SPOILER ACTUATOR MECHANISM AND							Service ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16
T2760040 ^S	FUNCTIONAL TEST OF SPOILER RESTRICTOR BYPASS VALVE COMPUTER CIRCUITRY AND WIRING. (REFER TO 27-60-03.)							Service ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								PKG:16
T2760084 ^S	VISUAL INSPECTION SPOILER CENTER ANGLE BRACKET RIVETS AND UPPER AND LOWER SKIN CENTER RIB AREA. (REFER TO 5-10-00.)							Service ATA:27
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4
U2700033 ^S	INSPECT ALL CABLES, PULLEYS, SECTORS, AND PULLEY GUARD FOR PROPER OPERATION AND GENERAL CONDITION. PARTICULAR ATTENTION SHOULD BE GIVEN TO THOSE AREAS OF CABLES THAT PASS OVER PULLEYS, SECTORS, OR THROUGH FAIRLEADS.							Service ATA:27
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
U2710006	^S	RUDDER TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK. (REFER TO 27-20-02.)						Service ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-20-02PROC. REF: AMM 27-20-02								PKG:18
U2710033	^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK.						Service ATA:27
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								PKG:16
U2710034	^S	GENERAL VISUAL INSPECTION AILERON TRIM TAB INSTALLATION. (REFER TO 5-10-00.)						Service ATA:27
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4
U2710035	^S	GENERAL VISUAL INSPECTION RUDDER TRIM TAB INSTALLATION. (REFER TO 5-10-00)						Service ATA:27
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:6
U2731050	^S	VISUAL INSPECTION ANGLE-OF-ATTACK VANES. (REFER TO 5-10-00)						Service ATA:27
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
W2700062 ^S	CHECK CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION. (REFER TO 5-10-00.)							Service ATA:27
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
ATA 28 - FUEL								
05-10-29-L2812002L	INSPECT LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602							Service ATA:28
	MOS	07-Oct-23	24 (+14d/-14d)	Adj 7d	14-Oct-25	28-Oct-25	223 d (+14)	
	HRS	1309.3						
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812002R	INSPECT RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602							Service ATA:28
	MOS	07-Oct-23	24 (+14d/-14d)	Adj 7d	14-Oct-25	28-Oct-25	223 d (+14)	
	HRS	1309.3						
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812010L	INSPECT LEFT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA							Service ATA:28
	MOS	07-Oct-23	24 (+14d/-14d)	Adj 7d	14-Oct-25	28-Oct-25	223 d (+14)	
	HRS	1309.3						
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812010R	INSPECT RIGHT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA							Service ATA:28
	MOS	07-Oct-23	24 (+14d/-14d)	Adj 7d	14-Oct-25	28-Oct-25	223 d (+14)	
	HRS	1309.3						
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
05-10-29-L2812020L	INSPECT LEFT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION							Service ATA:28
	MOS	07-Oct-23	24 (+14d/-14d)	Adj 7d	14-Oct-25	28-Oct-25	223 d (+14)	
	HRS	1309.3						
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-L2812020R	INSPECT RIGHT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION							Service ATA:28
	MOS	07-Oct-23	24 (+14d/-14d)	Adj 7d	14-Oct-25	28-Oct-25	223 d (+14)	
	HRS	1309.3						
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-10-29-T2820012	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS							Service ATA:28
	MOS/MSC	08-Apr-11	-					
	HRS	510.5						
	AFL	414						
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								
05-11-00-G2820003	REPLACE ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AIRCRAFT (PRESSURE)							Service ATA:28
	MOS/MSC	22-Aug-07	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: AMM 28-00-00PROC. REF: AMM 28-00-00								
280002	FUEL CONTROL SWITCH PANEL ASEMBLY							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-02PROC. REF: AMM 28-00-02								
280003	LEFT WING DEFUEL VALVE							Component ATA:28
PN:6022315V5-003	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0044	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-03PROC. REF: AMM 28-00-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
280004	RIGHT WING DEFUEL VALVE							Component ATA:28
PN:6022315V5-003	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0042	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-00-03PROC. REF: AMM 28-00-03								
281007	LEFT CHECK, CROSSFLOW VALVE							Component ATA:28
PN:7600004-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-0417206	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05PROC. REF: AMM 28-14-05								
281008	RIGHT CHECK, CROSSFLOW VALVE							Component ATA:28
PN:7600004-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-0417184	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05PROC. REF: AMM 28-14-05								
281201	AFT FUSELAGE FUEL CELL							Component ATA:28
PN:501847	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:104869	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281202	FORWARD FUSELAGE FUEL CELL							Component ATA:28
PN:501848	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:104884	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-02PROC. REF: AMM 28-12-02								
281283	FUSELAGE DRAIN VALVE							Component ATA:28
PN:50C-2L6	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281301	LEFT WING FUEL VENT FLOAT VALVE							Component ATA:28
PN:35C15G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4227	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01								
281302	RIGHT WING FUEL VENT FLOAT VALVE							Component ATA:28
PN:35C15G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4234	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01								
281303	FUSELAGE FUEL VENT FLOAT VALVE							Component ATA:28
PN:35C15G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4213	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-01PROC. REF: AMM 28-13-01								
281305	LEFT WING FLAME ARRESTOR							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-03PROC. REF: AMM 28-13-03								
281306	RIGHT WING FLAME ARRESTOR							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-03PROC. REF: AMM 28-13-03								
281307	LEFT FUEL CELL PRESSURE RELIEF VALVE							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-07PROC. REF: AMM 28-13-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281308	RIGHT FUEL CELL PRESSURE RELIEF VALVE							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-07PROC. REF: AMM 28-13-07								
281309	FUSELAGE FLAME ARRESTOR							Component ATA:28
PN:9909018-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:498	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-13-09PROC. REF: AMM 28-13-09								
281401	LEFT FUSELAGE CELL TRANSFER PUMP							Component ATA:28
PN:2380060-052	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:L4169	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-01PROC. REF: AMM 28-14-01								
281402	RIGHT FUSELAGE CELL TRANSFER PUMP							Component ATA:28
PN:2380060-052	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:L4170	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-01PROC. REF: AMM 28-14-01								
281403	LEFT INBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281404	RIGHT INBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281405	LEFT CENTER WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281406	RIGHT CENTER WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281407	LEFT OUTBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281408	RIGHT OUTBOARD WING SCAVENGE JET PUMP							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-02PROC. REF: AMM 28-14-02								
281409	LEFT SCAVENGE PUMP							Component ATA:28
PN:2380060-051	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:C4181	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-03PROC. REF: AMM 28-14-03								
281410	RIGHT SCAVENGE PUMP							Component ATA:28
PN:2380060-051	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:C4183	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-03PROC. REF: AMM 28-14-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281411		LEFT FUEL TRANSFER VALVE					Component	ATA:28
PN:EM91-119	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-081146	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-04PROC. REF: AMM 28-14-04								
281412		RIGHT FUEL TRANSFER VALVE					Component	ATA:28
PN:EM91-42	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-091634	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-04PROC. REF: AMM 28-14-04								
281413		CROSSFLOW VALVE					Component	ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-05PROC. REF: AMM 28-14-05								
281414		FUSELAGE HIGH-LEVEL FLOAT SWITCH					Component	ATA:28
PN:L14F-110	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:113	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-07PROC. REF: AMM 28-14-07								
281415		LEFT FUEL TRANSFER PRESSURE INDICATING SWITCH					Component	ATA:28
PN:7600002-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1373	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-06PROC. REF: AMM 28-14-06								
281416		RIGHT FUEL TRANSFER PRESSURE INDICATING SWITCH					Component	ATA:28
PN:7600002-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1362	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-06PROC. REF: AMM 28-14-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281417	LEFT WING HIGH-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-59	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:179	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-08PROC. REF: AMM 28-14-08								
281418	RIGHT WING HIGH-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-59	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:193	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-08PROC. REF: AMM 28-14-08								
281419	LEFT WING LOW-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-59	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:175	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-09PROC. REF: AMM 28-14-09								
281420	RIGHT WING LOW-LEVEL FLOAT SWITCH							Component ATA:28
PN:L15H-59	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:165	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-14-09PROC. REF: AMM 28-14-09								
281421	FUEL FILL AND TRANSFER BOX							Component ATA:28
PN:6018255-012	MOS/MSC	26-Mar-21	O/C					
SN:MRP531026-01	HRS	1109.9						
	AFL	869						
PROC. REF: AMM 28-14-10PROC. REF: AMM 28-14-10								
282001	LEFT INBOARD JET PUMP							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282002	RIGHT INBOARD JET PUMP							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01								
2820021	WHEEL WELL AND KEEL BEAM AREA - PERFORM DETAILED VISUAL INSPECTION OF FUEL TUBE FERRULE ENDS (UNDERNEATH COUPLING ASSEMBLIES) BETWEEN FS 346 AND FS 421 (FRAMES 24 AND 31) FOR EVIDENCE OF FATIGUE CRACKS, CORROSION OR OTHER DEGRADATION							Service ATA:28
	MOS	12-Nov-24	36 (+14d/-14d)	Adj -25d	18-Oct-27	01-Nov-27	957 d (+14)	
	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 28-20-00PROC. REF: AMM 28-20-00								
282003	LEFT STANDBY PUMP							Component ATA:28
PN:2380060-053	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:C4188	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02								
282004	RIGHT STANDBY PUMP							Component ATA:28
PN:2380060-053	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:C4091	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02								
282005	LEFT FUEL FILTER ASSEMBLY							Component ATA:28
PN:6600488-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1954	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								
282006	RIGHT FUEL FILTER ASSEMBLY							Component ATA:28
PN:6600488-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1953	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282007	LEFT ENGINE FUEL SHUTOFF VALVE							Component ATA:28
PN:EM91-119	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-081143	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05								
282008	RIGHT ENGINE FUEL SHUTOFF VALVE							Component ATA:28
PN:EM91-42	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-0914378	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05								
282009	LEFT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE							Component ATA:28
PN:EM91-41	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-081148	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06								
282010	RIGHT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE							Component ATA:28
PN:EM91-41	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:07-0207264	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06								
282011	LEFT ENGINE RELIEF VALVE							Component ATA:28
PN:7600005-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-0908260	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07								
282012	RIGHT ENGINE RELIEF VALVE							Component ATA:28
PN:7600005-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-0908245	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282013	FUEL CONTROL RELAY PANEL							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-08PROC. REF: AMM 28-20-08								
282015	LEFT WING PILOT VALVE							Component ATA:28
PN:2780610-103	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09								
282016	RIGHT WING PILOT VALVE							Component ATA:28
PN:2780610-103	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2250	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09								
282017	LEFT WING REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780614-104	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1450	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10								
282018	RIGHT WING REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780614-104	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1460	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10								
282019	FUSELAGE PILOT VALVE							Component ATA:28
PN:2780610-103	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2248	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282020	FUSELAGE VENT VALVE							Component ATA:28
PN:2780612-104	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:896	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12								
282021	REFUELING CHECK VALVE							Component ATA:28
PN:2780623-102	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:738	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-13PROC. REF: AMM 28-20-13								
282022	FUSELAGE REFUELING SHUTOFF VALVE							Component ATA:28
PN:2780624-103	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:856	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14								
282023	FUEL SOLENOID VALVE							Component ATA:28
PN:2780613-104	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0793	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15								
282024	PRESSURE REFUELING ADAPTER							Component ATA:28
PN:2780609-102	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:852	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-16PROC. REF: AMM 28-20-16								
282025	LEFT PRECHECK VALVE							Component ATA:28
PN:2780615-103	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1598	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-17PROC. REF: AMM 28-20-17								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
282026	RIGHT PRECHECK VALVE							Component ATA:28
PN:2780615-103	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1597	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-17PROC. REF: AMM 28-20-17								
282027	PRESSURE REFUELING CONTROL PANEL							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-18PROC. REF: AMM 28-20-18								
284001	LEFT INBOARD WING (MT5) FUEL PROBE							Component ATA:28
PN:FG250A55	MOS/MSC	24-Apr-23	O/C					
SN:07051207	HRS							
	AFL							
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284002	RIGHT INBOARD WING (MT6) FUEL PROBE							Component ATA:28
PN:2326014-12	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06050728	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284003	LEFT OUTBOARD WING (MT7) FUEL PROBE							Component ATA:28
PN:2326014-9	MOS/MSC	25-Sep-07	O/C					
SN:02022103	HRS	53.2						
	AFL	33						
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284004	RIGHT OUTBOARD WING (MT8) FUEL PROBE							Component ATA:28
PN:2326014-9	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06082185	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284005	LEFT INBOARD WING EXTENSION STA 189 (MT9) FUEL PROBE							Component ATA:28
PN:2826003-6	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06061466	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284006	RIGHT INBOARD WING EXTENSION STA 189 (MT10) FUEL PROBE							Component ATA:28
PN:2826003-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06061464	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284007	LEFT OUTBOARD WING EXTENSION STA 244 (MT11) FUEL PROBE							Component ATA:28
PN:2826003-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06041438	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284008	RIGHT OUTBOARD WING EXTENSION STA 244 (MT12) FUEL PROBE							Component ATA:28
PN:2826003-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06041434	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284009	FUSELAGE (MT18) FUEL PROBE							Component ATA:28
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284011	LEFT ENGINE LOW FUEL PRESSURE SWITCH							Component ATA:28
PN:7600002-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4326	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
284012	RIGHT ENGINE LOW FUEL PRESSURE SWITCH							Component ATA:28
PN:7600002-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4312	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
284013	FUEL QUANTITY INDICATOR							Component ATA:28
PN:2323-01-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:FM2941	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03								
B2813011 ^S	DEFUEL FUSELAGE FUEL CELL AND PERFORM FUEL CELL STATIC ELECTRICAL BONDING RESISTANCE CHECK. CHECK FUSELAGE FUEL CELL FOR CLEANLINESS. (REFER TO 28-12-00.)							Service ATA:28
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
PROC. REF: AMM 28-12-00PROC. REF: AMM 28-12-00								
C2820030 ^S	INSPECT FUEL SUPPLY LINE CHECK VALVE ORIFICES FOR CONDITION AND CLEANLINESS. (REFER TO 28-20-03.)							Service ATA:28
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03								
D2812030 ^S	WITH LOWER SURFACE ACCESS PLATES REMOVED, INSPECT INTERIOR AND EXTERIOR WING STRUCTURE FOR EVIDENCE OF FUEL LEAKAGE, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, BACTERIAL GROWTH, FILIFORM CORROSION, AND GENERAL CONDITION. INSPECT WING FLAPPER VALVES FOR F							Service ATA:28
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
E2820010 ^S	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS. ON AIRCRAFT EQUIPPED WITH PAPER FILTERS, REMOVE AND REPLACE FILTERS. (REFER TO 28-20-04)						Service	ATA:28
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								PKG:3
H2812060 ^S	OPERATIONAL CHECK OF WING LOW FUEL WARNING SYSTEM. (REFER TO 28-14-00.)						Service	ATA:28
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 28-14-00PROC. REF: AMM 28-14-00								PKG:16
H2820020 ^S	PERFORM OPERATIONAL CHECK OF FUEL SUPPLY SHUTOFF VALVE AND HYDRAULIC SUPPLY SHUTOFF VALVES. (REFER TO 28-20-05 AND 29-10-01)						Service	ATA:28
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 28-20-05, AMM 29-10-01PROC. REF: AMM 28-20-05, AMM 29-10-01								PKG:7
T2812070 ^S	OPERATIONAL CHECK OF FUEL CROSSFLOW VALVE AND MOTIVE FLOW CONTROL VALVES. (REFER TO 28-14-00 AND 28-20-00.)						Service	ATA:28
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 28-20-00, AMM 28-14-00PROC. REF: AMM 28-20-00, AMM 28-14-00								PKG:22
T2814021 ^S	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES. (REFER TO 28-13-07.)						Service	ATA:28
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 28-13-07PROC. REF: AMM 28-13-07								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
T2814039 ^S	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK VACUUM RELIEF VALVES. (REFER TO 28-13-06.)							Service ATA:28
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 28-13-06PROC. REF: AMM 28-13-06								PKG:14
T2820001 ^S	VISUALLY INSPECT FUEL PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.) CHECK FUEL DRAINS FOR OPERATION.							Service ATA:28
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
T2820004 ^S	INSPECT LOWER INBOARD GEAR DOORS AND CHECK ENTIRE KEELBEAM AND WHEEL WELL AREA FOR FUEL OR HYDRAULIC LEAKS, PLUMBING FOR ROUTING, CLEARANCES, SECURITY OF CLAMPS, AND GENERAL CONDITION.							Service ATA:28
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17
Y2814041 ^S	PERFORM BENCH CHECK OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES.							Service ATA:28
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: AMM 28-13-07PROC. REF: AMM 28-13-07								PKG:27
ATA 29 - HYDRAULIC POWER								
05-11-00-G2900001	REPLACE HYDRAULIC HOSE ASSEMBLIES(EXCLUDING HOSES FOR THE LANDING GEAR AND THE HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA)							Service ATA:29
	MOS/MSC	22-Aug-07	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
05-11-00-L2910020		REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS						Service ATA:29
	MOS/MSC	04-Oct-07	O/C					
	HRS	61.6						
	AFL	40						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								
290002		HYDRAULIC PRESSURE REGULATOR						Component ATA:29
PN:55950-2	MOS/MSC	18-Oct-10	O/C	TSN 0				
SN:0268	HRS	510.5		TSN 0				
	AFL	414		TSN 0				
PROC. REF: AMM 29-00-02PROC. REF: AMM 29-00-02								
290003		HYDRAULIC RESERVOIR						Component ATA:29
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-03PROC. REF: AMM 29-00-03								
290005		PRESSURE REGULATOR CHECK VALVE						Component ATA:29
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-05PROC. REF: AMM 29-00-05								
291001		LEFT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE						Component ATA:29
PN:AV24B1119B	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-091636	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01								
291002		RIGHT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE						Component ATA:29
PN:AV24B1119B	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-091634	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291003	LEFT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:6607066-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:K0676AB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02								
291004	RIGHT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:6607066-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:K0673AB	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02								
291005	HYDRAULIC PRESSURE FILTER ASSEMBLY							Component ATA:29
PN:M8815/2A-10	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0363	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								
291006	HYDRAULIC RETURN FILTER ASSEMBLY							Component ATA:29
PN:M8815/1A-10	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0356	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								
291007	HYDRAULIC SYSTEM ACCUMULATOR							Component ATA:29
PN:MS28700-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0423-12219	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04								
291008	HYDRAULIC THRUST REVERSER ACCUMULATOR							Component ATA:29
PN:MS28700-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:8424-19184	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291010	HYDRAULIC GROUND SERVICE PANEL							Component ATA:29
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291015	HYDRAULIC RELIEF VENT VALVE							Component ATA:29
PN:2380103-1	MOS/MSC	14-Oct-19	O/C					
SN:00510154	HRS	976.1						
	AFL	766						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
291020	HYDRAULIC RESERVOIR RELIEF VALVE							Component ATA:29
PN:5120T-8TT-20	MOS/MSC	07-Oct-23	O/C					
SN:4090624	HRS	1309.3						
	AFL	1026						
PROC. REF: AMM 29-00-08PROC. REF: AMM 29-00-08								
291220	THRUST REVERSER ISOLATION VALVE							Component ATA:29
PN:9555	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:333	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-27PROC. REF: AMM 78-30-27								
291225	HYDRAULIC PRESSURE RELIEF VALVE							Component ATA:29
PN:1280	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:352	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-00-08PROC. REF: AMM 29-00-08								
292001	AUXILIARY HYDRAULIC PUMP							Component ATA:29
PN:MP500	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:SN01912	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
293001	HYDRAULIC PRESSURE MT15 TRANSDUCER							Component ATA:29
PN:124058-3000	MOS/MSC	07-Oct-08	O/C	TSO 0				
SN:40318	HRS	446.6		TSO 0				
	AFL	360		TSO 0				
PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01								
293002	AUXILIARY HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730626	MOS/MSC	20-Jul-08	O/C	TSN 0				
SN:F1374	HRS	428.3		TSN 0				
	AFL	287		TSN 0				
PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02								
293003	HYDRAULIC PRESSURE INDICATOR							Component ATA:29
PN:S218-2	MOS/MSC	07-Oct-23	O/C					
SN:575	HRS	1309.3						
	AFL	1026						
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03								
293005	LEFT HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730635	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:C751	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04								
293006	RIGHT HYDRAULIC PUMP PRESSURE SWITCH							Component ATA:29
PN:730635	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:B736	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04								
293010	HYDRAULIC SYSTEM PRESSURE GAUGE							Component ATA:29
PN:S-218-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1528	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-05PROC. REF: AMM 29-30-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
293015	THRUST REVERSER HYDRAULIC PRESSURE GAUGE							Component ATA:29
PN:S-218-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1528	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-05PROC. REF: AMM 29-30-05								
H2910009 ^S	REMOVE AND CLEAN OR REPLACE AUXILIARY HYDRAULIC PUMP FILTER. (REFER TO 29-20-02.)							Service ATA:29
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02								
N2920000 ^S	FUNCTIONAL TEST THRUST REVERSER HYDRAULIC RETURN LINE CHECK VALVE. (REFER TO 78-30-03.)							Service ATA:29
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05								
P2910023 ^S	INSPECT HYDRAULIC RESERVOIR FILLER FILTER ELEMENT AND REPLACE IF REQUIRED. (REFER TO 29-00-04.)							Service ATA:29
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q2910019 ^S	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS. (REFER TO 29-10-03).							Service ATA:29
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
S2900004 ^S	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR PRESSURE RELIEF VALVE. (REFER TO 29-00-08.)							Service ATA:29
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 29-00-08PROC. REF: AMM 29-00-08								PKG:15
S2900005 ^S	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR VACUUM RELIEF VALVE. (REFER TO 29-00-08.)							Service ATA:29
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 29-00-08PROC. REF: AMM 29-00-08								PKG:15
S2910008 ^S	REMOVE HYDRAULIC RESERVOIR REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02.)							Service ATA:29
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 29-00-01PROC. REF: AMM 29-00-01								PKG:15
S2910025 ^S	REMOVE HYDRAULIC RESERVOIR PRESSURE REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02)							Service ATA:29
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 29-00-01, AMM 29-00-02PROC. REF: AMM 29-00-01, AMM 29-00-02								PKG:9
T2900000 ^S	VISUALLY INSPECT HYDRAULIC PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:29
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
W2910024 ^S	INSPECT HYDRAULIC FILTERS (PRESSURE AND RETURN) DIFFERENTIAL PRESSURE INDICATORS FOR BYPASS INDICATION.							Service ATA:29
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								PKG:3

ATA 30 - ICE AND RAIN PROTECTION								
300001	COPILOT ELECTRICAL EQUIPMENT BOX							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-00-01PROC. REF: AMM 30-00-01								

301001	WING ANTI-ICE SHUTOFF AND PRESSURE REGULATING VALVE							Component ATA:30
PN:15E51-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:DUK0018	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01								

301002	WING RT10 ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								

301003	WING (SPARE 2RT10) ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								

301004	WING (SPARE 3RT10) ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								
301005	WING OVERHEAT WARNING THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								
301006	WING TEMPERATURE INDICATOR							Component ATA:30
PN:820-685	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:652	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-04PROC. REF: AMM 30-10-04								
301007	LEFT WING ANTI-ICE BYPASS VALVE							Component ATA:30
PN:27441482-13	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10BB54	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05								
301008	RIGHT WING ANTI-ICE BYPASS VALVE							Component ATA:30
PN:27441482-13	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10BB53	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05, AMM 30-10-06PROC. REF: AMM 30-10-05, AMM 30-10-06								
301009	LEFT WING BLEED AIR OVERHEAT SWITCH							Component ATA:30
PN:M2-001-559	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:000151	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06								
301010	RIGHT WING BLEED AIR OVERHEAT SWITCH							Component ATA:30
PN:M2-001-559	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:000142	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06								
301011	WING UNDERHEAT WARNING SWITCH							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07								
301014	WING ANTI-ICE VALVE							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05, AMM 30-10-08PROC. REF: AMM 30-10-05, AMM 30-10-08								
301015	LEFT WING ANTI-ICE CHECK VALVE							Component ATA:30
PN:1H95-8	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6BB81	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08								
301016	RIGHT WING ANTI-ICE CHECK VALVE							Component ATA:30
PN:1H95-8	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:88B83	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08								
301101	HORIZONTAL STABILIZER ANTI-ICE CONTROLLER							Component ATA:30
PN:807-1-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:206300145	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-01PROC. REF: AMM 30-11-01								
301103	LEFT HORIZONTAL STABILIZER HEAT BLANKET (BOOT)							Component ATA:30
PN:4065-3481	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-64019	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-11-02PROC. REF: AMM 30-11-02								
301104	RIGHT HORIZONTAL STABILIZER HEAT BLANKET (BOOT)							Component ATA:30
PN:4065-3481	MOS/MSC	13-Jan-14	O/C					
SN:13-14265	HRS	565.7						
	AFL	464						
PROC. REF: AMM 30-11-02PROC. REF: AMM 30-11-02								
301109	CBR9 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	12-Jan-14	O/C	TSN 84				
SN:98606	HRS	565.7		TSN 0				
	AFL	464		TSN 0				
PROC. REF: AMM 30-11-03PROC. REF: AMM 30-11-03								
301110	CBR10 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:97409	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03PROC. REF: AMM 30-11-03								
301111	CBR11 REMOTE CIRCUIT BREAKER							Component ATA:30
PN:SM600BA40A1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:97405	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-11-03PROC. REF: AMM 30-11-03								
302101	LEFT NACELLE ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:27441482-09	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:11BB52	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-01PROC. REF: AMM 30-21-01								
302102	RIGHT NACELLE ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:27441482-09	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:11BB49	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-21-01PROC. REF: AMM 30-21-01								
302103	LEFT NACELLE ANTI-ICE PRESSURE SWITCH							Component ATA:30
PN:7600020-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4601TW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02								
302104	RIGHT NACELLE ANTI-ICE PRESSURE SWITCH							Component ATA:30
PN:7600020-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4459TW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02PROC. REF: AMM 30-21-02								
303001	LEFT PITOT HEAT MONITOR-							Component ATA:30
PN:76248-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:3662	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								
303002	RIGHT PITOT HEAT MONITOR-							Component ATA:30
PN:76248-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:3663	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								
303003	STANDBY PITOT HEAT MONITOR-							Component ATA:30
PN:76248-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:3666	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								
304001	WINDSHIELD ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:55510	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2848	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01								
304002	WINDSHIELD ANTI-ICE MODULATING VALVE							Component ATA:30
PN:27241287-12	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:9BB17	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-02PROC. REF: AMM 30-40-02								
304003	WINDSHIELD ANTI-ICE RAM AIR MODULATING VALVE							Component ATA:30
PN:27441500	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:9BB18	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-03PROC. REF: AMM 30-40-03								
304004	WINDSHIELD ANTI-ICE HEAT EXCHANGER							Component ATA:30
PN:5F295-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1150	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-04PROC. REF: AMM 30-40-04								
304005	WINDSHIELD ANTI-ICE TEMPERATURE SENSOR							Component ATA:30
PN:27431501-09	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:5BB12	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-05PROC. REF: AMM 30-40-05								
304007	LEFT WINDSHIELD ANTI-ICE LOW-LIMIT (S83) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07PROC. REF: AMM 30-40-07								
304008	RIGHT WINDSHIELD ANTI-ICE LOW-LIMIT (S82) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-40-07PROC. REF: AMM 30-40-07								
304009	LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07PROC. REF: AMM 30-40-07								
304010	RIGHT WINDSHIELD ANTI-ICE HIGH-LIMIT (S84) THERMOSWITCH							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-40-07PROC. REF: AMM 30-40-07								
304101	ALCOHOL SUPPLY TANK ASSEMBLY							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-01PROC. REF: AMM 30-41-01								
304102	ALCOHOL ANTI-ICE FLOAT SWITCH							Component ATA:30
PN:L14F-74	MOS/MSC	09-Nov-16	O/C					
SN:1156	HRS	733.8						
	AFL	566						
PROC. REF: AMM 30-41-02PROC. REF: AMM 30-41-02								
304104	ALCOHOL PRESSURE RELIEF VALVE							Component ATA:30
PN:4P152-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1545	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-04PROC. REF: AMM 30-41-04								
304105	ANTI-ICE THREE-WAY SHUTOFF VALVE							Component ATA:30
PN:6608258-2	MOS/MSC	16-Sep-11	O/C	TSR 0				
SN:1918	HRS	512.2		TSR 0				
	AFL	415		TSR 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
PROC. REF: AMM 30-41-05PROC. REF: AMM 30-41-05								
304106	ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE							Component ATA:30
PN:56410	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1758A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-41-06PROC. REF: AMM 30-41-06								
304203	WINDSHIELD DEFOG RELAY BOX							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-42-03PROC. REF: AMM 30-42-03								
308001	LEFT ICE DETECT LAMP							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01								
308002	RIGHT ICE DETECT LAMP							Component ATA:30
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01								
G3010001 ^S	OPERATIONAL CHECK WING ANTI-ICE CHECK VALVE. (REFER TO 30-10-08).							Service ATA:30
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
H3020002	^S	REMOVE INLET COWL ACCESS PANEL. VISUALLY INSPECT ANTI-ICE PLUMBING CONNECTOR FOR CONDITION, SECURITY, AND EVIDENCE OF LEAKAGE. (REFER TO 5-10-00)					Service	ATA:30
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3020003	^S	REMOVE UPPER ENGINE ACCESS COWL AND PERFORM A VISUAL INSPECTION OF NACELLE ANTI-ICE PLUMBING AND ALOCHOL PRESSURE LINE. (REFER TO 5-10-00)					Service	ATA:30
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T3040004	^S	INSPECT WINDSHIELD DEFOG DUCTS AND EXTERNAL OUTLETS FOR SECURITY, CONTOUR, AND INTEGRITY OF SEALANT TO WINDSHIELD. CHECK THAT THE EXTERNAL ANTI-ICE NOZZLES ARE CLEAR OF OBSTRUCTIONS.					Service	ATA:30
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:14
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T3040008	^S	FUNCTIONAL TEST OF WINDSHIELD ANTI-ICE SYSTEM TIMER CIRCUIT. (REFER TO 30-40-00.)					Service	ATA:30
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:19
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00								
T3050003	^S	OPERATIONAL CHECK OF ALCOHOL ANTI-ICE SYSTEM. (REFER TO 30-41-00.)					Service	ATA:30
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:14
PROC. REF: AMM 30-41-00PROC. REF: AMM 30-41-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
T3050009 ^S	CLEAN ALCOHOL ANTI-ICE FILTER ELEMENT. REPLACE FILTER ELEMENT IF MADE OF PAPER. (REFER TO 30-41-03.)							Service ATA:30
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 30-41-03PROC. REF: AMM 30-41-03								PKG:14
U3020001A ^S	INSPECT NO. 1 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION							Service ATA:30
	MOS	22-Aug-07						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:29
U3020001B ^S	INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION							Service ATA:30
	MOS	22-Aug-07						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:30
ATA 31 - INDICATING/RECORDING SYSTEMS								
311006	TEST SWITCH PANEL ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-06PROC. REF: AMM 31-10-06								
311007	PILOT DISPLAY CONTROL (DCP) PANEL							Component ATA:31
PN:822-2117-202	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2G6CJ	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-07PROC. REF: AMM 31-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
311008 COPILOT DISPLAY CONTROL (DCP) PANEL								Component ATA:31
PN:822-2117-202	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2G64P	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-07PROC. REF: AMM 31-10-07								
311009 LEFT CURSOR CONTROL (CCP) PANEL								Component ATA:31
PN:822-1746-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:SFY8P	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-09PROC. REF: AMM 31-10-09								
311010 RIGHT CURSOR CONTROL (CCP) PANEL								Component ATA:31
PN:822-1746-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:SFY1B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-10-09PROC. REF: AMM 31-10-09								
312001 PILOT CREW CLOCK								Component ATA:31
PN:6420093-1	MOS/MSC	11-Oct-21	O/C					
SN:J20-11419	HRS	1173.5						
	AFL	920						
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01								
312002 COPILOT CREW CLOCK								Component ATA:31
PN:6420093-1	MOS/MSC	11-Oct-21	O/C					
SN:J20-11418	HRS	1173.5						
	AFL	920						
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01								
313001 FLIGHT DATA (FDR) RECORDER								Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
313018	FDR INERTIA SWITCH							Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
313103	MULTI-AXIAL ACCELEROMETER							Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
314002	IAPS CARD CAGE							Component ATA:31
PN:822-2018-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2GYVM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-02PROC. REF: AMM 31-40-02								
314004	IAPS ENVIRONMENTAL (IEC) CONTROLLER							Component ATA:31
PN:822-1167-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2GLBV	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-04PROC. REF: AMM 31-40-04								
314007	NO. 1 OPTIONS CONTROL MODULE							Component ATA:31
PN:822-1484-205	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2809G	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-08PROC. REF: AMM 31-40-08								
314008	NO. 2 OPTIONS CONTROL MODULE							Component ATA:31
PN:822-1484-205	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:28P5H	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-08PROC. REF: AMM 31-40-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314011		1A PWR-851A POWER SUPPLY CARD					Component	ATA:31
PN:822-1137-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2GKWR	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314012		2A PWR-851A POWER SUPPLY CARD					Component	ATA:31
PN:822-1137-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2GKWT	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314013		1B PWR-851A POWER SUPPLY CARD					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314014		2B PWR-851A POWER SUPPLY CARD					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314021		1A FLIGHT CONTROL CARD					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314022		2A FLIGHT CONTROL CARD					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314031	1B FLIGHT MANAGEMENT - FMC 851C CARD							Component ATA:31
PN:822-0891-027	MOS/MSC	17-Feb-21	O/C	TSO 0				
SN:31TOK	HRS	1099.6		TSO 0				
	AFL	858		TSO 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314032	2B FLIGHT MANAGEMENT - FMC 851C CARD							Component ATA:31
PN:822-0891-027	MOS/MSC	17-Feb-21	O/C	TSO 0				
SN:3J6KL	HRS	1099.6		TSO 0				
	AFL	858		TSO 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314033	1B FLIGHT MANAGEMENT - FMC 852C CARD							Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314034	2B FLIGHT MANAGEMENT - FMC 852C CARD							Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01PROC. REF: AMM 31-40-01								
314041	1A INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:822-1361-321	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:28L0K	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02PROC. REF: AMM 31-40-01, AMM 31-40-02								
314042	2A INPUT/OUTPUT CONCENTRATOR CARD							Component ATA:31
PN:822-1361-321	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:28L6K	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02PROC. REF: AMM 31-40-01, AMM 31-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314043		1B INPUT/OUTPUT CONCENTRATOR CARD					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02PROC. REF: AMM 31-40-01, AMM 31-40-02								
314044		2B INPUT/OUTPUT CONCENTRATOR CARD					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-01, AMM 31-40-02PROC. REF: AMM 31-40-01, AMM 31-40-02								
314047		NO. 1 CONFIGURATION STRAPPING (CSU) UNIT					Component	ATA:31
PN:822-1363-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2FMVP	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-05PROC. REF: AMM 31-40-05								
314048		NO. 2 CONFIGURATION STRAPPING (CSU) UNIT					Component	ATA:31
PN:822-1363-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2D80F	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-40-05PROC. REF: AMM 31-40-05								
314101		DATA ACQUISITION UNIT					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01								
314110		MINI-FLIGHT DATA ACQUISITION (MFDAU) UNIT					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
315101	AURAL WARNING CONTROL UNIT							Component ATA:31
PN:883-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2256	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01								
315102	TONE GENERATOR							Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-02PROC. REF: AMM 31-51-02								
315103	AURAL WARNING MIXER							Component ATA:31
PN:1882-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:793	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-03PROC. REF: AMM 31-51-03								
315201	GLARESHIELD ANNUNCIATOR PANEL							Component ATA:31
PN:828-1-14	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:206510238	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-52-01PROC. REF: AMM 31-52-01								
315203	MASTER CAUTION/WARNING TRIGGER UNIT ASSEMBLY							Component ATA:31
PN:6018604-005	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:206510238	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-52-03PROC. REF: AMM 31-52-03								
316001	PILOT EFD-871 ELECTRONIC FLIGHT DISPLAY							Component ATA:31
PN:822-1084-020	MOS/MSC	25-May-21	O/C					
SN:2G77K	HRS	1120						
	AFL	881						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316002		COPILOT EFD-871 ELECTRONIC FLIGHT DISPLAY					Component	ATA:31
PN:822-1084-020	MOS/MSC	05-Apr-21	O/C					
SN:2K84P	HRS	1114						
	AFL	878						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316003		MULTIFUNCTION DISPLAY					Component	ATA:31
PN:822-1753-020	MOS/MSC	16-Sep-11	O/C	TSO 0				
SN:2C4LD	HRS	512.2		TSO 0				
	AFL	415		TSO 0				
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316004		MULTIFUNCTION DISPLAY					Component	ATA:31
PN:822-1753-020	MOS/MSC	13-Feb-25	O/C	TSO 1				
SN:2NN2Y	HRS	1385		TSO 0				
	AFL	1094		TSO 0				
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316005		PILOT EFIS CONTROL PANEL					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02								
316006		COPILOT EFIS CONTROL PANEL					Component	ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02								
316011		NO. 1 DISPLAY IMT-871 TRAY					Component	ATA:31
PN:822-1140-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2CJ5X	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316012	NO. 2 DISPLAY IMT-871 TRAY							Component ATA:31
PN:822-1140-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2CJ5Y	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316013	NO. 3 DISPLAY IMT-871 TRAY							Component ATA:31
PN:822-1140-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:299PP	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316014	NO. 4 DISPLAY IMT-871 TRAY							Component ATA:31
PN:822-1140-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2CKBN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316101	SENSOR DISPLAY UNIT							Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01PROC. REF: AMM 31-61-01								
316102	SENSOR DISPLAY DRIVER UNIT							Component ATA:31
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-02PROC. REF: AMM 31-61-02								
316201	NO. 1 FILE SERVER (FSU) UNIT							Component ATA:31
PN:822-1543-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2G3DD	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-01PROC. REF: AMM 31-62-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316202	NO. 2 FILE SERVER (FSU) UNIT							Component ATA:31
PN:822-1543-101	MOS/MSC	13-Feb-25	O/C	TSO 4				
SN:1YX6M	HRS	1385		TSO 0				
	AFL	1094		TSO 0				
PROC. REF: AMM 31-62-01PROC. REF: AMM 31-62-01								
316203	NO. 1 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:31
PN:822-1200-998	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2B54G	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-03PROC. REF: AMM 31-62-03								
316204	NO. 2 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:31
PN:822-1200-998	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2FPPP	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-62-03PROC. REF: AMM 31-62-03								
316301	MAINTENANCE WARNING PANEL ASSEMBLY							Component ATA:31
PN:6018449-006	MOS/MSC	17-Feb-21	O/C	TSR 0				
SN:A01858556-01	HRS	1099.6		TSR 0				
	AFL	858		TSR 0				
PROC. REF: AMM 31-63-01PROC. REF: AMM 31-63-01								
P3151001 ^S	PERFORM OPERATIONAL CHECK OF THE AUTOPILOT AURAL WARNING. (REFER TO 31-51-00) (EFFECTIVE ON AIRCRAFT 60-307, 60-319 AND SUBSEQUENT)							Service ATA:31
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 31-51-00PROC. REF: AMM 31-51-00								
P3160001 ^S	PERFORM OPERATIONAL CHECK OF THE ELECTRONIC FLIGHT INSTRUCMENT SYSTEM (EFIS). (REFER TO 31-60-03)							Service ATA:31
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						

PKG:1

PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
PROC. REF: AMM 31-60-03PROC. REF: AMM 31-60-03								
T3110000 ^S	INSPECT EQUIPMENT INSTALLATIONS BETWEEN FORWARD PRESSURE BULKHEAD AND INSTRUMENT PANEL FOR SECURITY OF MOUNTING, WIRE ROUTING, AND CLEARANCES OF WIRING AND PLUMBING.							Service ATA:31
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:19
U3100001 ^S GENERAL VISUAL INSPECTION INSTRUMENT PANEL (REFER TO 5-10-00.)								
	MOS	12-Nov-24	12 (+14d/-14d)					Service ATA:31
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
ATA 32 - LANDING GEAR								
05-11-00-E3211066	REPLACE NOSE LANDING GEAR ACTUATOR BOLT (6042007-4)							Service ATA:32
	MOS	14-Oct-19						
	HRS	976.1						
	AFL	766	6000 (+25/-25)		6766	6791	5672 (+25)	
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
05-11-00-E3211074L	REPLACE LEFT * MLG UPPER BEARINGS (6041104) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	3000		3000		1906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211074R	REPLACE RIGHT * MLG UPPER BEARINGS (6041104) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	3000		3000		1906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
05-11-00-E3211084L	REPLACE LEFT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211084R	REPLACE RIGHT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	20000		20000		18906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211090L	REPLACE LEFT * MLG UPPER BEARING RETENTION PIN (6041110-1) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	3000		3000		1906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211090R	REPLACE RIGHT * MLG UPPER BEARING RETENTION PIN (6041110-1) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	3000		3000		1906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211092L	REPLACE LEFT * MLG UPPER BEARING (7600839) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211092R	REPLACE RIGHT * MLG UPPER BEARING (7600839) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
05-11-00-E3211093L	REPLACE LEFT * MLG LOWER BEARING (6041105) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-E3211093R	REPLACE RIGHT * MLG LOWER BEARING (6041105) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
05-11-00-G3210003	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN AND NOSE GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR							Service ATA:32
	MOS/MSC	19-Aug-12	O/C					TEFLON
	HRS	532.3						
	AFL	427						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-G3233007	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY FREEFALL EXTENSION, LANDING GEAR EMERGENCY BLOWDOWN, AND EMERGENCY BRAKING SYSTEMS							Service ATA:32
	MOS/MSC	22-Aug-07	O/C					TEFLON
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-G3243040	REPLACE HYDRAULIC BRAKE HOSE ASSEMBLIES LOCATED ON THE STRUT AND IN WHEEL WELL AREA							Service ATA:32
	MOS/MSC	22-Aug-12	O/C					TEFLON
	HRS	532.3						
	AFL	427						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-U3211091L	REPLACE LEFT * MLG UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)							Service ATA:32
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0						
	AFL	0	6000		6000		4906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
05-11-00-U3211091R REPLACE RIGHT * MLG UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)								
	MOS	22-Aug-07						Service ATA:32
	HRS	0						LIFE LIMIT
	AFL	0	6000		6000		4906	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
321001 * LEFT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*)								
PN:6041000V3-001	MOS	22-Aug-07		TSN 0				Component ATA:32
SN:022	HRS	0		TSN 0				LIFE LIMIT
	AFL	0	16500	TSN 0	16500		15406	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
321002 * RIGHT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*)								
PN:6041000V3-002	MOS	22-Aug-07		TSN 0				Component ATA:32
SN:023	HRS	0		TSN 0				LIFE LIMIT
	AFL	0	16500	TSN 0	16500		15406	
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
321003 * LEFT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*)								
PN:PN	MOS	22-Aug-07		TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				AIRWORTHINESS
	AFL	0	6000	TSN 0	6000		4906	
PROC. REF: AMM 32-11-01PROC. REF: AMM 32-11-01								
321004 * RIGHT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*)								
PN:PN	MOS	22-Aug-07		TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				AIRWORTHINESS
	AFL	0	6000	TSN 0	6000		4906	
PROC. REF: AMM 32-11-01PROC. REF: AMM 32-11-01								
321005 * LEFT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)								
PN:PN	MOS	22-Aug-07		TSN 0				Component ATA:32
SN:UNKNOWN	HRS	0		TSN 0				AIRWORTHINESS
	AFL	0	6000	TSN 0	6000		4906	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-11-01PROC. REF: AMM 32-11-01								
321006	* RIGHT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*)							Component ATA:32
PN:PN	MOS	22-Aug-07		TSN 0				AIRWORTHINESS
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	6000	TSN 0	6000		4906	
PROC. REF: AMM 32-11-01PROC. REF: AMM 32-11-01								
321501	LEFT HYDRAULIC, GEAR RETRACTION RESTRICTOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
321502	RIGHT HYDRAULIC, GEAR RETRACTION RESTRICTOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
321511	LEFT HYDRAULIC, GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
321512	RIGHT HYDRAULIC, GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
321515	LEFT HYDRAULIC RESTRICTOR							Component ATA:32
PN:1R3665-035	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D7156	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321516 RIGHT HYDRAULIC RESTRICTOR								Component ATA:32
PN:1R3665-059	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D2255	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
322001 * NOSE GEAR STRUT ASSEMBLY (AWL*)								Component ATA:32
PN:2342100-030	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:117	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		8906	
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
322002 NOSE LANDING GEAR & STEERING ASSEMBLY STRUT								Component ATA:32
PN:2342003-090	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:117	HRS	0		TSN 0				
	AFL	0	10000	TSN 0	10000		8906	
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
323019 LEFT MAIN LANDING GEAR SQUAT SWITCH								Component ATA:32
PN:426EN9-8	MOS/MSC	28-Feb-16	O/C	TSN 0				
SN:NONE	HRS	676.2		TSN 0				
	AFL	543		TSN 0				
PROC. REF: AMM 32-30-03PROC. REF: AMM 32-30-03								
323020 RIGHT MAIN LANDING GEAR SQUAT SWITCH								Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-03PROC. REF: AMM 32-30-03								
323031 * LEFT MAIN LANDING GEAR ACTUATOR (AWL*)								Component ATA:32
PN:6600264-008	MOS	01-Jun-21		TSO 0				LIFE LIMIT
SN:1619A	HRS	1124.2		TSO 0				
	AFL	886	20000	TSO 0	20017 (M)		18923	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
323032	* RIGHT MAIN LANDING GEAR ACTUATOR (AWL*)							Component ATA:32
PN:7535-6	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:126	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		18906	
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
323043	LEFT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR							Component ATA:32
PN:95919-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0557	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-03PROC. REF: AMM 32-31-03								
323044	RIGHT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR							Component ATA:32
PN:95919-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0558	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-03PROC. REF: AMM 32-31-03								
323052	LANDING GEAR CONTROL PANEL ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-06PROC. REF: AMM 32-30-06								
323055	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6013	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
323056	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6014	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
323057	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6015	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-04PROC. REF: AMM 32-33-04								
323058	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6016	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-04PROC. REF: AMM 32-33-04								
323073	* NOSE LANDING GEAR ACTUATOR (AWL*)							Component ATA:32
PN:2317100-018	MOS	21-Jul-11		TSR 0				LIFE LIMIT
SN:MTM0032	HRS	512.2		TSR 0				
	AFL	415	10000	TSN 210, TSR 0	10205		9111	
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
323079	NOSE LANDING GEAR UPLOCK ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6012	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02								
323080	UPLOCK, NOSE LANDING GEAR FREEFALL ACTUATOR							Component ATA:32
PN:2417016-1	MOS/MSC	14-Oct-19	O/C					
SN:4003	HRS	976.1						
	AFL	766						
PROC. REF: AMM 32-33-05PROC. REF: AMM 32-33-05								
323098	GEAR DOOR CONTROL VALVE							Component ATA:32
PN:6600361-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1393	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-30-08PROC. REF: AMM 32-30-08								
323099	SELECT, LANDING GEAR VALVE							Component ATA:32
PN:48C48641	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0038T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-05PROC. REF: AMM 32-30-05								
323105	NOSE LANDING GEAR SHUTTLE VALVE							Component ATA:32
PN:2SV0614	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4576	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323110	NOSE LANDING GEAR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18408	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323205	LEFT MAIN LANDING GEAR EXTEND SHUTTLE VALVE							Component ATA:32
PN:92465	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4560	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323210	RIGHT MAIN LANDING GEAR EXTEND SHUTTLE VALVE							Component ATA:32
PN:92465	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4566	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323222	* LEFT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*)							Component ATA:32
PN:PN	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		18906	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-31-05PROC. REF: AMM 32-31-05								
323223	* RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*)							Component ATA:32
PN:PN	MOS	22-Aug-07		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		18906	
PROC. REF: AMM 32-31-05PROC. REF: AMM 32-31-05								
323305	LEFT MAIN LANDING GEAR DOOR SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18381	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323310	RIGHT MAIN LANDING GEAR DOOR SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18398	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323315	LEFT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:95930	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1201	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323320	RIGHT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE							Component ATA:32
PN:95930	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1206	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
323401	AFT EMERGENCY GEAR BLOWDOWN EXTENSION VALVE							Component ATA:32
PN:53620-6	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2394	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-33-02PROC. REF: AMM 32-33-02								
323402	FORWARD EMERGENCY GEAR FREEFALL EXTENSION VALVE							Component ATA:32
PN:53620-6	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2393	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-03PROC. REF: AMM 32-33-03								
323405	LEFT CHECK, FREEFALL VALVE							Component ATA:32
PN:92465	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4565	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-01PROC. REF: AMM 32-33-01								
323406	RIGHT CHECK, FREEFALL VALVE							Component ATA:32
PN:7600833-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4578	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-33-01PROC. REF: AMM 32-33-01								
323409	UPPER EMERGENCY GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:6R7742S-0135	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4788	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323410	LOWER EMERGENCY GEAR EXTENSION RESTRICTOR							Component ATA:32
PN:6R7742S-0135	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4787	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323430	NO. 1 EMERGENCY AIR BLOWDOWN SHUTTLE VALVE							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324001	NOSE TIRE							Component ATA:32
PN:184F10-2	MOS/MSC	12-Nov-24	O/C	TSN 1				
SN:33070682	HRS	1375.9		TSN 0				
	AFL	1084		TSN 0				
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
324007	ASSEMBLY, NOSE WHEEL							Component ATA:32
PN:9544207-4	MOS/MSC	12-Nov-24	O/C					
SN:SEP06-10222	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
324013	NO. 1 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	12-Nov-24	O/C					
SN:60770716	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324014	NO. 2 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	12-Nov-24	O/C					
SN:60770860	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324015	NO. 3 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	12-Nov-24	O/C					
SN:60730736	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324016	NO. 4 MAIN LANDING GEAR TIRE							Component ATA:32
PN:178K43-1	MOS/MSC	12-Nov-24	O/C					
SN:60770704	HRS	1375.9						
	AFL	1084						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324020	NOSE TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324021	NO. 1 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324022	NO. 2 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324023	NO. 3 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324024	NO. 4 TIRE PRESSURE SENSOR							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324037	NO. 1 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:011740	MOS/MSC	12-Nov-24	O/C					
SN:APR99-27	HRS	1375.9						
	AFL	1084						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324037A	NDT INSPECT NO. 1 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:011740	MOS/MSC		O/C					
SN:APR99-27	HRS							
	AFL							
PROC. REF: NDT 32-40-01PROC. REF: NDT 32-40-01								
324038	NO. 2 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	12-Nov-24	O/C					
SN:APR08-2805	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324038A	NDT INSPECT NO. 2 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC	12-Nov-24	O/C					
SN:APR08-2805	HRS	1375.9						
	AFL	1084						
PROC. REF: NDT 32-40-01PROC. REF: NDT 32-40-01								
324039	NO. 3 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	12-Nov-24	O/C	TSR 30				
SN:JUL99-1145	HRS	1375.9		TSR 147.4				
	AFL	1084		TSR 128				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324039A	NDT INSPECT NO. 3 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC		O/C					
SN:JUL99-1145	HRS							
	AFL							
PROC. REF: NDT 32-40-01PROC. REF: NDT 32-40-01								
324040	NO. 4 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:5011740	MOS/MSC	12-Nov-24	O/C	TSR 30				
SN:FEB01-1569	HRS	1375.9		TSR 147.4				
	AFL	1084		TSR 128				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324040A	NDT INSPECT NO. 4 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:5011740	MOS/MSC		O/C					
SN:FEB01-1569	HRS							
	AFL							
PROC. REF: NDT 32-40-01PROC. REF: NDT 32-40-01								
324048	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:6600518-003	MOS/MSC	15-Apr-19	O/C	TSO 0				
SN:DEC11-1528	HRS	940.3		TSO 0				
	AFL	730		TSO 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324049	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:90002424-2	MOS/MSC	30-Apr-18	O/C	TSO 7				
SN:AUG11-1491	HRS	827		TSO 0				
	AFL	646		TSO 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324050	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:90002424-2	MOS/MSC	07-Oct-23	O/C	TSO 0				
SN:FEB10-1279	HRS	1309.3		TSO 0				
	AFL	1026		TSO 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324051	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE							Component ATA:32
PN:6600518-003	MOS/MSC	11-Oct-21	O/C					
SN:MAY05-0459	HRS	1173.5						
	AFL	920						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324061	NO. 1 POWER BRAKE, PILOTS VALVE							Component ATA:32
PN:3321200-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2011	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-41-03, AMM 32-41-02PROC. REF: AMM 32-41-03, AMM 32-41-02								
324062	NO. 2 POWER BRAKE, PILOTS VALVE							Component ATA:32
PN:3321200-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2013	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02PROC. REF: AMM 32-41-03, AMM 32-41-02								
324063	NO. 1 POWER BRAKE, COPILOTS VALVE							Component ATA:32
PN:3321200-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2010	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02PROC. REF: AMM 32-41-03, AMM 32-41-02								
324064	NO. 2 POWER BRAKE, COPILOTS VALVE							Component ATA:32
PN:3321200-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2014	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03, AMM 32-41-02PROC. REF: AMM 32-41-03, AMM 32-41-02								
324085	NO. 1 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:2380114-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7222	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324086	NO. 2 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:2380114-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7220	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324109	NO. 3 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:2380114-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7215	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324110	NO. 4 HYDRAULIC, BRAKE FUSE							Component ATA:32
PN:2380114-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7189	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324133	AFT PARKING BRAKE VALVE							Component ATA:32
PN:6600392-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:96-C0164	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04								
324134	FWD PARKING BRAKE VALVE							Component ATA:32
PN:6600392-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0219	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04								
324145	NO. 1 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7647	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
324146	NO. 2 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7645	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
324147	NO. 3 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7635	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
324148	NO. 4 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:40-911	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7647	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
324169	LEFT ANTI-SKID VALVE							Component ATA:32
PN:39-309-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2630	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01								
324170	RIGHT ANTI-SKID VALVE							Component ATA:32
PN:39-309-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2631	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01								
324175	ANTI-SKID CONTROL							Component ATA:32
PN:42-379-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1906B	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-03PROC. REF: AMM 32-42-03								
324413	PARK BRAKE ANNUNCIATOR BOX ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-06PROC. REF: AMM 32-42-06								
324501	EMERGENCY BRAKE CONTROL VALVE							Component ATA:32
PN:63500-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:528A	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-43-01PROC. REF: AMM 32-43-01								
324505	LEFT MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:AN6277-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18384	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324510	RIGHT MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:AN6277-4	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18388	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324601	NO. 1 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18385	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324602	NO. 2 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18395	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324603	NO. 3 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18399	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
324604	NO. 4 MAIN LANDING GEAR BRAKE SHUTTLE VALVE							Component ATA:32
PN:2SV0413	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:D18389	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-00-01PROC. REF: AMM 32-00-01								
325001	NOSE WHEEL STEERING ACTUATOR							Component ATA:32
PN:501-1711-02	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80043	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-05PROC. REF: AMM 32-50-05								
325005	NOSE WHEEL STEERING COMPUTER							Component ATA:32
PN:501-1708-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80043	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04								
325015	LEFT RUDDER POSITION SENSOR							Component ATA:32
PN:501-1123-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80330	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03								
325016	RIGHT RUDDER POSITION SENSOR							Component ATA:32
PN:501-1123-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:80361	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03								
325019	NOSE WHEEL STEERING ACTUATOR GEARBOX							Component ATA:32
PN:3142020-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:330	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02								
325020	NOSE WHEEL STEERING FOLLOW UP ASSEMBLY							Component ATA:32
PN:2618274-10	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:002	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-50-05PROC. REF: AMM 32-50-05								
325024 RIGHT NOSE WHEEL STEERING FOLLOWUP								Component ATA:32
PN:CU41096004-0	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2264	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01								
325025 LEFT NOSE WHEEL STEERING FOLLOWUP								Component ATA:32
PN:CU41096004-0	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2259	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01								
325628 AFT EMERGENCY GEAR CONTROL VALVE								Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
326011 SQUAT SWITCH RELAY BOX								Component ATA:32
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-30-07PROC. REF: AMM 32-30-07								
AA3211058 ^S COMPLETELY DISASSEMBLE MAIN LANDING GEAR STRUTS AND ACTUATORS. REMOVE AXLES AND PISTONS FROM HUBS. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. CONDUCT FLUORESCENT PENETRANT OR MAGNETIC PARTICLE INSPECTION OF ALL COMPONENTS. PAY PARTICULAR ATTENTION TO THE MAIN GEAR UPPER TRUNNION AREAS AND LOWER GLAND NUT OF THE CYLINDER FORGING FOR CRACKS.								Service ATA:32
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: NDT 32-13-01PROC. REF: NDT 32-13-01								

PKG:26

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
C3211040	^S	CLEAN AND EDDY CURRENT INSPECT UPPER CYLINDER. (SEE FIGURE 1.) (REFER TO NDI MANUAL [NDI-2], PART 3, 32-40-02.)					Service	ATA:32
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: NDT 32-40-02PROC. REF: NDT 32-40-02							PKG:26	
C3211050	^S	DEFLATE STRUTS AND STROKE FROM FULLY EXTENDED TO FULLY COMPRESSED POSITIONS. NOTE BINDING TENDENCIES DURING STROKING, PARTICULARLY NEAR THE FULLY COMPRESSED POSITION.					Service	ATA:32
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							PKG:26	
C3231030	^S	INSPECT INBOARD ATTACHMENT OF MAIN GEAR ACTUATOR FOR SECURITY, LOOSENESS, OVERLOAD INDICATIONS, AND FATIGUE CRACKS. THE PILLAR ATTACHMENTS TO SPARS 7 AND 8 ARE TO BE SPECIFICALLY INSPECTED FOR DISCREPANT CONDITIONS. PILLAR REMOVAL IS REQUIRED TO FACILITATE DEFINI					Service	ATA:32
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							PKG:26	
C3233010	^S	FUNCTIONAL TEST OF LANDING GEAR EMERGENCY BLOWDOWN EXTENSION SYSTEM. (REFER TO 32-33-00.)					Service	ATA:32
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00							PKG:27	
C3233011	^S	FUNCTIONAL TEST OF LANDING GEAR EMERGENCY FREEFALL SYSTEM. (REFER TO 32-33-00.)					Service	ATA:32
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00							PKG:27	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
D3211060 ^S	COMPLETELY DISASSEMBLE NOSE LANDING GEAR STRUT AND ACTUATOR. REMOVE AXLE AND PISTON FROM HUB. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. (REFER TO 32-21-00 AND 32-32-01.) CONDUCT FLUORE							Service ATA:32
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								PKG:26
D3211061 ^S	VISUALLY INSPECT NOSE GEAR TRUNNION AXLE AND INSTALLATION AREA OF TRUNNION FOR CRACKS, CORROSION, AND DAMAGE. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION I							Service ATA:32
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								PKG:26
E3230020 ^S	INSPECT LANDING GEAR SQUAT SWITCHES FOR CONDITION.							Service ATA:32
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5
E3242000 ^S	INSPECT NOSE AND MAIN TIRES FOR WEAR, CUTS, ABRASIONS, AND FLAT SPOTS. CHECK CHINE CONDITION ON CHINED TIRE. (REFER TO 32-40-00)							Service ATA:32
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 32-40-00PROC. REF: AMM 32-40-00								PKG:5
E3243010 ^S	INSPECT BRAKE ASSEMBLIES FO RWEAR, CRACKS, HYDRAULIC LEAKS, AND RELEASE.							Service ATA:32
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
E3244020	^S	REMOVE AND CLEAN ANTI-SKID VALVE FILTERS. (REFER TO 32-42-01).						Service ATA:32
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01								PKG:11
F3233020	^S	FUNCTIONAL TEST OF EMERGENCY BRAKE SYSTEM. (REFER TO 34-43-00.)						Service ATA:32
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: AMM 32-43-00PROC. REF: AMM 32-43-00								PKG:27
G3200000	^S	PERFORM VISUAL INSPECTION OF LANDING GEAR SHOCK STRUTS FOR LEAKS AND GENERAL CONDITION. VISUALLY INSPECT LANDING GEAR SHOCK STRUTS AND LANDING GEAR ACTUATOR ATTACH POINTS FOR SECURITY AND GERNAL CONDITION. (REFER TO 5-10-00)						Service ATA:32
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:5
H3210000	^S	VISUALLY INSPECT MAIN AND NOSE LANDING GEAR STRUT ASSEMBLIES, ACTUATORS, FASTENERS, AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT NOSE GEAR ACTUATOR ATTACH BRACKET IN THE AREA AROUND THE GREASE FITTING. INSPECT FOR CRACKS EM						Service ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17
H3211010	^S	INSPECT MAIN LANDING GEAR TORQUE LINKS FOR LOOSENESS.						Service ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3211020 ^S	INSPECT INTERIOR AND EXTERIOR OF MAIN LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-11-00.)						Service	ATA:32
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:23
PROC. REF: AMM 32-11-00PROC. REF: AMM 32-11-00								
H3221000 ^S	INSPECT NOSE GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION.						Service	ATA:32
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:23
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3221010 ^S	INSPECT INTERIOR AND EXTERIOR OF NOSE LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-21-00.)						Service	ATA:32
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:23
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								
H3230000 ^S	INSPECT LANDING GEAR ELECTRICAL WIRING FOR ROUTING AND GENERAL CONDITION.						Service	ATA:32
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:11
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3230010 ^S	PERFORM LANDING GEAR RETRACTION AND EXTENSION CHECK. CHECK AUTOMATIC BRAKE SNUBBING AND LANDING LIGHTS FOR RETRACT CUTOFF. (REFER TO 32-30-00.)						Service	ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:17
PROC. REF: AMM 32-30-00PROC. REF: AMM 32-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H3230021	^S	INSPECT LANDING GEAR SQUAT SWITCHES FOR PROPER OPERATION AND CONDITION. (REFER TO 32-30-03.)						Service ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17
H3231014	^S	INSPECT MAIN GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FASTEMER CONDITION, AND PERMANENT DEFORMATION.						Service ATA:32
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23
H3232002	^S	INSPECT NOSE GEAR ACTUATOR BOOT AND HYDRAULIC PLUMBING FOR SECURITY AND GENERAL CONDITION.						Service ATA:32
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
H3233000	^S	VISUALLY INSPECT GEAR FREE FALL, GEAR BLOW DOWN, AND EMERGENCY BRAKE VALVES AND FITTINGS FOR SECURITY OF ATTACHMENT. (REFER TO 5-10-00.)						Service ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
H3233012	^S	PERFORM EMERGENCY AIR EXTENSION SYSTEM AND EMERGENCY BRAKE SYSTEM PLUMBING LEAKAGE CHECK. (REFER TO 32-33-00 AND 32-43-00.)						Service ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 32-33-00, AMM 32-43-00PROC. REF: AMM 32-33-00, AMM 32-43-00								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H3243000 ^S	INSPECT BRAKE LINES FOR ROUTING AND LEAKS, MLG AND DOOR ACTUATOR ATTACH POINTS FOR SECURITY, AND STRUT HINGE POINTS FOR GENERAL CONDITION.						Service	ATA:32
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
H3243023 ^S	INSPECT POWER BRAKE VALVES FOR SECURITY, OPERATION, AND LEAKS. ENSURE POWER BRAKE VALVE LEVER CONTACTS MECHANICAL STOP. (REFER TO 32-41-02.)						Service	ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								PKG:14
H3243030 ^S	FUNCTIONAL TEST OF HYDRAULIC BRAKE FUSES. (REFER TO 32-41-03.)						Service	ATA:32
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								PKG:23
N3243024 ^S	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.						Service	ATA:32
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								PKG:8
N3243050 ^S	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.						Service	ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
Q3242001 ^S	OPERATIONAL CHECK ANTI-SKID VALVES (REFER TO 32-42-00)							Service ATA:32
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 32-42-00PROC. REF: AMM 32-42-00								PKG:5
T3211030 ^S	REMOVE AND REPLACE RETAINER RING LOCKSCREW FROM NOSE LANDING GEAR STRUT (P/N AN500A6-10).							Service ATA:32
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 32-21-00PROC. REF: AMM 32-21-00								PKG:11
T3231040 ^S	INSPECT MAIN LANDING GEAR DOOR ACTUATORS AND HINGES FOR SECURITY AND GENERAL CONDITION.							Service ATA:32
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
W3232003 ^S	NOSE LANDING GEAR FREE FALL UPLATCH ACTUATOR - PERFORM DETAILED CHECK. (REFER TO 32-33-05.)							Service ATA:32
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 32-33-05PROC. REF: AMM 32-33-05								PKG:17
ATA 33 - LIGHTS								
330000 ^{U S}	OPERATIONAL TEST OF THE PASSENGER COMPARTMENT LIGHTING							Service ATA:33
	MOS	08-Nov-22					SMM	
	HRS	1247	300					
	AFL	971						
								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331201	LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY							Component ATA:33
PN:6900115-000	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6624	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02PROC. REF: AMM 33-12-02								
331202	RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY							Component ATA:33
PN:6900115-000	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6655	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02PROC. REF: AMM 33-12-02								
331303	QUAD EL (ELECTROLUMINESCENT) POWER SUPPLY							Component ATA:33
PN:SDA 16	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:474	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-13-03PROC. REF: AMM 33-13-03								
331311	PILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331312	COPILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331313	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331314	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331401	PILOT DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1998	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331402	COPILOT DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1994	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331403	CENTER INSTRUMENT AND PEDESTAL DIMMING CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2001	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331404	PEDESTAL DIMMING CONTROL BOX							Component ATA:33
PN:LT-48E	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6382	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331405	FUEL QUANTITY INDICATOR DIMMING CONTROL BOX							Component ATA:33
PN:LT-48E	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6380	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331406 CDU LAMP DIMMING CONTROL BOX								Component ATA:33
PN:LT-48E	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-01PROC. REF: AMM 33-14-01								
331407 INSTRUMENT BACKLIGHTING FUSE BOX								Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-14-02PROC. REF: AMM 33-14-02								
331601 LEFT ACS DIMMER CONTROL BOX								Component ATA:33
PN:LT-48G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1970	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331602 RIGHT ACS DIMMER CONTROL BOX								Component ATA:33
PN:LT-48G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1981	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331701 LEFT AFT LIGHT DIMMING (E215) CONTROL BOX								Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-17-01PROC. REF: AMM 33-17-01								
331801 LEFT FORWARD LIGHT DIMMING (AE9) CONTROL BOX								Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-18-01PROC. REF: AMM 33-18-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331802	RIGHT LIGHT DIMMING (2AE9) CONTROL BOX							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-18-01PROC. REF: AMM 33-18-01								
332001	OVERHEAD INDIRECT LIGHTING (PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332002	OVERHEAD INDIRECT LIGHTING (2PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332003	OVERHEAD INDIRECT LIGHTING (3PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332004	OVERHEAD INDIRECT LIGHTING (4PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332005	OVERHEAD INDIRECT LIGHTING (5PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
332006	OVERHEAD INDIRECT LIGHTING (6PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332007	OVERHEAD INDIRECT LIGHTING (7PS2) INVERTER							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-08PROC. REF: AMM 33-20-08								
332009	INDIRECT LIGHTING CONTROL							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-09PROC. REF: AMM 33-20-09								
332010	ALTERNATE/MOMENTARY SWITCHING MODULE							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
332014	ZONE BACK LIGHTING CONTROL							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-14PROC. REF: AMM 33-20-14								
332400 ^{U S}	OPERATIONAL TEST OF THE ORDINANCE SIGNS							Service ATA:33
	MOS	08-Nov-22					SMM	
	HRS	1247	300					
	AFL	971						
PKG:5								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334101		LEFT LANDING AND TAXI LIGHT					Component	ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-01PROC. REF: AMM 33-41-01								
334102		RIGHT LANDING AND TAXI LIGHT					Component	ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-41-01PROC. REF: AMM 33-41-01								
334201		LEFT NAVIGATION LIGHT					Component	ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-01PROC. REF: AMM 33-42-01								
334202		RIGHT NAVIGATION LIGHT					Component	ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-01PROC. REF: AMM 33-42-01								
334203		TAIL NAVIGATION LIGHT					Component	ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-02PROC. REF: AMM 33-42-02								
334301		UPPER STROBE/BEACON LIGHT					Component	ATA:33
PN:GE 16386-9-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:AF0367	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01PROC. REF: AMM 33-43-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334302	LOWER STROBE/BEACON LIGHT							Component ATA:33
PN:GE 16386-9-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1221862	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-43-01PROC. REF: AMM 33-43-01								
334401	WING ICE INSPECTION LIGHT							Component ATA:33
PN:GLJ-140	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:12461	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-44-01PROC. REF: AMM 33-44-01								
334501	RECOGNITION LIGHT							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-45-01PROC. REF: AMM 33-45-01								
334502	RECOGNITION LIGHT PULSE CONTROL UNIT							Component ATA:33
PN:2401S	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:AR-01169	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-45-02PROC. REF: AMM 33-45-02								
335000 ^{U S}	GENERAL VISUAL INSPECTION OF THE EMERGENCY LIGHTING SYSTEM COMPONENTS IAW SMM 33-50-00							Service ATA:33
	MOS							INSPECT
	HRS		4800					
	AFL							
								PKG:7
335001	EMERGENCY EXIT LIGHTING PANEL							Component ATA:33
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
P3310004 ^S	CHECK OPERATION OF INTERIOR LIGHTING SYSTEMS							Service ATA:33
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
P3340012 ^S	CHECK OPERATION OF EXTERIOR LIGHTING SYSTEMS							Service ATA:33
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:1
ATA 34 - NAVIGATION								
05-10-29-W3411025	FUNCTIONAL TEST AIR DATA SYSTEM							Service ATA:34
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00								
05-10-30-RVSM-W3411015	PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (RVSM) (REFER TO 34-17-00)							Service ATA:34
	MOS	12-Nov-24	12 (+14d/-14d)	Adj -36d	07-Oct-25	21-Oct-25	216 d (+14)	
	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00								
34-00-FAR-91.171	CHECK VOR FAR 91.171							Service ATA:34
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF, FAR FAR 91.171PROC. REF: GENERIC NO REF, FAR FAR 91.171								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-00-FAR-91.217	PERFORM ALTITUDE DATA TRANSMISSION TEST							Service ATA:34
	MOS/MSC	22-Aug-07	A/R					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REF, FAR FAR 91.217PROC. REF: GENERIC NO REF, FAR FAR 91.217								
34-00-FAR-91.411	RECERTIFY PITOT-STATIC SYSTEM							Service ATA:34
	MOS	12-Nov-24	24		12-Nov-26		617 d	
	HRS	1375.9						
	AFL	1084						
PROC. REF: GENERIC NO REF, FAR FAR 91.411PROC. REF: GENERIC NO REF, FAR FAR 91.411								
341020	LEFT PITOT/STATIC PROBE							Component ATA:34
PN:856KR7	MOS	08-Nov-22		TSN 183				LIFE LIMIT
SN:238695	HRS	1247	15000 (+25/-25)	TSN 1247	15000	15025	13615 (+25)	
	AFL	971		TSN 971				
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341020A	VERIFY LEFT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016							Service ATA:34
PN:856KR7	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
SN:238695	HRS							
	AFL							
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341020B	DETAILED VISUAL INSPECTION LEFT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064							Service ATA:34
PN:856KR7	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
SN:238695	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341025	RIGHT PITOT/STATIC PROBE							Component ATA:34
PN:856KR8	MOS	08-Nov-22		TSN 183				LIFE LIMIT
SN:233694	HRS	1247	15000 (+25/-25)	TSN 1247	15000	15025	13615 (+25)	
	AFL	971		TSN 971				
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341025A	VERIFY RIGHT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016							Service ATA:34
PN:856KR8	MOS	26-Nov-24	24 (+14d/-14d)	Adj -18d	08-Nov-26	22-Nov-26	613 d (+14)	
SN:233694	HRS							
	AFL							
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341025B	DETAILED VISUAL INSPECTION RIGHT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064							Service ATA:34
PN:856KR8	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
SN:233694	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341026	PITOT/STATIC PROBE							Component ATA:34
PN:856KR8 (STDBY)	MOS/MSC	10-Sep-18	O/C	TSN 0				
SN:277341	HRS	871.9		TSN 0				
	AFL	675		TSN 0				
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								
341105	PILOT RIGHT STATIC SHUTOFF VALVE							Component ATA:34
PN:6600473-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0355T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03PROC. REF: AMM 34-11-03								
341106	COPILOT RIGHT STATIC SHUTOFF VALVE							Component ATA:34
PN:6600473-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0333T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03PROC. REF: AMM 34-11-03								
341107	PILOT LEFT STATIC SHUTOFF VALVE							Component ATA:34
PN:6600473-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0355T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03PROC. REF: AMM 34-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341108	COPILOT LEFT STATIC SHUTOFF VALVE							Component ATA:34
PN:6600473-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0296T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-03PROC. REF: AMM 34-11-03								
341111	STANDBY ALTIMETER							Component ATA:34
PN:501-1860-0101	MOS/MSC	14-Jan-14	O/C					
SN:1552	HRS	565.7						
	AFL	464						
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01								
341111A	RECERTIFY STANDBY ALTIMETER							Service ATA:34
PN:501-1860-0101	MOS/MSC	07-Sep-16	-					N/A EQUIPMENT NOT INSTALLED
SN:1552	HRS	733.8						
	AFL	566						
PROC. REF: FAR FAR 91.411, AMM 34-15-01PROC. REF: FAR FAR 91.411, AMM 34-15-01								
341133	NO. 1 LOWER (ADC) AIR DATA COMPUTER							Component ATA:34
PN:822-0389-629	MOS/MSC	08-Nov-22	O/C					
SN:2VBTX	HRS	1247						
	AFL	971						
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01								
341133A	RECERTIFY NO. 1 LOWER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM							Service ATA:34
PN:822-0389-629	MOS	12-Nov-24	24		12-Nov-26		617 d	
SN:2VBTX	HRS	1375.9						
	AFL	1084						
Calibration Date: : 12-Nov-24								
PROC. REF: FAR FAR 91.411, AMM 34-17-00PROC. REF: FAR FAR 91.411, AMM 34-17-00								
341134	NO. 2 UPPER (ADC) AIR DATA COMPUTER							Component ATA:34
PN:822-0389-629	MOS/MSC	08-Nov-22	O/C	TSR 99				
SN:2C56L	HRS	1247		TSR 669.6				
	AFL	971		TSR 493				
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341134A	RECERTIFY NO. 2 UPPER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM							Service ATA:34
PN:822-0389-629	MOS	12-Nov-24	24		12-Nov-26		617 d	
SN:2C56L	HRS	1375.9						
	AFL	1084						
Calibration Date: : 12-Nov-24								
PROC. REF: FAR FAR 91.411, AMM 34-17-00PROC. REF: FAR FAR 91.411, AMM 34-17-00								
341222	ESIS CONFIGURATION MODULE							Component ATA:34
PN:501-1870-66	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1157	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341225	STANDBY AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01								
341401	RADIO ALTIMETER TRANSCEIVER							Component ATA:34
PN:822-0615-205	MOS/MSC	13-Dec-21	O/C					
SN:29V9B	HRS	1201.9						
	AFL							
PROC. REF: AMM 34-14-01PROC. REF: AMM 34-14-01								
341402	RADIO ALTIMETER CONVERTER							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02								
341403	AFT RADIO ALTIMETER ANTENNA							Component ATA:34
PN:622-0954-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2GGVG	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-14-03PROC. REF: AMM 34-14-03								
341404 FORWARD RADIO ALTIMETER ANTENNA								Component ATA:34
PN:622-0954-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2GGVD	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-03PROC. REF: AMM 34-14-03								
341703 FORWARD SIGNAL INTERFACE ADAPTER								Component ATA:34
PN:622-9732-003	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2FKTT	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02								
341704 AFT SIGNAL INTERFACE ADAPTER								Component ATA:34
PN:622-9732-003	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2FKTN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02								
341705 PILOT AIR DATA REFERENCE PANEL								Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-03PROC. REF: AMM 34-17-03								
341706 COPILOT AIR DATA REFERENCE PANEL								Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-03PROC. REF: AMM 34-17-03								
341707 TAT SENSOR PROBE								Component ATA:34
PN:102AU1AG	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:A67879	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-17-04PROC. REF: AMM 34-17-04								
341709	PRIMARY ADC SWITCHING UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-06PROC. REF: AMM 34-17-06								
341710	SECONDARY ADC SWITCHING UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-06PROC. REF: AMM 34-17-06								
341801	STANDBY MACH/AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01								
342001	MAGNETIC COMPASS MAGNETOMETER							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342025	AHRs COOLING FAN							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342055	NO. 1 FLUX DETECTOR UNIT							Component ATA:34
PN:622-5812-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:35622	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02								
342056	NO. 2 FLUX DETECTOR UNIT							Component ATA:34
PN:622-5812-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:35623	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02								
342057	NO. 1 INTERNAL COMPENSATOR (ICU-85) UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-04PROC. REF: AMM 34-26-04								
342058	NO. 2 INTERNAL COMPENSATOR (ICU-85) UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-04PROC. REF: AMM 34-26-04								
342301	STANDBY GYRO							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01								
342401	MAGNETIC COMPASS							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-24-01PROC. REF: AMM 34-24-01								
342410	NO. 1 ATTITUDE/HEADING (AHC-85E) COMPUTER							Component ATA:34
PN:822-1110-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2G19J	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01								
342411	NO. 2 ATTITUDE/HEADING (AHC-85E) COMPUTER							Component ATA:34
PN:822-1110-002	MOS/MSC	28-Nov-07	O/C					
SN:13CMV	HRS	135						
	AFL	93						
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01								
342412	NO. 1 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:34
PN:822-1200-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2G1BX	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-06PROC. REF: AMM 34-26-06								
342413	NO. 2 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000)							Component ATA:34
PN:822-1200-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2G1BW	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-06PROC. REF: AMM 34-26-06								
342501	STANDBY ATTITUDE DIRECTIONAL (ADI) INDICATOR							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-25-01PROC. REF: AMM 34-25-01								
342605	AUXILIARY SWITCHING UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03								
343007	MARKER BEACON (37X-2) ANTENNA							Component ATA:34
PN:522-0854-069	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:53707	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-51-04PROC. REF: AMM 34-51-04								
344007	NO. 1 GPS						Component	ATA:34
PN:822-1377-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:26XNF	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-54-02PROC. REF: AMM 34-54-02								
344008	NO. 2 GPS						Component	ATA:34
PN:822-1377-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2FTFC	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344111	LOWER TCAS DIRECTIONAL (TRE-920) ANTENNA						Component	ATA:34
PN:622-8973-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2FH5V	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344112	UPPER TCAS DIRECTIONAL (TRE-920) ANTENNA						Component	ATA:34
PN:622-8973-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2FHVL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344142	TCAS (TTR-920) PROCESSOR						Component	ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01								
344143	TCAS (TTR-4000) PROCESSOR						Component	ATA:34
PN:822-1294-032	MOS/MSC	26-Mar-21	O/C	TSN 163				
SN:153352	HRS	1109.9		TSN 1109.9				
	AFL	869		TSN 869				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01								
344151	STORMSCOPE PROCESSOR							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344153	STORMSCOPE DISPLAY							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344155	STORMSCOPE ANTENNA							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344171	NO. 1 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
344176	NO. 2 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
344201	EFIS RADAR (ERP) PANEL							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-61-07PROC. REF: AMM 34-61-07								
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA							Component ATA:34
PN:622-8440-004	MOS/MSC	29-Jun-12	O/C	TSO 0				
SN:33K6B	HRS	532.3		TSO 0				
	AFL	427		TSO 0				
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01								
344220	AV200 WSI ANTENNA							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344225	AV200 WSI SATELLITE RECEIVER							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344226	WSI RECEIVER MOUNT TRAY							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344513	TAWS COMPUTER							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344515	TAWS CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344520	TERRAIN AWARENESS ISOLATION BOX							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344806	WEATHER RADAR INDICATOR							Component ATA:34
PN:622-8440-003	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:279YH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344807	PILOT EFIS RADAR CONTROL PANEL							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-07PROC. REF: AMM 34-61-07								
344808	COPILOT EFIS RADAR CONTROL PANEL							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-07PROC. REF: AMM 34-61-07								
345001	NO. 1 ADF (ADF-462) RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:27XJP	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01								
345002	NO. 2 ADF (ADF-462) RECEIVER							Component ATA:34
PN:622-7382-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2D3XX	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01								
345005	ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER							Component ATA:34
PN:965-0976-040-226-226	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:25404	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01								
345010	AUX GPWS/WINDSHEAR INDICATOR							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345011	NO. 1 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	17-Jun-10	O/C	TSO 0				
SN:4T6F	HRS	510.5		TSO 0				
	AFL	414		TSO 0				
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01								
345012	NO. 2 DME TRANSCEIVER							Component ATA:34
PN:622-7309-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2D3RH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01								
345013	ADF, DUAL (ANT-462B) ANTENNA							Component ATA:34
PN:622-7384-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2D8MH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-02PROC. REF: AMM 34-57-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345021	NO. 1 VHF (VIR 432) RECEIVER							Component ATA:34
PN:622-7194-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:29TTL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01PROC. REF: AMM 34-51-01								
345022	NO. 2 VHF (VIR 432) RECEIVER							Component ATA:34
PN:622-7194-101	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:29TTY	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01PROC. REF: AMM 34-51-01								
345031	NO. 1 NAVIGATION COMPUTER							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-06PROC. REF: AMM 34-61-06								
345032	NO. 2 NAVIGATION COMPUTER							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-06PROC. REF: AMM 34-61-06								
345043	LEFT NAVIGATION (BLADE) ANTENNA							Component ATA:34
PN:DMN4-45	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10553	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345044	RIGHT NAVIGATION (BLADE) ANTENNA							Component ATA:34
PN:DMN4-45	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:10554	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345045	NO. 1 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345046	NO. 2 VHF/NAV ANTENNA							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345079	PRIMARY ATC TRANSPONDER							Component ATA:34
PN:GTX-3000	MOS/MSC	08-Nov-22	O/C					
SN:20S008676	HRS	1247						
	AFL	971						
PROC. REF: AMM 34-56-01PROC. REF: AMM 34-56-01								
345079A	TEST/INSPECT PRIMARY ATC TRANSPONDER							Service ATA:34
PN:GTX-3000	MOS	12-Nov-24	24	12-Nov-26		617 d		
SN:20S008676	HRS	1375.9						
	AFL	1084						
Calibration Date: : 12-Nov-24								
PROC. REF: AMM 34-56-00, FAR FAR 91.413PROC. REF: AMM 34-56-00, FAR FAR 91.413								
345080	SECONDARY ATC TRANSPONDER							Component ATA:34
PN:GTX-3000	MOS/MSC	08-Nov-22	O/C					
SN:20S008718	HRS	1247						
	AFL	971						
PROC. REF: AMM 34-56-01PROC. REF: AMM 34-56-01								
345080A	TEST/INSPECT SECONDARY ATC TRANSPONDER							Service ATA:34
PN:GTX-3000	MOS	12-Nov-24	24	12-Nov-26		617 d		
SN:20S008718	HRS	1375.9						
	AFL	1084						
Calibration Date: : 12-Nov-24								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-56-00, FAR FAR 91.413PROC. REF: AMM 34-56-00, FAR FAR 91.413								
345085	NO. 1 ATC TRANSPONDER CONTROL ADAPTER							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-03PROC. REF: AMM 34-56-03								
345086	NO. 2 ATC TRANSPONDER CONTROL ADAPTER							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-56-03PROC. REF: AMM 34-56-03								
345091	NO. 1 TRANSPONDER ANTENNA							Component ATA:34
PN:CI110-60-30	MOS/MSC	14-Oct-19	O/C					
SN:595083	HRS	976.1						
	AFL	766						
PROC. REF: AMM 34-56-02PROC. REF: AMM 34-56-02								
345092	NO. 2 TRANSPONDER ANTENNA							Component ATA:34
PN:CI110-60-30	MOS/MSC	14-Oct-19	O/C					
SN:595082	HRS	976.1						
	AFL	766						
PROC. REF: AMM 34-56-02PROC. REF: AMM 34-56-02								
345108	ADF PRIMARY ANTENNA							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-02PROC. REF: AMM 34-57-02								
345605	NO. 1 DME ANTENNA							Component ATA:34
PN:N813-9011	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:157973	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-55-02PROC. REF: AMM 34-55-02								
345606	NO. 2 DME ANTENNA							Component ATA:34
PN:N813-9011	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:157977	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-02PROC. REF: AMM 34-55-02								
346004	DATA BASE - DBU-4000 UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-04PROC. REF: AMM 34-60-04								
346007	DATA LOAD (DLP) PANEL							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-07PROC. REF: AMM 34-60-07								
346011	NO. 1 FLIGHT MANAGEMENT COMPUTER							Component ATA:34
PN:822-0891-027	MOS/MSC	28-Apr-15	O/C	TSR 0				
SN:45LNK	HRS	599.3		TSR 0				
	AFL	501		TSR 0				
PROC. REF: AMM 34-60-09PROC. REF: AMM 34-60-09								
346012	NO. 2 FLIGHT MANAGEMENT COMPUTER							Component ATA:34
PN:822-0891-027	MOS/MSC	28-Apr-15	O/C	TSR 0				
SN:2875X	HRS	599.3		TSR 0				
	AFL	501		TSR 0				
PROC. REF: AMM 34-60-09PROC. REF: AMM 34-60-09								
346015	NO. 1 FLIGHT MANAGEMENT SYSTEM CDU							Component ATA:34
PN:822-0884-364	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:27J7D	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-60-01, AMM 34-61-01PROC. REF: AMM 34-60-01, AMM 34-61-01								
346016	NO. 2 FLIGHT MANAGEMENT SYSTEM CDU							Component ATA:34
PN:822-0884-364	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:27J8L	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-01, AMM 34-61-01PROC. REF: AMM 34-60-01, AMM 34-61-01								
346017	NO. 3 FLIGHT MANAGEMENT SYSTEM CDU							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-01, AMM 34-61-01PROC. REF: AMM 34-60-01, AMM 34-61-01								
346021	PRIMARY FMS DATA TRANSFER (DTU) UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-04PROC. REF: AMM 34-61-04								
346022	SECONDARY FMS DATA TRANSFER (DTU) UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-04PROC. REF: AMM 34-61-04								
346025	NO. 1 FMS CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346026	NO. 2 FMS CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346031	PILOT ALTITUDE AWARENESS PANEL							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-03, AMM 34-61-03PROC. REF: AMM 34-60-03, AMM 34-61-03								
346032	COPILOT ALTITUDE AWARENESS PANEL							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-03, AMM 34-61-03PROC. REF: AMM 34-60-03, AMM 34-61-03								
346041	COURSE HEADING PANEL							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-60-02, AMM 34-61-02PROC. REF: AMM 34-60-02, AMM 34-61-02								
346055	CONFIGURATION, AFIS MODULE							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346071	UNILINK CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346090	AFIS DATA MANAGEMENT UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346091	DATA TRANSFER, AFIS UNIT							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346092	AFIS ANTENNA							Component ATA:34
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
347510	FORWARD GPS ANTENNA							Component ATA:34
PN:CI401-420	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:160957	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
347511	AFT GPS ANTENNA							Component ATA:34
PN:CI401-420	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:155721	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3411010 ^S	INSPECT PITOT TUBES, STATIC AND PITOT LINES, DRAIN LINES, AND WIRING FOR CONDITION AND SECURITY. CHECK STATIC PORTS AND PITOT/STAIC PROBES FOR DISTORTION. CHECK OPERATION OF DRAIN VALVES. (REFER TO 34-11-02)							Service ATA:34
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								

PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
H3411012 ^S	INSPECT AIR TEMPERATURE SENSOR OR AIR DATA COMPUTER STATIC, PITOT, AND DRAIN LINES FOR CONDITION AND SECURITY. CHECK OPERATION OF DRAIN VALVES.						Service	ATA:34
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
H3411031 ^S	PERFORM FUNCTIONAL TEST OF STATIC SHUTOFF (ISOLATION) VALVES. (REFER TO 34-11-00)						Service	ATA:34
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 34-11-00PROC. REF: AMM 34-11-00								PKG:7
K3411061 ^S	PITOT-STATIC PROBE HEATING CURRENT SENSING RELAY - PERFORM FUNCTIONAL TEST. (REFER TO 30-30-01)						Service	ATA:34
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								PKG:7
P3400004 ^S	INSPECT NOSE COMPARTMENT FROM THE FORWARD SIDE OF THE FORWARD PRESSURE BULKHEAD, FORWARD, FOR CLEANLINESS. ELECTRONIC AND ELECTRICAL EQUIPMENT AND ANTENNA INSTALLATIONS FOR SECURITY OF MOUNTING AND GENERAL CONDITION. WIRE BUNDLE AND PLUMBING ROUTING FOR SECURIT						Service	ATA:34
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
T3453003 ^S	INSPECT ANTENNA INSTALLATIONS FOR SECURITY, CORROSION, AND PROPER TENSION OF HF ANTENNA WIRE. (REFER TO 23-12-03.)						Service	ATA:34
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
U3411014 ^S	INSPECT PITOT STATIC PROBES - PERFORM PITOT-STATIC PROBE DRAIN HOLE CHECK. (REFER TO 34-11-02)							Service ATA:34
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 34-11-02PROC. REF: AMM 34-11-02								PKG:2
ATA 35 - OXYGEN								
350003	NOSE OXYGEN SYSTEM PRESSURE TRANSDUCER							Component ATA:35
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:NOT INSTALLED	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-02PROC. REF: AMM 35-00-02								
350004	DORSAL OXYGEN SYSTEM PRESSURE TRANSDUCER							Component ATA:35
PN:124058-2000	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:42917	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-02PROC. REF: AMM 35-00-02								
350005	NOSE OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY							Component ATA:35
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03								
350006	DORSAL OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY							Component ATA:35
PN:172180	MOS/MSC	14-Oct-19	O/C					
SN:0847	HRS	976.1						
	AFL	766						
PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03								
350007	NOSE OXYGEN PRESSURE INDICATOR							Component ATA:35
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: AMM 35-00-04PROC. REF: AMM 35-00-04								
350008	DORSAL OXYGEN PRESSURE INDICATOR							Component ATA:35
PN:820-707	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:365	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-04PROC. REF: AMM 35-00-04								
351001	PILOT OXYGEN MASK							Component ATA:35
PN:174262-11	MOS/MSC	05-Mar-21	O/C					
SN:23381	HRS							
	AFL							
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
351001A	OVERHAUL PILOT OXYGEN MASK							Service ATA:35
PN:174262-11	MOS	05-Mar-21	72 (+14d/-14d)		05-Mar-27	19-Mar-27	730 d (+14)	
SN:23381	HRS							
	AFL							
OverHaul Date:: 05-Mar-21								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
351002	COPILOT OXYGEN MASK							Component ATA:35
PN:174262-11	MOS/MSC	14-Oct-19	O/C	TSO 0				
SN:09443	HRS	976.1		TSO 0				
	AFL	766		TSO 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
351002A	OVERHAUL COPILOT OXYGEN MASK							Service ATA:35
PN:174262-11	MOS	14-Oct-19	72 (+14d/-14d)		14-Oct-25	28-Oct-25	223 d (+14)	
SN:09443	HRS							
	AFL							
OverHaul Date:: 14-Oct-19								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
351025	OXYGEN SYSTEM PRESSURE SWITCH							Component ATA:35
PN:P24028	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:4097	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-07PROC. REF: AMM 35-00-07								
351071	PILOT CREW OXYGEN MASK BOX							Component ATA:35
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
351072	COPILOT CREW OXYGEN MASK BOX							Component ATA:35
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
352000 ^{U S}	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM							Service ATA:35
	MOS	25-Jan-22					SMM	
	HRS	1207.3	600					
	AFL	939						
PKG:6								
352001 ^{U S}	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS							Service ATA:35
	MOS	25-Jan-22					SMM	
	HRS	1207.3	600					
	AFL	939						
PKG:6								
352006	NOSE OXYGEN CYLINDER							Component ATA:35
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
352007	DORSAL OXYGEN CYLINDER							Component ATA:35
PN:176194-76	MOS	07-Oct-23	288 (+14d/-14d)		01-Apr-32 (M)	15-Apr-32	2584 d (+14)	LIFE LIMIT
SN:0927-K944342	HRS	1309.3						
	AFL	1026						
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01								
352007A	HYDROSTATIC TEST DORSAL OXYGEN CYLINDER							Service ATA:35
PN:176194-76	MOS		36 (+14d/-14d)		01-Sep-26 (M)	15-Sep-26	545 d (+14)	
SN:0927-K944342	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
352027	PASSENGER OXYGEN CONTROL VALVE							Component ATA:35
PN:P21004-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0214	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-20-03PROC. REF: AMM 35-20-03								
352031	FORWARD SELECTOR, OXYGEN VALVE							Component ATA:35
PN:ZVC256	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-1018145	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05								
352032	AFT SELECTOR, OXYGEN VALVE							Component ATA:35
PN:ZVC256	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:07-0426336	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05								
352033	RIGHT AFT SELECTOR, OXYGEN VALVE							Component ATA:35
PN:ZVC179	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06-0210246	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-06PROC. REF: AMM 35-00-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
352040	PROTECTIVE BREATHING (PBE) EQUIPMENT							Component ATA:35
PN:802300-14	MOS	23-Aug-17	120 (+14d/-14d)	TSN 11	23-Sep-26	07-Oct-26	567 d (+14)	LIFE LIMIT
SN:E16090054	HRS	760.4						
	AFL	584						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353001	L1 OXYGEN MASK DROP BOX							Component ATA:35
PN:6025206042-049	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0548	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353002	R1 OXYGEN MASK DROP BOX							Component ATA:35
PN:6025206042-049	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0551	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353003	L2 OXYGEN MASK DROP BOX							Component ATA:35
PN:602520642-053	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0712	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353004	R3 OXYGEN MASK DROP BOX							Component ATA:35
PN:6025206042-049	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0555	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353005	L3 OXYGEN MASK DROP BOX							Component ATA:35
PN:6025206042-051	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0708	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
353006	R4 OXYGEN MASK DROP BOX							Component ATA:35
PN:602520642-051	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0709	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353007	R2 OXYGEN MASK DROP BOX							Component ATA:35
PN:6025206042-051	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0718	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3500020 ^S	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY.							Service ATA:35
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
P3510020 ^S	ON AIRCRAFT EQUIPPED WITH E.R.O.S. AVIATION CREW MASKS, PERFORM FUNCTIONAL TEST OF OXYGEN MASK. (REFER TO 35-10-01.)							Service ATA:35
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								PKG:13
T3500000 ^S	FUNCTIONAL TEST OF OXYGEN SYSTEM. (REFER TO 35-00-00.)							Service ATA:35
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
T3500010	^S	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY.						Service ATA:35
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
T3500040	^S	CHECK CREW MEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) FOIL POUCH FOR VACUUM SEAL INTEGRITY. IF VACUUM SEAL IS BROKEN, REPLACE EQUIPMENT.						Service ATA:35
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:7
ATA 36 - PNEUMATIC								
05-11-00-W3610011		REPLACE ENGINE BLEED AIR CHECK VALVES						Service ATA:36
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								
360001		REPLACE LEFT ENGINE PYLON BLEED AIR SEALS						Service ATA:36
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01								
360002		REPLACE RIGHT ENGINE PYLON BLEED AIR SEALS						Service ATA:36
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
360003	REPLACE TAILCONE BLEED AIR SEALS (LOCATED BETWEEN THE FORWARD BLEED AIR MANIFOLD AND AFT BLEED AIR MANIFOLD) (REFER TO 36-10-01)							Service ATA:36
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01								
361001	NO. 1 BLEED AIR REGULATING/SHUTOFF VALVE							Component ATA:36
PN:7608071-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:DUK0136	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04								
361002	NO. 2 BLEED AIR REGULATING/SHUTOFF VALVE							Component ATA:36
PN:7608071-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:DUK0137	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04								
361007	LEFT MIXING VALVE CONTROL BOX							Component ATA:36
PN:5418553-019	MOS/MSC	18-Apr-24	O/C					
SN:MRP623877-01(A)	HRS	1336.5						
	AFL	1050						
PROC. REF: AMM 36-10-05PROC. REF: AMM 36-10-05								
361008	RIGHT MIXING VALVE CONTROL BOX							Component ATA:36
PN:5418553-019	MOS/MSC	15-Jul-13	O/C	TSN 0				
SN:N/A	HRS	544		TSN 0				
	AFL	444		TSN 0				
PROC. REF: AMM 36-10-05PROC. REF: AMM 36-10-05								
361011	LEFT BLEED AIR MIXING VALVE							Component ATA:36
PN:1H106-9	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:11BB49	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361012	RIGHT BLEED AIR MIXING VALVE							Component ATA:36
PN:1H106-9	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:11BB50	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02								
361013	NO. 1 BLEED AIR CHECK VALVE							Component ATA:36
PN:6608295-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2955	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								
361014	NO. 2 BLEED AIR CHECK VALVE							Component ATA:36
PN:6608295-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2966	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								
361017	NO. 1 BLEED AIR (1 1/4) CHECK VALVE							Component ATA:36
PN:60160-10	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7578	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
361018	NO. 2 BLEED AIR (1 1/4) CHECK VALVE							Component ATA:36
PN:60160-10	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7574	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
361037	* NO. 1 EMERGENCY AIR BOTTLE (AWL*)							Component ATA:36
PN:6600194-008	MOS	24-Mar-23	180		01-Jan-38		4685 d	SCRAP
SN:01284	HRS	1280.7		TSN 0				
	AFL	1000		TSN 0				
Manufacture Date:: 01-Jan-23								
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361037A PERFORM * NO. 1 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST Service ATA:36								
PN:6600194-008	MOS	24-Mar-23	36 (+14d/-14d)		01-Jan-26 (M)	15-Jan-26	302 d (+14)	
SN:01284	HRS							
	AFL							
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361037B X-RAY INSPECT * NO. 1 EMERGENCY AIR BOTTLE Service ATA:36								
PN:6600194-008	MOS	24-Mar-23	36 (+14d/-14d)		01-Jan-26 (M)	15-Jan-26	302 d (+14)	
SN:01284	HRS							
	AFL							
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361038 * NO. 2 EMERGENCY AIR BOTTLE (AWL*) Component ATA:36								
PN:6600194-008	MOS	24-Mar-23	180		01-Jan-38		4685 d	SCRAP
SN:01283	HRS	1280.7		TSN 0				
	AFL	1000		TSN 0				
Manufacture Date:: 01-Jan-23								
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361038A PERFORM * NO. 2 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST Service ATA:36								
PN:6600194-008	MOS	24-Mar-23	36 (+14d/-14d)		01-Jan-26 (M)	15-Jan-26	302 d (+14)	
SN:01283	HRS							
	AFL							
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361038B PERFORM * NO. 2 EMERGENCY AIR BOTTLE X-RAY INSPECTION Service ATA:36								
PN:6600194-008	MOS	24-Mar-23	36 (+14d/-14d)		01-Jan-26 (M)	15-Jan-26	302 d (+14)	
SN:01283	HRS							
	AFL							
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
361125 LEFT TAILCONE BLEED AIR CHECK VALVE Component ATA:36								
PN:M942-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1315	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361126	RIGHT TAILCONE BLEED AIR CHECK VALVE							Component ATA:36
PN:M942-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1312	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
362001	LANDING GEAR/BRAKE AIR PRESSURE INDICATOR							Component ATA:36
PN:820-666	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:493	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01								
362003	PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER							Component ATA:36
PN:124058-5000	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:42913	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02								
362004	SECONDARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER							Component ATA:36
PN:124058-5000	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:42918	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02								
362011	NO. 1 ENGINE HI-LIMIT BLEED AIR THERMOSTAT							Component ATA:36
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03								
362012	NO. 2 ENGINE HI-LIMIT BLEED AIR THERMOSTAT							Component ATA:36
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
362019	NO. 1 INBOARD OVERHEAT SWITCH							Component ATA:36
PN:6600213-5	MOS/MSC	17-Feb-21	O/C	TSN 0				
SN:000785	HRS	1099.6		TSN 0				
	AFL	858		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
362020	NO. 2 INBOARD OVERHEAT SWITCH							Component ATA:36
PN:6600213-5	MOS/MSC	20-May-10	O/C	TSN 0				
SN:000652	HRS	506.9		TSN 0				
	AFL	413		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H3620001 ^S	FUNCTIONAL TEST OF PYLON OVERHEAT THERMOSTAT, DUCT TEMPERATURE SENSOR, AND ELECTRICAL SYSTEM. (REFER TO 36-20-03 AND 36-20-04.)							Service ATA:36
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 36-20-03, AMM 36-20-04PROC. REF: AMM 36-20-03, AMM 36-20-04								PKG:21
J3610037 ^S	VISUALLY INSPECT HIGH PRESSURE BLEED AIR CHECK VALVES							Service ATA:36
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								PKG:21
L3610039 ^S	PERFORM OPERATIONAL CHECK OF BLLED AIR CHECK VALVES. (REFER TO 36-10-03).							Service ATA:36
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
U3610044 ^S	GENERAL VISUAL INSPECTION BLEED AIR DUCTING (INCLUDING CLAMPS AND VALVES). (REFER TO 5-10-00)							Service ATA:36
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
ATA 38 - WATER/WASTE								
381008	LAVATORY SINK FAUCET							Component ATA:38
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
381009	FORWARD TOILET DRAIN, HEATED MAST							Component ATA:38
PN:116393-101E	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2064	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-32-01PROC. REF: AMM 38-32-01								
381010	AFT TOILET DRAIN, HEATED MAST							Component ATA:38
PN:116393-101	MOS/MSC	17-Dec-07	O/C					
SN:2297	HRS	150.5						
	AFL	109						
PROC. REF: AMM 38-32-01PROC. REF: AMM 38-32-01								
381020	TOILET WATER PUMP							Component ATA:38
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
381030	TOILET TIMER							Component ATA:38
PN:9060-2	MOS/MSC	17-Dec-07	O/C					
SN:T5066	HRS	150.5						
	AFL	109						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
381050	TOILET MACERATOR							Component ATA:38
PN:5300-1	MOS/MSC	08-Nov-22	O/C	TSN 0				
SN:M7457	HRS	1247		TSN 0				
	AFL	971		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
381060	LAVATORY ON-DEMAND WATER SYSTEM VOLTAGE REGULATOR							Component ATA:38
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
381070	LAVATORY SINK PUMP							Component ATA:38
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
382015	NO. 1 HOT WATER TANK							Component ATA:38
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
382016	NO. 2 HOT WATER TANK							Component ATA:38
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
383101	LAVATORY TOILET ASSEMBLY							Component ATA:38
PN:9060-20	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:U3183	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
PROC. REF: AMM 38-31-01PROC. REF: AMM 38-31-01								
ATA 44 - CABIN SYSTEMS								
441000	U S	FUNCTIONAL TEST OF THE PASSENGER ADDRESS SYSTEM					Service	ATA:44
	MOS	08-Nov-22					SMM	
	HRS	1247	300					
	AFL	971						
								PKG:5
442400	U S	GENERAL VISUAL INSPECTION OF THE SATELLITE RADIO SYSTEM					Service	ATA:44
	MOS						SMM	
	HRS		4800					
	AFL							
								PKG:7
442401		XM RADIO RECEIVER					Component	ATA:44
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-54-01PROC. REF: AMM 34-54-01								
442403		GPS/XM ANTENNA					Component	ATA:44
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
442900	U S	GENERAL VISUAL INSPECTION OF THE PASSENGER INFORMATION SYSTEM COMPONENTS					Service	ATA:44
	MOS						SMM	
	HRS		4800					
	AFL							
								PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 45 - CENTRAL MAINT SYSTEM									
451001	MAINTENANCE DIAGNOSTIC (MDC) COMPUTER							Component	ATA:45
PN:822-1987-005	MOS/MSC	28-Apr-15	O/C	TSO 45, TSR 0					
SN:28J7Y	HRS	599.3	TSO 87.1, TSR 0						
	AFL	501	TSO 86, TSR 0						
PROC. REF: AMM 45-10-00PROC. REF: AMM 45-10-00									
ATA 49 - AIRBORNE AUXILIARY POWER									
490020	APU - ESU - ELECTRONIC SENSOR UNIT							Component	ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	APUS	0	TSN 0						
490030	APU - SEAL PLATE							Component	ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	APUS	0	TSN 0						
490101	COCKPIT APU CONTROL PANEL							Component	ATA:49
PN:201-6-003-9	MOS/MSC	06-Nov-07	O/C	TSN 0					
SN:4872-42-1	HRS	108	TSN 0						
	AFL	76	TSN 0						
PROC. REF: GENERIC NO REF, SMM 49-01-01PROC. REF: GENERIC NO REF, SMM 49-01-01									
490102	APU RELAY BOX							Component	ATA:49
PN:201-6-028-9	MOS/MSC	22-Aug-07	O/C	TSN 0					
SN:AA1215010	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: GENERIC NO REF, SMM 49-01-02PROC. REF: GENERIC NO REF, SMM 49-01-02									
490103	(ESU / DESU) ELECTRONIC SEQUENCE UNIT							Component	ATA:49
PN:4506305	MOS/MSC	19-Jan-08	O/C	TSN 0					
SN:0013	HRS	201.1	TSN 0						
	AFL	134	TSN 0						
PROC. REF: GENERIC NO REF, SMM 49-01-03, SMM 49-01-04PROC. REF: GENERIC NO REF, SMM 49-01-03, SMM 49-01-04									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
490105	APU (GCU) GENERATOR CONTROL UNIT							Component ATA:49
PN:GCSG505-16G	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1198C	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-05PROC. REF: GENERIC NO REF, SMM 49-01-05								
490106	BITE ANNUNCIATOR BOX							Component ATA:49
PN:161212-100	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0630-0820	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-06PROC. REF: GENERIC NO REF, SMM 49-01-06								
490109	UPPER CURRENT TRANSFORMER							Component ATA:49
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-09PROC. REF: GENERIC NO REF, SMM 49-01-09								
490110	LOWER CURRENT TRANSFORMER							Component ATA:49
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
490111	CURRENT SENSOR							Component ATA:49
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-01-10PROC. REF: GENERIC NO REF, SMM 49-01-10								
492001	APU - COMBUSTOR HOUSING ASSEMBLY							Component ATA:49
PN:160541-102	MOS/MSC	28-Apr-07	O/C	TSN 0				
SN:C07-003	HRS	1.5		TSN 0				
	APUS	26		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
492002	APU - APU EXHAUST THERMOCOUPLE							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492010	APU - TURBINE NOZZLE							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492020	APU - IGNITER							Component ATA:49
PN:PN	MOS/MSC	11-Oct-21	O/C	TSN 0				
SN:UNKNOWN	HRS	862		TSN 0				
	APUS	1727		TSN 0				
492030	APU - OUTPUT GEAR							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492040	APU - BITE BOX							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492050	APU - SHAFT							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
492201	APU - ROTOR BEARING							Component ATA:49
PN:161623-1	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:F099	HRS	0		TSN 0				
	APUS	0		TSN 0				
492202	APU - ROTOR BEARING							Component ATA:49
PN:161623-1	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:F101	HRS	0		TSN 0				
	APUS	0		TSN 0				
492207	APU - HOUSING BEARING SUPPORT							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492208	APU - BEARING HOUSING ADAPTER							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
492300	APU - PRESSURE (LOW OIL) SWITCH							Component ATA:49
PN:4951600	MOS/MSC	19-Sep-06	O/C	TSN 0				
SN:322	HRS	0		TSN 0				
	APUS	0		TSN 0				
492320	APU - SPEED (MAGNETIC PICK-UP) SENSOR							Component ATA:49
PN:169080-1	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:B296	HRS	0		TSN 0				
	APUS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
493001	APU - FUEL CONTROL							Component ATA:49
PN:160962-6	MOS/MSC	28-Apr-07	O/C	TSN 0				
SN:15103743	HRS	1.5		TSN 0				
	APUS	26		TSN 0				
493003	APU - PUMP ASSEMBLY, FUEL CONTROL							Component ATA:49
PN:4502863C	MOS/MSC	28-Apr-07	O/C	TSN 0				
SN:04-07-06	HRS	1.5		TSN 0				
	APUS	26		TSN 0				
493005	APU - FUEL ATOMIZER INTERCONNECT HARNESS							Component ATA:49
PN:4505684	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:S207	HRS	0		TSN 0				
	APUS	0		TSN 0				
493007	APU - ASSEMBLY, FUEL ATOMIZER							Component ATA:49
PN:4504283A	MOS/MSC	11-Oct-21	O/C	TSR 0				
SN:10-07-31	HRS	862		TSR 0				
	APUS	1727		TSR 0				
493010	APU - HARNESS							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
493055	APU - ATOMIZER CUP MOTOR							Component ATA:49
PN:4951372	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:M540	HRS	0		TSN 0				
	APUS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
493101	APU FUEL SHUTOFF VALVE							Component ATA:49
PN:EM91-41	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:05-1004147	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-31-01PROC. REF: GENERIC NO REF, SMM 49-31-01								
493102	APU - FUEL PUMP							Component ATA:49
PN:161627-2	MOS/MSC	28-Apr-07	O/C	TSN 0				
SN:V60 T 0399	HRS	1.5		TSN 0				
	APUS	26		TSN 0				
493102	APU FUEL BOOST PUMP							Component ATA:49
PN:1500-00-22	MOS/MSC	15-Apr-19	O/C	TSO 0				
SN:2230	HRS	940.3		TSO 0				
	AFL	730		TSO 0				
PROC. REF: GENERIC NO REF, SMM 49-31-02PROC. REF: GENERIC NO REF, SMM 49-31-02								
494001	APU - IGNITION EXCITER							Component ATA:49
PN:4951302	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:06257015	HRS	0		TSN 0				
	APUS	0		TSN 0				
495001	APU - TURBINE WHEEL							Component ATA:49
PN:164253-3	MOS	25-Aug-06		TSN 0				LIFE LIMIT
SN:HA569	HRS	0		TSN 0				
	APUS	0	3500	TSN 0	3500		1565	
495005	APU - COMPRESSOR WHEEL							Component ATA:49
PN:160915-4	MOS	25-Aug-06		TSN 0				LIFE LIMIT
SN:H001B	HRS	0		TSN 0				
	APUS	0	7000	TSN 0	7000		5065	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
495010	APU - AIR INLET HOUSING							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
496103	APU FIRE HORN							Component ATA:49
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF, SMM 49-61-03PROC. REF: GENERIC NO REF, SMM 49-61-03								
497010	APU - HOURMETER/EVENT COUNTER INDICATOR							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
498010	EXHAUST (APU) DUCT							Component ATA:49
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
499010	APU - OIL PUMP GEAR							Component ATA:49
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
49APU1	APU							Component ATA:49
PN:4503134	MOS/MSC		E/C					
SN:SP-E060440	HRS							
WC#: 49.APU1	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
05-10-29-L5210025	VISUAL INSPECTION EXTERIOR LWR DOOR STRUCTURE/HINGE FOR CORROSION							Service ATA:52
	MOS	07-Oct-23	24 (+14d/-14d)	Adj 7d	14-Oct-25	28-Oct-25	223 d (+14)	
	HRS	1309.3						
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
521001	UPPER PASSENGER/CREW DOOR							Component ATA:52
PN:5410501-127	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:W262	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00PROC. REF: AMM 52-10-00								
521002	LOWER PASSENGER/CREW DOOR							Component ATA:52
PN:5410536-032	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:W370	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00PROC. REF: AMM 52-10-00								
521003	UPPER PASSENGER/CREW DOOR HANDLE							Component ATA:52
PN:6600480-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:390	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-02PROC. REF: AMM 52-10-02								
521004	UPPER PASSENGER/CREW DOOR LOCK ASSEMBLY							Component ATA:52
PN:AS848	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:SG5956022	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-03PROC. REF: AMM 52-10-03								
5210054	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE - REPLACE							Service ATA:52
	MOS	14-Oct-19	144 (+14d/-14d)		14-Oct-31	28-Oct-31	2414 d (+14)	
	HRS	976.1						
	AFL	766	6000 (+25/-25)		6766	6791	5672 (+25)	
PROC. REF: AMM 52-10-02, AMM 52-20-02PROC. REF: AMM 52-10-02, AMM 52-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
521006	UPPER PASSENGER/CREW DOOR DAMPER							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-06PROC. REF: AMM 52-10-06								
521008	LOWER PASSENGER/CREW DOOR HANDLE							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-08PROC. REF: AMM 52-10-08								
521010	FORWARD PASSENGER/CREW LOWER DOOR CABLE							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-10PROC. REF: AMM 52-10-10								
521011	AFT PASSENGER/CREW LOWER DOOR CABLE							Component ATA:52
PN:6015550-002	MOS/MSC	14-Oct-19	O/C	TSN 0				
SN:N/A	HRS	976.1		TSN 0				
	AFL	766		TSN 0				
PROC. REF: AMM 52-10-10PROC. REF: AMM 52-10-10								
521012	LOWER PASSENGER/CREW DOOR DAMPER							Component ATA:52
PN:1025-9400-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1178	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11								
522000	EMERGENCY EXIT / BAGGAGE DOOR							Component ATA:52
PN:6011501-015	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:W333	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
522002	EMERGENCY EXIT / BAGGAGE DOOR HANDLE							Component ATA:52
PN:ARS1411.1	MOS/MSC	14-Oct-19	O/C	TSN 0				
SN:UNKNOWN	HRS	976.1		TSN 0				
	AFL	766		TSN 0				
PROC. REF: AMM 52-20-02PROC. REF: AMM 52-20-02								
522005	PASSENGER DOOR FORWARD SNUBBER							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-15PROC. REF: AMM 52-10-15								
522006	PASSENGER DOOR AFT SNUBBER							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-15PROC. REF: AMM 52-10-15								
522007	EMERGENCY EXIT DOOR FORWARD SNUBBER							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07								
522008	EMERGENCY EXIT DOOR AFT SNUBBER							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07								
522025	EMERGENCY EXIT/BAGGAGE DAMPER							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
522032	EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06								
522032A	PRISM CHECK EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY 05-10-29-M5600008							Service ATA:52
PN:PN	MOS/MSC	05-Oct-14	C/C					
SN:UNKNOWN	HRS	578.5						
	AFL	480						
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
523101	TAILCONE BAGGAGE DOOR							Component ATA:52
PN:6011552-17	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7118265	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-01PROC. REF: AMM 52-31-01								
523102	TAILCONE BAGGAGE HANDLE							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-31-01PROC. REF: AMM 52-31-01								
524001	PERFORM AFT AVIONICS DOOR GAP AND MISMATCH INSPECTION (RVSM) (REFER TO 52-40-01)							Service ATA:52
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS	1375.9						
	AFL	1084						
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
524003	LEFT FORWARD NOSE AVIONICS DOOR							Component ATA:52
PN:6010430-003-903	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0283	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
524004	RIGHT FORWARD NOSE AVIONICS DOOR							Component ATA:52
PN:6010430-004-904	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0283	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
524005	LEFT AFT NOSE AVIONICS DOOR							Component ATA:52
PN:6010431-003-903	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0283	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
524006	RIGHT AFT NOSE AVIONICS DOOR							Component ATA:52
PN:6010431-004-904	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0283	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
524007	TAILCONE AVIONICS DOOR							Component ATA:52
PN:5412500-021	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0238	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02								
527005	CREW DOOR WARNING BOX ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-70-05PROC. REF: AMM 52-70-05								
527006	EMERGENCY EXIT DOOR WARNING BOX ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-70-05PROC. REF: AMM 52-70-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
528001	LEFT INBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
528002	RIGHT INBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
528003	LEFT OUTBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
528004	RIGHT OUTBOARD MAIN LANDING GEAR DOOR							Component ATA:52
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
528101	LEFT NOSE LANDING GEAR DOOR							Component ATA:52
PN:5410450-19	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:60-0328	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01								
528102	RIGHT NOSE LANDING GEAR DOOR							Component ATA:52
PN:5410450-20	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:60-0320	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
A5210030 ^S	REMOVE TENSION FITTINGS AND PLATES FROM PASSENGER/CREW DOORS (SIX [6] IN EACH DOOR). MAGNETIC PARTICLE INSPECT FOR EVIDENCE OF CRACKS. (REFER TO NDI MANUAL [NDI-2], PART 6, 52-10-01 AND 53-10-01.)							Service ATA:52
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
PROC. REF: NDT 52-10-01, NDT 53-10-01, AMM 52-10-17PROC. REF: NDT 52-10-01, NDT 53-10-01, AMM 52-10-17								PKG:25
AA5210056 ^S	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION							Service ATA:52
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:18
C5210052 ^S	UPPER AND LOWER DOOR HANDLE MECHANISM: GAIN ACCESS TO UPPER AND LOWER DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION.							Service ATA:52
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
C5220021 ^S	EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM; GAIN ACCESS TO EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION.							Service ATA:52
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 52-60-01PROC. REF: NDT 52-60-01								PKG:27
E5220010 ^S	EMERGENCY EXIT/BAGGAGE DOOR HINGE INSTALLATION FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT HINGE INSTALLATIONS WHILE RACKING THE DOOR WITH ALTERNATING LOADS.							Service ATA:52
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
E5220020 ^S	EMERGENCY EXIT/BAGGAGE DOOR HANDLE AND CONTROL ASSEMBLY FREE PLAY CHECK. OPEN DOOR AND REMOVE UPHOLSETRY TO GAIN ACCESS TO ROD CONTROL ASSEMBLY. RESTRAIN THE DOOR PINS AND MOVE THE EMERGENCY EXIT/BAGGAGE DOOR HANDLE TOWARD THE CLOSED POSITION AND THEN TO						Service	ATA:52
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 52-20-00PROC. REF: AMM 52-20-00								PKG:18
E5280002 ^S	VISUALLY INSPECT TAILCONE AVIONICS AND BAGGAGE DOOR ELECTRICAL BONDING JUMPERS, WHEN INSTALLED, FOR SECURITY AND GENERAL CONDITION						Service	ATA:52
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:6
H5210020 ^S	UPPER AND LOWER DOOR HINGE INSTALLATIONS FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT EDGES OF HINGE INSTALLATION WHILE RACKING THE DOORS WITH ALTERNATING LOADS. IF HINGE INSTALLATION CONDITION REQUIRES A MORE THO						Service	ATA:52
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
H5210040 ^S	CLEAN ARM GUIDES OF PASSENGER/CREW UPPER DOOR AND VISUALLY CHECK FOR CRACKS. (SEE FIGURE 1.)						Service	ATA:52
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
H5210060 ^S	INSPECT ENTIRE LENGTH OF LOWER DOOR CABLES FOR EVIDENCE OF FRAYING OR OTHER DAMAGE. DOOR ACCESS PANELS MUST BE REMOVED. (REFER TO 52-10-10)						Service	ATA:52
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:12

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
PROC. REF: AMM 52-10-10PROC. REF: AMM 52-10-10								
H5210065 ^S	CLEAN LATCH ARM OF PASSENGER/CREW LOWER DOOR AND VISUALLY INSPECT FOR CRACKS. (SEE FIGURE 1.)							Service ATA:52
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
H5210086 ^S	CHECK LOWER CABIN DOOR MECHANISM. OPEN UPPER AND LOWER CABIN DOORS. MOVE LOWER DOOR HANLE TOWARD THE DOOR PIN MOVEMENT. CHECK FOR SECURITY AND FREE PLAY IN MECHANISM. EXCESSIVE FREE PLAY MAY BE DUE TO MECHANISM FAILURE, EXCESSIVE WEAR, OR DEFORMATION. CHECK DOO							Service ATA:52
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
H5280001 ^S	VISUALLY INSPECT INBOARD AND OUTBOARD MAIN LANDING GEAR DOOR BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00)							Service ATA:52
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
K5210070 ^S	EDDY CURRENT INSPECT AROUND LOWER CABIN DOOR LATCH ARM FASTENERS AND PERIPHERY OF ARM PIN EYES FOR CRACKS. (REFER TO NDI MANUAL [NDI-2], PART 3, 52-10-01.)							Service ATA:52
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 52-10-01PROC. REF: NDT 52-10-01								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
P5210042 ^S	INSPECT CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR SEALS FOR ADHESIONS, CUTS, AND ABRASION; LATCH FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY.						Service	ATA:52
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
T5230011 ^S	VISUALLY INSPECT AVIONICS DOORS, HINGES, AND FASTENERS FOR GENERAL CONDITION, PROPER FIT, SEALS, ELECTRICAL BONDING, AND GENERAL CONDITION.						Service	ATA:52
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
T5240002 ^S	VISUAL INSPECTION SINGLE POINT REFUELING DOOR. (REFER TO 5-10-00)						Service	ATA:52
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
T5280000 ^S	VISUALLY INSPECT EMERGENCY EXIT/BAGGAGE DOOR ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00).						Service	ATA:52
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
T5280003 ^S	VISUALLY INSPECT NOSE AVIONICS DOOR AND NOSE LANDING GEAR DOOR ELECTRICAL BONDING JUMPERS FRO SECURITY AND GENERAL CONDITION.						Service	ATA:52
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
05-10-29-Y5331017	INSPECTION OF UPPER FUSELAGE SKIN UNDER THE AFT OXYGEN LINE FAIRING							Service ATA:53
	MOS	15-Oct-16	144 (+14d/-14d)		15-Oct-28	29-Oct-28	1320 d (+14)	
	HRS	733.8						
	AFL	566						
PROC. REF: AMM 53-50-06PROC. REF: AMM 53-50-06								
05-10-30-RVSM-N5313000	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (RVSM) (REFER TO 53-11-01)							Service ATA:53
	MOS	12-Nov-24	24 (+14d/-14d)	Adj -4d	08-Nov-26	22-Nov-26	613 d (+14)	
	HRS							
	AFL							
PROC. REF: AMM 53-11-01PROC. REF: AMM 53-11-01								
05-11-00-T5322000	REPLACE KEELBEAM ATTACHMENT BOLTS							Service ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)		14-Oct-31	28-Oct-31	2414 d (+14)	
	HRS	976.1						
	AFL	766	6000 (+25/-25)		6766	6791	5672 (+25)	
PROC. REF: AMM 53-10-02PROC. REF: AMM 53-10-02								
531001	AFT PRESSURE BULKHEAD							Component ATA:53
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-10-01PROC. REF: AMM 53-10-01								
534001	NO. 1 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								
534002	NO. 2 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
534003	NO. 1 ENGINE AFT ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								
534004	NO. 2 ENGINE AFT ENGINE MOUNT ATTACH FITTING							Component ATA:53
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								
535001	RADOME							Component ATA:53
PN:5410420-039-539	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:009R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01								
A5321060 ^S	WING/FUSELAGE FITTINGS: CLEAN AND VISUALLY INSPECT ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE). USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, VISUALLY INSPECT FITTINGS AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHE							Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
AA5323107 ^S	CIRCUMFERENTIAL SKIN SPLICES - CONDUCT AN X-RAY INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW: A. FRAMES 17, 20, 25, 26 AND 30. B. ON AIRCRAFT 60-002, FRAME 12. C. ON AIRCRAFT 60-003 AND SUBSEQUENT, FRAME 13. D. ON AIRCRAFT 60-002 THRU 60-093, FRAME 20B. CONDUCT SPECIFIC X-RAY INSPECTIONS OF THE CIRCUMFERENTIAL SKIN SPLICES IN THE PRESSURE CABIN ACROSS THE TOP OF THE FUSELAGE FROM STRINGER 8L TO 8R.							Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: NDT 53-20-02, NDT 53-20-03, NDT 53-20-04PROC. REF: NDT 53-20-02, NDT 53-20-03, NDT 53-20-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
B5331030 ^S	TAILCONE STRUCTURE (REFER TO 5-10-00.): CONDUCT A VISUAL INSPECTION OF THE TAILCONE STRUCTURE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. FROM THE TAILCONE ACCESS DOOR OPENING, VISUALLY INSPECT ACCESSIBLE AREAS						Service	ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C5314011 ^S	BELOW FLOORBOARD INSPECTION INSPECT FOR CORROSION, GENERAL CONDITION, AND FATIGUE CRACKS.						Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C5314040 ^S	EMERGENCY EXIT/BAGGAGE DOOR FUSELAGE FRAMING STRUCTURE: CONDUCT X-RAY INSPECTION OF FUSELAGE DOOR FRAMING STRUCTURE IN AREA OF BORDERING INNER SKIN. PAY PARTICULAR ATTENTION TO HINGES, HINGE ATTACHMENTS, CORNER DOUBLERS, AND THE LATCH PIN AND RECEPTACLE S						Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27
PROC. REF: NDT 52-60-01PROC. REF: NDT 52-60-01								
C5321000 ^S	FUSELAGE FRAMES AND STRINGERS: GAIN ACCESS TO ALL FUSELAGE FRAMES AND STRINGERS FROM FRAME 6 TO AFT PRESSURE BULKHEAD. CONDUCT AN INTERIOR VISUAL INSPECTION OF ALL FUSELAGE FRAMES AND STRINGERS. PARTICULAR ATTENTION SHOULD BE GIVEN TO ALL FRAME SPLICES. I						Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
C5321040	^S	WITH WING/FUSELAGE FAIRINGS REMOVED, USE FLASHLIGHT AND MIRROR TO VISUALLY INSPECT THE HONEYCOMB SUPPORT ANGLE SEGMENTS AT THE OUTBOARD ENDS OF THE FORWARD BAGGAGE FLOOR FOR FATIGUE CRACKS, CORROSION, FASTENER SECURITY, AND GENERAL CONDITION					Service	ATA:53
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
							PKG:25	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C5321055	^S	WING-TO-FUSELAGE ATTACHMENT FITTINGS: CLEAN AND VISUALLY INSPECT WITH THE AID OF 10X MAGNIFICATION, FLASHLIGHT, AND MIRROR, ALL EIGHT WING-TO-FUSELAGE ATTACHMENT FITTINGS. INSPECT FITTINGS AND SUPPORT STRUCTURE FOR CRACKS, CORROSION, MARKS, SCRATCHES, FAS					Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
							PKG:27	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D5321020	^S	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. TAP-TEST FLOOR PANEL, WHICH SUPPORTS THE ELECTRICAL EQUIPMENT, TO CHECK FOR UNBONDING OF UPPER SURFACE PLATE FROM THE HONEYCOMB CORE STRUCTURE. VISUALLY INSPECT FOR CORROSION, PARTICULARLY IN THE					Service	ATA:53
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
							PKG:25	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D5350020	^S	INSPECT UNDER WING KEELBEAM AND ATTACHMENTS FOR SECURITY, CORROSION, FASTENER CONDITION, FATIGUE CRACKS, AND PERMANENT DEFORMATION. ALSO INSPECT ATTACHING FITTINGS, FORWARD OF FRAME 24 AND AFT OF FRAME 31, FOR SIMILAR EFFECTS.					Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
							PKG:27	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
D5350051	^S	UNDERWING KEEL BEAM: VISUALLY INSPECT REMOVED ASSEMBLY FOR CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO END FITTINGS COMMON TO BEAM ASSEMBLY AS WELL AS THOSE MATING FITTINGS FORWARD OF FRAME 24 AND AFT OF FRAME 31. (REFER						Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
F5350010	^S	VISUALLY INSPECT KEELBEAM, FORWARD AND AFT ATTACH FITTINGS ON KEELBEAM AND ON AIRCRAFT, FOR CRACKS AND GENERAL CONDITION. (REFER TO 5-10-00.)						Service ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
G5321021	^S	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. VISUALLY INSPECT FLOOR PANEL WHICH SUPPORTS THE ELECTRICAL EQUIPMENT AND FRAMES 25, 26, AND 26A FOR CORROSION AND ANY OTHER DAMAGE.						Service ATA:53
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:8
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
G5321079	^S	AFT PRESSURE BULKHEAD REMOVE FUEL BLADDER AND VISUALLY INSPECT BULKHEAD FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, OR OTHER DAMAGE. VISUALLY INSPECT SUPPORTING STRUCTURE ALONG FLOOR, FRAME PERIPHERY, AND CENTERLINE BEAM FOR FATIGUE CRACKS, FASTENER SECURI						Service ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H5230020 ^S	INSPECT TAILCONE EQUIPMENT ACCESS AND TAILCONE BAGGAGE COMPARTMENT DOOR SEALS FOR CUTS, ADHESION, AND ABRASION; LOCKING MECHANISM FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY.						Service	ATA:53
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
H5311000 ^S	INSPECT NOSE GEAR SUPPORT INSTALLATION FOR SECURITY, FASTENER CONDITION, PANEL FATIGUE CRACKS, PERMANENT DEFORMATION AT TRUNNION FITTINGS, ACTUATOR ATTACHMENT SUPPORT STRUCTURE AREAS, AND GENERAL CONDITION.						Service	ATA:53
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23
H5314031 ^S	FRAMING MEMBERS OF PASSENGER/CREW AND EMERGENCY EXIT/BAGGAGE DOORS AND SURROUNDING FUSELAGESTRUCTURE FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION.						Service	ATA:53
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
H5321014 ^S	IF INSTALLED, INSPECT ACCESSIBLE AREAS AROUND THE GALLEY, POTTY, AND LAVATORY FOR EVIDENCE OF SPILLAGE. INVESTIGATE FURTHER IF EVIDENCE OF SPILLAGE IS FOUND.						Service	ATA:53
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:8
H5321039 ^S	VISUALLY INSPECT LOWER LONGERON IN REGION OF WING FOR FATIGUE CRACKS, PERMANENT DEFORMATION, AND GENERAL CONDITION.						Service	ATA:53
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H5321042 ^S	BAGGAGE FLOOR/OVER WING AREA: A. INSPECT ENTIRE AREA FOR CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT THE SEGMENTED HONEYCOMB FLOOR SUPPORT ANGLES AT THE OUTBOARD EDGES FOR FATIGUE CRACKS, FASTENER SECURITY, AND GENERAL CONDITION. B. INSPECT FRAME							Service ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
H5321048 ^S	BAGGAGE FLOOR/OVER WING AREA (REFER TO 5-10-00.) A. SUPPORT STRUCTURE FOR WING-TO-FUSELAGE FITTINGS. AT EACH LOCATION (SPAR/FRAME) 2/25, 5/27, 7/29, AND 8/30)8 LOCATIONS TOTAL) INSPECT FUSELAGE FRAME STRUCTURE FOR CRACKS, CORROSION, FASTENER CONDITION, P							Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28
H5321049 ^S	VISUALLY INSPECT OVERWING CUTOUT RADIUS AT FS 346 AND FS 421 (FRAMES 24 AND 31 FUSELAGE SKIN PANELS). (REFER TO 5-10-00.)							Service ATA:53
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
H5321050 ^S	INSPECT ACCESSIBLE PORTIONS OF LOWER CAP OF THE FRAME 26A AREA, AND ADJACENT FLOOR STRUCTURE, FRAME 24-26A. VISUALLY INSPECT FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)							Service ATA:53
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:17

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
H5323011	^S	INSPECT CORNER OF DOORS FOR FASTENER SECURITY AND GENERAL CONDITION.						Service ATA:53
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:12
H5331010	^S	INSPECT BULKHEADS, FRAMES, AND STIFFENERS IN THE TAILCONE FOR FASTENER SECURITY, CRACKS, AND GENERAL CONDITION.						Service ATA:53
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
H5331020	^S	INSPECT CANTED BULKHEADS AND LOWER VERTICAL STABILIZER ATTACHMENTS IN THE AFT TAILCONE FOR FASTENER SECURITY AND PERMANENT DEFORMATION AT BULKHEADS AND SPAR ASSEMBLIES.						Service ATA:53
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:21
J5340001	^S	EDDY CURRENT FORWARD BEAM SUPPORT FITTING. (REFER TO NDI MANUAL [NDI-2], PART 3, 53-40-01.)						Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 53-40-01PROC. REF: NDT 53-40-01								PKG:28
J5340002	^S	VISUAL INSPECTION FORWARD ENGINE BEAM ASSEMBLY. (REFER TO 5-10-00.)						Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
J5340003 ^S	VISUAL INSPECTION FORWARD ENGINE BEAM STABILIZER STRUCTURE. (REFER TO 5-10-00.)							Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28
J5340004 ^S	EDDY CURRENT AFT BEAM SUPPORT FITTING - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 53-40-02.)							Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 53-40-02PROC. REF: NDT 53-40-02								PKG:28
J5340005 ^S	VISUAL INSPECTION AFT ENGINE BEAM - PERFORM VISUAL INSPECTION. (REFER TO 5-10-00.)							Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28
J5340006 ^S	VISUAL INSPECTION AFT ENGINE BEAM AND FRAME STRUCTURE - PERFORM VISUAL INSPECTION. (REFER TO 5-10-00.)							Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28
K5321081 ^S	VISUALLY INSPECT FORWARD PRESSURE BULKHEAD FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION.							Service ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
L5321085 ^S	FORWARD PRESURE BULKHEAD: VISUALLY INSPECT FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION. GAIN ACCESS TO THE FORWARD SIDE OF THE FORWARD PRESSURE B						Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
M5323065 ^S	CIRCUMFERENTIAL SKIN SPLICES: CONDUCT A GENERAL VISUAL INTERNAL AND EXTERNAL INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW: A. FRAMES 8, 17, 20, 25, AND 26. B. ON AIRCRAFT 60-002, FRAME 12. C. ON AIRCRAFT 60-003 AND SUBSEQUENT,						Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
M5323106 ^S	LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) : A. CONDUCT AN INTERNAL AND EXTERNAL VISUAL INSPECTION OF THE LONGITUDINAL SKIN SPLICES ALONG THE MAIN "T" STRINGERS AT STRINGERS 4L, 6L, 7AL, 18L, 23L, 2R, 6R, 8R, AND 18R. (REFER TO 5-10-00.)						Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
M5323108 ^S	LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) - PERFORM AN X-RAY INSPECTION OF THE LONGITUDIAL SKIN SPLICES ALONG THE "T" STRINGERS AT STRINGERS 4L, 6L, 18L, 23L, 2R, 6R, AND 18R. (REFER TO NDI MANUAL [NDI-2], PART 2, CHAPTER 53-20-05, 53-20-06, 53-20-07, 53						Service	ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 53-20-05, NDT 53-20-06, NDT 53-20-07, NDT 53-20-08, NDT 53-20-09, NDT 53-20-10PROC. REF: NDT 53-20-05, NDT 53-20-06, NDT 53-20-07, NDT 53-20-08, NDT 53-20-09, NDT 53-20-10								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
N5323010 ^S	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00)							Service ATA:53
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2
N5323012 ^S	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00)							Service ATA:53
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2
O5331035 ^S	REMOVE TAIL CONE ACCESS PLATES AND USE A FLASHLIGHT AND MIRROR TO INSPECT INTERNAL TAIL CONE STRUCTURE IN AREA WHERE THE VERTICAL STABILIZER SPARS ATTACH TO THE CANTED FUSELAGE FRAMES. CHECK FOR ATTACHMENT SECURITY, FRAME CRIPPLING, CORROSION, AND FATIGUE CRACKS							Service ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28
P5311006 ^S	REMOVE NOSE GEAR TRUNNION FITTINGS AND VISUALLY INSPECT NOSE GEAR TRUNNION FITTING AREA IN FORWARD FUSELAGE FOR CRACKS, CORROSION, AND PERMANENT DEFORMATION. EDDY CURRENT INSPECT NOSE GEAR TRUNNION FITTING ATTACH HOLES AND TRUNNION AXLE BOSS. (REFER TO NDI MANUA							Service ATA:53
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)					
PROC. REF: NDT 53-61-02PROC. REF: NDT 53-61-02								PKG:26
P5311007 ^S	EDDY CURRENT INSPECT UPPER ATTACHEMNET AREA OF NOSE GEAR ACTUATOR FOR CRACKS, CORROSION, PERMANENT DEFORMATION, AND ATTACHMENY FITTING SECURITY. (REFER TO NDI MANUAL [NDI-2], PART 3, 56-60-01.)							Service ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: NDT 53-60-01PROC. REF: NDT 53-60-01								
P5320008	^S	INSPECT CENTER PEDESTAL AND EQUIPMENT FOR SECURITY AND GENERAL CONDITION. SPOILER, THROTTLE, AND FLAP CONTROLS FOR GENERAL CONDITION AND SERVICEABILITY.					Service	ATA:53
	MOS	12-Nov-24	12	(+14d/-14d)				
	HRS	1375.9	300	(+25/-25)				
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P5321087	^S	AFT PRESSURE BULKHEAD A. GAIN ACCESS TO AND REMOVE AFT PRESSURE BULKHEAD. B. EDDY CURRENT INSPECT THE FORWARD FRAME FLANGE OF FRAM 26A AFT PRESSURE BULKHEAD. (REFER TO NDI MANUAL [NDI-2], PART 3, CHAPTER 53-20-01 AND 53-20-05.) C. EDDY CURRENT INSPECT SUP					Service	ATA:53
	MOS	22-Aug-07						
	HRS	0	T:12000	(+25/-25)				
	AFL	0						
PROC. REF: NDT 53-20-01, NDT 53-20-02, NDT 53-20-03, NDT 53-20-04, NDT 53-20-05PROC. REF: NDT 53-20-01, NDT 53-20-02, NDT 53-20-03, NDT 53-20-04, NDT 53-20-05								
P5323162	^S	VISUALLY INSPECT EXTERNAL LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR EVIDENCE OF FATIGUE CRACKS, WORKING RIVETS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)					Service	ATA:53
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000	(+25/-25)				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
S5230021	^S	OPERATIONAL CHECK OF TAILCONE BAGGAGE AND TAILCONE ACCESS DOOR WARNING SYSTEMS. (REFER TO 52-70-00).					Service	ATA:53
	MOS	12-Nov-24	24	(+14d/-14d)				
	HRS	1375.9	600	(+25/-25)				
	AFL	1084						
PROC. REF: AMM 52-70-00PROC. REF: AMM 52-70-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
S5314070 ^S	UPPER AND LOWER CABIN DOOR HINGES AND FUSELAGE FRAMING STRUCTURE: A. VISUALLY INSPECT ACCESSIBLESTRUCTURE FOR SECURITY, GENERAL CONDITION, EXCESSIVE WEAR OR LOOSENESS, AND FATIGUE CRACKS. (REFER TO 5-10-00.) B. CONDUCT X-RAY INSPECTION OF UPPER AND LOWER						Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 52-20-01PROC. REF: NDT 52-20-01								PKG:27
S5323158 ^S	INSPECT EXTERIOR OF THE SKIN, GIVING PARTICULAR ATTENTION TO LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR FASTENER CONDITION, FATIGUE CRACKS, AND GENERAL SPLICE CONDITION.						Service	ATA:53
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:20
T5321013 ^S	INSPECT ACCESSIBLE PORTION OF FRAME 26A AREA VISIBLE THROUGH WHEEL WELLS FOR FATIGUE CRACKS, PERMANENT DEFORMATION, SECURITY, AND GENERAL CONDITION.						Service	ATA:53
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
T5321093 ^S	INSPECT TAILCONE BAGGAGE COMPARTMENT UPHOLSTERY FOR CUTS, TEARS , AND GENERAL CONDITION.						Service	ATA:53
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
U5323146 ^S	SKIN CUTOUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT SKIN PENETRATIONS AND CUTOUTS FOR ANTENNAS AND ELECTRICAL COMPONENTS. (REFER TO 5-10-00.)						Service	ATA:53
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
U5331012	* REMOVE ACCESS PANELS (TOP OF FUSELAGE) AND PERFORM VISUAL INSPECTION OF ELECTRICAL BOXES FOR SECURITY OF ATTACHMENT, CORROSION, AND GENERAL CONDITION. INSPECT DOUBLERS, FUSELAGE SKIN, INTERIOR FRAMES, AND INTERCOSTALS FOR FATIGUE CRACKS AND GENERAL CONDITION. (AWL*)							Service ATA:53
	MOS	11-Oct-21	49		11-Nov-25		251 d	AIRWORTHINESS
	HRS	1173.5						
	AFL	920						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

U5360005 ^S	GENERAL VISUAL INSPECTION RADOME AND LIGHTNING DIVERTER STRIPS. (REFER TO 5-10-00)							Service ATA:53
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:2

ATA 54 - NACELLES/PYLONS

H5450000 ^S	CHECK PYLON FIREWALLS FOR CRACKS, CONDITION OF FIREWALL SEALANT, SECURITY OF HYDRAULIC AND FUEL CONNECTIONS, ELECTRICAL AND MECHANICAL FEED-THROUGHS, AND CONDITION OF BLEED AIR FLANGE GASKETS.							Service ATA:54
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9

H5450002 ^S	VISUAL INSPECTION ENGINE SUPPORT STRUCTURE. (REFER TO 5-10-00.)							Service ATA:54
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28

K5450010 ^S	INSPECT PYLON BEAMS FOR CRACKS, FASTENER CONDITION, ATTACHMENT TO FUSELGAE FRAMES, AND GENERAL CONDITION OF FITTINGS. REMOVE UPPER AND LOWER PYLON ACCESS COVERS FOR COMPLETE INSPECTION.							Service ATA:54
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 55 - STABILIZERS								
5520020 ^S	ELEVATOR (REMOVED FROM HORIZONTAL STABILIZER) (REFER TO 5-10-00.): A. CLEAN HINGE LOCATIONS AND VISUALLY INSPECT LOCAL STRUCTURE USING PROPER LIGHTING AND 10X MAGNIFICATION. INSPECT HINGE SUPPORT STRUCTURE FOR DEFORMATION, CORROSION, LOOSE OR WORKING FAST						Service	ATA:55
	MOS	22-Aug-07						
	HRS	0	T:12000 (+14/-14)					
	AFL	0						
								PKG:28
PROC. REF: NDT 55-20-01PROC. REF: NDT 55-20-01								
553001	VERTICAL STABILIZER						Component	ATA:55
PN:5431000-030	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:W519	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
A5510061 ^S	HORIZONTAL STABILIZER (DETACHED FROM VERTICAL STABILIZER): A. CONDUCT A GENERAL VISUAL INSPECTION OF THE STABILIZER ASSEMBLY INCLUDING UPPER AND LOWER SKIN SPLICES AT BL 4.5 RIB, ACCESSIBLE PORTIONS OF FRONT AND REAR SPAR INSTALLATIONS, ELEVATOR HINGE SUP						Service	ATA:55
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
A5510062 ^S	CLEAN AND VISUALLY INSPECT THE HINGE PIN FOR WEAR AND CORROSION (INCLUDING THE INTERNAL SURFACE OF THE PIN). APPLY A COAT OF EPOXY PRIMER TO THE INTERNAL SURFACE OF THE PIN PRIOR TO REINSTALLATION. (REFER TO 5-10-00.) MAGNETIC PARTICLE INSPECT PIN FOR CRACKS.						Service	ATA:55
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: NDT 55-30-01PROC. REF: NDT 55-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
AD5510095 ^S	HORIZONTAL STABILIZER (WITH ELEVATOR REMOVED) – PERFORM DETAILED VISUAL INSPECTION OF THE HORIZONTAL STABILIZER REAR SPAR AND ASSOCIATED STRUCTURE FROM BL 65.60 TO BL 81.00 FOR DEFORMATION, CORROSION, LOOSE OR WORKING FASTENERS AND FATIGUE CRACKS							Service ATA:55
	MOS	22-Aug-07	144					
	HRS	0						
	AFL	0	6000					
								PKG:27
B5530010 ^S	VERTICAL STABILIZER (ATTACHE DTO FUSELAGE) (REFER TO 5-10-00.): A. CONDUCT A GENERAL VISUAL INSPECTION OF THE VERICAL STABILIZER ABOVE THE FUSELAGE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION. LOOSE OR WORKING FASTENERS, FATIGUE CRACKS, AND GENERAL C							Service ATA:55
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
B5540020 ^S	RUDDER (REMOVED FROM VERTICAL STABILIZER) (REFER TO 5-10-00.) A. CLEAN HINGE LOCATIONS AND VISUALLY INSPECT LOCAL STRUCTURE USING PROPER LIGHTING AND 10X MAGNIFICATION. INSPECT HIMGE SUPPORT STRUCTURE FOR DEFORMATION, CORROSION, AND FATIGUE CRACKS. (INCLU							Service ATA:55
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C5510050 ^S	HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER) (REFER TO 5-10-00.) A. WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LB.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FIT							Service ATA:55
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
E5510040 ^S	WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCTURE ATTACHING BOLTS, AND BOLT RETAINERS FOR WEAR, LOOSENE							Service ATA:55
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
E5520010 ^S	WITH CONTROL COLUMN FIXED, APPLY ALTERNATE UP AND DOWN LOADS TO THE ELEVATOR TRAILING EDGE. INSPECT EACH ELEVATOR HINGE LOCATION FOR LOOSENESS, FREE PLAY, FATIGUE CRACKS, AND GENERAL SECURITY.							Service ATA:55
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
E5540010 ^S	WITH RUDDER PEDALS RESTRAINED, APPLY ALTERNATING LEFT AND RIGHT LOADS TO THE RUDDER TRAILING EDGE. OBSERVE RUDDER HINGE FITTING ATTACHMENTS FOR LOOSENESS, FREE PLAY, AND GENERAL SECURITY.							Service ATA:55
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18
H5510031 ^S	REMOVE ACCESS PANELS AND INSPECT UPPER AND LOWER FLANGES OF HORIZONTAL STABILIZER RIBS AT RIGHT AND LEFT BUTT LINE 19.4 FOR CRACKS.							Service ATA:55
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H5510035 ^S	INSPECT HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS (INCLUDING ATTACH BOLTS), SUPPORT STRUCTURE, AND ATTACH BOLT RETAINING CLIPS (IF INSTALLED) FOR CRACKS, FASTENER CONDITION, SECURITY, WEAR, AND GENERAL CONDITION.						Service	ATA:55
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5520000 ^S	ELEVATOR: WITH PUSH-PULL TUBES DISCONNECTED FROM ELEVATOR BELLCRANKS, MOVE EACH ELEVATOR SURFACE THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR SMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, RUST OR CORROSION, TURNING ON BOLT RATHER THAN BEA						Service	ATA:55
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:24
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5530001 ^S	VERTICAL STABILIZER FOR CRACKS, FASTENER CONDITION, AND SECURITY AT ATTACH POINTS, AND STRUCTURE IN AREA OF HORIZONTAL STABILIZER ATTACH FITTINGS.						Service	ATA:55
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H5540011 ^S	RUDDER: WITH CABLES DISCONNECTED AT AFT BELLCRANK LOCATION, MOVE RUDDER THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR AMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, TURNING ON BOLT RATHER THAN BEARING, RUST OR CORROSION, AND GENERAL CONDITI						Service	ATA:55
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:24
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
H5560001	^S	VISUALLY INSPECT THE DELTA FIN SURFACES. REMOVE TAILCONE ACCESS COVERS AND VISUALLY INSPECT SUPPORT STRUCTURE FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, PERMANENT DEFORMATION, AND CORROSION. INSPECT UPPER AND LOWER SURFACES, PAYING PARTICULAR ATTENTION TO THE TAILCON					Service	ATA:55
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:21
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
M5530003	^S	VERTICAL STABILZER (ATTACHED TO FUSELAGE) (REFER TO 5-10-00.) A. CONDUCT A VISUAL INSPECTION OF THE VERTICAL STABILIZER ABOVE THE FUSLEAGE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, LOSE OR WORKING FASTENERS, FATIGUE CRACKS, AND GENERAL CONDITION.					Service	ATA:55
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
O5510060	^S	HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER): WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCT					Service	ATA:55
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P5510089	^S	CONDUCT A THOROUGH EXTERNAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER FORWARD AND REAR SPAR CAPS (UPPER AND LOWER) FOR CORROSION, INTEGRITY OF PAINT, AND GENERAL CONDITION. (ELEVATOR REMOVAL NOT REQUIRED.) (REFER TO 5-10-00)					Service	ATA:55
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
								PKG:6
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
T5500002	^S	INSPECT RUDDER, RUDDER TAB, AND ELEVATOR HINGE POINTS FOR EVIDENCE OF WEAR, SECURITY, AND GENERAL CONDITION. WHEN INSTALLING VERTICAL STABILIZER AFT FAIRING, ENSURE THAT ELEVATOR TO FAIRING CLEARANCE IS 0.31 (+0.12) INCH [7.9 (+3) MM].						Service ATA:55
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:18
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U5500000	^S	GENERAL VISUAL INSPECTION FILLETS, FAIRINGS, AND SKINS. (REFER TO 5-10-00)						Service ATA:55
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
								PKG:6
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U5560000	^S	GENERAL VISUAL INSPECTION DELTA FINS. (REFER TO 5-10-00)						Service ATA:55
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 56 - WINDOWS								
05-10-29-C5610022L		LEFT WINDSHIELD PRISM CHECK						Service ATA:56
PN:6600394-609	MOS/MSC	07-Oct-23	C/C					
SN:473	HRS							
	AFL							
PROC. REF: NDT 56-10-01PROC. REF: NDT 56-10-01								
05-10-29-C5610022R		RIGHT WINDSHIELD PRISM CHECK						Service ATA:56
PN:6600394-608	MOS/MSC	07-Oct-23	C/C					
SN:458	HRS							
	AFL							
PROC. REF: NDT 56-10-01PROC. REF: NDT 56-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
561001	LEFT WINDSHIELD ASSY							Component ATA:56
PN:6600394-609	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:473	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01								
561002	RIGHT WINDSHIELD ASSY							Component ATA:56
PN:6600394-608	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:458	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01								
561009	LEFT COCKPIT CREW WINDOW							Component ATA:56
PN:6600512-001	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:187	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02PROC. REF: AMM 56-10-02								
561010	RIGHT COCKPIT CREW WINDOW							Component ATA:56
PN:6600512-002	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:194	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-10-02PROC. REF: AMM 56-10-02								
562011	LEFT NO. 1 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562011A	PRISM CHECK LEFT NO. 1 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562013	LEFT NO. 2 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562013A	PRISM CHECK LEFT NO. 2 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562015	LEFT NO. 3 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562015A	PRISM CHECK LEFT NO. 3 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562017	LEFT NO. 4 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562017A	PRISM CHECK LEFT NO. 4 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562019	LEFT NO. 5 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562019A	PRISM CHECK LEFT NO. 5 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562022	RIGHT NO. 1 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562022A	PRISM CHECK RIGHT NO. 1 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562024	RIGHT NO. 2 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562024A	PRISM CHECK RIGHT NO. 2 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562026	RIGHT NO. 3 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562026A	PRISM CHECK RIGHT NO. 3 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562028	RIGHT NO. 4 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562028A	PRISM CHECK RIGHT NO. 4 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								
562030	RIGHT NO. 5 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562030A	PRISM CHECK RIGHT NO. 5 CABIN WINDOW 05-10-29-M5600008							Service ATA:56
PN:PN	MOS/MSC	07-Oct-23	C/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: NDT 56-30-01PROC. REF: NDT 56-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
H5610024 ^S	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE) A. CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS. B. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS FOR DELAMINATION, CHIPPING,							Service ATA:56
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
H5620000 ^S	PERFORM AN EXTERNAL VISUAL INSPECTION OF THE CABIN WINDOWS AND RETAINERS FOR GENERAL CONDITION, SECURITY, AND CLEANLINESS. INSPECT INTERNAL AND EXTERNAL SURFACES OF THE CABIN WINDOWS FOR SCRATCHES, PITS, OR OTHER DAMAGE. (REFER TO 56-20-01)							Service ATA:56
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								PKG:8
M5610010 ^S	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE): (A.) CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS IN ACCORDANCE WITH CHAPTER 12. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS FOR DELAMINATION, CHIPPING, CRAZING, CRACKS, GOUGES, HEAT DAMAGE IN THE EXTERNAL DEFOG AREA, AND GENERAL CONDITION. (B.) CONDUCT AN X-RAY INSPECTION OF THE WINDSHIELD SUPPORTING STRUCTURE. REMOVAL NOT REQUIRED UNLESS X-RAY INDICATES POSSIBLE CRACKS. (C.) EDDY CURRENT INSPECT OUTER RETAINER.							Service ATA:56
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 56-20-01, NDT 56-20-01PROC. REF: NDT 56-20-01, NDT 56-20-01								PKG:27
M5620001 ^S	CABIN WINDOWS AND FRAMING MEMBERS: A. VISUALLY INSPECT ACCESSIBLE STRUCTURE FOR SECURITY, GENERAL CONDITION, AND FATIGUE CRACKS. (REFER TO 5-10-00.) B. CONDUCT X-RAY INSPECTION OF SUPPORT STRUCTURE. (REFER TO NDI MANUAL [NDI-2], PART 2, 56-50-01.)							Service ATA:56
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 56-50-01PROC. REF: NDT 56-50-01								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
T5610002	^S	INSPECT INTERIOR AND EXTERIOR OF WINDSHIELD FOR CRAZING, INCLUDING VISIBLE PORTION UMDER RETAINERS FOR CRACKS, CLEANLINESS, SECURITY, AND GENERAL CONDITION. AREA UNDER ANTI-ICE DUCT SHALL BE INSPECTED BY VIEWING THE EPOXY-PRIMED OUTER SURFACE OF THE WINDSHIELD FR						Service ATA:56
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:14
PROC. REF: AMM 12-24-00, AMM 12-25-00PROC. REF: AMM 12-24-00, AMM 12-25-00								
T5620007	^S	CABIN WINDOWS: USING PRISM TECHNIQUES, INSPECT WINDOWS FOR CRACKS, CHIPS, DELAMINATION, OR OTHER DAMAGE. THIS INSPECTION IS ALSO CAPABLE OF VISUALLY ASSESSING THE CONDITION OF THE ATTACHING FASTENERS. BROWN DISCOLORATIONS IN THE AREA OF THE FASTENERS MAY						Service ATA:56
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
								PKG:24
ATA 57 - WINGS								
05-10-29-L5720012L		PERFORM LEFT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	T:10000 (+25/-25)		10000	10025	8906 (+25)	
PROC. REF: NDT 57-40-03PROC. REF: NDT 57-40-03								
05-10-29-L5720012R		PERFORM RIGHT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	T:10000 (+25/-25)		10000	10025	8906 (+25)	
PROC. REF: NDT 57-40-03PROC. REF: NDT 57-40-03								
570001		LEFT WING						Component ATA:57
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-00-01PROC. REF: AMM 57-00-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
570002	RIGHT WING							Component ATA:57
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-00-01PROC. REF: AMM 57-00-01								
572001	LEFT WINGLET ASSEMBLY							Component ATA:57
PN:2822650-43	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:411	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-01PROC. REF: AMM 57-20-01								
5720013 ^S	LEFT FLAP LOWER SECTOR SUPPORT BRACKET - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	22-Aug-07	T:36 (+14d/-14d)					
	HRS	0	T:600 (+25/-25)					
	AFL	0						
PROC. REF: NDT 57-40-04PROC. REF: NDT 57-40-04								
5720013 ^S	RIGHT FLAP LOWER SECTOR SUPPORT BRACKET - PERFORM EDDY CURRENT INSPECTION.							Service ATA:57
	MOS	22-Aug-07	T:36 (+14d/-14d)					
	HRS	0	T:600 (+25/-25)					
	AFL	0						
PROC. REF: NDT 57-40-04PROC. REF: NDT 57-40-04								
572002	RIGHT WINGLET ASSEMBLY							Component ATA:57
PN:2822650-44	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:421	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-01PROC. REF: AMM 57-20-01								
572003	LEFT WING LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-02PROC. REF: AMM 57-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
572004	RIGHT WING LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-20-02PROC. REF: AMM 57-20-02								
572025	LEFT FRONT WINGLET SPAR FITTING							Component ATA:57
PN:6022621-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6804 / 015	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
572026	RIGHT FRONT WINGLET SPAR FITTING							Component ATA:57
PN:6022621-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6805 / 017	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
572027	LEFT AFT WINGLET SPAR FITTING							Component ATA:57
PN:6022622-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:H0087	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
572028	RIGHT AFT WINGLET SPAR FITTING							Component ATA:57
PN:6022622-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:6806 / 014	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
A5710045 ^S	REMOVE LOWER SURFACE ACCESS PLATES FROM WS 92 INBOARD TO BL 0.0 INCLUDING FUEL PUMPS AT WS 6.0 AND 11.0. VISUALLY INSPECT THE PERIPHERY OF THESE CUTOUTS FOR FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.) CONDUCT EDDY CURRENT INSPECTIONS A							Service ATA:57
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 57-10-01PROC. REF: NDT 57-10-01								PKG:28
A5710070 ^S	CLEAN UPPER AND LOWER CENTERLINE SPLICE PLATE (SPAR 2 TO 5 AND 7 TO 8) ADJACENT TO BL 0.0 RIB CAP. VISUALLY INSPECT THESE AREAS FOR CORROSION, FATIGUE CRACKS, WORKING FASTENERS, AND GENERAL SECURITY. (REFER TO 5-10-00)							Service ATA:57
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28
A5760010 ^S	AILERON (REMOVED FROM WING) (REFER TO 5-10-00.)							Service ATA:57
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:28
B5710050 ^S	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER AND LOWER STRUCTURE IN THE CENTERLINE DOUBLER AREA. INSPECT FOR FATIGUE CRACKS, CORROSION, LOOSE OR MISSING FASTENERS, AND GENERAL SECURITY. (REFER TO NDI MANUAL [NDI-2], PART 2, 57-20-01 AND 57-21-01.)							Service ATA:57
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 57-20-01, NDT 57-21-01PROC. REF: NDT 57-20-01, NDT 57-21-01								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
C5710040 ^S	CLEAN AND CONDUCT A GENERAL EXTERNAL AND INTERNAL VISUAL INSPECTION OF THE WING CENTER SECTION, PAYING PARTICULAR ATTENTION TO THE LOWER SKIN AT THE FUEL PUMP LOCATIONS AND THE SPLICE DETAILS AT BL 0.0, AS ACCESSIBLE. INSPECT FOR EVIDENCE OF AFTIGUE CRACKS, COR						Service	ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
C5710055 ^S	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER STRUCTURE INBOARD OF THE WING-TO-FUSELAGE FITTINGS AND FORWARD OF SPAR 5. INSPECT FOR CORROSION, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. IF CORROSION IS FOUND, WING REMOVAL FROM FUSELAGE MAY						Service	ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 57-12-01PROC. REF: NDT 57-12-01								PKG:27
C5710060 ^S	CONDUCT AN EDDY CURRENT INSPECTION FOR THE FOLLOWING WING STRUCTURAL AREAS: SURFACE OF ACCESSIBLE AREAS OF LOWER DOUBLER FROM BL 0.0 TO OUTBOARD END OF DOUBLER ALONG SPARS 4, 5, AND 7, AND LOWER SKIN ADJACENT TO THE OUTBOARD 2 INCHES OF DOUBLER FINGERS. SKIN ADJA						Service	ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 57-12-01PROC. REF: NDT 57-12-01								PKG:27
C5710062 ^S	REMOVE THE ACCESS COVER AT WS 73.0 BETWEEN SPARS 4/5 AND 6/7. INSPECT ALL HOLES AT THIS LOCATION IN THE SPAR AND SKIN USING AN EDDY CURRENT HOLE PROBE. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-12-01.)						Service	ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 57-12-01PROC. REF: NDT 57-12-01								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
C5710065 ^S	EDDY CURRENT AREA AROUND FASTENERS COMMON TO TRUNNION FITTINGS. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-12-01, AREAS E AND D.)							Service ATA:57
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
PROC. REF: NDT 57-12-01PROC. REF: NDT 57-12-01								PKG:25
C5720020 ^S	VISUALLY INSPECT INTERNAL AND EXTERNAL AREA OF WING WHEEL WELL STRUCTURE, PAYING PARTICULAR ATTENTION TO THE MAIN LANDING GEAR ACTUATOR UPPER ATTACHMENT AND LANDING GEAR RIB STRUCTURE AT WS 53.04. (REFER TO 5-10-00.)							Service ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
C5720025 ^S	X-RAY INSPECT THE OUTBOARD LOWER WING SKIN FROM WS 31 TO WS 61. (REFER TO NDI MANUAL [NDI-2], PART 2, 57-30-01.)							Service ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: NDT 57-30-01PROC. REF: NDT 57-30-01								PKG:27
C5720040 ^S	INSPECT THE JOINT AT WS 181 THAT SPLICES THE WING TO THE OUTER WING EXTENSION. VISUALLY INSPECT FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, AND GENERAL SECURITY. (REFER TO 5-10-00.)							Service ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
C5740001 ^S	WITH LEADING EDGE ASSEMBLIES REMOVED, INSPECT FORWARD SIDE OF SPAR 1 FOR EVIDENCE OF FATIGUE CRACKS, OVERHEAT (DISCOLORED PRIMER), GENERAL CORROSION, LOOSE OR MISSING FASTENERS, FIFLIFORM CORROSION, AND GENERAL CONDITION.							Service ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
C5740002	^S	WITH LEADING EDGE LOWER CUFF FAIRING ASSEMBLIES REMOVED, INSPECT LOWER WING SKIN COVERED BY CUFF FAIRING AND INNER SURFACE OF CUFF FOR EVIDENCE OF FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, CORROSION, AND GENERAL CONDITION.						Service ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
								PKG:27
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5710066	^S	CONDUCT A VISUAL AND EDDY CURRENT INSPECTION OF THE FOLLOWING LOWER WING STRUCTURAL AREAS						Service ATA:57
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: NDT 57-10-01, NDT 57-12-01PROC. REF: NDT 57-10-01, NDT 57-12-01								
E5710071	^S	CONDUCT AN EDDY CURRENT INSPECTION OF THE LOWER SPLICE PLATE ALONG THE CENTERLINE FASTENER ROWS. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-10-01)						Service ATA:57
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
								PKG:28
PROC. REF: NDT 57-10-01PROC. REF: NDT 57-10-01								
E5720010	^S	INSPECT FLAP SECTOR SUPPORT BRACKETS AND FLAP ACTUATOR SUPPORT FLAP BRACKET FOR CRACKS, DISTORTION, INTERFERENCE, AND FASTENER CONDITION. (REFER TO 57-40-03).						Service ATA:57
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:10
PROC. REF: AMM 57-40-03PROC. REF: AMM 57-40-03								
E5750020	^S	WITH FLAPS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO FLAP TRAILING EDGE. INSPECT INBOARD AND OUTBOARD FLAP TRACKS AND NOSE ROLLER SUPPORT STRUCTURE CRACKS, DISTORTION, FASTENER CONDITION, EVIDENCE OF CHAFING OR INTERFERENCE, AND GENERAL SECURITY.						Service ATA:57
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5750030 ^S	INSPECT FLAP NOSE ROLLER BUSHINGS. REPLACE FLAP NOSE ROLLER IF WORN TO A DIAMETER LESS THAN 0.744 INCH. REPLACE FLAP NOSE ROLLER TRACK IF SLOT EXCEEDS 0.775 INCH AT ANY POINT WITH FLAPS FULLY EXTENDED. ENSURE THAT A POSITIVE CLEARANCE EXISTS BETWEEN NOSE ROLLERS							Service ATA:57
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:16
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5750060 ^S	CLEAN AND VISUALLY INSPECT FLAP ATTACH FITTING (CASTINGS ATTACHED TO FLAP SPAR) FOR CRACKS. (REFER TO 5-10-00.) (SEE FIGURE 3.)							Service ATA:57
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:16
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5770010 ^S	INSPECT SPOILER CENTER HINGE BRACKETS (ATTACHED TO WING SPAR 8) FOR CRACKS EMANATING FROM THE BOLT HOLE AND/OR BRACKET BEND RELIEF. INSPECT BOLT HOLE FOR ELONGATION OR DISTORTION.							Service ATA:57
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:10
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
G5720021 ^S	VISUALLY INSPECT INTERNAL AND EXTERNAL AREAS OF WING STRUCTURE ADJACENT TO LANDING GEAR RIB WS 53.04 (BETWEEN SPARS 4 AND 8). INSPECT TRUNNION FITTINGS FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, ELONGATION OF TRUNNION PIN HOLES, AND GENERAL SECURITY. CHECK							Service ATA:57
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	6000 (+25/-25)					
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
H5750000	^S	INSPECT TRAILING EDGE REGION OF WING FOR LOCAL DEFORMATION AFFECTING NORMAL USAGE OF FLAP AND AILERON.						Service ATA:57
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:22
H5750047	^S	FLAP (REMOVED FROM WING) VISUALLY INSPECT THE FOLLOWING (REFER TO 5-10-00): A. FLAP SUPPRT FOR SECURITY, CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERFERENCE, AND GENERAL CONDITION. INSPECT THE FLAP SECTOR AND SUPPORTIN BRACKERTY FOR EVIDENCE OF OVER						Service ATA:57
	MOS	22-Aug-07						
	HRS	0						
	AFL	0	3000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:25
J5720011	^S	FLAP SUPPORT FITTING (ALUMINUM, P/N 6022521-1 THRU 6022521-8) - OERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-40-02.)						Service ATA:57
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: NDT 57-40-02PROC. REF: NDT 57-40-02								PKG:16
K5730012	^S	DETAILED INSPECTION AILERON BRUSH SEALS. (REFER TO 57-30-07)						Service ATA:57
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 57-30-07PROC. REF: AMM 57-30-07								PKG:4
N5700004	^S	VISUAL INSPECTION WING SURFACE, WING TO FUSELAGE FAIRING AND WINGLET EXTERIOR. (REFER TO 5-10-00)						Service ATA:57
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5710140 ^S	REMOVE UPPER WING-TO-FUSELAGE FAIRINGS AND INSPECT WING SKINS, WING TO FUSELAGE ATTACH FITTINGS, AND ADJACENT STRUCTURE FOR CORROSION, FASTENER SECURITY, CRACKS, PERMANENT DEFORMATION, PROTECTIVE COATING, AND GENERAL CONDITION. EXAMINE EXPOSED EDGE OF HONEYCOMB							Service ATA:57
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:22
P5710141 ^S	INSPECT WING-TO-FUSELAGE ATTACH POINTS FOR SECURITY (THAT PORTION VISIBLE THROUGH WHEEL WELLS).							Service ATA:57
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23
P5710142 ^S	WITH WING-TO-FUSELAGE FAIRING REMOVED, CLEAN AND VISUALLY INSPECT ALL EIGHT WING-TO-FUSELAGE FITTINGS (FOUR PER SIDE). USING A 10X MAGNIFYING GLASS, ADEQUATE LIGHTING, AND MIRROR, INSPECT FITTINGS AND SUPPORT STRUCTURES FOR FATIGUE CRACKS, DEFORMATION, CO							Service ATA:57
	MOS	14-Oct-19	144 (+14d/-14d)					
	HRS	976.1						
	AFL	766	6000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
P5710143 ^S	CLEAN CLEAN AND VISUALLY INSPECT, USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE) AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHES, FASTENER WORKING, AND GENERAL SECURITY. (REFER TO 5-10-00.)							Service ATA:57
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 57-13-01PROC. REF: NDT 57-13-01								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5710144	^S	INSPECT WHEEL WELL AND CENTER SECTION OF WING FOR GENERAL CONDITION OF SKIN, SPARS, ATTACH FITTINGS AND SUPPORTING STRUCTURE, LANDING GEAR RIB, AND TRUNNION FITTINGS. CHECK FOR DEFORMATION, FATIGUE CRACKS, PROTECTIVE FINISH CONDITION, AND GENERAL SECURITY.						Service ATA:57
	MOS	07-Oct-23	96 (+14d/-14d)					
	HRS	1309.3	2400 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:23
P5710146	^S	INSPECT UPPER PORTION OF BL 0.0 RIB CAP, JUST FORWARD OF SPAR 7. INSPECT FOR ANY EVIDENCE OF CORROSION, PRIMER BLISTERING, AND CONDITION OF PRIMER SURFACE. (SEE FIGURE 2.)						Service ATA:57
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:16
P5750050	^S	INSPECT FLAP UPPER AND LOWER SURFACES FOR SKIN CRACKS, LOOSE RIVETS, AND OTHER DAMAGE. CHECK NOSE ROLLERS FOR FREEDOM OF ROTATION. PAY PARTICULAR ATTENTION TO NOSE ROLLER SUPPORT STRUCTURE FOR CRACKS.						Service ATA:57
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4
U5720071	^S	GENERAL VISUAL INSPECTION STALL FENCES, STALL STRIPS, WING STALL TRIANGLES, AND BOUNDARY LAYER ENERGIZERS. (REFER TO 5-10-00.)						Service ATA:57
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:4

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 70 - STANDARD PRACTICES - ENGINES								
700010	LEFT ENGINE INSPECTION-AIRFRAME ITEMS							Package ATA:70
	MOS	22-Aug-07						
	HRS	0	3600 (+50)		3600	3650	2215 (+50)	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:29
700020	RIGHT ENGINE INSPECTION-AIRFRAME ITEMS							Package ATA:70
	MOS	22-Aug-07						
	HRS	0	3600 (+50)		3600	3650	2215 (+50)	
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:30
ATA 71 - POWER PLANT								
05-11-00-E7120049L	REPLACE * NO. 1 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)							Service ATA:71
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
05-11-00-E7120049R	REPLACE * NO. 2 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)							Service ATA:71
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
05-11-00-G7110021L	REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA							Service ATA:71
	MOS/MSC	22-Aug-12	O/C					TEFLON
	HRS	532.3						
	AFL	427						
PROC. REF: AMM 28-00-00PROC. REF: AMM 28-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-11-00-G7110021R	REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA							Service ATA:71
	MOS/MSC	22-Aug-12	O/C					TEFLON
	HRS	532.3						
	AFL	427						
PROC. REF: AMM 28-00-00PROC. REF: AMM 28-00-00								
05-11-00-G7110022L	REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)							Service ATA:71
	MOS/MSC	22-Aug-12	O/C					TEFLON
	HRS	532.3						
	AFL	427						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-G7110022R	REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)							Service ATA:71
	MOS/MSC	22-Aug-12	O/C					TEFLON
	HRS	532.3						
	AFL	427						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-11-00-M7120048L	REPLACE NO. 1 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)							Service ATA:71
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
05-11-00-M7120048R	REPLACE NO. 2 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)							Service ATA:71
	MOS	22-Aug-07						LIFE LIMIT
	HRS	0	20000		20000		18615	
	AFL	0						
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-P&W-710001	NO. 1 ENGINE - PERFORM OVERHAUL ENGINE							Service ATA:71
	MOS	10-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710001	NO. 2 ENGINE - PERFORM OVERHAUL ENGINE							Service ATA:71
	MOS	11-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710006	NO. 1 ENGINE - PERFORM HOT SECTION INSPECTION							Service ATA:71
	MOS	10-Nov-06						INSPECT
	HRS	0	3600 (+50)		(3600) 3600	3650	2215 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710006	NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION							Service ATA:71
	MOS	11-Nov-06						INSPECT
	HRS	0	3600 (+50)		(3600) 3600	3650	2215 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710015	NO. 1 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS							Service ATA:71
	MOS	16-Sep-20						
	HRS	1050.2	1200 (+25/-25)		(2250.2) 2250.2	2275.2	865.2 (+25)	
	ENC	823						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-P&W-710015	NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS							Service ATA:71
	MOS	16-Sep-20						
	HRS	1050.2	1200 (+25/-25)		(2250.2) 2250.2	2275.2	865.2 (+25)	
	ENC	823						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710017	NO. 1 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR							Service ATA:71
	MOS	15-May-23						
	HRS	1283	600 (+25/-25)		(1883) 1883	1908	498 (+25)	
	ENC	1003						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710017	NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR							Service ATA:71
	MOS	15-May-23						
	HRS	1283	600 (+25/-25)		(1883) 1883	1908	498 (+25)	
	ENC	1003						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEED OFF VALVE SOLENOID							Service ATA:71
PN:30B7178-03	MOS	04-Nov-22						
SN:AGJ12431040	HRS	1232	1500 (+300/-300)		(2732) 2732	3032	1347 (+300)	
	ENC	960						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
05-P&W-710019	NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID							Service ATA:71
PN:30B7178-03	MOS	04-Nov-22						
SN:AGJ12431036	HRS	1232	1500 (+300/-300)		(2732) 2732	3032	1347 (+300)	
	ENC	960						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
05-P&W-710020	NO. 1 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESSSES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR							Service ATA:71
	MOS	10-Nov-06						
	HRS	0	3600 (+50)		(3600) 3600	3650	2215 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
05-P&W-710020	NO. 2 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESSSES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR							Service ATA:71
	MOS	11-Nov-06						
	HRS	0	3600 (+50)		(3600) 3600	3650	2215 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
710000	NO. 1 ENGINE - COMPRESSOR WASH							Service ATA:71
	MOS/MSC	10-May-17	A/R					
	HRS	734.6						
	ENC	567						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
710000	NO. 2 ENGINE - COMPRESSOR WASH							Service ATA:71
	MOS/MSC	10-May-17	A/R					
	HRS	734.6						
	ENC	567						
PROC. REF: EMM 71-00-00PROC. REF: EMM 71-00-00								
710050	NO. 1 ENGINE - RUN ENGINES							Service ATA:71
	MOS/MSC	17-Apr-17	A/R					
	HRS	734.6						
	ENC	567						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710050	NO. 2 ENGINE - RUN ENGINES							Service ATA:71
	MOS/MSC	17-Apr-17	A/R					
	HRS	734.6						
	ENC	567						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
711005	LEFT ENGINE INLET COWL							Component ATA:71
PN:L60-NC-6000-101	MOS/MSC	13-Feb-25	O/C	TSR 1				
SN:L60NC005	HRS	1385		TSR 0				
	AFL	1094		TSR 0				
PROC. REF: AMM 71-10-05PROC. REF: AMM 71-10-05								
711006	RIGHT ENGINE INLET COWL							Component ATA:71
PN:L60-NC-6000-103	MOS/MSC	08-Nov-22	O/C					
SN:L60NC-082R	HRS	1247						
	AFL	971						
PROC. REF: AMM 71-10-05PROC. REF: AMM 71-10-05								
711011	LEFT ENGINE UPPER ACCESS COWL							Component ATA:71
PN:266-0208-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-300	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10PROC. REF: AMM 71-10-10								
711012	RIGHT ENGINE UPPER ACCESS COWL							Component ATA:71
PN:266-0208-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-850	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10PROC. REF: AMM 71-10-10								
711013	LEFT ENGINE LOWER ACCESS COWL							Component ATA:71
PN:266-0209-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-400	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10PROC. REF: AMM 71-10-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711014	RIGHT ENGINE LOWER ACCESS COWL							Component ATA:71
PN:266-0209-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-450	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-10PROC. REF: AMM 71-10-10								
711015	LEFT ENGINE PYLON APRON ASSEMBLY							Component ATA:71
PN:266-0213-511	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-510	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-15PROC. REF: AMM 71-10-15								
711016	RIGHT ENGINE PYLON APRON ASSEMBLY							Component ATA:71
PN:266-0213-512	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-560	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-15PROC. REF: AMM 71-10-15								
711021	LEFT ENGINE OUTER FAN DUCT							Component ATA:71
PN:282-0075-5	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-610	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-20PROC. REF: AMM 71-10-20								
711022	RIGHT ENGINE OUTER FAN DUCT							Component ATA:71
PN:282-0075-7	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:18-660	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-20PROC. REF: AMM 71-10-20								
711023	LEFT ENGINE LEFT FORWARD CORE COWL							Component ATA:71
PN:266-0261-501	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:36-710	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711024 RIGHT ENGINE LEFT FORWARD CORE COWL								Component ATA:71
PN:266-0261-501	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:35-710	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711025 LEFT ENGINE RIGHT FORWARD CORE COWL								Component ATA:71
PN:266-0261-503	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:31-720	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711026 RIGHT ENGINE RIGHT FORWARD CORE COWL								Component ATA:71
PN:266-0261-503	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:33-720	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711027 LEFT ENGINE UPPER AFT CORE COWL								Component ATA:71
PN:266-0263-511	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:32-740	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711028 RIGHT ENGINE UPPER AFT CORE COWL								Component ATA:71
PN:266-0263-511	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:33-740	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
711029 LEFT ENGINE LOWER AFT CORE COWL								Component ATA:71
PN:266-0263-509	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:34-730	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711030	RIGHT ENGINE LOWER AFT CORE COWL							Component ATA:71
PN:266-0263-509	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:35-730	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-25PROC. REF: AMM 71-10-25								
712001	LEFT ENGINE FORWARD INTERMEDIATE FITTING							Component ATA:71
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-01PROC. REF: AMM 71-20-01								
712002	RIGHT ENGINE FORWARD INTERMEDIATE FITTING							Component ATA:71
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-01PROC. REF: AMM 71-20-01								
712005	LEFT ENGINE FORWARD UPPER VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-501	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1369	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712006	RIGHT ENGINE FORWARD UPPER VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-505	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1344	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712007	LEFT ENGINE FORWARD LOWER VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-505	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1329	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712008	RIGHT ENGINE FORWARD LOWER VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-501	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1374	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712009	LEFT ENGINE FORWARD MOUNT YOKE							Component ATA:71
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712010	RIGHT ENGINE FORWARD MOUNT YOKE							Component ATA:71
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-05PROC. REF: AMM 71-20-05								
712011	LEFT ENGINE AFT VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-503	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1025	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
712012	RIGHT ENGINE AFT VIBRATION ISOLATOR							Component ATA:71
PN:266D0820-503	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1018	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
712013	LEFT ENGINE UPPER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712014	RIGHT ENGINE UPPER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
712015	LEFT ENGINE LOWER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
712016	RIGHT ENGINE LOWER AFT MOUNT LINK							Component ATA:71
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-10PROC. REF: AMM 71-20-10								
715020	NO. 1 ENGINE - ENGINE WIRE HARNESS							Component ATA:71
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
715020	NO. 2 ENGINE - ENGINE WIRE HARNESS							Component ATA:71
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
715025	NO. 1 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR							Component ATA:71
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01PROC. REF: EMM 72-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
715025	NO. 2 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR							Component ATA:71
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01PROC. REF: EMM 72-60-01								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:31B4067-04	MOS/MSC		E/C					
SN:PCE-CA0499	HRS							
WC#: 71.EN1	AFL							
PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:31B4067-04	MOS/MSC		E/C					
SN:PCE-CA0498	HRS							
WC#: 71.EN2	AFL							
PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00PROC. REF: AMM 71-00-00, EMM 70-00-00, EMM 70-00-00								
E7100004 ^S	VISUAL INSPECTION OF ALL BLEED AIR DUCTS, LINES, HOSES, AND ELECTRICAL WIRING IN THE ENGINE NACELLE. INSPECT FOR SECURITY, CLAMPING, ROUTING, CLEARANCE, EVIDENCE OF LEAKS, AND GENERAL CONDITION. (REFER TO 5-10-00)							Service ATA:71
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:3
E7100016 ^S	INSPECT HOLD OPEN RODS FOR SECURITY OF INSTALLATION AND EVIDENCE OF DAMAGE.							Service ATA:71
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:3

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
E7100020	^S	REMOVE IGNITER ACCESS PANEL AND INSPECT CORE COWL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE.						Service ATA:71
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:3
E7100022	^S	INSPECT IGNITER ACCESS PANEL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE.						Service ATA:71
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:3
E7100030	^S	INSPECT FUEL, HYDRAULIC, FIRE EXTINGUISHER, AND DRAIN LINES, CONTROLS CONNECTIONS, COUPLINGS, AND ACCESSORIES FOR LOOSE OR FAILED FASTENERS, CHAFING WEAR, ROUTING, PROPER SAFETY, SECURITY OF MOUNTING, AND EVIDENCE OF DAMAGE. INSPECT SHIELDED FADEC ELECTRICAL HAR						Service ATA:71
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:3
J7120051	^S	FORWARD ENGINE BEAM INTERMEDIATE FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-01.)						Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-01PROC. REF: NDT 71-20-01								PKG:28
J7120052	^S	FORWARD ENGINE MOUNT YOKE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-02.)						Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-02PROC. REF: NDT 71-20-02								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
J7120053 ^S	BOLT/FORWARD INTERMEDIATE FITTING TO FORWARD BEAM SUPPORT FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-03.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-03PROC. REF: NDT 71-20-03								PKG:28
J7120054 ^S	BOLT/FORWARD YOKE TO INTERMEDIATE FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-04.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-04PROC. REF: NDT 71-20-04								PKG:28
J7120055 ^S	BOLT/FORWARD YOKE TO ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-05.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-05PROC. REF: NDT 71-20-05								PKG:28
J7120056 ^S	BOLT/FORWARD ENGINE ISOLATOR TO ENGINE CASE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-06.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-06PROC. REF: NDT 71-20-06								PKG:28
J7120057 ^S	FORWARD TO ENGINE ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-07.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-07PROC. REF: NDT 71-20-07								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
 Serial: 60 320
 RegNo: N328AJ
 HRS: 1385
 AFL: 1094
 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
J7120058 ^S	AFT ENGINE ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-08.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-08PROC. REF: NDT 71-20-08								PKG:28
J7120059 ^S	AFT MOUNT LINKS - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-09.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-09PROC. REF: NDT 71-20-09								PKG:28
J7120060 ^S	BOLT/AFT ISOLATOR TO SUPPORT FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL {NDI-2}, PART 5, 71-20-10.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-10PROC. REF: NDT 71-20-10								PKG:28
J7120061 ^S	BOLT/AFT ISOLATOR TO MOUNT LINKS - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-11.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-11PROC. REF: NDT 71-20-11								PKG:28
J7120062 ^S	BOLT/MOUNT LINKS TO ENGINE CASE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-12.)							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	T:12000 (+25/-25)					
	AFL	0						
PROC. REF: NDT 71-20-12PROC. REF: NDT 71-20-12								PKG:28

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
M7120068A	INSPECT NO. 1 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	3600 (+25/-25)		3600	3625	2215 (+25)	
	AFL	0						
PROC. REF: AMM 71-20-05, AMM 71-20-10PROC. REF: AMM 71-20-05, AMM 71-20-10								
M7120068B	INSPECT NO. 2 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS							Service ATA:71
	MOS	22-Aug-07						
	HRS	0	3600 (+25/-25)		3600	3625	2215 (+25)	
	AFL	0						
PROC. REF: AMM 71-20-05, AMM 71-20-10PROC. REF: AMM 71-20-05, AMM 71-20-10								
T7100010 ^S	INSPECT UPPER COWL DOOR AND APRON FOR FAILED FASTENERS, SECURITY, AND EVIDENCs OF DAMAGE. INSPECT BONDING JUMPERS ACROSS COWLING HINGES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR AND APRON FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY							Service ATA:71
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
T7100012 ^S	INSPECT LOWER COWL DOOR INNER AND OUTER SKINS AND SEALS FOR EVIDENCE OF DAMAGE. INSPECT LATCH ASSEMBLIES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY AROUND THE HEADS OF FASTENERS AND ALONG							Service ATA:71
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:15
T7100018 ^S	GENERAL VISUAL INSPECTION FAN DUCT OUTER SKIN AND ATTACHMENT. (REFER TO 5-10-00)							Service ATA:71
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
U7100014	^S	GENERAL VISUAL INSPECTION OIL FILLER DOOR. (REFER TO 5-10-00)						Service ATA:71
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
U7110032	^S	GENERAL VISUAL INSPECTION GENERATOR INLET DUCT SEAL. (REFER TO 5-10-00)						Service ATA:71
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:3
U7110041	^S	GENERAL VISUAL INSPECTION NACELLE OUTER SKIN ATTACHMENT. (REFER TO 5-10-00)						Service ATA:71
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
U7110042	^S	GENERAL VISUAL INSPECTION NACELLE LIP ASSEMBLY AND INNER BARREL. (REFER TO 5-10-00)						Service ATA:71
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
ATA 72 - ENGINE								
496010		APU - H.O.T. SWITCH						Component ATA:72
PN:PN	MOS/MSC	25-Aug-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION							Service ATA:72
	MOS	04-Nov-22	24 (+12m)		04-Nov-24	04-Nov-25	TOL (+244 d)	
	HRS	1232						
	ENC	960						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION							Service ATA:72
	MOS	04-Nov-22	24 (+12m)		04-Nov-24	04-Nov-25	TOL (+244 d)	
	HRS	1232						
	ENC	960						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
720010 ^S	NO. 1 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720010 ^S	NO. 2 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720015 ^S	NO. 1 ENGINE - EEC - REMOVE, CHECK CONDITION, CLEAN THE CONNECTORS AND REINSTALL							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720015 ^S	NO. 2 ENGINE - EEC - REMOVE, CHECK CONDITION, CLEAN THE CONNECTORS AND REINSTALL							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 70-00-00PROC. REF: EMM 70-00-00								PKG:1
720020 ^S	NO. 1 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720020 ^S	NO. 2 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720030 ^S	NO. 1 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720030 ^S	NO. 2 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720040 ^S	NO. 1 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720040 ^S	NO. 2 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720050 ^S	NO. 1 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720050 ^S	NO. 2 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720060 ^S	NO. 1 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720060 ^S	NO. 2 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720070 ^S	NO. 1 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720070 ^S	NO. 2 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720080 ^S	NO. 1 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720080 ^S	NO. 2 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720090 ^S	NO. 1 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640)							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720090 ^S	NO. 2 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640)							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720095	NO. 1 ENGINE - DISCARD LP COMPRESSOR NO. 1 FAN BLADE							Service ATA:72
PN:PN	MOS	10-Nov-06						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	ENC	0	15000		(15000) 15000		13906	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720095	NO. 2 ENGINE - DISCARD LP COMPRESSOR NO. 1 FAN BLADE							Service ATA:72
PN:PN	MOS	11-Nov-06						LIFE LIMIT
SN:UNKNOWN	HRS	0						
	ENC	0	15000		(15000) 15000		13906	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
720100 ^S	NO. 1 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720100 ^S	NO. 2 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720110 ^S	NO. 1 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720110 ^S	NO. 2 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720120 ^S	NO. 1 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720120 ^S	NO. 2 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720130 ^S	NO. 1 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720130 ^S	NO. 2 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720140 ^S	NO. 1 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720140 ^S	NO. 2 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720150 ^S	NO. 1 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720150 ^S	NO. 2 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720160 ^S	NO. 1 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720160 ^S	NO. 2 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720170 ^S	NO. 1 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								PKG:1
720170 ^S	NO. 2 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
720180 ^S	NO. 1 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720180 ^S	NO. 2 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720190 ^S	NO. 1 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720190 ^S	NO. 2 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								
720200 ^S	NO. 1 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE						Service	ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
								PKG:1
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720200 ^S	NO. 2 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720210 ^S	NO. 1 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720210 ^S	NO. 2 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720220 ^S	NO. 1 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND.							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720220 ^S	NO. 2 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND.							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720230 ^S	NO. 1 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720230 ^S	NO. 2 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720240 ^S	NO. 1 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720240 ^S	NO. 2 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720250 ^S	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE.							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720250 ^S	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE.							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720260 ^S	NO. 1 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720260 ^S	NO. 2 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720270 ^S	NO. 1 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 77-20-02, EMM 75-30-03PROC. REF: EMM 77-20-02, EMM 75-30-03								PKG:1
720270 ^S	NO. 2 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 77-20-02, EMM 75-30-03PROC. REF: EMM 77-20-02, EMM 75-30-03								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720280 ^S	NO. 1 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720280 ^S	NO. 2 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720290 ^S	NO. 1 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY.							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720290 ^S	NO. 2 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY.							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720300 ^S	NO. 1 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
720300 ^S	NO. 2 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720310 ^S	NO. 1 ENGINE - SPARK IGNITERS, OPERATIONAL TEST							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
720310 ^S	NO. 2 ENGINE - SPARK IGNITERS, OPERATIONAL TEST							Service ATA:72
	MOS	07-Oct-23	36					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 05-20-00PROC. REF: EMM 05-20-00								PKG:1
723001	NO. 1 ENGINE - FAN HUB							Component ATA:72
PN:30B2256	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:A0021M1T	HRS	0		TSN 0				
	ENC	0		TSN 0	(12000) 12000 (M)		10906	
	ACCCYC	0	12000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723001	NO. 2 ENGINE - FAN HUB							Component ATA:72
PN:30B2256	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:A0022D3K	HRS	0		TSN 0				
	ENC	0		TSN 0	(12000) 12000 (M)		10906	
	ACCCYC	0	12000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723002	NO. 1 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723002	NO. 2 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723003	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:30B4565-01	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:A0020MY5	HRS	0		TSN 0				
	ENC	0		TSN 0	(7000) 7000 (M)		5906	
	ACCCYC	0	7000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723003	NO. 2 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:30B4565-01	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:A0022D22C	HRS	0		TSN 0				
	ENC	0		TSN 0	(7000) 7000 (M)		5906	
	ACCCYC	0	7000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723004	NO. 1 ENGINE - PRESSURE CHECK IMPELLER SHROUD							Service ATA:72
	MOS/MSC	10-Nov-06	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723004	NO. 2 ENGINE - PRESSURE CHECK IMPELLER SHROUD							Service ATA:72
	MOS/MSC	11-Nov-06	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723005	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR							Component ATA:72
PN:30B6531-01	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:TXA1B0496	HRS	0		TSN 0				
	ENC	0		TSN 0	(12000) 12000 (M)		10906	
	ACCCYC	0	12000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723005	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR							Component ATA:72
PN:30B6531-01	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:TXA1B0087	HRS	0		TSN 0				
	ENC	0		TSN 0	(12000) 12000 (M)		10906	
	ACCCYC	0	12000	TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723005A	NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR)							Service ATA:72
PN:30B6531-01	MOS	11-Oct-21						
SN:TXA1B0496	HRS	1173.5	300 (+25)		(1473.5) 1473.5	1498.5	88.5 (+25)	
	ENC	920						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
723005A	NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR)							Service ATA:72
PN:30B6531-01	MOS	11-Oct-21						
SN:TXA1B0087	HRS	1173.5	300 (+25)		(1473.5) 1473.5	1498.5	88.5 (+25)	
	ENC	920						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723008	NO. 1 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR							Component ATA:72
PN:30B4745-01	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:56B003	HRS	0		TSN 0				
	ENC	0		TSN 0	(8500) 8500 (M)		7406	
	ACCCYC	0	8500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723008	NO. 2 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR							Component ATA:72
PN:30B4745-01	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:56B047	HRS	0		TSN 0				
	ENC	0		TSN 0	(8500) 8500 (M)		7406	
	ACCCYC	0	8500	TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723008A	NO. 1 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM							Service ATA:72
PN:30B4745-01	MOS/MSC	10-Nov-06	O/C					
SN:56B003	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723008A	NO. 2 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM							Service ATA:72
PN:30B4745-01	MOS/MSC	11-Nov-06	O/C					
SN:56B047	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723027	NO. 1 ENGINE - LOW COMPRESSOR SHAFT							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723027	NO. 2 ENGINE - LOW COMPRESSOR SHAFT							Component ATA:72
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-30-01PROC. REF: EMM 72-30-01								
723040	NO. 1 ENGINE - LP COMPRESSOR - NO. 1 FAN BLADE							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
723040	NO. 2 ENGINE - LP COMPRESSOR - NO. 1 FAN BLADE							Component ATA:72
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724010	NO. 1 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)							Service ATA:72
	MOS	10-Nov-06						
	HRS	0	T:3000 (+25/-25)	(3000) 3000	3025	1615 (+25)		
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
724010	NO. 2 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)							Service ATA:72
	MOS	11-Nov-06						
	HRS	0	T:3000 (+25/-25)	(3000) 3000	3025	1615 (+25)		
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725001	NO. 1 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725001	NO. 2 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING							Component ATA:72
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725003	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-03PROC. REF: EMM 72-50-03								
725003	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:30A1824	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:MAA28351	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-50-03PROC. REF: EMM 72-50-03								
725101	NO. 1 ENGINE - STAGE 1 TURBINE DISC							Component ATA:72
PN:PN	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0	(3100) 3100 (M)		2006	
	ACCCYC	0	3100	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725101	NO. 2 ENGINE - STAGE 1 TURBINE DISC							Component ATA:72
PN:30B2981-01	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:A002HN6	HRS	0		TSN 0				
	ENC	0		TSN 0	(3100) 3100 (M)		2006	
	ACCCYC	0	3100	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725102	NO. 1 ENGINE - STAGE 2 TURBINE DISC							Component ATA:72
PN:PN	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0	(1250) 1250 (M)		156	
	ACCCYC	0	1250	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725102	NO. 2 ENGINE - STAGE 2 TURBINE DISC							Component ATA:72
PN:30B2912-01	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:A0022HNNH	HRS	0		TSN 0				
	ENC	0		TSN 0	(3300) 3300 (M)		2206	
	ACCCYC	0	3300	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725103	NO. 1 ENGINE - STAGE 3 TURBINE DISC							Component ATA:72
PN:30A1853	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:MAA13076	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		8906	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725103	NO. 2 ENGINE - STAGE 3 TURBINE DISC							Component ATA:72
PN:30A1853	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:MAA13073	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		8906	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725104	NO. 1 ENGINE - STAGE 4 TURBINE DISC							Component ATA:72
PN:30A1854	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:MAA13388	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		8906	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725104	NO. 2 ENGINE - STAGE 4 TURBINE DISC							Component ATA:72
PN:30A1854	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:MAA13392	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		8906	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725105	NO. 1 ENGINE - STAGE 5 TURBINE DISC							Component ATA:72
PN:30A1835	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:MAA29342	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		8906	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725105	NO. 2 ENGINE - STAGE 5 TURBINE DISC							Component ATA:72
PN:30A1835	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:MAA29341	HRS	0		TSN 0				
	ENC	0		TSN 0	(10000) 10000 (M)		8906	
	ACCCYC	0	10000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725107	NO. 1 ENGINE - FRONT HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B2748-01	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:A00217CP	HRS	0		TSN 0				
	ENC	0		TSN 0	(4800) 4800 (M)		3706	
	ACCCYC	0	4800	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725107	NO. 2 ENGINE - FRONT HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B2748-01	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:A00222LW	HRS	0		TSN 0				
	ENC	0		TSN 0	(4800) 4800 (M)		3706	
	ACCCYC	0	4800	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725109	NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B2747-01	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:A0021B73	HRS	0		TSN 0				
	ENC	0		TSN 0	(4400) 4400 (M)		3306	
	ACCCYC	0	4400	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725109	NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE COVER							Component ATA:72
PN:30B2747-01	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:A0021B74	HRS	0		TSN 0				
	ENC	0		TSN 0	(4400) 4400 (M)		3306	
	ACCCYC	0	4400	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725111	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL							Component ATA:72
PN:30B2793-01	MOS	10-Nov-06		TSN 0				LIFE LIMIT
SN:AWE009350	HRS	0		TSN 0				
	ENC	0		TSN 0	(4000) 4000 (M)		2906	
	ACCCYC	0	4000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
725111	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL							Component ATA:72
PN:30B2793-01	MOS	11-Nov-06		TSN 0				LIFE LIMIT
SN:AWE009351	HRS	0		TSN 0				
	ENC	0		TSN 0	(4000) 4000 (M)		2906	
	ACCCYC	0	4000	TSN 0				
PROC. REF: EMM 72-50-01PROC. REF: EMM 72-50-01								
726001	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01PROC. REF: EMM 72-60-01								
726001	NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING							Component ATA:72
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-60-01PROC. REF: EMM 72-60-01								
726011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)							Service ATA:72
	MOS	10-Nov-06						
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)							Service ATA:72
	MOS	11-Nov-06						
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
727001	NO. 1 ENGINE - COMBUSTION CHAMBER LINER							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
727001	NO. 2 ENGINE - COMBUSTION CHAMBER LINER							Component ATA:72
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
727001A	NO. 1 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER							Service ATA:72
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	3600 (+50)		(3600) 3600	3650	2215 (+50)	
	ENC	0						
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
727001A	NO. 2 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER							Service ATA:72
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	3600 (+50)		(3600) 3600	3650	2215 (+50)	
	ENC	0						
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
727002	NO. 1 ENGINE - INNER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
727002	NO. 2 ENGINE - INNER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
727003	NO. 1 ENGINE - OUTER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
727003	NO. 2 ENGINE - OUTER COMBUSTION LINER ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 72-40-01PROC. REF: EMM 72-40-01								
ATA 73 - ENGINE FUEL AND CONTROL								
05-P&W-730001	NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT							Service ATA:73
	MOS	12-Nov-24	12		12-Nov-25		252 d	
	HRS	1375.9	1200 (+25/-25)		(2575.9) 2575.9	2600.9	1190.9 (+25)	
	ENC	1084						
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
05-P&W-730001	NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT							Service ATA:73
	MOS	12-Nov-24	12		12-Nov-25		252 d	
	HRS	1375.9	1200 (+25/-25)		(2575.9) 2575.9	2600.9	1190.9 (+25)	
	ENC	1084						
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
05-P&W-730005	NO. 1 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE							Service ATA:73
	MOS	10-Nov-06						
	HRS	0	1800 (+600/-600)		(1800) 1800	2400	415 (+600)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
05-P&W-730005	NO. 2 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE							Service ATA:73
	MOS	11-Nov-06						
	HRS	0	1800 (+600/-600)		(1800) 1800	2400	415 (+600)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731001	NO. 1 ENGINE - FUEL PUMP							Component ATA:73
PN:30B1910	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:MX702024A	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731001	NO. 2 ENGINE - FUEL PUMP							Component ATA:73
PN:30B1910	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:MX703147A	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731002	NO. 1 ENGINE - MOTIVE FLOW VALVE							Component ATA:73
PN:30B2062	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:C37623	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
731002	NO. 2 ENGINE - MOTIVE FLOW VALVE							Component ATA:73
PN:30B2062	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:C37609	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
731003	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH							Component ATA:73
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
731003	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH							Component ATA:73
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
731004	NO. 1 ENGINE - UPPER PRIMARY FUEL NOZZLE							Component ATA:73
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731004	NO. 2 ENGINE - UPPER PRIMARY FUEL NOZZLE							Component ATA:73
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731005	NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE							Component ATA:73
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731005	NO. 2 ENGINE - LOWER PRIMARY FUEL NOZZLE							Component ATA:73
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731010	NO. 1 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY							Component ATA:73
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731010	NO. 2 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY							Component ATA:73
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731011 ^S	NO. 1 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY							Service ATA:73
	MOS	07-Oct-23	24					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 73-10-05, EMM 73-10-04PROC. REF: EMM 73-10-05, EMM 73-10-04								PKG:1
731011 ^S	NO. 2 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY							Service ATA:73
	MOS	07-Oct-23	24					
	HRS	1309.3	600					
	ENC	1026						
PROC. REF: EMM 73-10-05, EMM 73-10-04PROC. REF: EMM 73-10-05, EMM 73-10-04								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731012	NO. 1 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP							Service ATA:73
PN:30B1910	MOS	10-Nov-06						OVERHAUL
SN:MX702024A	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731012	NO. 2 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP							Service ATA:73
PN:30B1910	MOS	11-Nov-06						OVERHAUL
SN:MX703147A	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-02PROC. REF: EMM 73-10-02								
731013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH							Service ATA:73
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH							Service ATA:73
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731014	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY							Service ATA:73
	MOS	10-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731014	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY							Service ATA:73
	MOS	11-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY)							Service ATA:73
PN:30B2062	MOS	10-Nov-06						
SN:C37623	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY)							Service ATA:73
PN:30B2062	MOS	11-Nov-06						
SN:C37609	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731023	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK							Service ATA:73
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731023	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK							Service ATA:73
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731024	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY							Service ATA:73
	MOS	10-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731024	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY							Service ATA:73
	MOS	11-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731025	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE							Service ATA:73
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731025	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE							Service ATA:73
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
731026	NO. 1 ENGINE - FUEL WASTE EJECTOR							Component ATA:73
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731026	NO. 2 ENGINE - FUEL WASTE EJECTOR							Component ATA:73
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-03PROC. REF: EMM 73-10-03								
731044	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - INLET							Service ATA:73
	MOS	10-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731044	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - INLET							Service ATA:73
	MOS	11-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-04PROC. REF: EMM 73-10-04								
731045	NO. 1 ENGINE - DISCARD - FUEL SHUT-OFF CABLE							Service ATA:73
	MOS	10-Nov-06						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731045	NO. 2 ENGINE - DISCARD - FUEL SHUT-OFF CABLE							Service ATA:73
	MOS	11-Nov-06						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731051	NO. 1 ENGINE - FUEL START & DUMP VALVE							Component ATA:73
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731051	NO. 2 ENGINE - FUEL START & DUMP VALVE							Component ATA:73
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731055	NO. 1 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF							Service ATA:73
	MOS	10-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
731055	NO. 2 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF							Service ATA:73
	MOS	11-Nov-06						OVERHAUL
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 73-10-05PROC. REF: EMM 73-10-05								
732001	NO. 1 ENGINE - HYDRO MECHANICAL FUEL CONTROL							Component ATA:73
PN:31B4469-07	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:SHU06-044	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
732001	NO. 2 ENGINE - HYDRO MECHANICAL FUEL CONTROL							Component ATA:73
PN:31B4469-07	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:SHU05-092	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
732002	NO. 1 ENGINE - REPLACE TRIM PLUG							Service ATA:73
	MOS	29-Mar-24	120		29-Mar-34		3311 d	
	HRS	1336.5						
	ENC	1050						
PROC. REF: EMM 70-00-00, EMM 73-20-02PROC. REF: EMM 70-00-00, EMM 73-20-02								
732002	NO. 2 ENGINE - REPLACE TRIM PLUG							Service ATA:73
	MOS	16-Apr-21	120		16-Apr-31		2233 d	
	HRS							
	ENC							
PROC. REF: EMM 70-00-00, EMM 73-20-02PROC. REF: EMM 70-00-00, EMM 73-20-02								
732003	NO. 1 ENGINE - ELECTRICAL FRONT HARNESS							Component ATA:73
PN:30B7462-02	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:EFCA0123	HRS	1232		TSN 0				
	ENC	960		TSN 0				
PROC. REF: EMM 73-20-03, EMM 73-20-03PROC. REF: EMM 73-20-03, EMM 73-20-03								
732003	NO. 2 ENGINE - ELECTRICAL FRONT HARNESS							Component ATA:73
PN:30B7462-02	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:EFCA0175	HRS	1232		TSN 0				
	ENC	960		TSN 0				
PROC. REF: EMM 73-20-03, EMM 73-20-03PROC. REF: EMM 73-20-03, EMM 73-20-03								
732004	NO. 1 ENGINE - ELECTRICAL REAR HARNESS							Component ATA:73
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
732004	NO. 2 ENGINE - ELECTRICAL REAR HARNESS							Component ATA:73
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
732005	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC							Component ATA:73
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-02PROC. REF: EMM 73-20-02								
732005	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL EEC							Component ATA:73
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-02PROC. REF: EMM 73-20-02								
732011	NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU							Service ATA:73
PN:31B4469-07	MOS	10-Nov-06						
SN:SHU06-044	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732011	NO. 2 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU							Service ATA:73
PN:31B4469-07	MOS	11-Nov-06						
SN:SHU05-092	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC							Service ATA:73
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC							Service ATA:73
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR)							Service ATA:73
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR)							Service ATA:73
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
732021	NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU							Service ATA:73
PN:31B4469-07	MOS/MSC	10-Nov-06	N/A					
SN:SHU06-044	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								
732021	NO. 2 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU							Service ATA:73
PN:31B4469-07	MOS/MSC	11-Nov-06	N/A					
SN:SHU05-092	HRS	0						
	ENC	0						
PROC. REF: EMM 73-20-01PROC. REF: EMM 73-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732101	NO. 1 ENGINE - ENGINE FADEC							Component ATA:73
PN:822821-6-004	MOS/MSC	08-Oct-08	O/C	TSN 23				
SN:06090170	HRS	446.6		TSN 446.6				
	ENC	360		TSN 360				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
732101	NO. 2 ENGINE - ENGINE FADEC							Component ATA:73
PN:822821-6-004	MOS/MSC	08-Oct-08	O/C	TSN 23				
SN:07059614	HRS	446.6		TSN 446.6				
	ENC	360		TSN 360				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
733010	DUAL FUEL FLOW CONVERTER							Component ATA:73
PN:10540B08F07	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:06110999A	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03								
733101	LEFT ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:7600021-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:600576	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01								
733102	RIGHT ENGINE FUEL FLOW TRANSMITTER							Component ATA:73
PN:7600021-1	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:600579	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01								
733103	LEFT ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
733104	RIGHT ENGINE FUEL FLOW INDICATOR							Component ATA:73
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02								
ATA 74 - IGNITION								
741001	NO. 1 ENGINE - NO. 1 IGNITION EXCITER							Component ATA:74
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741001	NO. 2 ENGINE - NO. 1 IGNITION EXCITER							Component ATA:74
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741002	NO. 1 ENGINE - NO. 2 IGNITION EXCITER							Component ATA:74
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741002	NO. 2 ENGINE - NO. 2 IGNITION EXCITER							Component ATA:74
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741003	NO. 1 ENGINE - NO. 1 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741003	NO. 2 ENGINE - NO. 1 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741004	NO. 1 ENGINE - NO. 2 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741004	NO. 2 ENGINE - NO. 2 IGNITION CABLE							Component ATA:74
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX							Service ATA:74
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7200	7250	5815 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX							Service ATA:74
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7200	7250	5815 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX							Service ATA:74
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX							Service ATA:74
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES							Service ATA:74
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES							Service ATA:74
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES							Service ATA:74
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES							Service ATA:74
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
741031	NO. 1 ENGINE - REPLACE - NO. 1 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	04-Nov-22						REPLACE
SN:UNKNOWN	HRS	1232	7200 (+50)		(8432) 8432	8482	7047 (+50)	
	ENC	960						
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741031	NO. 2 ENGINE - REPLACE - NO. 1 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	04-Nov-22						REPLACE
SN:UNKNOWN	HRS	1232	7200 (+50)		(8432) 8432	8482	7047 (+50)	
	ENC	960						
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741032	NO. 1 ENGINE - REPLACE - NO. 2 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	04-Nov-22						REPLACE
SN:UNKNOWN	HRS	1232	7200 (+50)		(8432) 8432	8482	7047 (+50)	
	ENC	960						
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
741032	NO. 2 ENGINE - REPLACE - NO. 2 IGNITER PLUGS							Service ATA:74
PN:31B5168-01	MOS	04-Nov-22						REPLACE
SN:UNKNOWN	HRS	1232	7200 (+50)		(8432) 8432	8482	7047 (+50)	
	ENC	960						
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742025	NO. 1 ENGINE - NO. 1 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:UNKNOWN	HRS	1232		TSN 0				
	ENC	960		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
742025	NO. 2 ENGINE - NO. 1 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:UNKNOWN	HRS	1232		TSN 0				
	ENC	960		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
742026	NO. 1 ENGINE - NO. 2 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:UNKNOWN	HRS	1232		TSN 0				
	ENC	960		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
742026	NO. 2 ENGINE - NO. 2 IGNITER PLUG							Component ATA:74
PN:31B5168-01	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:UNKNOWN	HRS	1232		TSN 0				
	ENC	960		TSN 0				
PROC. REF: EMM 74-10-01PROC. REF: EMM 74-10-01								
743003	ENGINE WARNING LIGHT BOX							Component ATA:74
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 74-30-03PROC. REF: AMM 74-30-03								
ATA 75 - AIR								
751001	NO. 1 ENGINE - ANTI-ICING SOLENOID VALVE							Component ATA:75
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-10-01PROC. REF: EMM 75-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
751001	NO. 2 ENGINE - ANTI-ICING SOLENOID VALVE							Component ATA:75
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-10-01PROC. REF: EMM 75-10-01								
751011	NO. 1 ENGINE - OVERHAUL - ANTI-ICING VALVE							Service ATA:75
PN:PN	MOS	10-Nov-06					OVERHAUL	
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 75-10-01PROC. REF: EMM 75-10-01								
751011	NO. 2 ENGINE - OVERHAUL - ANTI-ICING VALVE							Service ATA:75
PN:PN	MOS	11-Nov-06					OVERHAUL	
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 75-10-01PROC. REF: EMM 75-10-01								
753001	NO. 1 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES							Service ATA:75
	MOS	10-Nov-06					OVERHAUL	
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753001	NO. 2 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES							Service ATA:75
	MOS	11-Nov-06					OVERHAUL	
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753002	NO. 1 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS	10-Nov-06						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753002	NO. 2 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS	11-Nov-06						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER							Service ATA:75
	MOS/MSC	10-Nov-06	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER							Service ATA:75
	MOS/MSC	11-Nov-06	N/A					
	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753004	NO. 1 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04PROC. REF: EMM 75-30-04								
753004	NO. 2 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
PROC. REF: EMM 75-30-04PROC. REF: EMM 75-30-04								
753005	NO. 1 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04PROC. REF: EMM 75-30-04								
753005	NO. 2 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR							Component ATA:75
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-04PROC. REF: EMM 75-30-04								
753012	NO. 1 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS/MSC	10-Nov-06	N/A					DISCARD
	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753012	NO. 2 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID							Service ATA:75
	MOS/MSC	11-Nov-06	N/A					DISCARD
	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753014	NO. 1 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR							Service ATA:75
PN:PN	MOS	10-Nov-06						DISCARD
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753014	NO. 2 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR							Service ATA:75
PN:PN	MOS/MSC	11-Nov-06	N/A					DISCARD
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753024	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR							Service ATA:75
PN:PN	MOS/MSC	10-Nov-06	N/A					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753024	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR							Service ATA:75
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200 (M)	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753081	NO. 1 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID							Component ATA:75
PN:30B7178-03	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:AGJ12431040	HRS	1232		TSN 0				
	ENC	960		TSN 0				
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753081	NO. 2 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID							Component ATA:75
PN:30B7178-03	MOS/MSC	04-Nov-22	O/C	TSN 0				
SN:AGJ12431036	HRS	1232		TSN 0				
	ENC	960		TSN 0				
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753082	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT							Component ATA:75
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753082	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT							Component ATA:75
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
753083	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE							Service ATA:75
PN:PN	MOS/MSC	10-Nov-06	N/A					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753083	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE							Service ATA:75
PN:PN	MOS/MSC	11-Nov-06	N/A					
SN:UNKNOWN	HRS	0						
	ENC	0						
PROC. REF: EMM 75-30-02PROC. REF: EMM 75-30-02								
753101	NO. 1 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5758-01	MOS	04-Nov-22		TSO 0				REPLACE
SN:AHX008856	HRS	1232	3600 (+50)	TSO 0	(4832) 4832	4882	3447 (+50)	
	ENC	960		TSO 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753101	NO. 2 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5758-01	MOS	04-Nov-22		TSO 0				REPLACE
SN:GF001063	HRS	1232	3600 (+50)	TSO 0	(4832) 4832	4882	3447 (+50)	
	ENC	960		TSO 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753102	NO. 1 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5758-01	MOS	04-Nov-22		TSO 0				REPLACE
SN:32A626	HRS	1232	3600 (+50)	TSO 0	(4832) 4832	4882	3447 (+50)	
	ENC	960		TSO 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753102	NO. 2 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Component ATA:75
PN:31B5758-01	MOS	04-Nov-22		TSO 0				REPLACE
SN:18A306	HRS	1232	3600 (+50)	TSO 0	(4832) 4832	4882	3447 (+50)	
	ENC	960		TSO 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753105	NO. 1 ENGINE - COMPRESSOR BLEED - P2.8 VALVE							Component ATA:75
PN:31B5756-01	MOS	04-Nov-22		TSR 0				REPLACE
SN:AHX3400972	HRS	1232	3600 (+50)	TSN 2100, TSR 0	(2732) 2732	2782	1347 (+50)	
	ENC	960		TSR 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753105	NO. 2 ENGINE - COMPRESSOR BLEED - P2.8 VALVE							Component ATA:75
PN:31B5756-01	MOS	04-Nov-22		TSO 0				REPLACE
SN:21A600	HRS	1232	3600 (+50)	TSO 0	(4832) 4832	4882	3447 (+50)	
	ENC	960		TSO 0				
PROC. REF: EMM 75-30-01PROC. REF: EMM 75-30-01								
753111	NO. 1 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5758-01	MOS	04-Nov-22						
SN:AHX008856	HRS	1232	1500 (+300/-300)		(2732) 2732	3032	1347 (+300)	
	ENC	960						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
753111	NO. 2 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5758-01	MOS	04-Nov-22						
SN:GF001063	HRS	1232	1500 (+300/-300)		(2732) 2732	3032	1347 (+300)	
	ENC	960						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753112	NO. 1 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5758-01	MOS	04-Nov-22						
SN:32A626	HRS	1232	1500 (+300/-300)		(2732) 2732	3032	1347 (+300)	
	ENC	960						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753112	NO. 2 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE							Service ATA:75
PN:31B5758-01	MOS	04-Nov-22						
SN:18A306	HRS	1232	1500 (+300/-300)		(2732) 2732	3032	1347 (+300)	
	ENC	960						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753115	NO. 1 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE							Service ATA:75
PN:31B5756-01	MOS	04-Nov-22						
SN:AHX3400972	HRS	1232	1500 (+300/-300)		(2732) 2732	3032	1347 (+300)	
	ENC	960						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								
753115	NO. 2 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE							Service ATA:75
PN:31B5756-01	MOS	04-Nov-22						
SN:21A600	HRS	1232	1500 (+300/-300)		(2732) 2732	3032	1347 (+300)	
	ENC	960						
PROC. REF: EMM 75-30-01, EMM 75-30-01PROC. REF: EMM 75-30-01, EMM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
754001	NO. 1 ENGINE - PRESSURE P3 TRANSDUCER							Component ATA:75
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-03PROC. REF: EMM 75-30-03								
754001	NO. 2 ENGINE - PRESSURE P3 TRANSDUCER							Component ATA:75
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 75-30-03PROC. REF: EMM 75-30-03								
ATA 76 - ENGINE CONTROLS								
761001	THROTTLE/THRUST REVERSER QUADRANT ASSEMBLY							Component ATA:76
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01								
761003	LEFT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER							Component ATA:76
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02								
761004	RIGHT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER							Component ATA:76
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02								
761101	NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS							Component ATA:76
PN:6008016-031	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:40	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
761101	NO. 2 ENGINE - FADEC, ENGINE TAILCONE HARNESS							Component ATA:76
PN:6008016-032	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:49	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761103	NO. 1 ENGINE - FADEC, ENGINE HARNESS							Component ATA:76
PN:6008016-029	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:193	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761103	NO. 2 ENGINE - FADEC, ENGINE HARNESS							Component ATA:76
PN:6008016-030	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:191	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761105	NO. 1 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:6008408-037	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:253	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761105	NO. 2 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:6008408-038	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:095	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761107	NO. 1 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:6008408-033	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:200	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
761107	NO. 2 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS							Component ATA:76
PN:6008408-032	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:262	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 73-20-03PROC. REF: EMM 73-20-03								
761201	ENGINE FADEC SLAVE/MASTER SWITCH							Component ATA:76
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-12-01PROC. REF: AMM 76-12-01								
E7614000 ^S	FUNCTIONAL TEST OF APR (AUTOMATIC PERFORMANCE RESERVE) SYSTEM. (REFER TO 76-14-00)							Service ATA:76
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
PROC. REF: AMM 76-14-00PROC. REF: AMM 76-14-00								
H7611007 ^S	VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS FOR SECURITY AND GENERAL CONDITION. REMOVAL OF UPPER COWLING IS REQUIRED FOR THIS INSPECTION. (REFER TO 5-10-00)							Service ATA:76
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
J7611006 ^S	VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS FOR SECURITY AND GENERAL CONDITION, INCLUDING THE SHIELDED HARNESSES ROUTED TO THE FADEC MAINTENANCE PANEL. PAY PARTICULAR ATTENTION TO SIGNS OF CHAFING AGAINST STRUCTURE ADJACENT TO ELECTRICAL BONDING CLAMP LOCATIONS. (							Service ATA:76
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771001	LEFT ENGINE N1 INDICATOR							Component ATA:77
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-10-01PROC. REF: AMM 77-10-01								
771001	NO. 1 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS							Service ATA:77
	MOS	10-Nov-06						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771001	NO. 2 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS							Service ATA:77
	MOS	11-Nov-06						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771002	RIGHT ENGINE N1 INDICATOR							Component ATA:77
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-10-01PROC. REF: AMM 77-10-01								
771003	LEFT ENGINE N2 INDICATOR							Component ATA:77
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-10-02PROC. REF: AMM 77-10-02								
771004	RIGHT ENGINE N2 INDICATOR							Component ATA:77
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
PROC. REF: AMM 77-10-02PROC. REF: AMM 77-10-02								
771011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS							Service ATA:77
	MOS	10-Nov-06						
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS							Service ATA:77
	MOS	11-Nov-06						
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771012	LEFT DATA CONCENTRATOR (DCU) UNIT							Component ATA:77
PN:822-1483-350	MOS/MSC	13-Aug-08	O/C	TSN 12				
SN:2B2VP	HRS	453.3		TSN 453.3				
	AFL	312		TSN 312				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771012	RIGHT DATA CONCENTRATOR (DCU) UNIT							Component ATA:77
PN:822-1483-350	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2B2TM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771014	LEFT ENGINE DATA CONCENTRATOR (EDC) UNIT							Component ATA:77
PN:822-1483-350	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2B2WP	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771014	RIGHT ENGINE DATA CONCENTRATOR (EDC) UNIT							Component ATA:77
PN:822-1483-350	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:2B2TT	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
771022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR							Service ATA:77
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771027	NO. 1 ENGINE - CHANNEL A N1 SPEED SENSOR							Component ATA:77
PN:PN	MOS	10-Nov-06		TSN 0				
SN:UNKNOWN	HRS	0	3600 (+50)	TSN 0	(3600) 3600	3650	2215 (+50)	
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771027	NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR							Component ATA:77
PN:PN	MOS	11-Nov-06		TSN 0				
SN:UNKNOWN	HRS	0	3600 (+50)	TSN 0	(3600) 3600	3650	2215 (+50)	
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771028	NO. 1 ENGINE - CHANNEL B N1 SPEED SENSOR							Component ATA:77
PN:PN	MOS	10-Nov-06		TSN 0				
SN:UNKNOWN	HRS	0	3600 (+50)	TSN 0	(3600) 3600	3650	2215 (+50)	
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771028	NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR							Component ATA:77
PN:PN	MOS	11-Nov-06		TSN 0				
SN:UNKNOWN	HRS	0	3600 (+50)	TSN 0	(3600) 3600	3650	2215 (+50)	
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771040	NO. 1 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
771040	NO. 2 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771041	NO. 1 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
771041	NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR							Component ATA:77
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-10-01PROC. REF: EMM 77-10-01								
772001	LEFT ENGINE ITT INDICATOR							Component ATA:77
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-20-01PROC. REF: AMM 77-20-01								
772002	RIGHT ENGINE ITT INDICATOR							Component ATA:77
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-20-01PROC. REF: AMM 77-20-01								
772010	NO. 1 ENGINE - T4.5 THERMOCOUPLE HARNESS							Component ATA:77
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
772010	NO. 2 ENGINE - T4.5 THERMOCOUPLE HARNESS							Component ATA:77
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
772013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS							Service ATA:77
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
772013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS							Service ATA:77
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
772014	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-02PROC. REF: EMM 77-20-02								
772014	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-02PROC. REF: EMM 77-20-02								
772015	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
PROC. REF: EMM 77-20-02PROC. REF: EMM 77-20-02								
772015	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR							Component ATA:77
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 77-20-02PROC. REF: EMM 77-20-02								
772021	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX							Service ATA:77
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
772021	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX							Service ATA:77
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 77-20-01PROC. REF: EMM 77-20-01								
772022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS							Service ATA:77
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
772022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS							Service ATA:77
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
774001	ENGINE DIAGNOSTIC UNIT							Component ATA:77
PN:9-361-06	MOS/MSC	04-Oct-23	O/C	TSR 0				
SN:0075	HRS	1309.3		TSR 0				
	AFL	1026		TSR 0				
PROC. REF: AMM 77-40-01PROC. REF: AMM 77-40-01								
774001A ^U	REPLACE ENGINE DIAGNOSTIC UNIT EDU BATTERY							Service ATA:77
PN:9-361-06	MOS/MSC	04-Oct-23	DUE		01-Aug-26 (M)		514 d	VENDOR RECOMMENDATION
SN:0075	HRS	1309.3						
	AFL	1026						
774002	CONTROL AND DISPLAY (CDU) UNIT							Component ATA:77
PN:9-362-03	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:C210	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-02PROC. REF: AMM 77-40-02								
774003	LEFT ENGINE ISOLATION INTERFACE UNIT							Component ATA:77
PN:9-343-04	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:C398	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-03PROC. REF: AMM 77-40-03								
774004	RIGHT ENGINE ISOLATION INTERFACE UNIT							Component ATA:77
PN:9-343-04	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:C394	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-40-03PROC. REF: AMM 77-40-03								
774101	SIGNAL CONDITIONING BOX							Component ATA:77
PN:6600504-5	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:AC00256	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
774103	LEFT ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:6600504-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1490	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								
774104	RIGHT ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:6600504-2	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1593	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								
ATA 78 - EXHAUST								
780001	LEFT THRUST REVERSER							Component ATA:78
PN:282-0052-519	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-230	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-05PROC. REF: AMM 78-30-05								
780001A ^S	REPLACE LEFT THRUST REVERSER * LEFT THRUST REVERSER DOOR DRIVER LINK BOLTS (NAS6305U18D) (AWL*)							Service ATA:78
PN:282-0052-519	MOS/MSC	22-Aug-07	O/C					
SN:17-230	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
780001B ^S	REPLACE LEFT THRUST REVERSER * LEFT THRUST REVERSER SUPPORT BEAM DRIVER LINK BOLTS (122450-8A49) (ALT P/N PBF1344-8-49D) (AWL*)							Service ATA:78
PN:282-0052-519	MOS/MSC	22-Aug-07	O/C					
SN:17-230	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-20PROC. REF: AMM 78-30-20								
780001C ^S	REPLACE LEFT THRUST REVERSER * LEFT THRUST REVERSER OVERCENTER LINK DRIVER LINK BOLTS (NAS6304U20D) (AWL*)							Service ATA:78
PN:282-0052-519	MOS/MSC	22-Aug-07	O/C					
SN:17-230	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-20PROC. REF: AMM 78-30-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
780001D ^S REPLACE LEFT THRUST REVERSER * LEFT THRUST REVERSER CARRIAGE ASSEMBLY OVERCENTER LINK BOLTS (NAS6307U15D) (AWL*) Service ATA:78								
PN:282-0052-519	MOS/MSC	22-Aug-07	O/C					
SN:17-230	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-20PROC. REF: AMM 78-30-20								
780002 RIGHT THRUST REVERSER Component ATA:78								
PN:282-0052-521	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:17-280	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-05PROC. REF: AMM 78-30-05								
780002A ^S REPLACE RIGHT THRUST REVERSER DOOR DRIVER LINK BOLTS (NAS6305U18D) * (AWL*) Service ATA:78								
PN:282-0052-521	MOS/MSC	22-Aug-07	O/C					
SN:17-280	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
780002B ^S REPLACE RIGHT THRUST REVERSER * SUPPORT BEAM DRIVER LINK BOLTS (122450-8A49) (ALT PBF1344-8-49D) (AWL*) Service ATA:78								
PN:282-0052-521	MOS/MSC	22-Aug-07	O/C					
SN:17-280	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-20PROC. REF: AMM 78-30-20								
780002C ^S REPLACE RIGHT THRUST REVERSER * OVER-CENTER LINK DRIVER LINK BOLTS (NAS6304U20D) (AWL*) Service ATA:78								
PN:282-0052-521	MOS/MSC	22-Aug-07	O/C					
SN:17-280	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-20PROC. REF: AMM 78-30-20								
780002D ^S REPLACE RIGHT THRUST REVERSER * CARRIAGE ASSEMBLY OVER-CENTER LINK BOLTS (NAS6307U15D) (AWL*) Service ATA:78								
PN:282-0052-521	MOS/MSC	22-Aug-07	O/C					
SN:17-280	HRS	0						
	AFL	0						
PROC. REF: AMM 78-30-20PROC. REF: AMM 78-30-20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783001	LEFT THRUST REVERSER RELAY BOX							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-01PROC. REF: AMM 78-30-01								
783002	RIGHT THRUST REVERSER RELAY BOX							Component ATA:78
PN:6018425-017	MOS/MSC	16-Apr-21	O/C					
SN:MRP531128-01B	HRS							
	AFL							
PROC. REF: AMM 78-30-01PROC. REF: AMM 78-30-01								
783005	LEFT THRUST REVERSER HYDRAULIC CONTROL UNIT							Component ATA:78
PN:282D0007-507	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:0731	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-03PROC. REF: AMM 78-30-03								
783006	RIGHT THRUST REVERSER HYDRAULIC CONTROL UNIT							Component ATA:78
PN:282D0007-507	MOS/MSC	26-Mar-21	O/C					
SN:0181	HRS	1109.9						
	AFL	869						
PROC. REF: AMM 78-30-03PROC. REF: AMM 78-30-03								
783008	HYDRAULIC CONTROL RELAY BOX							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-06PROC. REF: AMM 78-30-06								
783009	THRUST REVERSER INTERFACE BOX							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-07PROC. REF: AMM 78-30-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783013	LEFT ENGINE THRUST REVERSER UPPER DOOR							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
783014	RIGHT ENGINE THRUST REVERSER UPPER DOOR							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
783015	LEFT ENGINE THRUST REVERSER LOWER DOOR							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
783016	RIGHT ENGINE THRUST REVERSER LOWER DOOR							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-10PROC. REF: AMM 78-30-10								
783025	LEFT ENGINE THRUST REVERSER SWITCH CABLE							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-25PROC. REF: AMM 78-30-25								
783026	RIGHT ENGINE THRUST REVERSER SWITCH CABLE							Component ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-25PROC. REF: AMM 78-30-25								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783105 LEFT OUTBOARD THRUST REVERSER ACTUATOR								Component ATA:78
PN:282D0006-501	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1389R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05PROC. REF: AMM 78-31-05								
783106 LEFT INBOARD THRUST REVERSER ACTUATOR								Component ATA:78
PN:282D0006-501	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1396R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05PROC. REF: AMM 78-31-05								
783107 RIGHT INBOARD THRUST REVERSER ACTUATOR								Component ATA:78
PN:282D0006-501	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1399R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05PROC. REF: AMM 78-31-05								
783108 RIGHT OUTBOARD THRUST REVERSER ACTUATOR								Component ATA:78
PN:282D0006-501	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1397R	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-05PROC. REF: AMM 78-31-05								
783115 LEFT UPPER SECONDARY LOCK ACTUATOR								Component ATA:78
PN:266D0486-507	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1601	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15PROC. REF: AMM 78-31-15								
783116 RIGHT UPPER SECONDARY LOCK ACTUATOR								Component ATA:78
PN:266D0486-507	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1600	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15PROC. REF: AMM 78-31-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
783117		LEFT LOWER SECONDARY LOCK ACTUATOR					Component	ATA:78
PN:266D0486-507	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1602	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15PROC. REF: AMM 78-31-15								
783118		RIGHT LOWER SECONDARY LOCK ACTUATOR					Component	ATA:78
PN:266D0486-507	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:1603	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-15PROC. REF: AMM 78-31-15								
783132		LEFT OUTBOARD STANG FAIRING ASSEMBLY					Component	ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								
783136		RIGHT OUTBOARD STANG FAIRING ASSEMBLY					Component	ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								
783142		LEFT INBOARD STANG FAIRING ASSEMBLY					Component	ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								
783146		RIGHT INBOARD STANG FAIRING ASSEMBLY					Component	ATA:78
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-15PROC. REF: AMM 78-30-15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
C7830027A ^S	VISUAL INSPECTION THRUST REVERSER DRIVER LINKS (EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 78-30-00)						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:31
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C7830027B ^S	VISUAL INSPECTION THRUST REVERSER DRIVER LINKS (EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 78-30-00)						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:32
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C7830029A ^S	VISUAL INSPECTION THRUST REVERSER OVER-CENTER LINK (EIGHT PER AIRCRAFT) AND OVER-CENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:31
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C7830029B ^S	VISUAL INSPECTION THRUST REVERSER OVER-CENTER LINK (EIGHT PER AIRCRAFT) AND OVER-CENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:32
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C7830031A ^S	VISUAL INSPECTION THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:31

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C7830031B ^S	VISUAL INSPECTION THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:32
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C7830033A ^S	VISUAL INSPECTION THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:31
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C7830033B ^S	VISUAL INSPECTION THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:32
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
C7830035A ^S	VISUAL INSPECTION THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:31
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
C7830035B ^S	VISUAL INSPECTION THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:32
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D7830015A ^S	CHECK THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:31
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D7830015B ^S	CHECK THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION						Service	ATA:78
	MOS/MSC	22-Aug-07	O/C					
	HRS	0						
	AFL	0						
								PKG:32
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E7830038 ^S	DETAILED INSPECTION THRUST REVERSERS FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 78-30-00.)						Service	ATA:78
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
								PKG:15
PROC. REF: AMM 78-30-00PROC. REF: AMM 78-30-00								
M7830084 ^S	INSPECT THRUST REVERSER SECONDARY LATCH - LUBRICATE LATCH SWITCH PLUNGERS, ROLLER ASSEMBLY, AND ACTUATOR PINS. (REFER TO 12-21-04)						Service	ATA:78
	MOS	12-Nov-24	12 (+14d/-14d)					
	HRS	1375.9	300 (+25/-25)					
	AFL	1084						
								PKG:3
PROC. REF: AMM 12-21-04PROC. REF: AMM 12-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
P7830022	^S	FUNCTIONAL TEST OF THRUST REVERSER HYDRAULIC CONTROL VALVE ASSEMBLY CHECK VALVES. (REFER TO 78-30-03.)					Service	ATA:78
	MOS	14-Oct-19	144	(+14d/-14d)				
	HRS	976.1						
	AFL	766	6000	(+25/-25)				
PROC. REF: AMM 78-30-03PROC. REF: AMM 78-30-03								
T7830014	^S	VISUAL INSPECTION OF THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION. (REFER TO 5-10-00)					Service	ATA:78
	MOS	12-Nov-24	24	(+14d/-14d)				
	HRS	1375.9	600	(+25/-25)				
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830016	^S	VISUAL INSPECTION OF THRUST REVERSER ACTUATOR FOR HYDRAULIC LEAKS, DAMAGED PUSHROD, DAMAGED FLEXIBLE HOSES, AND SECURITY OF INSTALLATION. (REFER TO 5-10-00)					Service	ATA:78
	MOS	12-Nov-24	24	(+14d/-14d)				
	HRS	1375.9	600	(+25/-25)				
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830018	^S	VISUAL INSPECTION OF HYDRAULIC CONTROL UNITS, PRESSURE SWITCH, CHECK VALVES, AND HYDRAULIC LINES FOR LEAKAGE, CLEANLINESS, SECURITY OF INSTALLATION, AND CONDITION OF ECLECTRICAL COMPONENTS. (REFER TO 5-10-00)					Service	ATA:78
	MOS	12-Nov-24	24	(+14d/-14d)				
	HRS	1375.9	600	(+25/-25)				
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830020	^S	VISUAL INSPECTION OF STOW AND DEPLOY SWITCHES FOR SECURITY OF INSTALLATION AND CONDITION OF ELECTRICAL COMPONENTS. VISUALLY INSPECT SHIELDED ELECTRICAL THRUST REVERSER HARNESS FOR CONDITION. (REFER TO 5-10-00)					Service	ATA:78
	MOS	12-Nov-24	24	(+14d/-14d)				
	HRS	1375.9	600	(+25/-25)				
	AFL	1084						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830026 ^S	VISUAL INSPECTION OF THRUST REVERSER DRIVER LINKS(EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT.) INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)						Service	ATA:78
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830028 ^S	VISUAL INSPECTION OF THRUST REVERSER OVERCENTER LINK (EIGHT PER AIRCRAFT) AND OVERCENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)						Service	ATA:78
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830030 ^S	VISUAL INSPECTION OF THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATI						Service	ATA:78
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T7830032 ^S	VISUAL INSPECTION OF THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS. (REFER TO 5-10-00)						Service	ATA:78
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
								PKG:9
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
T7830034 ^S	VISUAL INSPECTION OF THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS. (REFER TO 5-10-00)							Service ATA:78
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
T7830039 ^S	VISUAL INSPECTION OF FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 5-10-00)							Service ATA:78
	MOS	12-Nov-24	24 (+14d/-14d)					
	HRS	1375.9	600 (+25/-25)					
	AFL	1084						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:9
T7830085 ^S	FUNCTIONAL TEST ** OF THE THRUST REVERSER WITH WHEEL SPEED DETECT INTERFACE. (REFER TO 78-30-00.) (AWL **)							Service ATA:78
	MOS	07-Oct-23	48 (+14d/-14d)					
	HRS	1309.3	1200 (+25/-25)					
	AFL	1026						
PROC. REF: AMM 78-30-00PROC. REF: AMM 78-30-00								PKG:15
U7830010A ^S	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION							Service ATA:78
	MOS	22-Aug-07						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:29
U7830010B ^S	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION							Service ATA:78
	MOS	22-Aug-07						
	HRS	0	3600 (+50)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:30

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
U7830012A ^S	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE							Service ATA:78
	MOS	22-Aug-07						
	HRS	0	3600 (+50)					
	AFL	0						
								PKG:29
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
U7830012B ^S	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE							Service ATA:78
	MOS	22-Aug-07						
	HRS	0	3600 (+50)					
	AFL	0						
								PKG:30
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 79 - OIL								
05-P&W-790001	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT							Service ATA:79
	MOS	18-Apr-24	12		18-Apr-25		44 d	
	HRS	1336.5	1200 (+25/-25)		(2536.5) 2536.5	2561.5	1151.5 (+25)	
	ENC	1050						
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
05-P&W-790001	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT							Service ATA:79
	MOS	18-Apr-24	12		18-Apr-25		44 d	
	HRS	1336.5	1200 (+25/-25)		(2536.5) 2536.5	2561.5	1151.5 (+25)	
	ENC	1050						
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
05-P&W-790002	NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE							Service ATA:79
	MOS	18-Apr-24	12		18-Apr-25		44 d	
	HRS	1336.5	600 (+50/-50)		(1936.5) 1936.5	1986.5	551.5 (+50)	
	ENC	1050						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
05-P&W-790002	NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE							Service ATA:79
	MOS	18-Apr-24	12		18-Apr-25		44 d	
	HRS	1336.5	600 (+50/-50)		(1936.5) 1936.5	1986.5	551.5 (+50)	
	ENC	1050						
PROC. REF: EMM 72-00-00PROC. REF: EMM 72-00-00								
792001	NO. 1 ENGINE - OIL PUMP							Component ATA:79
PN:30B4857-01	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:EC01A000A725	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05PROC. REF: EMM 79-20-05								
792001	NO. 2 ENGINE - OIL PUMP							Component ATA:79
PN:31B6167-01	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:EC01A000A720	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05PROC. REF: EMM 79-20-05								
792002	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER							Component ATA:79
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
792002	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER							Component ATA:79
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-02PROC. REF: EMM 79-20-02								
792005	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH							Component ATA:79
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792005	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH							Component ATA:79
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-01PROC. REF: EMM 79-20-01								
792010	NO. 1 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH							Component ATA:79
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792010	NO. 2 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH							Component ATA:79
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH							Service ATA:79
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7200	7250	5815 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH							Service ATA:79
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)	(7200) 7200	7250	5815 (+50)		
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792012	NO. 1 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER							Service ATA:79
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792012	NO. 2 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER							Service ATA:79
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792020	NO. 1 ENGINE - OIL PUMP HOUSING							Component ATA:79
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05PROC. REF: EMM 79-20-05								
792020	NO. 2 ENGINE - OIL PUMP HOUSING							Component ATA:79
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-20-05PROC. REF: EMM 79-20-05								
792035	NO. 1 ENGINE - OIL FILTER BYPASS SWITCH							Component ATA:79
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
792035	NO. 2 ENGINE - OIL FILTER BYPASS SWITCH							Component ATA:79
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR
Serial: 60 320
RegNo: N328AJ
HRS: 1385
AFL: 1094
As Of: 13-Feb-2025
05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
793001	LEFT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR							Component ATA:79
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01								
793001	NO. 1 ENGINE - DISCARD - CHIP DETECTOR							Service ATA:79
	MOS	10-Nov-06						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-01PROC. REF: EMM 79-30-01								
793001	NO. 2 ENGINE - DISCARD - CHIP DETECTOR							Service ATA:79
	MOS	11-Nov-06						DISCARD
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-01PROC. REF: EMM 79-30-01								
793002	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH							Service ATA:79
	MOS	10-Nov-06						
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-02PROC. REF: EMM 79-30-02								
793002	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH							Service ATA:79
	MOS	11-Nov-06						
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-02PROC. REF: EMM 79-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793002	RIGHT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR							Component ATA:79
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01								
793003	LEFT ENGINE OIL PRESSURE TRANSDUCER							Component ATA:79
PN:APTE-250L-1000-225D	MOS/MSC	02-Oct-11	O/C	TSN 0				
SN:7612-5-275	HRS	512.2		TSN 0				
	AFL	415		TSN 0				
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02								
793003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP							Service ATA:79
	MOS	10-Nov-06						
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-03PROC. REF: EMM 79-30-03								
793003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP							Service ATA:79
	MOS	11-Nov-06						
	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: EMM 79-30-03PROC. REF: EMM 79-30-03								
793004	RIGHT ENGINE OIL PRESSURE TRANSDUCER							Component ATA:79
PN:APTE-250L-1000-225D	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:7185-5-72	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02								
793005	NO. 1 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				REPLACE
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025

05-Mar-2025 10:30 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
PROC. REF: EMM 79-30-01PROC. REF: EMM 79-30-01								
793005	NO. 2 ENGINE - CHIP DETECTOR							Component ATA:79
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				REPLACE
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-01PROC. REF: EMM 79-30-01								
793010	LEFT ENGINE OIL TEMPERATURE BULB							Component ATA:79
PN:MS28034-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:N5308	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								
793011	RIGHT ENGINE OIL TEMPERATURE BULB							Component ATA:79
PN:MS28034-3	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:N5316	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								
793013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)							Service ATA:79
PN:PN	MOS	10-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
793013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)							Service ATA:79
PN:PN	MOS	11-Nov-06						
SN:UNKNOWN	HRS	0	7200 (+50)		(7200) 7200	7250	5815 (+50)	
	ENC	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 05-Mar-2025 10:30 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793030	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR							Component ATA:79
PN:PN	MOS/MSC	10-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-03PROC. REF: EMM 79-30-03								
793030	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR							Component ATA:79
PN:PN	MOS/MSC	11-Nov-06	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: EMM 79-30-03PROC. REF: EMM 79-30-03								
ATA 80 - STARTING								
801001	CROSS START RELAY BOX							Component ATA:80
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 80-10-01PROC. REF: AMM 80-10-01								
801002	AIR START RELAY BOX							Component ATA:80
PN:PN	MOS/MSC	22-Aug-07	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 80-10-02PROC. REF: AMM 80-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task