

OWNER: WP AIR LLC
ADDRESS: 250 NORTH HARTFORD AVE STE 300
 COLUMBUS OH 43222
PHONE:
FAX:

OPERATOR: WP AIR LLC
ADDRESS: 250 NORTH HARTFORD AVE STE 300
 COLUMBUS OH 43222
PHONE:
FAX:

ANALYST: BOUN EM
EMAIL: BEM@CAMPSYSTEMS.COM

+1-316-462-2400 (DIRECT)
 1-866-581-2267 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS;

AIRCRAFT SERIAL/REGNO: 60 300/N357WP **MODEL:** LEARJET 60 **MANUFACTURER:** BOMBARDIER AVIATION

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	11-MAR-2006	4901.4 A/C HRS	as of 31-MAR-2022	A/C HRS	as of ___/___/___
		2815 AFL	as of 31-MAR-2022	AFL	as of ___/___/___
		1949 APH	as of 30-JAN-2022	APH	as of ___/___/___
		0 ACH	as of 04-SEP-2017	ACH	as of ___/___/___

APU SERIAL/PART: SP-E050424/4503134 **MODEL:** T-20G-10C3A (CIMMS) **MANUFACTURER:** HAMILTON SUNDSTRAND CORPORATION

INSTALLED ON 30-DEC-2005		LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS		1949 APU HRS	as of 30-JAN-2022	APU HRS	as of ___/___/___
0 APUS		2982 APUS	as of 30-JAN-2022	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-CA0457/31B4067-04 **MODEL:** PW305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 12-NOV-2012		LAST ACTUALS		CURRENT ACTUAL	
2852.1 ENG. HRS	2940.8 A/C HRS	4812.73 ENG. HRS	as of 31-MAR-2022	ENG. HRS	as of ___/___/___
1527 ENC		2767 ENC	as of 31-MAR-2022	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-CA0459/31B4067-04 **MODEL:** PW305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 17-MAR-2015		LAST ACTUALS		CURRENT ACTUAL	
3622.55 ENG. HRS	3839.9 A/C HRS	4685.08 ENG. HRS	as of 31-MAR-2022	ENG. HRS	as of ___/___/___
1881 ENC		2722 ENC	as of 31-MAR-2022	ENC	as of ___/___/___

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-A1	PHASE A1-300 HOUR							
	PKG 1	MOS	12	+14d/-14d	-52	31-MAR-2022	07-FEB-2023	21-FEB-2023
		HRS/MSC	300	+25/-25	-9.9	4901.4	5191.5	5216.5
	REF: AMM 5-10-01	AFL				2815		
<hr/>								
05-10-02-A2	PHASE A2-300 HOUR							
	PKG 2	MOS	12	+14d/-14d	-52	31-MAR-2022	07-FEB-2023	21-FEB-2023
		HRS/MSC	300	+25/-25	-9.9	4901.4	5191.5	5216.5
	REF: AMM 5-10-02	AFL				2815		
<hr/>								
05-10-03-A3	PHASE A3-300 HOUR							
	PKG 3	MOS	12	+14d/-14d	-52	31-MAR-2022	07-FEB-2023	21-FEB-2023
		HRS/MSC	300	+25/-25	-9.9	4901.4	5191.5	5216.5
	REF: AMM 5-10-03	AFL				2815		
<hr/>								
05-10-04-A4	PHASE A4-300 HOUR							
	PKG 4	MOS	12	+14d/-14d	-52	31-MAR-2022	07-FEB-2023	21-FEB-2023
		HRS/MSC	300	+25/-25	-9.9	4901.4	5191.5	5216.5
	REF: AMM 5-10-04	AFL				2815		
<hr/>								
05-10-05-A5	PHASE A5-300 HOUR							
	PKG 5	MOS	12	+14d/-14d	-52	31-MAR-2022	07-FEB-2023	21-FEB-2023
		HRS/MSC	300	+25/-25	-9.9	4901.4	5191.5	5216.5
	REF: AMM 5-10-05	AFL				2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-06-A6	PHASE A6-300 HOUR							
	PKG 6	MOS	12	+14d/-14d	-52	31-MAR-2022	07-FEB-2023	21-FEB-2023
		HRS/MSC	300	+25/-25	-9.9	4901.4	5191.5	5216.5
	REF: AMM 5-10-06	AFL				2815		
05-10-07-B1	PHASE B1-600 HOUR							
	PKG 7	MOS	24	+14d/-14d	-53	31-MAR-2022	07-FEB-2024	21-FEB-2024
		HRS/MSC	600	+25/-25	-9.9	4901.4	5491.5	5516.5
	REF: AMM 5-10-07	AFL				2815		
05-10-08-B2	PHASE B2-600 HOUR							
	PKG 8	MOS	24	+14d/-14d	-53	31-MAR-2022	07-FEB-2024	21-FEB-2024
		HRS/MSC	600	+25/-25	-9.9	4901.4	5491.5	5516.5
	REF: AMM 5-10-08	AFL				2815		
05-10-09-B3	PHASE B3-600 HOUR							
	PKG 9	MOS	24	+14d/-14d	-53	31-MAR-2022	07-FEB-2024	21-FEB-2024
		HRS/MSC	600	+25/-25	-9.9	4901.4	5491.5	5516.5
	REF: AMM 5-10-09	AFL				2815		
05-10-10-B4	PHASE B4-600 HOUR							
	PKG 10	MOS	24	+14d/-14d	-53	31-MAR-2022	07-FEB-2024	21-FEB-2024
		HRS/MSC	600	+25/-25	-9.9	4901.4	5491.5	5516.5
	REF: AMM 5-10-10	AFL				2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-11-B5	PHASE B5-600 HOUR							
	PKG 11	MOS	24	+14d/-14d	-53	31-MAR-2022	07-FEB-2024	21-FEB-2024
		HRS/MSC	600	+25/-25	-9.9	4901.4	5491.5	5516.5
	REF: AMM 5-10-11	AFL				2815		
05-10-12-B6	PHASE B6-600 HOUR							
	PKG 12	MOS	24	+14d/-14d	-53	31-MAR-2022	07-FEB-2024	21-FEB-2024
		HRS/MSC	600	+25/-25	-9.9	4901.4	5491.5	5516.5
	REF: AMM 5-10-12	AFL				2815		
05-10-13-C1	PHASE C1-1200 HOUR							
	PKG 13	MOS	48	+14d/-14d	-52	31-MAR-2022	07-FEB-2026	21-FEB-2026
		HRS/MSC	1200	+25/-25		4901.4	6101.4	6126.4
	REF: AMM 5-10-13	AFL				2815		
05-10-14-C2	PHASE C2-1200 HOUR							
	PKG 14	MOS	48	+14d/-14d	-52	31-MAR-2022	07-FEB-2026	21-FEB-2026
		HRS/MSC	1200	+25/-25		4901.4	6101.4	6126.4
	REF: AMM 5-10-14	AFL				2815		
05-10-15-C3	PHASE C3-1200 HOUR							
	PKG 15	MOS	48	+14d/-14d	-52	31-MAR-2022	07-FEB-2026	21-FEB-2026
		HRS/MSC	1200	+25/-25		4901.4	6101.4	6126.4
	REF: AMM 5-10-15	AFL				2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-16-C4	PHASE C4-1200 HOUR							
	PKG 16	MOS	48	+14d/-14d	-52	31-MAR-2022	07-FEB-2026	21-FEB-2026
		HRS/MSC	1200	+25/-25		4901.4	6101.4	6126.4
	REF: AMM 5-10-16	AFL				2815		
05-10-17-C5	PHASE C5-1200 HOUR							
	PKG 17	MOS	48	+14d/-14d	-52	31-MAR-2022	07-FEB-2026	21-FEB-2026
		HRS/MSC	1200	+25/-25		4901.4	6101.4	6126.4
	REF: AMM 5-10-17	AFL				2815		
05-10-18-C6	PHASE C6-1200 HOUR							
	PKG 18	MOS	48	+14d/-14d	-52	31-MAR-2022	07-FEB-2026	21-FEB-2026
		HRS/MSC	1200	+25/-25		4901.4	6101.4	6126.4
	REF: AMM 5-10-18	AFL				2815		
05-10-19-D1	PHASE D1-2400 HOUR							
	PKG 19	MOS	96	+14d/-14d		07-FEB-2018	07-FEB-2026	21-FEB-2026
		HRS/MSC	2400	+25/-25		3852.6	6252.6	6277.6
	REF: AMM 5-10-19	AFL				1982		
05-10-20-D2	PHASE D2-2400 HOUR							
	PKG 20	MOS	96	+14d/-14d		07-FEB-2018	07-FEB-2026	21-FEB-2026
		HRS/MSC	2400	+25/-25		3852.6	6252.6	6277.6
	REF: AMM 5-10-20	AFL				1982		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-21-D3	PHASE D3-2400 HOUR							
	PKG 21	MOS	96	+14d/-14d		07-FEB-2018	07-FEB-2026	21-FEB-2026
		HRS/MSC	2400	+25/-25		3852.6	6252.6	6277.6
	REF: AMM 5-10-21	AFL				1982		
05-10-22-D4	PHASE D4-2400 HOUR							
	PKG 22	MOS	96	+14d/-14d		07-FEB-2018	07-FEB-2026	21-FEB-2026
		HRS/MSC	2400	+25/-25		3852.6	6252.6	6277.6
	REF: AMM 5-10-22	AFL				1982		
05-10-23-D5	PHASE D5-2400 HOUR							
	PKG 23	MOS	96	+14d/-14d		07-FEB-2018	07-FEB-2026	21-FEB-2026
		HRS/MSC	2400	+25/-25		3852.6	6252.6	6277.6
	REF: AMM 5-10-23	AFL				1982		
05-10-24-D6	PHASE D6 2400 HOUR							
	PKG 24	MOS	96	+14d/-14d		07-FEB-2018	07-FEB-2026	21-FEB-2026
		HRS/MSC	2400	+25/-25		3852.6	6252.6	6277.6
	REF: AMM 5-10-24	AFL				1982		
05-10-25-3000 LDG	3000 LANDING							
	PKG 25	MOS				11-MAR-2006		
		HRS/MSC				0		
	REF: AMM 5-10-25	AFL	3000	+25/-25		0	3000	3025

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-26-6000 LDG	MAJOR LANDING GEAR							
	PKG 26	MOS				11-MAR-2006		
		HRS/MSC				0		
	REF: AMM 5-10-26	AFL	6000	+25/-25		0	6000	6025
05-10-27-12 YR	12 YEAR AIRFRAME							
	PKG 27	MOS	144	+14d/-14d		07-FEB-2018	07-FEB-2030	21-FEB-2030
		HRS/MSC				3852.6		
	REF: AMM 05-10-27	AFL	6000	+25/-25		1982	7982	8007
05-10-28-12000 HR	12000 HOUR AIRFRAME							
	PKG 28	MOS				11-MAR-2006		
		HRS/MSC	12000	+25/-25		0	12000	12025
	REF: AMM 5-10-28	AFL				0		

ENGINE NO. 1 Model : PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0457 Part # 31B4067-04

052000

NO. 1 ENGINE - MINOR INSPECTION ITEMS

PKG 1	MOS	24	+14d/-14d	-49	04-MAR-2021	14-JAN-2023	28-JAN-2023
	HRS/MSC	600	+25/-25		4525.42	(5125.42) 5214.08	5150.42
REF: GENERIC NO REF	ENC				2540		

ENGINE NO. 2 Model : PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0459 Part # 31B4067-04

052000

NO. 2 ENGINE - MINOR INSPECTION ITEMS

PKG 1	MOS	24	+14d/-14d	-7	04-MAR-2021	25-FEB-2023	11-MAR-2023
	HRS/MSC	600	+25/-25		4396.77	(4996.77) 5213.08	5021.77
REF: GENERIC NO REF	ENC				2495		

CHAPTER 70 STANDARD PRACTICES - ENGINES



BOMBARDIER

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
700010	LEFT ENGINE INSPECTION-AIRFRAME ITEMS							
	PKG 29	MOS				17-MAR-2015		
		HRS/MSC	3850			3839.9		7689.9
	REF: GENERIC NO REF	AFL				1974		
700020	RIGHT ENGINE INSPECTION-AIRFRAME ITEMS							
	PKG 30	MOS				17-MAR-2015		
		HRS/MSC	3850			3839.9		7689.9
	REF: GENERIC NO REF	AFL				1974		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
CI60-150730	REVIEW LEARJET 60 AMM REV A13, DATED 22-JUN-2015								
REQUIREMENT CHANGE FORMS	REF: RCF CI60	MOS HRS/MSC - AFL					(EBT)		
CI60-160128	REVIEW LEARJET 60/60XR AMM REV A14 DATED JAN 11/2016 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI60	MOS HRS/MSC - AFL					(EBT)		
CI60-161006	REVIEW LEARJET 60 AMM REVISION A15								
REQUIREMENT CHANGE FORMS	REF: RCF CI60	MOS HRS/MSC - AFL					(EBT)		
CI60-161011	REVIEW LEARJET 60 EINSPECTOR REVISION 2016.10.11								
REQUIREMENT CHANGE FORMS	REF: RCF CI60	MOS HRS/MSC - AFL							
CI60-170728	REVIEW LEARJET 60 AMM REVISION A16								
REQUIREMENT CHANGE FORMS	REF: RCF CI60	MOS HRS/MSC - AFL					01-SEP-2017 3840.35 1975		
+ CI60-171024	REVIEW LEARJET 60 EINSPECTOR REVISION 2017.10.24								
REQUIREMENT CHANGE FORMS	REF: RCF CI60	MOS HRS/MSC - AFL					11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI60-171027	REVIEW LEARJET 60/60XR AMM TR 04-06 AND 05-68	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI60	HRS/MSC - AFL							
<hr/>									
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
EC24-151014-1	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 63.0 DATED NOV 24/2014 - CAMP CHANGE FORM	MOS					24-NOV-2015		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
<hr/>									
EC24-151014-2	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 64.0 DATED JUN 15/2015 - CAMP CHANGE FORM	MOS					24-NOV-2015		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
<hr/>									
EC24-151014-3	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 65.0 DATED JUL 20/2015 - CAMP CHANGE FORM	MOS					24-NOV-2015		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
<hr/>									
EC24-160115	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL REV NO. 65.1 DATED DEC 9/2015	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-160516	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-161024	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 67.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-161220	NO. 1 ENGINE - REVIEW PW305/305A305B MM REV 67.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-170116	NO. 1 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2	MOS					24-JAN-2017		
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC - ENC					3751.65 1927		
EC24-170619	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B REV 68.0	MOS					01-SEP-2017		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC					3751.65 1927		
EC24-180214	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							

ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-151014-1	NO. 2 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 63.0 DATED NOV 24/2014 - CAMP CHANGE FORM	MOS						24-NOV-2015	
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-151014-2	NO. 2 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 64.0 DATED JUN 15/2015 - CAMP CHANGE FORM	MOS						24-NOV-2015	
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-151014-3	NO. 2 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 65.0 DATED JUL 20/2015 - CAMP CHANGE FORM	MOS						24-NOV-2015	
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-160115	NO. 2 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL REV NO. 65.1 DATED DEC 9/2015	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-160516	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-161024	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 67.0	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-161220	NO. 2 ENGINE - REVIEW PW305/305A305B MM REV 67.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
EC24-170116	NO. 2 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2	MOS					24-JAN-2017		
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC - ENC					3623 1882		
EC24-170619	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B REV 68.0	MOS					01-SEP-2017		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC					3623 1882		
EC24-180214	NO. 2 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 69.1	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC - ENC							
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05-50-02	PERFORM HARD LANDING OR DEPARTURE FROM RUNWAY MAINTENANCE CHECKS (REFER TO 5-50-00)								
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	MOS HRS/MSC A/R AFL					11-MAR-2006 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-03	PERFORM OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT) MAINTENANCE CHECKS (REFER TO 5-50-00)								
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	MOS HRS/MSC AFL	A/R				11-MAR-2006 0 0		
05-50-04	PERFORM SEVERE TURBULENCE AND/OR MANEUVERS MAINTENANCE CHECKS (REFER TO 5-50-00)								
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	MOS HRS/MSC AFL	A/R				11-MAR-2006 0 0		
05-50-05 (s)	PERFORM NO. 1 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00) PKG 29						PKG 11-MAR-2006		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	MOS HRS/MSC AFL	A/R				0 0		
05-50-05 (s)	PERFORM NO. 2 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00) PKG 30						PKG 11-MAR-2006		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	MOS HRS/MSC AFL	A/R				0 0		
05-50-06	PERFORM HIGH ENERGY STOP (LANDING AND REJECTED TAKEOFF) MAINTENANCE CHECKS (REFER TO 5-50-00)								
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	MOS HRS/MSC AFL	A/R				11-MAR-2006 0 0		
05-50-07	PERFORM PERFORM THRUST REVERSER INSPECTION FOR SLAM-STOW OR HIGH THRUST EMERGENCY STOW OPERATION (REFER TO 78-40-00)								
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	MOS HRS/MSC AFL	A/R				11-MAR-2006 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-08	PERFORM OVERSPEED RECOVERY LANDING GEAR INSPECTION (LANDING GEAR EXTENSION AND RETRACTION AT HIGH SPEED) (REFER TO 5-50-00)	MOS						11-MAR-2006	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R					0	
		AFL						0	
05-50-09	PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 5-50-00)	MOS						11-MAR-2006	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R					0	
		AFL						0	
05-50-10	PERFORM HIGH GROUND WIND GUST INSPECTION (REFER TO 5-50-00)	MOS						11-MAR-2006	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R					0	
		AFL						0	
05-50-11	PERFORM HEAT DAMAGE INSPECTION (REFER TO 5-50-00)	MOS						11-MAR-2006	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R					0	
		AFL						0	
05-50-12	PERFORM PRESSURE CABIN SKIN THICKNESS MEASUREMENTS (REFER TO 5-50-00)	MOS						11-MAR-2006	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R					0	
		AFL						0	
05-50-13	PERFORM FLAP INSPECTION AFTER CONTAMINATED RUNWAY TAKEOFF OR LANDING (REFER TO 5-50-00)	MOS						11-MAR-2006	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R					0	
		AFL						0	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-14	PERFORM VOLCANIC ASH INSPECTION AND MAINTENANCE PROCEDURES (REFER TO 5-50-00)	MOS					11-MAR-2006		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R				0		
		AFL					0		
05-50-15	MAINTENANCE PROCEDURES ON AIRCRAFT EXTERIOR SURFACE WITHIN SALT INFLUENCED ENVIRONMENTS (REFER TO 5-50-00)	MOS					11-MAR-2006		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R				0		
		AFL					0		
05-50-16	PERFORM FLAP OVERSPEED INSPECTION AND REPAIR (REFER TO 5-50-00)	MOS					11-MAR-2006		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R				0		
		AFL					0		
05-50-17	PERFORM FOREIGN OBJECT DAMAGE INSPECTION (REFER TO 5-50-00)	MOS							
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 5-50-00	HRS/MSC	A/R						
		AFL							
05-PATS-490005	VISUALLY INSPECT ALL MOUNT PARTS AND FUSELAGE ATTACHMENT POINTS FOR CRACKS OR DAMAGE	MOS					06-SEP-2012		
	REF: See Workcard	HRS/MSC	3000				2852.1		5852.1
		AFL					1527		
05-PATS-490006	PERFORM EXHAUST & INLET DOUBLER FRAMES & STRINGERS	MOS					11-MAR-2006		
	REF: See Workcard	HRS/MSC	10000				0		10000
		AFL					0		

APU Model : T-20G-10C3A (CIMMS) Serial # SP-E050424 Part # 4503134

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-PATS-490001	APU - INSPECT APU PER MANUFACTURERS INSTRUCTIONS REF: SMM 49-11-03	MOS HRS/MSC APUS	200				07-FEB-2018 1871 2703	2071	
05-PATS-490002	APU - ANNUAL INSPECTION OF APU MOUNTS FOR LOOSENESS & DAMAGE REF: SMM 49-11-03	MOS HRS/MSC APUS	12				04-MAR-2021 1946 2942	04-MAR-2022	
05-PATS-490004	APU - VISUALLY INSPECT ALL APU MOUNT PARTS & FUSELAGE ATTACHMENT POINTS FOR CRACKS OR DAMAGE REF: SMM 49-11-03	MOS HRS/MSC APUS	3000				30-DEC-2005 0 0	3000	
05-PATS-490007	APU - DRAIN EPA SUMP REF:	MOS HRS/MSC APUS	O/C				14-OCT-2013 1637.83 2222		
05-T20G-490001	APU - PERFORM OIL LEVEL CHECK REF: MM 49-20-00	MOS HRS/MSC APUS	PR/C				07-FEB-2018 1871 2703		
05-T20G-490002	APU - CHECK EXTERNAL FUEL AND OIL LEAKAGE, AIR INLET AND EXHAUST DUCTS FOR OBSTRUCTION AND ATTACHING BOLTS AND SCREWS FOR ATTACHMENT AND SECURITY REF: MM 49-20-00	MOS HRS/MSC APUS	500				07-FEB-2018 1871 2703	2371	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-T20G-HS-490003	APU - PERFORM APU OIL & FILTER CHANGE REF: See Workcard	MOS HRS/MSC APUS	24 500				07-FEB-2020 1934 2871	07-FEB-2022 2434	
05-T20G-HS-490004	APU - VISUAL INSPECTION ENGINE HARNESS REF: MM 49-20-00	MOS HRS/MSC APUS	500				07-FEB-2018 1871 2703	2371	
05-T20G-HS-490005	APU - INSPECT IGNITER PLUG CH38013 NSN REF: MM 49-20-00	MOS HRS/MSC APUS	500				17-OCT-2014 1760 2339	2260	
05-T20G-HS-490006	APU - INSPECT COMBUSTOR FUEL DRAIN LINE REF: MM 49-20-00	MOS HRS/MSC APUS	500				07-FEB-2018 1871 2703	2371	
05-T20G-HS-490007	APU - INSPECT OIL OVERFILL TUBE ASSEMBLY FOR CLEANLINESS AND OBSTRUCTIONS REF: MM 49-20-00	MOS HRS/MSC APUS	500				07-FEB-2018 1871 2703	2371	
05-T20G-HS-490010	APU - INSPECT APU HOUSING, COVERS AND BRACKETS REF: MM 49-20-00	MOS HRS/MSC APUS	500				07-FEB-2018 1871 2703	2371	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	-------------	------------	---------------------------	--------------

05-T20G-HS-490011	APU - REPLACE FUEL INLET FILTER	MOS	24				07-FEB-2020	07-FEB-2022	
		HRS/MSC	500				1934	2434	
	REF: MM 49-20-00	APUS					2871		

ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04

055002	NO. 1 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)	MOS					19-DEC-2005		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		

055003	NO. 1 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)	MOS					19-DEC-2005		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		

055004	NO. 1 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)	MOS					19-DEC-2005		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		

055005	NO. 1 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)	MOS					19-DEC-2005		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	ENC					0		

055008	NO. 1 ENGINE - PERFORM ENGINE OPERATION IN VISIBLE VOLCANIC ASH INSPECTION (REFER TO 05-50-00)	MOS					19-DEC-2005		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
055009	NO. 1 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)	MOS						19-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
055010	NO. 1 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)	MOS						19-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
055011	NO. 1 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)	MOS						19-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
055002	NO. 2 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)	MOS						29-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC	A/R				0		
		ENC					0		
055003	NO. 2 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)	MOS						29-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC	A/R				0		
		ENC					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
055004	NO. 2 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)	MOS						29-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC	A/R				0		
		ENC					0		
055005	NO. 2 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)	MOS						29-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
055008	NO. 2 ENGINE - PERFORM ENGINE OPERATION IN VISIBLE VOLCANIC ASH INSPECTION (REFER TO 05-50-00)	MOS						29-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC	A/R				0		
		ENC					0		
055009	NO. 2 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)	MOS						29-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
055010	NO. 2 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)	MOS						29-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
055011	NO. 2 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)	MOS						29-DEC-2005	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05-50 TIME LIMITS/MAINTENANCE CHECKS									
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
055012	NO. 1 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)							19-DEC-2005	
		MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard								
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
055012	NO. 2 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)							29-DEC-2005	
		MOS						0	
		HRS/MSC	A/R					0	
		ENC						0	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard								
CHAPTER 08 LEVELING AND WEIGHING									
082000	WEIGHT AND BALANCE							31-MAR-2022	31-MAR-2026
		MOS	48					4901.4	
		HRS/MSC						2815	
		AFL							
	REF: AMM 08-20-00								
CHAPTER 11 PLACARDS AND MARKINGS									
T1130001 (s)	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS. (REFER TO 11-30-00.)						PKG		
	PKG 20	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
		AFL						1982	
	REF: AMM 11-30-00								
CHAPTER 12 SERVICING									
121005	PERFORM NOSE AND MAIN TIRE PRESSURE CHECKS							07-FEB-2018	
		MOS							
		HRS/MSC	A/R						
		AFL						1982	
	REF: AMM 12-10-05								

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D1221001 (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR - LUBRICATE ATTACH FITTING. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
D1221002 (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-01) PKG 11 REF: AMM 12-21-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
D1221006 (s)	INSPECT THRUST REVERSERS - LUBRICATE IDLER LINKS AND DRIVE LINKS. (REFER TO 12-21-04) PKG 3 REF: AMM 12-21-04	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
D1221010 (s)	LUBRICATE MAIN LANDING GEAR AFT TRUNNION PIN. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
D1221011 (s)	LUBRICATE MAIN LANDING GEAR FORWARD TRUNNION PIN. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
D1221012 (s)	LUBRICATE MAIN LANDING GEAR TORQUE LINK BUSHINGS. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D1221013 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR STRUT ATTACH POINT. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
F1221008 (s)	LUBRICATE MAIN LANDING GEAR DOOR ACTUATOR (48C48608) PISTON ROD FELT WIPER. (REFER TO 12-21-01). PKG 11 REF: AMM 12-21-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221004 (s)	LUBRICATE NOSE LANDING GEAR DOORS HINGES. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221005 (s)	LUBRICATE MAIN LANDING GEAR DOORS HINGES. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221007 (s)	LUBRICATE NOSE LANDING GEAR UPLATCH ACTUATOR PISTON ROD FELT WIPERS. (REFER TO 12-21-01). PKG 11 REF: AMM 12-21-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221019 (s)	LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE. (REFER TO 12-21-03) PKG 6 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G1221020 (s)	LUBRICATE SINGLE POINT REFUELING ACCESS DOOR HINGES. (REFER TO 12-21-03) PKG 6 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221021 (s)	LUBRICATE EMERGENCY EXIT/BAGGAGE DOOR HINGES AND LATCH PINS. (REFER TO 12-21-03) PKG 6 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221023 (s)	LUBRICATE TOILET SERVICING DOOR HINGE. (REFER TO 12-21-03) PKG 6 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221024 (s)	LUBRICATE TAILCONE EQUIPMENT DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03) PKG 6 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221025 (s)	LUBRICATE TAILCONE BAGGAGE DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03) PKG 6 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1221029 (s)	INSPECT LOWER NACELLE - LUBRICATE HINGES. (REFER TO 12-21-03) PKG 3 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G1221030 (s)	LUBRICATE OXYGEN SERVICING ACCESS DOOR HINGE. (REFER TO 12-21-03) PKG 2 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
G1230000 (s)	INSPECT ALCOHOL ANTI-ICE TANK - CHECK FOR QUANTITY OF FLUID. (REFER TO 12-10-08) PKG 2 REF: AMM 12-10-08	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H1221003 (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.) PKG 17 REF: AMM 12-21-01	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H1221028 (s)	LUBRICATE UPPER AND LOWER ENTRY DOORS HINGES AND LATCH PINS. (REFER TO 12-21-03) PKG 12 REF: AMM 12-21-03	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
L1221017 (s)	LUBRICATE FLAP CAM FOLLOWERS. (REFER TO 12-21-02) PKG 4 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
L1221036 (s)	LUBRICATE SPOILER ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-02). PKG 10 REF: AMM 12-21-02	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
M1221038 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) WING ATTACH POINTS. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
M1221040 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.) PKG 17 REF: AMM 12-21-01	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
M1221041 (s)	INSPECT THRUST REVERSERS - LUBRICATE GUIDE RODS. (REFER TO 12-21-04) PKG 3 REF: AMM 12-21-04	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
P1210051 (s)	CHECK NOSE GEAR SHOCK STRUT FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-03) PKG 5 REF: AMM 12-10-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
P1210052 (s)	CHECK MAIN GEAR SHOCK STRUTS FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-04) PKG 5 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
P1210053 (s)	INSPECT EMERGENCY AIR PRESSURE GAUGE - CHECK FOR PROPER AIR PRESSURE (1800 TO 3000 PSI). (REFER TO 12-10-07) PKG 1 REF: AMM 12-10-07	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P1210054 (s)	INSPECT OXYGEN PRESSURE GAUGE - CHECK FOR PROPER INFLATION (1500 TO 1850 PSI). (REFER TO 12-10-09) PKG 1 REF: AMM 12-10-09	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
P1210055 (s)	CHECK NOSE AND MAIN TIRES FOR PROPER INFLATION. (REFER TO 12-10-05) PKG 5 REF: AMM 12-10-05	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
P1210056 (s)	INSPECT HYDRAULIC AND THRUST REVERSER ACCUMULATORS - CHECK ACCUMULATOR PRECHARGE (850 PSI). (REFER TO 12-21-04) PKG 3 REF: AMM 12-10-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
P1221043 (s)	LUBRICATE NOSE LANDING GEAR TRUNNION PINS. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
R1221039 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 2327100) PISTON ROD FELT WIPER. (REFER TO 12-21-01). PKG 11 REF: AMM 12-21-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
X1221045 (s)	LUBRICATE R/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184) PKG 2 REF: AMM 12-21-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			07-FEB-2020 4291.5 2345		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
X1221046 (s)	LUBRICATE L/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184)						PKG		
	PKG 2	MOS	12	+14d/-14d			07-FEB-2020		
	REF: AMM 12-21-03	HRS/MSC	300	+25/-25			4291.5		
		AFL					2345		
CHAPTER 21 AIR CONDITIONING									
05-10-29-L2150053	FUNCTION TEST REFRIGERATION SYSTEM PRESSURE SWITCH								
		MOS					11-MAR-2006		
	REF: AMM 21-50-05	HRS/MSC	O/C				0		
		AFL					0		
05-10-29-N2150019	PENETRANT INSPECT AC COMPRESSOR FAN BLADES								
		MOS					11-MAR-2006		
	REF: NDT 21-50-01	HRS/MSC	O/C				0		
		AFL					0		
05-10-29-U2130007	PERFORM CABIN LEAK RATE CHECK								
		MOS					07-FEB-2018		
	REF: AMM 21-30-00	HRS/MSC	1200	+25/-25			3852.6	5052.6	5077.6
		AFL					1982		
212001	COCKPIT AIR CHECK VALVE								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 21-20-01	AFL					0		
212003	LEFT CABIN AIR CHECK VALVE								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 21-20-02	AFL					0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212004	RIGHT CABIN AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212005	LEFT CABIN OVERHEAD DIFFUSER PN SN-UNKNOWN REF: AMM 21-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212006	RIGHT CABIN OVERHEAD DIFFUSER PN SN-UNKNOWN REF: AMM 21-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212007	AFT EVAPORATOR BLOWER ASSEMBLY 66-0261-2 K16721 REF: AMM 21-51-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212007A	INSPECT AFT EVAPORATOR BLOWER ASSEMBLY BRUSHES 66-0261-2 K16721 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-MAR-2006 0 0		
212008	FWD EVAPORATOR BLOWER ASSEMBLY 66-0251-4 K16123 REF: AMM 21-51-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212101	CABIN EVAPORATOR BLOWER PN SN-UNKNOWN REF: AMM 21-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212104	COCKPIT EVAPORATOR BLOWER PN SN-UNKNOWN REF: AMM 21-21-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212105	COCKPIT BLOWER CONTROL BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 21-21-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212155	LEFT BLEED AIR MUFFLER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212156	RIGHT BLEED AIR MUFFLER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212201	LEFT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN PN SN-UNKNOWN REF: AMM 21-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212202	RIGHT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN PN SN-UNKNOWN REF: AMM 21-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
212205	AVIONICS COOLING FAN PN SN-UNKNOWN REF: AMM 21-22-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213001	PRIMARY OUTFLOW VALVE 6600812-010 115-C0140 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213002	SECONDARY OUTFLOW VALVE 6600812-011 105-B0319 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213003	CABIN AIR PRESSURE SELECTOR 6600812-013 71-B0254 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213004	CABIN PRESSURE CONTROLLER 6600812-014 55-F0049 REF: AMM 21-30-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			13-JUN-2008 949.87 522		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213005	MANUAL PRESSURE CONTROLLER 6600812-9 1250D REF: AMM 21-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213008	PRESSURIZATION MODE SWITCH PN SN-UNKNOWN REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213009	EMERGENCY DEPRESSURIZATION SWITCH PN SN-UNKNOWN REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213010	CABIN PRESSURE INDICATOR 10403N04C00 0760A REF: AMM 21-30-10	MOS HRS/MSC AFL	O/C	N:3840.35 N:1975			30-MAR-2017 3840.35 1975		
213011	VACUUM REGULATOR 6600812-006 1379D REF: AMM 21-30-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213012	VACUUM PUMP 6600812-015 75-1636 REF: AMM 21-30-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213013	VACUUM CHECK VALVE 6600812-016 95-4225 REF: AMM 21-30-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213101	LEFT EMERGENCY PRESSURIZATION VALVE 61700-1 1030 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213102	RIGHT EMERGENCY PRESSURIZATION VALVE 61700-1 1031 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213103	LEFT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 781 REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213104	RIGHT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 759 REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213105	LEFT CONDITIONED AIR CHECK VALVE 6600210-5 7332AC REF: AMM 21-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213106	RIGHT CONDITIONED AIR CHECK VALVE 6600210-5 7325AC REF: AMM 21-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
213107	POSITIVE VENTILATION CHECK VALVE PN SN-UNKNOWN REF: AMM 21-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214001	FLOW CONTROL VALVE 320335-3 552 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214002	HEAT EXCHANGER 6608060-009 A177 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214101	COCKPIT HEATER PN SN-UNKNOWN REF: AMM 21-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214201	LEFT AUXILIARY CABIN HEATER 7026-3 0275 REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
214202	RIGHT AUXILIARY CABIN HEATER 7026-4 0286 REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214203	AUXILIARY HEAT OVERTEMPERATURE MONITOR BOX PN SN-UNKNOWN REF: AMM 21-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214301	LEFT OUTBOARD ELECTRIC FOOT WARMER ASSEMBLY PN SN-UNKNOWN REF: AMM 21-43-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214302	LEFT INBOARD ELECTRIC FOOT WARMER ASSEMBLY PN SN-UNKNOWN REF: AMM 21-43-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214303	RIGHT INBOARD ELECTRIC FOOT WARMER ASSEMBLY PN SN-UNKNOWN REF: AMM 21-43-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
214304	RIGHT OUTBOARD ELECTRIC FOOT WARMER ASSEMBLY PN SN-UNKNOWN REF: AMM 21-43-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215001	AIR CONDITIONING COMPRESSOR JBS222-1 SA2186 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			31-MAR-2022 4901.4 2815		
215003	CONDENSER 7608061-1 966 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215004	RECEIVER/DRYER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215005	FREON PRESSURE SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215006	COCKPIT EVAPORATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215007	FREON COMPRESSOR DRIVE (R134) MOTOR PN SN-UNKNOWN REF: AMM 21-51-02	MOS HRS/MSC AFL		N:0 N:0 N:0			11-MAR-2006 0 0		
OVERHAUL		AFL ACH	2000	+25/-25 N:0			0	2000	2025

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215007A	INSPECT/REPLACE FREON COMPRESSOR DRIVE (R134) MOTOR BRUSHES - 05-10-29-K2150036 PN SN-UNKNOWN REF: AMM 21-51-02	MOS HRS/MSC AFL ACH	1200	+25/-25			11-MAR-2006 0 0 0	1200	1225
215008	COCKPIT EVAPORATOR PRESSURE REGULATOR VALVE PN SN-UNKNOWN REF: AMM 21-50-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215009	CABIN EVAPORATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215010	CABIN EXPANSION VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215012	FREON MOTOR CONTROL BOX PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215013	K61 FREON MOTOR CONTACTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215016	FREON MOTOR DIFFERENTIAL CURRENT SENSOR 268-1-1 205470276 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215017	COMPRESSOR MOTOR HOURMETER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215031	ABSOLUTE PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215049	COCKPIT EXPANSION VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215101	FREON COMPRESSOR DRIVE (R-12) MOTOR ES61134-3 385 REF: AMM 21-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
215120	CONDENSER FAN PN SN-UNKNOWN REF: AMM 21-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216001	REMOTE CABIN TEMPERATURE SETTING BOX MSM-9660 030600303 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216002	CREW TEMPERATURE SELECTOR PN SN-UNKNOWN REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216004	TEMPERATURE CONTROL INDICATOR 820-699 335 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216005	COCKPIT TEMPERATURE CONTROLLER 625734-2 625734-01083 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216006	CABIN TEMPERATURE CONTROLLER 625734-2 625734-01082 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216007	COCKPIT TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216008	CABIN TEMPERATURE SENSOR 625704-1 105C-6859 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216009	COCKPIT TEMPERATURE SENSOR BLOWER 6600231-1 6829 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-JUL-2011 2290.88 1230		
216010	CABIN TEMPERATURE SENSOR BLOWER PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216011	COCKPIT SKIN TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216012	CABIN SKIN TEMPERATURE SENSOR 625704-1 105C-6860 REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216013	COCKPIT TEMPERATURE CONTROL VALVE 3291290-1 612 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216014	CABIN TEMPERATURE CONTROL VALVE 3291290-2 604 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216015	COCKPIT TEMPERATURE CONTROL VALVE TORQUE MOTOR 124904-1-1 6190 REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216016	CABIN TEMPERATURE CONTROL VALVE TORQUE MOTOR 124904-1-1 6194 REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216017	SERVO AIR PRESSURE REGULATOR 6600245-004 1112 REF: AMM 21-60-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216018	COCKPIT AIR DISTRIBUTION CHECK VALVE 3202078-1 1322 REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216019	CABIN AIR DISTRIBUTION CHECK VALVE 3202188-1 709 REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216020	COCKPIT DUCT TEMPERATURE SENSOR 627962-2 627962-19236 REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216021	CABIN DUCT TEMPERATURE SENSOR 627962-2 627962-19235 REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216022	COCKPIT DUCT OVERHEAT THERMOSTAT PN SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216023	CABIN DUCT OVERHEAT THERMOSTAT PN SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216024	CLIMATE CONTROL BOX PN SN-UNKNOWN REF: AMM 21-60-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216025	PILOT ELECTRICAL EQUIPMENT BOX PN SN-UNKNOWN REF: AMM 21-60-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216050	MEMBRANE, CABIN TEMPERATURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216101	CABIN TEMPERATURE INDICATOR 820-701 324 REF: AMM 21-61-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
216102	CABIN TEMPERATURE INDICATOR SENSOR PN SN-UNKNOWN REF: AMM 21-61-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
218105	LEFT TRANSITION DUCT ASSEMBLY PN SN-UNKNOWN REF: AMM 21-51-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
218106	RIGHT TRANSITION DUCT ASSEMBLY PN SN-UNKNOWN REF: AMM 21-51-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
B2121004 (s)	INSPECT POSITIVE VENTILATION CHECK VALVE. (REFER TO 21-31-04.) PKG 25 REF: AMM 21-31-04	MOS HRS/MSC AFL	3000				11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C2132030 (s)	INSPECT CABIN (PRESSURE) CONDITIONED AIR CHECK VALVES. (REFER TO 21-31-03.) PKG 25	MOS HRS/MSC					PKG 11-MAR-2006 0		
	REF: AMM 21-31-03	AFL	3000	+25/-25			0		
C2132031 (s)	INSPECT CABIN AIR AND COCKPIT AIR CHECK VALVES. (REFER TO 21-20-01 AND 21-20-02.) PKG 25	MOS HRS/MSC					PKG 11-MAR-2006 0		
	REF: AMM 21-20-01	AFL	3000	+25/-25			0		
E2130005 (s)	BORESCOPE INSPECTION PRIMARY AND SECONDARY OUTFLOW VALVE POPPETS AND SEATS FOR CONTAMINATION. (REFER TO 21-30-00). PKG 13	MOS HRS/MSC	48	+14d/-14d			PKG 31-MAR-2022 4901.4		
	REF: AMM 21-30-00	AFL	1200	+25/-25			2815		
E2130064 (s)	REMOVE AND REPLACE CABIN AIR FILTER. (REFER TO 21-30-06). PKG 13	MOS HRS/MSC	48	+14d/-14d			PKG 31-MAR-2022 4901.4		
	REF: AMM 21-30-06	AFL	1200	+25/-25			2815		
H2132004 (s)	PERFORM FUNCTIONAL TEST OF EMERGENCY PRESSURIZATION SYSTEM. (REFER TO 21-31-00) PKG 7	MOS HRS/MSC	24	+14d/-14d			PKG 31-MAR-2022 4901.4		
	REF: AMM 21-31-00	AFL	600	+25/-25			2815		
H2150000 (s)	INSPECT REFRIGERATION (AIR CONDITIONING) SYSTEM COMPONENTS INSTALLATION FOR PROPER V-BELT TENSION, SECURITY OF MOUNTING, AND GENERAL CONDITION. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND SHAFT) PKG 9	MOS HRS/MSC	24	+14d/-14d			PKG 31-MAR-2022 4901.4		
	REF: See Workcard	AFL	600	+25/-25			2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
K2150006 (s)	PERFORM REFRIGERATION COMPRESSOR MOTOR BRUSH WEAR INSPECTION. (REFER TO 21-50-02) PKG 9	MOS	24	+14d/-14d			PKG	31-MAR-2022	
	REF: AMM 21-50-02	HRS/MSC AFL	600	+25/-25			4901.4 2815		
L2150048 (s)	FUNCTIONAL TEST OF REFRIGERATION SYSTEM PRESSURE SWITCH. (REFER TO 21-50-05.) PKG 21	MOS	96	+14d/-14d			PKG	07-FEB-2018	
	REF: AMM 21-50-05	HRS/MSC AFL	2400	+25/-25			3852.6 1982		
N2131010 (s)	FUNCTIONAL TEST OF CABIN PRESSURE WARNING SYSTEM. (REFER TO 21-30-00.) PKG 13	MOS	48	+14d/-14d			PKG	31-MAR-2022	
	REF: AMM 21-30-00	HRS/MSC AFL	1200	+25/-25			4901.4 2815		
N2144000 (s)	FUNCTIONAL TEST OF TAILCONE BAGGAGE COMPARTMENT HEATING SYSTEM. (REFER TO 21-44-00.) PKG 21	MOS	96	+14d/-14d			PKG	07-FEB-2018	
	REF: AMM 21-44-00	HRS/MSC AFL	2400	+25/-25			3852.6 1982		
N2150017 (s)	PERFORM A FLUORESCENT PENETRANT INSPECTION OF THE AIR CONDITIONER COMPRESSOR MOTOR FAN BLADES. PARTICULAR ATTENTION SHOULD BE GIVEN TO THE FAN BLADES IN THE AREA OF THE HUB. (REFER TO NDI MANUAL [NDI-2], PART 5, 21-50-01.) PKG 15	MOS	48	+14d/-14d			PKG	31-MAR-2022	
	REF: NDT 21-50-01	HRS/MSC AFL	1200	+25/-25			4901.4 2815		
P2130070 (s)	FUNCTIONAL TEST OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00) PKG 13	MOS	48	+14d/-14d			PKG	31-MAR-2022	
	REF: AMM 21-30-00	HRS/MSC AFL	1200	+25/-25			4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2120001 (s)	INSPECT RAM AIR DUCTING AND HEAT EXCHANGER FRO SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 21	MOS	96	+14d/-14d			07-FEB-2018		
		HRS/MSC	2400	+25/-25			3852.6		
	REF: GENERIC NO REF	AFL					1982		
T2130012 (s)	PERFORM FUNCTIONAL TEST OF PRESSURIZATION SYSTEM VACUUM PUMP HEATING ELEMENT. (REFER TO 21-30-12)						PKG		
	PKG 8	MOS	24	+14d/-14d			07-FEB-2020		
		HRS/MSC	600	+25/-25			4291.5		
	REF: AMM 21-30-12	AFL					2345		
T2130069 (s)	PERFORM OPERATIONAL CHECK OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00)						PKG		
	PKG 7	MOS	24	+14d/-14d			31-MAR-2022		
		HRS/MSC	600	+25/-25			4901.4		
	REF: AMM 21-30-00	AFL					2815		
T2142002 (s)	FUNCTIONAL TEST OF AUXILIARY CABIN HEAT SYSTEM. (REFER TO 21-42-00.)						PKG		
	PKG 13	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: AMM 21-42-00	AFL					2815		
T2144010 (s)	VISUALLY INSPECT TAILCONE BAGGAGE COMPARTMENT HEATER BLANKETS. (REFER TO 5-10-00.)						PKG		
	PKG 21	MOS	96	+14d/-14d			07-FEB-2018		
		HRS/MSC	2400	+25/-25			3852.6		
	REF: GENERIC NO REF	AFL					1982		
CHAPTER 22	AUTO FLIGHT								
221001	AUTOPILOT CONTROLLER								
	501-1679-02	MOS					23-FEB-2016		
	1285	HRS/MSC	O/C				3839.9		
	REF: AMM 22-10-01	AFL					1974		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221002	AUTOPILOT ELECTRICAL BOX PN SN-UNKNOWN REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
221003	PITCH SERVO ACTUATOR 622-5027-102 22J8J REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
221004	PITCH SERVO MOUNT 622-5029-101 20D4X REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
221005	AUTOPITCH TRIM AMPLIFIER BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
221006	ROLL SERVO ACTUATOR 622-5027-102 21JKR REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	N:834.9 N:454			28-JUL-2008 1030.08 559		
221007	ROLL DISCONNECT RELAY BOX PN SN-UNKNOWN REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221008	YAW DISCONNECT RELAY BOX PN SN-UNKNOWN REF: AMM 22-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
221009	YAW SERVO ACTUATOR 622-5027-102 20F0V REF: AMM 22-10-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
221010	YAW SERVO MOUNT 622-5029-101 21K4B REF: AMM 22-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
221011	ROLL SERVO MOUNT 622-5029-102 22KMY REF: AMM 22-10-11	MOS HRS/MSC AFL	O/C				28-JUL-2008 1030.08 559		
221012	REMOTE TUNING RELAY BOX PN SN-UNKNOWN REF: AMM 22-10-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
222001	MACH TRIM COMPUTER 501-1132-04 80019 REF: AMM 22-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
222002	MACH TRIM ADAPTER 902-1-2 205420054 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
222003	MACH TRIM POSITION (FOLLOW UP) SENSOR PN SN-UNKNOWN REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
225001	YAW FORCE INTERFACE BOX PN SN-UNKNOWN REF: AMM 22-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
225002	PILOT FORCE SENSOR 3454-101-650 2660 REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
225003	COPILOT FORCE SENSOR 3454-101-650 2656 REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
B2211016 (s)	CHECK PRIMARY YAW DAMPER SERVO ACTUATOR AND SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-09.) PKG 28 REF: AMM 22-10-10	MOS HRS/MSC AFL	12000	+25/-25			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B2212013 (s)	CHECK PITCH SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-06.) PKG 28 REF: AMM 22-10-04	MOS HRS/MSC AFL	12000	+25/-25			PKG 11-MAR-2006 0 0		
B2213006 (s)	CHECK AUTOPILOT ROLL SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-06.) PKG 28 REF: AMM 22-10-11	MOS HRS/MSC AFL	12000	+25/-25			PKG 11-MAR-2006 0 0		
H2211034 (s)	CHECK ROLL SERVO CABLE TENSION. (REFER TO 22-10-11.) PKG 17 REF: AMM 22-10-11	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H2211039 (s)	CHECK PITCH SERVO AND YAW SERVO CABLE TENSION. (REFER TO 22-10-04 AND 22-10-10.) PKG 15 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T2211022 (s)	CHECK YAW SERVO CABLE FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR CONDITION AND SECURITY. PKG 15 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T2212022 (s)	INSPECT ELEVATOR SERVO CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR GENERAL CONDITION AND SECURITY. PKG 15 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

CHAPTER 23 COMMUNICATIONS

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-LC23155000-SMM-2	DETAILED VISUAL INSPECTION IRIIDIUM ANTENNA SKIN CUTOUT AND DOUBLER	MOS					11-MAR-2006		
	REF:	HRS/MSC					0		
		AFL	4250				0	4250	
231101	NO. 1 VHF TRANSCEIVER	MOS					11-MAR-2006		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	REF: AMM 23-11-01			N:0			0		
231102	NO. 2 VHF TRANSCEIVER	MOS					11-MAR-2006		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	REF: AMM 23-11-01			N:0			0		
231103	NO. 1 VHF ANTENNA	MOS					11-MAR-2006		
	VF10-347	HRS/MSC	O/C	N:0			0		
	5148	AFL		N:0			0		
	REF: AMM 23-11-02			N:0			0		
231104	NO. 2 VHF ANTENNA	MOS					11-MAR-2006		
	VF10-347	HRS/MSC	O/C	N:0			0		
	5149	AFL		N:0			0		
	REF: AMM 23-11-02			N:0			0		
231121	AERO M SATCOM ANTENNA	MOS					11-MAR-2006		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	REF: GENERIC NO REF			N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231123	SATCOM PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231180	NO. 1 HF AUDIO AMPLIFIER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231181	NO. 2 HF AUDIO AMPLIFIER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231192	HF ANTENNA LEADTHRU INSULATOR PN SN-UNKNOWN REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231201	NO. 1 HF RECEIVER/EXCITER 064-1015-01 34345 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231202	NO. 2 HF RECEIVER/EXCITER 064-1015-01 32299 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-OCT-2008 1100.28 595		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231203	PRIMARY POWER AMPLIFIER/ANTENNA COUPLER 064-1017-01 19469 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231204	STANDBY POWER AMPLIFIER/ANTENNA COUPLER 064-1017-01 19464 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231205	HF ANTENNA 071-1269-02 1568 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231207	NO. 1 HF CONTROL UNIT 064-1016-03 3108 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			24-APR-2008 855.52 488		
231208	NO. 2 HF CONTROL UNIT 064-1016-03 12692 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231209	HF AUDIO ADAPTER PN SN-UNKNOWN REF: AMM 23-12-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231210	HF COMMUNICATION FUSE BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 23-12-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231211	(CBR8) HF REMOTE CIRCUIT BREAKER SM600BA25N1/N536-9077 92059 REF: AMM 23-12-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231271	HF GROUND ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231301	FLITEFONE TRANSCEIVER PN SN-UNKNOWN REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231302	FLITEFONE ANTENNA PN SN-UNKNOWN REF: AMM 23-13-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231303	COCKPIT FLITEFONE BASE - CONTROL UNIT PN SN-UNKNOWN REF: AMM 23-13-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231304	CABIN FLITEPHONE BASE - CONTROL UNIT PN SN-UNKNOWN REF: AMM 23-13-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231305	COCKPIT ASSEMBLY PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231306	CABIN ASSEMBLY PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231307	COCKPIT FLIGHT PHONE (TT-3000) HANDSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231308	CABIN FLIGHT PHONE (TT-3000) HANDSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231310	AIRBORNE RADIO TELECOMMUNICATIONS TRAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231312	CABIN DISTRIBUTION BUS REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231313	LEFT CABIN DISTRIBUTION, FLITEFONE REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231314	RIGHT CABIN DISTRIBUTION, FLITEFONE REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231315	CALL ALERTER, FLITEFONE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231316	ASSEMBLY, ARTU TRAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231317	MAGNASTAR (C-2000/C-750 TMU) ARTU PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231318	MAGNASTAR ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231319	MAGNASTAR ANALOG INTERFACE UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231320	AIRSAT 1 TRANSCEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231321	AIRSAT 1 HANDSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231335	CELLULAR PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231340	CELL PHONE ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231351	SATELLITE DATA (SDU) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231401	SELCAL CONTROL PANEL PN SN-UNKNOWN REF: AMM 23-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231402	SELCAL DECODER 2800-0012-105 5375053 REF: AMM 23-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231403	SELCAL SONALERT PN SN-UNKNOWN REF: AMM 23-14-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231501	PASSENGER BRIEFER CONTROL PANEL PN SN-UNKNOWN REF: AMM 23-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
231502	PASSENGER BRIEFER COMPUTER PN SN-UNKNOWN REF: AMM 23-15-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232001	IRIDIUM SATCOM TRANSCEIVER 500617-2 5408 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				02-OCT-2013		
232005	IRIDIUM SATCOM ANTENNA 500644-1/CI490-1 5023580 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
232010	COCKPIT IRIDIUM SATCOM PHONE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
232015	CABIN IRIDIUM SATCOM PHONE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
232020	COCKPIT IRIDIUM SATCOM HANDSET 463092-110 S3002067 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-APR-2008 855.52 488		
232025	CABIN IRIDIUM SATCOM HANDSET 463092-110 3001931 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-APR-2008 855.52 488		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232030	IRIDIUM SATCOM PHONE CRADLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
232035	IRIDIUM SATCOM PHONE CRADLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
232040	IRIDIUM SATCOM CORDLESS BASE UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
232045	IRIDIUM SATCOM CORDLESS BASE UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
232055	UNILINK (UL-601) PROCESSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
232120	SATPHONE ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233001	LEFT FORWARD CABIN STEREO SPEAKER EN-MT-60-8 120500752 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233002	RIGHT FORWARD CABIN STEREO SPEAKER EN-MT-60-8 120500747 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233003	LEFT AFT CABIN STEREO SPEAKER EN-MT-60-8 120500755 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233004	RIGHT AFT CABIN STEREO SPEAKER EN-MT-60-8 120500751 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233005	PASSENGER SPEAKER AMPLIFIER PN SN-UNKNOWN REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233007	DVD PLAYER DVD-301-01-1 060600463 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			22-APR-2008 855.52 488		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233023	FORWARD WOOFER, CABIN SPEAKER EN-W-60-4 030600503 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233024	AFT WOOFER, CABIN SPEAKER EN-W-60-4 020400301 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-APR-2008 855.52 488		
233026	VIDEO CASSETTE PLAYER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233030	CONFIGURATION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233040	INFRARED REMOTE CONTROL IFR-485-10-1 060500910 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233051	CD CHANGER MCD-102-RU-1 060501049 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233052	CONTROL HEAD CD CHANGER MCD-102-CH-1 100500043 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233075	CABIN DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233084	FORWARD 15.1 LCD COLOR DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233085	FORWARD VIDEO MONITOR- PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233086	AFT VIDEO MONITOR- PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233087	FORWARD 10.4 LCD COLOR DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233088	AFT 15.1 LCD COLOR DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233102	STEREO PN SN-UNKNOWN REF: AMM 23-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233105	AUDIO DISTRIBUTION MODULE PN SN-UNKNOWN REF: AMM 23-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233106	LEFT DIGITAL SELECTOR MODULE PN SN-UNKNOWN REF: AMM 23-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
233107	RIGHT DIGITAL SELECTOR MODULE PN SN-UNKNOWN REF: AMM 23-31-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
234101	INTERPHONE AUDIO AMPLIFIER MODEL204 2624 REF: AMM 23-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
235001	PILOT AUDIO CONTROL PANEL 802-009 2051 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
235002	COPILOT AUDIO CONTROL PANEL 802-009 819 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	R:6 R:0 R:0			14-OCT-2013 3035.77 1634		
235003	LEFT AUDIO AMPLIFIER 700-002 1713 REF: AMM 23-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
235004	RIGHT AUDIO AMPLIFIER 700-002 1714 REF: AMM 23-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
236005	WEATHER WORX XM RADIO CONTROLLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
236010	WEATHER WORX XM DATA PORT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237001	COCKPIT VOICE (CVR) RECORDER 1603-02-12 1514 REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C				17-MAR-2014 3200.95 1714		
237002	CVR REMOTE MICROPHONE AMPLIFIER 1635-02 225 REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
237003	CVR REMOTE AREA MICROPHONE 16301-01 1820 REF: AMM 23-70-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
237004	CVR INERTIA SWITCH PN SN-UNKNOWN REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
237021	CVR UNDERWATER LOCATOR (ULB) BEACON DK120 SD65052 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C				01-SEP-2017 3840.35 1975		
237021A	CLEAN/FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY DK120 SD65052 REF: AMM 25-63-00	MOS HRS/MSC AFL	24	+14d/-14d			08-JUL-2021 4712.9 2660	08-JUL-2023	22-JUL-2023

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237021B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000 DK120 SD65052 REF: AMM 25-63-00	MOS HRS/MSC AFL	DUE				01-SEP-2017 3840.35 1975	31-AUG-2023 M	
237021C	PERFORM FDR UNDERWATER LOCATOR (ULB) BEACON INSPECTION OF THE UNDERWATER LOCATING BEACON (DK100, DK120, DK130, DK140, DUKANE CORPORATION) PERFORM ACOUSTICS CHARACTERISTICS CHECK (REFER TO 25-63-00) DK120 SD65052 REF:	MOS HRS/MSC AFL	216				01-SEP-2017 3840.35 1975	01-SEP-2035	
237032	AUDIO/VIDEO AMPLIFIER AV-9665 120600346 REF: AMM 23-41-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			24-APR-2008 855.52 488		
238001	NO. 1 RADIO TUNING (RTU) UNIT 822-1825-102 1YG3M REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C				24-JUN-2013 2995.73 1605		
238002	NO. 2 RADIO TUNING (RTU) UNIT 822-1825-102 195 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			15-JAN-2010 1535.15 835		
239007	NO. 1 SWITCHING MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
239008	NO. 2 SWITCHING MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
239009	NO. 3 SWITCHING MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
239015	ORDINANCE SIGN SWITCH SP-60-004 020600360 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
239016	AUDIO AMPLIFIER PN SN-UNKNOWN REF: AMM 23-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
E2360010 (s)	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00) PKG 6 REF: AMM 23-60-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
E2360011 (s)	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00) PKG 6 REF: AMM 23-60-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H2360021 (s)	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.) PKG 22	MOS	96	+14d/-14d			PKG 07-FEB-2018 3852.6		
	REF: AMM 23-60-00	HRS/MSC AFL	2400	+25/-25			1982		
P2360022 (s)	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.) PKG 24	MOS	96	+14d/-14d			PKG 07-FEB-2018 3852.6		
	REF: AMM 23-60-00	HRS/MSC AFL	2400	+25/-25			1982		
CHAPTER 24 ELECTRICAL POWER									
05-10-29-B2432010	INSPECT MAIN AIRCRAFT BATTERY INSTALLATION	MOS	6	+14d/-14d			31-MAR-2022 4901.4	30-SEP-2022	14-OCT-2022
	REF: AMM 24-31-01	HRS/MSC AFL					2815		
05-10-29-H2431017	PERFORM BATTERY CABLES & RECEPTACLES - BATTERY CONNECTOR INSPECTION	MOS					08-JUL-2021 4712.9	5012.9	5037.9
	REF: AMM 24-31-01	HRS/MSC AFL	300	+25/-25			2660		
242001	LEFT PRIMARY AC POWER INVERTER 501-1666-01	MOS			N:0		11-MAR-2006		
	80037	HRS/MSC	O/C		N:0		0		
	REF: AMM 24-20-01	AFL			N:0		0		
242002	RIGHT SECONDARY AC POWER INVERTER 501-1666-01	MOS			N:0		11-MAR-2006		
	80038	HRS/MSC	O/C		N:0		0		
	REF: AMM 24-20-01	AFL			N:0		0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242003	POWER MONITOR INDICATOR 11003-003 108761 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			24-JUL-2006 117.28 98		
242005	ISOLATION PARALLELING BOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
242009	NO. 1 GROUND FAULT TRANSFORMER CTSG700 3650 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
242010	NO. 2 GROUND FAULT TRANSFORMER CTSG700 3638 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
242016	GENERATOR CONTROL PANEL M6008801-300-002 W60300131-01 REF: AMM 24-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
242031	DC AMMETER SENSOR PN SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242032	NO. 1 DC CURRENT SENSOR 952-500-C 3129 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
242033	NO. 2 DC CURRENT SENSOR PN SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
242081	1200 VA, 115 VAC, 60 HZ INVERTER PN SN-UNKNOWN REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
243001	NO. 1 STARTER/GENERATOR 400SG138Q S00029 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			14-DEC-2018 4058.68 2139		
243001A	OVERHAUL NO. 1 STARTER/GENERATOR - (Y2431025) 400SG138Q S00029 REF: GENERIC NO REF	MOS HRS/MSC AFL	1000	+25/-25			14-DEC-2018 4058.68 2139	5058.68	5083.68
243002	NO. 2 STARTER/GENERATOR 400SG138Q-2 4017 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-DEC-2021 4833.3 2764		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243002A	OVERHAUL NO. 2 STARTER/GENERATOR - (Y2431025)								
	400SG138Q-2	MOS					03-DEC-2021		
	4017	HRS/MSC	1000	+25/-25			4833.3	5833.3	5858.3
OVERHAUL	REF: GENERIC NO REF	AFL					2764		
243003	APU STARTER/GENERATOR								
	400SG159Q	MOS		O:13			14-AUG-2014		
	1713	HRS/MSC	O/C	O:0			3487.22		
	REF: See Workcard	AFL		O:0			1827		
		APH		O:0			1752		
243003A	OVERHAUL/REPLACE APU STARTER/GENERATOR BRUSHES								
	400SG159Q	MOS					14-AUG-2014		
	1713	HRS/MSC					3487.22		
	REF: GENERIC NO REF	AFL					1827		
		APH	1000				1752	2752	
243005	LEFT (GCU) GENERATOR CONTROL UNIT								
	GCS-505-16B	MOS		N:0			11-MAR-2006		
	1676B	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-03	AFL		N:0			0		
243006	RIGHT (GCU) GENERATOR CONTROL UNIT								
	GCS-505-16B	MOS		N:0			11-MAR-2006		
	1675B	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-03	AFL		N:0			0		
243007	A11 GENERATOR CURRENT TRANSFORMER								
	CTSG700	MOS		N:0			11-MAR-2006		
	3661	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-30-04	AFL		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243008	2A11 GENERATOR CURRENT TRANSFORMER CTSG700 3369 REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
243009	A12 GENERATOR CURRENT TRANSFORMER CTSG700 3659 REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
243010	2A12 GENERATOR CURRENT TRANSFORMER CTSG700 3666 REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
243011	LEFT DC AMMETER CURRENT SENSOR 256-1 205450146 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
243012	RIGHT DC AMMETER CURRENT SENSOR 256-1 205450143 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
243049	UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY RG-380E/60L 41175187 REF: AMM 24-31-01	MOS HRS/MSC AFL	48	N:0			31-MAR-2022 4901.4 2815	31-MAR-2026	
SERVICE LIFE LIMIT									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243049B	CAPACITY CHECK UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002 RG-380E/60L 41175187 REF: AMM 12-22-00	MOS HRS/MSC AFL	6				31-MAR-2022 4901.4 2815	30-SEP-2022	
243050	LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY RG-380E/60L 41096626 REF: AMM 24-31-01	MOS HRS/MSC AFL	48	N:0 N:0 N:0			05-SEP-2020 4468.9 2486	05-SEP-2024	
SERVICE LIFE LIMIT									
243050B	CAPACITY CHECK LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002 RG-380E/60L 41096626 REF: AMM 12-22-00	MOS HRS/MSC AFL	6				31-MAR-2022 4901.4 2815	30-SEP-2022	
243055	EMERGENCY POWER (24VDC TO 5VDC) CONVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
243062	NO. 1 EMERGENCY POWER BATTERY 501-1712-02 1413 REF: AMM 24-32-01	MOS HRS/MSC AFL	O/C				04-MAR-2021 4614.1 2588		
243062A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 1 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010 501-1712-02 1413 REF: AMM 24-32-01	MOS HRS/MSC AFL	6	+14d/-14d			31-MAR-2022 4901.4 2815	30-SEP-2022	14-OCT-2022

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243062B	PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 1 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015								
	501-1712-02	MOS	12	+14d/-14d		-27	31-MAR-2022	04-MAR-2023	18-MAR-2023
	1413	HRS/MSC					4901.4		
	REF: See Workcard	AFL					2815		
243063	NO. 2 EMERGENCY POWER BATTERY								
	501-1712-02	MOS					04-MAR-2021		
	1396	HRS/MSC	O/C				4614.1		
	REF: AMM 24-32-01	AFL					2588		
243063A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010								
	501-1712-02	MOS	6	+14d/-14d			31-MAR-2022	30-SEP-2022	14-OCT-2022
	1396	HRS/MSC					4901.4		
	REF: AMM 24-32-01	AFL					2815		
243063B	PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015								
	501-1712-02	MOS	12	+14d/-14d		-27	31-MAR-2022	04-MAR-2023	18-MAR-2023
	1396	HRS/MSC					4901.4		
	REF: See Workcard	AFL					2815		
243103	BATTERY TEMPERATURE INDICATOR								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 24-31-03	AFL					0		
243301	NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK								
	PN	MOS					14-OCT-2013		
	SN-UNKNOWN	HRS/MSC	O/C				3035.77		
	REF: GENERIC NO REF	AFL					1634		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243301A	CHARGE NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030 PN SN-UNKNOWN REF: AMM 12-23-02	MOS HRS/MSC AFL	12	+14d/-14d		-52	31-MAR-2022 4901.4 2815	07-FEB-2023	21-FEB-2023
243302	NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-OCT-2013 3035.77 1634		
243302A	CHARGE NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030 PN SN-UNKNOWN REF: AMM 12-23-02	MOS HRS/MSC AFL	12	+14d/-14d		-52	31-MAR-2022 4901.4 2815	07-FEB-2023	21-FEB-2023
244002	GROUND POWER MONITOR- PN SN-UNKNOWN REF: AMM 24-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
245001	PILOT CIRCUIT BREAKER PANEL M6008817-300-001 W60300131-01 REF: AMM 24-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
245002	COPILOT CIRCUIT BREAKER PANEL M6008818-300-001 W60300131-01 REF: AMM 24-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
AA2432003 (s)	PERFORM OPERATIONAL CHECK OF AC POWER SYSTEM PKG 19 REF: AMM 24-20-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 11-MAR-2006 0 0		
H2400004 (s)	INSPECT PEDESTAL INTERIOR WIRING FOR WIRE ROUTING, CLEARANCES, DETERIORATION, AND GENERAL CONDITION. PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H2432001 (s)	OPERATIONAL CHECK EMERGENCY DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-51-00.) PKG 13 REF: AMM 24-51-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H2450021 (s)	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE. PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
P2400008 (s)	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCE, AND GENERAL CONDITION (THAT PORTION VISIBLE THROUGH WHEEL WELLS). PKG 11 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
Q2400006 (s)	PERFORM INSPECTION OF ALL 4 AWG OR GREATER ELECTRICAL CABLES. VERIFY THERE IS NO HEAT DAMAGE TO THE LARGE GAUGE WIRE TERMINAL CONNECTIONS TO THE POWER DISTRIBUTION ASSEMBLY. INSPECT CONNECTORS AND TERMINAL LUGS FOR CONDITION AND SECURITY. INSPECT CABLE ROUTING TO PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2400003 (s)	INSPECT ELECTRICAL WIRING, HYDRAULIC, AND PNEUMATIC LINES UNDER FLOORBOARDS FOR EVIDENCE OF LEAKAGE, SECURITY OF CLAMPS, AND CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 20	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: GENERIC NO REF	AFL						1982	
T2400009 (s)	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCES SECURITY, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 15	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T2432000 (s)	OPERATIONAL CHECK OF DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-50-00.)						PKG		
	PKG 19	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: AMM 24-50-00	AFL						1982	
T2450020 (s)	CHECK SWITCH AND CIRCUIT BREAKER PANELS FOR GENERAL CONDITION. ENSURE MARKINGS ARE CLEAR AND READABLE.						PKG		
	PKG 13	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
CHAPTER 25	EQUIPMENT/FURNISHINGS								
250000	STEREO/PAGE AMPLIFIER								
	PN	MOS		N:0				11-MAR-2006	
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	AFL		N:0				0	
251001	PILOT CREW SEAT								
	3A213-0007-01-2	MOS		N:0				11-MAR-2006	
	44999	HRS/MSC	O/C	N:0				0	
	REF: AMM 25-10-01	AFL		N:0				0	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251002	COPILOT CREW SEAT 3A213-0008-01-2 45000 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
251005	PILOT LIGHTED CHART HOLDER 10-62-01 4622 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
251006	COPILOT LIGHTED CHART HOLDER 10-62-01 4626 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
252001	LEFT FORWARD PASSENGER SEAT PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
252002	RIGHT FORWARD PASSENGER SEAT PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
252003	LEFT MID PASSENGER SEAT 303690-4ST 23906 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252004	RIGHT MID PASSENGER SEAT 303690-2ST 30270 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
252005	LEFT AFT PASSENGER SEAT 303690-1ST 30269 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
252006	RIGHT AFT PASSENGER SEAT 303690-3ST 24952 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
252007	RIGHT PASSENGER DIVAN SP-60-001A 030600309 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
252025	RIGHT LOWER DIFFUSER PN SN-UNKNOWN REF: AMM 25-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
252027	LEFT LOWER DIFFUSER PN SN-UNKNOWN REF: AMM 25-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253007	LEFT FORWARD COLD CATHODE LAMP INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
253009	LEFT FORWARD COLD CATHODE LAMP INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
253010	RIGHT FORWARD COLD CATHODE LAMP INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
253012	RIGHT FORWARD COLD CATHODE LAMP INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
253052	VOLTAGE REGULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
253068	WARMER-LIQUID PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253069	WARMER-LIQUID PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
253090	AM/FM/CASSETTE STEREO PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
255050	MICROWAVE OVEN 400-1726-01-L 06-01-38338 N/A EQUIPMENT NOT INSTALLED	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
255050A	ANNUAL INSPECTION MICROWAVE OVEN M100367ICT-SMM-1 (25-35-13) 400-1726-01-L 06-01-38338 N/A EQUIPMENT NOT INSTALLED	MOS HRS/MSC AFL	N/A				07-FEB-2018 3852.6 1982		
256001	(ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000 210-04374 REF: AMM 25-62-01	MOS HRS/MSC AFL	O/C	N:584			27-SEP-2017		
256001A	INSPECT/FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000 210-04374 REF: AMM 25-62-00	MOS HRS/MSC AFL	12	+14d/-14d			31-MAR-2022 4901.4 2815	31-MAR-2023	14-APR-2023

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256001B	REPLACE BATTERY - 05-11-00-L2564000 PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE				01-APR-2019	01-JAN-2024 M	
256003	ELT CONTROLLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
256010	ELT/NAV INTERFACE 453-6500 05281 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
256061	NO. 1 LIFE VEST 63600-101 L4891630 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		
256061A	INSPECT NO. 1 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891630 REF: See Workcard	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256062	NO. 2 LIFE VEST 63600-101 L4891631 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256062A	INSPECT NO. 2 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891631 REF: See Workcard	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256063	NO. 3 LIFE VEST 63600-101 L4891632 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		
256063A	INSPECT NO. 3 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891632 REF: See Workcard	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256064	NO. 4 LIFE VEST 63600-101 L4891633 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		
256064A	INSPECT NO. 4 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891633 REF: See Workcard	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256065	NO. 5 LIFE VEST 63600-101 L4891634 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256065A	INSPECT NO. 5 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891634 REF: See Workcard	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256066	NO. 6 LIFE VEST 63600-101 L4891635 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		
256066A	INSPECT NO. 6 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891635 REF: See Workcard	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256067	NO. 7 LIFE VEST 63600-101 L4891636 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		
256067A	INSPECT NO. 7 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891636 REF: See Workcard	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256068	NO. 8 LIFE VEST LAVATORY 63600-101 L4891637 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256068A	INSPECT NO. 8 LIFE VEST LAVATORY 63600-101 L4891637 REF: AMM 25-61-00	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256071	PILOT LIFE VEST 63600-101 L4891638 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		
256071A	INSPECT PILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891638 REF: See Workcard	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256072	COPILOT LIFE VEST 63600-101 L4891639 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-DEC-2020 4540.4 2538		
256072A	INSPECT COPILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 63600-101 L4891639 REF: AMM 25-61-00	MOS HRS/MSC AFL	60				20-DEC-2020 4540.4 2538	20-DEC-2025	
256076	FIRST AID KIT AFAK1.0 080917013 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256076A	CONDITION CHECK FIRST AID KIT INVENTORY & EXPIRATION DATES AFAK1.0 080917013 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				31-MAR-2022 4901.4 2815	31-MAR-2023	
256076B	INSPECT FIRST AID KIT CONTENTS AFAK1.0 080917013 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				31-MAR-2022 4901.4 2815	31-MAR-2023	
256078	EMERGENCY MEDICAL KIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
256078A	INSPECT EMERGENCY MEDICAL KIT CONTENTS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-MAR-2006 0 0		
256116	ELT REMOTE SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
256202	ELT ANTENNA 110-337 5085072 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256410	(ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY								
	PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
257101	NOSE AVIONICS EXHAUST BLOWER								
	PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-71-01	AFL		N:0			0		
258010	AIRSHOW DIGITAL INTERFACE UNIT								
	920040	MOS		N:0			11-MAR-2006		
	D03357101	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
258011	COCKPIT CONTROL - AIRSHOW UNIT								
	PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
258012	AIRSHOW FLIGHT DECK CONTROLLER								
	922000-2	MOS		N:0			11-MAR-2006		
	H00569139	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
258014	FORWARD AIRSHOW COLOR MONITOR-								
	AI-LCD151-11-1	MOS					14-JUN-2006		
	050600909	HRS/MSC	O/C				49		
	REF: GENERIC NO REF	AFL					44		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
258015	AFT AIRSHOW COLOR MONITOR- AI-LCD104-01-1 010200634 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
258016	FORWARD 10.4 LCD COLOR, AIRSHOW 400 DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
258017	AFT 10.4 LCD COLOR, AIRSHOW 400 DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
258020	AIRSHOW 400 VIDEO SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
E2510010 (s)	INSPECT CREW SEATS AND SEAT BELTS FOR OPERATION, SECURITY OF MOUNTING, AND GENERAL CONDITION PKG 1 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
N2571002 (s)	PERFORM FUNCTIONAL TEST OF NOSE AVIONICS COMPARTMENT EXHAUST BLOWERS AND THEIR RESPECTIVE CONTROL TEMPERATURE SWITCHES. (REFER TO 25-71-01.) PKG 14 REF: AMM 25-71-01	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P2520007 (s)	INSPECT CABIN SEATS AND SEAT BELTS FOR CONDITION; BAGGAGE COMPARTMENT, STOWAGE CABINETS, STOWAGE CABINET LATCHES, RUGS, HEADLINER, AND SIDE PANELS FOR SECURITY AND CONDITION.						PKG		
	PKG 2	MOS	12	+14d/-14d			31-MAR-2022		
		HRS/MSC	300	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
U2510005 (s)	GENERAL VISUAL INSPECTION GLARESHIELD, HEADLINER, AND TRIM STRIPS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00)						PKG		
	PKG 1	MOS	12	+14d/-14d			31-MAR-2022		
		HRS/MSC	300	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
U2540004 (s)	INSPECT ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.						PKG		
	PKG 8	MOS	24	+14d/-14d			31-MAR-2022		
		HRS/MSC	600	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
CHAPTER 26	FIRE PROTECTION								
261001	NO. 1 FIRE DETECTION CONTROL UNIT								
	377-02833	MOS					N:0	11-MAR-2006	
	0507-192	HRS/MSC	O/C				N:0	0	
	REF: AMM 26-11-02	AFL					N:0	0	
261002	NO. 2 FIRE DETECTION CONTROL UNIT								
	377-02833	MOS					N:0	11-MAR-2006	
	0507-190	HRS/MSC	O/C				N:0	0	
	REF: AMM 26-11-02	AFL					N:0	0	
261006	TAILCONE BLEED AIR OVERHEAT (E267) CONTROL BOX								
	35009-20	MOS					N:0	11-MAR-2006	
	D2933	HRS/MSC	O/C				N:0	0	
	REF: AMM 26-13-02	AFL					N:0	0	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261007	TAILCONE BLEED AIR OVERHEAT (E268) CONTROL BOX PN SN-UNKNOWN REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
261051	NO. 1 TEE DOUBLE CHECK VALVE PN SN-UNKNOWN REF: AMM 26-21-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
261052	NO. 2 TEE DOUBLE CHECK VALVE PN SN-UNKNOWN REF: AMM 26-21-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
261207	BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY FR2222 FX829 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
262013	FORWARD FIRE EXTINGUISHER BOTTLE 32700004-1 18613C1 REF: AMM 26-21-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			05-SEP-2020 4468.9 2486		
262013A	CHECK FORWARD FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY (REF TO 05-10-00) 32700004-1 18613C1 REF: AMM 26-21-00	MOS HRS/MSC AFL	6	+14d/-14d			31-MAR-2022 4901.4 2815	30-SEP-2022	14-OCT-2022

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262013C	HYDROSTATIC TEST FORWARD FIRE EXTINGUISHER BOTTLE 32700004-1 18613C1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			10-AUG-2020	10-AUG-2025	24-AUG-2025
262014	AFT FIRE EXTINGUISHER BOTTLE 32700004-1 28686C1 REF: AMM 26-21-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			07-FEB-2018 3852.6 1982		
262014A	CHECK AFT FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 05-10-00) 32700004-1 28686C1 REF: AMM 26-21-00	MOS HRS/MSC AFL	6	+14d/-14d			31-MAR-2022 4901.4 2815	30-SEP-2022	14-OCT-2022
262014C	HYDROSTATIC TEST AFT FIRE EXTINGUISHER BOTTLE 32700004-1 28686C1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			07-FEB-2018	07-FEB-2023	21-FEB-2023
262036	FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB M30903823 11006 REF: AMM 26-21-04	MOS HRS/MSC AFL	72	+14d/-14d	-37		31-MAR-2022 4901.4 2815	? ?	
+ 262036A	REPLACE FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB M30903823 11006 REF: AMM 26-21-04	MOS HRS/MSC AFL	108	+14d/-14d				? ?	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262037	AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB M30903823 11008	MOS HRS/MSC AFL	72	+14d/-14d			31-MAR-2022 4901.4 2815	? ?	
SERVICE LIFE LIMIT	REF: AMM 26-21-04								
+ 262037A	REPLACE AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB M30903823 11008	MOS HRS/MSC AFL	108	+14d/-14d				? ?	
LIFE LIMIT	REF: AMM 26-21-04								
262038	FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB M30903823 11004	MOS HRS/MSC AFL	72	+14d/-14d	-37		31-MAR-2022 4901.4 2815	? ?	
SERVICE LIFE LIMIT	REF: AMM 26-21-04								
+ 262038A	REPLACE FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB M30903823 11004	MOS HRS/MSC AFL	108	+14d/-14d				? ?	
LIFE LIMIT	REF: AMM 26-21-04								
262039	AFT ENGINE FIRE EXTINGUISHER AFT SQUIB M30903823 11002	MOS HRS/MSC AFL	72	+14d/-14d			31-MAR-2022 4901.4 2815	? ?	
SERVICE LIFE LIMIT	REF: AMM 26-21-04								
+ 262039A	REPLACE AFT ENGINE FIRE EXTINGUISHER AFT SQUIB M30903823 11002	MOS HRS/MSC AFL	108	+14d/-14d				? ?	
LIFE LIMIT	REF: AMM 26-21-04								

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262041	PILOT PORTABLE FIRE EXTINGUISHER 344T Y-197463 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:33 N:0 N:0			14-JAN-2015 3792.43 1953		
262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030 344T Y-197463 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d			10-JUL-2013	10-JUL-2025	24-JUL-2025
262041C	12 MONTH INSPECTION OF THE PILOTS HAND HELD FIRE EXTINGUISHER 344T Y-197463 REF:	MOS HRS/MSC AFL	12				31-MAR-2022 4901.4 2815	31-MAR-2023	
STLMC									
262042	COPILOT PORTABLE FIRE EXTINGUISHER 344T Y-197553 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				14-JAN-2015 3792.43 1953		
262042B	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030 344T Y-197553 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d			10-JUL-2013	10-JUL-2025	24-JUL-2025
262042C	12 MONTH INSPECTION OF THE COPILOTS HAND HELD FIRE EXTINGUISHER 344T Y-197553 REF:	MOS HRS/MSC AFL	12				31-MAR-2022 4901.4 2815	31-MAR-2023	
STLMC									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262045	NO. 1 ENGINE FIRE - PULL SWITCH 6608480-3 697 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
262046	NO. 2 ENGINE FIRE - PULL SWITCH 6608480-3 699 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
262050	APU FIRE EXTINGUISHER 50-1200 18-1014 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-SEP-2020 4468.9 2486		
262050C	INSPECT APU FIRE EXTINGUISHER WEIGHT CHECK AND REPLACE AS NECESSARY 50-1200 18-1014 REF: See Workcard	MOS HRS/MSC AFL	12				15-AUG-2021	15-AUG-2022	
262051	CABIN PORTABLE FIRE EXTINGUISHER C352TS Y361650 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:10			22-NOV-2013 3076.45 1651		
262051B	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030 C352TS Y361650 REF: GENERIC NO REF	MOS HRS/MSC AFL	144	+14d/-14d			22-JAN-2013	22-JAN-2025	05-FEB-2025

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262051C	12 MONTH INSPECTION OF THE CABIN HAND HELD FIRE EXTINGUISHER C352TS Y361650	MOS HRS/MSC AFL	12				31-MAR-2022 4901.4 2815	31-MAR-2023	
STLMC	REF:	AFL					2815		
262057	APU FIRE BOTTLE SQUIB PN SN-UNKNOWN	MOS HRS/MSC AFL	60	N:0 N:0			05-SEP-2020 4468.9 2486	05-SEP-2025	
LIFE LIMIT	REF: See Workcard	AFL					2486		
H2610010 (s)	INSPECT FIREWALL AND ACCESSORY GEARBOX FIRE DETECTOR ELEMENTS FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION. PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		PKG
REF: GENERIC NO REF		AFL					2815		
H2620020 (s)	DISCONNECT PLUMBING FROM THE FIRE EXTINGUISHER TWO-WAY CHECK VALVE ASSEMBLY. INSPECT FOR FREEDOM OF MOVEMENT OF THE TWO-WAY CHECK VALVE, EVIDENCE OF DEFECTS, WEAR, AND CORROSION. REPLACE VALVE CAP O-RING. (REFER TO 26-21-05.) PKG 21	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-FEB-2018 3852.6 1982		PKG
REF: AMM 26-21-05		AFL					1982		
P2620041 (s)	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. PKG 2	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		PKG
REF: GENERIC NO REF		AFL					2815		
Q2620010 (s)	PERFORM WEIGHT CHECK OF FIRE EXTINGUISHER CONTAINERS. AFTER INSTALLATION OF CONTAINERS, PERFORM FUNCTIONAL TEST OF ENGINE FIRE EXTINGUISHER SYSTEM. (REFER TO 26-21-00). PKG 9	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		PKG
REF: AMM 26-21-00		AFL					2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2614000 (s)	PERFORM FUNCTIONAL TEST OF BAGGAGE COMPARTMENT SMOKE DETECTOR SYSTEM. (REFER TO 26-12-00) PKG 8	MOS	24	+14d/-14d			PKG 31-MAR-2022 4901.4 2815		
	REF: AMM 26-12-00	HRS/MSC AFL	600	+25/-25			4901.4 2815		
+ T2620045 (s)	INSPECT COPILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE PKG 1	MOS	12	+14d/-14d			PKG 31-MAR-2022 4901.4 2815		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			4901.4 2815		
T2620045 (s)	INSPECT PILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. PKG 1	MOS	12	+14d/-14d			PKG 31-MAR-2022 4901.4 2815		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			4901.4 2815		
U2610020A (s)	INSPECT NO. 1 ENGINE TAILCONE FIRE DETECTION ELEMENT PKG 29	MOS					PKG 17-MAR-2015 3839.9 1974		
	REF: GENERIC NO REF	HRS/MSC AFL	3850				3839.9 1974		
U2610020B (s)	INSPECT NO. 2 ENGINE TAILCONE FIRE DETECTION ELEMENT PKG 30	MOS					PKG 17-MAR-2015 3839.9 1974		
	REF: GENERIC NO REF	HRS/MSC AFL	3850				3839.9 1974		
CHAPTER 27 FLIGHT CONTROLS									
05-10-29-H2750044L	PERFORM DETAILED INSPECTION OF THE LEFT FLAP CAM FOLLOWER BEARING	MOS					08-JUL-2021 4712.9 2660		
	REF: AMM 5-10-00	HRS/MSC AFL	1200	+25/-25	-25.68		4712.9 2660	5887.22	5912.22

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-29-H2750044R	PERFORM DETAILED INSPECTION OF THE RIGHT FLAP CAM FOLLOWER BEARING	MOS					08-JUL-2021		
	REF: AMM 5-10-00	HRS/MSC	1200	+25/-25		-25.68	4712.9	5887.22	5912.22
		AFL					2660		
05-11-00-E2710010L	REPLACE LEFT *AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)	MOS					14-AUG-2014		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	3600				3487.22	7087.22	
		AFL					1827		
05-11-00-E2710010R	REPLACE RIGHT *AILERON DRIVE YOKE BOLT (NAS1104-38D) (AWL*)	MOS					14-AUG-2014		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	3600				3487.22	7087.22	
		AFL					1827		
05-11-00-E2710013L	* REPLACE LEFT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)	MOS					14-AUG-2014		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	3600				3487.22	7087.22	
		AFL					1827		
05-11-00-E2710013R	* REPLACE RIGHT AILERON CENTER HINGE BOLT (AN4H13A) (AWL*)	MOS					14-AUG-2014		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	3600				3487.22	7087.22	
		AFL					1827		
05-11-00-E2710020L	REPLACE LEFT *AILERON CLEVIS BOLT (NAS464P4) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	20000				0	20000	
		AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2710020R	REPLACE RIGHT * AILERON CLEVIS BOLT (NAS464P4) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2710022L	* REPLACE LEFT AILERON SECTOR (5425105) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-10	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2710022R	* REPLACE RIGHT AILERON SECTOR (5425105) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-10	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2710024L	* REPLACE LEFT AILERON CLEVIS (2324517) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2710024R	* REPLACE RIGHT AILERON CLEVIS (2324517) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2710026L	REPLACE LEFT * AILERON YOKE ASSEMBLY (2324511) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0	20000	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2710026R	REPLACE RIGHT * AILERON YOKE ASSEMBLY (2324511) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2710028L	REPLACE LEFT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2710028R	REPLACE RIGHT * AILERON BEARING SUPPORT ASSEMBLY (5425016) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2710031L	REPLACE LEFT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2710031R	REPLACE RIGHT * AILERON HINGE BRACKET ASSEMBLY (2322530) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2720020	REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P5) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-20-01	HRS/MSC	20000				0		20000
		AFL					0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2720022	REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-20-09	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2720026	REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2730021L	REPLACE LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2730021R	REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2730022L	REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC	20000				0		20000
		AFL					0		
05-11-00-E2730022R	REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC	20000				0		20000
		AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2730024L	REPLACE LEFT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2730024R	REPLACE RIGHT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2740010	REPLACE * HORIZONTAL STABILIZER HINGE PIN (2331028) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-40-01	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2750002L	REPLACE LEFT FLAP NOSE ROLLER BUSHINGS (NAS76A4)	MOS					23-FEB-2016		
	REF: AMM 27-50-01	HRS/MSC AFL	1200	+25/-25			3839.9 1974	5039.9	5064.9
05-11-00-E2750002R	REPLACE RIGHT FLAP NOSE ROLLER BUSHINGS (NAS76A4)	MOS					23-FEB-2016		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	1200	+25/-25			3839.9 1974	5039.9	5064.9
05-11-00-E2750035L	REPLACE LEFT * FLAP SECTOR (2625031) (AWL*)	MOS					11-MAR-2006		
	REF: AMM 27-50-01	HRS/MSC AFL	6000				0 0	6000	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2750035R	REPLACE RIGHT * FLAP SECTOR (2625031) (AWL*)	MOS					11-MAR-2006		
	REF: AMM 27-50-01	HRS/MSC					0		
		AFL	6000				0		6000
05-11-00-E2760059L	REPLACE LEFT * SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14) (AWL*)	MOS					05-SEP-2020		
	REF: AMM 27-60-01	HRS/MSC	4500				4468.9		8968.9
LIFE LIMIT		AFL					2486		
05-11-00-E2760059R	REPLACE RIGHT * SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14) (AWL*)	MOS					05-SEP-2020		
	REF: AMM 27-60-01	HRS/MSC	4500				4468.9		8968.9
LIFE LIMIT		AFL					2486		
05-11-00-E2760061L	REPLACE LEFT * SPOILER ACTUATOR ARM (2422511) (AWL*)	MOS					05-SEP-2020		
	REF: AMM 27-60-04	HRS/MSC	4500				4468.9		8968.9
LIFE LIMIT		AFL					2486		
05-11-00-E2760061R	REPLACE RIGHT * SPOILER ACTUATOR ARM (2422511) (AWL*)	MOS					05-SEP-2020		
	REF: AMM 27-60-04	HRS/MSC	4500				4468.9		8968.9
LIFE LIMIT		AFL					2486		
05-11-00-E2760062L	REPLACE LEFT * SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)	MOS					05-SEP-2020		
	REF: AMM 27-60-04	HRS/MSC	4500				4468.9		8968.9
LIFE LIMIT		AFL					2486		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2760062R	REPLACE RIGHT * SPOILER ACTUATOR BOLT (NAS464P4) (AWL*)	MOS					05-SEP-2020		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4468.9 2486		8968.9
05-11-00-E2760063L	REPLACE LEFT * SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)	MOS					05-SEP-2020		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4468.9 2486		8968.9
05-11-00-E2760063R	REPLACE RIGHT * SPOILER CENTER PIVOT BOLT (NAS464P5) (AWL*)	MOS					05-SEP-2020		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4468.9 2486		8968.9
05-11-00-E2760064LI	REPLACE LEFT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)	MOS					05-SEP-2020		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4468.9 2486		8968.9
05-11-00-E2760064LO	REPLACE LEFT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)	MOS					05-SEP-2020		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4468.9 2486		8968.9
05-11-00-E2760064RI	REPLACE RIGHT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)	MOS					05-SEP-2020		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4468.9 2486		8968.9

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2760064RO	REPLACE RIGHT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*)	MOS					05-SEP-2020		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4468.9 2486	8968.9	
05-11-00-F2710036	REPLACE * PRIMARY AILERON CONTROL CABLES (AWL*)	MOS					08-JUL-2021		
LIFE LIMIT	REF: AMM 27-10-07	HRS/MSC AFL	2400				4712.9 2660	7112.9	
05-11-00-F2720029	REPLACE PRIMARY RUDDER CONTROL CABLES	MOS					08-JUL-2021		
LIFE LIMIT	REF: AMM 27-20-10	HRS/MSC AFL	2400	+25/-25			4712.9 2660	7112.9 M 7137.9	
05-11-00-F2730030	REPLACE * PRIMARY ELEVATOR CONTROL SYSTEM CABLES (AWL*)	MOS					08-JUL-2021		
LIFE LIMIT	REF: AMM 27-30-05	HRS/MSC AFL	2400				4712.9 2660	7112.9	
05-11-00-G2740011	REPLACE * HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS (NAS464P6) (AWL*)	MOS	144				07-FEB-2018	07-FEB-2030	
LIFE LIMIT	REF: AMM 27-40-02	HRS/MSC AFL	6000				3852.6 1982	7982	
05-11-00-G2750034L	REPLACE LEFT WING FLAP SECTOR MOUNTING BOLT	MOS	144	+14d/-14d			07-FEB-2018	07-FEB-2030	21-FEB-2030
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	6000	+25/-25			3852.6 1982	7982	8007

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-G2750034R	REPLACE RIGHT WING FLAP SECTOR MOUNTING BOLT	MOS	144	+14d/-14d			07-FEB-2018	07-FEB-2030	21-FEB-2030
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC					3852.6		
		AFL	6000	+25/-25			1982	7982	8007
05-11-00-L2750027LI	REPLACE LEFT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC					0		
		AFL	20000				0	20000	
05-11-00-L2750027LO	REPLACE LEFT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC					0		
		AFL	20000				0	20000	
05-11-00-L2750027RI	REPLACE RIGHT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC					0		
		AFL	20000				0	20000	
05-11-00-L2750027RO	REPLACE RIGHT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC					0		
		AFL	20000				0	20000	
05-11-00-L2750028	REPLACE * INBOARD NOSE ROLLER TRACK (2322511) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC					0		
		AFL	20000				0	20000	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-L2750029	REPLACE * OUTBOARD NOSE ROLLER TRACK (2322512) (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000				0		20000
<hr/>									
05-11-00-L2750033L	REPLACE LEFT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000				0		10000
<hr/>									
05-11-00-L2750033R	REPLACE RIGHT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000				0		10000
<hr/>									
05-11-00-M2710021LI	REPLACE LEFT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC	20000				0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL					0		
<hr/>									
05-11-00-M2710021LO	REPLACE LEFT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC	20000				0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL					0		
<hr/>									
05-11-00-M2710021RI	REPLACE RIGHT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC	20000				0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-M2710021RO	REPLACE RIGHT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0	20000	
05-11-00-M2730031	REPLACE * HINGE ASSEMBLIES (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 INBOARD)(LOCATED ON HORIZONTAL STABILIZER ASSEMBLY) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC AFL	20000				0 0	20000	
05-11-00-M2750049LI	REPLACE LEFT INBOARD * FLAP SUPPORT FITTING (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0	20000	
05-11-00-M2750049LO	REPLACE LEFT OUTBOARD * FLAP SUPPORT FITTING (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0	20000	
05-11-00-M2750049RI	REPLACE RIGHT INBOARD * FLAP SUPPORT FITTING (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0	20000	
05-11-00-M2750049RO	REPLACE RIGHT OUTBOARD * FLAP SUPPORT FITTING (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0	20000	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-N2750025	REPLACE * INBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625023) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	6000				0 0		6000
05-11-00-N2750026	REPLACE * OUTBOARD FLAP TRACK HINGE FITTING (ON FLAP) (P/N 2625024) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	6000				0 0		6000
05-11-00-N2750031	REPLACE * INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-1 THRU-8) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	3000				0 0		3000
05-11-00-N2750032	REPLACE * UPPER FLAP SECTOR BRACKET ASSEMBLY (6022511-1, -2, -801, AND -802) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	3000				0 0		3000
05-11-00-N2750051	REPLACE * INBOARD FLAP HINGE FITTING (P/N 6025022) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-N2750052	REPLACE * OUTBOARD FLAP HINGE FITTING (P/N 6025021) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-R2750050L	REPLACE LEFT UPPER * UPPER FLAP SECTOR BRACKET (AWL*)								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000				0		20000
05-11-00-R2750050R	REPLACE RIGHT UPPER * UPPER FLAP SECTOR BRACKET (AWL*)								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC					0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000				0		20000
05-11-00-R2760079L	REPLACE LEFT LEFT * SPOILER ACTUATOR ATTACH FITTING AND BOLT (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC	10000				0		10000
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
05-11-00-R2760079R	REPLACE RIGHT RIGHT * SPOILER ACTUATOR ATTACH FITTING AND BOLT (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC	10000				0		10000
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
27-51-06-082	LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM								
	PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-01	AFL		N:0			0		
27-51-06-082	LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM								
	PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-01	AFL		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-082	RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM PN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
27-51-06-082	RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM PN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
27-51-06-085	LEFT FLAP LEADING EDGE RIB PN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
27-51-06-085	RIGHT FLAP LEADING EDGE RIB PN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
270505	TRIM SWITCH PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 27-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271013	AILERON TRIM TAB ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271015	LEFT AILERON BALANCE TAB ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271016	RIGHT AILERON BALANCE TAB ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271019	AILERON TRIM ACTUATOR 2R6203B B0161 REF: AMM 27-10-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271025	PILOT CONTROL WHEEL 2415151-017 2742 REF: AMM 27-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271026	COPILOT CONTROL WHEEL 2415151-018 2751 REF: AMM 27-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271027	PILOT CONTROL COLUMN PN SN-UNKNOWN REF: AMM 27-30-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271028	COPILOT CONTROL COLUMN PN SN-UNKNOWN REF: AMM 27-30-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271031	AILERON TRIM TAB ACTUATOR POTENTIOMETER RV4SAYS102A NSN REF: AMM 27-10-12	MOS HRS/MSC AFL	O/C				23-FEB-2016 3839.9 1974		
271126	AILERON TRIM POSITION INDICATOR 720-319 349 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271131	LEFT AILERON POSITION SENSOR 501-1123-03 80201 REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271132	RIGHT AILERON POSITION SENSOR 501-1123-03 80207 REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
271701	* LEFT AILERON ASSEMBLY (AWL*) 2424000-313 W751 REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			11-MAR-2006 0 0	20000	
LIFE LIMIT									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271702	* RIGHT AILERON ASSEMBLY (AWL*) 2424000-314 W726	MOS HRS/MSC	20000	N:0 N:0			11-MAR-2006 0		20000
LIFE LIMIT	REF: AMM 27-10-02	AFL		N:0			0		
272001	* RUDDER ASSEMBLY (AWL*) 5433000-020 W525	MOS HRS/MSC	20000	N:0 N:0			11-MAR-2006 0		20000
LIFE LIMIT	REF: AMM 27-20-01	AFL		N:0			0		
272005	AFT RUDDER SECTOR PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-20-09	AFL		N:0			0		
272007	RUDDER TRIM TAB PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-20-02	AFL		N:0			0		
272013	RUDDER TRIM TAB ACTUATOR 2R6204B	MOS		N:0			11-MAR-2006		
	B0111	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-20-03	AFL		N:0			0		
272020	RUDDER TRIM TAB POTENTIOMETER P30LS0GJS102KAG22	MOS		N:20			13-APR-2017		
	NSN	HRS/MSC	O/C	N:0			3840.35		
	REF: AMM 27-20-04	AFL		N:0			1975		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272026	RUDDER TRIM INDICATOR 720-318 337 REF: AMM 27-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
272031	PILOT RUDDER PEDAL ACTUATOR EM423-4 786 REF: AMM 27-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
272032	COPILOT RUDDER PEDAL ACTUATOR EM423-4 772 REF: AMM 27-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273001	* LEFT ELEVATOR ASSEMBLY (AWL*) 2434000-177 W711 REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			11-MAR-2006 0 0	20000	
LIFE LIMIT									
273002	* RIGHT ELEVATOR ASSEMBLY (AWL*) 2434000-178 W735 REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			11-MAR-2006 0 0	20000	
LIFE LIMIT									
+ 2730036	ELEVATOR BELLCRANKS - PERFORM EDDY CURRENT INSPECTION REF: NDT 27-30-01	MOS HRS/MSC AFL	96 2400				03-DEC-2021 4833.3 2764	03-DEC-2029 7233.3	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273013	STALL WARNING COMPUTER 54301-3LMODA GST02821 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273017	PILOT STICK SHAKER 20-7 978A REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273018	COPILOT STICK SHAKER 20-7 975A REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273101	PILOT STALL WARNING TRANSDUCER 25147A-12 GST05516 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273102	COPILOT STALL WARNING TRANSDUCER 25147A-12 GST05561 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273105	PILOT ANGLE-OF-ATTACK (AOA) INDICATOR N617-9025 05105429 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273106	COPILOT ANGLE-OF-ATTACK (AOA) INDICATOR N617-9025 05105430 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273107	LEFT ANGLE OF ATTACK TRANSDUCER PN SN-UNKNOWN REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273108	RIGHT ANGLE OF ATTACK TRANSDUCER PN SN-UNKNOWN REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
273110	ANGLE-OF-ATTACK (AOA) VANE PN SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
274001	HORIZONTAL STABILIZER 2332000-60 W408 REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
274003	HORIZONTAL STABILIZER ACTUATOR CONTROLLER 660844-2 1306A REF: AMM 27-40-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-NOV-2018 4051.98 2131		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274010	TRIM-IN-MOTION DETECTOR 231-1-2 0041016 REF: AMM 27-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
274013	HORIZONTAL STABILIZER ACTUATOR 5435005-028 058 REF:	MOS HRS/MSC AFL	600	+25/-25 O:0 O:0 O:0		-3.8	05-SEP-2020 4468.9 2486	5065.1	5090.1
274013	HORIZONTAL STABILIZER ACTUATOR PN SN-UNKNOWN REF: AMM 27-40-02	MOS HRS/MSC AFL	-						
274062	PITCH TRIM INDICATOR N617-9024 321 REF: AMM 27-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
274070	STABILIZER POSITION SWITCH CS402-3 10623 REF: AMM 27-40-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
274072	STABILIZER POSITION SENSOR 501-1123-03 80205 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275001	* LEFT FLAP ASSEMBLY (AWL*) 6025010-035 W1516	MOS HRS/MSC		N:0 N:0			11-MAR-2006 0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0			0	10000	
275002	* RIGHT FLAP ASSEMBLY (AWL*) 6025010-036 W1505	MOS HRS/MSC		N:0 N:0			11-MAR-2006 0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0			0	10000	
275005	LEFT LOWER FLAP SECTOR BRACKET PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF:	AFL		N:0			0		
275005	LEFT UPPER FLAP SECTOR BRACKET PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF:	AFL		N:0			0		
275005	RIGHT LOWER FLAP SECTOR BRACKET PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF:	AFL		N:0			0		
275005	RIGHT UPPER FLAP SECTOR BRACKET PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF:	AFL		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2750058	* LEFT FLAP LEADING EDGE RIB - REPLACE (AWL*)								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
NOT APPLICABLE	REF: AMM 27-50-01	AFL					0		
<hr/>									
+ 2750058	* LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 27-50-01	AFL					0		
<hr/>									
+ 2750058	* LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 27-50-01	AFL					0		
<hr/>									
2750058	* RIGHT FLAP LEADING EDGE RIB - REPLACE (AWL*)								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
NOT APPLICABLE	REF: AMM 27-50-01	AFL					0		
<hr/>									
+ 2750058	* RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 27-50-01	AFL					0		
<hr/>									
+ 2750058	* RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*)								
	PN	MOS					11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 27-50-01	AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275010	FLAP & ENGINE SYNCHRONIZER RELAY BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275012	FLAP POSITION POTENTIOMETER PN SN-UNKNOWN REF: AMM 27-50-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-FEB-2016 3839.9 1974		
275019	LEFT LIMIT, INBOARD FLAP/STABILIZER SWITCH CS402-3 10582 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275020	RIGHT LIMIT, INBOARD FLAP/STABILIZER SWITCH CS402-3 10526 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275021	LEFT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 10533 REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275022	RIGHT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 10048 REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275031	FLAP CONTROL (FLAP/SPOILER) VALVE 6600362-1 1125A REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275036	FLAP RESTRICTOR VALVE 2R1047-0312 2244 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275037	LEFT FLAP ACTUATOR 6600493-2 0511 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275038	RIGHT FLAP ACTUATOR 6600493-2 0513 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275200	FLAP POSITION INDICATOR 820-712 0760A REF: AMM 27-50-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275213	FLAP PRESSURE RELIEF VALVE AN6245A4 19041 REF: AMM 27-50-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275217	FLAP ACTUATION CHECK VALVE PN SN-UNKNOWN REF: AMM 27-50-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
275407	FLAP SELECT SWITCH PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
276001	* LEFT SPOILER ASSEMBLY (AWL*) 2422510-137 352 REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	N:0 N:0 N:0			05-SEP-2020 4468.9 2486	8968.9	
LIFE LIMIT									
276002	* RIGHT SPOILER ASSEMBLY (AWL*) 2422510-136 348 REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	N:0 N:0 N:0			05-SEP-2020 4468.9 2486	8968.9	
LIFE LIMIT									
276005	LEFT SPOILER FLOW CONTROL SERVO VALVE PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
276006	RIGHT SPOILER FLOW CONTROL SERVO VALVE PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276010	SPOILER COMPUTER 6018300V3-002 80021 REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
276013	* LEFT SPOILER ACTUATOR ASSEMBLY (AWL*) 2417015-5 2357 REF: AMM 27-60-04	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			11-MAR-2006 0 0	10000	
276014	* RIGHT SPOILER ACTUATOR ASSEMBLY (AWL*) 2417015-5 2358 REF: AMM 27-60-04	MOS HRS/MSC AFL	10000	N:119 N:3839.9 N:1974			23-FEB-2016 3839.9 1974	10000	
276037	LEFT SPOILER POSITION SENSOR 501-1123-03 80183 REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
276038	RIGHT SPOILER POSITION SENSOR 501-1123-03 80197 REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
276043	SPOILER POTENTIOMETER P30LS0GJS102KAG222 NSN REF: AMM 27-60-09	MOS HRS/MSC AFL	O/C	N:6 N:0 N:0			23-FEB-2016 3839.9 1974		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276049	SPOILER POSITION INDICATOR								
	820-711	MOS		N:0			11-MAR-2006		
	326	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-60-10	AFL		N:0			0		
276128	SPOILER MANIFOLD VALVE								
	2627023-1	MOS		N:0			11-MAR-2006		
	1130	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-60-03	AFL		N:0			0		
276265	WHEEL SPEED DETECTION BOX								
	PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-60-12	AFL		N:0			0		
AB2700049 (s)	REMOVE ALL PANELS REQUIRED TO GAIN ACCESS TO CABLES, PULLEYS, SECTORS, AND ASSOCIATED EQUIPMENT. VISUALLY INSPECT ACCESSIBLE PORTIONS OF FLIGHT CONTROLS FOR PROPER CONDITION, CABLE CLEARANCE, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO FLIGHT CONTROL CABLE CLEARANCES AT FUEL CROSSOVER TUBES.						PKG		
	PKG 11	MOS	24	+14d/-14d			31-MAR-2022		
		HRS/MSC	600	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
B2760050 (s)	PERFORM FUNCTIONAL TEST OF SPOILER (UP LIMIT) SWITCH. (REFER TO 27-60-05.)						PKG		
	PKG 28	MOS					11-MAR-2006		
		HRS/MSC	12000	+25/-25			0		
	REF: AMM 27-60-05	AFL					0		
C2700011 (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						PKG		
	PKG 27	MOS	144	+14d/-14d			07-FEB-2018		
		HRS/MSC					3852.6		
	REF: GENERIC NO REF	AFL	6000	+25/-25			1982		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C2700013 (s)	WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (FLAPS, AILERONS, AND SPOILERS), INSPECT ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
C2700019 (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
C2700020 (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
C2700022 (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
C2700023 (s)	WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (RUDDER AND ELEVATORS), INSPECT ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERF						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
E2700031 (s)	CHECK ELEVATOR AND RUDDER CONTROL CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEY, PULLEY BRACKETS, AND GUARDS FOR SECURITY AND GENERAL CONDITION.						PKG		
	PKG 9	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E2700032 (s)	INSPECT CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION. PKG 8	MOS	24	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			4901.4 2815		
E2710005 (s)	HOLD CONTROL WHEEL INA FIXED POSITION AND APPLY UP AND DOWN LOADS ON THE AILERON TRAILING EDGE. OBSERVE AILERON DRIVE ASSEMBLY AREA FOR WEAR IN SHAFT KEYWAYS, FAILURE OF BEARINGS, AND AILERON YOKE SLIPPAGE. PKG 16	MOS	48	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			4901.4 2815		
E2730025 (s)	INSPECT CONTROL COLUMNS (INCLUDING CONTROL WHEELS AND BOOTS) FOR CONDITION, PROPER OPERATION, AND CLEARANCES. PKG 1	MOS	12	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			4901.4 2815		
F2740020 (s)	REMOVE STABILIZER ACTUATOR. INSPECT UPPER AND LOWER ATTACHMENT STRUCTURE FOR FATIGUE CRACKS, DISTORTION, WEAR, CORROSION, AND GENERAL SECURITY. PKG 27	MOS	144	+14d/-14d			07-FEB-2018		
	REF: AMM 27-40-02	HRS/MSC AFL	6000	+25/-25			3852.6 1982		
H2700018 (s)	VISUALLY INSPECT SPOILER, FLAP, AILERON, AND AILERON TRIM TAB ELECTRICAL BONDING JMPERS FRO SECURITY AND GENERAL CONDITION. PKG 10	MOS	24	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			4901.4 2815		
H2700021 (s)	INSPECT THE RUDDER AND ELEVATOR BALANCE WEIGHT INSTALLATIONS AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUC PKG 18	MOS	48	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H2700024 (s)	INSPECT THE AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUCTURE. PKG 16 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
H2710032 (s)	CHECK AILERON, RUDDER, AND ELEVATOR CONTROL SYSTEM CABLE TENSIONS. (REFER TO 27-10-00, 27-20-00 AND 27-30-00.) PKG 14 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
H2731000 (s)	PERFORM STALL WARNING SYSTEM FUNCTIONAL TEST. (REFER TO 27-31-00) PKG 7 REF: AMM 27-31-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
P2700050 (s)	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS. PKG 1 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
P2700055 (s)	VISUALLY INSPECT ELEVATOR, RUDDER, AND RUDDER TRIM TAB ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. PKG 12 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
P2700057 (s)	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS. PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P2710044 (s)	CHECK AILERON AND FLAP SYSTEM CONTROL CABLE TENSIONS. (REFER TO 27-10-00 AND 27-50-00.) PKG 16 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
P2710045 (s)	REMOVE CONTROL WHEEL SECTOR AND TURNBUCKLE COVERPLATE FROM CONTROL COLUMN. MOVE CONTROL WHEEL TO BOTH EXTREME RIGHT AND LEFT WHILE INSPECTING FOR FRAYED OR DAMAGED CABLES. PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
P2710046 (s)	DISASSEMBLE CONTROL COLUMN AS REQUIRED TO INSPECT PULLEYS, BEARINGS, ELECTRICAL WIRING FOR PROPER ROUTING AND CHAFING, AND CONTROL COLUMNS FOR GENERAL CONDITION. PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-FEB-2018 3852.6 1982		
P2760003 (s)	INSPECT SPOILER ACTUATOR INSTALLATION FOR SECURITY, SUPPORT STRUCTURE CRACKS, AND GENERAL CONDITION. PKG 10 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
Q2700051 (s)	INSPECT RUDDER AND ELEVATOR CONTROLS (INCLUDING DOWNSPRING INSTALLATION WHEN INSTALLED AND PUSH-PULL TUBES) FOR PROPER OPERATION, GENERAL CONDITION AND SECURITY. PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
T2700017 (s)	INSPECT STRUCTURE, PULLEY BRACKETS, AND CONTROLS UNDER FLOORBOARDS FROM PEDESTAL AND CONTROL COLUMN AFT TO FRAME 24 FOR OPERATION, CLEARANCES, CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO THE ELEVATOR PULLEY BRACKET CUTOUT AREA RADIUS FOR CRACKS. (S PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2700052 (s)	USING THE PROPER COCKPIT CONTROLS, CHECK FLAPS, SPOILERS, HORIZONTAL STABILIZER, AND TRIM TABS FOR PROPER OPERATION AND ACCURATE INDICATION. PKG 13 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T2700056 (s)	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS. PKG 12 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T2700058 (s)	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS. PKG 20 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
T2700059 (s)	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS. PKG 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
T2700060 (s)	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS. PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
T2710042 (s)	INSPECT AILERON AND AILERON TABS AND DRIVE MECHANISM FOR SECURITY, OPERATION, AND GENERAL CONDITION. PKG 16 REF: AMM 27-10-04	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2720027 (s)	INSPECT RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS FOR SECURITY, PROPER OPERATION, AND CLEARANCES.						PKG		
	PKG 20	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: GENERIC NO REF	AFL						1982	
T2730029 (s)	CHECK CONTROL COLUMN ASSEMBLY FREE PLAY. (REFER TO 27-30-06.)						PKG		
	PKG 20	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: AMM 27-30-06	AFL						1982	
T2731075 (s)	FUNCTIONAL TEST OF STALL WARNING ALTITUDE SWITCHES. (REFER TO 27-31-00.)						PKG		
	PKG 19	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: AMM 27-31-00	AFL						1982	
T2760030 (s)	INSPECT SPOILER AND HINGE INSTALLATION FOR SECURITY, CRACKS, AND GENERAL CONDITION.						PKG		
	PKG 16	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T2760031 (s)	INSPECT SPOILER CENTER ANGLE BRACKET RIVETS, LOWER SKIN CENTER RIB AND SUBSPAR RIVETS FOR EVIDENCE OF WORKING. WITH SPOILERS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO SPOILER TRAILING EDGE. CHECK MOTION AT CENTER HINGE. INSPECT SPOILER ACTUATOR MECHANISM AND						PKG		
	PKG 16	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T2760040 (s)	FUNCTIONAL TEST OF SPOILER RESTRICTOR BYPASS VALVE COMPUTER CIRCUITRY AND WIRING. (REFER TO 27-60-03.)						PKG		
	PKG 16	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: AMM 27-60-03	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2760084 (s)	VISUAL INSPECTION SPOILER CENTER ANGLE BRACKET RIVETS AND UPPER AND LOWER SKIN CENTER RIB AREA. (REFER TO 5-10-00.)						PKG		
	PKG 4	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
U2700033 (s)	INSPECT ALL CABLES, PULLEYS, SECTORS, AND PULLEY GUARD FOR PROPER OPERATION AND GENERAL CONDITION. PARTICULAR ATTENTION SHOULD BE GIVEN TO THOSE AREAS OF CABLES THAT PASS OVER PULLEYS, SECTORS, OR THROUGH FAIRLEADS.						PKG		
	PKG 10	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
U2710006 (s)	RUDDER TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK. (REFER TO 27-20-02.)						PKG		
	PKG 18	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: AMM 27-20-02	AFL						2815	
U2710033 (s)	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK.						PKG		
	PKG 16	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: AMM 27-10-04	AFL						2815	
U2710034 (s)	GENERAL VISUAL INSPECTION AILERON TRIM TAB INSTALLATION. (REFER TO 5-10-00.)						PKG		
	PKG 4	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
U2710035 (s)	GENERAL VISUAL INSPECTION RUDDER TRIM TAB INSTALLATION. (REFER TO 5-10-00)						PKG		
	PKG 6	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U2731050 (s)	VISUAL INSPECTION ANGLE-OF-ATTACK VANES. (REFER TO 5-10-00) PKG 2	MOS	12	+14d/-14d			PKG 31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			4901.4 2815		
W2700062 (s)	CHECK CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION. (REFER TO 5-10-00.) PKG 8	MOS	24	+14d/-14d			PKG 31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			4901.4 2815		
CHAPTER 28 FUEL									
05-10-29-L2812002L	INSPECT LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602	MOS	24	+14d/-14d			08-JUL-2021 4712.9	08-JUL-2023	22-JUL-2023
	REF: GENERIC NO REF	HRS/MSC AFL					2660		
05-10-29-L2812002R	INSPECT RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602	MOS	24	+14d/-14d			08-JUL-2021 4712.9	08-JUL-2023	22-JUL-2023
	REF: GENERIC NO REF	HRS/MSC AFL					2660		
05-10-29-L2812010L	INSPECT LEFT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA	MOS	24	+14d/-14d			08-JUL-2021 4712.9	08-JUL-2023	22-JUL-2023
	REF: GENERIC NO REF	HRS/MSC AFL					2660		
05-10-29-L2812010R	INSPECT RIGHT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA	MOS	24	+14d/-14d			08-JUL-2021 4712.9	08-JUL-2023	22-JUL-2023
	REF: GENERIC NO REF	HRS/MSC AFL					2660		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-29-L2812020L	INSPECT LEFT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION	MOS	24	+14d/-14d			08-JUL-2021 4712.9 2660	08-JUL-2023	22-JUL-2023
	REF: GENERIC NO REF	HRS/MSC AFL							
05-10-29-L2812020R	INSPECT RIGHT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION	MOS	24	+14d/-14d			08-JUL-2021 4712.9 2660	08-JUL-2023	22-JUL-2023
	REF: GENERIC NO REF	HRS/MSC AFL							
05-10-29-T2820012	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS	MOS					14-JUN-2006 49 44		
	REF: AMM 28-20-04	HRS/MSC AFL	-						
05-11-00-G2820003	REPLACE ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AIRCRAFT (PRESSURE)	MOS					11-MAR-2006 0 0		
TEFLON	REF: AMM 28-00-00	HRS/MSC AFL	O/C						
280002	FUEL CONTROL SWITCH PANEL ASEMBLY	MOS					11-MAR-2006 0 0		
	PN	HRS/MSC	O/C	N:0					
	SN-UNKNOWN	AFL		N:0					
	REF: AMM 28-00-02			N:0					
280003	LEFT WING DEFUEL VALVE	MOS					11-MAR-2006 0 0		
	6600145-3	HRS/MSC	O/C	N:0					
	3916	AFL		N:0					
	REF: AMM 28-00-03			N:0					

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280004	RIGHT WING DEFUEL VALVE 6600145-3 3976 REF: AMM 28-00-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281007	LEFT CHECK, CROSSFLOW VALVE 7600004-1 05-061416 REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281008	RIGHT CHECK, CROSSFLOW VALVE 7600004-1 05-061413 REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281201	AFT FUSELAGE FUEL CELL 6600501-003 101746 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281202	FORWARD FUSELAGE FUEL CELL 6600500-005 91596 REF: AMM 28-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281283	FUSELAGE DRAIN VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281301	LEFT WING FUEL VENT FLOAT VALVE 6600346-2 4175 REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281302	RIGHT WING FUEL VENT FLOAT VALVE 6600346-2 4187 REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281303	FUSELAGE FUEL VENT FLOAT VALVE 6600346-2 4157 REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281307	LEFT FUEL CELL PRESSURE RELIEF VALVE PN SN-UNKNOWN REF: AMM 28-13-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281308	RIGHT FUEL CELL PRESSURE RELIEF VALVE PN SN-UNKNOWN REF: AMM 28-13-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281309	FUSELAGE FLAME ARRESTOR 9909018-101 473 REF: AMM 28-13-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281401	LEFT FUSELAGE CELL TRANSFER PUMP 601600V7-001 C4051 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281402	RIGHT FUSELAGE CELL TRANSFER PUMP 601600V7-001 C3765 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281403	LEFT INBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281404	RIGHT INBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281405	LEFT CENTER WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281406	RIGHT CENTER WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281407	LEFT OUTBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281408	RIGHT OUTBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281409	LEFT SCAVENGE PUMP 2380060-042 C4061 REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281410	RIGHT SCAVENGE PUMP 2380060-042/6026003V1-002 C4065 REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281411	LEFT FUEL TRANSFER VALVE 6600355-005 05-0727194 REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281412	RIGHT FUEL TRANSFER VALVE 6600355-005 05-0727191 REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281413	CROSSFLOW VALVE PN SN-UNKNOWN REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281414	FUSELAGE HIGH-LEVEL FLOAT SWITCH L14F-94 300 REF: AMM 28-14-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281415	LEFT FUEL TRANSFER PRESSURE INDICATING SWITCH 7600002-3 1285 REF: AMM 28-14-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281416	RIGHT FUEL TRANSFER PRESSURE INDICATING SWITCH 7600002-3 1283 REF: AMM 28-14-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281417	LEFT WING HIGH-LEVEL FLOAT SWITCH L15H-8 12284 REF: AMM 28-14-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281418	RIGHT WING HIGH-LEVEL FLOAT SWITCH L15H-59 754 REF: AMM 28-14-08	MOS HRS/MSC AFL	O/C	N:12 N:0 N:0			06-JUN-2014 3337.13 1768		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281419	LEFT WING LOW-LEVEL FLOAT SWITCH TRACKED ITEM L15H-8 12289 REF: AMM 28-14-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
281420	RIGHT WING LOW-LEVEL FLOAT SWITCH TRACKED ITEM L15H-59 969 REF: AMM 28-14-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-JUL-2011 2321.3 1248		
281421	FUEL FILL AND TRANSFER BOX PN SN-UNKNOWN REF: AMM 28-14-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282001	LEFT INBOARD JET PUMP PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282002	RIGHT INBOARD JET PUMP PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
+ 2820021	WHEEL WELL AND KEEL BEAM AREA - PERFORM DETAILED VISUAL INSPECTION OF FUEL TUBE FERRULE ENDS (UNDERNEATH COUPLING ASSEMBLIES) BETWEEN FS 346 AND FS 421 (FRAMES 24 AND 31) FOR EVIDENCE OF FATIGUE CRACKS, CORROSION OR OTHER DEGRADATION REF: AMM 28-20-00	MOS HRS/MSC AFL	36	+14d/-14d			(EBT)	18-OCT-2024	01-NOV-2024

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282003	LEFT STANDBY PUMP 2380060-049 C4045 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282004	RIGHT STANDBY PUMP 2380060-049 C4063 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282005	LEFT FUEL FILTER ASSEMBLY 6600488-4 1890 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282006	RIGHT FUEL FILTER ASSEMBLY 6600488-4 1887 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282007	LEFT ENGINE FUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282008	RIGHT ENGINE FUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282009	LEFT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE 30B2062 C37569 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282010	RIGHT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE EM91-41 70926117 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	R:15 R:0 R:0			08-APR-2014 3235.87 1731		
282011	LEFT ENGINE RELIEF VALVE 7600005-1 10615195 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282012	RIGHT ENGINE RELIEF VALVE 7600005-1 10615171 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282013	FUEL CONTROL RELAY PANEL PN SN-UNKNOWN REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282015	LEFT WING PILOT VALVE 2780610-102 2178 REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282016	RIGHT WING PILOT VALVE 2780610-102 2175 REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282017	LEFT WING REFUELING SHUTOFF VALVE 2780614-102 1411 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282018	RIGHT WING REFUELING SHUTOFF VALVE 2780614-102 1408 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282019	FUSELAGE PILOT VALVE 2780610-102 2177 REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282020	FUSELAGE VENT VALVE PN SN-UNKNOWN REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282021	REFUELING CHECK VALVE 2780623-101 711 REF: AMM 28-20-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282022	FUSELAGE REFUELING SHUTOFF VALVE 2780624-102 835 REF: AMM 28-20-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282023	FUEL SOLENOID VALVE 2780613-101 0773 REF: AMM 28-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282024	PRESSURE REFUELING ADAPTER 2780609-101 833 REF: AMM 28-20-16	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282025	LEFT PRECHECK VALVE 2780615-102 1557 REF: AMM 28-20-17	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
282026	RIGHT PRECHECK VALVE 2780615-102 1551 REF: AMM 28-20-17	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284001	LEFT INBOARD WING (MT5) FUEL PROBE 2326014-016 07061243A REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C				17-OCT-2014 3622.55 1881		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284002	RIGHT INBOARD WING (MT6) FUEL PROBE 2326014-12 04090678 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284003	LEFT OUTBOARD WING (MT7) FUEL PROBE 2326014-9 05062143 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284004	RIGHT OUTBOARD WING (MT8) FUEL PROBE 2326014-9 05062139 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284005	LEFT INBOARD WING EXTENSION STA 189 (MT9) FUEL PROBE 2826003-6 05101431 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284006	RIGHT INBOARD WING EXTENSION STA 189 (MT10) FUEL PROBE 2826003-3 05101428 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284007	LEFT OUTBOARD WING EXTENSION STA 244 (MT11) FUEL PROBE 2826003-3 01051299 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284008	RIGHT OUTBOARD WING EXTENSION STA 244 (MT12) FUEL PROBE 2826003-3 01041290 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284009	FUSELAGE (MT18) FUEL PROBE 0118KTU01 FP027486 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284011	LEFT ENGINE LOW FUEL PRESSURE SWITCH 7600002-2 4265 REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284012	RIGHT ENGINE LOW FUEL PRESSURE SWITCH 7600002-2 4360 REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
284013	FUEL QUANTITY INDICATOR 2323-01-1 029 REF: AMM 28-40-03	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			19-JUL-2010 1777.65 967		
B2813011 (s)	DEFUEL FUSELAGE FUEL CELL AND PERFORM FUEL CELL STATIC ELECTRICAL BONDING RESISTANCE CHECK. CHECK FUSELAGE FUEL CELL FOR CLEANLINESS. (REFER TO 28-12-00.) PKG 25 REF: AMM 28-12-00	MOS HRS/MSC AFL					11-MAR-2006 0 0		
			3000	+25/-25					

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C2820030 (s)	INSPECT FUEL SUPPLY LINE CHECK VALVE ORIFICES FOR CONDITION AND CLEANLINESS. (REFER TO 28-20-03.) PKG 27 REF: AMM 28-20-03	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
D2812030 (s)	WITH LOWER SURFACE ACCESS PLATES REMOVED, INSPECT INTERIOR AND EXTERIOR WING STRUCTURE FOR EVIDENCE OF FUEL LEAKAGE, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, BACTERIAL GROWTH, FILIFORM CORROSION, AND GENERAL CONDITION. INSPECT WING FLAPPER VALVES FOR F PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
E2820010 (s)	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS. ON AIRCRAFT EQUIPPED WITH PAPER FILTERS, REMOVE AND REPLACE FILTERS. (REFER TO 28-20-04) PKG 3 REF: AMM 28-20-04	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H2812060 (s)	OPERATIONAL CHECK OF WING LOW FUEL WARNING SYSTEM. (REFER TO 28-14-00.) PKG 16 REF: AMM 28-14-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H2820020 (s)	PERFORM OPERATIONAL CHECK OF FUEL SUPPLY SHUTOFF VALVE AND HYDRAULIC SUPPLY SHUTOFF VALVES. (REFER TO 28-20-05 AND 29-10-01) PKG 7 REF: See Workcard	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T2812070 (s)	OPERATIONAL CHECK OF FUEL CROSSFLOW VALVE AND MOTIVE FLOW CONTROL VALVES. (REFER TO 28-14-00 AND 28-20-00.) PKG 22 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2814021 (s)	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES. (REFER TO 28-13-07.)						PKG		
	PKG 14	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: AMM 28-13-07	AFL					2815		
T2814039 (s)	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK VACUUM RELIEF VALVES. (REFER TO 28-13-06.)						PKG		
	PKG 14	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: AMM 28-13-06	AFL					2815		
T2820001 (s)	VISUALLY INSPECT FUEL PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.) CHECK FUEL DRAINS FOR OPERATION.						PKG		
	PKG 15	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
T2820004 (s)	INSPECT LOWER INBOARD GEAR DOORS AND CHECK ENTIRE KEELBEAM AND WHEEL WELL AREA FOR FUEL OR HYDRAULIC LEAKS, PLUMBING FOR ROUTING, CLEARANCES, SECURITY OF CLAMPS, AND GENERAL CONDITION.						PKG		
	PKG 17	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
+ Y2814041 (s)	PERFORM BENCH CHECK OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES.						PKG		
	PKG 27	MOS	144	+14d/-14d			07-FEB-2018		
		HRS/MSC					3852.6		
	REF: AMM 28-13-07	AFL	6000	+25/-25			1982		
CHAPTER 29	HYDRAULIC POWER								
05-11-00-G2900001	REPLACE HYDRAULIC HOSE ASSEMBLIES(EXCLUDING HOSES FOR THE LANDING GEAR AND THE HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA)								
		MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
TEFLON	REF: GENERIC NO REF	AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-L2910020	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS	MOS						14-JUN-2006	
	REF: AMM 29-10-03	HRS/MSC AFL	O/C					49 44	
290002	HYDRAULIC PRESSURE REGULATOR	MOS						11-MAR-2006	
	2702-13	HRS/MSC	O/C	N:0				0	
	0825	AFL		N:0				0	
	REF: AMM 29-00-02			N:0				0	
290003	HYDRAULIC RESERVOIR	MOS						11-MAR-2006	
	PN	HRS/MSC	O/C	N:0				0	
	SN-UNKNOWN	AFL		N:0				0	
	REF: AMM 29-00-03			N:0				0	
290005	PRESSURE REGULATOR CHECK VALVE	MOS						11-MAR-2006	
	PN	HRS/MSC	O/C	N:0				0	
	SN-UNKNOWN	AFL		N:0				0	
	REF: AMM 29-00-05			N:0				0	
291001	LEFT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE	MOS						11-MAR-2006	
	6600355-2	HRS/MSC	O/C	N:0				0	
	05-092332	AFL		N:0				0	
	REF: AMM 29-10-01			N:0				0	
291002	RIGHT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE	MOS						11-MAR-2006	
	6600355-2	HRS/MSC	O/C	N:0				0	
	05-092331	AFL		N:0				0	
	REF: AMM 29-10-01			N:0				0	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291003	LEFT ENGINE DRIVEN HYDRAULIC PUMP 6607066-1 K0630AB REF: AMM 29-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
291004	RIGHT ENGINE DRIVEN HYDRAULIC PUMP 6607066-1 KA0641AB REF: AMM 29-10-02	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			13-OCT-2010 1954.32 1064		
291005	HYDRAULIC PRESSURE FILTER ASSEMBLY M8815/1A-10 0337 REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
291006	HYDRAULIC RETURN FILTER ASSEMBLY M8815/2A-10 0290 REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
291007	HYDRAULIC SYSTEM ACCUMULATOR MS28700-4 8424-13041 REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			14-JUN-2007 541.67 336		
291008	HYDRAULIC THRUST REVERSER ACCUMULATOR MS28700-3 8423-12002 REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291010	HYDRAULIC GROUND SERVICE PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
291015	HYDRAULIC RELIEF VENT VALVE 2380103-1 05-0718103 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
291020	HYDRAULIC RESERVOIR RELIEF VALVE 5120T-8TT-20 05-082434 REF: AMM 29-00-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
291220	THRUST REVERSER ISOLATION VALVE 6607070-1 311 REF: AMM 78-30-27	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
291225	HYDRAULIC PRESSURE RELIEF VALVE 5120T8TT20 SN-UNKNOWN REF: AMM 29-00-08	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.6 1982		
292001	AUXILIARY HYDRAULIC PUMP 6600248-1 SN01891 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293001	HYDRAULIC PRESSURE MT15 TRANSDUCER 124058-3000 55559-12 REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
293002	AUXILIARY HYDRAULIC PUMP PRESSURE SWITCH 730626 F1420 REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
293003	HYDRAULIC PRESSURE INDICATOR S218-2 1424 REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C				25-APR-2016 3839.9 1974		
293005	LEFT HYDRAULIC PUMP PRESSURE SWITCH 730635 B701 REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
293006	RIGHT HYDRAULIC PUMP PRESSURE SWITCH 730635 A685 REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
293010	HYDRAULIC SYSTEM PRESSURE GAUGE S-218-2 1424 REF: AMM 29-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293015	THRUST REVERSER HYDRAULIC PRESSURE GAUGE S-218-2 1423 REF: AMM 29-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
H2910009 (s)	REMOVE AND CLEAN OR REPLACE AUXILIARY HYDRAULIC PUMP FILTER. (REFER TO 29-20-02.) PKG 15 REF: AMM 29-20-02	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
N2920000 (s)	FUNCTIONAL TEST THRUST REVERSER HYDRAULIC RETURN LINE CHECK VALVE. (REFER TO 78-30-03.) PKG 27 REF: AMM 29-10-05	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
P2910023 (s)	INSPECT HYDRAULIC RESERVOIR FILLER FILTER ELEMENT AND REPLACE IF REQUIRED. (REFER TO 29-00-04.) PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
Q2910019 (s)	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS. (REFER TO 29-10-03.) PKG 9 REF: AMM 29-10-03	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
S2900004 (s)	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR PRESSURE RELIEF VALVE. (REFER TO 29-00-08.) PKG 15 REF: AMM 29-00-08	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
S2900005 (s)	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR VACUUM RELIEF VALVE. (REFER TO 29-00-08.)						PKG		
	PKG 15	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: AMM 29-00-08	AFL						2815	
S2910008 (s)	REMOVE HYDRAULIC RESERVOIR REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02.)						PKG		
	PKG 15	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: AMM 29-00-01	AFL						2815	
S2910025 (s)	REMOVE HYDRAULIC RESERVOIR PRESSURE REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02)						PKG		
	PKG 9	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: See Workcard	AFL						2815	
T2900000 (s)	VISUALLY INSPECT HYDRAULIC PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 15	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
W2910024 (s)	INSPECT HYDRAULIC FILTERS (PRESSURE AND RETURN) DIFFERENTIAL PRESSURE INDICATORS FOR BYPASS INDICATION.						PKG		
	PKG 3	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: AMM 29-10-03	AFL						2815	

CHAPTER 30	ICE AND RAIN PROTECTION
-------------------	--------------------------------

300001	COPILOT ELECTRICAL EQUIPMENT BOX								
	PN	MOS			N:0			11-MAR-2006	
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0	
	REF: AMM 30-00-01	AFL			N:0			0	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301001	WING ANTI-ICE SHUTOFF AND PRESSURE REGULATING VALVE 6600259-3 265 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301002	WING RT10 ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301003	WING (SPARE 2RT10) ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301004	WING (SPARE 3RT10) ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301005	WING OVERHEAT WARNING THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301006	WING TEMPERATURE INDICATOR 820-685 622 REF: AMM 30-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301007	LEFT WING ANTI-ICE BYPASS VALVE 27441482-13 11BA19 REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301008	RIGHT WING ANTI-ICE BYPASS VALVE 27441482-13 11BA18 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301014	WING ANTI-ICE VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301015	LEFT WING ANTI-ICE CHECK VALVE 1H95-8 8BG24 REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-SEP-2012 2852.1 1527		
301016	RIGHT WING ANTI-ICE CHECK VALVE 1H95-8 7BE21 REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-JUN-2010 1691.87 920		
301101	HORIZONTAL STABILIZER ANTI-ICE CONTROLLER 807-1-3 205420080 REF: AMM 30-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301103	LEFT HORIZONTAL STABILIZER HEAT BLANKET (BOOT) 4065-3481 05-30147 REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301104	RIGHT HORIZONTAL STABILIZER HEAT BLANKET (BOOT) 4065-3481 05-30146 REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301109	CBR9 REMOTE CIRCUIT BREAKER SM600BA40A1 94283 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301110	CBR10 REMOTE CIRCUIT BREAKER SM600BA40A1 94289 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
301111	CBR11 REMOTE CIRCUIT BREAKER SM600BA40A1 94281 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
302101	LEFT NACELLE ANTI-ICE SHUTOFF VALVE 27441482-09 11BA21 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302102	RIGHT NACELLE ANTI-ICE SHUTOFF VALVE 27441482-09 11BA19 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
302103	LEFT NACELLE ANTI-ICE PRESSURE SWITCH 7600020-1 4203 REF: AMM 30-21-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-APR-2008 855.52 488		
302104	RIGHT NACELLE ANTI-ICE PRESSURE SWITCH 7600020-1 12423TW REF: AMM 30-21-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
303001	LEFT PITOT HEAT MONITOR- 76248-2 3593 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
303002	RIGHT PITOT HEAT MONITOR- 76248-2 3597 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
303003	STANDBY PITOT HEAT MONITOR- 76248-2 3600 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304001	WINDSHIELD ANTI-ICE SHUTOFF VALVE 55510 2827 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304002	WINDSHIELD ANTI-ICE MODULATING VALVE PN SN-UNKNOWN REF: AMM 30-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304003	WINDSHIELD ANTI-ICE RAM AIR MODULATING VALVE 27441500 11BA12 REF: AMM 30-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304004	WINDSHIELD ANTI-ICE HEAT EXCHANGER 5F295-001 1105 REF: AMM 30-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304005	WINDSHIELD ANTI-ICE TEMPERATURE SENSOR 27431501-09 5BA8 REF: AMM 30-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304007	LEFT WINDSHIELD ANTI-ICE LOW-LIMIT (S83) THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304008	RIGHT WINDSHIELD ANTI-ICE LOW-LIMIT (S82) THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304009	LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304010	RIGHT WINDSHIELD ANTI-ICE HIGH-LIMIT (S84) THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304101	ALCOHOL SUPPLY TANK ASSEMBLY PN SN-UNKNOWN REF: AMM 30-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304102	ALCOHOL ANTI-ICE FLOAT SWITCH L14F74 1237 REF: AMM 30-41-02	MOS HRS/MSC AFL	O/C				08-JUL-2021 4712.9 2660		
304104	ALCOHOL PRESSURE RELIEF VALVE 4P152-4 1511 REF: AMM 30-41-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304105	ANTI-ICE THREE-WAY SHUTOFF VALVE 56360-1 1749 REF: AMM 30-41-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304106	ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE 56410 1708A REF: AMM 30-41-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
304203	WINDSHIELD DEFOG RELAY BOX PN SN-UNKNOWN REF: AMM 30-42-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
308001	LEFT ICE DETECT LAMP 0871HJ1 0100 REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C				04-FEB-2010 1542.9 841		
308002	RIGHT ICE DETECT LAMP PN SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
G3010001 (s)	OPERATIONAL CHECK WING ANTI-ICE CHECK VALVE. (REFER TO 30-10-08). PKG 9 REF: AMM 30-10-08	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3020002 (s)	REMOVE INLET COWL ACCESS PANEL. VISUALLY INSPECT ANTI-ICE PLUMBING CONNECTOR FOR CONDITION, SECURITY, AND EVIDENCE OF LEAKAGE. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			31-MAR-2022		
		HRS/MSC	600	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
H3020003 (s)	REMOVE UPPER ENGINE ACCESS COWL AND PERFORM A VISUAL INSPECTION OF NACELLE ANTI-ICE PLUMBING AND ALOCHOL PRESSURE LINE. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			31-MAR-2022		
		HRS/MSC	600	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
T3040004 (s)	INSPECT WINDSHIELD DEFOG DUCTS AND EXTERNAL OUTLETS FOR SECURITY, CONTOUR, AND INTEGRITY OF SEALANT TO WINDSHIELD. CHECK THAT THE EXTERNAL ANTI-ICE NOZZLES ARE CLEAR OF OBSTRUCTIONS.						PKG		
	PKG 14	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
T3040008 (s)	FUNCTIONAL TEST OF WINDSHIELD ANTI-ICE SYSTEM TIMER CIRCUIT. (REFER TO 30-40-00.)						PKG		
	PKG 19	MOS	96	+14d/-14d			07-FEB-2018		
		HRS/MSC	2400	+25/-25			3852.6		
	REF: AMM 30-40-00	AFL					1982		
T3050003 (s)	OPERATIONAL CHECK OF ALCOHOL ANTI-ICE SYSTEM. (REFER TO 30-41-00.)						PKG		
	PKG 14	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: AMM 30-41-00	AFL					2815		
T3050009 (s)	CLEAN ALCOHOL ANTI-ICE FILTER ELEMENT. REPLACE FILTER ELEMENT IF MADE OF PAPER. (REFER TO 30-41-03.)						PKG		
	PKG 14	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: AMM 30-41-03	AFL					2815		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U3020001A (s)	INSPECT NO. 1 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 29 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				17-MAR-2015 3839.9 1974		
U3020001B (s)	INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				17-MAR-2015 3839.9 1974		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
311006	TEST SWITCH PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 31-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
312001	PILOT CREW CLOCK 6420093-1 K17-10228 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.6 1982		
312002	COPILOT CREW CLOCK 6420093-1 K17-10233 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.6 1982		
312011	REPLACE PILOT DIGITAL CLOCK BATTERY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	24	N:0 N:0 N:0			17-MAR-2022 4901.4 2815	17-MAR-2024	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
312012	REPLACE COPILOT DIGITAL CLOCK BATTERY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	24	N:0 N:0 N:0			17-MAR-2022 4901.4 2815	17-MAR-2024	
313001	FLIGHT DATA (FDR) RECORDER 2100-2042-00 000341849 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				17-MAR-2014 3200.95 1714		
313018	FDR INERTIA SWITCH 3LO-453/8 12699 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314002	IAPS CARD CAGE 822-0269-001 23N9J REF: AMM 31-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314011	1A PWR-851A POWER SUPPLY CARD 622-8365-003 240XM REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314012	2A PWR-851A POWER SUPPLY CARD 622-8365-003 23RRJ REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314013	1B PWR-851A POWER SUPPLY CARD 622-8365-003 240XL REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314014	2B PWR-851A POWER SUPPLY CARD 622-8365-003 23RVN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314021	1A FLIGHT CONTROL CARD 822-0592-407 848 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C				22-NOV-2013 3076.45 1651		
314022	2A FLIGHT CONTROL CARD 822-0592-407 580 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C				22-NOV-2013 3076.45 1651		
314033	1B FLIGHT MANAGEMENT - FMC 852C CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314034	2B FLIGHT MANAGEMENT - FMC 852C CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314041	1A INPUT/OUTPUT CONCENTRATOR CARD 622-9343-234 1303 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-NOV-2006 313.28 218		
314042	2A INPUT/OUTPUT CONCENTRATOR CARD 622-9343-234 23T4V REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314043	1B INPUT/OUTPUT CONCENTRATOR CARD 622-9343-234 23T4W REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314044	2B INPUT/OUTPUT CONCENTRATOR CARD 622-9343-234 223FC REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314101	DATA ACQUISITION UNIT 622-9344-001 1VVBY REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
314110	MINI-FLIGHT DATA ACQUISITION (MFDAU) UNIT 2231230-7 00596 REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C				14-OCT-2013 3035.77 1634		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
315101	AURAL WARNING CONTROL UNIT 883-1 2237 REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
315102	TONE GENERATOR PN SN-UNKNOWN REF: AMM 31-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
315103	AURAL WARNING MIXER 1882-1 716 REF: AMM 31-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
315201	GLARESHIELD ANNUNCIATOR PANEL PN SN-UNKNOWN REF: AMM 31-52-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
315203	MASTER CAUTION/WARNING TRIGGER UNIT ASSEMBLY SP-60-005 020600358 REF: AMM 31-52-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316001	PILOT EFD-871 ELECTRONIC FLIGHT DISPLAY 622-9345-026 1M58W REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316002	COPILOT EFD-871 ELECTRONIC FLIGHT DISPLAY 622-9345-026 276TB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			17-MAR-2015 3839.9 1974		
316004	MULTIFUNCTION DISPLAY PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316005	PILOT EFIS CONTROL PANEL PN SN-UNKNOWN REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316006	COPILOT EFIS CONTROL PANEL PN SN-UNKNOWN REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316011	NO. 1 DISPLAY IMT-871 TRAY 822-0278-001 2220N REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316012	NO. 2 DISPLAY IMT-871 TRAY 822-0278-001 2220M REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316013	NO. 3 DISPLAY IMT-871 TRAY 822-0278-001 21Y2Y REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316014	NO. 4 DISPLAY IMT-871 TRAY 822-0278-001 21Y2X REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316101	SENSOR DISPLAY UNIT 622-9735-002 226YX REF: AMM 31-61-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316102	SENSOR DISPLAY DRIVER UNIT 622-9347-001 1VX3G REF: AMM 31-61-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
316301	MAINTENANCE WARNING PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 31-63-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
317021	FDR UNDERWATER LOCATOR (ULB) BEACON DK120 SD65053 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C				01-SEP-2017 3840.35 1975		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
317021A	CLEAN/FUNCTIONAL TEST FDR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY DK120 SD65053 REF: AMM 25-63-00	MOS HRS/MSC AFL	24	+14d/-14d			08-JUL-2021 4712.9 2660	08-JUL-2023	22-JUL-2023
317021B	REPLACE FDR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000 DK120 SD65053 REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE			01-SEP-2017 3840.35 1975	31-AUG-2023 M		
317021C	PERFORM FDR UNDERWATER LOCATOR (ULB) BEACON INSPECTION OF THE UNDERWATER LOCATING BEACON (DK100, DK120, DK130, DK140, DUKANE CORPORATION) PERFORM ACOUSTICS CHARACTERISTICS CHECK (REFER TO 25-63-00) DK120 SD65053 REF:	MOS HRS/MSC AFL	216	+14d/-14d		01-SEP-2017 3840.35 1975	01-SEP-2035	15-SEP-2035	
P3151001 (s)	PERFORM OPERATIONAL CHECK OF THE AUTOPILOT AURAL WARNING. (REFER TO 31-51-00) (EFFECTIVE ON AIRCRAFT 60-307, 60-319 AND SUBSEQUENT) PKG 1 REF: AMM 31-51-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		04-MAR-2021 4614.1 2588	PKG		
P3160001 (s)	PERFORM OPERATIONAL CHECK OF THE ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS). (REFER TO 31-60-03) PKG 7 REF: AMM 31-60-03	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25		07-FEB-2020 4291.5 2345	PKG		
T3110000 (s)	INSPECT EQUIPMENT INSTALLATIONS BETWEEN FORWARD PRESSURE BULKHEAD AND INSTRUMENT PANEL FOR SECURITY OF MOUNTING, WIRE ROUTING, AND CLEARANCES OF WIRING AND PLUMBING. PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25		07-FEB-2018 3852.6 1982	PKG		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U3100001 (s)	GENERAL VISUAL INSPECTION INSTRUMENT PANEL (REFER TO 5-10-00.) PKG 1	MOS	12	+14d/-14d			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			31-MAR-2022 4901.4 2815		
CHAPTER 32 LANDING GEAR									
05-11-00-E3211066	REPLACE NOSE LANDING GEAR ACTUATOR BOLT (6042007-4)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-32-01	HRS/MSC AFL	6000	+25/-25			0 0	6000	6025
05-11-00-E3211074L	REPLACE LEFT * MLG UPPER BEARINGS (6041104) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	3000				0 0	3000	
05-11-00-E3211074R	REPLACE RIGHT * MLG UPPER BEARINGS (6041104) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	3000				0 0	3000	
05-11-00-E3211084L	REPLACE LEFT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E3211084R	REPLACE RIGHT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	20000				0 0	20000	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E3211090L	REPLACE LEFT * MLG UPPER BEARING RETENTION PIN (6041110-1) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	3000				0 0		3000
05-11-00-E3211090R	REPLACE RIGHT * MLG UPPER BEARING RETENTION PIN (6041110-1) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	3000				0 0		3000
05-11-00-E3211092L	REPLACE LEFT * MLG UPPER BEARING (7600839) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0		6000
05-11-00-E3211092R	REPLACE RIGHT * MLG UPPER BEARING (7600839) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0		6000
05-11-00-E3211093L	REPLACE LEFT * MLG LOWER BEARING (6041105) (AWL*)	MOS					06-SEP-2012		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				2852.1 1527		7527
05-11-00-E3211093R	REPLACE RIGHT * MLG LOWER BEARING (6041105) (AWL*)	MOS					06-SEP-2012		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				2852.1 1527		7527

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-G3210003	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN AND NOSE GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR	MOS						12-OCT-2009	
TEFLON	REF: GENERIC NO REF	HRS/MSC AFL	O/C				1446.98 781		
05-11-00-G3233007	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY FREEFALL EXTENSION, LANDING GEAR EMERGENCY BLOWDOWN, AND EMERGENCY BRAKING SYSTEMS	MOS						11-MAR-2006	
TEFLON	REF: GENERIC NO REF	HRS/MSC AFL	O/C				0 0		
05-11-00-G3243040	REPLACE HYDRAULIC BRAKE HOSE ASSEMBLIES LOCATED ON THE STRUT AND IN WHEEL WELL AREA	MOS						09-FEB-2011	
TEFLON	REF: GENERIC NO REF	HRS/MSC AFL	O/C				2087.38 1135		
05-11-00-U3211091L	REPLACE LEFT * MLG UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)	MOS						11-MAR-2006	
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL		6000			0 0		6000
05-11-00-U3211091R	REPLACE RIGHT * MLG UPPER BEARING RETENTION PIN (6041110-002 AND SUBSEQUENT) (AWL*)	MOS						11-MAR-2006	
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL		6000			0 0		6000
321001	* LEFT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*) 6041000V3-001 001	MOS						21-FEB-2014	
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL APH ACH		16500			3143.92 1686		16500 M

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321002	* RIGHT MAIN LANDING GEAR STRUT ASSEMBLY (AWL*) 6041000V3-002 001	MOS HRS/MSC					21-FEB-2014 3143.92		
LIFE LIMIT	REF: AMM 32-11-00	AFL APH ACH	16500				1686	16500 M	
321003	* LEFT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*) PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			11-MAR-2006 0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	N:0			0	6000	
321004	* RIGHT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM (AWL*) PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			11-MAR-2006 0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	N:0			0	6000	
321005	* LEFT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*) PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			11-MAR-2006 0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	N:0			0	6000	
321006	* RIGHT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM (AWL*) PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			11-MAR-2006 0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	N:0			0	6000	
321011	LEFT MAIN LANDING GEAR PISTON ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			11-MAR-2006 0		
	REF: AMM 32-11-00	AFL	O/C	N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321012	RIGHT MAIN LANDING GEAR PISTON ASSEMBLY PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
321013	LEFT MAIN LANDING GEAR AXLE PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
321014	RIGHT MAIN LANDING GEAR AXLE PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
321501	LEFT HYDRAULIC, GEAR RETRACTION RESTRICTOR PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
321502	RIGHT HYDRAULIC, GEAR RETRACTION RESTRICTOR PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
321511	LEFT HYDRAULIC, GEAR EXTENSION RESTRICTOR PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321512	RIGHT HYDRAULIC, GEAR EXTENSION RESTRICTOR PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
321515	LEFT HYDRAULIC RESTRICTOR 1R3665-035 D7092 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
321516	RIGHT HYDRAULIC RESTRICTOR 1R3665-059 D2213 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
322001	* NOSE GEAR STRUT ASSEMBLY (AWL*) 2342100-030 094 REF: AMM 32-21-00	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			11-MAR-2006 0 0		10000
LIFE LIMIT									
322002	NOSE LANDING GEAR & STEERING ASSEMBLY STRUT 2342003-090 094 REF: AMM 32-21-00	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			11-MAR-2006 0 0		10000
LIFE LIMIT									
323019	LEFT MAIN LANDING GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323020	RIGHT MAIN LANDING GEAR SQUAT SWITCH 426EN9-8 NSN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	N:5 N:0 N:0			08-JUN-2014 3337.13 1768		
323031	* LEFT MAIN LANDING GEAR ACTUATOR (AWL*) 6600264-008 1406 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			09-FEB-2011 2087.38 1135	21135	
323032	* RIGHT MAIN LANDING GEAR ACTUATOR (AWL*) 6600264-008 1418 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			09-FEB-2011 2087.38 1135	21135	
323036	LEFT MAIN LANDING GEAR ACTUATOR ATTACH PIN 5441011-007 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				21-FEB-2014 3143.92 1686		
323037	RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PIN 5441011-007 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				21-FEB-2014 3143.92 1686		
323043	LEFT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR 66000085-009 0415 REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			08-JUL-2021 4712.9 2660		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323044	RIGHT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR 6600085-009 0715 REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			09-FEB-2011 2087.38 1135		
323052	LANDING GEAR CONTROL PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 32-30-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323055	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 6487 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C				16-APR-2010 1606.58 882		
323056	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 6486 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C				16-APR-2010 1606.58 882		
323057	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR 2417016-1 5881 REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323058	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR 2417016-1 5882 REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323073	* NOSE LANDING GEAR ACTUATOR (AWL*) 2317100-018 MTM0009	MOS HRS/MSC		N:0 N:0			27-FEB-2009 1268.93		
LIFE LIMIT	REF: AMM 32-32-01	AFL	10000	N:0			683	10683	
323079	NOSE LANDING GEAR UPLOCK ACTUATOR 2417016-1 5880	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF: AMM 32-32-02	AFL		N:0			0		
323080	UPLOCK, NOSE LANDING GEAR FREEFALL ACTUATOR 2417016-1 5913	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF: AMM 32-33-05	AFL		N:0			0		
323098	GEAR DOOR CONTROL VALVE 6600361-1 1369	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF: AMM 32-30-08	AFL		N:0			0		
323099	SELECT, LANDING GEAR VALVE 48C48641 0742	MOS HRS/MSC	O/C	N:0 N:0			02-OCT-2008 1100.28		
	REF: AMM 32-30-05	AFL		N:0			595		
323105	NOSE LANDING GEAR SHUTTLE VALVE 2SV0614 4471	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323110	NOSE LANDING GEAR UPLATCH SHUTTLE VALVE 2SV0413 D18214 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323205	LEFT MAIN LANDING GEAR EXTEND SHUTTLE VALVE 95930 1169 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323210	RIGHT MAIN LANDING GEAR EXTEND SHUTTLE VALVE 95930 1170 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323222	* LEFT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*) PN SN-UNKNOWN REF: AMM 32-31-05	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			11-MAR-2006 0 0	20000	
LIFE LIMIT									
323223	* RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR (AWL*) PN SN-UNKNOWN REF: AMM 32-31-05	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			11-MAR-2006 0 0	20000	
LIFE LIMIT									
323305	LEFT MAIN LANDING GEAR DOOR SHUTTLE VALVE 2SV0413 D18198 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323310	RIGHT MAIN LANDING GEAR DOOR SHUTTLE VALVE 2SV0413 D18216 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323315	LEFT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE 92465 4474 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323320	RIGHT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE 92465 4467 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323401	AFT EMERGENCY GEAR BLOWDOWN EXTENSION VALVE 53620-6 2354 REF: AMM 32-33-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323402	FORWARD EMERGENCY GEAR FREEFALL EXTENSION VALVE 53620-6 2360 REF: AMM 32-33-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323405	LEFT CHECK, FREEFALL VALVE 92465 4483 REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323406	RIGHT CHECK, FREEFALL VALVE 7600833-001 0311 REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323409	UPPER EMERGENCY GEAR EXTENSION RESTRICTOR 6R7742S0135 4747 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323410	LOWER EMERGENCY GEAR EXTENSION RESTRICTOR 6R7742S0135 4748 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
323430	NO. 1 EMERGENCY AIR BLOWDOWN SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324001	NOSE TIRE TRACKED ITEM PN SN-UNKNOWN REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
324007	ASSEMBLY, NOSE WHEEL 9544207-4 NOV95-7917 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324013	NO. 1 MAIN LANDING GEAR TIRE TRACKED ITEM 178K43-1 10560585 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:7 N:0 N:0			05-OCT-2021 4796.2 2733		
324014	NO. 2 MAIN LANDING GEAR TIRE TRACKED ITEM 178K43-1 83113049 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:29 N:0 N:0			05-OCT-2021 4796.2 2733		
324015	NO. 3 MAIN LANDING GEAR TIRE TRACKED ITEM 178K43-1 00440881 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-SEP-2020 4468.9 2486		
324016	NO. 4 MAIN LANDING GEAR TIRE TRACKED ITEM 178K43-1 00420936 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-SEP-2020 4468.9 2486		
324037	NO. 1 MAIN LANDING GEAR WHEEL 6600330-20 MAY95-457 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	R:5 R:0 R:0			05-OCT-2021 4796.2 2733		
324037A	NDT INSPECT NO. 1 MAIN LANDING GEAR WHEEL 6600330-20 MAY95-457 REF: NDT 32-40-01	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324038	NO. 2 MAIN LANDING GEAR WHEEL 6600330-20 APR09-3043 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	R:3 R:0 R:0			05-OCT-2021 4796.2 2733		
324038A	NDT INSPECT NO. 2 MAIN LANDING GEAR WHEEL 6600330-20 APR09-3043 REF: NDT 32-40-01	MOS HRS/MSC AFL	O/C						
324039	NO. 3 MAIN LANDING GEAR WHEEL 5011740 DEC11-3280 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				05-SEP-2020 4468.9 2486		
324039A	NDT INSPECT NO. 3 MAIN LANDING GEAR WHEEL 5011740 DEC11-3280 REF: NDT 32-40-01	MOS HRS/MSC AFL	O/C				05-SEP-2020 4468.9 2486		
324040	NO. 4 MAIN LANDING GEAR WHEEL 5011740 DEC11-3277 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				05-SEP-2020 4468.9 2486		
324040A	NDT INSPECT NO. 4 MAIN LANDING GEAR WHEEL 5011740 DEC11-3277 REF: NDT 32-40-01	MOS HRS/MSC AFL	O/C				05-SEP-2020 4468.9 2486		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324048	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE 6600518-003 MAR04-0230 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
324049	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE 6600518-003 JUN10-1329 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
324050	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 NOV05-0616 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			06-SEP-2012 2852.1 1527		
324051	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 JAN08-0883 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				06-SEP-2012 2852.1 1527		
324061	NO. 1 POWER BRAKE, PILOTS VALVE 3321200-2 1928 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324062	NO. 2 POWER BRAKE, PILOTS VALVE 3321200-2 1926 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324063	NO. 1 POWER BRAKE, COPILOTS VALVE 3321200-2 1929 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324064	NO. 2 POWER BRAKE, COPILOTS VALVE 3321200-2 1932 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324085	NO. 1 HYDRAULIC, BRAKE FUSE 2380114-1 7114 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324086	NO. 2 HYDRAULIC, BRAKE FUSE 2380114-1 7112 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324109	NO. 3 HYDRAULIC, BRAKE FUSE 2380114-1 6918 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324110	NO. 4 HYDRAULIC, BRAKE FUSE 2380114-1 6923 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324133	AFT PARKING BRAKE VALVE 6600392-003 0180 REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324134	FWD PARKING BRAKE VALVE 6600392-003 0176 REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324145	NO. 1 WHEEL SPEED TRANSDUCER 40-911 7556 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324146	NO. 2 WHEEL SPEED TRANSDUCER 40-911 7554 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324147	NO. 3 WHEEL SPEED TRANSDUCER 40-911 7530 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324148	NO. 4 WHEEL SPEED TRANSDUCER 40-911 7534 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324169	LEFT ANTI-SKID VALVE 39-309-2 2531A REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	N:1030.08 N:559			28-JUL-2008 1030.08 559		
324170	RIGHT ANTI-SKID VALVE 39-309-2 2592A REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2008 722.77 425		
324175	ANTI-SKID CONTROL 42-379-1 1852B REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324413	PARK BRAKE ANNUNCIATOR BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 32-42-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324501	EMERGENCY BRAKE CONTROL VALVE 63500-2 502A REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324505	LEFT MAIN LANDING GEAR BRAKE SHUTTLE VALVE AN6227/2SV0413 D18215 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324510	RIGHT MAIN LANDING GEAR BRAKE SHUTTLE VALVE AN6227/2SV0413 D18225 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324601	NO. 1 MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 D18224 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324602	NO. 2 MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 D18200 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324603	NO. 3 MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 D18199 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
324604	NO. 4 MAIN LANDING GEAR BRAKE SHUTTLE VALVE 2SV0413 D18217 REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
325001	NOSE WHEEL STEERING ACTUATOR 501-1711-02 80020 REF: AMM 32-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325005	NOSE WHEEL STEERING COMPUTER 501-1708-03 1281 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	R:0 R:0			15-NOV-2006 302.37 210		
325015	LEFT RUDDER POSITION SENSOR 501-1123-03 80167 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
325016	RIGHT RUDDER POSITION SENSOR 501-1123-03 80490 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-DEC-2006 326.15 228		
325019	NOSE WHEEL STEERING ACTUATOR GEARBOX 3142020-3 310 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
325020	NOSE WHEEL STEERING FOLLOW UP ASSEMBLY 2618274-12 355 REF: AMM 32-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
325024	RIGHT NOSE WHEEL STEERING FOLLOWUP CU41096004-0 2205 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325025	LEFT NOSE WHEEL STEERING FOLLOWUP CU41096004-0 2206 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
325628	AFT EMERGENCY GEAR CONTROL VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
326011	SQUAT SWITCH RELAY BOX PN SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
AA3211058 (s)	COMPLETELY DISASSEMBLE MAIN LANDING GEAR STRUTS AND ACTUATORS. REMOVE AXLES AND PISTONS FROM HUBS. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. CONDUCT FLUORESCENT PENETRANT OR MAGNETIC PARTICLE INSPECTION OF ALL COMPONENTS. PAY PARTICULAR ATTENTION TO THE MAIN GEAR UPPER TRUNNION AREAS AND LOWER GLAND NUT OF THE CYLINDER FORGING FOR CRACKS. PKG 26 REF: NDT 32-13-01	MOS HRS/MSC AFL	6000	+25/-25			11-MAR-2006 0 0		
C3211040 (s)	CLEAN AND EDDY CURRENT INSPECT UPPER CYLINDER. (SEE FIGURE 1.) (REFER TO NDI MANUAL [NDI-2], PART 3, 32-40-02.) PKG 26 REF: NDT 32-40-02	MOS HRS/MSC AFL	6000	+25/-25			11-MAR-2006 0 0		
C3211050 (s)	DEFLATE STRUTS AND STROKE FROM FULLY EXTENDED TO FULLY COMPRESSED POSITIONS. NOTE BINDING TENDENCIES DURING STROKING, PARTICULARLY NEAR THE FULLY COMPRESSED POSITION. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	6000	+25/-25			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C3231030 (s)	INSPECT INBOARD ATTACHMENT OF MAIN GEAR ACTUATOR FOR SECURITY, LOOSENESS, OVERLOAD INDICATIONS, AND FATIGUE CRACKS. THE PILLAR ATTACHMENTS TO SPARS 7 AND 8 ARE TO BE SPECIFICALLY INSPECTED FOR DISCREPANT CONDITIONS. PILLAR REMOVAL IS REQUIRED TO FACILITATE DEFINI						PKG		
	PKG 26	MOS					11-MAR-2006		
	REF: GENERIC NO REF	AFL	6000	+25/-25			0		0
C3233010 (s)	FUNCTIONAL TEST OF LANDING GEAR EMERGENCY BLOWDOWN EXTENSION SYSTEM. (REFER TO 32-33-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			07-FEB-2018		
	REF: AMM 32-33-00	AFL	6000	+25/-25			3852.6		1982
C3233011 (s)	FUNCTIONAL TEST OF LANDING GEAR EMERGENCY FREEFALL SYSTEM. (REFER TO 32-33-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			07-FEB-2018		
	REF: AMM 32-33-00	AFL	6000	+25/-25			3852.6		1982
D3211060 (s)	COMPLETELY DISASSEMBLE NOSE LANDING GEAR STRUT AND ACTUATOR. REMOVE AXLE AND PISTON FROM HUB. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. (REFER TO 32-21-00 AND 32-32-01.) CONDUCT FLUORE						PKG		
	PKG 26	MOS					11-MAR-2006		
	REF: AMM 32-32-01	AFL	6000	+25/-25			0		0
D3211061 (s)	VISUALLY INSPECT NOSE GEAR TRUNNION AXLE AND INSTALLATION AREA OF TRUNNION FOR CRACKS, CORROSION, AND DAMAGE. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION I						PKG		
	PKG 26	MOS					11-MAR-2006		
	REF: AMM 32-21-00	AFL	6000	+25/-25			0		0
E3230020 (s)	INSPECT LANDING GEAR SQUAT SWITCHES FOR CONDITION.						PKG		
	PKG 5	MOS	12	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	AFL	300	+25/-25			4901.4		2815

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E3242000 (s)	INSPECT NOSE AND MAIN TIRES FOR WEAR, CUTS, ABRASIONS, AND FLAT SPOTS. CHECK CHINE CONDITION ON CHINED TIRE. (REFER TO 32-40-00)						PKG		
	PKG 5	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: AMM 32-40-00	AFL						2815	
E3243010 (s)	INSPECT BRAKE ASSEMBLIES FO RWEAR, CRACKS, HYDRAULIC LEAKS, AND RELEASE.						PKG		
	PKG 5	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: AMM 32-41-01	AFL						2815	
E3244020 (s)	REMOVE AND CLEAN ANTI-SKID VALVE FILTERS. (REFER TO 32-42-01).						PKG		
	PKG 11	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: AMM 32-42-01	AFL						2815	
F3233020 (s)	FUNCTIONAL TEST OF EMERGENCY BRAKE SYSTEM. (REFER TO 34-43-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: AMM 32-43-00	AFL	6000	+25/-25				1982	
G3200000 (s)	PERFORM VISUAL INSPECTION OF LANDING GEAR SHOCK STRUTS FOR LEAKS AND GENERAL CONDITION. VISUALLY INSPECT LANDING GEAR SHOCK STRUTS AND LANDING GEAR ACTUATOR ATTACH POINTS FOR SECURITY AND GERNAL CONDITION. (REFER TO 5-10-00)						PKG		
	PKG 5	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
H3210000 (s)	VISUALLY INSPECT MAIN AND NOSE LANDING GEAR STRUT ASSEMBLIES, ACTUATORS, FASTENERS, AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT NOSE GEAR ACTUATOR ATTACH BRACKET IN THE AREA AROUND THE GREASE FITTING. INSPECT FOR CRACKS EM						PKG		
	PKG 17	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3211010 (s)	INSPECT MAIN LANDING GEAR TORQUE LINKS FOR LOOSENESS. PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H3211020 (s)	INSPECT INTERIOR AND EXTERIOR OF MAIN LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-11-00.) PKG 23 REF: AMM 32-11-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
H3221000 (s)	INSPECT NOSE GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. PKG 23 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
H3221010 (s)	INSPECT INTERIOR AND EXTERIOR OF NOSE LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-21-00.) PKG 23 REF: AMM 32-21-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
H3230000 (s)	INSPECT LANDING GEAR ELECTRICAL WIRING FOR ROUTING AND GENERAL CONDITION. PKG 11 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H3230010 (s)	PERFORM LANDING GEAR RETRACTION AND EXTENSION CHECK. CHECK AUTOMATIC BRAKE SNUBBING AND LANDING LIGHTS FOR RETRACT CUTOFF. (REFER TO 32-30-00.) PKG 17 REF: AMM 32-30-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3230021 (s)	INSPECT LANDING GEAR SQUAT SWITCHES FOR PROPER OPERATION AND CONDITION. (REFER TO 32-30-03.) PKG 17 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H3231014 (s)	INSPECT MAIN GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FASTEMER CONDITION, AND PERMANENT DEFORMATION. PKG 23 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
H3232002 (s)	INSPECT NOSE GEAR ACTUATOR BOOT AND HYDRAULIC PLUMBING FOR SECURITY AND GENERAL CONDITION. PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H3233000 (s)	VISUALLY INSPECT GEAR FREE FALL, GEAR BLOW DOWN, AND EMERGENCY BRAKE VALVES AND FITTINGS FOR SECURITY OF ATTACHMENT. (REFER TO 5-10-00.) PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H3233012 (s)	PERFORM EMERGENCY AIR EXTENSION SYSTEM AND EMERGENCY BRAKE SYSTEM PLUMBING LEAKAGE CHECK. (REFER TO 32-33-00 AND 32-43-00.) PKG 17 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H3243000 (s)	INSPECT BRAKE LINES FOR ROUTING AND LEAKS, MLG AND DOOR ACTUATOR ATTACH POINTS FOR SECURITY, AND STRUT HINGE POINTS FOR GENERAL CONDITION. PKG 11 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3243023 (s)	INSPECT POWER BRAKE VALVES FOR SECURITY, OPERATION, AND LEAKS. ENSURE POWER BRAKE VALVE LEVER CONTACTS MECHANICAL STOP. (REFER TO 32-41-02.)						PKG		
	PKG 14	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: AMM 32-41-02	AFL						2815	
H3243030 (s)	FUNCTIONAL TEST OF HYDRAULIC BRAKE FUSES. (REFER TO 32-41-03.)						PKG		
	PKG 23	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: AMM 32-41-03	AFL						1982	
N3243024 (s)	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.						PKG		
	PKG 8	MOS	24	+14d/-14d				07-FEB-2020	
		HRS/MSC	600	+25/-25				4291.5	
	REF: AMM 32-41-02	AFL						2345	
N3243050 (s)	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.						PKG		
	PKG 14	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: AMM 32-41-02	AFL						2815	
Q3242001 (s)	OPERATIONAL CHECK ANTI-SKID VALVES (REFER TO 32-42-00)						PKG		
	PKG 5	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: AMM 32-42-00	AFL						2815	
T3211030 (s)	REMOVE AND REPLACE RETAINER RING LOCKSCREW FROM NOSE LANDING GEAR STRUT (P/N AN500A6-10).						PKG		
	PKG 11	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: AMM 32-21-00	AFL						2815	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T3231040 (s)	INSPECT MAIN LANDING GEAR DOOR ACTUATORS AND HINGES FOR SECURITY AND GENERAL CONDITION. PKG 11	MOS	24	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			4901.4 2815		
W3232003 (s)	NOSE LANDING GEAR FREE FALL UPLATCH ACTUATOR - PERFORM DETAILED CHECK. (REFER TO 32-33-05.) PKG 17	MOS	48	+14d/-14d			31-MAR-2022		
	REF: AMM 32-33-05	HRS/MSC AFL	1200	+25/-25			4901.4 2815		
CHAPTER 33 LIGHTS									
331201	LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY 6900115-000	MOS		N:0			11-MAR-2006		
	6099	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-12-02	AFL		N:0			0		
331202	RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY 6900115-000	MOS		N:0			11-MAR-2006		
	6102	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-12-02	AFL		N:0			0		
331303	QUAD EL (ELECTROLUMINESCENT) POWER SUPPLY SDA 16	MOS		O:0			22-AUG-2008		
	181	HRS/MSC	O/C	O:0			1074.43		
	REF: AMM 33-13-03	AFL		O:0			582		
331311	PILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331312	COPILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY 7608040-018 0078 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-FEB-2016 3839.9 1974		
331313	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331314	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331401	PILOT DIMMING CONTROL BOX LT-48E 5474 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331402	COPILOT DIMMING CONTROL BOX LT-48E 5471 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331403	CENTER INSTRUMENT AND PEDESTAL DIMMING CONTROL BOX LT-48G 1806 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331404	PEDESTAL DIMMING CONTROL BOX LT-48G 1794 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331405	FUEL QUANTITY INDICATOR DIMMING CONTROL BOX LT-48G 1807 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331406	CDU LAMP DIMMING CONTROL BOX PN SN-UNKNOWN REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331407	INSTRUMENT BACKLIGHTING FUSE BOX PN SN-UNKNOWN REF: AMM 33-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331601	LEFT ACS DIMMER CONTROL BOX LT-48G 1796 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331602	RIGHT ACS DIMMER CONTROL BOX LT-48G 1801 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331701	LEFT AFT LIGHT DIMMING (E215) CONTROL BOX PN SN-UNKNOWN REF: AMM 33-17-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331801	LEFT FORWARD LIGHT DIMMING (AE9) CONTROL BOX PN SN-UNKNOWN REF: AMM 33-18-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
331802	RIGHT LIGHT DIMMING (2AE9) CONTROL BOX PN SN-UNKNOWN REF: AMM 33-18-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
332001	OVERHEAD INDIRECT LIGHTING (PS2) INVERTER 6900115-000 6098 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
332002	OVERHEAD INDIRECT LIGHTING (2PS2) INVERTER 6900115-000 6711 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUL-2009 1385.17 747		
332003	OVERHEAD INDIRECT LIGHTING (3PS2) INVERTER 6900115-000 5965 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332004	OVERHEAD INDIRECT LIGHTING (4PS2) INVERTER 6900115-000 6917 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:37 N:0 N:0			23-FEB-2016 3839.9 1974		
332005	OVERHEAD INDIRECT LIGHTING (5PS2) INVERTER 6900115-000 5821 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
332006	OVERHEAD INDIRECT LIGHTING (6PS2) INVERTER 6900115-000 6097 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
332007	OVERHEAD INDIRECT LIGHTING (7PS2) INVERTER 6900115-000 6101 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
332009	INDIRECT LIGHTING CONTROL PN SN-UNKNOWN REF: AMM 33-20-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
332010	ALTERNATE/MOMENTARY SWITCHING MODULE PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332014	ZONE BACK LIGHTING CONTROL PN SN-UNKNOWN REF: AMM 33-20-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
334101	LEFT LANDING AND TAXI LIGHT 01-0790750-20 06502 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
334102	RIGHT LANDING AND TAXI LIGHT PN SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
334201	LEFT NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
334202	RIGHT NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
334203	TAIL NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334301	UPPER STROBE/BEACON LIGHT GE16386-9-2 9709 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
334302	LOWER STROBE/BEACON LIGHT GE 16386-9-1 990227 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-MAY-2007 453.43 295		
334401	WING ICE INSPECTION LIGHT GLJ140 12442 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
334501	RECOGNITION LIGHT PN SN-UNKNOWN REF: AMM 33-45-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
334502	RECOGNITION LIGHT PULSE CONTROL UNIT 2401S 00893 REF: AMM 33-45-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
335001	EMERGENCY EXIT LIGHTING PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P3310004 (s)	CHECK OPERATION OF INTERIOR LIGHTING SYSTEMS PKG 1	MOS	12	+14d/-14d			PKG 31-MAR-2022 4901.4 2815		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			4901.4 2815		
P3340012 (s)	CHECK OPERATION OF EXTERIOR LIGHTING SYSTEMS PKG 1	MOS	12	+14d/-14d			PKG 31-MAR-2022 4901.4 2815		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			4901.4 2815		
CHAPTER 34 NAVIGATION									
05-10-29-W3411025	FUNCTIONAL TEST AIR DATA SYSTEM	MOS	24	+14d/-14d		-55	31-MAR-2022 4901.4 2815	05-FEB-2024	19-FEB-2024
	REF: AMM 34-17-00	HRS/MSC AFL					4901.4 2815		
05-10-30-RVSM-W3411015	PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (RVSM) (REFER TO 34-17-00)	MOS	12	+14d/-14d		1	31-MAR-2022 4901.4 2815	01-APR-2023	15-APR-2023
	REF: AMM 34-17-00	HRS/MSC AFL					4901.4 2815		
34-00-FAR-91.171	CHECK VOR FAR 91.171	MOS					11-MAR-2006 0 0		
	REF: See Workcard	HRS/MSC AFL	O/C				0 0		
34-00-FAR-91.411	RECERTIFY PITOT-STATIC SYSTEM	MOS					31-MAR-2022 4901.4 2815		
	REF: See Workcard	HRS/MSC AFL	A/R				4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341020	LEFT PITOT/STATIC PROBE 856KR7 234603 REF: AMM 34-11-02	MOS HRS/MSC AFL	15000	+25/-25	N:68 N:2508.82 N:1358		14-DEC-2011 2508.82 1358	15000	15025
LIFE LIMIT									
341020A	VERIFY LEFT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016 856KR7 234603 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d		-53	31-MAR-2022 4901.4 2815	07-FEB-2024	21-FEB-2024
341020B	DETAILED VISUAL INSPECTION LEFT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064 856KR7 234603 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d		-53	31-MAR-2022 4901.4 2815	07-FEB-2024	21-FEB-2024
341025	RIGHT PITOT/STATIC PROBE 856KR8 235158 REF: AMM 34-11-02	MOS HRS/MSC AFL	15000	+25/-25	N:68 N:2508.82 N:1358		14-DEC-2011 2508.82 1358	15000	15025
LIFE LIMIT									
341025A	VERIFY RIGHT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (RVSM) (REFER TO 34-11-02) 5-10-30-N3411016 856KR8 235158 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d		-53	31-MAR-2022 4901.4 2815	07-FEB-2024	21-FEB-2024
341025B	DETAILED VISUAL INSPECTION RIGHT PITOT/STATIC PROBE (RVSM) (REFER TO 34-11-02) 5-10-30-N3411064 856KR8 235158 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+14d/-14d		-53	31-MAR-2022 4901.4 2815	07-FEB-2024	21-FEB-2024

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341026	PITOT/STATIC PROBE 856KR8 235160 REF: AMM 34-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341105	PILOT RIGHT STATIC SHUTOFF VALVE 6600473-2 0551T REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341106	COPILOT RIGHT STATIC SHUTOFF VALVE 6600473-2 0550T REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341107	PILOT LEFT STATIC SHUTOFF VALVE 6600473-1 0619T REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341108	COPILOT LEFT STATIC SHUTOFF VALVE 6600473-1 0612T REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341133	NO. 1 LOWER (ADC) AIR DATA COMPUTER 822-0389-429 22F7B REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341133A	RECERTIFY NO. 1 LOWER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM 822-0389-429 22F7B REF: See Workcard	MOS HRS/MSC AFL	24				31-MAR-2022	31-MAR-2024	
341134	NO. 2 UPPER (ADC) AIR DATA COMPUTER 822-0389-429 1MJ0K REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
341134A	RECERTIFY NO. 2 UPPER (ADC) AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM 822-0389-429 1MJ0K REF: See Workcard	MOS HRS/MSC AFL	24				31-MAR-2022	31-MAR-2024	
341220	INTEGRATED / ELECTRONIC STANDBY INDICATOR SYSTEM 3 IN 1 GAUGE 314MFD1-1 ND7129 REF: AMM 34-19-01	MOS HRS/MSC AFL	O/C	N:823.9 N:454			28-JUL-2008 1030.08 559		
341220A	RECERTIFY INTEGRATED / ELECTRONIC STANDBY INDICATOR SYSTEM 3 IN 1 GAUGE 314MFD1-1 ND7129 REF: AMM 34-19-01	MOS HRS/MSC AFL	24				31-MAR-2022 4901.4 2815	31-MAR-2024	
341225	STANDBY AIRSPEED INDICATOR PN SN-UNKNOWN REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341401	RADIO ALTIMETER TRANSCEIVER PN SN-UNKNOWN REF: AMM 34-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341402	RADIO ALTIMETER CONVERTER PN SN-UNKNOWN REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341403	AFT RADIO ALTIMETER ANTENNA 622-0954-002 1NM7R REF: AMM 34-14-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341404	FORWARD RADIO ALTIMETER ANTENNA 622-0954-002 240MK REF: AMM 34-14-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341703	FORWARD SIGNAL INTERFACE ADAPTER 622-9732-003 248XC REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341704	AFT SIGNAL INTERFACE ADAPTER 622-9732-003 24GBN REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341705	PILOT AIR DATA REFERENCE PANEL 622-9500-002 1YKCF REF: AMM 34-17-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341706	COPILOT AIR DATA REFERENCE PANEL 622-9500-002 23V3R REF: AMM 34-17-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341707	TAT SENSOR PROBE 102AU1AG A59939 REF: AMM 34-17-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
341801	STANDBY MACH/AIRSPEED INDICATOR PN SN-UNKNOWN REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
342001	MAGNETIC COMPASS MAGNETOMETER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
342025	AHRS COOLING FAN 012070500 104295434 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342055	NO. 1 FLUX DETECTOR UNIT 622-5812-001 32462 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
342056	NO. 2 FLUX DETECTOR UNIT 622-5812-001 34223 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
342057	NO. 1 INTERNAL COMPENSATOR (ICU-85) UNIT 622-6189-002 2472M REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
342058	NO. 2 INTERNAL COMPENSATOR (ICU-85) UNIT 622-6189-022 2L82K REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			13-JUN-2008 950 522		
342301	STANDBY GYRO PN SN-UNKNOWN REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
342401	MAGNETIC COMPASS PN SN-UNKNOWN REF: AMM 34-24-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342410	NO. 1 ATTITUDE/HEADING (AHC-85E) COMPUTER 622-9336-400 NM5N REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C				13-JUN-2008 950 522		
342411	NO. 2 ATTITUDE/HEADING (AHC-85E) COMPUTER 622-9336-400 227YU REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			14-MAR-2008 790.4 456		
342501	STANDBY ATTITUDE DIRECTIONAL (ADI) INDICATOR PN SN-UNKNOWN REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
342605	AUXILIARY SWITCHING UNIT PN SN-UNKNOWN REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
343007	MARKER BEACON (37X-2) ANTENNA 522-0854-069 53579 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344007	NO. 1 GPS PN SN-UNKNOWN REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344008	NO. 2 GPS PN SN-UNKNOWN REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344111	LOWER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 40N608 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:16 N:0 N:0			13-JUN-2014 3352.78 1772		
344112	UPPER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 21496 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			04-NOV-2011 2492.98 1343		
344142	TCAS (TTR-920) PROCESSOR TTR400 INSTALLED TTR400 INSTALLED REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344143	TCAS (TTR-4000) PROCESSOR 822-1294-032 148060 REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C	R:78 R:2446.87 R:1223			04-FEB-2016 3839.9 1974		
344151	STORMSCOPE PROCESSOR 78-8060-6086-5 80679 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344153	STORMSCOPE DISPLAY 78-8060-5900-8 80624 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344155	STORMSCOPE ANTENNA 78-8051-9200-8 81126 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344171	NO. 1 VHF/NAV ANTENNA PN SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344176	NO. 2 VHF/NAV ANTENNA PN SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344201	EFIS RADAR (ERP) PANEL PN SN-UNKNOWN REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA PN SN-UNKNOWN REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344220	AV200 WSI ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344225	AV200 WSI SATELLITE RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344226	WSI RECEIVER MOUNT TRAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344513	TAWS COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344515	TAWS CONFIGURATION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344520	TERRAIN AWARENESS ISOLATION BOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344806	WEATHER RADAR INDICATOR 622-8440-004 22HYK REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344807	PILOT EFIS RADAR CONTROL PANEL 1015-1-11 797 REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
344808	COPILOT EFIS RADAR CONTROL PANEL 1015-1-11 131 REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	O:0 O:0			09-JUN-2006 37 39		
345001	NO. 1 ADF (ADF-462) RECEIVER 622-7382-101 1NLFP REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345002	NO. 2 ADF (ADF-462) RECEIVER 622-7382-101 1YH8L REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345005	ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER 965-0976-040-212-212 23021 REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345010	AUX GPWS/WINDSHEAR INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345011	NO. 1 DME TRANSCEIVER 622-7309-101 1VY3P REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C				01-FEB-2010 1542.9 841		
345012	NO. 2 DME TRANSCEIVER 622-7309-101 FLOH REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C				01-FEB-2010 1542.9 841		
345013	ADF, DUAL (ANT-462B) ANTENNA 622-7384-001 1G84H REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345021	NO. 1 VHF (VIR 432) RECEIVER 622-7194-101 1N46D REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C				04-MAR-2016 3839.9 1974		
345022	NO. 2 VHF (VIR 432) RECEIVER 622-7194-201 3C9VB REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C				01-SEP-2017 3840.35 1975		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345031	NO. 1 NAVIGATION COMPUTER PN SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345032	NO. 2 NAVIGATION COMPUTER PN SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345043	LEFT NAVIGATION (BLADE) ANTENNA DMN4-45 10211 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345044	RIGHT NAVIGATION (BLADE) ANTENNA DMN4-45 10212 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345045	NO. 1 VHF/NAV ANTENNA PN SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345046	NO. 2 VHF/NAV ANTENNA PN SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345079	PRIMARY ROCKWELL/COLLINS TDR-94D TRANSPONDER 622-9210-501 392VV REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
345079A	RECERTIFY PRIMARY ROCKWELL/COLLINS TDR-94D TRANSPONDER 622-9210-501 392VV REF: See Workcard	MOS HRS/MSC AFL	24				31-MAR-2022	31-MAR-2024	
345080	SECONDARY ROCKWELL/COLLINS TDR-94DS 622-9210-501 1L2VG REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
345080A	RECERTIFY SECONDARY ROCKWELL/COLLINS TDR-94DS 622-9210-501 1L2VG REF: See Workcard	MOS HRS/MSC AFL	24				31-MAR-2022	31-MAR-2024	
345085	NO. 1 ATC TRANSPONDER CONTROL ADAPTER PN SN-UNKNOWN REF: AMM 34-56-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
345086	NO. 2 ATC TRANSPONDER CONTROL ADAPTER PN SN-UNKNOWN REF: AMM 34-56-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345091	NO. 1 TRANSPONDER ANTENNA CI100-2 645088 REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
345092	NO. 2 TRANSPONDER ANTENNA CI100-2 688727 REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
345108	ADF PRIMARY ANTENNA PN SN-UNKNOWN REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
346004	DATA BASE - DBU-4000 UNIT PN SN-UNKNOWN REF: AMM 34-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
346015	#1 UNS-LEW 3017-41-221 2317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-FEB-2018 3852.65 1982		
346016	#2 UNS-LEW TRACKED ITEM 3017-41-221 2316 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-FEB-2018 3852.65 1982		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346017	NO. 3 FLIGHT MANAGEMENT SYSTEM CDU PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
346021	PRIMARY FMS DATA TRANSFER (DTU) UNIT PN SN-UNKNOWN REF: AMM 34-61-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
346022	SSDTU UNIT 1408-00-1 3972 REF: AMM 34-61-04	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.65 1982		
346025	#1 UNS-1EW CONFIGURATION MODULE 30171 2403 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.6 1982		
346026	#2 UNS-1EW CONFIGURATION MODULE 30171 2402 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.6 1982		
346031	PILOT ALTITUDE AWARENESS PANEL 822-0328-004 1RY6C REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346032	COPILOT ALTITUDE AWARENESS PANEL 822-0328-004 246VJ REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
346041	COURSE HEADING PANEL 622-7397-006 540 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-OCT-2006 242 182		
346055	CONFIGURATION, AFIS MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
346071	UNILINK CONFIGURATION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
346090	AFIS DATA MANAGEMENT UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
346091	DATA TRANSFER, AFIS UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346092	AFIS ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
347510	FORWARD GPS ANTENNA 10708 10759 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.6 1982		
347511	AFT GPS ANTENNA 10708 10758 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.6 1982		
H3411010 (s)	INSPECT PITOT TUBES, STATIC AND PITOT LINES, DRAIN LINES, AND WIRING FOR CONDITION AND SECURITY. CHECK STATIC PORTS AND PITOT/STAIC PROBES FOR DISTORTION. CHECK OPERATION OF DRAIN VALVES. (REFER TO 34-11-02)	PKG 8 MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
H3411012 (s)	INSPECT AIR TEMPERATURE SENSOR OR AIR DATA COMPUTER STATIC, PITOT, AND DRAIN LINES FOR CONDITION AND SECURITY. CHECK OPERATION OF DRAIN VALVES.	PKG 8 MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
H3411031 (s)	PERFORM FUNCTIONAL TEST OF STATIC SHUTOFF (ISOLATION) VALVES. (REFER TO 34-11-00)	PKG 7 MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
K3411061 (s)	PITOT-STATIC PROBE HEATING CURRENT SENSING RELAY - PERFORM FUNCTIONAL TEST. (REFER TO 30-30-01) PKG 7 REF: AMM 30-30-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
P3400004 (s)	INSPECT NOSE COMPARTMENT FROM THE FORWARD SIDE OF THE FORWARD PRESSURE BULKHEAD, FORWARD, FOR CLEANLINESS. ELECTRONIC AND ELECTRICAL EQUIPMENT AND ANTENNA INSTALLATIONS FOR SECURITY OF MOUNTING AND GENERAL CONDITION. WIRE BUNDLE AND PLUMBING ROUTING FOR SECURIT PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T3453003 (s)	INSPECT ANTENNA INSTALLATIONS FOR SECURITY, CORROSION, AND PROPER TENSION OF HF ANTENNA WIRE. (REFER TO 23-12-03.) PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
U3411014 (s)	INSPECT PITOT STATIC PROBES - PERFORM PITOT-STATIC PROBE DRAIN HOLE CHECK. (REFER TO 34-11-02) PKG 2 REF: AMM 34-11-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
CHAPTER 35	OXYGEN								
350003	NOSE OXYGEN SYSTEM PRESSURE TRANSDUCER PN SN-UNKNOWN REF: AMM 35-00-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
350004	DORSAL OXYGEN SYSTEM PRESSURE TRANSDUCER 124058-2000 42482 REF: AMM 35-00-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350006	DORSAL OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY 172180 0805 REF: AMM 35-00-03	MOS HRS/MSC AFL	O/C	O:6 O:0 O:0			25-APR-2016 3839.9 1974		
350008	DORSAL OXYGEN PRESSURE INDICATOR 820-707 353 REF: AMM 35-00-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
351001	PILOT OXYGEN MASK 174262-11 20925 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	O:0 O:0			07-FEB-2018 3852.6 1982		
351001A OVERHAUL	OVERHAUL PILOT OXYGEN MASK 174262-11 20925 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d			07-FEB-2018 3852.6 1982	01-DEC-2023 M	15-DEC-2023
351002	COPILOT OXYGEN MASK 174262-11 25970 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C				01-SEP-2017 3840.35 1975		
351002A OVERHAUL	OVERHAUL COPILOT OXYGEN MASK 174262-11 25970 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d			01-SEP-2017 3840.35 1975	01-SEP-2023	15-SEP-2023

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351025	OXYGEN SYSTEM PRESSURE SWITCH P24028 3369 REF: AMM 35-00-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-AUG-2006 148 115		
351071	PILOT CREW OXYGEN MASK BOX PN SN-UNKNOWN REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
351072	COPILOT CREW OXYGEN MASK BOX PN SN-UNKNOWN REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
352007	DORSAL OXYGEN CYLINDER 176194-76 K675301/0805 REF: AMM 35-00-01 LIFE LIMIT Manufacture Date: 01-OCT-2006	MOS HRS/MSC AFL	288	+14d/-14d			07-FEB-2018 3852.6 1982	01-OCT-2030	15-OCT-2030
352007A	HYDROSTATIC TEST DORSAL OXYGEN CYLINDER 176194-76 K675301/0805 REF: GENERIC NO REF	MOS HRS/MSC AFL	36	+14d/-14d		-18	25-FEB-2021	07-FEB-2024	21-FEB-2024
352027	PASSENGER OXYGEN CONTROL VALVE P21004-3 0196 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
352031	FORWARD SELECTOR, OXYGEN VALVE PN SN-UNKNOWN REF: AMM 35-00-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352032	AFT SELECTOR, OXYGEN VALVE PN SN-UNKNOWN REF: AMM 35-00-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
352033	RIGHT AFT SELECTOR, OXYGEN VALVE ZCV179 04-110657 REF: AMM 35-00-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
352040	PROTECTIVE BREATHING (PBE) EQUIPMENT 802300-14 E19080455 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+14d/-14d N:0 N:0 N:0	-7		07-FEB-2020 4291.5 2345	31-JAN-2030	14-FEB-2030
LIFE LIMIT									
353001	L1 OXYGEN MASK DROP BOX 833-812-02 0605 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
353002	R1 OXYGEN MASK DROP BOX 833-812-02 0607 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
353003	L2 OXYGEN MASK DROP BOX 833-812-01 1481 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
353004	R3 OXYGEN MASK DROP BOX 833-812-02 0592 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
353005	L3 OXYGEN MASK DROP BOX 833-812-01 1472 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
353006	R4 OXYGEN MASK DROP BOX 833-812-02 0606 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
353007	R2 OXYGEN MASK DROP BOX 833-812-01 1480 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
H3500020 (s)	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY. PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
P3510020 (s)	ON AIRCRAFT EQUIPPED WITH E.R.O.S. AVIATION CREW MASKS, PERFORM FUNCTIONAL TEST OF OXYGEN MASK. (REFER TO 35-10-01.) PKG 13 REF: AMM 35-10-01	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T3500000 (s)	FUNCTIONAL TEST OF OXYGEN SYSTEM. (REFER TO 35-00-00.) PKG 14 REF: AMM 35-00-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T3500010 (s)	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY. PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T3500040 (s)	CHECK CREW MEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) FOIL POUCH FOR VACUUM SEAL INTEGRITY. IF VACUUM SEAL IS BROKEN, REPLACE EQUIPMENT.						PKG		
	PKG 7	MOS	24	+14d/-14d			31-MAR-2022		
		HRS/MSC	600	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
CHAPTER 36 PNEUMATIC									
05-11-00-W3610011	REPLACE ENGINE BLEED AIR CHECK VALVES								
		MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: AMM 36-10-06	AFL					0		
360001	REPLACE LEFT ENGINE PYLON BLEED AIR SEALS								
		MOS					30-SEP-2008		
		HRS/MSC	O/C				1100.28		
	REF: AMM 36-10-01	AFL					595		
360002	REPLACE RIGHT ENGINE PYLON BLEED AIR SEALS								
		MOS					30-SEP-2008		
		HRS/MSC	O/C				1100.28		
	REF: AMM 36-10-01	AFL					595		
360003	REPLACE TAILCONE BLEED AIR SEALS (LOCATED BETWEEN THE FORWARD BLEED AIR MANIFOLD AND AFT BLEED AIR MANIFOLD) (REFER TO 36-10-01)								
		MOS					02-OCT-2008		
		HRS/MSC	N/A				1100.28		
NOT APPLICABLE	REF: AMM 36-10-01	AFL					595		
361001	NO. 1 BLEED AIR REGULATING/SHUTOFF VALVE								
	7608071-1	MOS					11-MAR-2006		
	417	HRS/MSC	O/C				0		
	REF: AMM 36-10-04	AFL					0		
361002	NO. 2 BLEED AIR REGULATING/SHUTOFF VALVE								
	7608071-1	MOS					11-MAR-2006		
	418	HRS/MSC	O/C				0		
	REF: AMM 36-10-04	AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361007	LEFT MIXING VALVE CONTROL BOX PN SN-UNKNOWN REF: AMM 36-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
361008	RIGHT MIXING VALVE CONTROL BOX PN SN-UNKNOWN REF: AMM 36-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
361011	LEFT BLEED AIR MIXING VALVE 1H106-9 10AH11 REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			16-FEB-2007 402.47 274		
361012	RIGHT BLEED AIR MIXING VALVE 1H106-9 12BA33 REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
361013	NO. 1 BLEED AIR CHECK VALVE 6C1005 2477 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
361014	NO. 2 BLEED AIR CHECK VALVE 6C1005 2478 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
361017	NO. 1 BLEED AIR (1 1/4) CHECK VALVE 1H95-8 3AP32 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			02-OCT-2008 1100.28 595		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361018	NO. 2 BLEED AIR (1 1/4) CHECK VALVE 1H95-8 10BA35 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
361037	* NO. 1 EMERGENCY AIR BOTTLE (AWL*) 23111425 898 REF: AMM 36-15-01 Manufacture Date: 01-JUL-2007	MOS HRS/MSC AFL APH ACH	180	N:117			13-APR-2017 3840.35 1975	01-JUL-2022	
361037A	PERFORM * NO. 1 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST 23111425 898 REF: AMM 36-15-01	MOS HRS/MSC AFL	36	+14d/-14d			07-OCT-2019 4237.4 2300	07-OCT-2022	21-OCT-2022
361037B	X-RAY INSPECT * NO. 1 EMERGENCY AIR BOTTLE 23111425 898 REF: AMM 36-15-01	MOS HRS/MSC AFL	36	+14d/-14d			07-OCT-2019 4237.4 2300	07-OCT-2022	21-OCT-2022
361038	* NO. 2 EMERGENCY AIR BOTTLE (AWL*) 23111425 906 REF: AMM 36-15-01 Manufacture Date: 01-OCT-2007	MOS HRS/MSC AFL APH ACH	180	N:114			13-APR-2017 3840.35 1975	01-OCT-2022	
361038A	PERFORM * NO. 2 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST 23111425 906 REF: AMM 36-15-01	MOS HRS/MSC AFL	36	+14d/-14d			07-OCT-2019 4237.4 2300	07-OCT-2022	21-OCT-2022
361038B	PERFORM * NO. 2 EMERGENCY AIR BOTTLE X-RAY INSPECTION 23111425 906 REF: AMM 36-15-01	MOS HRS/MSC AFL	36	+14d/-14d			07-OCT-2019 4237.4 2300	07-OCT-2022	21-OCT-2022

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361125	LEFT TAILCONE BLEED AIR CHECK VALVE M942-2 1252 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
361126	RIGHT TAILCONE BLEED AIR CHECK VALVE M942-2 1251 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
362001	LANDING GEAR/BRAKE AIR PRESSURE INDICATOR 820-666 494 REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
362003	PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER 124058-5000 42832 REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
362004	SECONDARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER 124058-5000 42833 REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
362011	NO. 1 ENGINE HI-LIMIT BLEED AIR THERMOSTAT PN SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
362012	NO. 2 ENGINE HI-LIMIT BLEED AIR THERMOSTAT PN SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
362019	NO. 1 INBOARD OVERHEAT SWITCH 6600213-5 000057 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
362020	NO. 2 INBOARD OVERHEAT SWITCH 6600213-5 000051 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
H3620001 (s)	FUNCTIONAL TEST OF PYLON OVERHEAT THERMOSTAT, DUCT TEMPERATURE SENSOR, AND ELECTRICAL SYSTEM. (REFER TO 36-20-03 AND 36-20-04.) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-FEB-2018 3852.6 1982	PKG	
J3610037 (s)	VISUALLY INSPECT HIGH PRESSURE BLEED AIR CHECK VALVES PKG 21 REF: AMM 36-10-06	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-FEB-2018 3852.6 1982	PKG	
L3610039 (s)	PERFORM OPERATIONAL CHECK OF BLED AIR CHECK VALVES. (REFER TO 36-10-03). PKG 9 REF: AMM 36-10-03	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815	PKG	
U3610044 (s)	GENERAL VISUAL INSPECTION BLEED AIR DUCTING (INCLUDING CLAMPS AND VALVES). (REFER TO 5-10-00) PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815	PKG	
CHAPTER 38	WATER/WASTE								
381008	LAVATORY SINK FAUCET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381009	FORWARD TOILET DRAIN, HEATED MAST 116393-101 1756 REF: AMM 38-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
381010	AFT TOILET DRAIN, HEATED MAST 116393-101 1792 REF: AMM 38-32-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
381020	TOILET WATER PUMP 5250-10 P6614 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-JAN-2010 1535.15 835		
381030	TOILET TIMER 9060-2 T4312 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
381050	TOILET MACERATOR 5300-1 M6307 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				05-SEP-2020 4468.9 2486		
381060	LAVATORY ON-DEMAND WATER SYSTEM VOLTAGE REGULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
381070	LAVATORY SINK PUMP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
382015	NO. 1 HOT WATER TANK H60WC-02001-1 187 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				24-JUN-2013 2995.73 1605		
382016	NO. 2 HOT WATER TANK H60WC-02001-1 137 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
383101	LAVATORY TOILET ASSEMBLY 9060-10 U2921 REF: AMM 38-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
CHAPTER 49 AIRBORNE AUXILIARY POWER									
490101	COCKPIT APU CONTROL PANEL 201-6-035-9 5238-17 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
490102	APU RELAY BOX 201-6-028-9 5238-004 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
490103	(ESU / DESU) ELECTRONIC SEQUENCE UNIT 160935-203B 0214 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			06-SEP-2007 670.02 392		
490105	APU (GCU) GENERATOR CONTROL UNIT 505-16G 1165C REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
490106	BITE ANNUNCIATOR BOX 161212-100 0523-0785 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
490109	UPPER CURRENT TRANSFORMER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
490110	LOWER CURRENT TRANSFORMER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
490111	CURRENT SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
493101	APU FUEL SHUTOFF VALVE EM91-41 04-101474 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
493102	APU FUEL BOOST PUMP 1500-00-22 2227 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:3 O:0 O:0			22-NOV-2013 3076.45 1651		
496103	APU FIRE HORN PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
498010	EXHAUST (APU) DUCT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
49APU1 49.APU1	APU 4503134 SP-E050424 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C						
APU Model : T-20G-10C3A (CIMMS) Serial # SP-E050424 Part # 4503134									
490020	APU - ESU - ELECTRONIC SENSOR UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
490030	APU - SEAL PLATE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
490102	APU - BYTE BOX 161212-100 0542-0789 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
490103	APU - ELECTRONIC SENSOR (ESU) UNIT 160935-2038 0214 REF:	MOS HRS/MSC APUS	O/C	R:0 R:0 R:0			07-FEB-2018 1871 2703		
492001	APU - COMBUSTOR HOUSING ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
492002	APU - APU EXHAUST THERMOCOUPLE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492010	APU - TURBINE NOZZLE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492020	APU - IGNITER CH38013 NSN REF:	MOS HRS/MSC APUS	O/C	N:18 N:0 N:0			17-OCT-2014		
492030	APU - OUTPUT GEAR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492040	APU - BITE BOX PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492050	APU - SHAFT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492201	APU - ROTOR BEARING 161623-1 F013 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
492202	APU - ROTOR BEARING 161623-1 FO18 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492207	APU - HOUSING BEARING SUPPORT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492208	APU - BEARING HOUSING ADAPTER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492300	APU - PRESSURE (LOW OIL) SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
492320	APU - SPEED (MAGNETIC PICK-UP) SENSOR 169080-1 B248 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
493001	APU - FUEL CONTROL 160962-6 14498041 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
493003	APU - PUMP ASSEMBLY, FUEL CONTROL 4502863D 12-03-18 REF:	MOS HRS/MSC APUS	O/C	R:0 R:0 R:0			13-SEP-2011 1345 1725		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493005	APU - FUEL ATOMIZER INTERCONNECT HARNESS 4505684 V28-S103 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
493007	APU - ASSEMBLY, FUEL ATOMIZER 4504283A 12-02-22 REF:	MOS HRS/MSC APUS	O/C				17-OCT-2014		
493010	APU - HARNESS PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
493055	APU - ATOMIZER CUP MOTOR 4951372 M475 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
493102	APU - FUEL PUMP 161627-2 V60T0390 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
494001	APU - IGNITION EXCITER 4951302 05451025 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
495001	APU - TURBINE WHEEL 164253-3 HA549 REF:	MOS HRS/MSC APUS		N:0 N:0 N:0			30-DEC-2005 0 0		
LIFE LIMIT			3500					3500	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
495005	APU - COMPRESSOR WHEEL 160915-4 H961A	MOS HRS/MSC		N:0 N:0			30-DEC-2005 0		
LIFE LIMIT	REF:	APUS	7000	N:0			0	7000	
495010	APU - AIR INLET HOUSING PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			30-DEC-2005 0		
	REF:	APUS		N:0			0		
497010	APU - HOURMETER/EVENT COUNTER INDICATOR PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			30-DEC-2005 0		
	REF:	APUS		N:0			0		
499010	APU - OIL PUMP GEAR PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			30-DEC-2005 0		
	REF:	APUS		N:0			0		
CHAPTER 52 DOORS									
05-10-29-L5210025	VISUAL INSPECTION EXTERIOR LWR DOOR STRUCTURE/HINGE FOR CORROSION	MOS HRS/MSC	24	+14d/-14d			08-JUL-2021 4712.9	08-JUL-2023	22-JUL-2023
	REF: GENERIC NO REF	AFL					2660		
521001	UPPER PASSENGER/CREW DOOR 5410501-127 242	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF: AMM 52-10-00	AFL		N:0			0		
521002	LOWER PASSENGER/CREW DOOR 5410536-032 W350	MOS HRS/MSC	O/C	N:0 N:0			11-MAR-2006 0		
	REF: AMM 52-10-00	AFL		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521003	UPPER PASSENGER/CREW DOOR HANDLE 6600480-1 363 REF: AMM 52-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
521004	UPPER PASSENGER/CREW DOOR LOCK ASSEMBLY AS848 SG5954071 REF: AMM 52-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
+ 5210054	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE - REPLACE REF: See Workcard	MOS HRS/MSC AFL	144 O/C 6000	+14d/-14d +25/-25		-69	08-JUL-2021 4712.9 2660	30-APR-2033 8660	14-MAY-2033 8685
521006	UPPER PASSENGER/CREW DOOR DAMPER PN SN-UNKNOWN REF: AMM 52-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
521008	LOWER PASSENGER/CREW DOOR HANDLE PN SN-UNKNOWN REF: AMM 52-10-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
521010	FORWARD PASSENGER/CREW LOWER DOOR CABLE 6015550-001 SN-UNKNOWN REF: AMM 52-10-10	MOS HRS/MSC AFL	O/C				07-FEB-2018 3852.6 1982		
521011	AFT PASSENGER/CREW LOWER DOOR CABLE PN SN-UNKNOWN REF: AMM 52-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521012	LOWER PASSENGER/CREW DOOR DAMPER 6600425-2 1140 REF: AMM 52-10-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
522000	EMERGENCY EXIT / BAGGAGE DOOR 6011501-015 W313 REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
522002	EMERGENCY EXIT / BAGGAGE DOOR HANDLE PN SN-UNKNOWN REF: AMM 52-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
522005	PASSENGER DOOR FORWARD SNUBBER PN SN-UNKNOWN REF: AMM 52-10-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
522006	PASSENGER DOOR AFT SNUBBER PN SN-UNKNOWN REF: AMM 52-10-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
522007	EMERGENCY EXIT DOOR FORWARD SNUBBER PN SN-UNKNOWN REF: AMM 52-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
522008	EMERGENCY EXIT DOOR AFT SNUBBER PN SN-UNKNOWN REF: AMM 52-20-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
522025	EMERGENCY EXIT/BAGGAGE DAMPER PN SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
522032	EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY PN SN-UNKNOWN REF: AMM 52-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
522032A	PRISM CHECK EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY 05-10-29-M5600008 PN SN-UNKNOWN REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				11-MAR-2006 0 0		
523101	TAILCONE BAGGAGE DOOR 6011552-17 575437 REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
523102	TAILCONE BAGGAGE HANDLE 6600480-2 348 REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
524001	PERFORM AFT AVIONICS DOOR GAP AND MISMATCH INSPECTION (RVSM) (REFER TO 52-40-01) REF: AMM 52-40-01	MOS HRS/MSC AFL	24	+14d/-14d		-53	31-MAR-2022 4901.4 2815	07-FEB-2024	21-FEB-2024
524003	LEFT FORWARD NOSE AVIONICS DOOR 6010430-003-903 0263 REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
524004	RIGHT FORWARD NOSE AVIONICS DOOR 6010430-004-904 0263 REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
524005	LEFT AFT NOSE AVIONICS DOOR 6010431-003-903 0263 REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
524006	RIGHT AFT NOSE AVIONICS DOOR 6010431-004-904 0263 REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
524007	TAILCONE AVIONICS DOOR PN SN-UNKNOWN REF: AMM 52-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
527005	CREW DOOR WARNING BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
527006	EMERGENCY EXIT DOOR WARNING BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
528001	LEFT INBOARD MAIN LANDING GEAR DOOR PN SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
528002	RIGHT INBOARD MAIN LANDING GEAR DOOR PN SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
528003	LEFT OUTBOARD MAIN LANDING GEAR DOOR 6022151-801 NSN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			21-FEB-2014 3143.92 1686		
528004	RIGHT OUTBOARD MAIN LANDING GEAR DOOR PN SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
528101	LEFT NOSE LANDING GEAR DOOR 5410450-19 60-300 REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
528102	RIGHT NOSE LANDING GEAR DOOR 5410450-20 60-300 REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
A5210030 (s)	REMOVE TENSION FITTINGS AND PLATES FROM PASSENGER/CREW DOORS (SIX [6] IN EACH DOOR). MAGNETIC PARTICLE INSPECT FOR EVIDENCE OF CRACKS. (REFER TO NDI MANUAL [NDI-2], PART 6, 52-10-01 AND 53-10-01.) PKG 25 REF: See Workcard	MOS HRS/MSC AFL					11-MAR-2006 0 0	PKG	
AA5210056 (s)	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION PKG 18 REF: AMM 12-21-03	MOS HRS/MSC AFL		48 1200	+14d/-14d +25/-25		31-MAR-2022 4901.4 2815	PKG	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C5210052 (s)	UPPER AND LOWER DOOR HANDLE MECHANISM: GAIN ACCESS TO UPPER AND LOWER DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION. PKG 27	MOS	144	+14d/-14d			07-FEB-2018 3852.6 1982		
	REF: GENERIC NO REF	AFL	6000	+25/-25					
C5220021 (s)	EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM; GAIN ACCESS TO EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION. PKG 27	MOS	144	+14d/-14d			07-FEB-2018 3852.6 1982		
	REF: NDT 52-60-01	AFL	6000	+25/-25					
E5220010 (s)	EMERGENCY EXIT/BAGGAGE DOOR HINGE INSTALLATION FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT HINGE INSTALLATIONS WHILE RACKING THE DOOR WITH ALTERNATING LOADS. PKG 18	MOS	48	+14d/-14d			31-MAR-2022 4901.4 2815		
	REF: AMM 52-20-00	AFL	1200	+25/-25					
E5220020 (s)	EMERGENCY EXIT/BAGGAGE DOOR HANDLE AND CONTROL ASSEMBLY FREE PLAY CHECK. OPEN DOOR AND REMOVE UPHOLSTERY TO GAIN ACCESS TO ROD CONTROL ASSEMBLY. RESTRAIN THE DOOR PINS AND MOVE THE EMERGENCY EXIT/BAGGAGE DOOR HANDLE TOWARD THE CLOSED POSITION AND THEN TO PKG 18	MOS	48	+14d/-14d			31-MAR-2022 4901.4 2815		
	REF: AMM 52-20-00	AFL	1200	+25/-25					
E5280002 (s)	VISUALLY INSPECT TAILCONE AVIONICS AND BAGGAGE DOOR ELECTRICAL BONDING JUMPERS, WHEN INSTALLED, FOR SECURITY AND GENERAL CONDITION PKG 6	MOS	12	+14d/-14d			31-MAR-2022 4901.4 2815		
	REF: GENERIC NO REF	AFL	300	+25/-25					
H5210020 (s)	UPPER AND LOWER DOOR HINGE INSTALLATIONS FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT EDGES OF HINGE INSTALLATION WHILE RACKING THE DOORS WITH ALTERNATING LOADS. IF HINGE INSTALLATION CONDITION REQUIRES A MORE THO PKG 24	MOS	96	+14d/-14d			07-FEB-2018 3852.6 1982		
	REF: GENERIC NO REF	AFL	2400	+25/-25					

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H5210040 (s)	CLEAN ARM GUIDES OF PASSENGER/CREW UPPER DOOR AND VISUALLY CHECK FOR CRACKS. (SEE FIGURE 1.) PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H5210060 (s)	INSPECT ENTIRE LENGTH OF LOWER DOOR CABLES FOR EVIDENCE OF FRAYING OR OTHER DAMAGE. DOOR ACCESS PANELS MUST BE REMOVED. (REFER TO 52-10-10) PKG 12 REF: AMM 52-10-10	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H5210065 (s)	CLEAN LATCH ARM OF PASSENGER/CREW LOWER DOOR AND VISUALLY INSPECT FOR CRACKS. (SEE FIGURE 1.) PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H5210086 (s)	CHECK LOWER CABIN DOOR MECHANISM. OPEN UPPER AND LOWER CABIN DOORS. MOVE LOWER DOOR HANLE TOWARD THE DOOR PIN MOVEMENT. CHECK FOR SECURITY AND FREE PLAY IN MECHANISM. EXCESSIVE FREE PLAY MAY BE DUE TO MECHANISM FAILURE, EXCESSIVE WEAR, OR DEFORMATION. CHECK DOO PKG 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
H5280001 (s)	VISUALLY INSPECT INBOARD AND OUTBOARD MAIN LANDING GEAR DOOR BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00) PKG 11 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
K5210070 (s)	EDDY CURRENT INSPECT AROUND LOWER CABIN DOOR LATCH ARM FASTENERS AND PERIPHERY OF ARM PIN EYES FOR CRACKS. (REFER TO NDI MANUAL [NDI-2], PART 3, 52-10-01.) PKG 27 REF: NDT 52-10-01	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5210042 (s)	INSPECT CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR SEALS FOR ADHESIONS, CUTS, AND ABRASION; LATCH FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY. PKG 12 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
T5230011 (s)	VISUALLY INSPECT AVIONICS DOORS, HINGES, AND FASTENERS FOR GENERAL CONDITION, PROPER FIT, SEALS, ELECTRICAL BONDING, AND GENERAL CONDITION. PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
T5240002 (s)	VISUAL INSPECTION SINGLE POINT REFUELING DOOR. (REFER TO 5-10-00) PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
T5280000 (s)	VISUALLY INSPECT EMERGENCY EXIT/BAGGAGE DOOR ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00). PKG 12 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
T5280003 (s)	VISUALLY INSPECT NOSE AVIONICS DOOR AND NOSE LANDING GEAR DOOR ELECTRICAL BONDING JUMPERS FRO SECURITY AND GENERAL CONDITION. PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
CHAPTER 53 FUSELAGE									
05-10-29-Y5331017	INSPECTION OF UPPER FUSELAGE SKIN UNDER THE AFT OXYGEN LINE FAIRING REF: AMM 53-50-06	MOS HRS/MSC AFL	144	+14d/-14d			(EBT)	06-OCT-2028	20-OCT-2028
05-10-30-RVSM-N5313000	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (RVSM) (REFER TO 53-11-01) REF: AMM 53-11-01	MOS HRS/MSC AFL	24	+14d/-14d	-53		31-MAR-2022 4901.4 2815	07-FEB-2024	21-FEB-2024

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-T5322000	REPLACE KEELBEAM ATTACHMENT BOLTS	MOS	144	+14d/-14d			07-FEB-2018 3852.6	07-FEB-2030	21-FEB-2030
	REF: AMM 53-10-02	AFL	6000	+25/-25			1982	7982	8007
534001	NO. 1 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING	PN					11-MAR-2006		
	SN-UNKNOWN	MOS					0		
	REF: AMM 53-40-02	AFL					0		
534002	NO. 2 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING	PN					11-MAR-2006		
	SN-UNKNOWN	MOS					0		
	REF: AMM 53-40-02	AFL					0		
534003	NO. 1 ENGINE AFT ENGINE MOUNT ATTACH FITTING	PN					11-MAR-2006		
	SN-UNKNOWN	MOS					0		
	REF: AMM 53-40-02	AFL					0		
534004	NO. 2 ENGINE AFT ENGINE MOUNT ATTACH FITTING	PN					11-MAR-2006		
	SN-UNKNOWN	MOS					0		
	REF: AMM 53-40-02	AFL					0		
535001	RADOME	5410420-801					07-SEP-2012		
	0235	MOS					2852.1		
	REF: AMM 53-50-01	AFL					1527		
A5321060 (s)	WING/FUSELAGE FITTINGS: CLEAN AND VISUALLY INSPECT ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE). USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, VISUALLY INSPECT FITTINGS AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHE	PKG 28					11-MAR-2006		
		MOS	12000	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
AA5323107 (s)	CIRCUMFERENTIAL SKIN SPLICES - CONDUCT AN X-RAY INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW: A. FRAMES 17, 20, 25, 26 AND 30. B. ON AIRCRAFT 60-002, FRAME 12. C. ON AIRCRAFT 60-003 AND SUBSEQUENT, FRAME 13. D. ON AIRCRAFT 60-002 THRU 60-093, FRAME 20B. CONDUCT SPECIFIC X-RAY INSPECTIONS OF THE CIRCUMFERENTIAL SKIN SPLICES IN THE PRESSURE CABIN ACROSS THE TOP OF THE FUSELAGE FROM STRINGER 8L TO 8R.						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: See Workcard	AFL						0	
B5331030 (s)	TAILCONE STRUCTURE (REFER TO 5-10-00.): CONDUCT A VISUAL INSPECTION OF THE TAILCONE STRUCTURE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. FROM THE TAILCONE ACCESS DOOR OPENING, VISUALLY INSPECT ACCESSIBLE AREAS						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
C5314011 (s)	BELOW FLOORBOARD INSPECTION INSPECT FOR CORROSION, GENERAL CONDITION, AND FATIGUE CRACKS.						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
C5314040 (s)	EMERGENCY EXIT/BAGGAGE DOOR FUSELAGE FRAMING STRUCTURE: CONDUCT X-RAY INSPECTION OF FUSELAGE DOOR FRAMING STRUCTURE IN AREA OF BORDERING INNER SKIN. PAY PARTICULAR ATTENTION TO HINGES, HINGE ATTACHMENTS, CORNER DOUBLERS, AND THE LATCH PIN AND RECEPTACLE S						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: NDT 52-60-01	AFL	6000	+25/-25				1982	
C5321000 (s)	FUSELAGE FRAMES AND STRINGERS: GAIN ACCESS TO ALL FUSELAGE FRAMES AND STRINGERS FROM FRAME 6 TO AFT PRESSURE BULKHEAD. CONDUCT AN INTERIOR VISUAL INSPECTION OF ALL FUSELAGE FRAMES AND STRINGERS. PARTICULAR ATTENTION SHOULD BE GIVEN TO ALL FRAME SPLICES. I						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
C5321040 (s)	WITH WING/FUSELAGE FAIRINGS REMOVED, USE FLASHLIGHT AND MIRROR TO VISUALLY INSPECT THE HONEYCOMB SUPPORT ANGLE SEGMENTS AT THE OUTBOARD ENDS OF THE FORWARD BAGGAGE FLOOR FOR FATIGUE CRACKS, CORROSION, FASTENER SECURITY, AND GENERAL CONDITION						PKG		
	PKG 25	MOS						11-MAR-2006	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	3000	+25/-25				0	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C5321055 (s)	WING-TO-FUSELAGE ATTACHMENT FITTINGS: CLEAN AND VISUALLY INSPECT WITH THE AID OF 10X MAGNIFICATION, FLASHLIGHT, AND MIRROR, ALL EIGHT WING-TO-FUSELAGE ATTACHMENT FITTINGS. INSPECT FITTINGS AND SUPPORT STRUCTURE FOR CRACKS, CORROSION, MARKS, SCRATCHES, FAS						PKG		
	PKG 27	MOS	144	+14d/-14d			07-FEB-2018	3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25			1982		
D5321020 (s)	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. TAP-TEST FLOOR PANEL, WHICH SUPPORTS THE ELECTRICAL EQUIPMENT, TO CHECK FOR UNBONDING OF UPPER SURFACE PLATE FROM THE HONEYCOMB CORE STRUCTURE. VISUALLY INSPECT FOR CORROSION, PARTICULARLY IN THE						PKG		
	PKG 25	MOS					11-MAR-2006	0	
	REF: GENERIC NO REF	AFL	3000	+25/-25			0		
D5350020 (s)	INSPECT UNDER WING KEELBEAM AND ATTACHMENTS FOR SECURITY, CORROSION, FASTENER CONDITION, FATIGUE CRACKS, AND PERMANENT DEFORMATION. ALSO INSPECT ATTACHING FITTINGS, FORWARD OF FRAME 24 AND AFT OF FRAME 31, FOR SIMILAR EFFECTS.						PKG		
	PKG 27	MOS	144	+14d/-14d			07-FEB-2018	3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25			1982		
D5350051 (s)	UNDERWING KEEL BEAM: VISUALLY INSPECT REMOVED ASSEMBLY FOR CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO END FITTINGS COMMON TO BEAM ASSEMBLY AS WELL AS THOSE MATING FITTINGS FORWARD OF FRAME 24 AND AFT OF FRAME 31. (REFER						PKG		
	PKG 28	MOS					11-MAR-2006	0	
	REF: GENERIC NO REF	AFL	12000	+25/-25			0		
F5350010 (s)	VISUALLY INSPECT KEELBEAM, FORWARD AND AFT ATTACH FITTINGS ON KEELBEAM AND ON AIRCRAFT, FOR CRACKS AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			07-FEB-2018	3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25			1982		
G5321021 (s)	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. VISUALLY INSPECT FLOOR PANEL WHICH SUPPORTS THE ELECTRICAL EQUIPMENT AND FRAMES 25, 26, AND 26A FOR CORROSION AND ANY OTHER DAMAGE.						PKG		
	PKG 8	MOS	24	+14d/-14d			31-MAR-2022	4901.4	
	REF: GENERIC NO REF	AFL	600	+25/-25			2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G5321079 (s)	AFT PRESSURE BULKHEAD REMOVE FUEL BLADDER AND VISUALLY INSPECT BULKHEAD FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, OR OTHER DAMAGE. VISUALLY INSPECT SUPPORTING STRUCTURE ALONG FLOOR, FRAME PERIPHERY, AND CENTERLINE BEAM FOR FATIGUE CRACKS, FASTENER SECURI PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
H5230020 (s)	INSPECT TAILCONE EQUIPMENT ACCESS AND TAILCONE BAGGAGE COMPARTMENT DOOR SEALS FOR CUTS, ADHESION, AND ABRASION; LOCKING MECHANISM FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY. PKG 12 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H5311000 (s)	INSPECT NOSE GEAR SUPPORT INSTALLATION FOR SECURITY, FASTENER CONDITION, PANEL FATIGUE CRACKS, PERMANENT DEFORMATION AT TRUNNION FITTINGS, ACTUATOR ATTACHMENT SUPPORT STRUCTURE AREAS, AND GENERAL CONDITION. PKG 23 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
H5314031 (s)	FRAMING MEMBERS OF PASSENGER/CREW AND EMERGENCY EXIT/BAGGAGE DOORS AND SURROUNDING FUSELAGESTRUCTURE FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. PKG 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
H5321014 (s)	IF INSTALLED, INSPECT ACCESSIBLE AREAS AROUND THE GALLEY, POTTY, AND LAVATORY FOR EVIDENCE OF SPILLAGE. INVESTIGATE FURTHER IF EVIDENCE OF SPILLAGE IS FOUND. PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H5321039 (s)	VISUALLY INSPECT LOWER LONGERON IN REGION OF WING FOR FATIGUE CRACKS, PERMANENT DEFORMATION, AND GENERAL CONDITION. PKG 23 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H5321042 (s)	BAGGAGE FLOOR/OVER WING AREA: A. INSPECT ENTIRE AREA FOR CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT THE SEGMENTED HONEYCOMB FLOOR SUPPORT ANGLES AT THE OUTBOARD EDGES FOR FATIGUE CRACKS, FASTENER SECURITY, AND GENERAL CONDITION. B. INSPECT FRAME						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
H5321048 (s)	BAGGAGE FLOOR/OVER WING AREA (REFER TO 5-10-00.) A. SUPPORT STRUCTURE FOR WING-TO-FUSELAGE FITTINGS. AT EACH LOCATION (SPAR/FRAME) 2/25, 5/27, 7/29, AND 8/30)8 LOCATIONS TOTAL) INSPECT FUSELAGE FRAME STRUCTURE FOR CRACKS, CORROSION, FASTENER CONDITION, P						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
H5321049 (s)	VISUALLY INSPECT OVERWING CUTOUT RADIUS AT FS 346 AND FS 421 (FRAMES 24 AND 31 FUSELAGE SKIN PANELS). (REFER TO 5-10-00.)						PKG		
	PKG 20	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: GENERIC NO REF	AFL						1982	
H5321050 (s)	INSPECT ACCESSIBLE PORTIONS OF LOWER CAP OF THE FRAME 26A AREA, AND ADJACENT FLOOR STRUCTURE, FRAME 24-26A. VISUALLY INSPECT FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 17	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
H5323011 (s)	INSPECT CORNER OF DOORS FOR FASTENER SECURITY AND GENERAL CONDITION.						PKG		
	PKG 12	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
H5331010 (s)	INSPECT BULKHEADS, FRAMES, AND STIFFENERS IN THE TAILCONE FOR FASTENER SECURITY, CRACKS, AND GENERAL CONDITION.						PKG		
	PKG 21	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: GENERIC NO REF	AFL						1982	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H5331020 (s)	INSPECT CANTED BULKHEADS AND LOWER VERTICAL STABILIZER ATTACHMENTS IN THE AFT TAILCONE FOR FASTENER SECURITY AND PERMANENT DEFORMATION AT BULKHEADS AND SPAR ASSEMBLIES. PKG 21	MOS	96	+14d/-14d			07-FEB-2018		
	REF: GENERIC NO REF	AFL	2400	+25/-25			3852.6		1982
J5340001 (s)	EDDY CURRENT FORWARD BEAM SUPPORT FITTING. (REFER TO NDI MANUAL [NDI-2], PART 3, 53-40-01.) PKG 28	MOS					11-MAR-2006		
	REF: NDT 53-40-01	AFL	12000	+25/-25			0		0
J5340002 (s)	VISUAL INSPECTION FORWARD ENGINE BEAM ASSEMBLY. (REFER TO 5-10-00.) PKG 28	MOS					11-MAR-2006		
	REF: GENERIC NO REF	AFL	12000	+25/-25			0		0
J5340003 (s)	VISUAL INSPECTION FORWARD ENGINE BEAM STABILIZER STRUCTURE. (REFER TO 5-10-00.) PKG 28	MOS					11-MAR-2006		
	REF: GENERIC NO REF	AFL	12000	+25/-25			0		0
J5340004 (s)	EDDY CURRENT AFT BEAM SUPPORT FITTING - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 53-40-02.) PKG 28	MOS					11-MAR-2006		
	REF: NDT 53-40-02	AFL	12000	+25/-25			0		0
J5340005 (s)	VISUAL INSPECTION AFT ENGINE BEAM - PERFORM VISUAL INSPECTION. (REFER TO 5-10-00.) PKG 28	MOS					11-MAR-2006		
	REF: GENERIC NO REF	AFL	12000	+25/-25			0		0
J5340006 (s)	VISUAL INSPECTION AFT ENGINE BEAM AND FRAME STRUCTURE - PERFORM VISUAL INSPECTION. (REFER TO 5-10-00.) PKG 28	MOS					11-MAR-2006		
	REF: GENERIC NO REF	AFL	12000	+25/-25			0		0

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
K5321081 (s)	VISUALLY INSPECT FORWARD PRESSURE BULKHEAD FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION. PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
L5321085 (s)	FORWARD PRESURE BULKHEAD: VISUALLY INSPECT FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION. GAIN ACCESS TO THE FORWARD SIDE OF THE FORWARD PRESSURE B PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
M5323065 (s)	CIRCUMFERENTIAL SKIN SPLICES: CONDUCT A GENERAL VISUAL INTERNAL AND EXTERNAL INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW: A. FRAMES 8, 17, 20, 25, AND 26. B. ON AIRCRAFT 60-002, FRAME 12. C. ON AIRCRAFT 60-003 AND SUBSEQUENT, PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
M5323106 (s)	LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) : A. CONDUCT AN INTERNAL AND EXTERNAL VISUAL INSPECTION OF THE LONGITUDINAL SKIN SPLICES ALONG THE MAIN "T" STRINGERS AT STRINGERS 4L, 6L, 7AL, 18L, 23L, 2R, 6R, 8R, AND 18R. (REFER TO 5-10-00.) PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
M5323108 (s)	LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) - PERFORM AN X-RAY INSPECTION OF THE LONGITUDIAL SKIN SPLICES ALONG THE "T" STRINGERS AT STRINGERS 4L, 6L, 18L, 23L, 2R, 6R, AND 18R. (REFER TO NDI MANUAL [NDI-2], PART 2, CHAPTER 53-20-05, 53-20-06, 53-20-07, 53 PKG 28 REF: See Workcard	MOS HRS/MSC AFL	12000	+25/-25			PKG 11-MAR-2006 0 0		
N5323010 (s)	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00) PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N5323012 (s)	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00) PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
O5331035 (s)	REMOVE TAIL CONE ACCESS PLATES AND USE A FLASHLIGHT AND MIRROR TO INSPECT INTERNAL TAIL CONE STRUCTURE IN AREA WHERE THE VERTICAL STABILIZER SPARS ATTACH TO THE CANTED FUSELAGE FRAMES. CHECK FOR ATTACHMENT SECURITY, FRAME CRIPPLING, CORROSION, AND FATIGUE CRACKS PKG 28 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 11-MAR-2006 0 0		
P5311006 (s)	REMOVE NOSE GEAR TRUNNION FITTINGS AND VISUALLY INSPECT NOSE GEAR TRUNNION FITTING AREA IN FORWARD FUSELAGE FOR CRACKS, CORROSION, AND PERMANENT DEFORMATION. EDDY CURRENT INSPECT NOSE GEAR TRUNNION FITTING ATTACH HOLES AND TRUNNION AXLE BOSS. (REFER TO NDI MANUA PKG 26 REF: NDT 53-61-02	MOS HRS/MSC AFL	6000	+25/-25			PKG 11-MAR-2006 0 0		
P5311007 (s)	EDDY CURRENT INSPECT UPPER ATTACHEMNET AREA OF NOSE GEAR ACTUATOR FOR CRACKS, CORROSION, PERMANENT DEFORMATION, AND ATTACHMENY FITTING SECURITY. (REFER TO NDI MANUAL [NDI-2], PART 3, 56-60-01.) PKG 27 REF: NDT 53-60-01	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
P5320008 (s)	INSPECT CENTER PEDESTAL AND EQUIPMENT FOR SECURITY AND GENERAL CONDITION. SPOILER, THROTTLE, AND FLAP CONTROLS FOR GENERAL CONDITION AND SERVICEABILITY. PKG 1 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
P5321087 (s)	AFT PRESSURE BULKHEAD A. GAIN ACCESS TO AND REMOVE AFT PRESSURE BULKHEAD. B. EDDY CURRENT INSPECT THE FORWARD FRAME FLANGE OF FRAM 26A AFT PRESSURE BULKHEAD. (REFER TO NDI MANUAL [NDI-2], PART 3, CHAPTER 53-20-01 AND 53-20-05.) C. EDDY CURRENT INSPECT SUP PKG 28 REF: See Workcard	MOS HRS/MSC AFL	12000	+25/-25			PKG 11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5323162 (s)	VISUALLY INSPECT EXTERNAL LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR EVIDENCE OF FATIGUE CRACKS, WORKING RIVETS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 25	MOS						11-MAR-2006	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	3000	+25/-25				0	
S5230021 (s)	OPERATIONAL CHECK OF TAILCONE BAGGAGE AND TAILCONE ACCESS DOOR WARNING SYSTEMS. (REFER TO 52-70-00).						PKG		
	PKG 12	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: AMM 52-70-00	AFL						2815	
S5314070 (s)	UPPER AND LOWER CABIN DOOR HINGES AND FUSELAGE FRAMING STRUCTURE: A. VISUALLY INSPECT ACCESSIBLE STRUCTURE FOR SECURITY, GENERAL CONDITION, EXCESSIVE WEAR OR LOOSENESS, AND FATIGUE CRACKS. (REFER TO 5-10-00.) B. CONDUCT X-RAY INSPECTION OF UPPER AND LOWER						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: NDT 52-20-01	AFL	6000	+25/-25				1982	
S5323158 (s)	INSPECT EXTERIOR OF THE SKIN, GIVING PARTICULAR ATTENTION TO LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR FASTENER CONDITION, FATIGUE CRACKS, AND GENERAL SPLICE CONDITION.						PKG		
	PKG 20	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: GENERIC NO REF	AFL						1982	
T5321013 (s)	INSPECT ACCESSIBLE PORTION OF FRAME 26A AREA VISIBLE THROUGH WHEEL WELLS FOR FATIGUE CRACKS, PERMANENT DEFORMATION, SECURITY, AND GENERAL CONDITION.						PKG		
	PKG 11	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T5321093 (s)	INSPECT TAILCONE BAGGAGE COMPARTMENT UPHOLSTERY FOR CUTS, TEARS , AND GENERAL CONDITION.						PKG		
	PKG 15	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U5323146 (s)	SKIN CUTOUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT SKIN PENETRATIONS AND CUTOUTS FOR ANTENNAS AND ELECTRICAL COMPONENTS. (REFER TO 5-10-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			07-FEB-2018		
		HRS/MSC					3852.6		
	REF: GENERIC NO REF	AFL	6000	+25/-25			1982		
U5331012	* REMOVE ACCESS PANELS (TOP OF FUSELAGE) AND PERFORM VISUAL INSPECTION OF ELECTRICAL BOXES FOR SECURITY OF ATTACHMENT, CORROSION, AND GENERAL CONDITION. INSPECT DOUBLERS, FUSELAGE SKIN, INTERIOR FRAMES, AND INTERCOSTALS FOR FATIGUE CRACKS AND GENERAL CONDITION. (AWL*)								
		MOS	49				08-JUL-2021	08-AUG-2025	
		HRS/MSC					4712.9		
AIRWORTHINESS	REF: GENERIC NO REF	AFL					2660		
U5360005 (s)	GENERAL VISUAL INSPECTION RADOME AND LIGHTNING DIVERter STRIPS. (REFER TO 5-10-00)						PKG		
	PKG 2	MOS	12	+14d/-14d			31-MAR-2022		
		HRS/MSC	300	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
CHAPTER 54 NACELLES/PYLONS									
H5450000 (s)	CHECK PYLON FIREWALLS FOR CRACKS, CONDITION OF FIREWALL SEALANT, SECURITY OF HYDRAULIC AND FUEL CONNECTIONS, ELECTRICAL AND MECHANICAL FEED-THROUGHS, AND CONDITION OF BLEED AIR FLANGE GASKETS.						PKG		
	PKG 9	MOS	24	+14d/-14d			31-MAR-2022		
		HRS/MSC	600	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
H5450002 (s)	VISUAL INSPECTION ENGINE SUPPORT STRUCTURE. (REFER TO 5-10-00.)						PKG		
	PKG 28	MOS					11-MAR-2006		
		HRS/MSC	12000	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		
K5450010 (s)	INSPECT PYLON BEAMS FOR CRACKS, FASTENER CONDITION, ATTACHMENT TO FUSELAGE FRAMES, AND GENERAL CONDITION OF FITTINGS. REMOVE UPPER AND LOWER PYLON ACCESS COVERS FOR COMPLETE INSPECTION.						PKG		
	PKG 15	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
CHAPTER 55 STABILIZERS									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5520020 (s)	ELEVATOR (REMOVED FROM HORIZONTAL STABILIZER) (REFER TO 5-10-00.): A. CLEAN HINGE LOCATIONS AND VISUALLY INSPECT LOCAL STRUCTURE USING PROPER LIGHTING AND 10X MAGNIFICATION. INSPECT HINGE SUPPORT STRUCTURE FOR DEFORMATION, CORROSION, LOOSE OR WORKING FAST						PKG		
	PKG 28	MOS						11-MAR-2006	
	REF: NDT 55-20-01	HRS/MSC AFL	12000	+14/-14				0	0
553001	VERTICAL STABILIZER								
	5431000-030	MOS						11-MAR-2006	
	W498	HRS/MSC	O/C					0	
	REF: GENERIC NO REF	AFL						0	
A5510061 (s)	HORIZONTAL STABILIZER (DETACHED FROM VERTICAL STABILIZER): A. CONDUCT A GENERAL VISUAL INSPECTION OF THE STABILIZER ASSEMBLY INCLUDING UPPER AND LOWER SKIN SPLICES AT BL 4.5 RIB, ACCESSIBLE PORTIONS OF FRONT AND REAR SPAR INSTALLATIONS, ELEVATOR HINGE SUP						PKG		
	PKG 28	MOS						11-MAR-2006	
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25				0	0
A5510062 (s)	CLEAN AND VISUALLY INSPECT THE HINGE PIN FOR WEAR AND CORROSION (INCLUDING THE INTERNAL SURFACE OF THE PIN). APPLY A COAT OF EPOXY PRIMER TO THE INTERNAL SURFACE OF THE PIN PRIOR TO REINSTALLATION. (REFER TO 5-10-00.) MAGNETIC PARTICLE INSPECT PIN FOR CRACKS.						PKG		
	PKG 28	MOS						11-MAR-2006	
	REF: NDT 55-30-01	HRS/MSC AFL	12000	+25/-25				0	0
B5530010 (s)	VERTICAL STABILIZER (ATTACHE DTO FUSELAGE) (REFER TO 5-10-00.): A. CONDUCT A GENERAL VISUAL INSPECTION OF THE VERICAL STABILIZER ABOVE THE FUSELAGE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION. LOOSE OR WORKING FASTENERS, FATIGUE CRACKS, AND GENERAL C						PKG		
	PKG 28	MOS						11-MAR-2006	
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25				0	0
B5540020 (s)	RUDDER (REMOVED FROM VERTICAL STABILIZER) (REFER TO 5-10-00.) A. CLEAN HINGE LOCATIONS AND VISUALLY INSPECT LOCAL STRUCTURE USING PROPER LIGHTING AND 10X MAGNIFICATION. INSPECT HIMGE SUPPORT STRUCTURE FOR DEFORMATION, CORROSION, AND FATIGUE CRACKS. (INCLU						PKG		
	PKG 28	MOS						11-MAR-2006	
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25				0	0

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C5510050 (s)	HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER) (REFER TO 5-10-00.) A. WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LB.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FIT						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
E5510040 (s)	WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCTURE ATTACHING BOLTS, AND BOLT RETAINERS FOR WEAR, LOOSENE						PKG		
	PKG 18	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
E5520010 (s)	WITH CONTROL COLUMN FIXED, APPLY ALTERNATE UP AND DOWN LOADS TO THE ELEVATOR TRAILING EDGE. INSPECT EACH ELEVATOR HINGE LOCATION FOR LOOSENESS, FREE PLAY, FATIGUE CRACKS, AND GENERAL SECURITY.						PKG		
	PKG 18	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
E5540010 (s)	WITH RUDDER PEDALS RESTRAINED, APPLY ALTERNATING LEFT AND RIGHT LOADS TO THE RUDDER TRAILING EDGE. OBSERVE RUDDER HINGE FITTING ATTACHMENTS FOR LOOSENESS, FREE PLAY, AND GENERAL SECURITY.						PKG		
	PKG 18	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
H5510031 (s)	REMOVE ACCESS PANELS AND INSPECT UPPER AND LOWER FLANGES OF HORIZONTAL STABILIZER RIBS AT RIGHT AND LEFT BUTT LINE 19.4 FOR CRACKS.						PKG		
	PKG 18	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
H5510035 (s)	INSPECT HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS (INCLUDING ATTACH BOLTS), SUPPORT STRUCTURE, AND ATTACH BOLT RETAINING CLIPS (IF INSTALLED) FOR CRACKS, FASTENER CONDITION, SECURITY, WEAR, AND GENERAL CONDITION.						PKG		
	PKG 18	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H5520000 (s)	ELEVATOR: WITH PUSH-PULL TUBES DISCONNECTED FROM ELEVATOR BELLCRANKS, MOVE EACH ELEVATOR SURFACE THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR SMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, RUST OR CORROSION, TURNING ON BOLT RATHER THAN BEA PKG 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 1982	07-FEB-2018 3852.6 1982	
H5530001 (s)	VERTICAL STABILIZER FOR CRACKS, FASTENER CONDITION, AND SECURITY AT ATTACH POINTS, AND STRUCTURE IN AREA OF HORIZONTAL STABILIZER ATTACH FITTINGS. PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 2815	31-MAR-2022 4901.4 2815	
H5540011 (s)	RUDDER: WITH CABLES DISCONNECTED AT AFT BELLCRANK LOCATION, MOVE RUDDER THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR AMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, TURNING ON BOLT RATHER THAN BEARING, RUST OR CORROSION, AND GENERAL CONDITI PKG 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 1982	07-FEB-2018 3852.6 1982	
H5560001 (s)	VISUALLY INSPECT THE DELTA FIN SURFACES. REMOVE TAILCONE ACCESS COVERS AND VISUALLY INSPECT SUPPORT STRUCTURE FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, PERMANENT DEFORMATION, AND CORROSION. INSPECT UPPER AND LOWER SURFACES, PAYING PARTICULAR ATTENTION TO THE TAILCON PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 1982	07-FEB-2018 3852.6 1982	
M5530003 (s)	VERTICAL STABILIZER (ATTACHED TO FUSELAGE) (REFER TO 5-10-00.) A. CONDUCT A VISUAL INSPECTION OF THE VERTICAL STABILIZER ABOVE THE FUSLEAGE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, LOSE OR WORKING FASTENERS, FATIGUE CRACKS, AND GENERAL CONDITION. PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 1982	07-FEB-2018 3852.6 1982	
O5510060 (s)	HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER): WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCT PKG 28 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 0 0	11-MAR-2006 0 0	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5510089 (s)	CONDUCT A THOROUGH EXTERNAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER FORWARD AND REAR SPAR CAPS (UPPER AND LOWER) FOR CORROSION, INTEGRITY OF PAINT, AND GENERAL CONDITION. (ELEVATOR REMOVAL NOT REQUIRED.) (REFER TO 5-10-00)						PKG		
	PKG 6	MOS	12	+14d/-14d			31-MAR-2022		
		HRS/MSC	300	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
T5500002 (s)	INSPECT RUDDER, RUDDER TAB, AND ELEVATOR HINGE POINTS FOR EVIDENCE OF WEAR, SECURITY, AND GENERAL CONDITION. WHEN INSTALLING VERTICAL STABILIZER AFT FAIRING, ENSURE THAT ELEVATOR TO FAIRING CLEARANCE IS 0.31 (+0.12) INCH [7.9 (+3) MM].						PKG		
	PKG 18	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
U5500000 (s)	GENERAL VISUAL INSPECTION FILLETS, FAIRINGS, AND SKINS. (REFER TO 5-10-00)						PKG		
	PKG 6	MOS	12	+14d/-14d			31-MAR-2022		
		HRS/MSC	300	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		
U5560000 (s)	GENERAL VISUAL INSPECTION DELTA FINS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			31-MAR-2022		
		HRS/MSC	600	+25/-25			4901.4		
	REF: GENERIC NO REF	AFL					2815		

CHAPTER 56	WINDOWS								
05-10-29-C5610022L	PRISM CHECK LEFT								
	6600394-609	MOS					13-JUN-2016		
	407	HRS/MSC	C/C				3840.35		
	REF: NDT 56-10-01	AFL					1975		
05-10-29-C5610022R	PRISM CHECK RIGHT								
	6600394-608	MOS					13-JUN-2016		
	402	HRS/MSC	C/C				3840.35		
	REF: NDT 56-10-01	AFL					1975		
561001	LEFT WINDSHIELD ASSY								
	6600394-609	MOS			N:0		11-MAR-2006		
	407	HRS/MSC	O/C		N:0		0		
	REF: AMM 56-10-01	AFL			N:0		0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561002	RIGHT WINDSHIELD ASSY 6600394-608 402 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
561009	LEFT COCKPIT CREW WINDOW 6600512-001 170 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
561010	RIGHT COCKPIT CREW WINDOW 6600512-002 173 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
562011	LEFT NO. 1 CABIN WINDOW PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
562011A	PRISM CHECK LEFT NO. 1 CABIN WINDOW 05-10-29-M5600008 PN SN-UNKNOWN REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				13-JUN-2016 3840.35 1975		
562013	LEFT NO. 2 CABIN WINDOW PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
562013A	PRISM CHECK LEFT NO. 2 CABIN WINDOW 05-10-29-M5600008 PN SN-UNKNOWN REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				13-JUN-2016 3840.35 1975		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562015	LEFT NO. 3 CABIN WINDOW LA6600405-20 3099 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-JUL-2011 2290.88 1230		
562015A	PRISM CHECK LEFT NO. 3 CABIN WINDOW 05-10-29-M5600008 LA6600405-20 3099 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				13-JUN-2016 3840.35 1975		
562017	LEFT NO. 4 CABIN WINDOW LA6600405-32 10368 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
562017A	PRISM CHECK LEFT NO. 4 CABIN WINDOW 05-10-29-M5600008 LA6600405-32 10368 REF: NDT 56-30-01	MOS HRS/MSC AFL	600	+25/-25			31-MAR-2022 4901.4 2815	5501.4	
562019	LEFT NO. 5 CABIN WINDOW LA6600405-31 1008 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-NOV-2012 2940.8 1575		
562019A	PRISM CHECK LEFT NO. 5 CABIN WINDOW 05-10-29-M5600008 LA6600405-31 1008 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				13-JUN-2016 3840.35 1975		
562022	RIGHT NO. 1 CABIN WINDOW PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562022A	PRISM CHECK RIGHT NO. 1 CABIN WINDOW PN SN-UNKNOWN REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				13-JUN-2016 3840.35 1975		
562024	RIGHT NO. 2 CABIN WINDOW LA6600405-32 10361 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C				31-MAR-2022 4901.4 2815		
562024A	PRISM CHECK RIGHT NO. 2 CABIN WINDOW LA6600405-32 10361 REF: NDT 56-30-01	MOS HRS/MSC AFL	600	+25/-25			31-MAR-2022 4901.4 2815	5501.4	
562026	RIGHT NO. 3 CABIN WINDOW PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		11-MAR-2006 0 0		
562026A	PRISM CHECK RIGHT NO. 3 CABIN WINDOW PN SN-UNKNOWN REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				13-JUN-2016 3840.35 1975		
562028	RIGHT NO. 4 CABIN WINDOW PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		11-MAR-2006 0 0		
562028A	PRISM CHECK RIGHT NO. 4 CABIN WINDOW PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	C/C				13-JUN-2016 3840.35 1975		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562030	RIGHT NO. 5 CABIN WINDOW LA6600405-20 3199 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				17-NOV-2011 2503.48 1348	
562030A	PRISM CHECK RIGHT NO. 5 CABIN WINDOW 05-10-29-M5600008 LA6600405-20 3199 REF:	MOS HRS/MSC AFL	C/C					13-JUN-2016 3840.35 1975	
H5610024 (s)	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE) A. CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS. B. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS FOR DELAMINATION, CHIPPING, PKG 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25				07-FEB-2018 3852.6 1982	
H5620000 (s)	PERFORM AN EXTERNAL VISUAL INSPECTION OF THE CABIN WINDOWS AND RETAINERS FOR GENERAL CONDITION, SECURITY, AND CLEANLINESS. INSPECT INTERNAL AND EXTERNAL SURFACES OF THE CABIN WINDOWS FOR SCRATCHES, PITS, OR OTHER DAMAGE. (REFER TO 56-20-01) PKG 8 REF: AMM 56-20-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25				31-MAR-2022 4901.4 2815	
M5610010 (s)	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE): (A.) CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS IN ACCORDANCE WITH CHAPTER 12. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS FOR DELAMINATION, CHIPPING, CRAZING, CRACKS, GOUGES, HEAT DAMAGE IN THE EXTERNAL DEFOG AREA, AND GENERAL CONDITION. (B.) CONDUCT AN X-RAY INSPECTION OF THE WINDSHIELD SUPPORTING STRUCTURE. REMOVAL NOT REQUIRED UNLESS X-RAY INDICATES POSSIBLE CRACKS. (C.) EDDY CURRENT INSPECT OUTER RETAINER. PKG 27 REF: See Workcard	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25				07-FEB-2018 3852.6 1982	
M5620001 (s)	CABIN WINDOWS AND FRAMING MEMBERS: A. VISUALLY INSPECT ACCESSIBLE STRUCTURE FOR SECURITY, GENERAL CONDITION, AND FATIGUE CRACKS. (REFER TO 5-10-00.) B. CONDUCT X-RAY INSPECTION OF SUPPORT STRUCTURE. (REFER TO NDI MANUAL [NDI-2], PART 2, 56-50-01.) PKG 27 REF: NDT 56-50-01	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25				07-FEB-2018 3852.6 1982	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T5610002 (s)	INSPECT INTERIOR AND EXTERIOR OF WINDSHIELD FOR CRAZING, INCLUDING VISIBLE PORTION UNDER RETAINERS FOR CRACKS, CLEANLINESS, SECURITY, AND GENERAL CONDITION. AREA UNDER ANTI-ICE DUCT SHALL BE INSPECTED BY VIEWING THE EPOXY-PRIMED OUTER SURFACE OF THE WINDSHIELD FR						PKG		
	PKG 14	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: See Workcard	AFL					2815		
T5620007 (s)	CABIN WINDOWS: USING PRISM TECHNIQUES, INSPECT WINDOWS FOR CRACKS, CHIPS, DELAMINATION, OR OTHER DAMAGE. THIS INSPECTION IS ALSO CAPABLE OF VISUALLY ASSESSING THE CONDITION OF THE ATTACHING FASTENERS. BROWN DISCOLORATIONS IN THE AREA OF THE FASTENERS MAY						PKG		
	PKG 24	MOS	96	+14d/-14d			07-FEB-2018		
		HRS/MSC	2400	+25/-25			3852.6		
	REF:	AFL					1982		
CHAPTER 57 WINGS									
05-10-29-L5720012L	PERFORM LEFT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION								
		MOS					11-MAR-2006		
		HRS/MSC					0		
	REF: NDT 57-40-03	AFL	10000	+25/-25			0	10000	10025
05-10-29-L5720012R	PERFORM RIGHT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION								
		MOS					11-MAR-2006		
		HRS/MSC					0		
	REF: NDT 57-40-03	AFL	10000	+25/-25			0	10000	10025
570001	LEFT WING								
	PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-00-01	AFL		N:0			0		
570002	RIGHT WING								
	PN	MOS		N:0			11-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-00-01	AFL		N:0			0		
572001	LEFT WINGLET ASSEMBLY								
	2822650-43	MOS		N:0			11-MAR-2006		
	385	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-20-01	AFL		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
572002	RIGHT WINGLET ASSEMBLY 2822650-44 400 REF: AMM 57-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
572003	LEFT WING LEADING EDGE PN SN-UNKNOWN REF: AMM 57-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
572004	RIGHT WING LEADING EDGE PN SN-UNKNOWN REF: AMM 57-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
572025	LEFT FRONT WINGLET SPAR FITTING 6022621-1 H0050 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
572026	RIGHT FRONT WINGLET SPAR FITTING 6022621-2 H0056 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
572027	LEFT AFT WINGLET SPAR FITTING 6022622-1 H0081 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
572028	RIGHT AFT WINGLET SPAR FITTING 6022622-2 H0066 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A5710045 (s)	REMOVE LOWER SURFACE ACCESS PLATES FROM WS 92 INBOARD TO BL 0.0 INCLUDING FUEL PUMPS AT WS 6.0 AND 11.0. VISUALLY INSPECT THE PERIPHERY OF THESE CUTOUTS FOR FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.) CONDUCT EDDY CURRRRENT INSPECTIONS A						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 57-10-01	AFL						0	
A5710070 (s)	CLEAN UPPER AND LOWER CENTERLINE SPLICE PLATE (SPAR 2 TO 5 AND 7 TO 8) ADJACENT TO BL 0.0 RIB CAP. VISUALLY INSPECT THESE AREAS FOR CORROSION, FATIGUE CRACKS, WORKING FASTENERS, AND GENERAL SECURITY. (REFER TO 5-10-00)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
A5760010 (s)	AILERON (REMOVED FROM WING) (REFER TO 5-10-00.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: GENERIC NO REF	AFL						0	
B5710050 (s)	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER AND LOWER STRUCTURE IN THE CENTERLINE DOUBLER AREA. INSPECT FOR FATIGUE CRACKS, CORROSION, LOOSE OR MISSING FASTENERS, AND GENERAL SECURITY. (REFER TO NDI MANUAL [NDI-2], PART 2, 57-20-01 AND 57-21-01.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: See Workcard	AFL						0	
C5710040 (s)	CLEAN AND CONDUCT A GENERAL EXTERNAL AND INTERNAL VISUAL INSPECTION OF THE WING CENTER SECTION, PAYING PARTICULAR ATTENTION TO THE LOWER SKIN AT THE FUEL PUMP LOCATIONS AND THE SPLICE DETAILS AT BL 0.0, AS ACCESSIBLE. INSPECT FOR EVIDENCE OF AFTIGUE CRACKS, COR						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
C5710055 (s)	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER STRUCTURE INBOARD OF THE WING-TO-FUSELAGE FITTINGS AND FORWARD OF SPAR 5. INSPECT FOR CORROSION, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. IF CORROSION IS FOUND, WING REMOVAL FROM FUSELAGE MAY						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: NDT 57-12-01	AFL	6000	+25/-25				1982	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C5710060 (s)	CONDUCT AN EDDY CURRENT INSPECTION FOR THE FOLLOWING WING STRUCTURAL AREAS: SURFACE OF ACCESSIBLE AREAS OF LOWER DOUBLER FROM BL 0.0 TO OUTBOARD END OF DOUBLER ALONG SPARS 4, 5, AND 7, AND LOWER SKIN ADJACENT TO THE OUTBOARD 2 INCHES OF DOUBLER FINGERS. SKIN ADJA PKG 27 REF: NDT 57-12-01	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
C5710062 (s)	REMOVE THE ACCESS COVER AT WS 73.0 BETWEEN SPARS 4/5 AND 6/7. INSPECT ALL HOLES AT THIS LOCATION IN THE SPAR AND SKIN USING AN EDDY CURRENT HOLE PROBE. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-12-01.) PKG 27 REF: NDT 57-12-01	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
C5710065 (s)	EDDY CURRENT AREA AROUND FASTENERS COMMON TO TRUNNION FITTINGS. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-12-01, AREAS E AND D.) PKG 25 REF: NDT 57-12-01	MOS HRS/MSC AFL	 3000	 +25/-25			PKG 11-MAR-2006 0 0		
C5720020 (s)	VISUALLY INSPECT INTERNAL AND EXTERNAL AREA OF WING WHEEL WELL STRUCTURE, PAYING PARTICULAR ATTENTION TO THE MAIN LANDING GEAR ACTUATOR UPPER ATTACHMENT AND LANDING GEAR RIB STRUCTURE AT WS 53.04. (REFER TO 5-10-00.) PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
C5720025 (s)	X-RAY INSPECT THE OUTBOARD LOWER WING SKIN FROM WS 31 TO WS 61. (REFER TO NDI MANUAL [NDI-2], PART 2, 57-30-01.) PKG 27 REF: NDT 57-30-01	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		
C5720040 (s)	INSPECT THE JOINT AT WS 181 THAT SPLICES THE WING TO THE OUTER WING EXTENSION. VISUALLY INSPECT FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, AND GENERAL SECURITY. (REFER TO 5-10-00.) PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 07-FEB-2018 3852.6 1982		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C5740001 (s)	WITH LEADING EDGE ASSEMBLIES REMOVED, INSPECT FORWARD SIDE OF SPAR 1 FOR EVIDENCE OF FATIGUE CRACKS, OVERHEAT (DISCOLORED PRIMER), GENERAL CORROSION, LOOSE OR MISSING FASTENERS, FIFLIFORM CORROSION, AND GENERAL CONDITION.						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
C5740002 (s)	WITH LEADING EDGE LOWER CUFF FAIRING ASSEMBLIES REMOVED, INSPECT LOWER WING SKIN COVERED BY CUFF FAIRING AND INNER SURFACE OF CUFF FOR EVIDENCE OF FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, CORROSION, AND GENERAL CONDITION.						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	
E5710066 (s)	CONDUCT A VISUAL AND EDDY CURRENT INSPECTION OF THE FOLLOWING LOWER WING STRUCTURAL AREAS						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: See Workcard	AFL						0	
E5710071 (s)	CONDUCT AN EDDY CURRENT INSPECTION OF THE LOWER SPLICE PLATE ALONG THE CENTERLINE FASTENER ROWS. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-10-01)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 57-10-01	AFL						0	
E5720010 (s)	INSPECT FLAP SECTOR SUPPORT BRACKETS AND FLAP ACTUATOR SUPPORT FLAP BRACKET FOR CRACKS, DISTORTION, INTERFERENCE, AND FASTENER CONDITION. (REFER TO 57-40-03).						PKG		
	PKG 10	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: AMM 57-40-03	AFL						2815	
E5750020 (s)	WITH FLAPS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO FLAP TRAILING EDGE. INSPECT INBOARD AND OUTBOARD FLAP TRACKS AND NOSE ROLLER SUPPORT STRUCTURE CRACKS, DISTORTION, FASTENER CONDITION, EVIDENCE OF CHAFING OR INTERFERENCE, AND GENERAL SECURITY.						PKG		
	PKG 16	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5750030 (s)	INSPECT FLAP NOSE ROLLER BUSHINGS. REPLACE FLAP NOSE ROLLER IF WORN TO A DIAMETER LESS THAN 0.744 INCH. REPLACE FLAP NOSE ROLLER TRACK IF SLOT EXCEEDS 0.775 INCH AT ANY POINT WITH FLAPS FULLY EXTENDED. ENSURE THAT A POSITIVE CLEARANCE EXISTS BETWEEN NOSE ROLLERS						PKG		
	PKG 16	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
E5750060 (s)	CLEAN AND VISUALLY INSPECT FLAP ATTACH FITTING (CASTINGS ATTACHED TO FLAP SPAR) FOR CRACKS. (REFER TO 5-10-00.) (SEE FIGURE 3.)						PKG		
	PKG 16	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
E5770010 (s)	INSPECT SPOILER CENTER HINGE BRACKETS (ATTACHED TO WING SPAR 8) FOR CRACKS EMANATING FROM THE BOLT HOLE AND/OR BRACKET BEND RELIEF. INSPECT BOLT HOLE FOR ELONGATION OR DISTORTION.						PKG		
	PKG 10	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
G5720021 (s)	VISUALLY INSPECT INTERNAL AND EXTERNAL AREAS OF WING STRUCTURE ADJACENT TO LANDING GEAR RIB WS 53.04 (BETWEEN SPARS 4 AND 8). INSPECT TRUNNION FITTINGS FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, ELONGATION OF TRUNNION PIN HOLES, AND GENERAL SECURITY. CHECK						PKG		
	PKG 26	MOS						11-MAR-2006	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	6000	+25/-25				0	
H5750000 (s)	INSPECT TRAILING EDGE REGION OF WING FOR LOCAL DEFORMATION AFFECTING NORMAL USAGE OF FLAP AND AILERON.						PKG		
	PKG 22	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: GENERIC NO REF	AFL						1982	
H5750047 (s)	FLAP (REMOVED FROM WING) VISUALLY INSPECT THE FOLLOWING (REFER TO 5-10-00): A. FLAP SUPPRT FOR SECURITY, CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERFERENCE, AND GENERAL CONDITION. INSPECT THE FLAP SECTOR AND SUPPORTIN BRACKERTY FOR EVIDENCE OF OVER						PKG		
	PKG 25	MOS						11-MAR-2006	
		HRS/MSC						0	
	REF: GENERIC NO REF	AFL	3000	+25/-25				0	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
J5720011 (s)	FLAP SUPPORT FITTING (ALUMINUM, P/N 6022521-1 THRU 6022521-8) - OERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-40-02.)						PKG		
	PKG 16	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: NDT 57-40-02	AFL						2815	
K5730012 (s)	DETAILED INSPECTION AILERON BRUSH SEALS. (REFER TO 57-30-07)						PKG		
	PKG 4	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: AMM 57-30-07	AFL						2815	
N5700004 (s)	VISUAL INSPECTION WING SURFACE, WING TO FUSELAGE FAIRING AND WINGLET EXTERIOR. (REFER TO 5-10-00)						PKG		
	PKG 4	MOS	12	+14d/-14d				31-MAR-2022	
		HRS/MSC	300	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
P5710140 (s)	REMOVE UPPER WING-TO-FUSELAGE FAIRINGS AND INSPECT WING SKINS, WING TO FUSELAGE ATTACH FITTINGS, AND ADJACENT STRUCTURE FOR CORROSION, FASTENER SECURITY, CRACKS, PERMANENT DEFORMATION, PROTECTIVE COATING, AND GENERAL CONDITION. EXAMINE EXPOSED EDGE OF HONEYCOMB						PKG		
	PKG 22	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: GENERIC NO REF	AFL						1982	
P5710141 (s)	INSPECT WING-TO-FUSELAGE ATTACH POINTS FOR SECURITY (THAT PORTION VISIBLE THROUGH WHEEL WELLS).						PKG		
	PKG 23	MOS	96	+14d/-14d				07-FEB-2018	
		HRS/MSC	2400	+25/-25				3852.6	
	REF: GENERIC NO REF	AFL						1982	
P5710142 (s)	WITH WING-TO-FUSELAGE FAIRING REMOVED, CLEAN AND VISUALLY INSPECT ALL EIGHT WING-TO-FUSELAGE FITTINGS (FOUR PER SIDE). USING A 10X MAGNIFYING GLASS, ADEQUATE LIGHTING, AND MIRROR, INSPECT FITTINGS AND SUPPORT STRUCTURES FOR FATIGUE CRACKS, DEFORMATION, CO						PKG		
	PKG 27	MOS	144	+14d/-14d				07-FEB-2018	
		HRS/MSC						3852.6	
	REF: GENERIC NO REF	AFL	6000	+25/-25				1982	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5710143 (s)	CLEAN CLEAN AND VISUALLY INSPECT, USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE) AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHES, FASTENER WORKING, AND GENERAL SECURITY. (REFER TO 5-10-00.)						PKG		
	PKG 28	MOS					11-MAR-2006		
	REF: NDT 57-13-01	HRS/MSC	12000	+25/-25			0		
		AFL					0		
P5710144 (s)	INSPECT WHEEL WELL AND CENTER SECTION OF WING FOR GENERAL CONDITION OF SKIN, SPARS, ATTACH FITTINGS AND SUPPORTING STRUCTURE, LANDING GEAR RIB, AND TRUNNION FITTINGS. CHECK FOR DEFORMATION, FATIGUE CRACKS, PROTECTIVE FINISH CONDITION, AND GENERAL SECURITY.						PKG		
	PKG 23	MOS	96	+14d/-14d			07-FEB-2018		
	REF: GENERIC NO REF	HRS/MSC	2400	+25/-25			3852.6		
		AFL					1982		
P5710146 (s)	INSPECT UPPER PORTION OF BL 0.0 RIB CAP, JUST FORWARD OF SPAR 7. INSPECT FOR ANY EVIDENCE OF CORROSION, PRIMER BLISTERING, AND CONDITION OF PRIMER SURFACE. (SEE FIGURE 2.)						PKG		
	PKG 16	MOS	48	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC	1200	+25/-25			4901.4		
		AFL					2815		
P5750050 (s)	INSPECT FLAP UPPER AND LOWER SURFACES FOR SKIN CRACKS, LOOSE RIVETS, AND OTHER DAMAGE. CHECK NOSE ROLLERS FOR FREEDOM OF ROTATION. PAY PARTICULAR ATTENTION TO NOSE ROLLER SUPPORT STRUCTURE FOR CRACKS.						PKG		
	PKG 4	MOS	12	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC	300	+25/-25			4901.4		
		AFL					2815		
U5720071 (s)	GENERAL VISUAL INSPECTION STALL FENCES, STALL STRIPS, WING STALL TRIANGLES, AND BOUNDARY LAYER ENERGIZERS. (REFER TO 5-10-00.)						PKG		
	PKG 4	MOS	12	+14d/-14d			31-MAR-2022		
	REF: GENERIC NO REF	HRS/MSC	300	+25/-25			4901.4		
		AFL					2815		
CHAPTER 71	POWER PLANT								
05-11-00-E7120049L	REPLACE * NO. 1 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)								
		MOS					11-MAR-2006		
		HRS/MSC	20000				0		20000
LIFE LIMIT	REF: AMM 71-20-10	AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E7120049R	REPLACE * NO. 2 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 71-20-10	HRS/MSC AFL	20000				0 0	20000	
05-11-00-G7110021L	REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA	MOS					09-FEB-2011		
TEFLON	REF: AMM 28-00-00	HRS/MSC AFL	O/C				2087.38 1135		
05-11-00-G7110021R	REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA	MOS					09-FEB-2011		
TEFLON	REF: AMM 28-00-00	HRS/MSC AFL	O/C				2087.38 1135		
05-11-00-G7110022L	REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)	MOS					09-FEB-2011		
TEFLON	REF: GENERIC NO REF	HRS/MSC AFL	O/C				2087.38 1135		
05-11-00-G7110022R	REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)	MOS					09-FEB-2011		
TEFLON	REF: GENERIC NO REF	HRS/MSC AFL	O/C				2087.38 1135		
05-11-00-M7120048L	REPLACE NO. 1 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 71-20-05	HRS/MSC AFL	20000				0 0	20000	
05-11-00-M7120048R	REPLACE NO. 2 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)	MOS					11-MAR-2006		
LIFE LIMIT	REF: AMM 71-20-05	HRS/MSC AFL	20000				0 0	20000	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711005	LEFT ENGINE INLET COWL 282-0211-505 L60728-150 REF: AMM 71-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711006	RIGHT ENGINE INLET COWL 282-0211-507 731 REF: AMM 71-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711011	LEFT ENGINE UPPER ACCESS COWL 266-0208-1 728 REF: AMM 71-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711012	RIGHT ENGINE UPPER ACCESS COWL 266-0208-2 735 REF: AMM 71-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711013	LEFT ENGINE LOWER ACCESS COWL 266-0209-1 L60726-275 REF: AMM 71-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711014	RIGHT ENGINE LOWER ACCESS COWL 266-0209-2 L60729-275 REF: AMM 71-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711015	LEFT ENGINE PYLON APRON ASSEMBLY 266-0213-511 730 REF: AMM 71-10-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711016	RIGHT ENGINE PYLON APRON ASSEMBLY 266-0213-512 729 REF: AMM 71-10-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711021	LEFT ENGINE OUTER FAN DUCT 282-0075-1 L60751-018 REF: AMM 71-10-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711022	RIGHT ENGINE OUTER FAN DUCT 282-0075-3 753 REF: AMM 71-10-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711023	LEFT ENGINE LEFT FORWARD CORE COWL 266-0261-501 728 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711024	RIGHT ENGINE LEFT FORWARD CORE COWL 266-0261-501 729 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711025	LEFT ENGINE RIGHT FORWARD CORE COWL 266-0261-503 728 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711026	RIGHT ENGINE RIGHT FORWARD CORE COWL 266-0261-503 729 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711027	LEFT ENGINE UPPER AFT CORE COWL 266-0263-511 730 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711028	RIGHT ENGINE UPPER AFT CORE COWL 266-0263-511 729 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711029	LEFT ENGINE LOWER AFT CORE COWL 266-0263-509 730 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
711030	RIGHT ENGINE LOWER AFT CORE COWL 266-0263-509 729 REF: AMM 71-10-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712001	LEFT ENGINE FORWARD INTERMEDIATE FITTING PN SN-UNKNOWN REF: AMM 71-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712002	RIGHT ENGINE FORWARD INTERMEDIATE FITTING PN SN-UNKNOWN REF: AMM 71-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712005	LEFT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-501 1209 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712006	RIGHT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-505 1239 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712007	LEFT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-505 1249 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712008	RIGHT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-501 1207 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712009	LEFT ENGINE FORWARD MOUNT YOKE PN SN-UNKNOWN REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712010	RIGHT ENGINE FORWARD MOUNT YOKE PN SN-UNKNOWN REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712011	LEFT ENGINE AFT VIBRATION ISOLATOR 266D0820-503 0978 REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712012	RIGHT ENGINE AFT VIBRATION ISOLATOR 266D0820-503 0975 REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712013	LEFT ENGINE UPPER AFT MOUNT LINK PN SN-UNKNOWN REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712014	RIGHT ENGINE UPPER AFT MOUNT LINK PN SN-UNKNOWN REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712015	LEFT ENGINE LOWER AFT MOUNT LINK PN SN-UNKNOWN REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
712016	RIGHT ENGINE LOWER AFT MOUNT LINK PN SN-UNKNOWN REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
71EN1	NO. 1 ENGINE 31B4067-04 PCE-CA0457 REF: See Workcard	MOS HRS/MSC AFL	E/C	N:2852.1			12-NOV-2012 2940.8 1575		
71EN2	NO. 2 ENGINE 31B4067-04 PCE-CA0459 REF: See Workcard	MOS HRS/MSC AFL	E/C	N:3622.55 R:0			17-MAR-2015 3839.9 1974		
E7100004 (s)	VISUAL INSPECTION OF ALL BLEED AIR DUCTS, LINES, HOSES, AND ELECTRICAL WIRING IN THE ENGINE NACELLE. INSPECT FOR SECURITY, CLAMPING, ROUTING, CLEARANCE, EVIDENCE OF LEAKS, AND GENERAL CONDITION. (REFER TO 5-10-00) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815	PKG	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E7100016 (s)	INSPECT HOLD OPEN RODS FOR SECURITY OF INSTALLATION AND EVIDENCE OF DAMAGE. PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
E7100020 (s)	REMOVE IGNITER ACCESS PANEL AND INSPECT CORE COWL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE. PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
E7100022 (s)	INSPECT IGNITER ACCESS PANEL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE. PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
E7100030 (s)	INSPECT FUEL, HYDRAULIC, FIRE EXTINGUISHER, AND DRAIN LINES, CONTROLS CONNECTIONS, COUPLINGS, AND ACCESSORIES FOR LOOSE OR FAILED FASTENERS, CHAFING WEAR, ROUTING, PROPER SAFETY, SECURITY OF MOUNTING, AND EVIDENCE OF DAMAGE. INSPECT SHIELDED FADEC ELECTRICAL HAR PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
J7120051 (s)	FORWARD ENGINE BEAM INTERMEDIATE FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-01.) PKG 28 REF: NDT 71-20-01	MOS HRS/MSC AFL	12000	+25/-25			PKG 11-MAR-2006 0 0		
J7120052 (s)	FORWARD ENGINE MOUNT YOKE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-02.) PKG 28 REF: NDT 71-20-02	MOS HRS/MSC AFL	12000	+25/-25			PKG 11-MAR-2006 0 0		
J7120053 (s)	BOLT/FORWARD INTERMEDIATE FITTING TO FORWARD BEAM SUPPORT FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-03.) PKG 28 REF: NDT 71-20-03	MOS HRS/MSC AFL	12000	+25/-25			PKG 11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
J7120054 (s)	BOLT/FORWARD YOKE TO INTERMEDIATE FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-04.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-04	AFL						0	
J7120055 (s)	BOLT/FORWARD YOKE TO ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-05.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-05	AFL						0	
J7120056 (s)	BOLT/FORWARD ENGINE ISOLATOR TO ENGINE CASE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-06.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-06	AFL						0	
J7120057 (s)	FORWARD TO ENGINE ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-07.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-07	AFL						0	
J7120058 (s)	AFT ENGINE ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-08.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-08	AFL						0	
J7120059 (s)	AFT MOUNT LINKS - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-09.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-09	AFL						0	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
J7120060 (s)	BOLT/AFT ISOLATOR TO SUPPORT FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL {NDI-2}, PART 5, 71-20-10.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-10	AFL						0	
J7120061 (s)	BOLT/AFT ISOLATOR TO MOUNT LINKS - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-11.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-11	AFL						0	
J7120062 (s)	BOLT/MOUNT LINKS TO ENGINE CASE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-12.)						PKG		
	PKG 28	MOS						11-MAR-2006	
		HRS/MSC	12000	+25/-25				0	
	REF: NDT 71-20-12	AFL						0	
M7120068A	INSPECT NO. 1 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS								
		MOS						17-MAR-2015	
		HRS/MSC	3850					3839.9	7689.9
	REF: See Workcard	AFL						1974	
M7120068B	INSPECT NO. 2 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS								
		MOS						17-MAR-2015	
		HRS/MSC	3850					3839.9	7689.9
	REF: See Workcard	AFL						1974	
T7100010 (s)	INSPECT UPPER COWL DOOR AND APRON FOR FAILED FASTENERS, SECURITY, AND EVIDENCs OF DAMAGE. INSPECT BONDING JUMPERS ACROSS COWLING HINGES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR AND APRON FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY						PKG		
	PKG 15	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T7100012 (s)	INSPECT LOWER COWL DOOR INNER AND OUTER SKINS AND SEALS FOR EVIDENCE OF DAMAGE. INSPECT LATCH ASSEMBLIES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY AROUND THE HEADS OF FASTENERS AND ALONG PKG 15 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
T7100018 (s)	GENERAL VISUAL INSPECTION FAN DUCT OUTER SKIN AND ATTACHMENT. (REFER TO 5-10-00) PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
U7100014 (s)	GENERAL VISUAL INSPECTION OIL FILLER DOOR. (REFER TO 5-10-00) PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
U7110032 (s)	GENERAL VISUAL INSPECTION GENERATOR INLET DUCT SEAL. (REFER TO 5-10-00) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
U7110041 (s)	GENERAL VISUAL INSPECTION NACELLE OUTER SKIN ATTACHMENT. (REFER TO 5-10-00) PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
U7110042 (s)	GENERAL VISUAL INSPECTION NACELLE LIP ASSEMBLY AND INNER BARREL. (REFER TO 5-10-00) PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		

ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
05-P&W-710001	NO. 1 ENGINE - PERFORM OVERHAUL ENGINE								
		MOS					19-DEC-2005		
		HRS/MSC	7700	+50			0	(7700) 7788.67	7750
	REF: GENERIC NO REF	ENC					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-P&W-710006	NO. 1 ENGINE - PERFORM HOT SECTION INSPECTION	MOS					09-MAR-2015		
	REF: GENERIC NO REF	HRS/MSC ENC	3850	+50			3751.2 1926	(7601.2) 7689.87	7651.2
05-P&W-710015	NO. 1 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS	MOS					07-FEB-2018		
	REF: GENERIC NO REF	HRS/MSC ENC	1200	+25/-25			3763.9 1934	(4963.9) 5052.57	4988.9
05-P&W-710017	NO. 1 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR	MOS					20-DEC-2020		
	REF: GENERIC NO REF	HRS/MSC ENC	600	+25/-25			4451.7 2490	(5051.7) 5140.37	5076.7
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEED OFF VALVE SOLENOID	MOS					08-JUL-2021		
	30B7178-02 AGJA000A792 REF: EMM 75-30-02	HRS/MSC ENC	1500	+300/-300			4624.22 2612	(6124.22) 6212.88	6424.22
05-P&W-710020	NO. 1 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESSES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR	MOS					07-FEB-2018		
	REF: GENERIC NO REF	HRS/MSC ENC	3850	+50			3763.9 1934	(7613.9) 7702.57	7663.9
710000	NO. 1 ENGINE - COMPRESSOR WASH	MOS					19-DEC-2005		
	REF: EMM 71-00-00	HRS/MSC ENC	A/R				0 0		
710050	NO. 1 ENGINE - RUN ENGINES	MOS					13-APR-2017		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				3751.65 1927		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
715020	NO. 1 ENGINE - ENGINE WIRE HARNESS 30B3089-03 AA54039 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
05-P&W-710001	NO. 2 ENGINE - PERFORM OVERHAUL ENGINE REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
05-P&W-710006	NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION REF: GENERIC NO REF	MOS HRS/MSC ENC	3850	+50			25-FEB-2015 3622.55 1881	(7472.55) 7688.87	7522.55
05-P&W-710015	NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS REF: GENERIC NO REF	MOS HRS/MSC ENC	1200	+25/-25			07-FEB-2018 3635.3 1889	(4835.3) 5051.62	4860.3
05-P&W-710017	NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR REF: GENERIC NO REF	MOS HRS/MSC ENC	600	+25/-25			20-DEC-2020 4323.05 2445	(4923.05) 5139.37	4948.05
05-P&W-710019	NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID 100094000-003 841 REF: EMM 75-30-02	MOS HRS/MSC ENC	1500	+300/-300			25-FEB-2015 3622.55 1881	(5122.55) 5338.87	5422.55
05-P&W-710020	NO. 2 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR REF: GENERIC NO REF	MOS HRS/MSC ENC	3850	+50			07-FEB-2018 3635.3 1889	(7485.3) 7701.62	7535.3

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710000	NO. 2 ENGINE - COMPRESSOR WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	A/R				29-DEC-2005 0 0		
710050	NO. 2 ENGINE - RUN ENGINES REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				13-APR-2017 3623 1882		
715020	NO. 2 ENGINE - ENGINE WIRE HARNESS 30B3089-03 AA57185 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
715025	NO. 2 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR PN SN-UNKNOWN REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
CHAPTER 72 ENGINE									
APU Model : T-20G-10C3A (CIMMS) Serial # SP-E050424 Part # 4503134									
496010	APU - H.O.T. SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			30-DEC-2005 0 0		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
720000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	180	+12m			19-DEC-2005 0 0	19-DEC-2021 M	19-DEC-2022
+ 720010 (s)	NO. 1 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				04-MAR-2021 4525.42 2540		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720015 (s)	NO. 1 ENGINE - EEC - REMOVE, CHECK CONDITION, CLEAN THE CONNECTORS AND REINSTALL PKG 1 REF: EMM 70-00-00	MOS HRS/MSC ENC	24 600				PKG 19-DEC-2005 0 0		
+ 720020 (s)	NO. 1 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 04-MAR-2021 4525.42 2540		
+ 720030 (s)	NO. 1 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 04-MAR-2021 4525.42 2540		
+ 720040 (s)	NO. 1 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 04-MAR-2021 4525.42 2540		
+ 720050 (s)	NO. 1 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 04-MAR-2021 4525.42 2540		
+ 720060 (s)	NO. 1 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 04-MAR-2021 4525.42 2540		
+ 720070 (s)	NO. 1 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 04-MAR-2021 4525.42 2540		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720080 (s)	NO. 1 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720090 (s)	NO. 1 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640) PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
720095	NO. 1 ENGINE - DISCARD LP COMPRESSOR FAN BLADES PN SN-UNKNOWN	MOS					19-DEC-2005 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000				0	(15000) 15048	
+ 720100 (s)	NO. 1 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720110 (s)	NO. 1 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720120 (s)	NO. 1 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720130 (s)	NO. 1 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720140 (s)	NO. 1 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP						PKG		
	PKG 1	MOS	24				04-MAR-2021		
		HRS/MSC	600				4525.42		
	REF: EMM 05-20-00	ENC					2540		
+ 720150 (s)	NO. 1 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT						PKG		
	PKG 1	MOS	24				04-MAR-2021		
		HRS/MSC	600				4525.42		
	REF: EMM 05-20-00	ENC					2540		
+ 720160 (s)	NO. 1 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION						PKG		
	PKG 1	MOS	24				04-MAR-2021		
		HRS/MSC	600				4525.42		
	REF: EMM 05-20-00	ENC					2540		
+ 720170 (s)	NO. 1 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE						PKG		
	PKG 1	MOS	24				04-MAR-2021		
		HRS/MSC	600				4525.42		
	REF: EMM 79-20-01	ENC					2540		
+ 720180 (s)	NO. 1 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE						PKG		
	PKG 1	MOS	24				04-MAR-2021		
		HRS/MSC	600				4525.42		
	REF: EMM 05-20-00	ENC					2540		
+ 720190 (s)	NO. 1 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND						PKG		
	PKG 1	MOS	24				04-MAR-2021		
		HRS/MSC	600				4525.42		
	REF: EMM 05-20-00	ENC					2540		
+ 720200 (s)	NO. 1 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE						PKG		
	PKG 1	MOS	24				04-MAR-2021		
		HRS/MSC	600				4525.42		
	REF: EMM 05-20-00	ENC					2540		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720210 (s)	NO. 1 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720220 (s)	NO. 1 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND. PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720230 (s)	NO. 1 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720240 (s)	NO. 1 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720250 (s)	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE. PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720260 (s)	NO. 1 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	ENC	600						
+ 720270 (s)	NO. 1 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: See Workcard	ENC	600						

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720280 (s)	NO. 1 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720290 (s)	NO. 1 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY. PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720300 (s)	NO. 1 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720310 (s)	NO. 1 ENGINE - SPARK IGNITERS, OPERATIONAL TEST PKG 1	MOS	24				PKG 04-MAR-2021 4525.42 2540		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
723001	NO. 1 ENGINE - FAN HUB 30B2256 A001T60C	MOS		N:0			19-DEC-2005 0 0		
LIFE LIMIT	REF: EMM 72-30-01	HRS/MSC ENC ACCCYC	12000	N:0 N:0 N:0					
723003	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 30B4565-01 A001PE54	MOS		N:0			19-DEC-2005 0 0		
LIFE LIMIT	REF: EMM 72-30-01	HRS/MSC ENC ACCCYC	7000	N:0 N:0 N:0					
723004	NO. 1 ENGINE - PRESSURE CHECK IMPELLER SHROUD	MOS					19-DEC-2005 0 0		
	REF: GENERIC NO REF	HRS/MSC ENC	N/A						

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723005	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR 30B6551-01 TXA1C7397	MOS HRS/MSC		N:0 N:0			16-NOV-2012 2852.1		
LIFE LIMIT	REF: EMM 72-30-01	ENC ACCCYC	12000	N:0 N:0			1527		
723005A	NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR) 30B6551-01 TXA1C7397	MOS HRS/MSC	N/A						
NOT APPLICABLE	REF: EMM 72-00-00	ENC							
723008	NO. 1 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 30B4745-01 55B996	MOS HRS/MSC		N:0 N:0			19-DEC-2005 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC ACCCYC	8500	N:0 N:0			0		
723008A	NO. 1 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM 30B4745-01 55B996	MOS HRS/MSC	O/C				19-DEC-2005 0		
	REF: GENERIC NO REF	ENC					0		
723040	NO. 1 ENGINE - LP COMPRESSOR BLADES PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2005 0		
	REF: GENERIC NO REF	ENC		N:0			0		
724010	NO. 1 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)	MOS HRS/MSC	N/A				19-DEC-2005 0		
	REF: GENERIC NO REF	ENC					0		
725001	NO. 1 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING 30B3012CLO1 B363	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2005 0		
	REF: EMM 72-50-01	ENC		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725003	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 31A1026-03 MTU27608 REF: EMM 72-50-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
725101	NO. 1 ENGINE - STAGE 1 TURBINE DISC 30B2981-01 A001T5K9 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	3100	N:0 N:0 N:0 N:0			19-DEC-2005 0 0		
LIFE LIMIT									
725102	NO. 1 ENGINE - STAGE 2 TURBINE DISC 30B2912-01 A001TPLP REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	3300	N:0 N:0 N:0 N:0			19-DEC-2005 0 0		
LIFE LIMIT									
725103	NO. 1 ENGINE - STAGE 3 TURBINE DISC 30A1853 ATP32721 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	10000	N:0 N:0 N:0 N:0			19-DEC-2005 0 0		
LIFE LIMIT									
725104	NO. 1 ENGINE - STAGE 4 TURBINE DISC 30A1854 ATP32793 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	10000	N:0 N:0 N:0 N:0			19-DEC-2005 0 0		
LIFE LIMIT									
725105	NO. 1 ENGINE - STAGE 5 TURBINE DISC 30A1835 78B357 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	10000	N:0 N:0 N:0 N:0			19-DEC-2005 0 0		
LIFE LIMIT									
725107	NO. 1 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A001TDP6 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	4800	N:0 N:0 N:0 N:0			19-DEC-2005 0 0		
LIFE LIMIT									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725109	NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B2747-01 A001RD0E	MOS HRS/MSC		N:0 N:0			19-DEC-2005 0		
LIFE LIMIT	REF: EMM 72-50-01	ENC ACCCYC 4400		N:0 N:0			0		
725111	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 AWE007596	MOS HRS/MSC		N:0 N:0			19-DEC-2005 0		
LIFE LIMIT	REF: EMM 72-50-01	ENC ACCCYC 4000		N:0 N:0			0		
726001	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING 30B4808-01 A001TH0E	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2005 0		
	REF: EMM 72-60-01	ENC		N:0			0		
+ 726011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)	MOS HRS/MSC	7700	+50			19-DEC-2005 0	(7700) 7788.67	7750
	REF: GENERIC NO REF	ENC					0		
727001	NO. 1 ENGINE - COMBUSTION CHAMBER LINER 30B6146-01 A001TKBX	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2005 0		
	REF: EMM 72-40-01	ENC		N:0			0		
727001A	NO. 1 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER 30B6146-01 A001TKBX	MOS HRS/MSC	3850	+50			09-MAR-2015 3751.2	(7601.2) 7689.87	7651.2
	REF: EMM 72-40-01	ENC					1926		
727002	NO. 1 ENGINE - INNER COMBUSTION LINER ASSEMBLY 30B4561-01 A001TMR9	MOS HRS/MSC	O/C	N:0 N:0			19-DEC-2005 0		
	REF: EMM 72-40-01	ENC		N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727003	NO. 1 ENGINE - OUTER COMBUSTION LINER ASSEMBLY PN SN-UNKNOWN REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	180	+12m			29-DEC-2005 0 0	19-DEC-2021 M	19-DEC-2022
+ 720010 (s)	NO. 2 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24	600			04-MAR-2021 4396.77 2495	PKG	
+ 720015 (s)	NO. 2 ENGINE - EEC - REMOVE, CHECK CONDITION, CLEAN THE CONNECTORS AND REINSTALL PKG 1 REF: EMM 70-00-00	MOS HRS/MSC ENC	24	600			29-DEC-2005 0 0	PKG	
+ 720020 (s)	NO. 2 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24	600			04-MAR-2021 4396.77 2495	PKG	
+ 720030 (s)	NO. 2 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24	600			04-MAR-2021 4396.77 2495	PKG	
+ 720040 (s)	NO. 2 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION PKG 1 REF: EMM 05-20-00	MOS HRS/MSC ENC	24	600			04-MAR-2021 4396.77 2495	PKG	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720050 (s)	NO. 2 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720060 (s)	NO. 2 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720070 (s)	NO. 2 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720080 (s)	NO. 2 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720090 (s)	NO. 2 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640) PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
720095	NO. 2 ENGINE - DISCARD LP COMPRESSOR FAN BLADES PN SN-UNKNOWN	MOS					29-DEC-2005 0		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC	15000				0 0	(15000) 15093	
+ 720100 (s)	NO. 2 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	HRS/MSC ENC	600						

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720110 (s)	NO. 2 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720120 (s)	NO. 2 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720130 (s)	NO. 2 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720140 (s)	NO. 2 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720150 (s)	NO. 2 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720160 (s)	NO. 2 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720170 (s)	NO. 2 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 79-20-01	ENC	600						

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720180 (s)	NO. 2 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE						PKG		
	PKG 1	MOS	24					04-MAR-2021	
		HRS/MSC	600					4396.77	
	REF: EMM 05-20-00	ENC						2495	
+ 720190 (s)	NO. 2 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND						PKG		
	PKG 1	MOS	24					04-MAR-2021	
		HRS/MSC	600					4396.77	
	REF: EMM 05-20-00	ENC						2495	
+ 720200 (s)	NO. 2 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE						PKG		
	PKG 1	MOS	24					04-MAR-2021	
		HRS/MSC	600					4396.77	
	REF: EMM 05-20-00	ENC						2495	
+ 720210 (s)	NO. 2 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS						PKG		
	PKG 1	MOS	24					04-MAR-2021	
		HRS/MSC	600					4396.77	
	REF: EMM 05-20-00	ENC						2495	
+ 720220 (s)	NO. 2 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND.						PKG		
	PKG 1	MOS	24					04-MAR-2021	
		HRS/MSC	600					4396.77	
	REF: EMM 05-20-00	ENC						2495	
+ 720230 (s)	NO. 2 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE						PKG		
	PKG 1	MOS	24					04-MAR-2021	
		HRS/MSC	600					4396.77	
	REF: EMM 05-20-00	ENC						2495	
+ 720240 (s)	NO. 2 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE						PKG		
	PKG 1	MOS	24					04-MAR-2021	
		HRS/MSC	600					4396.77	
	REF: EMM 05-20-00	ENC						2495	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720250 (s)	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE. PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720260 (s)	NO. 2 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720270 (s)	NO. 2 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: See Workcard	ENC	600						
+ 720280 (s)	NO. 2 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720290 (s)	NO. 2 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY. PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720300 (s)	NO. 2 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						
+ 720310 (s)	NO. 2 ENGINE - SPARK IGNITERS, OPERATIONAL TEST PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: EMM 05-20-00	ENC	600						

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723001	NO. 2 ENGINE - FAN HUB 30B2256 A001T63P	MOS HRS/MSC		N:0 N:0			29-DEC-2005 0		
LIFE LIMIT	REF: EMM 72-30-01	ENC ACCCYC	12000	N:0 N:0			0		
723003	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 30B4565-01 A001RW6C	MOS HRS/MSC		N:0 N:0			29-DEC-2005 0		
LIFE LIMIT	REF: EMM 72-30-01	ENC ACCCYC	7000	N:0 N:0			0		
723004	NO. 2 ENGINE - PRESSURE CHECK IMPELLER SHROUD	MOS HRS/MSC	N/A				29-DEC-2005 0		
	REF: GENERIC NO REF	ENC					0		
723005	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR 30B6551-01 TXA1D3506	MOS HRS/MSC		N:0 N:0			25-FEB-2015 3622.55		
LIFE LIMIT	REF: EMM 72-30-01	ENC ACCCYC	12000	N:0 N:0			1881		
723005A	NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR) 30B6551-01 TXA1D3506	MOS HRS/MSC	N/A				25-FEB-2015 3622.55		
NOT APPLICABLE	REF: EMM 72-00-00	ENC					1881		
723008	NO. 2 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 30B4745-01 56B000	MOS HRS/MSC		N:0 N:0			29-DEC-2005 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC ACCCYC	8500	N:0 N:0			0		
723008A	NO. 2 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM 30B4745-01 56B000	MOS HRS/MSC	O/C				29-DEC-2005 0		
	REF: GENERIC NO REF	ENC					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723040	NO. 2 ENGINE - LP COMPRESSOR BLADES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
724010	NO. 2 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM) REF: GENERIC NO REF	MOS HRS/MSC ENC	N/A				29-DEC-2005 0 0		
725001	NO. 2 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING 30B3012CL01 B367 REF: EMM 72-50-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
725003	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 31A1026-03 MTU26344 REF: EMM 72-50-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
725101	NO. 2 ENGINE - STAGE 1 TURBINE DISC 30B2981-01 A001T5KP REF: EMM 72-50-01 LIFE LIMIT	MOS HRS/MSC ENC ACCCYC	3100	N:0 N:0 N:0 N:0			29-DEC-2005 0 0		
725102	NO. 2 ENGINE - STAGE 2 TURBINE DISC 30B2912-01 A001WL6E REF: EMM 72-50-01 LIFE LIMIT	MOS HRS/MSC ENC ACCCYC	3300	N:0 N:0 N:0 N:0			29-DEC-2005 0 0		
725103	NO. 2 ENGINE - STAGE 3 TURBINE DISC 30A1853 MAA13036 REF: EMM 72-50-01 LIFE LIMIT	MOS HRS/MSC ENC ACCCYC	10000	N:0 N:0 N:0 N:0			29-DEC-2005 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725104	NO. 2 ENGINE - STAGE 4 TURBINE DISC 30A1854 MAA13344 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	10000	N:0 N:0 N:0 N:0			29-DEC-2005 0 0		
LIFE LIMIT									
725105	NO. 2 ENGINE - STAGE 5 TURBINE DISC 30A1835 78B332 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	10000	N:0 N:0 N:0 N:0			29-DEC-2005 0 0		
LIFE LIMIT									
725107	NO. 2 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A001TDP4 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	4800	N:0 N:0 N:0 N:0			29-DEC-2005 0 0		
LIFE LIMIT									
725109	NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B2747-01 A001W44T REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	4400	N:0 N:0 N:0 N:0			29-DEC-2005 0 0		
LIFE LIMIT									
725111	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 AWE007301 REF: EMM 72-50-01	MOS HRS/MSC ENC ACCCYC	4000	N:0 N:0 N:0 N:0			29-DEC-2005 0 0		
LIFE LIMIT									
726001	NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING 30B4808-01 A001TH0K REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
LIFE LIMIT									
+ 726011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA) REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727001	NO. 2 ENGINE - COMBUSTION CHAMBER LINER 30B6146-01 A001W1YK REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
727001A	NO. 2 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER 30B6146-01 A001W1YK REF: EMM 72-40-01	MOS HRS/MSC ENC	3850	+50			25-FEB-2015 3622.55 1881	(7472.55) 7688.87	7522.55
727002	NO. 2 ENGINE - INNER COMBUSTION LINER ASSEMBLY 30B4561-01 A001WFXK REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
727003	NO. 2 ENGINE - OUTER COMBUSTION LINER ASSEMBLY PN SN-UNKNOWN REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
CHAPTER 73	ENGINE FUEL AND CONTROL								
732101	NO. 1 ENGINE, ELECTRONIC CONTROL 822821-6-004 05061655 REF:	MOS HRS/MSC AFL	O/C				08-MAR-2012 2600.73 1408		
732102	NO. 2 ENGINE, ELECTRONIC CONTROL 822821-6-004 05061658 REF:	MOS HRS/MSC AFL	O/C				08-MAR-2012 2600.73 1408		
733101	LEFT ENGINE FUEL FLOW TRANSMITTER 7600021-1 519513 REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733102	RIGHT ENGINE FUEL FLOW TRANSMITTER 7600021-1 519518 REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
733103	LEFT ENGINE FUEL FLOW INDICATOR 62000-002 8289 REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
733104	RIGHT ENGINE FUEL FLOW INDICATOR 6608488-001 2948 REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C				23-FEB-2016 3839.9 1974		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
05-P&W-730001	NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT	MOS HRS/MSC ENC	12 1200	+25/-25			31-MAR-2022 4812.73 2767	31-MAR-2023 (6012.73) 6101.4	6037.73
+ 05-P&W-730005	NO. 1 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE	MOS HRS/MSC ENC	1800	+600/-600			31-MAR-2022 4812.73 2767	(6612.73) 6701.4	7212.73
731001	NO. 1 ENGINE - FUEL PUMP 30B1910 MX691512A REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
731002	NO. 1 ENGINE - MOTIVE FLOW VALVE 30B2062 C37569 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731003	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH 30B3500-03 HE0493 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C				07-NOV-2012 2852.1 1527		
731004	NO. 1 ENGINE - UPPER PRIMARY FUEL NOZZLE 31B5832-04 AAB90598 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C				31-MAR-2022 4812.73 2767		
731005	NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE 31B5832-04 1SK07012 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C				31-MAR-2022 4812.73 2767		
731010	NO. 1 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY PN SN-UNKNOWN REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
+ 731011 (s)	NO. 1 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY PKG 1 REF: See Workcard	MOS HRS/MSC ENC	24 600				PKG 04-MAR-2021 4525.42 2540		
+ 731012	NO. 1 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP 30B1910 MX691512A REF: EMM 73-10-02	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
OVERHAUL									
+ 731013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH 30B3500-03 HE0493 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731014	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY	MOS					19-DEC-2005		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
+ 731022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY)	MOS					19-DEC-2005		
	30B2062 C37569 REF: GENERIC NO REF	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
+ 731023	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK	MOS					19-DEC-2005		
	31B5132-01 9959510259 REF: GENERIC NO REF	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
+ 731024	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY	MOS					19-DEC-2005		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
+ 731025	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE	MOS					19-DEC-2005		
	31B5131-01 9959516217 REF: GENERIC NO REF	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
731026	NO. 1 ENGINE - FUEL WASTE EJECTOR	MOS					19-DEC-2005		
	31B5132-01 9959510259 REF: EMM 73-10-03	HRS/MSC ENC	O/C		N:0 N:0 N:0		0 0 0		
+ 731044	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - INLET	MOS					19-DEC-2005		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731045	NO. 1 ENGINE - DISCARD - FUEL SHUT-OFF CABLE	MOS					19-DEC-2005		
DISCARD	REF: EMM 73-10-05	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
731051	NO. 1 ENGINE - FUEL START & DUMP VALVE	MOS					19-DEC-2005		
	31B5131-01	HRS/MSC	O/C	N:0			0		
	9959516217	ENC		N:0			0		
	REF: EMM 73-10-05			N:0			0		
+ 731055	NO. 1 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF	MOS					19-DEC-2005		
OVERHAUL	REF: EMM 73-10-05	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
732001	NO. 1 ENGINE - HYDRO MECHANICAL FUEL CONTROL	MOS					19-DEC-2005		
	31B4469-07	HRS/MSC	O/C	N:0			0		
	SHU05-145	ENC		N:0			0		
	REF: EMM 73-20-01			N:0			0		
+ 732002	NO. 1 ENGINE - REPLACE TRIM PLUG	MOS	120				08-JUL-2021	08-JUL-2031	
	REF: EMM 73-20-02	HRS/MSC ENC					4624.22 2612		
732003	NO. 1 ENGINE - ELECTRICAL FRONT HARNESS	MOS					08-JUL-2021		
	31B3767-01	HRS/MSC	O/C				4624.22		
	EFC00362	ENC					2612		
	REF: See Workcard								
732004	NO. 1 ENGINE - ELECTRICAL REAR HARNESS	MOS					19-DEC-2005		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	ENC		N:0			0		
	REF: EMM 73-20-03			N:0			0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732005	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN SN-UNKNOWN REF: EMM 73-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
+ 732011	NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU 31B4469-07 SHU05-145 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 732012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 732013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR) 30B3089-03 AA54039 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 732021	NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 31B4469-07 SHU05-145 REF: EMM 73-20-01	MOS HRS/MSC ENC	N/A				19-DEC-2005 0 0		
732101	NO. 1 ENGINE - ENGINE FADEC 30B3200-06 05061658 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
05-P&W-730001	NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT REF: EMM 73-10-03	MOS HRS/MSC ENC	12 1200	+25/-25			31-MAR-2022 4685.08 2722	31-MAR-2023 (5885.08) 6101.4	5910.08

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-P&W-730005	NO. 2 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE	MOS					31-MAR-2022		
	REF: EMM 73-10-04	HRS/MSC ENC	1800	+600/-600			4685.08 2722	(6485.08) 6701.4	7085.08
731001	NO. 2 ENGINE - FUEL PUMP	MOS					29-DEC-2005		
	30B1910	HRS/MSC	O/C	N:0			0		
	MX692577A	ENC		N:0			0		
	REF: EMM 73-10-02								
731002	NO. 2 ENGINE - MOTIVE FLOW VALVE	MOS					29-DEC-2005		
	30B2062	HRS/MSC	O/C	N:0			0		
	C37573	ENC		N:0			0		
	REF: EMM 73-20-01								
731003	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH	MOS					25-FEB-2015		
	30B3500-03	HRS/MSC	O/C				3622.55		
	HE0923	ENC					1881		
	REF: EMM 73-10-03								
731004	NO. 2 ENGINE - UPPER PRIMARY FUEL NOZZLE	MOS					31-MAR-2022		
	31B5832-04	HRS/MSC	O/C				4685.08		
	1ACT0537	ENC					2722		
	REF: EMM 73-10-04								
731005	NO. 2 ENGINE - LOWER PRIMARY FUEL NOZZLE	MOS					31-MAR-2022		
	31B5832-04	HRS/MSC	O/C				4685.08		
	1ANT1948	ENC					2722		
	REF: EMM 73-10-04								
731010	NO. 2 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY	MOS					29-DEC-2005		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	ENC		N:0			0		
	REF: EMM 73-10-05								

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731011 (s)	NO. 2 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY PKG 1	MOS	24				PKG 04-MAR-2021 4396.77 2495		
	REF: See Workcard	HRS/MSC 600 ENC							
+ 731012	NO. 2 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP 30B1910 MX692577A	MOS	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
OVERHAUL	REF: EMM 73-10-02	ENC							
+ 731013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH 30B3500-03 HE0923	MOS	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
	REF: GENERIC NO REF	ENC							
+ 731014	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY REF: EMM 73-10-04	MOS	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
OVERHAUL		HRS/MSC ENC							
+ 731022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY) 30B2062 C37573	MOS	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
	REF: GENERIC NO REF	ENC							
+ 731023	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK 31B5132-01 9959510262	MOS	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
	REF: GENERIC NO REF	ENC							
+ 731024	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY REF: EMM 73-10-04	MOS	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
OVERHAUL		HRS/MSC ENC							

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731025	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE 31B5131-01 9959516392 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
731026	NO. 2 ENGINE - FUEL WASTE EJECTOR 31B5132-01 9959510262 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
+ 731044	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - INLET REF: EMM 73-10-04	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 731045	NO. 2 ENGINE - DISCARD - FUEL SHUT-OFF CABLE REF: EMM 73-10-05	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
731051	NO. 2 ENGINE - FUEL START & DUMP VALVE 31B5131-01 9959516392 REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			11-OCT-2007 691.03 404		
+ 731055	NO. 2 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF REF: EMM 73-10-05	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
732001	NO. 2 ENGINE - HYDRO MECHANICAL FUEL CONTROL 31B4469-07 SHU05-180 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 732002	NO. 2 ENGINE - REPLACE TRIM PLUG REF: EMM 73-20-02	MOS HRS/MSC ENC	120				05-SEP-2020 4251.57 2393	05-SEP-2030	
732003	NO. 2 ENGINE - ELECTRICAL FRONT HARNESS 31B3767-01 AA57774 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
732004	NO. 2 ENGINE - ELECTRICAL REAR HARNESS 31B3766-01 AA55618 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
732005	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN SN-UNKNOWN REF: EMM 73-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
+ 732011	NO. 2 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU 31B4469-07 SHU05-180 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 732012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 732013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSES (OUTER, INNER, FRONT AND REAR) 30B3089-03 AA57185 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 732021	NO. 2 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 31B4469-07 SHU05-180 REF: EMM 73-20-01	MOS HRS/MSC ENC	N/A				29-DEC-2005 0 0		
732101	NO. 2 ENGINE - ENGINE FADEC 30B3200-06 05061655 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
CHAPTER 74 IGNITION									
743003	ENGINE WARNING LIGHT BOX PN SN-UNKNOWN REF: AMM 74-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
741001	NO. 1 ENGINE - NO. 1 IGNITION EXCITER 31B4636-02 NNA05392291 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
741002	NO. 1 ENGINE - NO. 2 IGNITION EXCITER 31B4636-02 NNA05392293 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
741003	NO. 1 ENGINE - NO. 1 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
741004	NO. 1 ENGINE - NO. 2 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 741011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX 31B4636-02 NNA05392291 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 741012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX 31B4636-02 NNA05392293 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 741021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 741022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 741031	NO. 1 ENGINE - REPLACE - NO. 1 IGNITER PLUGS 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 741032	NO. 1 ENGINE - REPLACE - NO. 2 IGNITER PLUGS PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
742025	NO. 1 ENGINE - NO. 1 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				07-FEB-2018 3763.9 1934		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742026	NO. 1 ENGINE - NO. 2 IGNITER PLUG PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
741001	NO. 2 ENGINE - NO. 1 IGNITION EXCITER 31B4636-02 NNA05444498 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
741002	NO. 2 ENGINE - NO. 2 IGNITION EXCITER 31B4636-02 NNA05444498 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
741003	NO. 2 ENGINE - NO. 1 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
741004	NO. 2 ENGINE - NO. 2 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
+ 741011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX 31B4636-02 NNA05444498 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 741012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX 31B4636-02 NNA05444498 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 741021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 741022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 741031	NO. 2 ENGINE - REPLACE - NO. 1 IGNITER PLUGS 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
REPLACE									
+ 741032	NO. 2 ENGINE - REPLACE - NO. 2 IGNITER PLUGS 31B5168-01 NSN REF: EMM 74-10-01	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
REPLACE									
742025	NO. 2 ENGINE - NO. 1 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				07-FEB-2018 3635.3 1889		
742026	NO. 2 ENGINE - NO. 2 IGNITER PLUG 31B5168-01 NSN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				25-FEB-2015 3622.55 1881		

CHAPTER 75

AIR

ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04

751001	NO. 1 ENGINE - ANTI-ICING SOLENOID VALVE 31B5108-04 AL1311 REF: EMM 75-10-01	MOS HRS/MSC ENC	O/C				19-DEC-2005 0 0		
--------	---	-----------------------	-----	--	--	--	-----------------------	--	--

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 751011	NO. 1 ENGINE - OVERHAUL - ANTI-ICING VALVE 31B5108-04 AL1311 REF: EMM 75-10-01	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
OVERHAUL									
+ 753001	NO. 1 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES REF: EMM 75-30-01	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
OVERHAUL									
+ 753002	NO. 1 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
DISCARD									
+ 753003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
753004	NO. 1 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR 31B5255-01 SAU05-165 REF: EMM 75-30-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
+ 753012	NO. 1 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID REF: EMM 75-30-02	MOS HRS/MSC ENC	N/A				19-DEC-2005 0 0		
DISCARD									
+ 753014	NO. 1 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR REF: GENERIC NO REF	MOS HRS/MSC ENC	N/A				19-DEC-2005 0 0		
DISCARD									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753024	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR 31B5255-01 SAU05-165 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
753081	NO. 1 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID 30B7178-02 AGJA000A792 REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C				08-JUL-2021 4624.22 2612		
753082	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
753083	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE PN SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	N/A				19-DEC-2005 0 0		
753101	NO. 1 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 AHX006489 REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50	N:3173.5	O:0	08-JUL-2021 4624.22 2612	(8474.22) 8562.88	8524.22
REPLACE									
753102	NO. 1 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 AHX006445 REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50	N:3173.5	O:0	08-JUL-2021 4624.22 2612	(8474.22) 8562.88	8524.22
REPLACE									
753105	NO. 1 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 AHX013655 REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50	O:0		08-JUL-2021 4624.22 2612	(8474.22) 8562.88	8524.22
REPLACE									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753111	NO. 1 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 AHX006489 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			08-JUL-2021 4624.22 2612	(6124.22) 6212.88	6424.22
+ 753112	NO. 1 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 AHX006445 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			08-JUL-2021 4624.22 2612	(6124.22) 6212.88	6424.22
+ 753115	NO. 1 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 AHX013655 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			08-JUL-2021 4624.22 2612	(6124.22) 6212.88	6424.22
754001	NO. 1 ENGINE - PRESSURE P3 TRANSDUCER 30B3033-03 KL058948 REF: EMM 75-30-03	MOS HRS/MSC ENC	O/C				07-NOV-2012 2852.1 1527		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
751001	NO. 2 ENGINE - ANTI-ICING SOLENOID VALVE 31B5108-04 NAL1398 REF: EMM 75-10-01	MOS HRS/MSC ENC	O/C				29-DEC-2005 0 0		
+ 751011	NO. 2 ENGINE - OVERHAUL - ANTI-ICING VALVE 31B5108-04 NAL1398 REF: EMM 75-10-01	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
OVERHAUL									
+ 753001	NO. 2 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES REF: EMM 75-30-01	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
OVERHAUL									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753002	NO. 2 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID	MOS					29-DEC-2005		
DISCARD	REF: GENERIC NO REF	HRS/MSC	7700	+50			0	(7700) 7916.32	7750
		ENC					0		
+ 753003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER	MOS					29-DEC-2005		
	REF: GENERIC NO REF	HRS/MSC	7700	+50			0	(7700) 7916.32	7750
		ENC					0		
753004	NO. 2 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR	MOS					04-JUL-2011		
	2600-1	HRS/MSC	O/C	O:0			2290.88		
	2600047	ENC		O:0			1230		
	REF: EMM 75-30-04			O:0					
+ 753012	NO. 2 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID	MOS					29-DEC-2005		
DISCARD	REF: EMM 75-30-02	HRS/MSC	N/A				0		
		ENC					0		
+ 753014	NO. 2 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR	MOS					29-DEC-2005		
DISCARD	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		ENC					0		
+ 753024	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR	MOS					29-DEC-2005		
	2600-1	HRS/MSC	7700	+50			0	(7700) 7916.32	7750
	2600047	ENC					0		
	REF: GENERIC NO REF								
753081	NO. 2 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID	MOS					25-FEB-2015		
	100094000-003	HRS/MSC	O/C	O:0			3622.55		
	841	ENC		O:0			1881		
	REF: EMM 75-30-02			O:0					

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753082	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
753083	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE PN SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	N/A				29-DEC-2005 0 0		
753101	NO. 2 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5758-01 24A442 REPLACE REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50 O:0 O:0 O:0			03-JUN-2011 2255.63 1215	(6105.63) 6321.95	6155.63
753102	NO. 2 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5758-01 25A074 REPLACE REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50 O:0 O:0 O:0			03-JUL-2011 2255.63 1215	(6105.63) 6321.95	6155.63
753105	NO. 2 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 37A480 REPLACE REF: EMM 75-30-01	MOS HRS/MSC ENC	3850	+50 O:0 O:0 O:0			03-JUL-2011 2255.63 1215	(6105.63) 6321.95	6155.63
+ 753111	NO. 2 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5758-01 24A442 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			25-FEB-2015 3622.55 1881	(5122.55) 5338.87	5422.55
+ 753112	NO. 2 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5758-01 25A074 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			25-FEB-2015 3622.55 1881	(5122.55) 5338.87	5422.55

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753115	NO. 2 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 37A480 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			25-FEB-2015 3622.55 1881	(5122.55) 5338.87	5422.55
754001	NO. 2 ENGINE - PRESSURE P3 TRANSDUCER PN SN-UNKNOWN REF: EMM 75-30-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
CHAPTER 76 ENGINE CONTROLS									
761001	THROTTLE/THRUST REVERSER QUADRANT ASSEMBLY PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
E7614000 (s)	FUNCTIONAL TEST OF APR (AUTOMATIC PERFORMANCE RESERVE) SYSTEM. (REFER TO 76-14-00) PKG 3 REF: AMM 76-14-00	MOS HRS/MSC AFL	12	+14d/-14d +25/-25			PKG 31-MAR-2022 4901.4 2815		
H7611007 (s)	VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS FOR SECURITY AND GENERAL CONDITION. REMOVAL OF UPPER COWLING IS REQUIRED FOR THIS INSPECTION. (REFER TO 5-10-00) PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
J7611006 (s)	VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS FOR SECURITY AND GENERAL CONDITION, INCLUDING THE SHIELDED HARNESSES ROUTED TO THE FADEC MAINTENANCE PANEL. PAY PARTICULAR ATTENTION TO SIGNS OF CHAFING AGAINST STRUCTURE ADJACENT TO ELECTRICAL BONDING CLAMP LOCATIONS. (PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24	+14d/-14d +25/-25			31-MAR-2022 4901.4 2815		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
761101	NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS 6008016-031 30 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761103	NO. 1 ENGINE - FADEC, ENGINE HARNESS 6008016-029 167 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
761105	NO. 1 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS 6008408-033 235 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
761107	NO. 1 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS 6008408-037 246 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
761101	NO. 2 ENGINE - FADEC, ENGINE TAILCONE HARNESS 6008016-032 30 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
761103	NO. 2 ENGINE - FADEC, ENGINE HARNESS 6008016-030 171 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
761105	NO. 2 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS 6008408-032 248 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
761107	NO. 2 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS 6008408-038 168 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		

CHAPTER 77 ENGINE INDICATING

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771001	LEFT ENGINE N1 INDICATOR 64500-002 7449 REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
771002	RIGHT ENGINE N1 INDICATOR 64500-002 7441 REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
771003	LEFT ENGINE N2 INDICATOR 6608508-001 5465L REF: AMM 77-10-02	MOS HRS/MSC AFL	O/C				23-FEB-2016 3839.9 1974		
771004	RIGHT ENGINE N2 INDICATOR 64000-002 7568 REF: AMM 77-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
772001	LEFT ENGINE ITT INDICATOR 61500-002 7515 REF: AMM 77-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
772002	RIGHT ENGINE ITT INDICATOR 61500-002 7518 REF: AMM 77-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
773000	DOWNLOAD ENGINE DIAGNOSTIC SYSTEM FLASHCARD REF:	DAYS HRS/MSC AFL	30				31-MAR-2022 4901.4 2815	30-APR-2022	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774001	ENGINE DIAGNOSTIC UNIT 9-361-06 F244 REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C	N:114 R:5 N:3400.3 R:0 N:2146 R:0			13-APR-2017 3840.35 1975		
774001A	REPLACE ENGINE DIAGNOSTIC UNIT INTERNAL BATTERY 9-361-06 F244 REF:	MOS HRS/MSC AFL	36				29-OCT-2019 4249.1 2310	29-OCT-2022	
774002	CONTROL AND DISPLAY (CDU) UNIT 9-362-03 C194 REF: AMM 77-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
774003	LEFT ENGINE ISOLATION INTERFACE UNIT 9-343-04 C340 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
774004	RIGHT ENGINE ISOLATION INTERFACE UNIT 9-343-04 C339 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
774101	SIGNAL CONDITIONING BOX 6600504-5 AB49447 REF: AMM 77-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
774103	LEFT ENGINE VIBRATION ACCELEROMETER 6600504-2 1408 REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774104	RIGHT ENGINE VIBRATION ACCELEROMETER 6600504-2 1415 REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
+ 771001	NO. 1 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
DISCARD	REF: GENERIC NO REF								
+ 771011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
	REF: EMM 77-10-01								
+ 771021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR 30B1449 CH3507 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 771022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR 30B1449 CH3505 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
771027	NO. 1 ENGINE - CHANNEL A N1 SPEED SENSOR PN SN-UNKNOWN REF: EMM 77-10-01	MOS HRS/MSC ENC	3850	+50	N:0 N:0 N:0		07-FEB-2018 3763.9 1934	(7613.9) 7702.57	7663.9
771028	NO. 1 ENGINE - CHANNEL B N1 SPEED SENSOR PN SN-UNKNOWN REF: EMM 77-10-01	MOS HRS/MSC ENC	3850	+50	N:0 N:0 N:0		07-FEB-2018 3763.9 1934	(7613.9) 7702.57	7663.9

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771040	NO. 1 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 30B1449 CH3507 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				07-NOV-2012 2852.1 1527		
771041	NO. 1 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449 CH3505 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				07-NOV-2012 2852.1 1527		
772010	NO. 1 ENGINE - T4.5 THERMOCOUPLE HARNESS PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
+ 772013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
772014	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
772015	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
+ 772021	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESES AND T4.5 TERMINAL BOX PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 772022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
+ 771001	NO. 2 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS DISCARD	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 771011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS REF: EMM 77-10-01	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 771021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR 30B1449 CH3498 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 771022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR 30B1449 CH3542 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
771027	NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR 30B6152-04 CH1510 REF: EMM 77-10-01	MOS HRS/MSC ENC	3850	+50	N:0 N:0 N:0		25-FEB-2015 3622.55 1881	(7472.55) 7688.87	7522.55
771028	NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR 30B6150-04 CH1508 REF: EMM 77-10-01	MOS HRS/MSC ENC	3850	+50	N:0 N:0 N:0		25-FEB-2015 3622.55 1881	(7472.55) 7688.87	7522.55

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771040	NO. 2 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 30B1449 CH3498 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				25-FEB-2015 3622.55 1881		
771041	NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449 CH3542 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				25-FEB-2015 3622.55 1881		
772010	NO. 2 ENGINE - T4.5 THERMOCOUPLE HARNESS PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
+ 772013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
772014	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR 30B5895-02 ADXAB003533 REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C				25-FEB-2015 3622.55 1881		
772015	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
+ 772021	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESES AND T4.5 TERMINAL BOX PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 772022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS 30B5895-02 ADXAB003533 REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
CHAPTER 78 EXHAUST									
780001	LEFT THRUST REVERSER 282-0052-519 730 REF: AMM 78-30-05	MOS HRS/MSC AFL	O/C				11-MAR-2006 0 0		
780002	RIGHT THRUST REVERSER 282-0052-521 731 REF: AMM 78-30-05	MOS HRS/MSC AFL	O/C				11-MAR-2006 0 0		
783001	LEFT THRUST REVERSER RELAY BOX 6018425-017 A00476378-01(B) REF: AMM 78-30-01	MOS HRS/MSC AFL	O/C			N:1337.55 N:723	29-MAY-2009 1337.55 723		
783002	RIGHT THRUST REVERSER RELAY BOX 6018425-017 A00476320-01(B) REF: AMM 78-30-01	MOS HRS/MSC AFL	O/C			N:1337.55 N:723	29-MAY-2009 1337.55 723		
783005	LEFT THRUST REVERSER HYDRAULIC CONTROL UNIT 282D0007-507 0691 REF: AMM 78-30-03	MOS HRS/MSC AFL	O/C				08-MAR-2012 2600.73 1408		
783006	RIGHT THRUST REVERSER HYDRAULIC CONTROL UNIT 282D0007-507 0461 REF: AMM 78-30-03	MOS HRS/MSC AFL	O/C				22-NOV-2013 3076.45 1651		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783009	THRUST REVERSER INTERFACE BOX PN SN-UNKNOWN REF: AMM 78-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783013	LEFT ENGINE THRUST REVERSER UPPER DOOR PN SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783014	RIGHT ENGINE THRUST REVERSER UPPER DOOR PN SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783015	LEFT ENGINE THRUST REVERSER LOWER DOOR PN SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783016	RIGHT ENGINE THRUST REVERSER LOWER DOOR PN SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783025	LEFT ENGINE THRUST REVERSER SWITCH CABLE PN SN-UNKNOWN REF: AMM 78-30-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783026	RIGHT ENGINE THRUST REVERSER SWITCH CABLE PN SN-UNKNOWN REF: AMM 78-30-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783105	LEFT OUTBOARD THRUST REVERSER ACTUATOR 282D0006-501 1315R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783106	LEFT INBOARD THRUST REVERSER ACTUATOR 282D0006-501 1312R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783107	RIGHT INBOARD THRUST REVERSER ACTUATOR 282D0006-501 1313R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783108	RIGHT OUTBOARD THRUST REVERSER ACTUATOR 282D0006-501 1314R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783115	LEFT UPPER SECONDARY LOCK ACTUATOR 266D0486-507 1507 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783116	RIGHT UPPER SECONDARY LOCK ACTUATOR 266D0486-507 1508 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783117	LEFT LOWER SECONDARY LOCK ACTUATOR 266D0486-507 1510 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783118	RIGHT LOWER SECONDARY LOCK ACTUATOR 266D0486-507 1509 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783132	LEFT OUTBOARD STANG FAIRING ASSEMBLY PN SN-UNKNOWN REF: AMM 78-30-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783136	RIGHT OUTBOARD STANG FAIRING ASSEMBLY PN SN-UNKNOWN REF: AMM 78-30-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783142	LEFT INBOARD STANG FAIRING ASSEMBLY PN SN-UNKNOWN REF: AMM 78-30-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
783146	RIGHT INBOARD STANG FAIRING ASSEMBLY PN SN-UNKNOWN REF: AMM 78-30-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
C7830027A (s)	VISUAL INSPECTION THRUST REVERSER DRIVER LINKS (EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 78-30-00) PKG 31 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-MAR-2006 0 0		
C7830027B (s)	VISUAL INSPECTION THRUST REVERSER DRIVER LINKS (EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 78-30-00) PKG 32 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C7830029A (s)	VISUAL INSPECTION THRUST REVERSER OVER-CENTER LINK (EIGHT PER AIRCRAFT) AND OVER-CENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS						PKG		
	PKG 31	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
C7830029B (s)	VISUAL INSPECTION THRUST REVERSER OVER-CENTER LINK (EIGHT PER AIRCRAFT) AND OVER-CENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS						PKG		
	PKG 32	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
C7830031A (s)	VISUAL INSPECTION THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS						PKG		
	PKG 31	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
C7830031B (s)	VISUAL INSPECTION THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS						PKG		
	PKG 32	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
C7830033A (s)	VISUAL INSPECTION THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS						PKG		
	PKG 31	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
C7830033B (s)	VISUAL INSPECTION THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS						PKG		
	PKG 32	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C7830035A (s)	VISUAL INSPECTION THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS						PKG		
	PKG 31	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
C7830035B (s)	VISUAL INSPECTION THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS						PKG		
	PKG 32	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
D7830015A (s)	CHECK THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION						PKG		
	PKG 31	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
D7830015B (s)	CHECK THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION						PKG		
	PKG 32	MOS					11-MAR-2006		
		HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
E7830038 (s)	DETAILED INSPECTION THRUST REVERSERS FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 78-30-00.)						PKG		
	PKG 15	MOS	48	+14d/-14d			31-MAR-2022		
		HRS/MSC	1200	+25/-25			4901.4		
	REF: AMM 78-30-00	AFL					2815		
M7830084 (s)	INSPECT THRUST REVERSER SECONDARY LATCH - LUBRICATE LATCH SWITCH PLUNGERS, ROLLER ASSEMBLY, AND ACTUATOR PINS. (REFER TO 12-21-04)						PKG		
	PKG 3	MOS	12	+14d/-14d			31-MAR-2022		
		HRS/MSC	300	+25/-25			4901.4		
	REF: AMM 12-21-04	AFL					2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P7830022 (s)	FUNCTIONAL TEST OF THRUST REVERSER HYDRAULIC CONTROL VALVE ASSEMBLY CHECK VALVES. (REFER TO 78-30-03.) PKG 27	MOS	144	+14d/-14d			07-FEB-2018 3852.6		
	REF: AMM 78-30-03	AFL	6000	+25/-25			1982		
T7830014 (s)	VISUAL INSPECTION OF THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION. (REFER TO 5-10-00) PKG 9	MOS	24	+14d/-14d			31-MAR-2022 4901.4		
	REF: GENERIC NO REF	AFL	600	+25/-25			2815		
T7830016 (s)	VISUAL INSPECTION OF THRUST REVERSER ACTUATOR FOR HYDRAULIC LEAKS, DAMAGED PUSHROD, DAMAGED FLEXIBLE HOSES, AND SECURITY OF INSTALLATION. (REFER TO 5-10-00) PKG 9	MOS	24	+14d/-14d			31-MAR-2022 4901.4		
	REF: GENERIC NO REF	AFL	600	+25/-25			2815		
T7830018 (s)	VISUAL INSPECTION OF HYDRAULIC CONTROL UNITS, PRESSURE SWITCH, CHECK VALVES, AND HYDRAULIC LINES FOR LEAKAGE, CLEANLINESS, SECURITY OF INSTALLATION, AND CONDITION OF ELECTRICAL COMPONENTS. (REFER TO 5-10-00) PKG 9	MOS	24	+14d/-14d			31-MAR-2022 4901.4		
	REF: GENERIC NO REF	AFL	600	+25/-25			2815		
T7830020 (s)	VISUAL INSPECTION OF STOW AND DEPLOY SWITCHES FOR SECURITY OF INSTALLATION AND CONDITION OF ELECTRICAL COMPONENTS. VISUALLY INSPECT SHIELDED ELECTRICAL THRUST REVERSER HARNESS FOR CONDITION. (REFER TO 5-10-00) PKG 9	MOS	24	+14d/-14d			31-MAR-2022 4901.4		
	REF: GENERIC NO REF	AFL	600	+25/-25			2815		
T7830026 (s)	VISUAL INSPECTION OF THRUST REVERSER DRIVER LINKS(EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT.) INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00) PKG 9	MOS	24	+14d/-14d			31-MAR-2022 4901.4		
	REF: GENERIC NO REF	AFL	600	+25/-25			2815		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T7830028 (s)	VISUAL INSPECTION OF THRUST REVERSER OVERCENTER LINK (EIGHT PER AIRCRAFT) AND OVERCENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T7830030 (s)	VISUAL INSPECTION OF THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATI						PKG		
	PKG 9	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T7830032 (s)	VISUAL INSPECTION OF THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T7830034 (s)	VISUAL INSPECTION OF THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T7830039 (s)	VISUAL INSPECTION OF FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d				31-MAR-2022	
		HRS/MSC	600	+25/-25				4901.4	
	REF: GENERIC NO REF	AFL						2815	
T7830085 (s)	FUNCTIONAL TEST ** OF THE THRUST REVERSER WITH WHEEL SPEED DETECT INTERFACE. (REFER TO 78-30-00.) (AWL**)						PKG		
	PKG 15	MOS	48	+14d/-14d				31-MAR-2022	
		HRS/MSC	1200	+25/-25				4901.4	
	REF: AMM 78-30-00	AFL						2815	

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U7830010A (s)	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION PKG 29 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				PKG 17-MAR-2015 3839.9 1974		
U7830010B (s)	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				PKG 17-MAR-2015 3839.9 1974		
U7830012A (s)	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE PKG 29 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				PKG 17-MAR-2015 3839.9 1974		
U7830012B (s)	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE PKG 30 REF: GENERIC NO REF	MOS HRS/MSC AFL	3850				PKG 17-MAR-2015 3839.9 1974		

CHAPTER 79
OIL

793001	LEFT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR 65000-003 7484 REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
793002	RIGHT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR 65000-003 7485 REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
793003	LEFT ENGINE OIL PRESSURE TRANSDUCER 7600019-1 6801-7-1009 REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793004	RIGHT ENGINE OIL PRESSURE TRANSDUCER 7600019-1 6801-7-1018 REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
793010	LEFT ENGINE OIL TEMPERATURE BULB MS28034-3 L8275 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
793011	RIGHT ENGINE OIL TEMPERATURE BULB MS28034-3 112338 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-MAR-2006 0 0		
ENGINE NO. 1 Model : PW305A Serial # PCE-CA0457 Part # 31B4067-04									
05-P&W-790001	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT REF: EMM 79-20-01	MOS HRS/MSC ENC	12 1200	+25/-25			31-MAR-2022 4812.73 2767	31-MAR-2023 (6012.73) 6101.4	6037.73
05-P&W-790002	NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE REF: EMM 72-00-00	MOS HRS/MSC ENC	12 600	+50/-50			31-MAR-2022 4812.73 2767	31-MAR-2023 (5412.73) 5501.4	5462.73
792001	NO. 1 ENGINE - OIL PUMP 30B4857-01 EC01A000A068 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		
792002	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			19-DEC-2005 0 0		

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792005	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH 30B1506 1845 REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C				07-NOV-2012 2852.1 1527		
792010	NO. 1 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH 30B1948 0951 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				07-NOV-2012 2852.1 1527		
+ 792011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
+ 792012	NO. 1 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
792020	NO. 1 ENGINE - OIL PUMP HOUSING PN SN-UNKNOWN REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2005 0 0		
792035	NO. 1 ENGINE - OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		19-DEC-2005 0 0		
+ 793001	NO. 1 ENGINE - DISCARD - CHIP DETECTOR REF: EMM 79-30-01	MOS HRS/MSC ENC	7700	+50			19-DEC-2005 0 0	(7700) 7788.67	7750
DISCARD									

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793002	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH	MOS					19-DEC-2005		
	REF: EMM 79-30-02	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
+ 793003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP	MOS					19-DEC-2005		
	REF: EMM 79-30-03	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
793005	NO. 1 ENGINE - CHIP DETECTOR	MOS					19-DEC-2005		
REPLACE	PN SN-UNKNOWN REF: EMM 79-30-01	HRS/MSC ENC	O/C	N:0 N:0 N:0			0 0 0		
+ 793013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)	MOS					19-DEC-2005		
	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	7700	+50			0 0	(7700) 7788.67	7750
793030	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR	MOS					19-DEC-2005		
	PN SN-UNKNOWN REF: EMM 79-30-03	HRS/MSC ENC	O/C	N:0 N:0 N:0			0 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-CA0459 Part # 31B4067-04									
05-P&W-790001	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT	MOS	12				31-MAR-2022	31-MAR-2023	
	REF: EMM 79-20-01	HRS/MSC ENC	1200	+25/-25			4685.08 2722	(5885.08) 6101.4	5910.08
05-P&W-790002	NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE	MOS	12				31-MAR-2022	31-MAR-2023	
	REF: EMM 72-00-00	HRS/MSC ENC	600	+50/-50			4685.08 2722	(5285.08) 5501.4	5335.08

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022
Owner/Operator: WP AIR LLC
Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792001	NO. 2 ENGINE - OIL PUMP 30B4857-01 EC01A000A118 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
792002	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
792005	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH 30B1506 1871 REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C				25-FEB-2015 3622.55 1881		
792010	NO. 2 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
+ 792011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 792012	NO. 2 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
792020	NO. 2 ENGINE - OIL PUMP HOUSING PN SN-UNKNOWN REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792035	NO. 2 ENGINE - OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
+ 793001	NO. 2 ENGINE - DISCARD - CHIP DETECTOR REF: EMM 79-30-01	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
DISCARD									
+ 793002	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH REF: EMM 79-30-02	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
+ 793003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP REF: EMM 79-30-03	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
793005	NO. 2 ENGINE - CHIP DETECTOR PN SN-UNKNOWN REF: EMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		
REPLACE									
+ 793013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7700	+50			29-DEC-2005 0 0	(7700) 7916.32	7750
793030	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR PN SN-UNKNOWN REF: EMM 79-30-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-DEC-2005 0 0		

CHAPTER 80 STARTING

Status Report

LEARJET 60 S/N 60 300 (N357WP): 4901.4 HRS, 2815 AFL as of 31-Mar-2022

Owner/Operator: WP AIR LLC

Report Date: 13-APR-2022

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
801001	CROSS START RELAY BOX PN SN-UNKNOWN REF: AMM 80-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-MAR-2006 0 0	
801002	AIR START RELAY BOX PN SN-UNKNOWN REF: AMM 80-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-MAR-2006 0 0	