

OWNER: GOLDENEYE LLC		OPERATOR: GOLDENEYE LLC	
ADDRESS: 422 BEECHER ROAD GAHANNA COLUMBUS OH 43230		ADDRESS: 422 BEECHER ROAD GAHANNA COLUMBUS OH 43230	
OFFICE:		OFFICE:	
FAX:		FAX:	
ANALYST:	PATRICK VITAMVAS	+1-316-462-2484 (DIRECT)	800-787-9749 (EFAX-CARDS)
EMAIL:	PVITAMVAS@CAMPSYSTEMS.COM	+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)
		WWW.CAMPSYSTEMS.COM	
PROJECTED: 12 MOS. to 05-MAR-2026			

AIRCRAFT	SERIAL/REGNO: 60 320/N328AJ	MODEL:	LEARJET 60XR	MANUFACTURER: BOMBARDIER AVIATION	
CERTIFICATION DATE: 22-AUG-2007		LAST ACTUALS:		PROJECTED:	
		1385	A/C HRS	as of 13-FEB-2025	1745
		1094	AFL	as of 13-FEB-2025	1334
		989.2	APH	as of 16-OCT-2024	1109
		1849	ACH	as of 16-OCT-2024	1909

APU	SERIAL / PART: SP-E060440/4503134			MODEL:	T-20G-10C3A (CIMMS)		MANUFACTURER: HAMILTON SUNDSTRAND CORPORATION	
INSTALLED ON: 17-AUG-2007				LAST ACTUALS:			PROJECTED:	
7.5	APU HRS	0 A/C HRS	989.2	APU HRS	as of 16-OCT-2024	1109.20		
98	APUS		1935	APUS	as of 02-OCT-2024	2115		

ENGINE NO. 1	SERIAL/PART: PCE-CA0499/31B4067-04		MODEL:	PW305A		MANUFACTURER: PRATT & WHITNEY CANADA CORP.	
INSTALLED ON: 10-NOV-2006			LAST ACTUALS:			PROJECTED:	
0	ENG. HRS	0 A/C HRS	1385	ENG. HRS	as of 13-FEB-2025	1745	
0	ENC		1094	ENC	as of 13-FEB-2025	1334	

ENGINE NO. 2	SERIAL / PART: PCE-CA0498/31B4067-04		MODEL:	PW305A		MANUFACTURER: PRATT & WHITNEY CANADA CORP.	
INSTALLED ON: 11-NOV-2006			LAST ACTUALS:			PROJECTED:	
0	ENG. HRS	0 A/C HRS	1385	ENG. HRS	as of 13-FEB-2025	1745	
0	ENC		1094	ENC	as of 13-FEB-2025	1334	

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of:
13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
720000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION								Service ATA:72
	MOS	24 (+12m)	04-Nov-22		04-Nov-24	04-Nov-25	TOL (+244 d)	05-Mar-2025	28
	HRS		1232						153
	ENC		960						134
REF: EMM 72-00-00									
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION								Service ATA:72
	MOS	24 (+12m)	04-Nov-22		04-Nov-24	04-Nov-25	TOL (+244 d)	05-Mar-2025	28
	HRS		1232						153
	ENC		960						134
REF: EMM 72-00-00									
05-T20G-HS-490003	APU - PERFORM APU OIL & FILTER CHANGE								Service ATA:05
	MOS	24	24-Mar-23		24-Mar-25		19 d	24-Mar-2025	23.4
	HRS	500	916.4		1416.4		427.2		72.8
	APUS		1818						117
REF: MM 49-20-00									
05-T20G-HS-490011	APU - REPLACE FUEL INLET FILTER								Service ATA:05
	MOS	24	24-Mar-23		24-Mar-25		19 d	24-Mar-2025	23.4
	HRS	500	916.4		1416.4		427.2		72.8
	APUS		1818						117
REF: MM 49-20-00									
05-10-29-B2432010	INSPECT MAIN AIRCRAFT BATTERY INSTALLATION								Service ATA:24
	MOS	6 (+14d/-14d)	12-Nov-24	Adj:-44d	29-Mar-25	12-Apr-25	24 d (+14)	29-Mar-2025(2)	3.8
	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 24-31-01									
243063A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010								Service ATA:24
PN:501-1712-02	MOS	6 (+14d/-14d)	12-Nov-24	Adj:-44d	29-Mar-25	12-Apr-25	24 d (+14)	29-Mar-2025(2)	3.8
SN:2633	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 24-32-01									
243064A	PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 3 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010								Service ATA:24
PN:501-1712-02	MOS	6 (+14d/-14d)	12-Nov-24	Adj:-44d	29-Mar-25	12-Apr-25	24 d (+14)	29-Mar-2025(2)	3.8
SN:81687	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 24-32-01									

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of:
13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
262013A CHECK FORWARD FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY (REF TO 05-10-00)									Service ATA:26
PN:32700004-1	MOS	6 (+14d/-14d)	12-Nov-24	Adj:-44d	29-Mar-25	12-Apr-25	24 d (+14)	29-Mar-2025(2)	3.8
SN:25982C1	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 26-21-00									
262014A CHECK AFT FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 05-10-00)									Service ATA:26
PN:32700004-1	MOS	6 (+14d/-14d)	12-Nov-24	Adj:-44d	29-Mar-25	12-Apr-25	24 d (+14)	29-Mar-2025(2)	3.8
SN:26008C1	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 26-21-00									
256001A INSPECT/FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER									Service ATA:25
PN:453-5000-(366)	MOS	12 (+14d/-14d)	12-Nov-24		01-Apr-25 (M)	15-Apr-25	27 d (+14)	01-Apr-2025	3.8
SN:A00028	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 25-62-00									
05-P&W-790001 NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT									Service ATA:79
	MOS	12	18-Apr-24		18-Apr-25		44 d	18-Apr-2025	10.6
	HRS	1200 (+25/-25)	1336.5		(2536.5)2536.5	2561.5	1151.5 (+25)		48.5
	ENC		1050						44
REF: EMM 79-20-01									
05-P&W-790001 NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT									Service ATA:79
	MOS	12	18-Apr-24		18-Apr-25		44 d	18-Apr-2025	10.6
	HRS	1200 (+25/-25)	1336.5		(2536.5)2536.5	2561.5	1151.5 (+25)		48.5
	ENC		1050						44
REF: EMM 79-20-01									
05-P&W-790002 NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE									Service ATA:79
	MOS	12	18-Apr-24		18-Apr-25		44 d	18-Apr-2025	10.6
	HRS	600 (+50/-50)	1336.5		(1936.5)1936.5	1986.5	551.5 (+50)		48.5
	ENC		1050						44
REF: EMM 72-00-00									
05-P&W-790002 NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE									Service ATA:79
	MOS	12	18-Apr-24		18-Apr-25		44 d	18-Apr-2025	10.6
	HRS	600 (+50/-50)	1336.5		(1936.5)1936.5	1986.5	551.5 (+50)		48.5
	ENC		1050						44
REF: EMM 72-00-00									

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of:
13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-PATS-490002 APU - ANNUAL INSPECTION OF APU MOUNTS FOR LOOSENESS & DAMAGE									
	MOS	12	18-Apr-24		18-Apr-25		44 d	18-Apr-2025	10.6
	HRS								
	APUS								
REF: SMM 49-11-03									
243301A CHARGE NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030									
PN:501-1712-02	MOS	12 (+14d/-14d)	18-Apr-24		18-Apr-25	02-May-25	44 d (+14)	18-Apr-2025	10.6
SN:81687	HRS		1336.5						48.5
	AFL		1050						44
REF: AMM 12-23-02									
243302A CHARGE NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK 05-10-29-C1223030									
PN:501-1712-02	MOS	12 (+14d/-14d)	18-Apr-24		18-Apr-25	02-May-25	44 d (+14)	18-Apr-2025	10.6
SN:2633	HRS		1336.5						48.5
	AFL		1050						44
REF: AMM 12-23-02									
262050D CONTINUITY CHECK APU FIRE EXTINGUISHER PRESSURE SWITCH IAW SAFECRAFT CMM 26-20-02									
PN:50-1200	MOS	12	18-Apr-24		18-Apr-25		44 d	18-Apr-2025	10.6
SN:18-1011	HRS		1336.5						48.5
	AFL		1050						44
REF: GENERIC NO REF, CMM 26-20-02									
262050C INSPECT APU FIRE EXTINGUISHER WEIGHT CHECK AND REPLACE AS NECESSARY									
PN:50-1200	MOS	12	19-Apr-24		19-Apr-25		45 d	19-Apr-2025	10.5
SN:18-1011	HRS		1336.5						48.5
	AFL		1050						44
REF: GENERIC NO REF, SMM 49-11-03									
243049B CAPACITY CHECK UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002									
PN:RG-380E/60L	MOS	6	12-Nov-24		12-May-25		68 d	12-May-2025(2)	3.8
SN:41209090	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 12-22-00									
243050B CAPACITY CHECK LOWER / LEFT / NO. 1 LEAD-ACID (CAPTIVE) BATTERY 05-10-29-G1222002									
PN:RG-380E/60L	MOS	6	12-Nov-24		12-May-25		68 d	12-May-2025(2)	3.8
SN:41209129	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 12-22-00									

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of:
13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
723005A NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR)									
PN:30B6531-01	MOS		11-Oct-21					02-Jun-2025	40.8
SN:TXA1B0496	HRS	300 (+25)	1173.5		(1473.5)1473.5	1498.5	88.5 (+25)		211.5
	ENC		920						174
REF: EMM 72-00-00									
723005A NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR)									
PN:30B6531-01	MOS		11-Oct-21					02-Jun-2025	40.8
SN:TXA1B0087	HRS	300 (+25)	1173.5		(1473.5)1473.5	1498.5	88.5 (+25)		211.5
	ENC		920						174
REF: EMM 72-00-00									
050300 ^U PERFORM 300 HOUR SUPPLEMENTAL MAINTENANCE CHECKS									
	MOS		08-Nov-22					16-Aug-2025	27.9
	HRS	300	1247		1547		162		138
	AFL		971						123
Disposition: SMM REF:									
256001B REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - 05-11-00-L2564000									
PN:452-0133	MOS	60 (+14d/-14d)	16-Sep-20		16-Sep-25	30-Sep-25	195 d (+14)	16-Sep-2025	53.6
SN:384725-015	HRS		1050.2						334.8
	AFL		823						271
REF: GENERIC NO REF									
05-10-01-A1 PHASE A1-300 HOUR									
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS	300 (+25/-25)	1375.9		1675.9	1700.9	290.9 (+25)		9.1
	AFL		1084						10
REF: AMM 5-10-01									
05-10-02-A2 PHASE A2-300 HOUR									
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS	300 (+25/-25)	1375.9		1675.9	1700.9	290.9 (+25)		9.1
	AFL		1084						10
REF: AMM 5-10-02									
05-10-03-A3 PHASE A3-300 HOUR									
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS	300 (+25/-25)	1375.9		1675.9	1700.9	290.9 (+25)		9.1
	AFL		1084						10
REF: AMM 5-10-03									

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of:
13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-10-04-A4		PHASE A4-300 HOUR							Package ATA:05
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS	300 (+25/-25)	1375.9		1675.9	1700.9	290.9 (+25)		9.1
	AFL		1084						10
REF: AMM 5-10-04									
05-10-05-A5		PHASE A5-300 HOUR							Package ATA:05
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS	300 (+25/-25)	1375.9		1675.9	1700.9	290.9 (+25)		9.1
	AFL		1084						10
REF: AMM 5-10-05									
05-10-06-A6		PHASE A6-300 HOUR							Package ATA:05
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS	300 (+25/-25)	1375.9		1675.9	1700.9	290.9 (+25)		9.1
	AFL		1084						10
REF: AMM 5-10-06									
05-10-30-RVSM-W3411015		PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (RVSM) (REFER TO 34-17-00)							Service ATA:34
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 34-17-00									
231203A		PERFORM PRIMARY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHF 1050 SYSTEM							Service ATA:23
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 23-12-08									
Disposition: SMM									
231204A		PERFORM STANDBY POWER AMPLIFIER/ANTENNA COUPLER PRESSURE CHECK OF THE KAC 1052 PRESSURE INPUT AND MEASUREMENT CHECK VALVE OF THE KHF 1050 SYSTEM.							Service ATA:23
	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
	HRS		1375.9						9.1
	AFL		1084						10
REF: AMM 23-12-08									
Disposition: SMM									
243063B		PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015							Service ATA:24
PN:501-1712-02	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
SN:2633	HRS		1375.9						9.1
	AFL		1084						10
REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of:
13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
243064B PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 3 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015									Service ATA:24
PN:501-1712-02	MOS	12 (+14d/-14d)	12-Nov-24	Adj:-36d	07-Oct-25	21-Oct-25	216 d (+14)	07-Oct-2025	3.8
SN:81687	HRS		1375.9						9.1
	AFL		1084						10
REF: GENERIC NO REF, CMM TP-329 24-30-02, CMM 24-30-08, CMM SL-170									
05-10-29-L2812002L INSPECT LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602									Service ATA:28
	MOS	24 (+14d/-14d)	07-Oct-23	Adj:7d	14-Oct-25	28-Oct-25	223 d (+14)	14-Oct-2025	16.9
	HRS		1309.3						75.7
	AFL		1026						68
REF: GENERIC NO REF									
05-10-29-L2812002R INSPECT RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602									Service ATA:28
	MOS	24 (+14d/-14d)	07-Oct-23	Adj:7d	14-Oct-25	28-Oct-25	223 d (+14)	14-Oct-2025	16.9
	HRS		1309.3						75.7
	AFL		1026						68
REF: GENERIC NO REF									
05-10-29-L2812010L INSPECT LEFT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA									Service ATA:28
	MOS	24 (+14d/-14d)	07-Oct-23	Adj:7d	14-Oct-25	28-Oct-25	223 d (+14)	14-Oct-2025	16.9
	HRS		1309.3						75.7
	AFL		1026						68
REF: GENERIC NO REF									
05-10-29-L2812010R INSPECT RIGHT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA									Service ATA:28
	MOS	24 (+14d/-14d)	07-Oct-23	Adj:7d	14-Oct-25	28-Oct-25	223 d (+14)	14-Oct-2025	16.9
	HRS		1309.3						75.7
	AFL		1026						68
REF: GENERIC NO REF									
05-10-29-L2812020L INSPECT LEFT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION									Service ATA:28
	MOS	24 (+14d/-14d)	07-Oct-23	Adj:7d	14-Oct-25	28-Oct-25	223 d (+14)	14-Oct-2025	16.9
	HRS		1309.3						75.7
	AFL		1026						68
REF: GENERIC NO REF									
05-10-29-L2812020R INSPECT RIGHT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION									Service ATA:28
	MOS	24 (+14d/-14d)	07-Oct-23	Adj:7d	14-Oct-25	28-Oct-25	223 d (+14)	14-Oct-2025	16.9
	HRS		1309.3						75.7
	AFL		1026						68
REF: GENERIC NO REF									

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of: 13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-10-29-L5210025 VISUAL INSPECTION EXTERIOR LWR DOOR STRUCTURE/HINGE FOR CORROSION									
	MOS	24 (+14d/-14d)	07-Oct-23	Adj:7d	14-Oct-25	28-Oct-25	223 d (+14)	14-Oct-2025	16.9
	HRS		1309.3						75.7
	AFL		1026						68
REF: GENERIC NO REF									
351002A OVERHAUL COPILOT OXYGEN MASK									
PN:174262-11	MOS	72 (+14d/-14d)	14-Oct-19		14-Oct-25	28-Oct-25	223 d (+14)	14-Oct-2025	64.7
SN:09443	HRS								
	AFL								
REF: GENERIC NO REF									
725102 NO. 1 ENGINE - STAGE 2 TURBINE DISC									
PN:PN	MOS		10-Nov-06	TSN:0				28-Oct-2025	219.8
SN:UNKNOWN	HRS		0	TSN:0					1385
	ENC		0	TSN:0	(1250)1250 (M)		156		1094
	ACCCYC	1250	0	TSN:0					1094
Disposition: LIFE LIMIT REF: EMM 72-50-01									
243200 PERFORM NO. 1 EMERGENCY POWER BATTERY OPERATIONAL CHECK (XL2410) (IRN Y2431061)									
PN:100-2410-06	MOS	12 (+14d/-14d)	08-Nov-24		08-Nov-25	22-Nov-25	248 d (+14)	08-Nov-2025	3.9
SN:0705549	HRS		1370.4						14.6
	AFL		1078						16
REF: AMM 24-32-01									
250002 ^U INSPECT INTERIOR CABINET DRAWER AND DOOR LATCHES FOR WEAR, CONDITION, SECURITY OF ATTACHMENT IN THE STOWED POSITION, AND PROPER OPERATION									
	MOS	36	08-Nov-22		08-Nov-25		248 d	08-Nov-2025	27.9
	HRS		1247						138
	AFL		971						123
Disposition: SMM REF:									
U5331012 * REMOVE ACCESS PANELS (TOP OF FUSELAGE) AND PERFORM VISUAL INSPECTION OF ELECTRICAL BOXES FOR SECURITY OF ATTACHMENT, CORROSION, AND GENERAL CONDITION. INSPECT DOUBLERS, FUSELAGE SKIN, INTERIOR FRAMES, AND INTERCOSTALS FOR FATIGUE CRACKS AND GENERAL CONDITION. (AWL*)									
	MOS	49	11-Oct-21		11-Nov-25		251 d	11-Nov-2025	40.8
	HRS		1173.5						211.5
	AFL		920						174
Disposition: AIRWORTHINESS REF: GENERIC NO REF									
05-P&W-730001 NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT									
	MOS	12	12-Nov-24		12-Nov-25		252 d	12-Nov-2025	3.8
	HRS	1200 (+25/-25)	1375.9		(2575.9)2575.9	2600.9	1190.9 (+25)		9.1
	ENC		1084						10
REF: EMM 73-10-03									

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of:
13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-P&W-730001		NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT							Service ATA:73
	MOS	12	12-Nov-24		12-Nov-25		252 d	12-Nov-2025	3.8
	HRS	1200 (+25/-25)	1375.9		(2575.9)2575.9	2600.9	1190.9 (+25)		9.1
	ENC		1084						10
REF: EMM 73-10-03									
256076A		CONDITION CHECK FIRST AID KIT INVENTORY & EXPIRATION DATES							Service ATA:25
PN:FL220-FAKFAA	MOS	12	12-Nov-24		12-Nov-25		252 d	12-Nov-2025	3.8
SN:0923-3468	HRS		1375.9						9.1
	AFL		1084						10
REF: GENERIC NO REF									
274013		HORIZONTAL STABILIZER ACTUATOR							Component ATA:27
PN:5435005-028	MOS		16-Sep-20	TSO:0				28-Nov-2025	53.6
SN:371	HRS	600 (+25/-25)	1050.2	TSO:0	1650.2	1675.2	265.2 (+25)		334.8
	AFL		823	TSO:0					271
Disposition: OVERHAUL REF: AMM 27-40-02									
05-10-29-H2431017		PERFORM BATTERY CABLES & RECEPTACLES - BATTERY CONNECTOR INSPECTION							Service ATA:24
	MOS		12-Nov-24					24-Dec-2025	3.8
	HRS	300 (+25/-25)	1375.9		1675.9	1700.9	290.9 (+25)		9.1
	AFL		1084						10
REF: AMM 24-31-01									
361037A		PERFORM * NO. 1 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST							Service ATA:36
PN:6600194-008	MOS	36 (+14d/-14d)	24-Mar-23		01-Jan-26 (M)	15-Jan-26	302 d (+14)	01-Jan-2026	23.4
SN:01284	HRS								
	AFL								
REF: AMM 36-15-01									
361037B		X-RAY INSPECT * NO. 1 EMERGENCY AIR BOTTLE							Service ATA:36
PN:6600194-008	MOS	36 (+14d/-14d)	24-Mar-23		01-Jan-26 (M)	15-Jan-26	302 d (+14)	01-Jan-2026	23.4
SN:01284	HRS								
	AFL								
REF: AMM 36-15-01									
361038A		PERFORM * NO. 2 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST							Service ATA:36
PN:6600194-008	MOS	36 (+14d/-14d)	24-Mar-23		01-Jan-26 (M)	15-Jan-26	302 d (+14)	01-Jan-2026	23.4
SN:01283	HRS								
	AFL								
REF: AMM 36-15-01									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 60XR Serial: 60 320 RegNo: N328AJ HRS: 1385 AFL: 1094 As Of:
13-Feb-2025 Operator: GOLDENEYE LLC

Report Date: 05-Mar-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
361038B				PERFORM * NO. 2 EMERGENCY AIR BOTTLE X-RAY INSPECTION					Service ATA:36
PN:6600194-008	MOS	36 (+14d/-14d)	24-Mar-23		01-Jan-26 (M)	15-Jan-26	302 d (+14)	01-Jan-2026	23.4
SN:01283	HRS								
	AFL								
REF: AMM 36-15-01									
SB 60-28-16 R01				TAILCONE FUEL LINE BONDING FOR IMPROVED LIGHTNING STRIKE PROTECTION, SERVICE BULLETIN					Bulletin ATA:28
	MOS		EFF					24-Feb-2026	
	HRS	T:1200	EFF		1736.78 *	1736.78	351.8		
	AFL								
Disposition: RECOMMENDED REF: BULLETINS									
237021B				REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000					Service ATA:23
PN:DK120	MOS	DUE	03-Apr-20		01-Mar-26 (M)		361 d	01-Mar-2026	59.1
SN:SD37190	HRS		1010.3						374.7
	AFL		791						303
REF: AMM 25-63-00									