

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "350". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	8	8	8	0	0
Carbon Monoxide	4	4	4	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 90 % at the Main panel ./ Smk/ Co's Exp - 2030 (4 WIRE COSMOS)

**Reccomendations:**

This is a DSC System ./ No reccomendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "300". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	8	8	8	0	0
Carbon Monoxide	4	4	4	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

Defects or Malfunctions not corrected at conclusion of the test & inspection:
System Tested Pass / Battery 100 % at the Main panel ./ Smk/ Co's Exp - 2030 (4 WIRE COSMOS)

Reccomendations:
This is a DSC System ./ No reccomendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "256". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 100 % at the Main panel ./ Smk/ Co's Exp - 2029 (4 WIRE COSMOS)

**Reccomendations:**

This is a DSC System ./ N/R. at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "254". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 90 % at the Main panel ./ Smk/ Co's Exp - 2029 (4 WIRE COSMOS)

### Reccomendations:

This is a DSC System ./ N/R. at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "252". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 90 % at the Main panel ./ Smk/ Co's Exp - 2029 (4 WIRE COSMOS)

**Reccomendations:**

This is a DCS System ./ N/R. at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge 250". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 80 % at the Main panel ./ Smk/ Co's Exp - 2029 (4 WIRE COSMOS) ( fixed one smoke detector)

**Reccomendations:**

This is a DCS System ./ N/R. at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963 1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "236". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 100 % at the Main panel ./ Smk/ Co's Exp - 2029 (4 WIRE COSMOS)

**Reccomendations:**

This is a DCS System ./ N/R. at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963 1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "234". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 30 % at the Main panel ./ Replced battery (12v 8amp) Smk/ Co's Exp - 2029 (4 WIRE COSMOS)

### Reccomendations:

This is a DCS System ./ N/R. at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "232". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	0	0	0
Carbon Monoxide	3	3	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Fail / Battery 0 % at the Main panel ./Keypad and system were off , fire panel is not working./ Smk/ Co's Exp - 2029 (4 WIRE COSMOS)

### Reccomendations:

This is a DCS System ./ Need a new fire panel ( ASAP ) ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "230". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	2	2	2	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 90 % at the Main panel ./ Smk/ Co's Exp - 2029 (4 WIRE COSMOS)

**Reccomendations:**

This is a DCS System ./ no reccomendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "226". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	6	6	6	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 80 % at the Main panel ./ Smk/ Co's Exp - 2026

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "224". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	7	7	7	0	0
Carbon Monoxide	7	7	7	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 80 % at the Main panel ./ Smk/ Co's Exp - 2025

**Reccomendations:**

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 30th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "222". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 100 % at the Main panel ./ Smk/ Co's Exp - 2025

### Reccommendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "220". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	7	7	7	0	0
Carbon Monoxide	7	7	7	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 70 % at the Main panel ./ Smk/ Co's Exp - 2025

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "219". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	6	6	6	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 80 % at the Main panel ./ Smk/ Co's Exp - 2025

**Reccomendations:**

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963 1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "217". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	2	2	2	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 90 % at the Main panel ./ Smk/ Co's Exp -2025 One smoke detector missing / Entry smoke.

**Reccomendations:**

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "215". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	6	6	6	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 100 % at the Main panel ./ Smk/ Co's Exp -2025

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "213". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	7	7	7	0	0
Carbon Monoxide	7	7	7	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 80 % at the Main panel ./ Smk/ Co's Exp -2025

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "211". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	3	3	3	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 80 % at the Main panel /. Replaced battery (12v 8amp) Smk/ Co's Exp -2025

**Reccomendations:**

This is a DSC system / this system is 10 years plus /

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "209". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	7	7	7	0	0
Carbon Monoxide	7	7	7	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 100 % at the Main panel / . Replaced battery (12v 8amp) Smk/ Co's Exp - Nest smoke detectors/

### Reccomendations:

This is a DSC system / this system is 10 years plus / needs a new fire system /

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "207". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	2	2	2	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 0 % at the Main panel /. Replaced battery (12v 8amp) Smk/ Co's Exp - One smoke detector missing in Living Room./

### Reccomendations:

This is a DSC system / this system is 10 years plus / needs a new fire system /

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "205". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	<del>X</del>	<del>X</del>	-
Battery Backup	X	X	<del>X</del>	<del>X</del>	-
Communication	X	X	<del>X</del>	<del>X</del>	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	0	6	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested FAIL / Battery 0 % at the Main panel /. Smk/ Co's Exp - all smoke detectors expired . No display on key pad.

### Reccomendations:

This is a DSC system / this system is 10 years plus / needs a new fire system /

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "203". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	6	6	6	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 80 % at the Main panel /. Smk/ Co's Exp -2024

**Reccomendations:**

This is a DSC system / no reccomendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Overlook Ridge "201". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	XX	-
Battery Backup	X	X	.	XX	-
Communication	X	X	.	XX	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	0	6	0
Carbon Monoxide	3	3	0	3	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested ~~Pass~~ / Battery 0 % at the Main panel /. Smk/ Co's Exp - No testing was done panel was completely off.

### Reccomendations:

This is a DSC system / needs a new fire system , this system is 10 years plus./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "167". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 90 % at the Main panel /. Smk/ Co's Exp - Smoke detectors need to be replaced ./

**Recommendations:**

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "166". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	6	6	6	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 90 % at the Main panel /. Smk/ Co's Exp - 2026

### Reccomendations:

This is an ADT system. No reccomentaions at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

165

On January 26th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "165". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	XX	-
Battery Backup	X	X	.	XX	-
Communication	X	X	.	XX	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	5	5	0	5	0
Carbon Monoxide	3	3	0	3	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 10 % at the Main panel /. Smk/ Co's Exp.All devices fail no smoke or carbon monoxide detectors in the home./

**Reccomendations:**

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "164". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	7	7	7	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 80 % at the Main panel /. Smk/ Co's Exp.-2017 -

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 26th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "163". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	0	6	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested FAIL / Battery 0 % at the Main panel /. Smk/ Co's Exp.- No carbon monoxide detectors in Home .

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 25th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "161". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	6	6	6	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 100 % at the Main panel /. Smk/ Co's Exp.- (Nest smoke detectors)

**Reccomendations:**

This is a DSC system / no reccomendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963 1182

On January 25th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "160". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	8	8	8	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

Defects or Malfunctions not corrected at conclusion of the test & inspection:
System Tested Pass / Battery 90 % at the Main panel /. Smk/ Co's Exp.-

Recommendations:
This is a Concord system/ this system is Obsolete./ Needs a new fire panel . Replace Smoke detectors next year.

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963 1182

On January 25th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "158". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	8	8	8	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 100 % at the Main panel / . Smk/ Co's Exp.-

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel .

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963 1182

On January 25th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "156". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 80 % at the Main panel / . Smk/ Co's Exp.-

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel .

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 25th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "155". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	0	0
Tamper Switches	1	1	0	0	0
Smoke Detectors	5	5	0	5	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Fail / Battery 10 % at the Main panel / . Smk/ Co's Exp.- No carbon Monoxide detectors in Home / System off. No devices workin' /

**Reccomendations:**

This is a Concord system/ this system is Obsolete./ Needs a new fire panel .

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 20th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "154". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	0	0
Tamper Switches	1	1	0	0	0
Smoke Detectors	7	7	0	7	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Fail / Battery 90 % at the Main panel / . Smk/ Co's Exp.- No carbon Monoxide detectors in Home /

### Recommendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel .

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 20th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "153". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	0	0
Tamper Switches	1	1	0	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	2	2	2	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass/ Battery at 0 % at the Main panel /. Replaced Panel battery (12v 8amp) Smk/ Co's Exp.-

### Reccomendations:

This is a Concord system/ this system is Obsolete./ Needs a new fire panel .

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 20th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "152". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	0	0
Tamper Switches	1	1	0	0	0
Smoke Detectors	4	4	0	4	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Fail / Battery at 70 % at the Main panel / . Smk/ Co's Exp. All Expired/ And some devices missing .

**Reccomendations:**

This is a Concord system/ this system is Obsolete./replace the fire panel

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 20th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "151". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	0	0
Tamper Switches	1	1	0	0	0
Smoke Detectors	6	6	0	6	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Fail / Battery at 0 % at the Main panel / . Smk/ Co's Exp. All Expired/

**Reccomendations:**

This is a Concord system/ this system is Obsolete./replace the fire panel

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 20th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "150". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	8	8	8	0	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 100 % at the Main panel / . Smk/ Co's Exp.-

### Reccomendations:

This is a Concord system/ this system is Obsolete./replace the fire panel

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 20th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "145". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	<del>X</del>	<del>X</del>	-
Battery Backup	X	X	<del>X</del>	<del>X</del>	-
Communication	X	X	<del>X</del>	<del>X</del>	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	8	8	8	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Fail / Battery at 0 % at the Main panel /. Smk/ Co's Exp. All Expired/need a new fire system

**Reccomendations:**

This is a Concord system/ this system is Obsolete./replace the fire panel

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963 1182

On January 20th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "144". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	8	8	8	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 80 % at the Main panel /. Smk/ Co's Exp.-

### Reccomendations:

This is a Concord system/ this system is Obsolete./replace the fire panel

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 19 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "143". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	0	0
Tamper Switches	1	1	0	0	0
Smoke Detectors	6	6	0	6	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Fail / Battery at 0 % at the Main panel / . Smk/ Co's Exp. All expired / needs a new fire system

### Reccomendations:

This is a Concord system/ this system is Obsolete./replace the fire panel.

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

141

On January 19 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "141". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	7	7	7	0	0
Carbon Monoxide	1	1	1	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 10 % at the Main panel /. Smk/ Co's Exp. - replaced battery main fire panel (12v 5amp).

**Reccomendations:**

This is a Concord system/ this system is Obsolete./replace the fire panel.

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 19 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "140". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	7	7	7	0	0
Carbon Monoxide	1	1	1	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 100 % at the Main panel /. Smk/ Co's Exp. -

**Reccomendations:**

This is a Concord system/ this system is Obsolete./replace the fire panel. Add more carbon monoxide detectors at least one per level.

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 18th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "137". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	2	2	2	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 90 % at the Main panel /. Smk/ Co's Exp. 2025

### Reccomendations:

This is a Concord system/ this system is Obsolete./replace fire panel.

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 18th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "136". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	X	0
Tamper Switches	1	1	0	X	0
Smoke Detectors	0	0	0	X	0
Carbon Monoxide	0	0	0	X	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested FAIL / Battery at 0 % at the Main panel /. Smk/ Co's Exp. No smoke or carbon detectors in Home. This home is 0 percent protected against fire or carbon Monoxide /

**Reccomendations:**

This is a Concord system/ this system is Obsolete./replace fire panel and devices./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 18th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "135". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	0	0
Tamper Switches	1	1	0	0	0
Smoke Detectors	6	6	0	6	0
Carbon Monoxide	2	2	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested FAIL / Battery at 0 % at the Main panel / . Smk/ Co's Exp. Smoke detectors install in 2007

### Reccomendations:

This is a Concord system/ this system is Obsolete./replace Smoke detectors

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 18th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "134". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	X	-
Battery Backup	X	X	.	X	-
Communication	X	X	.	X	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	0	0	0
Tamper Switches	1	1	0	0	0
Smoke Detectors	6	6	0	6	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested FAIL / Battery at 0 % at the Main panel / . Smk/ Co's Exp. 2015 / Panel was off , missing a Transformer, no A/C power / had a panel battery from 2015.

### Reccomendations:

This is a Concord system/ this system is Obsolete./replace fire panel and devices.

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 18th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "133". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	.	-
Battery Backup	X	X	X	.	-
Communication	X	X	X	.	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	5	5	5	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 100 % at the Main panel / . Smk/ Co's Exp. -

**Reccomendations:**

This is a Concord system/ this system is Obsolete./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 18th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "131". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	x	-
Battery Backup	X	X	.	x	-
Communication	X	X	.	x	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	4	4	0	0	0
Carbon Monoxide	0	0	0	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Fail / Battery at 0 % at the Main panel / . Smk/ Co's Exp. - No carbon monoxide anywhere in House /

### Reccomendations:

This is a Concord system/ this system is Obsolete./ replace system and devices/

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 18th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "130". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	8	8	8	0	0
Carbon Monoxide	2	2	2	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 80 % at the Main panel /. Smk/ Co's Exp.-

**Reccomendations:**

This is a Concord system/ this system is Obsolete./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970.963.1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail "127". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 80 % at the Main panel / . Smk/ Co's Exp.-

### Reccomendations:

This is a Concord system/ this system is Obsolete./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "125". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	.	x	-
Battery Backup	X	X	.	x	-
Communication	X	X	.	x	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested fail/ Battery 0 % at the Main panel / Skm/Co's Exp. -

**Reccomendations:**

This is a Concord system / Needs a new system , smokes and carbon monoxide detectors//

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "123". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery 100% at the Main panel / Skm/Co's Exp. 2027

### Reccomendations:

This is a DSC system / no reccomendations at this time/

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "121". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	5	5	5	0	0
Carbon Monoxide	2	2	2	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery 10% at the Main panel / Skm/Co's Exp. 2025/ Replaced a panel Battery (12v 8amp) New. /

**Reccomendations:**

This is a Concord system / This system is Obsolete ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "120". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 100% at Main panel /need a new key pad and panel ./ Skm/Co's Exp. 2027 / we installed in lower level a 4 wire smoke/carbon combo . System is working but key pad is not ./

**Reccomendations:**

This is a DSC system / needs a new key pad or a new system to operate properly./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "118". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 100% at Main panel / Skm/Co's Exp. 2027

### Reccomendations:

This is a DSC system / No reccomendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "117". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

Defects or Malfunctions not corrected at conclusion of the test & inspection:
System Tested Pass / Battery at 90% at Main panel / Skm/Co's Exp. -

Reccomendations:
This is a Concord system/ this System is Obsolete./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "116". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

Defects or Malfunctions not corrected at conclusion of the test & inspection:
System Tested Pass / Battery at 80% at Main panel / Skm/Co's Exp. 2029

Reccomendations:
This is a DSC system / No reccomendations at this time /

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "115". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 80% at Main panel / Skm/Co's Exp. -

**Reccomendations:**

This is a Concord system / This system is Obsolete ./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "114". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	2	2	2	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 80% at Main panel / Skm/Co's Exp. 2027

**Reccomendations:**

This is a DSC system/ no reccomendations at this time/

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "113". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	2	2	2	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 90% at Main panel / Skm/Co's Exp. -

### Reccomendations:

This is a Concord system / This system is Obsolete./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "112". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 100% at Main panel / Skm/Co's Exp. 2027 Smoke was Taken off in the kitchen and living room / please re-install devices back in place./

**Reccomendations:**

This is a DSC system / please re-install devices back in place./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 17th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "111". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	5	5	5	0	0
Carbon Monoxide	2	2	2	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

**Defects or Malfunctions not corrected at conclusion of the test & inspection:**

System Tested Pass / Battery at 10% at Main panel / Skm/Co's Exp. 2024 / replaced battery (12v 8amp)

**Reccomendations:**

This is a Concord system / this system is Obsolete.

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 16th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "110". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	6	6	6	0	0
Carbon Monoxide		3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 90% at Main panel / Skm/Co's Exp. 2027 2 Smoke/Co not working correctly, living and upper level both devices need to be replace.

### Reccomendations:

This is a DSC system / Replace 2 Smoke/ carbon combos (4 Wire)

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 16th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "104". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	5	5	5	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 90% at Main panel / Skm/Co's Exp. 2027

### Reccomendations:

This is a DSC system / No Recommendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 16th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "102". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	5	5	5	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

### Defects or Malfunctions not corrected at conclusion of the test & inspection:

System Tested Pass / Battery at 30 % at Main panel / Skm/Co's Exp. 2027 We did replace battery on this Unit (12v 8amp) .

### Recommendations:

This is a DSC system / No Recommendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.

# ALLTEC SERVICES

970-963-1182

On January 16th 2023, a Test & Inspection was completed on your alarm system at Juniper Trail , "100". The system was inspected visually and tested for proper operation. Below is a summary of the Test & Inspection.

Panel	Inspected	Tested	Passed	Failed	DNF/DNT
Transformer Voltage	X	X	X	-	-
Battery Backup	X	X	X	-	-
Communication	X	X	X	-	-
Fire Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flow Switches	1	1	1	0	0
Tamper Switches	1	1	1	0	0
Smoke Detectors	5	5	5	0	0
Carbon Monoxide	3	3	3	0	0
Gas Detectors	0	0	0	0	0
Heat Detectors	0	0	0	0	0
Pull Stations	0	0	0	.	.
Speakers	x	x	x	.	.
Exterior Horn/Strobe	x	x	x	.	.
Security Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Doors	0	0	0	.	.
Windows	0	0	0	.	.
Panic Buttons	0	0	0	.	.
Glassbreak Detectors	0	0	0	.	.
Motion Detectors	0	0	0	.	.
Environmental Devices	Inspected	Tested	Passed	Failed	DNF/DNT
Flood Detector	0	0	0	.	.
Low Temperature Sensor	0	0	0	.	.
Humidity Sensor	0	0	0	.	.

Defects or Malfunctions not corrected at conclusion of the test & inspection:
System Tested Pass / Battery at 100 % at Main panel / Skm/Co's Exp. 2028

Reccomendations:
This is a DSC system / No Recommendations at this time./

Thank you for having Alltec Services as your fire and security alarm provider. If you have any further questions, please reach out to us at (970) 963-1182.