

ADDENDUM

Project: Harrisville DI Interior Remodel

Project No.: 500021624010101

Addendum No.: 2

Project Address: 435 North Wall Ave – Harrisville, UT

Date: October 20, 2025

Owner: The Church of Jesus Christ of Latter-day Saints, a Utah corporation sole

From (Architect): Bradley Gygi Architect & Associates, PLLC

Instructions to Prospective Bidders:

This Addendum forms a part of the Contract Documents and modifies the original Bidding Documents and/or prior Addenda as noted below. All conditions, requirements, materials and workmanship are to be as described in the Contract Documents unless specifically stated otherwise. This Addendum consists of one (1) page(s) and the attached drawing(s), Sheet(s) _____, dated _____.

1. Changes to prior Addenda:
 - a. Not Used.
2. Changes to Bidding Requirements:
 - a. Not Used.
3. Changes to Conditions of the Contract:
 - a. Not Used.
4. Changes to Specifications:
 - a. Substitution requested for Section 08 3323 is not approved. Only the specified Cornell Thermiser ESD20 is approved.
5. Changes to Drawings:
 - a. Sheet A101:
 - 1) General Notes, Walls: change shaded area noted as wood framed to “metal framed.” All new framed walls are to be metal-framed.
 - 2) Add Keyed Note #30 at Retail Sales 108, Hall 109, and Yard Area Sales 110: “Patch holes and damaged gypsum board, touch up texture to match, and paint all existing walls, including accent paint color bands to match existing.”
 - b. Sheet A151, New Reflected Ceiling Plan:
 - 1) At old “yard area” where two existing swamp coolers are to be removed, remove existing HVAC grilles in the ceiling soffit panels and patch with new panels to match.
 - c. Sheet A401:
 - 1) FRP paneling at back and side walls of recess for new drinking fountains shall be full height of recess, approximately 8'-0” tall. See elevation M/A401.
 - d. Sheet A601:
 - 1) Add new wall finish note W6: Patch holes and damaged gypsum board, touch up texture to match, and paint all existing walls, including accent paint color bands to match existing.
 - 2) Omit “W3” notes and replace with “W6” notes at Retail Sales 108, Hall 109, and Yard Area Sales 110.