



FLORIDA APARTMENT COMPLEX LIFT STATION 96 I

BACKGROUND DATA: 50 apartment units, one office, one laundry, and one car wash. The lift station was equipped with two 5 hp grinder pumps. The station is located in an area that was difficult for a Vac Truck to get to. Also one to two days after expensive pump-out, severe grease accumulated again.

BEFORE


PROBLEM: Solve a sewer grease problem

CONCERNS:

Floats sticking, pump-outs are expensive and not working, odor complaints

CHALLENGE:

Eliminate Fats, Oils, Grease (FOG), BOD, TSS, and ODORS without moving the problem downstream



AFTER

TREATMENT PROCEDURES:

Enviro-Tech proposed injecting **PX-700**[®] biostimulant and installing **System 1000** grease reduction and odor control.

Results:

100% satisfaction. No grease, BOD, or TSS moved downstream and 100% of the odors were eliminated. Pump-out contract was cancelled. **PX-700**[®] biostimulant outperformed and cost less than all other systems.

