









The 8 Wastes of Lean

Identify these non-value-add activities and reduce or eliminate them to become more efficient.

 Non-Utilized Talent	
 Extra Processing	
 Excess Waiting	
 Excess Motion	
 Inventory Quantity	
 Over Production	
 Product/Process Defects	
 Excess Transportation	

