

OWNER: ALEDO SUB LLC, JLB PARTNERS, LP
ADDRESS: 909 LAKE CAROLYN PKWY
 TX 75039
PHONE:
FAX:

OPERATOR: ALEDO SUB LLC, JLB PARTNERS, LP
ADDRESS: 3890 WEST NW HWY
 DALLAS, TX 75220
PHONE: 817-308-1916
FAX:

ANALYST: TRAVIS JINKS
EMAIL: TJINKS@CAMPSYSTEMS.COM

877-411-CAMP (2267) (OFFICE)
 631-588-3200 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (FAX)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 265/N868DB **MODEL:** FALCON 50EX **MANUFACTURER:** DASSAULT AVIATION S.A.

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 18-SEP-1997	7927.2 A/C HRS	as of 26-FEB-2019	A/C HRS	as of ___/___/___
	5240 AFL	as of 26-FEB-2019	AFL	as of ___/___/___
	3999.3 APH	as of 26-FEB-2019	APH	as of ___/___/___
	3840 APS	as of 01-MAR-2016	APS	as of ___/___/___

APU SERIAL/PART: P375/3800016-3 **MODEL:** GTCP36-100(A) **MANUFACTURER:** HONEYWELL

INSTALLED ON 18-SEP-1997	LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS	3999.3 APU HRS	as of 26-FEB-2019	APU HRS	as of ___/___/___
0 APUS	3840 APUS	as of 01-MAR-2016	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: P115150/3060050-1 **MODEL:** TFE731-40-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 04-MAR-2017		LAST ACTUALS		CURRENT ACTUAL	
7076.3 ENG. HRS	7347.9 A/C HRS	7655.6 ENG. HRS	as of 26-FEB-2019	ENG. HRS	as of ___/___/___
4683 ENC		5104 ENC	as of 26-FEB-2019	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: P115154/3060050-1 **MODEL:** TFE731-40-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 04-MAR-2017		LAST ACTUALS		CURRENT ACTUAL	
7229.3 ENG. HRS	7347.9 A/C HRS	7808.6 ENG. HRS	as of 26-FEB-2019	ENG. HRS	as of ___/___/___
4786 ENC		5207 ENC	as of 26-FEB-2019	ENC	as of ___/___/___

ENGINE NO. 3 SERIAL/PART: P115153/3060050-1 **MODEL:** TFE731-40-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 04-MAR-2017		LAST ACTUALS		CURRENT ACTUAL	
7229.3 ENG. HRS	7347.9 A/C HRS	7808.6 ENG. HRS	as of 26-FEB-2019	ENG. HRS	as of ___/___/___
4786 ENC		5207 ENC	as of 26-FEB-2019	ENC	as of ___/___/___



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS								
05-08-00-200-800-15	12 M INSPECTION PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			15-APR-2019	M 15-MAY-2019
05-08-00-200-800-16	24 M INSPECTION PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2020	M 15-MAY-2020
05-08-00-200-800-17	36 M INSPECTION PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			15-APR-2021	M 15-MAY-2021
+ 05-08-00-200-800-21	1B INSPECTION PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30	-50.5	02-JUN-2017 7416.5 4869	8866	8896
+ 05-08-00-200-800-22	2B INSPECTION PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000	+30	-4.4	25-JUL-2011 5870.4 3679	8866	8896
+ 05-08-00-200-800-23	3B INSPECTION PKG 23 REF: See Workcard	MOS HRS/MSC AFL	4500	+30	-50.5	02-JUN-2017 7416.5 4869	11866	11896
+ 05-08-00-200-800-24	4B INSPECTION PKG 24 REF: See Workcard	MOS HRS/MSC AFL	6000	+30	-4.4	25-JUL-2011 5870.4 3679	11866	11896
+ 05-08-00-200-800-31	1C INSPECTION PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m		01-APR-2016 7065.7 4612	01-APR-2022	01-JUN-2022
+ 05-08-00-200-800-32	2C INSPECTION PKG 32 REF: MPD 05-10-00	MOS HRS/MSC AFL	144	+2m	-39	10-MAY-2010 5668.9 3540	01-APR-2022	01-JUN-2022
+ 05-08-00-200-800-33	3C INSPECTION PKG 33 REF: MPD 05-10-00	MOS HRS/MSC AFL	N/A			01-APR-2016 7065.7 4612		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-08-00-200-800-34	4C INSPECTION PKG 34 REF: MPD 05-10-00	MOS HRS/MSC AFL	288 +2m		195	18-SEP-1997 0 0	01-APR-2022	01-JUN-2022
05-08-00-200-800-35	5C INSPECTION PKG 35 REF: MPD 05-10-00	MOS HRS/MSC AFL	360			18-SEP-1997 0 0	18-SEP-2027	
APU Model : GTCP36-100(A) Serial # P375 Part # 3800016-3								
054900	APU - 300 HOUR INSPECTION PKG 1 REF:	MOS HRS/MSC APUS	300			23-MAR-2016 3809.6	4109.6	
ENGINE NO. 1 Model : TFE731-20/-40/-50/-60 Serial # P115150 Part # 3060050-1								
+ 057110	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1 REF: GENERIC NO REF	MOS HRS/MSC ENC	250			05-APR-2018 7379.7 4910	(7629.7) 7901.3	
+ 057120	NO. 1 ENGINE - 500 TO 650 HOUR INSPECTION PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	600 +50			04-MAR-2017 7076.5 4684	(7676.5) 7948.1	7726.5
057125	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION PKG 3 REF: GENERIC NO REF	MOS HRS/MSC ENC	800 +50			04-MAR-2017 7076.5 4684	(7876.5) 8148.1	7926.5
+ 057130	NO. 1 ENGINE - 1000 TO 1300 HOUR INSPECTION PKG 4 REF: GENERIC NO REF	MOS HRS/MSC ENC	1200 +100			04-MAR-2017 7076.5 4684	(8276.5) 8548.1	8376.5
057135	NO. 1 ENGINE - 1500 TO 1650 HOUR INSPECTION PKG 5 REF: GENERIC NO REF	MOS HRS/MSC ENC	1600 +50			04-MAR-2017 7076.5 4684	(8676.5) 8948.1	8726.5
ENGINE NO. 2 Model : TFE731-20/-40/-50/-60 Serial # P115154 Part # 3060050-1								
+ 057110	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1 REF: GENERIC NO REF	MOS HRS/MSC ENC	250			05-APR-2018 7532.7 5013	(7782.7) 7901.3	



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 057120	NO. 2 ENGINE - 500 TO 650 HOUR INSPECTION PKG 2	MOS HRS/MSC ENC	600	+50		03-MAR-2017 7229.5 4787	(7829.5) 7948.1	7879.5
	REF: GENERIC NO REF							
057125	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION PKG 3	MOS HRS/MSC ENC	800	+50		03-MAR-2017 7229.5 4787	(8029.5) 8148.1	8079.5
	REF: GENERIC NO REF							
+ 057130	NO. 2 ENGINE - 1000 TO 1300 HOUR INSPECTION PKG 4	MOS HRS/MSC ENC	1200	+100		03-MAR-2017 7229.5 4787	(8429.5) 8548.1	8529.5
	REF: GENERIC NO REF							
057135	NO. 2 ENGINE - 1500 TO 1650 HOUR INSPECTION PKG 5	MOS HRS/MSC ENC	1600	+50		03-MAR-2017 7229.5 4787	(8829.5) 8948.1	8879.5
	REF: GENERIC NO REF							
ENGINE NO. 3 Model : TFE731-20/-40/-50/-60 Serial # P115153 Part # 3060050-1								
+ 057110	NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1	MOS HRS/MSC ENC	250			05-APR-2018 7532.7 5013	(7782.7) 7901.3	
	REF: GENERIC NO REF							
+ 057120	NO. 3 ENGINE - 500 TO 650 HOUR INSPECTION PKG 2	MOS HRS/MSC ENC	600	+50		03-MAR-2017 7229.5 4787	(7829.5) 7948.1	7879.5
	REF: GENERIC NO REF							
057125	NO. 3 ENGINE - 500 TO 850 HOUR INSPECTION PKG 3	MOS HRS/MSC ENC	800	+50		03-MAR-2017 7229.5 4787	(8029.5) 8148.1	8079.5
	REF: GENERIC NO REF							
+ 057130	NO. 3 ENGINE - 1000 TO 1300 HOUR INSPECTION PKG 4	MOS HRS/MSC ENC	1200	+100		03-MAR-2017 7229.5 4787	(8429.5) 8548.1	8529.5
	REF: GENERIC NO REF							
057135	NO. 3 ENGINE - 1500 TO 1650 HOUR INSPECTION PKG 5	MOS HRS/MSC ENC	1600	+50		03-MAR-2017 7229.5 4787	(8829.5) 8948.1	8879.5
	REF: GENERIC NO REF							

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00 INFORMATION									
3647-170701	REVIEW DASSAULT AVIATION FALCON 50EX MPD CHAPTER 5 REVISION 6, DATED JULY 2017 - SUMMARY CHANGE FORM								
	REF: GENERIC NO REF	MOS HRS/MSC - AFL					(EBT)		
3647-170809	REVIEW DASSAULT AVIATION FALCON 50EX MPD CHAPTER 5-40 REVISION 24, DATED JULY 2017 - SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: GENERIC NO REF	MOS HRS/MSC - AFL					(EBT)		
APU Model : GTCP36-100(A) Serial # P375 Part # 3800016-3									
A004-180112	APU - REVIEW HONEYWELL GTCP 36-100(A) APU-49 SIL REV 10								
REQUIREMENT CHANGE FORMS	REF: RCF APU-SIL-49	MOS HRS/MSC - APUS					(EBT)		
ENGINE NO. 1 Model : TFE731-40-1C Serial # P115150 Part # 3060050-1									
E004-170718	NO. 1 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 70-4								
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC					(EBT)		
E004-170913	NO. 1 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 72-235								
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC					(EBT)		
E004-180118	NO. 1 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM REV 13								
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC					(EBT)		



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E004-180802	NO. 1 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 5-17				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004-180802	MOS HRS/MSC - ENC							
ENGINE NO. 2 Model : TFE731-40-1C Serial # P115154 Part # 3060050-1									
E004-170718	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 70-4				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							
E004-170913	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 72-235				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							
E004-180118	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM REV 13				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							
E004-180802	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 5-17				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004-180802	MOS HRS/MSC - ENC							
ENGINE NO. 3 Model : TFE731-40-1C Serial # P115153 Part # 3060050-1									
E004-170718	NO. 3 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 70-4				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E004-170913	NO. 3 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 72-235				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							
E004-180118	NO. 3 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM REV 13				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							
E004-180802	NO. 3 ENGINE - REVIEW	TFE731-20/-40/-50/-60	LMM TR 5-17				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004-180802	MOS HRS/MSC - ENC							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
05-50-00-100-801-01	PERFORM CLEANING AFTER ELECTRLYTE SPILLAGE							18-SEP-1997	
	REF: See Workcard	MOS HRS/MSC A/R AFL					0 0		
05-50-00-200-801-01	CHECKS FOLLOWING INCIDENT THAT OCCURED WHILE TOWING THE AIRCRAFT							18-SEP-1997	
	REF: See Workcard	MOS HRS/MSC A/R AFL					0 0		
05-50-00-200-802-01	CHECKS FOLLOWING HAILSTORM							18-SEP-1997	
	REF: See Workcard	MOS HRS/MSC A/R AFL					0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-803-01	CHECKS FOLLOWING LIGHTNING STRIKE	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-804-01	CHECKS OF WHEELS AND BRAKE UNITS FOLLOWING AN ACCELERATION-STOP OR AN EMERGENCY BRAKING	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-805-01	PERFORM CHECKS AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE.	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-806-01	PERFORM CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-809-01	PERFORM INSPECTION AFTER SLAT EXTENSION IN OVERSPEED CONDITION	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-810-01	PERFORM INSPECTION AFTER FLAP EXTENSION IN OVERSPEED CONDITION	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-812-01	PERFORM INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-813-01	PERFORM CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-620-801-01	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTION AND ANTICORROSION TREATMENTS AT SHORT TIME INTERVALS	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-620-801-02	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTION AND ANTICORROSION TREATMENTS AT MEDIUM TIME INTERVALS	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-620-803-01	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN COLD WEATHER	MOS					18-SEP-1997		
05.020	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-620-804-01	PERFORM PROCEDURES FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-710-03	PERFORM PERIODIC INSPECTIONS AND CHECKS AFTER FLIGHTS THROUGH SAND	MOS					18-SEP-1997		
	REF: GENERIC NO REF	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-803-01	CHECK AFTER FIRE EXTINGUISHER PERCUSSION	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-700-807-01	CHECKS FOLLOWING A LANDING ON DRY UNPAVED RUNWAY	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-808-01	CHECKS FOLLOWING A HARD LANDING	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-810-01	PERFORM CHECKS AFTER EACH FLIGHT THROUGH SAND	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-810-02	PERFORM FURTHER INSPECTIONS IN CASE OF SAND DEPOSITS AFTER FLYING THROUGH SAND	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-810-04	PERFORM INSPECTIONS AND CHECKS AFTER A SANDSTORM (AIRCRAFT PARKED)	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-818-01	PERFORM CHECK AFTER AN ELECTRICAL FIRE	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
05-50-00-700-822-01	PERFORM CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-700-822-02	PERFORM FURTHER CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-822-03	PERFORM OPERATIONS AND CHECKS AFTER EXCEPTIONAL FLIGHT THROUGH A HIGH VOLCANIC ASH CONCENTRATION AREA	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-822-04	PERFORM OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-822-05	PERFORM OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A HEAVY VOLCANIC ASH FALLOUT AREA	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-860-801-01	PREPARATION OF AIRCRAFT FOR FERRY FLIGHT WITH ONE ENGINE INOPERATIVE	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-910-801-01 (s)	CHECK FLIGHT AIRCRAFT (COMPLETE)						PKG		
51.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+3%			01-APR-2016 7065.7 4612		
05-60-00-200-801-01	PERFORM BASIC INSPECTION								
05.010	REF: See Workcard	MOS HRS/MSC AFL	12 300	+1m +30			15-APR-2018 7651.3 5046	15-APR-2019 7951.3	15-MAY-2019 7981.3
05-60-00-200-801-03	PERFORM BASIC INSPECTION - GROUND SERVICING CHECKS								
05.010	REF: See Workcard	MOS HRS/MSC AFL	12 300	+1m +30			15-APR-2018 7651.3 5046	15-APR-2019 7951.3	15-MAY-2019 7981.3
CHAPTER 08 LEVELING AND WEIGHING									
08-10-00-910-801-01	WEIGHING THE AIRCRAFT								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
CHAPTER 09 TOWING AND TAXING									
09-10-00-910-810-01	DEBOGGING THE AIRCRAFT								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
10-10-00-200-801-01	PERFORM CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
10-10-00-550-801-01	PERFORM STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF 2 MONTHS	MOS					18-SEP-1997		
20.010	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-02	PERFORM STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 2 TO 12 MONTHS	MOS					18-SEP-1997		
20.010	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-03	PERFORM STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 12 TO 18 MONTHS	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
10-10-00-550-801-04	PERFORM PERIODIC (STORAGE) CHECKS EVERY MONTH	MOS					18-SEP-1997		
20.010	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-05	PERFORM PERIODIC (STORAGE) CHECKS EVERY 2 MONTHS	MOS					18-SEP-1997		
20.010	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-06	PERFORM PERIODIC (STORAGE) CHECKS EVERY 6 MONTHS	MOS					18-SEP-1997		
20.010	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-07	PERFORM REMOVAL FROM STORAGE AFTER 2 MONTHS OR LESS	MOS					18-SEP-1997		
20.010	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
10-10-00-550-801-08	PERFORM REMOVAL FROM STORAGE AFTER MORE THAN 2 MONTHS								
20.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
10-10-00-550-801-09	PERFORM PRE-STROAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 8 WEEKS								
20.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
10-20-00-910-802-01	MOORING THE AIRCRAFT IN CASE OF SNOWFALL								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
20-30-00-330-801-01	PERFORM TEMPORARY REPAIR PROCEDURE AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
20-31-00-140-801-01	PERFORM RINSING THE AIRCRAFT EXTERIOR								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
20-31-00-910-801-01	PERFORM ON GROUND DE-ICING TREATMENT								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
20-33-00-300-804-01	PERFORM TEMPORARY REPAIR OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20-60-00-370-813-01	PERFORM APPLICATION OF THE PAINT SCHEME ON COMPOSITE COMPONENTS	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (L2GF)	MOS					18-SEP-1997		
	C23791-1009	HRS/MSC	O/C				0		
	B31	AFL					0		
	REF: See Workcard								
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (R2GF)	MOS					18-SEP-1997		
	C23792-1009	HRS/MSC	O/C				0		
	B31	AFL					0		
	REF: See Workcard								
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (L2GF5)	MOS					18-SEP-1997		
	C23795-1004	HRS/MSC	O/C				0		
	SN-UNKNOWN	AFL					0		
	REF: See Workcard								
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (R2GF5)	MOS					18-SEP-1997		
	C23796-1004	HRS/MSC	O/C				0		
	SN-UNKNOWN	AFL					0		
	REF: See Workcard								
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (3GF)	MOS					18-SEP-1997		
	C23787-1007	HRS/MSC	O/C				0		
	B10	AFL					0		
	REF: See Workcard								
306151	PAINT	MOS					18-SEP-1997		
		HRS/MSC	-				0		
	REF: GENERIC NO REF	AFL					0		

CHAPTER 21 AIR CONDITIONING

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20-01-350-801-01	RESTORATION LH AIR CONDITIONING FLOW LIMITER (OVERHAUL) 2725F030100 21.070 01068 OVERHAUL	MOS HRS/MSC AFL	4500	+3%			29-JUL-2017 7448 4897	11948	12083
21-20-01-350-801-02	RESTORATION RH AIR CONDITIONING FLOW LIMITER (OVERHAUL) 2725F030100 21.070 01067 OVERHAUL	MOS HRS/MSC AFL	4500	+3%			29-JUL-2017 7448 4897	11948	12083
21-30-00-790-801-01	CHECK (GROUND) OF CABIN SEALING REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
21-30-00-790-802-01	CHECK (IN-FLIGHT) OF CABIN SEALING REF: See Workcard	MOS HRS/MSC AFL	7000				18-SEP-1997 0 0	7000	
21-30-00-790-802-01A	CHECK (IN-FLIGHT) OF CABIN SEALING (MANDATORY 5-40) MANDATORY 5-40 REF: See Workcard	MOS HRS/MSC AFL	7000				18-SEP-1997 0 0	7000	
21-30-01-900-801-01	CABIN PRESSURIZATION CONTROLLER 22201N071001 21.140 292 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:23 TSR:0 TSR:0		03-FEB-2013 6319.2 4025		
21-30-09-720-801-01	TEST TRIPLE ALTITUDE/DIFFERENTIAL PRESSURE INDICATOR ALTITUDE ALERT 3311AJ68 21.200 536 REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			29-NOV-2006 4655 3007	8655	8775

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30-09-900-801-01	TRIPLE ALTITUDE/DIFFERENTIAL PRESSURE INDICATOR								
21.200	3311AJ68 536 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			29-NOV-2006 4655 3007		
+ 21-30-17-820-801-01	CALIBRATION ALTIMETRIC SWITCH								
21.210	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
21-30-17-900-801-01	ALTIMETRIC SWITCH								
21.210	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
21-31-09-350-801-01	RESTORATION NOSE CONE BLOWER (REPLACEMENT OF BEARINGS)								
21.100	EVT205D 56 REF: See Workcard	MOS HRS/MSC AFL	3600	+3%			22-NOV-2011 5939.3 3734	9539.3	9647.3
21-31-09-900-801-01	NOSE CONE BLOWER								
21.100	EVT205D 56 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:7 TSR:0 TSO:121 TSR:0 TSO:88 TSR:0			22-NOV-2011 5939.3 3734		
+ 21-31-13-720-801-01 (s)	FUNCTIONAL TEST OF NOSE CONE PRESSURE REGULATION PNEUMATIC ACTUATOR								
21.090	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
21-31-13-720-801-02 (s)	FUNCTIONAL TEST OF NOSE CONE PRESSURE-RELIEF VALVE								
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-31-25-220-801-01	CHECK/REPLACEMENT NOSE CONE BLOWER BRUSHES								
21.100	EVT205D 56 REF: See Workcard	MOS HRS/MSC AFL	3600	+3%			22-NOV-2011 5939.3 3734	9539.3	9647.3
+ 21-32-00-710-801-01 (s)	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM						PKG		
21.120	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			29-JUL-2017 7448 4897		
21-32-00-710-801-01A	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM (MANDATORY 5-40)								
21.120 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	O/C				29-JUL-2017 7448 4897		
21-32-00-790-801-01 (s)	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (16F1)						PKG		
RVSM	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
21-32-00-790-801-02 (s)	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (16F2)						PKG		
RVSM	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
21-32-06-200-801-01	CLEANING ELECTROPNEUMATIC REGULATING VALVE								
21.160	2095L011000 108 REF: See Workcard	MOS HRS/MSC AFL	1640	+3%			01-MAR-2016 7065.7 4612	8705.7	8754.9
21-32-06-200-801-02	CLEANING PNEUMATIC REGULATING VALVE								
21.170	2096T021000 121 REF: See Workcard	MOS HRS/MSC AFL	1640	+3%			01-MAR-2016 7065.7 4612	8705.7	8754.9



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-06-200-801-03	CHECK ELECTROPNEUMATIC REGULATING VALVE OVERPRESSURE TIGHTNESS								
21.160	2095L011000 108 REF: See Workcard	MOS HRS/MSC AFL	1640				01-MAR-2016 7065.7 4612	8705.7	
+ 21-32-06-200-801-03A	CHECK ELECTROPNEUMATIC REGULATING VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)								
21.320 MANDATORY 5-40	2095L011000 108 REF: See Workcard	MOS HRS/MSC AFL	1640				01-MAR-2016 7065.7 4612	8705.7	
21-32-06-200-801-04	CHECK PNEUMATIC REGULATING VALVE OVERPRESSURE TIGHTNESS								
21.170	2096T021000 121 REF: See Workcard	MOS HRS/MSC AFL	1640				01-MAR-2016 7065.7 4612	8705.7	
+ 21-32-06-200-801-04A	CHECK PNEUMATIC REGULATING VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)								
21.315 MANDATORY 5-40	2096T021000 121 REF: See Workcard	MOS HRS/MSC AFL	1640				01-MAR-2016 7065.7 4612	8705.7	
21-32-06-200-801-05	INSPECTION/CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES								
21.170	REF: See Workcard	MOS HRS/MSC AFL	7500				01-MAR-2016 7065.7 4612	14565.7	
21-32-06-200-801-05A	INSPECTION/CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (MANDATORY 5-40)								
21.170 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	7500				01-MAR-2016 7065.7 4612	14565.7	
21-32-06-720-801-01	FUNCTIONAL TEST ELECTROPNEUMATIC REGULATING VALVE								
	2095L011000 108 REF: See Workcard	MOS HRS/MSC AFL	4500	+3%			26-OCT-2005 3926 2618	8426	8561

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-32-06-720-801-01A	FUNCTIONAL TEST ELECTROPNEUMATIC REGULATING VALVE (MANDATORY 5-40)								
21.160	2095L011000	MOS					26-OCT-2005		
MANDATORY 5-40	108 REF: See Workcard	HRS/MSC AFL	5000				3926 2618	8926	
21-32-06-720-801-02	FUNCTIONAL TEST PNEUMATIC REGULATING VALVE								
	2096T021000	MOS					26-OCT-2005		
	121 REF: See Workcard	HRS/MSC AFL	4500	+3%			3926 2618	8426	8561
+ 21-32-06-720-801-02A	FUNCTIONAL TEST PNEUMATIC REGULATING VALVE (ALTITUDE LIMIT) (MANDATORY 5-40)								
21.170	2096T021000	MOS					26-OCT-2005		
MANDATORY 5-40	121 REF: See Workcard	HRS/MSC AFL	5000				3926 2618	8926	
21-32-06-900-801-01	ELECTROPNEUMATIC REGULATING VALVE								
21.160	2095L011000	MOS					01-MAR-2016		
	108 REF: See Workcard	HRS/MSC AFL	O/C		TSO:125 TSO:3139.7 TSO:1994		7065.7 4612		
21-32-06-900-802-01	PNEUMATIC REGULATING VALVE								
21.170	2096T021000	MOS					01-MAR-2016		
	121 REF: See Workcard	HRS/MSC AFL	O/C				7065.7 4612		
+ 21-32-17-720-801-01 (s)	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - LH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (L536H)						PKG		
21.190	PKG 22	MOS					11-AUG-2008		
	REF: See Workcard	HRS/MSC AFL	3000	+30			5539.2 3454		
+ 21-32-17-720-801-01A	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - LH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (L536H) (MANDATORY 5-40)								
21.190		MOS					11-AUG-2008		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	3700				5539.2 3454	9239.2	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-32-17-720-801-02 (s)	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - RH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (R536H)						PKG		
21.190	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000	+30			25-JUL-2011 5870.4 3679		
+ 21-32-17-720-801-02A	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - RH POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE (R536H) (MANDATORY 5-40)								
21.190 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	3700				25-JUL-2011 5870.4 3679	9570.4	
+ 21-32-33-710-801-01	OPERATIONAL TEST BAGGAGE COMPARTMENT ISOLATION VALVE								
21.050	B97-26-553 20157 REF: See Workcard	MOS HRS/MSC AFL	600	+30			15-APR-2018 7651.3 5046	8251.3	8281.3
21-32-33-710-801-01A	OPERATIONAL TEST BAGGAGE COMPARTMENT ISOLATION VALVE (MANDATORY 5-40)								
21.050 MANDATORY 5-40	B97-26-553 20157 REF: See Workcard	MOS HRS/MSC AFL	650				15-APR-2018 7651.3 5046	8301.3	
+ 21-32-33-710-801-02	OPERATIONAL TEST BAGGAGE COMPARTMENT SUPPLY VALVE								
21.050	B97-26-551 20353 REF: See Workcard	MOS HRS/MSC AFL	600	+30			15-APR-2018 7651.3 5046	8251.3	8281.3
21-32-33-710-801-02A	OPERATIONAL TEST BAGGAGE COMPARTMENT SUPPLY VALVE (MANDATORY 5-40)								
21.050 MANDATORY 5-40	B97-26-551 20353 REF: See Workcard	MOS HRS/MSC AFL	650				15-APR-2018 7651.3 5046	8301.3	
21-32-41-200-801-01 (s)	INSPECTION OF THE NICOTINE FILTER CARTRIDGE - NICOTINE FILTER (534H)						PKG		
21.150	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			22-MAY-2017 7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-51-29-720-801-01 (s)	FUNCTIONAL TEST OF THE LOWER COOLING UNIT AIR INTAKE DOOR						PKG		
21.250	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
21-51-30-640-801-01 (s)	LUBRICATION OF THE LOWER COOLING UNIT AIR INTAKE DOOR CONTROL CABLE						PKG		
21.260	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
21-52-01-350-801-01	RESTORATION UPPER AIR COOLING UNIT (OVERHAUL)								
21.230 OVERHAUL	3500C01 283 REF: See Workcard	MOS HRS/MSC AFL	4000	TSI:2943.9 TSI:1843			05-AUG-2017 7451.3 4900	8507.4	
21-52-01-350-801-02	RESTORATION LOWER AIR COOLING UNIT (OVERHAUL)								
21.240 OVERHAUL	3500C01 405 REF: See Workcard	MOS HRS/MSC AFL	4000	TSI:2273.1			05-AUG-2017 7451.3 4900	9178.2	
21-52-01-900-801-01	LOWER AIR COOLING UNIT								
21.240	3500C01 405 REF: See Workcard	MOS HRS/MSC AFL	H/T				05-AUG-2017 7451.3 4900		
21-52-01-900-801-02	UPPER AIR COOLING UNIT								
21.230	3500C01 283 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:6926 TSO:2943.9 TSN:4627 TSO:1843			05-AUG-2017 7451.3 4900		
21-52-05-350-801-01	RESTORATION UPPER COOLING TURBINE (OVERHAUL)								
21.230 OVERHAUL	3176C01 00672 REF: See Workcard	MOS HRS/MSC AFL	4000	+3% TSI:2943.9			29-JUL-2017 7448 4897	8504.1	8624.1

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-05-350-801-02	RESTORATION LOWER COOLING TURBINE (OVERHAUL)								
21.240	3176C01 333 REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			18-OCT-2018 7448 4897	9721.1	9841.1
21-52-05-610-801-01	TURBOCOOLER OIL SERVICING - LOWER TURBOCOOLER (L544H)								
21.240	REF: See Workcard	MOS HRS/MSC AFL	600	+30			15-APR-2018 7651.3 5046	8251.3	8281.3
21-52-05-610-801-02	TURBOCOOLER OIL SERVICING - UPPER TURBOCOOLER (R544H)								
21.230	REF: See Workcard	MOS HRS/MSC AFL	600	+30			15-APR-2018 7651.3 5046	8251.3	8281.3
21-52-05-700-801-01	TURBOCOOLER OIL LEVEL CHECK - LOWER TURBOCOOLER (L544H)								
	REF: See Workcard	MOS HRS/MSC AFL	200					7851.3 M	
21-52-05-700-801-02	TURBOCOOLER OIL LEVEL CHECK - UPPER TURBOCOOLER (R544H)								
	REF: See Workcard	MOS HRS/MSC AFL	200					7851.3 M	
21-52-05-900-801-01	LOWER COOLING TURBINE								
21.240	3176C01 333 REF: See Workcard	MOS HRS/MSC AFL	H/T				29-JUL-2017 7448 4897		
21-52-05-900-801-02	UPPER COOLING TURBINE								
21.230	3176C01 00672 REF: See Workcard	MOS HRS/MSC AFL	H/T				29-JUL-2017 7448 4897		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-64-05-900-801-01	COCKPIT DUAL TEMPERATURE REGULATION VALVE								
21.280	BYLB50418-12 163 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			08-DEC-2015 7015 4577		
21-64-05-900-801-02	CABIN DUAL TEMPERATURE REGULATION VALVE								
21.280	BYLB50418-12 732 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			22-SEP-2006 4547 2950		
212101	CABIN AIR CONDITIONING VALVE								
21.010	BYLB50423-1 965 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
212121	COCKPIT AIR CONDITIONING VALVE								
21.010	BYLB50423-1 692 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			29-MAY-2014 6664 4295		
212141	LH COLD AIR NON RETURN VALVE								
21.020	CYLB50417 600 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
212146	RH COLD AIR NON RETURN VALVE								
21.020	CYLB50417 601 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
212151	LH AIR CONDITIONING NON RETURN VALVE								
21.030	CYLB50416 787 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212156	RH AIR CONDITIONING NON RETURN VALVE CYLB50416	MOS					18-SEP-1997		
21.030	788 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212161	BAGGAGE COMPARTMENT ISOLATION VALVE B97-26-553	MOS					18-SEP-1997		
21.050	20157 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212171	BAGGAGE COMPARTMENT SUPPLY VALVE B97-26-551	MOS					18-SEP-1997		
21.050	20353 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212181	PILOT AERATOR 2368	MOS					18-SEP-1997		
21.060	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212186	COPILOT AERATOR 2368	MOS					18-SEP-1997		
21.060	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212201	LH HOT AIR NON RETURN VALVE CYLB50414	MOS					18-SEP-1997		
21.040	1813 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212206	RH HOT AIR NON RETURN VALVE CYLB50414	MOS					18-SEP-1997		
21.040	1816 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212211	NOSE CONE SHUT OFF VALVE B97M19-201 20168 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
212241	NOSE CONE PRESSURE RELIEF VALVE P85-533 6101992 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
212251	LH ELECTRICAL RACK BLOWER 125XS01-62-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
212261	RH ELECTRICAL RACK BLOWER 125XS01-62-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
212271	FRONT TOILET BLOWER 125XS01-62-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
213091	NOSE CONE PRESSURE REGULATION PNEUMATIC ACTUATOR 7021-200 103 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
213106	STAND-BY REGULATOR 912K0101 870 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213131	NICOTINE FILTER								
21.150	234A0101 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
213141	UPPER NEGATIVE PRESSURE RELIEF VALVE								
21.180	CYLB50416 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
213156	LOWER NEGATIVE PRESSURE RELIEF VALVE								
21.180	CYLB50416 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
213171	LH BAGGAGE COMPARTMENT POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE								
21.190	2832C01 580 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
213191	RH BAGGAGE COMPARTMENT POSITIVE AND NEGATIVE PRESSURE RELIEF VALVE								
21.190	2832C01 581 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
213226	JET PUMP								
21.220	F50B722001 332 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
215113	RH AIR CONDITIONING FLOW LIMITER								
21.070	2725F030100 01067 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:17 TSO:0 TSO:0			29-JUL-2017 7448 4897		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215133	LH AIR CONDITIONING FLOW LIMITER 2725F030100	MOS		TSO:17			29-JUL-2017		
21.070	01068 REF: GENERIC NO REF	HRS/MSC AFL	H/T	TSO:0 TSO:0			7448 4897		
215801	UPPER ECU LOW LIMIT ANTI ICING VALVE/SENSOR 941G0127	MOS					18-SEP-1997		
	2060 REF:	HRS/MSC AFL	O/C				0 0		
215806	LOWER ECU LOW LIMIT ANTI ICING VALVE/SENSOR 941G0127	MOS		TSO:0			21-NOV-2006		
	1836 REF:	HRS/MSC AFL	O/C	TSO:0 TSO:0			4655 3007		
216101	CABIN TEMPERATURE THERMOSTAT 150T346	MOS					18-SEP-1997		
21.270	869 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
216106	COCKPIT TEMPERATURE THERMOSTAT 150T325	MOS					18-SEP-1997		
21.270	471 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
216126	CABIN TEMPERATURE AMPLIFIER PROBE HYLZ50514-11	MOS					05-DEC-2017		
21.290	756H REF: GENERIC NO REF	HRS/MSC AFL	O/C				7581.7 4993		
216136	COCKPIT TEMPERATURE AMPLIFIER PROBE HYLZ50514-11	MOS					18-SEP-1997		
21.290	11995 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
216146	CABIN DUCT TEMPERATURE PROBE									
21.300	AYLF50425 3026 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-APR-2017 7374 4841			
216151	COCKPIT DUCT TEMPERATURE PROBE									
21.300	AYLF50425 3019 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:25 TSN:0 TSN:0			08-DEC-2015 7015 4577			
216156	AIR CONDITIONING CONTROL BOX									
21.310	5897-651-8 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0			
CHAPTER 22 AUTO FLIGHT										
+ 22-10-00-710-801-01 (s)	OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)						PKG			
22.090	PKG 16	MOS	24	+1m			15-APR-2018			
RVSM	REF: See Workcard	HRS/MSC AFL					7651.3 5046			
22-10-02-900-802-01	PILOT AUTOPILOT DISPLAY UNIT									
22.020	822-1148-216 3131 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874			
22-10-02-900-802-02	COPILOT AUTOPILOT DISPLAY UNIT									
22.190	822-1148-216 410C REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-NOV-2006 4651 3002			
22-10-05-720-801-01 (s)	FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - AILERON SERVOMOTOR (210CA)						PKG			
	PKG 32	MOS	144	+2m			10-MAY-2010			
	REF: See Workcard	HRS/MSC AFL					5668.9 3540			

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-10-05-720-801-02 (s)	FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - ELEVATOR SERVOMOTOR (211CA) PKG 32	MOS	144	+2m			PKG 10-MAY-2010 5668.9 3540		
	REF: See Workcard	HRS/MSC AFL							
22-10-05-900-801-01	AILERON AUTOPILOT SERVOMOTOR 622-4404-002	MOS					18-SEP-1997		
22.050	787	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
22-10-05-900-801-02	ELEVATOR AUTOPILOT SERVOMOTOR 622-4404-002	MOS					18-SEP-1997		
22.060	825	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
22-10-05-900-801-03	RUDDER AUTOPILOT SERVOMOTOR 792-6781-001	MOS					18-SEP-1997		
22.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL					0		
22-10-07-700-801-01 (s)	CHECK OF THE AUTOPILOT AILERON SERVOMOTOR CABLES AND PULLEYS AILERON PKG 16	MOS	24	+1m			PKG 11-AUG-2008 5539.2 3454		
22.170		HRS/MSC							
RVSM	REF: See Workcard	AFL							
22-10-07-700-801-02 (s)	CHECK OF THE AUTOPILOT ELEVATOR SERVOMOTOR CABLES AND PULLEYS PKG 16	MOS	24	+1m			PKG 11-AUG-2008 5539.2 3454		
22.170		HRS/MSC							
RVSM	REF: See Workcard	AFL							
+ 22-10-13-700-801-01	CHECK/ADJUSTMENT AILERON SERVOMOTOR CAPSTAN SLIP TORQUE 622-5028-001	MOS		+3%					
22.110	534	HRS/MSC	14000	+3%			0	14000	14420
	REF: See Workcard	AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-10-13-700-801-02	CHECK/ADJUSTMENT ELEVATOR SERVOMOTOR CAPSTAN SLIP TORQUE								
22.120	622-5028-001 535 REF: See Workcard	MOS HRS/MSC AFL	14000	+3%			0 0	14000	14420
+ 22-10-13-720-801-03	RESTORATION RUDDER SERVOMOTOR CAPSTAN (FUNCTIONAL TEST)								
22.130	792-6785-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	10000	+3%			18-SEP-1997 0 0	10000	10300
22-10-13-900-801-01	AILERON SERVOMOTOR CAPSTAN								
22.110	622-5028-001 534 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
22-10-13-900-801-02	ELEVATOR SERVOMOTOR CAPSTAN								
22.120	622-5028-001 535 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
22-10-13-900-801-03	RUDDER SERVOMOTOR CAPSTAN								
22.130	792-6785-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
22-13-01-350-801-01	RESTORATION YAW DAMPER ACTUATOR (OVERHAUL)								
22.160 OVERHAUL	822-1169-001 6047 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%	TSI:0 TSI:0		24-JUL-2006 4405 2880	9405	9555
22-13-01-350-801-01A	RESTORATION YAW DAMPER ACTUATOR (OVERHAUL)(MADATORY 5-40)								
MANDATORY	822-1169-001 6047 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-JUL-2006 4405 2880		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-15-00-720-801-01	FUNCTIONAL TEST OF MACH TRIM	MOS					15-APR-2018		
	REF: See Workcard	HRS/MSC AFL	O/C				7651.3 5046		
221003	AUTOPILOT MODE SELECTOR	MOS					18-SEP-1997		
22.030	822-0385-002 189 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
221021	AUTOPILOT AMPLIFIER	MOS					18-SEP-1997		
	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		
221056	YAW DAMPER ACTUATOR	MOS					24-JUL-2006		
22.160	822-1169-001 6047 REF: GENERIC NO REF	HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			4405 2880		
221101	PILOT AUTOPILOT PITCH SERVO CABLE	MOS					18-SEP-1997		
22.080	59304 SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
221106	PILOT AUTOPILOT ROLL SERVO CABLE	MOS					18-SEP-1997		
22.080	59309 SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
221111	PILOT AUTOPILOT YAW SERVO CABLE	MOS					18-SEP-1997		
22.080	59303 SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0		

CHAPTER 23 COMMUNICATIONS

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-11-05-900-801-01	NO. 1 VHF ANTENNA AVS241VZ BZ334 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
23-11-05-900-801-02	NO. 2 VHF ANTENNA ANV142SZ BZ798 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
23-11-05-900-801-03	NO. 3 VHF ANTENNA S65-8280-10 1281 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAR-2011 5800.3 3635		
23-11-21-900-801-01	NO. 1 VHF TRANSCEIVER 822-1115-001 3128 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-MAY-2014 6664 4295		
23-11-21-900-801-02	NO. 2 VHF TRANSCEIVER 822-1115-001 4169 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-AUG-2011 5895 3706		
23-11-21-900-801-03	NO. 3 VHF TRANSCEIVER 822-1115-021 2900 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:90			22-NOV-1999 918 757		
23-12-13-900-801-01	HF ANTENNA F50B312001B2 BZ127 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 23-60-00-760-801-01 (s)	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS						PKG		
23.060	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500				15-APR-2018 7651.3 5046		
23-81-01-900-801-01	PILOT RADIO TUNING UNIT								
23.050	822-0730-334 1565 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:117 TSO:3523 TSO:2072			03-JUN-2014 6664 4295		
23-81-01-900-801-02	COPILOT RADIO TUNING UNIT								
23.050	822-0730-334 178H REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:117 TSO:3523 TSO:2072			03-JUN-2014 6664 4295		
231001	SELCAL DECODER								
	1200008-003 150 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
232071	HF TRANSCEIVER								
23.070	822-0102-001 217 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
232076	NO. 2 HF TRANSCEIVER								
23.170	822-0102-001 294 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-SEP-1998 374 336		
232081	HF AMPLIFIER COUPLER								
23.070	622-8114-002 1769 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
232083	NO. 2 HF AMPLIFIER/ COUPLER 622-8114-002 1777 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
232086	NO. 1 HF CONTROL UNIT 064-1016-03 98884 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
232088	NO. 2 HF CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
233001	PUBLIC ADDRESS (TEAM) AMPLIFIER M10502358-02 9706033 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
233006	PILOT AUDIO CONTROL B1045F357HRS7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
233011	COPILOT AUDIO CONTROL B1045F357HRS7 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
237101	HPA/LNA SATAFIS AMPLIFIER 153-017310-01 534 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237103	COMM UNIT,SATAFIS 153-017311-01 589 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
237105	SATAFIS ANTENNA S65-8282-111 4233 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
237121	AIRCELL AXCESS TRANSCEIVER P12023 1202310167 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-NOV-2006 4655 3007		
237129	AIRCELL AXCESS ROUTER P12083 1208310202 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-NOV-2006 4655 3007		
237141	COCKPIT AIRCELL HANDSET P12192-002 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-NOV-2006 4655 3007		
237145	LH CABIN AIRCELL HANDSET P12192-002 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-NOV-2006 4655 3007		
237147	RH CABIN AIRCELL HANDSET P12192-002 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-NOV-2006 4655 3007		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237155	AIRCELL LH CH#1 ANTENNA 015-10306-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-NOV-2006 4655 3007		
237157	AIRCELL RH CH#2 ANTENNA 015-10306-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-NOV-2006 4655 3007		
CHAPTER 24 ELECTRICAL POWER									
24-20-01-900-802-01	PILOT STATIC INVERTER PC17A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
24-20-01-900-802-02	COPILOT STATIC INVERTER PC17A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
24-20-01-900-802-03	STANDBY STATIC INVERTER PC17A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 24-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE ENGINE 1 VOLTAGE MONITORING CIRCUIT PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 22-MAY-2017 7416.5 4869		
+ 24-30-00-710-801-02 (s)	OPERATIONAL TEST OF THE ENGINE 2 VOLTAGE MONITORING CIRCUIT PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 22-MAY-2017 7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30-00-710-801-03 (s)	OPERATIONAL TEST OF THE ENGINE 3 VOLTAGE MONITORING CIRCUIT						PKG		
24.230	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			22-MAY-2017 7416.5 4869		
+ 24-30-00-710-801-04 (s)	OPERATIONAL TEST OF THE APU VOLTAGE MONITORING CIRCUIT						PKG		
24.240	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			29-MAY-2017 7416.5 4869		
24-31-09-900-801-01	ENGINE 1 GENERATOR CONTROL UNIT (GCU)								
24.070	D22-100 1187 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
24-31-09-900-801-02	ENGINE 2 GENERATOR CONTROL UNIT (GCU)								
24.070	D22-100 1171 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
24-31-09-900-801-03	ENGINE 3 GENERATOR CONTROL UNIT (GCU)								
24.070	D22-100 1178 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
24-31-09-900-801-04	APU GENERATOR CONTROL UNIT (GCU)								
24.300	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	O/C		TSN:0 TSN:0 TSN:0 TSN:0		18-SEP-1997 0 0 0		
24-31-13-350-801-01	RESTORATION NO. 1 ENGINE STARTER GENERATOR (OVERHAUL)								
24.080 OVERHAUL	8060-360 388 REF: See Workcard	MOS HRS/MSC AFL	1200	+3%			21-SEP-2018 7785.2 5145	8985.2	9021.2

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-13-350-801-02	RESTORATION NO. 2 ENGINE STARTER GENERATOR (OVERHAUL)								
24.090	8060-360	MOS					27-JUL-2018		
OVERHAUL	401 REF: See Workcard	HRS/MSC AFL	1200	+3%			7723.6 5103	8923.6	8959.6
24-31-13-350-801-03	RESTORATION NO. 3 ENGINE STARTER GENERATOR (OVERHAUL)								
24.085	8060-360	MOS					05-JUN-2018		
OVERHAUL	2105 REF: See Workcard	HRS/MSC AFL	1200	+3%			7685.2 5077	8885.2	8921.2
24-31-13-350-801-04	RESTORATION APU STARTER GENERATOR (OVERHAUL)								
24.210	8060-360	MOS					03-APR-2017		
OVERHAUL	301 REF: See Workcard	HRS/MSC AFL	1200	+3%			3902.9	5102.9	5138.9
24-31-13-900-801-01	NO. 1 ENGINE STARTER GENERATOR								
24.080	8060-360	MOS					21-SEP-2018		
	388 REF: See Workcard	HRS/MSC AFL	H/T				7785.2 5145		
24-31-13-900-801-02	NO. 2 ENGINE STARTER GENERATOR								
24.090	8060-360	MOS					27-JUL-2018		
	401 REF: See Workcard	HRS/MSC AFL	H/T				7723.6 5103		
24-31-13-900-801-03	NO. 3 ENGINE STARTER GENERATOR								
24.085	8060-360	MOS					05-JUN-2018		
	2105 REF: See Workcard	HRS/MSC AFL	H/T				7685.2 5077		
24-31-17-220-803-01	CHECK NO. 1 ENGINE STARTER GENERATOR BRUSHES								
	8060-360	MOS					21-SEP-2018		
	388 REF: See Workcard	HRS/MSC AFL	600	+60			7785.2 5145	8385.2	8445.2

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-17-220-803-02	CHECK NO. 2 ENGINE STARTER GENERATOR BRUSHES 8060-360 401 REF: See Workcard	MOS HRS/MSC AFL	600	+60			27-JUL-2018 7723.6 5103	8323.6	8383.6
24-31-17-220-803-03	CHECK NO. 3 ENGINE STARTER GENERATOR BRUSHES 8060-360 2105 REF: See Workcard	MOS HRS/MSC AFL	600	+60			05-JUN-2018 7685.2 5077	8285.2	8345.2
24-32-00-710-803-01 (s)	OPERATIONAL TEST OF THE BATTERY BUS DIODE (59P1) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 29-MAY-2017 7416.5 4869		
24-32-00-710-803-02 (s)	OPERATIONAL TEST OF THE BATTERY BUS DIODE (59P2) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 29-MAY-2017 7416.5 4869		
24-32-00-720-801-01	FUNCTIONAL TEST OF THE NO. 2 BATTERY BUS DIODE (59P1) REF: See Workcard	MOS HRS/MSC AFL	O/C				27-MAY-2014 6664 4295		
24-32-00-720-801-02	FUNCTIONAL TEST OF THE NO. 1 BATTERY BUS DIODE (59P2) REF: See Workcard	MOS HRS/MSC AFL	O/C				27-MAY-2014 6664 4295		
24-32-01-350-801-01	RESTORATION NO. 1 BATTERY (OVERHAUL) 2376-4 122444 OVERHAUL REF: See Workcard	MOS HRS/MSC AFL	12	+1m			11-OCT-2017	11-OCT-2018	11-NOV-2018

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-01-350-801-02	RESTORATION NO. 2 BATTERY (OVERHAUL)								
24.190 OVERHAUL	2376-4 09052000DFAD0 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			11-OCT-2017	11-OCT-2018	11-NOV-2018
24-32-01-700-801-01	REGULAR CHECK NO. 1 BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.100	2376-4 122444 REF: See Workcard	MOS HRS/MSC AFL	6 250	+15d +25			15-APR-2018 7651.3 5046	15-OCT-2018 7901.3	30-OCT-2018 7926.3
24-32-01-700-801-02	REGULAR CHECK NO. 2 BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.190	2376-4 09052000DFAD0 REF: See Workcard	MOS HRS/MSC AFL	6 250	+15d +25			15-APR-2018 7651.3 5046	15-OCT-2018 7901.3	30-OCT-2018 7926.3
24-32-01-700-802-01	REGULAR CHECK NO. 1 BATTERY (CONCORDE LEAD/ACID BATTERY ONLY)								
24.100	2376-4 122444 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-01-700-802-02	REGULAR CHECK NO. 2 BATTERY (CONCORDE LEAD/ACID BATTERY ONLY)								
24.190	2376-4 09052000DFAD0 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-01-900-801-01	NO. 1 BATTERY								
24.100	2376-4 122444 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-OCT-2017 7500.2 4933		
24-32-01-900-801-02	NO. 2 BATTERY								
24.190	2376-4 09052000DFAD0 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-OCT-2017 7500.2 4933		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-01-960-801-01	DISCARD NO. 1 BATTERY (CONCORDE LEAD/ACID BATTERY ONLY)								
24.100	2376-4 122444 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-01-960-801-02	DISCARD NO. 2 BATTERY (CONCORDE LEAD/ACID BATTERY ONLY)								
24.190	2376-4 09052000DFAD0 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-05-710-801-01	OPERATIONAL TEST BATTERY FAN								
24.170	VA0906XXA 11047 REF: See Workcard	MOS HRS/MSC AFL	C/C				23-OCT-2003 2404.2 1853		
+ 24-32-09-610-801-02	SERVICING NO. 1 IRS EMERGENCY POWER SUPPLY (NICKEL-CADMIUM BATTERY ONLY)								
	135687 5011 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			01-MAR-2017	01-MAR-2018	12-MAR-2018
24-32-09-610-801-03	SERVICING NO. 2 IRS EMERGENCY POWER SUPPLY (NICKEL-CADMIUM BATTERY ONLY)								
	135687 3389 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			11-OCT-2017 7500.2 4933	11-OCT-2018	22-OCT-2018
+ 24-32-09-610-801-04	SERVICING NO. 3 IRS EMERGENCY POWER SUPPLY (NICKEL-CADMIUM BATTERY ONLY)								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 24-32-09-610-801-05	SERVICING AUXILIARY POWER SUPPLY (NICKEL-CADMIUM BATTERY ONLY)								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-32-09-710-802-01	OPERATIONAL TEST STAND-BY HORIZON POWER SUPPLY (SECURAPLANE XL-245 TYPE BATTERY ONLY) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
+ 24-32-09-710-802-02	OPERATIONAL TEST NO. 1 IRS EMERGENCY POWER SUPPLY (SECURAPLANE XL-245 TYPE BATTERY ONLY) 135687 5011 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 24-32-09-710-802-03	OPERATIONAL TEST NO. 2 IRS EMERGENCY POWER SUPPLY (SECURAPLANE XL-245 TYPE BATTERY ONLY) 135687 3389 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 24-32-09-710-802-04	OPERATIONAL TEST NO. 3 IRS EMERGENCY POWER SUPPLY (SECURAPLANE XL-245 TYPE BATTERY ONLY) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 24-32-09-710-802-05	OPERATIONAL TEST AUXILIARY POWER SUPPLY (SECURAPLANE XL-245 TYPE BATTERY ONLY) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
24-32-09-900-801-01	STAND-BY HORIZON POWER SUPPLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
24-32-09-900-801-02	NO. 1 IRS EMERGENCY POWER SUPPLY 135687 5011 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-MAR-2017		
34.950									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-900-801-03	NO. 2 IRS EMERGENCY POWER SUPPLY								
34.950	135687 3389 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-OCT-2017 7500.2 4933		
24-32-09-900-801-04	NO. 3 IRS EMERGENCY POWER SUPPLY								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
24-32-09-900-801-05	AUXILIARY POWER SUPPLY								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
+ 24-32-09-960-802-01	DISCARD STAND-BY HORIZON POWER SUPPLY BATTERY (SECURAPLANE XL-245 TYPE BATTERY ONLY)								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
24-32-09-960-802-02	DISCARD NO. 1 IRS EMERGENCY POWER SUPPLY BATTERY (SECURAPLANE XL-245 TYPE BATTERY ONLY)								
34.950	135687 5011 REF: See Workcard	MOS HRS/MSC AFL	O/C						
24-32-09-960-802-03	DISCARD NO. 2 IRS EMERGENCY POWER SUPPLY BATTERY (SECURAPLANE XL-245 TYPE BATTERY ONLY)								
34.950	135687 3389 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-09-960-802-04	DISCARD NO. 3 IRS EMERGENCY POWER SUPPLY BATTERY (SECURAPLANE XL-245 TYPE BATTERY ONLY)								
34.950	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-32-09-960-802-05	DISCARD AUXILIARY POWER SUPPLY BATTERY (SECURAPLANE XL-245 TYPE BATTERY ONLY) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
24-33-01-900-801-01 24.210	APU STARTER GENERATOR 8060-360 301 REF: See Workcard	MOS HRS/MSC AFL APH	H/T 0	TSO:1 TSO:0			03-APR-2017		
24-33-05-220-803-01	CHECK APU STARTER GENERATOR BRUSHES 8060-360 301 REF: See Workcard	MOS HRS/MSC AFL APH	600	+60			03-APR-2017 3902.2	4502.2	4562.2
+ 24-40-00-720-801-01 (s) 24.250	FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 29-MAY-2017 7416.5 4869		
24-41-00-720-801-01	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE FUNCTION REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
24-41-00-720-801-02	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF THE SAFETY DEVICES REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
24-63-13-710-801-01 (s) 24.270	OPERATIONAL TEST OF THE DOME LIGHT PCB PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 29-MAY-2017 7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240011	PRINTED CIRCUIT BOARD CI915 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
240016	PRINTED CIRCUIT BOARD CI852A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
240021	PRINTED CIRCUIT BOARD CI853B SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
240026	PRINTED CIRCUIT BOARD CI854A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
240031	PRINTED CIRCUIT BOARD CI855B SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
240036	PRINTED CIRCUIT BOARD CI857 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
240041	PRINTED CIRCUIT BOARD CI857 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240046	PRINTED CIRCUIT BOARD								
39.040	C1955B SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
242111	NO. 1 FREQUENCY MONITOR PRINTED CARD								
24.020	C1-818A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
242116	NO. 2 FREQUENCY MONITOR PRINTED CARD								
24.020	C1-818A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243191	NO. 1 BATTERY (THERMISTOR) TEMPERATURE PROBE								
24.100	P600-14B SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-SEP-2012 6193.9 3935		
243196	NO. 2 BATTERY (THERMISTOR) TEMPERATURE PROBE								
24.190	P600-14B SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-SEP-2012 6193.9 3935		
243211	NO. 1 BATTERY CONNECTOR								
24.130	410 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243213	NO. 1 BATTERY REVERSE CURRENT RELAY								
24.140	317GC01Y1AB 860 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243216	NO. 2 BATTERY CONNECTOR								
24.130	410 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243219	NO. 2 BATTERY REVERSE CURRENT RELAY								
24.140	317GC01Y1AB 842 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243221	BATTERY FAN								
24.170	VA0906XXA 11047 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243236	NO. 1 GENERATOR REVERSE CURRENT RELAY								
24.150	3510M0 3663 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243238	NO. 1 STARTER/ RELAY								
24.160	2540M SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243241	NO. 2 GENERATOR REVERSE CURRENT RELAY								
24.150	3510M0 3661 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243243	NO. 2 STARTER/ RELAY								
24.160	2540M SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243246	NO. 3 GENERATOR REVERSE CURRENT RELAY 3510M0	MOS					18-SEP-1997		
24.150	3664 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
243248	NO. 3 STARTER/ RELAY 2540M	MOS					18-SEP-1997		
24.160	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
243249	APU GENERATOR REVERSE CURRENT RELAY 3510M0	MOS					18-SEP-1997		
24.280	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
243250	APU STARTER RELAY 2540M0	MOS					18-SEP-1997		
24.290	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
243251	LH POWER SUPPLY DC VOLTMETER 2396-118-0	MOS					18-SEP-1997		
24.050	1772 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
243261	RH POWER SUPPLY DC VOLTMETER 2396-118-0	MOS					19-MAR-1999		
24.050	1249 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			566 497		
243271	LH POWER SUPPLY DC AMMETER 2396-323-0	MOS					18-SEP-1997		
24.060	1374 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243281	RH POWER SUPPLY DC AMMETER								
24.060	2396-323-0 1376 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243291	BATTERY TEMPERATURE INDICATOR								
24.200	BT1600-3A1 8014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
243805	LEFT AMMETER SELECT (36P) SWITCH								
	K615-0-0 P5 REF:	MOS HRS/MSC AFL	O/C				17-JAN-2003 1881 1554		
243807	RIGHT AMMETER SELECT (37P) SWITCH								
	K615-0-0 P5 REF:	MOS HRS/MSC AFL	O/C				17-JAN-2003 1881 1554		
244401	GROUND POWER RECEPTACLE								
24.180	280B SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
CHAPTER 25		EQUIPMENT/FURNISHINGS							
25-00-01-200-801-01	INSPECTION OF THE ONBOARD KIT								
25.220	REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
25-11-01-900-801-01	LH PILOT SEAT								
25.010	394-14 324 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-01-900-801-02	RH PILOT SEAT								
25.010	394-24 324 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
25-11-05-200-801-01A	VISUAL INSPECTION OF BUCKLE SPRING OF ANJOU AERONAUTIQUE SAFETY BELTS AND RESTRAINT SYSTEM (TYPE 343 AMD 343-1)								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
25-11-05-220-801-01 (s)	DETAILED INSPECTION OF THE PILOT SEAT SAFETY BELT ASSEMBLY - LH PILOT SEAT (L2MG)								
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
25-11-05-220-801-02 (s)	DETAILED INSPECTION OF THE PILOT SEAT SAFETY BELT ASSEMBLY - RH PILOT SEAT (R2MG)								
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
25-11-13-640-801-01 (s)	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - LH PILOT SEAT (L2MG)								
25.010	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 29-MAY-2017 7416.5 4869		
25-11-13-640-801-02 (s)	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - RH PILOT SEAT (R2MG)								
25.010	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 29-MAY-2017 7416.5 4869		
25-11-19-960-801-01 (s)	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - LH PILOT SEAT (L2MG)								
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-19-960-801-02 (s)	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - RH PILOT SEAT (R2MG) PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
	REF: See Workcard								
+ 25-40-25-100-801-01	CLEANING OF THE TRASH CANS 25.060	MOS HRS/MSC AFL	1000				15-APR-2018 7651.3 5046	8651.3	
	REF: See Workcard								
+ 25-60-00-200-801-02 (s)	INSPECTION OF THE SAFETY EQUIPMENT PKG 16	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
	REF: See Workcard								
25-60-00-200-801-03 (s)	INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT PKG 16	MOS HRS/MSC AFL	24				PKG 18-SEP-1997 0 0		
	REF: See Workcard								
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207) MANDATORY	MOS HRS/MSC AFL	12				19-MAR-2018 7636.7 5034	19-MAR-2019	
	REF: GENERIC NO REF								
25-61-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM (SELF-TEST OF ELT) 25.210	MOS HRS/MSC AFL	6	+1m			15-APR-2018 7651.3 5046	15-OCT-2018	15-NOV-2018
	REF: See Workcard								
25-61-00-710-801-02 (s)	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM (CHECK OF ELT COCKPIT CONTROLS) PKG 17	MOS HRS/MSC AFL	36	+1m		-9	PKG 30-MAY-2017 7416.5 4869		
	REF: See Workcard								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-61-00-710-801-03	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM (ELT 90/91)	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
	REF: See Workcard								
25-61-00-710-801-04	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM (ELT) - CHECK OF ELT 96/97 UNIT CONTROLS	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
	REF: See Workcard								
25-61-01-710-801-01	OPERATIONAL TEST EMERGENCY LOCATOR (ELT) TRANSMITTER G-SWITCH ELT97A2560000000 2329	MOS HRS/MSC AFL	60	+3%			19-MAR-2018 7636.7 5034	19-MAR-2023	13-MAY-2023
	REF: See Workcard								
25-61-01-900-803-01	EMERGENCY LOCATOR (ELT) TRANSMITTER ELT97A2560000000 2329	MOS HRS/MSC AFL	O/C		TSR:50 TSO:7636.7 TSR:1055.1 TSR:799		19-MAR-2018 7636.7 5034		
25.210	REF: See Workcard								
25-61-13-960-801-01	DISCARD EMERGENCY LOCATOR (ELT) TRANSMITTER BATTERY PACK ELT97A2560000000 2329	MOS HRS/MSC AFL	DUE				19-MAR-2018 7636.7 5034	01-OCT-2020 M	
	REF: See Workcard								
25-62-00-900-801-01	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON DK-120 SC25588	MOS HRS/MSC AFL	O/C				27-SEP-2018 7790.4 5152		
31.100	REF: See Workcard								
25-62-00-900-801-02	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		18-SEP-1997 0 0		
	REF: See Workcard								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-01-720-801-01	FUNCTIONAL TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON								
31.100	DK-120 SC25588 REF: See Workcard	MOS HRS/MSC AFL	25				15-APR-2018 7651.3 5046	15-MAY-2020	
+ 25-62-01-720-801-02	FUNCTIONAL TEST FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
25-62-05-960-801-01	DISCARD COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY								
31.100 LIFE LIMIT	DK-120 SC25588 REF: See Workcard	MOS HRS/MSC AFL	DUE				27-SEP-2018 7790.4 5152	01-MAY-2020 M	
+ 25-62-05-960-801-02	DISCARD FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	DUE				18-SEP-1997 0 0		
LIFE LIMIT									
+ 25-64-17-200-802-01	INSPECTION PILOT LIFE VEST								
25.190	S-21150-7301 69595-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
+ 25-64-17-200-802-02	INSPECTION COPILOT LIFE VEST								
25.190	S21150-7301 47121-1141 REF:	MOS HRS/MSC AFL	24	+3%			20-SEP-2016	01-SEP-2021 M	22-SEP-2021
+ 25-64-17-200-803-01	INSPECTION NO. 1 PASSENGER LIFE VEST								
25.100	S21100-6301 82887-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-64-17-200-803-02	INSPECTION NO. 2 PASSENGER LIFE VEST S21100-6301 71471-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
25.110									
+ 25-64-17-200-803-03	INSPECTION NO. 3 PASSENGER LIFE VEST S21100-6301 71460-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
25.120									
+ 25-64-17-200-803-04	INSPECTION NO. 4 PASSENGER LIFE VEST S-21100-6301 82890-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
25.130									
+ 25-64-17-200-803-05	INSPECTION NO. 5 PASSENGER LIFE VEST S-21100-6301 71463-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
25.140									
+ 25-64-17-200-803-06	INSPECTION NO. 6 PASSENGER LIFE VEST S-21100-6301 71473-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
25.150									
+ 25-64-17-200-803-07	INSPECTION NO. 7 PASSENGER LIFE VEST S-21100-6301 73306-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
25.160									
+ 25-64-17-200-803-08	INSPECTION NO. 8 PASSENGER LIFE VEST S-21100-6301 82886-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
25.170									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-64-17-200-803-09	INSPECTION NO. 9 PASSENGER LIFE VEST								
25.180	S-21100-6301 71470-1141 REF:	MOS HRS/MSC AFL	24	+3%			12-SEP-2014	01-SEP-2019 M	22-SEP-2019
25-64-17-350-802-01	RESTORATION PILOT LIFE VEST (OVERHAUL OR DISCARD)								
25.190	S-21150-7301 69595-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSI:0 TSI:0 TSI:0		14-JUL-2006 4400 2874		
25-64-17-350-802-02	RESTORATION COPILOT LIFE VEST (OVERHAUL OR DISCARD)								
25.190	S21150-7301 47121-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSI:0 TSI:0 TSI:0		14-JUL-2006 4400 2874		
25-64-17-350-802-03	RESTORATION THIRD CREW MEMBER LIFE VEST (OVERHAUL OR DISCARD)								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
25-64-17-350-803-01	RESTORATION NO. 1 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.100	S21100-6301 82887-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSI:0 TSI:0 TSI:0		14-JUL-2006 4400 2874		
25-64-17-350-803-02	RESTORATION NO. 2 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.110	S21100-6301 71471-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSI:0 TSI:0 TSI:0		14-JUL-2006 4400 2874		
25-64-17-350-803-03	RESTORATION NO. 3 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.120	S21100-6301 71460-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSI:0 TSI:0 TSI:0		14-JUL-2006 4400 2874		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-04	RESTORATION NO. 4 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.130	S-21100-6301 82890-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			14-JUL-2006 4400 2874		
25-64-17-350-803-05	RESTORATION NO. 5 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.140	S-21100-6301 71463-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			14-JUL-2006 4400 2874		
25-64-17-350-803-06	RESTORATION NO. 6 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.150	S-21100-6301 71473-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			14-JUL-2006 4400 2874		
25-64-17-350-803-07	RESTORATION NO. 7 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.160	S-21100-6301 73306-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			14-JUL-2006 4400 2874		
25-64-17-350-803-08	RESTORATION NO. 8 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.170	S-21100-6301 82886-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			14-JUL-2006 4400 2874		
25-64-17-350-803-09	RESTORATION NO. 9 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.180	S-21100-6301 71470-1141 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			14-JUL-2006 4400 2874		
250002	RENEW ELT REGISTRATION (AIRFRAME MOUNTED ELT)								
	REF:	MOS HRS/MSC AFL	24				08-DEC-2015 7015 4577	08-DEC-2017	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251121	PILOT SEAT BELT 1101167-09 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
251126	COPILOT SEAT BELT 1101167-09 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
251130	PILOT SHOULDER HARNESS 2825A3X03 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
251135	COPILOT SHOULDER HARNESS 2825A3X03 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
251141	PILOT HEATING CARPET 592046 370 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-DEC-1997 28 14		
251146	COPILOT HEATING CARPET 592045 362 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
251151	THIRD CREW MEMBER HEATING CARPET 592044 363 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252102	FIRST AID KIT FK100 FK100-39779 REF:	MOS HRS/MSC AFL	O/C	TSN:38 TSN:766.3 TSN:587			05-MAR-2017 7347.9 4822		
252104	INSPECT/CHECK FIRST AID KIT FK100 FK100-39779 REF:	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046	15-APR-2019	
256001	NO. 1 LIFE RAFT 5A3204-30311 4R065 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:24 TSR:585.6 TSR:434			15-APR-2018 7651.3 5046		
256006	INSPECT/CHECK NO. 1 LIFE RAFT 5A3204-30311 4R065 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046	15-APR-2019	
256011	NO. 2 LIFE RAFT 5A3204-30321 4R068 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:44 TSR:24 TSO:930 TSR:585.6 TSO:707 TSR:434			15-APR-2018 7651.3 5046		
+ 256016	INSPECT/CHECK NO. 2 LIFE RAFT 5A3204-30321 4R068 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046	15-APR-2019	
256021	NO. 3 LIFE RAFT 5A3204-30311 4R041 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:24 TSR:585.6 TSR:434			15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256026	INSPECT/CHECK NO. 3 LIFE RAFT								
25.090	5A3204-30311 4R041 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046	15-APR-2019	
256031	NO. 1 PASSENGER LIFE VEST								
25.100	S21100-6301 82887-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			09-MAR-2017 7347.9 4822		
256041	NO. 2 PASSENGER LIFE VEST								
25.110	S21100-6301 71471-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			09-MAR-2017 7347.9 4822		
256051	NO. 3 PASSENGER LIFE VEST								
25.120	S21100-6301 71460-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			05-MAR-2017 7347.9 4822		
256061	NO. 4 PASSENGER LIFE VEST								
25.130	S-21100-6301 82890-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			06-MAR-2017 7347.9 4822		
256071	NO. 5 PASSENGER LIFE VEST								
25.140	S-21100-6301 71463-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			06-MAR-2017 7347.9 4822		
256081	NO. 6 PASSENGER LIFE VEST								
25.150	S-21100-6301 71473-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			06-MAR-2017 7347.9 4822		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256091	NO. 7 PASSENGER LIFE VEST S-21100-6301 73306-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			09-MAR-2017 7347.9 4822		
256101	NO. 8 PASSENGER LIFE VEST S-21100-6301 82886-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			09-MAR-2017 7347.9 4822		
256111	NO. 9 PASSENGER LIFE VEST S-21100-6301 71470-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			06-MAR-2017 7347.9 4822		
256121	PILOT LIFE VEST S-21150-7301 69595-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			09-MAR-2017 7347.9 4822		
256131	COPILOT LIFE VEST S21150-7301 47121-1141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:128 TSO:2947.9 TSO:1948			09-MAR-2017 7347.9 4822		
256138	THIRD CREW MEMBER LIFE JACKET S21150-7301 69595-1141 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			14-JUL-2006 4400 2874		
256139	INSPECT/CHECK THIRD CREW MEMBER LIFE JACKET S21150-7301 69595-1141 REF:	MOS HRS/MSC AFL	24				30-DEC-2014	30-DEC-2019 M	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256141	THIRD CREW MEMBER LIFE VEST PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
256812	RENEW NO. 2 LIFE RAFT [NO. 2 LEFT RAFT] NOAA 406 MHZ REGISTRATION 5A3204-30321 4R068 REF:	MOS HRS/MSC AFL	24				06-MAR-2017 7347.9 4822	06-MAR-2019	
256813	REPLACE NO. 2 LIFE RAFT ELT BATTERY 5A3204-30321 4R068 REF:	MOS HRS/MSC AFL	DUE				05-AUG-2014 6721.3 4339	01-MAY-2020 M	
257101	AM/FM/CD STEREO 5303 A4800035 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
257109	CABIN VIDEO CONTROL 990-4085-001 9707485 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
257111	CABIN VIDEO MONITOR- 990-4140-005 9706029 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-APR-2003 2081 1653		
257115	VIDEO CASSETTE PLAYER SVX-20 14128 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
257133	AIRSHOW CONTROL 922000-2 235 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
257135	COMM UNIT,DATA-AIRSHOW 920050 628 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-JAN-2011 5771.2 3612		
259060	FWD SEAT AUDIO CONTROLLER SPS-F90-5336 07970135 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-MAY-2004 2866 2076		
259070	AFT SEAT AUDIO CONTROLLER SPS-F90-5335 07970163 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-MAY-2004 2866 2076		

CHAPTER 26 FIRE PROTECTION

+ 26-10-00-720-801-01	FUNCTIONAL TEST NO. 1 ENGINE FIRE DETECTOR 30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5600/E/C				06-MAR-2017 7347.9 4822		12947.9
+ 26-10-00-720-801-01A	FUNCTIONAL TEST NO. 1 ENGINE FIRE DETECTOR (MANDATORY 5-40) 30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5600				06-MAR-2017 7347.9 4822		12947.9
+ 26-10-00-720-801-02	FUNCTIONAL TEST NO. 2 ENGINE FIRE DETECTOR 30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5600/E/C				06-MAR-2017 7347.9 4822		12947.9

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-10-00-720-801-02A	FUNCTIONAL TEST NO. 2 ENGINE FIRE DETECTOR (MANDATORY 5-40)								
26.015	30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5600				06-MAR-2017 7347.9 4822	12947.9	
MANDATORY 5-40									
+ 26-10-00-720-801-03	FUNCTIONAL TEST NO. 3 ENGINE FIRE DETECTOR								
26.010	30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5600/E/C				06-MAR-2017 7347.9 4822	12947.9	
+ 26-10-00-720-801-03A	FUNCTIONAL TEST NO. 3 ENGINE FIRE DETECTOR (MANDATORY 5-40)								
26.010	30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	5600				06-MAR-2017 7347.9 4822	12947.9	
MANDATORY 5-40									
+ 26-10-00-720-801-04	FUNCTIONAL TEST APU FIRE DETECTOR								
26.050	30011690040012 77731 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	5600				23-OCT-2003 2404.2 1853	8004.2	
+ 26-10-00-720-801-04A	FUNCTIONAL TEST APU FIRE DETECTOR (MANDATORY 5-40)								
26.050	30011690040012 77731 REF: See Workcard	MOS HRS/MSC AFL	5600				23-OCT-2003 2404.2 1853	8004.2	
MANDATORY 5-40									
+ 26-10-00-720-801-05	FUNCTIONAL TEST REAR COMPARTMENT FIRE DETECTOR								
26.050	30015160027012 77843 REF: See Workcard	MOS HRS/MSC AFL	5600				23-OCT-2003 2404.2 1853	8004.2	
+ 26-10-00-720-801-05A	FUNCTIONAL TEST REAR COMPARTMENT FIRE DETECTOR (MANDATORY 5-40)								
26.050	30015160027012 77843 REF: See Workcard	MOS HRS/MSC AFL	5600				23-OCT-2003 2404.2 1853	8004.2	
MANDATORY 5-40									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-10-00-720-801-06	FUNCTIONAL TEST LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR								
26.050	300119800270-3 77757 REF: See Workcard	MOS HRS/MSC AFL	5600				23-OCT-2003 2404.2 1853	8004.2	
+ 26-10-00-720-801-06A	FUNCTIONAL TEST LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (MANDATORY 5-40)								
26.050 MANDATORY 5-40	300119800270-3 77757 REF: See Workcard	MOS HRS/MSC AFL	5600				23-OCT-2003 2404.2 1853	8004.2	
+ 26-10-00-720-801-07	FUNCTIONAL TEST RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR								
26.050	300119800270-3 77668 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	5600				23-OCT-2003 2404.2 1853	8004.2	
+ 26-10-00-720-801-07A	FUNCTIONAL TEST RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR (MANDATORY 5-40)								
26.050 MANDATORY 5-40	300119800270-3 77668 REF: See Workcard	MOS HRS/MSC AFL	5600				23-OCT-2003 2404.2 1853	8004.2	
26-10-01-900-801-01	NO. 1 ENGINE FIRE DETECTOR								
26.010	30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:7347.9			06-MAR-2017 7347.9 4822		
26-10-01-900-801-02	NO. 2 ENGINE FIRE DETECTOR								
26.015	30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
26-10-01-900-801-03	NO. 3 ENGINE FIRE DETECTOR								
26.010	30016190040013 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-10-21-900-801-01	BAGGAGE COMPARTMENT SMOKE DETECTOR								
26.030	FR2210-2 325 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
26-20-01-760-801-01 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 1" SELECTOR SWITCH (POSITION "1")						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
26-20-01-760-801-02 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 1" SELECTOR SWITCH (POSITION "2")						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
26-20-01-760-801-03 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 2" SELECTOR SWITCH (POSITION "1")						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
26-20-01-760-801-04 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 2" SELECTOR SWITCH (POSITION "2")						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
26-20-01-760-801-05 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 3" SELECTOR SWITCH (POSITION "1")						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-01-760-801-06 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "ENG 3" SELECTOR SWITCH (POSITION "2")						PKG		
	PKG 31	MOS	72	+2m			01-APR-2016		
		HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		
+ 26-20-01-760-801-07 (s)	CHECK OF THE CORRECT OPERATION APU EXTINGUISHER CONTROL SWITCHES						PKG		
26.170	PKG 31	MOS	72	+2m			01-APR-2016		
		HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		
+ 26-20-01-760-801-08 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL "FIRE BAG COMP" SELECTOR SWITCH						PKG		
26.220	PKG 31	MOS	72	+2m			01-APR-2016		
		HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		
+ 26-20-01-760-801-09 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL "FIRE AFT COMP" SELECTOR SWITCH						PKG		
26.190	PKG 31	MOS	72	+2m			01-APR-2016		
		HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		
+ 26-20-09-220-801-01	WEIGHING ENGINE 1 FIRST- SHOOT, ENGINE 2 SECOND-SHOOT FIRE (14W1) EXTINGUISHER								
26.060	860640	MOS	12				15-APR-2018		15-APR-2019
	54267	HRS/MSC							
	REF: See Workcard	AFL							
+ 26-20-09-220-801-02	WEIGHING ENGINE 2 FIRST- SHOOT, ENGINE 3 SECOND-SHOOT FIRE (14W2) EXTINGUISHER								
26.070	860640	MOS	12				15-APR-2018		15-APR-2019
	53774	HRS/MSC							
	REF: See Workcard	AFL							
+ 26-20-09-220-801-03	WEIGHING ENGINE 3 FIRST- SHOOT, ENGINE 1 SECOND-SHOOT FIRE (14W3) EXTINGUISHER								
26.080	860640	MOS	12				15-APR-2018		15-APR-2019
	56146	HRS/MSC							
	REF: See Workcard	AFL							

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-09-220-801-04	WEIGHING APU (73W) FIRE EXTINGUISHER 30111102 31939A1 REF: See Workcard	MOS HRS/MSC AFL	12				15-APR-2018	15-APR-2019	
26.090									
+ 26-20-09-220-801-05	WEIGHING REAR COMPARTMENT (23W1) FIRE EXTINGUISHER 30702102-1 28548D6 REF: See Workcard	MOS HRS/MSC AFL	12				15-APR-2018	15-APR-2019	
26.210									
+ 26-20-09-220-801-06	WEIGHING REAR/BAGGAGE COMPARTMENT (23W2) FIRE EXTINGUISHER 30702102-1 29024D6 REF: See Workcard	MOS HRS/MSC AFL	12				15-APR-2018	15-APR-2019	
26.180									
26-20-09-350-801-01	RESTORATION ENGINE 1 FIRST- SHOOT, ENGINE 2 SECOND-SHOOT FIRE (14W1) EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) 860640 54267 REF: See Workcard	MOS HRS/MSC AFL	60				10-MAR-2016	10-MAR-2021	
26-20-09-350-801-02	RESTORATION ENGINE 2 FIRST- SHOOT, ENGINE 3 SECOND-SHOOT FIRE (14W2) EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) 860640 53774 REF: See Workcard	MOS HRS/MSC AFL	60				10-MAR-2016	10-MAR-2021	
26-20-09-350-801-03	RESTORATION ENGINE 3 FIRST- SHOOT, ENGINE 1 SECOND-SHOOT FIRE (14W3) EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) 860640 56146 REF: See Workcard	MOS HRS/MSC AFL	60				10-MAR-2016	10-MAR-2021	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-09-350-801-04	RESTORATION APU (73W) FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.090	30111102	MOS	60				02-MAR-2016	02-MAR-2021	
MANDATORY	31939A1 REF: See Workcard	HRS/MSC AFL							
+ 26-20-09-350-801-05	RESTORATION REAR COMPARTMENT (23W1) FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.210	30702102-1	MOS	60				02-MAR-2016	02-MAR-2021	
MANDATORY	28548D6 REF: See Workcard	HRS/MSC AFL							
+ 26-20-09-350-801-06	RESTORATION REAR/BAGGAGE COMPARTMENT (23W2) FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.180	30702102-1	MOS	60				02-MAR-2016	02-MAR-2021	
MANDATORY	29024D6 REF: See Workcard	HRS/MSC AFL							
26-20-09-900-801-01	ENGINE 1 FIRST- SHOOT, ENGINE 2 SECOND-SHOOT FIRE (14W1) EXTINGUISHER								
26.060	860640	MOS		TSN:314 TSO:24			15-APR-2018		
	54267	HRS/MSC	O/C	TSO:585.6			7651.3		
	REF: See Workcard	AFL		TSO:434			5046		
26-20-09-900-801-02	ENGINE 2 FIRST- SHOOT, ENGINE 3 SECOND-SHOOT FIRE (14W2) EXTINGUISHER								
26.070	860640	MOS		TSN:323 TSO:24			15-APR-2018		
	53774	HRS/MSC	O/C	TSO:585.6			7651.3		
	REF: See Workcard	AFL		TSO:434			5046		
26-20-09-900-801-03	ENGINE 3 FIRST- SHOOT, ENGINE 1 SECOND-SHOOT FIRE (14W3) EXTINGUISHER								
26.080	860640	MOS		TSN:256 TSO:24			15-APR-2018		
	56146	HRS/MSC	O/C	TSO:585.6			7651.3		
	REF: See Workcard	AFL		TSO:434			5046		
26-20-09-900-802-01	APU (73W) FIRE EXTINGUISHER								
26.090	30111102	MOS		TSN:259 TSO:24			15-APR-2018		
	31939A1	HRS/MSC	O/C	TSO:585.6			7651.3		
	REF: See Workcard	AFL		TSO:434			5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-09-900-803-01	REAR/BAGGAGE COMPARTMENT (23W2) FIRE EXTINGUISHER								
26.180	30702102-1 29024D6 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:258 TSO:25 TSO:585.6 TSO:434			15-APR-2018 7651.3 5046		
26-20-09-900-804-01	REAR COMPARTMENT (23W1) FIRE EXTINGUISHER								
26.210	30702102-1 28548D6 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:261 TSO:24 TSO:585.6 TSO:434			15-APR-2018 7651.3 5046		
+ 26-20-11-700-801-01 (s)	CHECKING APU EXTINGUISHING LINES FOR CLOGGING						PKG		
26.160	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
+ 26-20-11-700-801-02 (s)	CHECKING ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER DISCHARGE LINES FOR OBSTRUCTION						PKG		
26.100	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
+ 26-20-11-700-801-03 (s)	CHECKING ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER DISCHARGE LINES FOR OBSTRUCTION						PKG		
26.110	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
+ 26-20-11-700-801-04 (s)	CHECKING ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT EXTINGUISHING LINES FOR CLOGGING						PKG		
26.120	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
+ 26-20-11-700-801-05 (s)	CHECKING REAR/BAGGAGE COMPARTMENT FIRE EXTINGUISHING LINES FOR CLOGGING						PKG		
26.200	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-11-700-801-06 (s)	CHECKING REAR COMPARTMENT FIRE EXTINGUISHING LINES FOR CLOGGING						PKG		
26.230	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
+ 26-20-13-760-801-01	INSULATION TEST ENGINE 1 FIRST- SHOOT, ENGINE 2 SECOND-SHOOT FIRE (14W1) EXTINGUISHER ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT PERCUSSION CARTRIDGE SYSTEM								
26.060	860640 54267 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
+ 26-20-13-760-802-01	INSULATION TEST ENGINE 2 FIRST- SHOOT, ENGINE 3 SECOND-SHOOT FIRE (14W2) EXTINGUISHER ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE SYSTEM								
26.070	860640 53774 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
+ 26-20-13-760-803-01	INSULATION TEST ENGINE 3 FIRST- SHOOT, ENGINE 1 SECOND-SHOOT FIRE (14W3) EXTINGUISHER ENGINE 3 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE SYSTEM								
26.080	860640 56146 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
+ 26-20-13-760-804-01	INSULATION TEST APU (73W) FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM								
26.090	30111102 31939A1 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
+ 26-20-13-760-805-01	INSULATION TEST REAR/BAGGAGE COMPARTMENT (23W2) FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM								
26.180	30702102-1 29024D6 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-13-760-806-01	INSULATION TEST REAR COMPARTMENT (23W1) FIRE EXTINGUISHER PERCUSSION CARTRIDGE SYSTEM								
26.210	30702102-1 28548D6 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
26-20-13-900-802-01	ENGINE 1 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (L14W) CARTRIDGE								
	361385 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			04-APR-2016 7065.7 4612		
26-20-13-900-802-02	ENGINE 2 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (M14W) CARTRIDGE								
	361385 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			04-APR-2016 7065.7 4612		
26-20-13-900-802-03	ENGINE 3 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (R14W) CARTRIDGE								
	861375 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			04-APR-2016 7065.7 4612		
26-20-13-900-802-04	ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (L15W) CARTRIDGE								
	861385 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T				04-APR-2016 7065.7 4612		
26-20-13-900-802-05	ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (M15W) CARTRIDGE								
	361375 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			04-APR-2016 7065.7 4612		
26-20-13-900-802-06	ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (R15W) CARTRIDGE								
	861385 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			04-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-900-805-01	APU FIRE EXTINGUISHER PERCUSSION (28W) CARTRIDGE AE13083-5 LOT AEN 1-169 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			18-SEP-2013 6521.6 4194		
26-20-13-900-806-01	RH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (24W) CARTRIDGE AE13083-5 LOT AEN 1-169 REF: See Workcard	MOS HRS/MSC AFL	H/T				18-SEP-2013 6521.6 4194		
26-20-13-900-806-02	BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (23W) CARTRIDGE AE13083-5 LOT AEN 1-169 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			18-SEP-2013 6521.6 4194		
26-20-13-900-807-01	LH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (25W) CARTRIDGE AE13083-5 LOTAEN1-169 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			18-SEP-2013 6521.6 4194		
26-20-13-960-801-01 26.060 SCRAP	DISCARD ENGINE 1 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (L14W) CARTRIDGE (SERVICE LIFE) 361385 N/A REF: See Workcard	MOS HRS/MSC AFL	60				04-APR-2016	04-APR-2021	
26-20-13-960-801-01M 26.060 LIFE LIMIT	DISCARD ENGINE 1 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (L14W) CARTRIDGE (LIFE LIMIT) 361385 N/A REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84				01-FEB-2016	01-FEB-2023	
26-20-13-960-801-02 26.070 SCRAP	DISCARD ENGINE 2 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (M14W) CARTRIDGE (SERVICE LIFE) 361385 N/A REF: See Workcard	MOS HRS/MSC AFL	60				04-APR-2016	04-APR-2021	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-02M 26.070 LIFE LIMIT	DISCARD ENGINE 2 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (M14W) CARTRIDGE (LIFE LIMIT) 361385 N/A REF: See Workcard	MOS HRS/MSC AFL	84				01-FEB-2016	01-FEB-2023	
26-20-13-960-801-03 26.080 SCRAP	DISCARD ENGINE 3 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (R14W) CARTRIDGE (SERVICE LIFE) 861375 N/A REF: See Workcard	MOS HRS/MSC AFL	60				04-APR-2016	04-APR-2021	
26-20-13-960-801-03M 26.080 LIFE LIMIT	DISCARD ENGINE 3 FIRST-SHOOT FIRE EXTINGUISHER PERCUSSION (R14W) CARTRIDGE (LIFE LIMIT) 861375 N/A REF: See Workcard	MOS HRS/MSC AFL	84				01-FEB-2016	01-FEB-2023	
26-20-13-960-801-04 26.080 SCRAP	DISCARD ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (L15W) CARTRIDGE (SERVICE LIFE) 861385 N/A REF: See Workcard	MOS HRS/MSC AFL	60				04-APR-2016	04-APR-2021	
26-20-13-960-801-04M 26.080 LIFE LIMIT	DISCARD ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (L15W) CARTRIDGE (LIFE LIMIT) 861385 N/A REF: See Workcard	MOS HRS/MSC AFL	84				01-FEB-2016	01-FEB-2023	
26-20-13-960-801-05 26.060 SCRAP	DISCARD ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (M15W) CARTRIDGE (SERVICE LIFE) 361375 N/A REF: See Workcard	MOS HRS/MSC AFL	60				04-APR-2016	04-APR-2021	
26-20-13-960-801-05M 26.060 LIFE LIMIT	DISCARD ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (M15W) CARTRIDGE (LIFE LIMIT) 361375 N/A REF: See Workcard	MOS HRS/MSC AFL	84				01-FEB-2016	01-FEB-2023	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-06 26.070 SCRAP	DISCARD ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (R15W) CARTRIDGE (SERVICE LIFE) 861385 N/A REF: See Workcard	MOS HRS/MSC AFL	60				04-APR-2016	04-APR-2021	
26-20-13-960-801-06M 26.070 LIFE LIMIT	DISCARD ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER PERCUSSION (R15W) CARTRIDGE (LIFE LIMIT) 861385 N/A REF: See Workcard	MOS HRS/MSC AFL	84				01-FEB-2016	01-FEB-2023	
26-20-13-960-801-07 26.180 SCRAP	DISCARD BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (23W) CARTRIDGE (SERVICE LIFE) AE13083-5 LOT AEN 1-169 REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	72				18-SEP-2013	18-SEP-2019	
26-20-13-960-801-07M 26.180 LIFE LIMIT	DISCARD BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (23W) CARTRIDGE (LIFE LIMIT) AE13083-5 LOT AEN 1-169 REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	108				20-MAY-2013	20-MAY-2022	
26-20-13-960-801-08 26.180 SCRAP	DISCARD RH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (24W) CARTRIDGE (SERVICE LIFE) AE13083-5 LOT AEN 1-169 REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	72				18-SEP-2013	18-SEP-2019	
26-20-13-960-801-08M 26.180 LIFE LIMIT	DISCARD RH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (24W) CARTRIDGE (LIFE LIMIT) AE13083-5 LOT AEN 1-169 REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	108				20-MAY-2013	20-MAY-2022	
26-20-13-960-801-09 26.210 SCRAP	DISCARD LH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (25W) CARTRIDGE (SERVICE LIFE) AE13083-5 LOTAEN1-169 REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	72				18-SEP-2013	18-SEP-2019	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-09M 26.210 LIFE LIMIT	DISCARD LH REAR COMPARTMENT FIRE EXTINGUISHER PERCUSSION (25W) CARTRIDGE (LIFE LIMIT) AE13083-5 LOTAEN1-169 REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	108				20-MAY-2013	20-MAY-2022	
26-20-13-960-801-10 26.090 SCRAP	DISCARD APU FIRE EXTINGUISHER PERCUSSION (28W) CARTRIDGE (SERVICE LIFE) AE13083-5 LOT AEN 1-169 REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	72				18-SEP-2013	18-SEP-2019	
26-20-13-960-801-10M 26.090 LIFE LIMIT	DISCARD APU FIRE EXTINGUISHER PERCUSSION (28W) CARTRIDGE (LIFE LIMIT) AE13083-5 LOT AEN 1-169 REF: See Workcard	MOS HRS/MSC AFL	108				20-MAY-2013	20-MAY-2022	
+ 26-20-15-350-802-02	RESTORATION NO. 1 CABIN PORTABLE FIRE EXTINGUISHER (OVERHAUL) 898052 A-30840881 REF: See Workcard	MOS HRS/MSC AFL	O/C						
+ 26-20-15-350-802-03	RESTORATION NO. 2 CABIN PORTABLE FIRE EXTINGUISHER (OVERHAUL) 898052 A30840876 REF: See Workcard	MOS HRS/MSC AFL	O/C						
26-20-15-720-801-01	WEIGHING COCKPIT PORTABLE FIRE EXTINGUISHER 898052 A-30840877 REF: See Workcard	MOS HRS/MSC AFL	18				15-APR-2018	15-OCT-2019	
26-20-15-720-801-02	WEIGHING NO. 1 CABIN PORTABLE FIRE EXTINGUISHER 898052 A-30840881 REF: See Workcard	MOS HRS/MSC AFL	12				15-APR-2018	15-APR-2019	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-15-720-801-03	WEIGHING NO. 2 CABIN PORTABLE FIRE EXTINGUISHER 898052 A30840876 REF: See Workcard	MOS HRS/MSC AFL	12				15-APR-2018	15-APR-2019	
26-20-15-790-801-01	HYDROSTATIC TEST COCKPIT PORTABLE FIRE EXTINGUISHER 898052 A-30840877 REF: See Workcard	MOS HRS/MSC AFL	144				31-OCT-2014	31-OCT-2026	
26-20-15-790-801-02	HYDROSTATIC TEST NO. 1 CABIN PORTABLE FIRE EXTINGUISHER 898052 A-30840881 REF: See Workcard	MOS HRS/MSC AFL	144				30-OCT-2014	30-OCT-2026	
26-20-15-790-801-03	HYDROSTATIC TEST NO. 2 CABIN PORTABLE FIRE EXTINGUISHER 898052 A30840876 REF: See Workcard	MOS HRS/MSC AFL	144				09-JAN-2015	09-JAN-2027	
26-20-15-900-801-01	COCKPIT PORTABLE FIRE EXTINGUISHER 898052 A-30840877 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:39 TSN:832.2 TSN:631			15-APR-2018 7651.3 5046		
26-20-15-900-801-02	NO. 1 CABIN PORTABLE FIRE EXTINGUISHER 898052 A-30840881 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:39 TSN:832.2 TSN:631			15-APR-2018 7651.3 5046		
26-20-15-900-801-03	NO. 2 CABIN PORTABLE FIRE EXTINGUISHER 898052 A30840876 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:39 TSN:832.2 TSN:631			15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261155	LH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR 300119800270-3 77757 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
261160	RH MAIN LANDING GEAR (MLG) BAY FIRE DETECTOR 300119800270-3 77668 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
261165	APU FIRE DETECTOR 30011690040012 77731 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
261170	REAR COMPARTMENT FIRE DETECTOR 30015160027012 77843 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
261801	FIRE DETECTION PANEL 075-0361-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
262186	NO. 1 ENGINE DUAL CHECK VALVE 860655 2686 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
262196	NO. 2 ENGINE DUAL CHECK VALVE 860655 2687 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
262206	NO. 3 ENGINE DUAL CHECK VALVE									
26.260	860655 2688 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0			
262512	INSPECT/CHECK COCKPIT PORTABLE FIRE EXTINGUISHER									
	898052 A-30840877 REF:	MOS HRS/MSC AFL	72				16-OCT-2014	16-OCT-2020		
262532	INSPECT/CHECK NO. 1 CABIN PORTABLE FIRE EXTINGUISHER									
	898052 A-30840881 REF:	MOS HRS/MSC AFL	72				16-OCT-2014	16-OCT-2020		
262552	INSPECT/CHECK NO. 2 CABIN PORTABLE FIRE EXTINGUISHER									
	898052 A30840876 REF:	MOS HRS/MSC AFL	72				16-OCT-2014	16-OCT-2020		
CHAPTER 27 FLIGHT CONTROLS										
27-00-00-640-803-01 (s)	PRESSURE GREASING/LUBRICATION OF ROLL FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA						PKG			
27.050	PKG 32	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540			
	REF: See Workcard									
27-00-00-640-803-02 (s)	PRESSURE GREASING/LUBRICATION OF YAW FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA						PKG			
27.050	PKG 32	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540			
	REF: See Workcard									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-640-803-03 (s)	PRESSURE GREASING/LUBRICATION OF PITCH FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA PITCH						PKG		
27.050	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
27-00-00-640-804-01 (s)	PRESSURE GREASING/LUBRICATION OF ROLL FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.040	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
27-00-00-640-804-02 (s)	PRESSURE GREASING/LUBRICATION OF YAW FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.040	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
27-00-00-640-804-03 (s)	PRESSURE GREASING/LUBRICATION OF PITCH FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.040	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
27-00-00-640-806-01 (s)	VISUAL INSPECTION AND GREASING OF YAW AND PITCH CONTROL SEALED BOXES						PKG		
	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
27-00-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 HYDRAULIC SYSTEM FLIGHT CONTROLS						PKG		
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			29-MAY-2017 7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 HYDRAULIC SYSTEM FLIGHT CONTROLS PKG 21	MOS HRS/MSC AFL	1500	+30			PKG 29-MAY-2017 7416.5 4869		
	REF: See Workcard								
+ 27-00-00-710-802-01 (s)	OPERATIONAL TEST OF THE ROLL TRIM SYSTEMS PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27.200	REF: See Workcard								
+ 27-00-00-710-802-02 (s)	OPERATIONAL TEST OF THE YAW TRIM SYSTEMS PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27.200	REF: See Workcard								
27-00-00-720-803-01 (s)	FUNCTIONAL TEST OF LH ROLL AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
	REF: See Workcard								
27-00-00-720-803-02 (s)	FUNCTIONAL TEST OF RH ROLL AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
	REF: See Workcard								
+ 27-00-00-720-803-03 (s)	FUNCTIONAL TEST OF PITCH AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27.190	REF: See Workcard								
27-00-00-720-806-01	CHECK OF FLIGHT CONTROLS ARTIFICIAL FEEL LOADS-ROLL	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
	REF: See Workcard								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-720-806-02	CHECK OF FLIGHT CONTROLS ARTIFICIAL FEEL LOADS-RUDDER	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
27-00-00-720-806-03	CHECK OF FLIGHT CONTROLS ARTIFICIAL FEEL LOADS-ELEVATOR	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
27-00-00-900-806-01	HORIZONTAL STABILIZER AIRBRAKES-TRIM CONTROL BOX	MOS					04-APR-1998		
27.520	013015-18	HRS/MSC	O/C	TSN:15			149		
	1525	AFL		TSN:5			140		
	REF: See Workcard								
27-12-01-640-801-01 (s)	PRESSURE GREASING OF THE AILERON SERVO-ACTUATOR BEARINGS - LH AILERON SERVO-ACTUATOR (L950CC)	MOS	144	+2m			10-MAY-2010		
27.070	PKG 32	HRS/MSC					5668.9		
	REF: See Workcard	AFL					3540		
27-12-01-640-801-02 (s)	PRESSURE GREASING OF THE AILERON SERVO-ACTUATOR BEARINGS - RH AILERON SERVO-ACTUATOR (R950CC)	MOS	144	+2m			10-MAY-2010		
27.070	PKG 32	HRS/MSC					5668.9		
	REF: See Workcard	AFL					3540		
27-12-01-790-802-01 (s)	CHECK FOR INTERNAL LEAKS ON THE AILERON SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L950CC)	MOS	72	+2m			01-APR-2016		
27.070	PKG 31	HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		
27-12-01-790-802-02 (s)	CHECK FOR INTERNAL LEAKS ON THE AILERON SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R950CC)	MOS	72	+2m			01-APR-2016		
27.070	PKG 31	HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-12-01-900-801-01	LH AILERON SERVO-ACTUATOR								
27.070	103117-01 1023 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-12-01-900-801-02	RH AILERON SERVO-ACTUATOR								
27.070	103117-02 1026 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-13-01-640-806-01 (s)	LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.170	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-13-01-640-808-01 (s)	GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG		
	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
27-13-05-640-801-01 (s)	VISUAL INSPECTION AND GREASING OF ROLL CONTROL SEALED BOXES						PKG		
	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
+ 27-13-07-350-801-01	RESTORATION VARIABLE RATIO (AMEDEE) BELLCRANK (FUNCTIONAL TEST AND SERVICING)								
27.150	028008-28 2556 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	-234		10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022
+ 27-14-01-350-801-01	RESTORATION (NORMAL) NORMAL AILERON TRIM ACTUATOR (FUNCTIONAL TEST)								
27.100	021057-38 8511 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	-234		10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-14-03-350-801-01	RESTORATION AILERON EMERGENCY ACTUATOR (FUNCTIONAL TEST)								
27.140	021127-01 529 REF: See Workcard	MOS HRS/MSC AFL	144	+5m		-234	10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022
+ 27-14-03-720-802-01 (s)	FUNCTIONAL TEST OF THE ROLL EMERGENCY TRIM ACTUATOR - ROLL EMERGENCY TRIM ACTUATOR (103C)						PKG		
27.140	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			29-MAY-2017 7416.5 4869		
+ 27-14-05-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS						PKG		
27.110	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
27-15-00-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK MONITORING SYSTEM						PKG		
27.080	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000	+30			22-JAN-2013 6304.2 4016		
27-15-01-640-801-01 (s)	PRESSURE GREASING OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS - ROLL ARTHUR VARIABLE BELLCRANK (43C)						PKG		
27.080	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			22-JAN-2013 6304.2 4016		
+ 27-15-01-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK -ROLL ARTHUR VARIABLE BELLCRANK (43C)						PKG		
27.080	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-15-01-900-801-01	AILERON ARTHUR Q-UNIT								
27.080	106043-20 1817 REF: See Workcard	MOS HRS/MSC AFL	O/C				22-JAN-2013 6304.2 4016		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-15-05-350-801-01	RESTORATION AILERON ARTIFICIAL FEEL UNIT (INSPECTION, SERVICING AND FUNCTIONAL TEST) 105044-07 1131 REF: See Workcard	MOS HRS/MSC AFL	144	+5m		-234	10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022
27-15-05-900-801-01	AILERON ARTIFICIAL FEEL UNIT 105044-07 1131 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-15-07-640-801-01 (s)	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - LH ROLL AAFU (L960CC) PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540	PKG	
27-15-07-640-801-02 (s)	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - RH ROLL AAFU (R960CC) PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540	PKG	
27-22-01-350-801-01	RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST OF VALVES AND CHECK OF DAMPER) 103103-18 1028 REF: See Workcard	MOS HRS/MSC AFL	4000				26-OCT-2005 3926 2618	7926	
27-22-01-350-802-01	RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) 103103-18 1028 REF: See Workcard	MOS HRS/MSC AFL	O/C						
+ 27-22-01-350-802-01A	RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY 5-40) 103103-18 1028 MANDATORY 5-40 REF: See Workcard	MOS HRS/MSC AFL	10000				18-SEP-1997 0 0	10000	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-22-01-640-801-01 (s)	PRESSURE GREASING OF THE RUDDER SERVO-ACTUATOR BEARINGS - RUDDER SERVO-ACTUATOR (571CC)						PKG		
27.220	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
+ 27-22-01-790-802-01 (s)	CHECK FOR INTERNAL LEAKS ON THE RUDDER SERVO-ACTUATOR - RUDDER SERVO-ACTUATOR (571CC)						PKG		
27.220	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-22-01-900-801-01	RUDDER SERVO-ACTUATOR								
27.220	103103-18 1028 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		26-OCT-2005 3926 2618		
27-23-01-640-806-01 (s)	LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.300	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-23-01-640-807-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA.						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-23-01-640-808-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG		
27.290	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
+ 27-24-01-350-801-01	RESTORATION RUDDER TRIM ACTUATOR (FUNCTIONAL TEST)								
27.250	021057-36 8520 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	-234		10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-24-01-900-801-01	RUDDER TRIM ACTUATOR 021057-36 8520 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-24-01-900-801-02	RUDDER ARTIFICIAL FEEL UNIT 105043-07 1142 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-24-05-720-802-01 (s)	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAY (93C) PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 10-MAY-2010 5668.9 3540		
27-24-05-720-802-02 (s)	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAY (94C) PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 10-MAY-2010 5668.9 3540		
27-25-05-350-801-01	RESTORATION RUDDER ARTIFICIAL FEEL UNIT (INSPECTION, SERVICING AND FUNCTIONAL TEST) 105043-07 1142 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	-234		10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022
27-25-07-350-801-01	RESTORATION RUDDER AUXILIARY ARTIFICIAL FEEL UNIT (INSPECTION, SERVICING AND FUNCTIONAL TEST) 105070-04 1042 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	-234		10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022
27-25-07-900-801-01	RUDDER AUXILIARY ARTIFICIAL FEEL UNIT 105070-04 1042 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-31-01-640-801-01 (s)	GREASING OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (L8TB)						PKG		
27.060	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
27-31-01-640-801-02 (s)	GREASING OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (R8TB)						PKG		
27.060	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
27-31-01-900-801-01	PILOT CONTROL COLUMN								
27.060	VLP202-2 105 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-31-01-900-801-02	COPILOT CONTROL COLUMN								
27.060	VLC202-2 105 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 27-32-01-350-801-01	RESTORATION ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST)								
27.320	103062-36 3207 REF: See Workcard	MOS HRS/MSC AFL	10000				18-SEP-1997 0 0	10000	
27-32-01-350-801-01A	RESTORATION ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST)(MANDATORY 5-40)								
MANDATORY 5-40	103062-36 3207 REF: See Workcard	MOS HRS/MSC AFL	10000				18-SEP-1997 0 0	10000	
27-32-01-640-801-01 (s)	PRESSURE GREASING OF THE ELEVATOR SERVO-ACTUATOR BEARINGS - ELEVATOR SERVO-ACTUATOR (925CW)						PKG		
27.320	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-32-01-790-802-01 (s)	CHECK FOR INTERNAL LEAKS ON THE ELEVATOR SERVO-ACTUATOR - ELEVATOR SERVO-ACTUATOR (925CW)						PKG		
27.320	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-32-01-900-801-01	ELEVATOR SERVO-ACTUATOR								
27.320	103062-36 3207 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-32-03-350-801-01	RESTORATION PITCH GUST VALVE (FUNCTIONAL TEST)								
	104086-13 3843 REF: See Workcard	MOS HRS/MSC AFL	10000				18-SEP-1997 0 0	10000	
+ 27-32-03-350-801-01A	RESTORATION PITCH GUST VALVE (FUNCTIONAL TEST) (MANDATORY 5-40)								
27.960 MANDATORY 5-40	104086-13 3843 REF: See Workcard	MOS HRS/MSC AFL	10000				18-SEP-1997 0 0	10000	
27-33-01-640-806-01 (s)	LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.400	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-33-01-640-807-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-35-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM						PKG		
27.360	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000	+30			01-MAY-2013 6370 4067		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-35-01-640-801-01 (s)	PRESSURE GREASING OF THE PITCH ARTHUR VARIABLE BELLCRANK BEARINGS - PITCH ARTHUR VARIABLE BELLCRANK (42C)						PKG		
27.360	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			01-MAY-2013 6370 4067		
				TSI:142.37 TSI:97					
+ 27-35-01-720-801-01 (s)	FUNCTIONAL TEST OF THE PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (42C)						PKG		
27.360	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-35-01-900-801-01	ELEVATOR ARTHUR Q-UNIT								
27.360	106043-19 1365 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-MAY-2013 6370 4067		
				TSR:26 TSR:142.37 TSR:97					
27-35-05-350-801-01	RESTORATION PITCH MAIN ARTIFICIAL (AFU) FEEL UNIT (INSPECTION, SERVICING AND FUNCTIONAL TEST)								
	105034-07 1136 REF: See Workcard	MOS HRS/MSC AFL	144	+5m		-234	10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022
27-35-05-900-801-01	PITCH MAIN ARTIFICIAL (AFU) FEEL UNIT								
27.340	105034-07 1136 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
				TSN:0					
27-35-07-640-801-01 (s)	PRESSURE GREASING OF THE PITCH AUXILIARY AFU BEARINGS - PITCH AAFU (924CW)						PKG		
27.350	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			10-MAY-2010 5668.9 3540		
+ 27-40-00-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM						PKG		
27.460	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			29-MAY-2017 7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-01-210-802-01	VISUAL INSPECTION HORIZONTAL STABILIZER ELECTRIC ACTUATOR								
27.420	021121-08 539 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+3% +3%			11-APR-2016 7065.7 4612	11-APR-2022 8362	15-JUN-2022 8474.5
27-40-01-350-801-01	RESTORATION HORIZONTAL STABILIZER ELECTRIC ACTUATOR (FULL DISASSEMBLY, INSPECT/CHECK, AND NDT)								
27.420	021121-08 539 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+3% +3%			10-MAY-2010 5668.9 3540	10-MAY-2022 11040	19-SEP-2022 11265
27-40-01-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER ELECTRIC ACTUATOR HINGES AND JACK SCREW						PKG		
27.450	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			15-APR-2018 7651.3 5046		
27-40-01-720-801-01 (s)	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP NORMAL ELETRIC MOTOR						PKG		
27.470	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			29-MAY-2017 7416.5 4869		
27-40-01-720-801-02 (s)	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP EMERGENCY ELETRIC MOTOR						PKG		
27.470	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
27-40-01-900-801-01	HORIZONTAL STABILIZER ELECTRIC ACTUATOR								
27.420	021121-08 539 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSR:0 TSR:0 TSR:0	23-SEP-2003 2404 1853	
+ 27-40-03-100-801-01	CHECK / CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER ACTUATOR MOTORS - NORMAL ELECTRIC MOTOR (954CA)								
27.500	REF: See Workcard	MOS HRS/MSC AFL	N/A				29-OCT-1997 17 9		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-03-900-801-01	HORIZONTAL STABILIZER ACTUATOR NORMAL ELECTRIC MOTOR 0211212700	MOS					18-SEP-1997		
27.500	SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
27-40-05-900-801-01	HORIZONTAL STABILIZER POSITION PICK-OFF TRANSMITTER 016095-02	MOS					18-SEP-1997		
27.330	84 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
27-40-15-710-801-01 (s)	OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY PKG 32	MOS	144	+2m			PKG 18-SEP-1997		
	REF: See Workcard	HRS/MSC AFL					0 0		
+ 27-40-17-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX PKG 23	MOS					PKG 31-MAY-2017		
27.490	REF: See Workcard	HRS/MSC AFL	4500	+30			7416.5 4869		
+ 27-40-17-720-801-01A	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX (MANDATORY 5-40)	MOS					31-MAY-2017		
27.490 MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	5000				7416.5 4869	12416.5	
27-50-00-640-801-01 (s)	GREASING/LUBRICATION OF FLAP MECHANISMS PKG 16	MOS	24	+1m			PKG 15-APR-2018		
27.071	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
+ 27-50-00-720-801-01 (s)	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM PKG 21	MOS					PKG 31-MAY-2017		
27.620	REF: See Workcard	HRS/MSC AFL	1500	+30			7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50-00-720-802-01 (s)	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM						PKG		
27.630	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			15-APR-2018 7651.3 5046		
+ 27-50-00-720-804-01 (s)	MEASUREMENT OF LH WING OVERALL LINKAGE PLAY OF FLAP LINKAGE						PKG		
27.640	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
+ 27-50-00-720-804-02 (s)	MEASUREMENT OF RH WING OVERALL LINKAGE PLAY OF FLAP LINKAGE						PKG		
27.640	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
27-52-01-900-801-01	FLAP POWER DRIVE UNIT								
27.530	021138-06 459 REF: See Workcard	MOS HRS/MSC AFL	O/C			TSR:0 TSN:5797 TSR:0	22-FEB-2011 5797 3631		
+ 27-52-13-200-801-01 (s)	CHECK/GREASING OF LH WING FLAP CONTROL ROD SPLINES						PKG		
27.650	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
+ 27-52-13-200-801-02 (s)	CHECK/GREASING OF RH WING FLAP CONTROL ROD SPLINES						PKG		
27.650	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
27-52-13-900-804-01	FLAP ROTATING ROD								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-52-13-900-804-02	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-03	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-04	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-05	FLAP ROTATING ROD PN SN-UNKNOWN REF: AMM 27-52-13-900-804	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-06	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-07	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-08	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-52-13-900-804-09	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-10	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-11	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-12	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-52-13-900-804-13	FLAP ROTATING ROD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
27-53-01-220-801-01 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH OUTBOARD FLAP SCREW JACK (L502C) PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
27-53-01-220-801-02 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP LATERAL SCREW JACK (L501C) PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-220-801-03 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP CENTER SCREW JACK (L500C)						PKG		
	PKG 15	MOS	12	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
27-53-01-220-801-04 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP CENTER SCREW JACK (R500C)						PKG		
	PKG 15	MOS	12	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
27-53-01-220-801-05 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP LATERAL SCREW JACK (R501C)						PKG		
	PKG 15	MOS	12	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
27-53-01-220-801-06 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH OUTBOARD FLAP SCREW JACK (R502C)						PKG		
	PKG 15	MOS	12	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
27-53-01-350-801-01	RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL)								
	021137-21	MOS					18-SEP-1997		
27.560	2703	HRS/MSC	O/C		TSI:0		0		
	REF: See Workcard	AFL					0		
27-53-01-350-801-02	RESTORATION LH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL)								
	021137-19	MOS					18-SEP-1997		
27.540	2686	HRS/MSC	O/C		TSI:0		0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-350-801-03	RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL)								
27.540	021137-19 2685 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0			18-SEP-1997 0 0		
27-53-01-350-801-04	RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL)								
27.550	021137-19 2687 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			31-JUL-2011 5870.4 3679		
27-53-01-350-801-05	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL)								
27.550	021137-19 2688 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0			18-SEP-1997 0 0		
27-53-01-350-801-06	RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL)								
27.560	021137-20 2697 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0			18-SEP-1997 0 0		
27-53-01-640-802-01 (s)	GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502C)								
	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
27-53-01-640-802-02 (s)	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501C)								
	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
27-53-01-640-802-03 (s)	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500C)								
	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-640-802-04 (s)	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500C) PKG 15	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
	REF: See Workcard								
27-53-01-640-802-05 (s)	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501C) PKG 15	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
	REF: See Workcard								
27-53-01-640-802-06 (s)	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502C) PKG 15	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
	REF: See Workcard								
+ 27-53-01-720-804-01 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502C) PKG 21	MOS HRS/MSC AFL	1500	+30			PKG 02-JUN-2017 7416.5 4869		
27.560	REF: See Workcard								
+ 27-53-01-720-804-02 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501C) PKG 21	MOS HRS/MSC AFL	1500	+30			PKG 28-MAY-2017 7416.5 4869		
27.540	REF: See Workcard								
+ 27-53-01-720-804-03 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500C) PKG 21	MOS HRS/MSC AFL	1500	+30			PKG 28-MAY-2017 7416.5 4869		
27.540	REF: See Workcard								
+ 27-53-01-720-804-04 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500C) PKG 21	MOS HRS/MSC AFL	1500	+30			PKG 28-MAY-2017 7416.5 4869		
27.550	REF: See Workcard								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-53-01-720-804-05 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501C)						PKG		
27.550	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			28-MAY-2017 7416.5 4869		
+ 27-53-01-720-804-06 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502C)						PKG		
27.560	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			28-MAY-2017 7416.5 4869		
27-53-01-900-803-01	LH OUTBOARD FLAP SCREW JACK								
27.560	021137-21 2703 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-53-01-900-803-02	LH INBOARD FLAP LATERAL SCREW JACK								
27.540	021137-19 2686 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-53-01-900-803-03	LH INBOARD FLAP CENTER SCREW JACK								
27.540	021137-19 2685 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-53-01-900-803-04	RH INBOARD FLAP CENTER SCREW JACK								
27.550	021137-19 2687 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5870.4 TSR:0			31-JUL-2011 5870.4 3679		
27-53-01-900-803-05	RH INBOARD FLAP LATERAL SCREW JACK								
27.550	021137-19 2688 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-900-803-06	RH OUTBOARD FLAP SCREW JACK								
27.560	021137-20 2697 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 27-60-00-720-802-01 (s)	FUNCTIONAL TEST OF THE AIRBRAKE SYSTEM						PKG		
27.760	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			22-MAY-2017 7416.5 4869		
+ 27-60-00-720-802-01A	FUNCTIONAL TEST OF THE AIRBRAKE SYSTEM (MANDATORY 5-40)								
27.760 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	10000				22-MAY-2017 7416.5 4869	17416.5	
27-61-01-720-801-01 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD AIRBRAKE POSITION MICROWITCH						PKG		
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			22-MAY-2017 7416.5 4869		
27-61-01-720-801-02 (s)	FUNCTIONAL TEST OF THE LH CENTER AIRBRAKE POSITION MICROWITCH						PKG		
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			22-MAY-2017 7416.5 4869		
27-61-01-720-801-03 (s)	FUNCTIONAL TEST OF THE LH INBOARD AIRBRAKE POSITION MICROWITCH						PKG		
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			22-MAY-2017 7416.5 4869		
27-61-01-720-801-04 (s)	FUNCTIONAL TEST OF THE RH INBOARD AIRBRAKE POSITION MICROWITCH						PKG		
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			22-MAY-2017 7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-61-01-720-801-05 (s)	FUNCTIONAL TEST OF THE RH CENTER AIRBRAKE POSITION MICROWITCH PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 22-MAY-2017 7416.5 4869		
27-61-01-720-801-06 (s)	FUNCTIONAL TEST OF THE RH OUTBOARD AIRBRAKE POSITION MICROWITCH PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 23-MAY-2017 7416.5 4869		
27-62-01-640-801-01	GREASING OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L30C) REF: See Workcard	MOS HRS/MSC AFL	O/C				01-APR-2016 7065.7 4612		
27-62-01-640-801-02	GREASING OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L29C) REF: See Workcard	MOS HRS/MSC AFL	O/C				01-APR-2016 7065.7 4612		
27-62-01-640-801-03	GREASING OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L28C) REF: See Workcard	MOS HRS/MSC AFL	O/C				01-APR-2016 7065.7 4612		
27-62-01-640-801-04	GREASING OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R28C) REF: See Workcard	MOS HRS/MSC AFL	O/C				01-APR-2016 7065.7 4612		
27-62-01-640-801-05	GREASING OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R29C) REF: See Workcard	MOS HRS/MSC AFL	O/C				01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-62-01-640-801-06	GREASING OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R30C)	MOS						01-APR-2016	
	REF: See Workcard	HRS/MSC AFL	O/C				7065.7 4612		
27-62-01-900-801-01	LH OUTBOARD AIRBRAKE ACTUATOR	MOS						18-SEP-1997	
27.670	106091-07 4051 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
27-62-01-900-801-02	LH MIDDLE AIRBRAKE ACTUATOR	MOS						18-SEP-1997	
27.670	106091-08 4077 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
27-62-01-900-801-03	LH INBOARD AIRBRAKE ACTUATOR	MOS						18-SEP-1997	
27.670	106091-09 4111 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
27-62-01-900-801-04	RH INBOARD AIRBRAKE ACTUATOR	MOS						18-SEP-1997	
27.680	106091-09 4112 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
27-62-01-900-801-05	RH MIDDLE AIRBRAKE ACTUATOR	MOS						18-SEP-1997	
27.680	106091-08 4078 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
27-62-01-900-801-06	RH OUTBOARD AIRBRAKE ACTUATOR	MOS						18-SEP-1997	
27.680	106091-07 4020 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-80-00-710-806-01	OPERATIONAL TEST OF THE GROUND / FLIGHT RELAYS AND ANGLE-OF-ATTACK SENSOR CONTACTS								
27.950	REF: See Workcard	MOS HRS/MSC AFL	1000	+30			15-APR-2018 7651.3 5046	8651.3	8681.3
27-80-00-720-801-01 (s)	FUNCTIONAL TEST OF THE SLATS - NORMAL MODE						PKG		
	PKG 21	MOS HRS/MSC AFL	1500	+30			23-MAY-2017 7416.5 4869		
27-80-00-720-801-02 (s)	FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE						PKG		
	PKG 21	MOS HRS/MSC AFL	1500	+30			23-MAY-2017 7416.5 4869		
27-80-00-720-801-03 (s)	FUNCTIONAL TEST OF THE SLATS - EMERGENCY MODE						PKG		
	PKG 21	MOS HRS/MSC AFL	1500	+30			23-MAY-2017 7416.5 4869		
+ 27-80-01-350-802-01	RESTORATION SLAT SUPPLY DISTRIBUTOR (FUNCTIONAL TEST)								
27.810	108103-05 735 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	-234		10-MAY-2010 5668.9 3540	18-SEP-2021	18-FEB-2022
27-80-05-900-801-01	LH INBOARD SLAT ACTUATOR								
27.820	106132-05 1123 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
27-80-05-900-801-02	RH INBOARD SLAT ACTUATOR								
27.830	106132-05 1125 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-05-900-801-03	LH OUTBOARD SLAT INBOARD ACTUATOR 106132-06 3986 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-FEB-2007 4781 3071		
27-80-05-900-801-04	RH OUTBOARD SLAT INBOARD ACTUATOR 106132-08 1210 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-80-05-900-801-05	LH OUTBOARD SLAT EMERGENCY ACTUATOR 106132-07 1175 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-80-05-900-801-06	RH OUTBOARD SLAT EMERGENCY ACTUATOR 106132-07 1177 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-80-05-900-801-07	LH OUTBOARD SLAT OUTBOARD ACTUATOR 106132-08 4517 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-FEB-2007 4780 3071		
27-80-05-900-801-08	RH OUTBOARD SLAT OUTBOARD ACTUATOR 106132-06 1154 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
27-80-17-720-801-01 (s)	FUNCTIONAL TEST OF THE LH INBOARD SLAT RETRACTED MICROSWITCH PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-17-720-801-02 (s)	FUNCTIONAL TEST OF THE RH INBOARD SLAT RETRACTED MICROSWITCH PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27-80-17-720-801-03 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD SLAT RETRACTED MICROSWITCH PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27-80-17-720-801-04 (s)	FUNCTIONAL TEST OF THERLH OUTBOARD SLAT RETRACTED MICROSWITCH PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27-80-17-720-801-05 (s)	FUNCTIONAL TEST OF THE LH INBOARD SLAT EXTENDED MICROSWITCH PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27-80-17-720-801-06 (s)	FUNCTIONAL TEST OF THE RH INBOARD SLAT EXTENDED MICROSWITCH PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27-80-17-720-801-07 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD SLAT EXTENDED MICROSWITCH PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
27-80-17-720-801-08 (s)	FUNCTIONAL TEST OF THE RH OUTBOARD SLAT EXTENDED MICROSWITCH PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-31-640-801-01 (s)	SERVICING OF THE SLAT CONTROL CABLE - SLAT CONTROL CABLE (509D)						PKG		
27.920	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
270021	AILERON CONTROL PRESSURE SEAL BOX								
27.020	F50B271100 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
270041	RUDDER/ELEVATOR CONTROL PRESSURE SEAL BOX								
27.025	F50B270100 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
271160	ELEVATOR/AILERON ARTHUR Q-UNIT MONITORING-PRINTED CIRCUIT								
27.090	CI816D 61 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:124 TSN:0 TSN:0			03-FEB-2013 6319.2 4025		
271161	(NORMAL) NORMAL AILERON TRIM ACTUATOR								
27.100	021057-38 8511 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
271181	LH AILERON NEUTRAL RETURN UNIT								
27.130	105045-12 3916 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
271191	RH AILERON NEUTRAL RETURN UNIT								
27.130	105045-06 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271201	AILERON EMERGENCY ACTUATOR								
27.140	021127-01 529 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
271211	VARIABLE RATIO (AMEDEE) BELLCRANK								
27.150	028008-28 2556 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
272161	AILERON-RUDDER-ELEVATOR TRIM TRIPLE INDICATOR								
27.270	4863-559-80-10 229 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
273141	ELEVATOR NEUTRAL RETURN UNIT								
27.350	105045 3861 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
274186	HORIZONTAL STABILIZER ACTUATOR EMERGENCY ELECTRIC MOTOR								
27.510	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
275136	LH DOUBLE ANGLE GEARBOX								
27.570	021068-06 1968 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
275141	RH DOUBLE ANGLE GEARBOX								
27.570	021068-07 1973 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275146	LH FLAP SINGLE GEARBOX 021063-01	MOS					18-SEP-1997		
27.580	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
275151	RH FLAP SINGLE GEARBOX 021063-01	MOS					18-SEP-1997		
27.580	1962 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
275156	FLAP FLAP POSITION INDICATOR 021063-01	MOS					18-SEP-1997		
27.590	1961 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
275161	LH FLAP POSITION TRANSMITTER 1-4414-2	MOS					18-SEP-1997		
27.590	674 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
275166	RH FLAP POSITION TRANSMITTER 2-4415-2	MOS					18-SEP-1997		
27.590	476 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
276131	INBOARD/OUTBOARD AIRBRAKE ELECTRO- DISTRIBUTOR 65670-1	MOS					18-SEP-1997		
27.690	2182 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
276136	MIDDLE AIRBRAKE ELECTRO- DISTRIBUTOR 65670-1	MOS					18-SEP-1997		
27.690	2183 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276141	LH AIRBRAKE CHECK VALVE C24539000 H69 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276146	RH AIRBRAKE CHECK VALVE A24524 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276151	MIDDLE AIRBRAKE CIRCUIT PRESSURE RELIEF VALVE A24519 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276156	INBOARD/OUTBOARD AIRBRAKE CIRCUIT PRESSURE RELIEF VALVE A24519001 FM1149 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276161	CENTER AIRBRAKE ACTUATOR SUPPLY CHECK VALVE C24541000 U30 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276166	INBOARD/OUTBOARD AIRBRAKE ACTUATOR CIRCUIT NONRETURN VALVE A24515 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276171	LH INBOARD AIRBRAKE RESTRICTOR C24370-202 H497 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276176	RH INBOARD AIRBRAKE RESTRICTOR								
27.740	C24370-202 H498 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276181	LH MIDDLE AIRBRAKE RESTRICTOR								
27.730	C24370-302 H525 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276186	RH MIDDLE AIRBRAKE RESTRICTOR								
27.740	C24370-302 H526 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276191	LH OUTBOARD AIRBRAKE RESTRICTOR								
27.730	C24370-402 H555 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
276196	RH OUTBOARD AIRBRAKE RESTRICTOR								
27.740	C24370-402 H550 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278111	LH INTERMEDIATE BEARING								
27.780	021063-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278116	RH INTERMEDIATE BEARING								
27.780	021063-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278121	FLAP/SLAT FLAP/SLAT CONTROL BOX								
27.790	7016 1500 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278126	SLAT CONTROL DISTRIBUTOR								
27.800	108092-03 552 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278131	SLAT SUPPLY DISTRIBUTOR								
27.810	108103-05 735 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278136	SLAT STAND-BY DISTRIBUTOR								
27.800	65670-1 2181 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278181	LH SLATS EMERGENCY CIRCUIT ADJUSTABLE DIAPHRAGM								
27.850	JETX0504650AC MA335 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278186	RH SLATS EMERGENCY CIRCUIT ADJUSTABLE DIAPHRAGM								
27.850	JETX0504650AC MA334 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278191	SLAT SUPPLY CIRCUIT CHECK VALVE								
27.860	A24515 FM2358 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278196	OUTBOARD SLAT RETRACTION FLOW RESTRICTOR								
27.870	C24346-302 H135 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278201	LH INBOARD SLAT RETRACTION RESTRICTOR								
27.880	C24346-102 H109 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278206	RH INBOARD SLAT RETRACTION RESTRICTOR								
27.880	C24346-102 H108 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278211	LH NORMAL SLAT CIRCUIT ADJUSTABLE RESTRICTOR								
27.890	C24370-102 H0459 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278216	RH NORMAL SLAT CIRCUIT ADJUSTABLE RESTRICTOR								
27.890	C24370-102 H458 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278235	LEADING EDGE SELECTOR VALVE CONTROL CABLE								
27.920	F50B773001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
278286	PITCH GUST VALVE								
27.960	104086-13 3843 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278311	SLAT AIRSPEED SWITCH								
27.900	4219F010301 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57-41-13-640-801-01 (s)	LUBRICATION OF THE SLAT ROLLERS						PKG		
27.910	PKG 16 REF: AMM 27-80-00-640-801	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
CHAPTER 28 FUEL									
+ 28-00-00-280-801-01 (s)	PERFORM FUEL CONTAMINATION DETECTION TEST						PKG		
28.820	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			15-APR-2018 7651.3 5046		
28-00-00-910-803-01	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - FUEL INJECTION METHOD								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
28-00-00-910-803-02	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - GRAVITY POURING METHOD								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
28-00-00-910-803-03	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - FUEL INJECTION METHOD								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
28-00-00-910-803-04	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - GRAVITY POURING METHOD								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-910-803-06	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING / REPLACEMENT OF FILTERS	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
28-00-00-910-804-01	PERFORM MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
28-00-00-960-802-01	DISCARD LH FEEDER TANK SOLENOID/TRANSFER VALVE HOSE	MOS	144	+20%/-20%			10-MAY-2010	10-MAY-2022	04-OCT-2024
28.470	71029-380A	HRS/MSC			TSI:0		5668.9		
	69457	AFL			TSI:0		3540		
LIFE LIMIT	REF: See Workcard								
28-00-00-960-802-02	DISCARD CENTER FEEDER TANK SOLENOID/TRANSFER VALVE HOSE	MOS	144	+20%/-20%			10-MAY-2010	10-MAY-2022	04-OCT-2024
28.475	71029-420A	HRS/MSC			TSI:0		5668.9		
	72300	AFL			TSI:0		3540		
LIFE LIMIT	REF: AMM 28-00-00-960-802								
28-00-00-960-802-03	DISCARD RH FEEDER TANK SOLENOID/TRANSFER VALVE HOSE	MOS	144	+20%/-20%			10-MAY-2010	10-MAY-2022	04-OCT-2024
28.470	71029-380A	HRS/MSC			TSI:0		5668.9		
	73940	AFL			TSI:0		3540		
LIFE LIMIT	REF: See Workcard								
28-00-00-960-802-04	DISCARD LH FEEDER TANK REGULATION VALVE SUPPLY HOSE	MOS	144	+20%/-20%			10-MAY-2010	10-MAY-2022	04-OCT-2024
28.480	71029-1020A	HRS/MSC			TSI:0		5668.9		
	73662	AFL			TSI:0		3540		
LIFE LIMIT	REF: See Workcard								
28-00-00-960-802-05	DISCARD CENTER FEEDER TANK REGULATION VALVE SUPPLY HOSE	MOS	144	+20%/-20%			10-MAY-2010	10-MAY-2022	04-OCT-2024
28.485	71029-450A	HRS/MSC			TSI:0		5668.9		
	73016	AFL			TSI:0		3540		
LIFE LIMIT	REF: See Workcard								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-960-802-06	DISCARD RH FEEDER TANK REGULATION VALVE SUPPLY HOSE 71029-1020A 70989 REF: See Workcard	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.480 LIFE LIMIT				TSI:0 TSI:0					
28-00-00-960-802-07	DISCARD CENTER FEEDER TANK REGULATION/TRANSFER VALVE SPLY HOSE 71029-560A 72713 REF: See Workcard	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.490 LIFE LIMIT				TSI:0 TSI:0					
28-00-00-960-802-08	DISCARD LH FEEDER TANK HIGH LEVEL/SOLENOID VALVE HOSE 71028-610A 72232 REF: See Workcard	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.500 LIFE LIMIT				TSI:0 TSI:0					
28-00-00-960-802-09	DISCARD RH FEEDER TANK HIGH LEVEL/SOLENOID VALVE HOSE 71028-610A 73819 REF: See Workcard	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.500 LIFE LIMIT				TSI:0 TSI:0					
28-00-00-960-802-10	DISCARD LH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE 71028-1290A 72827 REF: See Workcard	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.510 LIFE LIMIT				TSI:0 TSI:0					
28-00-00-960-802-11	DISCARD CENTER FEEDER TANK LEVEL/VALVE SUPPLY HOSE 71028-2460A 72388 REF: See Workcard	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.515 LIFE LIMIT				TSI:0 TSI:0					
28-00-00-960-802-12	DISCARD RH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE 71028-1290A 72828 REF: See Workcard	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.510 LIFE LIMIT				TSI:0 TSI:0					

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-960-802-13	DISCARD LH FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE 71030-496A 69392 REF: AMM 28-00-00-960-802	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.520 LIFE LIMIT				TSl:0 TSl:0					
28-00-00-960-802-14	DISCARD CENTER FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE 71030-676A 73430 REF: AMM 28-00-00-960-802	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.525 LIFE LIMIT				TSl:0 TSl:0					
28-00-00-960-802-15	DISCARD RH FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE 71030-496A 69809 REF: See Workcard	MOS HRS/MSC AFL	144	+20%/-20%			10-MAY-2010 5668.9 3540	10-MAY-2022	04-OCT-2024
28.520 LIFE LIMIT				TSl:0 TSl:0					
28-20-00-710-802-01 (s)	OPERATIONAL TEST OF THE TRANSFER MANIFOLD TRANSFER VALVES (17Q1 AND 17Q2) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 23-MAY-2017 7416.5 4869		
28-20-00-710-802-02 (s)	OPERATIONAL TEST OF THE TRANSFER VALVES (13Q1 AND 13Q2) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 23-MAY-2017 7416.5 4869		
28-20-00-710-802-03 (s)	OPERATIONAL TEST OF THE ISOLATION VALVES (L17QD, M17QD, AND R17QD) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 23-MAY-2017 7416.5 4869		
28-21-01-350-801-01	RESTORATION NO. 1 BOOSTER PUMP (REPLACEMENT OF MOTOR BRUSHES) 226075-51 10037 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
28.600									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-01-350-801-02	RESTORATION NO. 2 BOOSTER PUMP (REPLACEMENT OF MOTOR BRUSHES)								
28.610	226075-51 10036 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
28-21-01-350-801-03	RESTORATION NO. 3 BOOSTER PUMP (REPLACEMENT OF MOTOR BRUSHES)								
28.620	226075-51 10038 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
28-21-01-350-802-01	RESTORATION NO. 1 BOOSTER PUMP (REPLACEMENT OF BEARINGS)								
28.600	226075-51 10037 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
28-21-01-350-802-02	RESTORATION NO. 2 BOOSTER PUMP (REPLACEMENT OF BEARINGS)								
28.610	226075-51 10036 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
28-21-01-350-802-03	RESTORATION NO. 3 BOOSTER PUMP (REPLACEMENT OF BEARINGS)								
28.620	226075-51 10038 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
28-21-01-900-801-01	NO. 1 BOOSTER PUMP								
28.600	226075-51 10037 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-21-01-900-801-02	NO. 2 BOOSTER PUMP								
28.610	226075-51 10036 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-01-900-801-03	NO. 3 BOOSTER PUMP 226075-51 10038 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 28-21-05-200-802-01	CHECK LH FEEDER TANK MANIFOLD LOW PRESSURE CROSSFEED DRAINING AND SHUT-OFF VALVE SEALS L88A19-208 20633 REF: See Workcard	MOS HRS/MSC AFL	10000	+3%	TSI:4130		24-FEB-2006 4130 2726	10000	10300
+ 28-21-05-200-802-02	CHECK RH FEEDER TANK MANIFOLD LOW PRESSURE CROSSFEED DRAINING AND SHUT-OFF VALVE SEALS L88A19-209 20635 REF: See Workcard	MOS HRS/MSC AFL	10000	+3%			18-SEP-1997 0 0	10000	10300
28-21-05-900-801-01	LH FEEDER TANK MANIFOLD L88A19-208 20633 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:4130 TSR:0			24-FEB-2006 4130 2726		
28-21-05-900-801-02	CENTER FEEDER TANK MANIFOLD L88A25-203 20287 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-21-05-900-801-03	RH FEEDER TANK MANIFOLD L88A19-209 20635 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-21-07-100-801-01 (s)	CLEANING OF THE JET PUMP FILTERS - LH JET PUMP FILTER (L40QD) PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-OCT-2016 7252.8 4752		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-07-100-801-02 (s)	CLEANING OF THE JET PUMP FILTERS - RH JET PUMP FILTER (R40QD)						PKG		
28.150	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-OCT-2016 7252.8 4752		
28-21-13-790-801-01	LEAK TEST LH FUEL FIRE SHUT-OFF VALVE								
28.570	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	1530/E/C		-6.4		25-JUN-2013 6435.4 4113	7959	
28-21-13-790-801-01A	LEAK TEST LH FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)								
28.570 MANDATORY 5-40	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	1530		-6.4		25-JUN-2013 6435.4 4113	7959	
28-21-13-790-801-02	LEAK TEST MIDDLE FUEL FIRE SHUT-OFF VALVE								
28.580	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	1530/E/C		-6.4		25-JUN-2013 6435.4 4113	7959	
28-21-13-790-801-02A	LEAK TEST MIDDLE FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)								
28.580 MANDATORY 5-40	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	1530		-6.4		25-JUN-2013 6435.4 4113	7959	
28-21-13-790-801-03	LEAK TEST RH FUEL FIRE SHUT-OFF VALVE								
28.590	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	1530/E/C		-6.4		25-JUN-2013 6435.4 4113	7959	
28-21-13-790-801-03A	LEAK TEST RH FUEL FIRE SHUT-OFF VALVE (MANDATORY 5-40)								
28.590 MANDATORY 5-40	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	1530		-6.4		25-JUN-2013 6435.4 4113	7959	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-21-14-720-801-01	FUNCTIONAL TEST LH FEEDER TANK MANIFOLD BP 1 THERMAL EXPANSION SYSTEMS L88A19-208 20633 REF: See Workcard	MOS HRS/MSC AFL	10000	+3%	TSI:4130		24-FEB-2006 4130 2726	10000	10300
+ 28-21-14-720-801-02	FUNCTIONAL TEST RH FEEDER TANK MANIFOLD BP 3 THERMAL EXPANSION SYSTEMS L88A19-209 20635 REF: See Workcard	MOS HRS/MSC AFL	10000	+3%			18-SEP-1997 0 0	10000	10300
28-21-16-610-801-01	SERVICING OF THE FUEL SHUT-OFF VALVE CONTROL CABLES AND CHECKING OF THE SHUT-OFF VALVES OPENING/CLOSING PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12 1000	+1m +30			15-APR-2018 7651.3 5046	15-APR-2019 8651.3	15-MAY-2019 8681.3
28-21-16-610-801-01A	SERVICING OF THE FUEL SHUT-OFF VALVE CONTROL CABLES AND CHECKING OF THE SHUT-OFF VALVES OPENING/CLOSING (MANDATORY 5-40) MANDATORY 5-40 REF: See Workcard	MOS HRS/MSC AFL	13 1000				15-APR-2018 7651.3 5046	15-MAY-2019 8651.3	
28-21-16-610-801-02 (s)	MEASUREMENT OF THE FUEL SHUT-OFF VALVE CONTROL CABLE SLIDING FORCES PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
28-21-16-900-801-01	LH SHUT-OFF VALVE FLEXIBLE CONTROL CABLE F50B795001A1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
28-21-16-900-801-02	CENTER SHUT-OFF VALVE FLEXIBLE CONTROL CABLE F50B795002A1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-16-900-801-03	RH SHUT-OFF VALVE FLEXIBLE CONTROL CABLE F50B795001A1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-21-33-900-801-01	NO. 1 ENGINE FUEL SUPPLY HOSE AE711064-10 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-21-33-900-801-02	NO. 2 ENGINE FUEL SUPPLY HOSE AE711064-12 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-21-33-900-801-03	NO. 3 ENGINE FUEL SUPPLY HOSE AE711064-19 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-21-33-900-803-01	APU FUEL SUPPLY HOSE 661-50EE10T00485 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-21-33-960-801-01	DISCARD APU FUEL SUPPLY HOSE 661-50EE10T00485 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSl:0			18-SEP-1997 0 0		
28-21-41-900-801-01	NO. 1 BP MANIFOLD TRANSFER VALVE ACTUATOR D97C00-215 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-41-900-801-02	NO. 3 BP MANIFOLD TRANSFER VALVE ACTUATOR D97C00-215 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-22-05-350-801-01	RESTORATION LH TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) 2060A-12 3128 REF: See Workcard	MOS HRS/MSC AFL	2000	+3%			30-MAY-2017 7416.5 4869	9416.5	9476.5
28-22-05-350-801-02	RESTORATION CENTER TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) 2060A-12 3082 REF: See Workcard	MOS HRS/MSC AFL	2000	+3%			30-MAY-2017 7416.5 4869	9416.5	9476.5
28-22-05-350-801-03	RESTORATION RH TRANSFER PUMP (REPLACEMENT OF MOTOR BRUSHES) 2060-A01 2188 REF: See Workcard	MOS HRS/MSC AFL	2000	+3%			27-SEP-2018 7790.4 5152	9790.4	9850.4
28-22-05-350-802-01	RESTORATION LH TRANSFER PUMP (REPLACEMENT OF BEARINGS) 2060A-12 3128 REF: See Workcard	MOS HRS/MSC AFL	2000	+3%			30-MAY-2017 7416.5 4869	9416.5	9476.5
28-22-05-350-802-02	RESTORATION CENTER TRANSFER PUMP (REPLACEMENT OF BEARINGS) 2060A-12 3082 REF: See Workcard	MOS HRS/MSC AFL	2000	+3%			30-MAY-2017 7416.5 4869	9416.5	9476.5
28-22-05-350-802-03	RESTORATION RH TRANSFER PUMP (REPLACEMENT OF BEARINGS) 2060-A01 2188 REF: See Workcard	MOS HRS/MSC AFL	2000	+3%			27-SEP-2018 7790.4 5152	9790.4	9850.4

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-22-05-900-801-01	LH TRANSFER PUMP								
28.270	2060A-12 3128 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-MAY-2017 7416.5 4869		
28-22-05-900-801-02	CENTER TRANSFER PUMP								
28.280	2060A-12 3082 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-MAY-2017 7416.5 4869		
28-22-05-900-801-03	RH TRANSFER PUMP								
28.290	2060-A01 2188 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			27-SEP-2018 7790.4 5152		
+ 28-22-13-220-801-01 (s)	INSPECTION FOR CORROSION OF THE TRANSFER VALVE BASES AND LINES FITTED WITH DRAINAGE SLEEVES								
28.330	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
28-22-15-350-801-01	RESTORATION LH FEEDER TANK TRANSFER VALVE (OVERHAUL)								
28.240 OVERHAUL	2504-3 1899 REF: See Workcard	MOS HRS/MSC AFL	108 4800	+3% +3%			15-MAY-2015 6883.5 4459	15-MAY-2024 11683.5	22-AUG-2024 11827.5
28-22-15-350-801-02	RESTORATION CENTER FEEDER TANK TRANSFER VALVE (OVERHAUL)								
28.240 OVERHAUL	2504-3 149 REF: See Workcard	MOS HRS/MSC AFL	108 4800	+3% +3%			14-MAY-2015 6883.5 4459	14-MAY-2024 11683.5	21-AUG-2024 11827.5
28-22-15-350-801-03	RESTORATION RH FEEDER TANK TRANSFER VALVE (OVERHAUL)								
28.240 OVERHAUL	2504-3 1170 REF: See Workcard	MOS HRS/MSC AFL	108 4800	+3% +3%			15-MAY-2015 6883.5 4459	15-MAY-2024 11683.5	22-AUG-2024 11827.5



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-22-15-900-801-01	LH FEEDER TANK TRANSFER VALVE								
28.240	2504-3 1899 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			15-MAY-2015 6883.5 4459		
28-22-15-900-801-02	CENTER FEEDER TANK TRANSFER VALVE								
28.240	2504-3 149 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			14-MAY-2015 6883.5 4459		
28-22-15-900-801-03	RH FEEDER TANK TRANSFER VALVE								
28.240	2504-3 1170 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			15-MAY-2015 6883.5 4459		
28-22-17-900-801-01	CENTER TANK LOW LEVEL FLOAT VALVE								
28.355	C21KL0014 2126 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-22-21-900-801-01	LH ISOLATING VALVE								
28.160	B97M31-201 20451 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-22-21-900-801-02	MIDDLE ISOLATING VALVE								
28.160	B97M31-201 20452 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-22-21-900-801-03	RH ISOLATING VALVE								
28.160	B97M31-201 20453 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-22-29-900-801-01	LEFT TRANSFER INTERCONNECTION VALVE ACTUATOR D97C00-202 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-22-29-900-801-02	RIGHT TRANSFER INTERCONNECTION VALVE ACTUATOR D97C00-202 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-22-31-900-801-01	LH TANK LEVEL SOLENOID VALVE C41BP0043 1139 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-22-31-900-801-02	MIDDLE TANK LEVEL SOLENOID VALVE C41BP0043 1109 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-JUN-2012 6097.1 3850		
28-22-31-900-801-03	RH TANK LEVEL SOLENOID VALVE C41BP0043 1136 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-30-00-680-802-01	DRAIN FUEL TANKS-LH TANK GROUP REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
28-30-00-680-802-02	DRAIN FUEL TANKS-CENTER TANK GROUP REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-30-00-680-802-03	DRAIN FUEL TANKS-RH TANK GROUP	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC AFL	O/C				0 0		
28-30-00-680-802-05	LEAK CHECK OF THE DRY BAY	MOS					05-AUG-2014		
	REF: See Workcard	HRS/MSC AFL	N/A				6721.3 4339		
28-30-00-680-802-06	PERFORM FUEL SAMPLING	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC AFL	O/C				0 0		
28-30-00-680-804-01	DRAINING WATER FROM THE FUEL TANKS	MOS	2				27-SEP-2018	27-NOV-2018	
	REF: See Workcard	HRS/MSC AFL					7790.4 5152		
28-30-11-960-802-01	DISCARD OF THE FUEL DRAIN CAPS	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC AFL	O/C				0 0		
+ 28-41-00-720-802-01 (s)	FUNCTIONAL TEST OF THE FEEDER TANK LOW LEVEL INDICATING SYSTEM						PKG		
28.810	PKG 15	MOS	12	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
28-41-05-900-801-01	LH FEEDER TANK QUANTITY GAUGE								
28.740	792-794-3	MOS				TSR:0	22-NOV-2005		
	1205	HRS/MSC	O/C			TSR:0	3966		
	REF: See Workcard	AFL				TSR:0	2641		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-05-900-801-02	RH FEEDER TANK QUANTITY GAUGE 792-794-3 820 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-41-05-900-801-03	CENTER WING FORWARD QUANTITY GAUGE 792-370-1 418 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-41-05-900-801-04	CENTER WING REAR QUANTITY GAUGE 792-371-1 413 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-41-05-900-801-05	CENTER FEEDER TANK QUANTITY GAUGE 792-795-2 488 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-41-09-900-801-01	LH WING INBOARD QUANTITY GAUGE 792-366-1 1057 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-41-09-900-801-02	RH WING INBOARD QUANTITY GAUGE 792-366-1 1058 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-41-09-900-801-03	LH WING CENTER QUANTITY GAUGE 792-367-2 1120 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-09-900-801-04	RH WING CENTER QUANTITY GAUGE								
28.720	792-367-2 1121 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-41-09-900-801-05	LH WING OUTBOARD QUANTITY GAUGE								
28.710	792-368-2 1137 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-41-09-900-801-06	RH WING OUTBOARD QUANTITY GAUGE								
28.720	792-368-2 1136 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-43-01-720-801-01 (s)	FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR								
28.840	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
28-43-05-900-801-01	FUEL TEMPERATURE INDICATOR								
28.800	162LC617 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 28-50-00-700-801-02 (s)	PERFORM INTEGRITY AND LEAK CHECK OF REFUELING CONNECTOR SEALING VALVE AND LEAK CHECK OF ISOLATION CHECK VALVES								
28.465	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 10-MAY-2010 5668.9 3540		
28-50-27-900-801-01	FUEL TEST VALVE PROXIMITY SENSOR								
28.790	8-240-02 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-70-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PRESSURIZATION SYSTEM						PKG		
28.450	PKG 24 REF: See Workcard	MOS HRS/MSC AFL	6000	+30			25-JUL-2011 5870.4 3679		
28-70-09-350-801-01	RESTORATION LH VALVE BOX (OVERHAUL)								
28.440	2415-1010 979 REF: See Workcard	MOS HRS/MSC AFL	72 1600	+3% +3%			07-DEC-2015 7015 4577	07-DEC-2021 8615	11-FEB-2022 8663
OVERHAUL									
28-70-09-350-801-02	RESTORATION RH VALVE BOX (OVERHAUL)								
28.440	2415-1010 1648 REF: See Workcard	MOS HRS/MSC AFL	72 1600	+3% +3%			07-DEC-2015 7015 4577	07-DEC-2021 8615	11-FEB-2022 8663
OVERHAUL									
+ 28-70-13-350-801-01	RESTORATION LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST)								
	B06GA1050 1215 REF: See Workcard	MOS HRS/MSC AFL	O/C				(EBT)		
+ 28-70-13-350-801-02	RESTORATION RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST)								
	B06GA1050 1136 REF: See Workcard	MOS HRS/MSC AFL	O/C				(EBT)		
28-70-13-720-802-01	FUNCTIONAL TEST LH WING TANK NEGATIVE PRESSURE RELIEF VALVE								
	B06GA1050 1215 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			14-JUL-2006 4400 2874	9400	9550
28-70-13-720-802-02	FUNCTIONAL TEST RH WING TANK NEGATIVE PRESSURE RELIEF VALVE								
	B06GA1050 1136 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			14-JUL-2006 4400 2874	9400	9550

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-13-900-801-01	LH WING TANK NEGATIVE PRESSURE RELIEF VALVE B06GA1050 1215 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:4400 TSR:0			14-JUL-2006 4400 2874		
28-70-13-900-801-02	RH WING TANK NEGATIVE PRESSURE RELIEF VALVE B06GA1050 1136 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:4400 TSR:0			14-JUL-2006 4400 2874		
28-70-17-130-801-01 (s)	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 1 PRESSURIZATION AIR FILTER (L206QP) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 25-MAY-2017 7416.5 4869		
28-70-17-130-801-02 (s)	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 2 PRESSURIZATION AIR FILTER (R206QP) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 25-MAY-2017 7416.5 4869		
28-70-21-900-801-01	LH WING AIR VENT VALVE B97L38-251 20129 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-70-21-900-801-02	RH WING AIR VENT VALVE B97L38-252 20155 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 28-70-41-710-801-01 (s)	OPERATIONAL TEST OF THE FEEDER TANK PRESSURE RELIEF VALVES - LH FEEDER TANK PRESSURE RELIEF VALVE (L300QP) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 23-MAY-2017 7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-70-41-710-801-02 (s)	OPERATIONAL TEST OF THE FEEDER TANK PRESSURE RELIEF VALVES - RH FEEDER TANK PRESSURE RELIEF VALVE (R300QP)						PKG		
28.410	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			23-MAY-2017 7416.5 4869		
28-70-41-900-801-01	LH FEEDER TANK PRESSURE RELIEF VALVE								
28.410	1551-1000 2263 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
28-70-41-900-801-02	RH FEEDER TANK PRESSURERELIEF VALVE								
28.410	1551-1000 2261 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
280111	LH WING DRAIN VALVE								
28.020	142D12-11 B91162 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-APR-2007 4899 3115		
280116	RH WING DRAIN VALVE								
28.020	142D12-11 1629 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
280121	FORWARD CENTER WING DRAIN VALVE								
28.030	142G12-43 A58542 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-DEC-2002 1863 1540		
280126	MIDDLE CENTER WING DRAIN VALVE								
28.030	142G12-43 1981 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280131	REAR CENTER WING DRAIN VALVE								
28.030	142G12-43 A52470 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-DEC-2002 1863 1540		
280136	LH FEEDER TANK DRAIN VALVE								
28.040	142G12-43 1963 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
280141	CENTER FEEDER TANK DRAIN VALVE								
28.040	142G12-43 1772 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			20-JUL-1998 266 263		
280146	RH FEEDER TANK DRAIN VALVE								
28.040	142G12-43 2087 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
280156	LH DOOR FEEDER TANK DRAIN VALVE								
28.045	142G12-43 2085 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
280161	RH DOOR FEEDER TANK DRAIN VALVE								
28.045	142G12-43 2086 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281101	LH FILLER PLUG								
28.060	431-1251 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281103	CENTER TRANSFER PUMP PRIMING CHECK VALVE								
28.110	L85Z13-201 21111 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281106	RH FILLER PLUG								
28.060	431-1251 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281108	RH TEST SYSTEM CHECK VALVE								
28.120	L85Z13-201 21088 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281111	LH STRAINER								
28.100	431-51-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281113	NO. 1 SYSTEM CENTER FEEDER TANK TEST CHECK VALVE								
28.130	L85Z13-201 21110 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281116	RIGHT STRAINER								
28.100	431-51-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281118	NO. 2 SYSTEM CENTER FEEDER TANK TEST CHECK VALVE								
28.130	L85Z13-201 21118 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281121	LH JET PUMP BOOSTER SYSTEM CHECK VALVE L96Z19-203	MOS					18-SEP-1997		
28.140	20564 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281126	RH JET PUMP BOOSTER SYSTEM CHECK VALVE L96Z19-203	MOS					18-SEP-1997		
28.140	20573 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281131	LH TRANSFER JET PUMP FILTER 30819-1	MOS					18-SEP-1997		
28.150	1509 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281141	RH TRANSFER JET PUMP FILTER 30819-1	MOS					18-SEP-1997		
28.150	1508 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281166	PRESSURE REFUELING UNIT K97-63-206	MOS					18-SEP-1997		
28.080	20547 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281176	NO. 1 FILLER VALVE L94Z31-201	MOS					18-SEP-1997		
28.070	21640 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281181	NO. 2 FILLER VALVE L94Z31-201	MOS					18-SEP-1997		
28.070	21641 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281186	NO. 3 FILLER VALVE L94Z31-201 21639 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281191	LH TRANSFER PUMP CHECK VALVE L96Z31-201 21876 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281196	MIDDLE TRANSFER PUMP CHECK VALVE L96Z31-201 21877 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281201	RH TRANSFER PUMP CHECK VALVE L96Z31-201 21875 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281206	FILLING CIRCUIT TRANSFER CHECK VALVE L96Z31-201 21878 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281211	FILLER BLOCK K99Z31-001 20273 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281216	FEEDER TANK AIR VENT VALVE B97J38-251 20153 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281221	LH CENTER SECTION AIR VENT DRAINING BALL VALVE L87D06-001	MOS					18-SEP-1997		
28.200	20572 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281226	RH CENTER SECTION AIR VENT DRAINING BALL VALVE L87D06-001	MOS					18-SEP-1997		
28.200	20571 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281241	LH WING FUELLING FLOAT SWITCH 005-906-001	MOS					18-SEP-1997		
28.210	1623 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281246	RH WING FUELLING FLOAT SWITCH 005-906-001	MOS					18-SEP-1997		
28.220	1626 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281251	LH CENTER SECTION OVERFULL FLOAT SWITCH 005-906-001	MOS					18-SEP-1997		
28.210	1573 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281256	RH CENTER SECTION OVERFULL FLOAT SWITCH 005-906-001	MOS					18-SEP-1997		
28.220	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281261	FEEDER TANK OVERFULL FLOAT SWITCH 005-906-001	MOS					18-SEP-1997		
28.230	1587 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281266	LH CENTER SECTION FUELLING FLOAT SWITCH								
28.210	005-909-001 1364 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281271	RH CENTER SECTION FUELLING FLOAT SWITCH								
28.220	005-909-001 1368 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281273	LATERAL TANK LOADING PRINTED CARD								
28.250	C1822A 311 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281275	CENTER TANK LOADING PRINTED CARD								
28.250	C1845A 324 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281276	TRANSFER UNIT								
28.260	L88A31-207 20294 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281353	TRANSFER MANIFOLD REFUELING VALVE								
28.300	B97-31-251 20127 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281355	(22Q3) NO. 3 TRANSFER PUMP SWITCH								
	810UN01S1BA0A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-MAR-2003 1999 1616		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281406	LH TANK HIGH LEVEL FLOAT VALVE C21KL0014 2144 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281411	LH TANK LOW LEVEL FLOAT VALVE C21KL0014 2133 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281416	MIDDLE TANK HIGH LEVEL FLOAT VALVE C21KL0014 2135 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281426	RH TANK HIGH LEVEL FLOAT VALVE C21KL0014 2141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281431	RH TANK LOW LEVEL FLOAT VALVE C21KL0014 2132 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281436	LH FEEDER TANK TRANSFER JET-PUMP C17AS0051 270 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281441	RH FEEDER TANK TRANSFER JET-PUMP C17AS0061 270 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281466	WING TANK PRESSURIZATION REAR NON RETURN VALVE L96Z19-003	MOS					18-SEP-1997		
28.380	22059 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281471	FEEDER TANK PRESSURIZATION FORWARD NON RETURN VALVE L96Z19-003	MOS					18-SEP-1997		
28.380	22058 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281476	WING TANK REAR PRESSURE REDUCER VALVE B14DE2041	MOS					18-SEP-1997		
28.390	488 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281481	FEEDER TANK FORWARD PRESSURE REDUCER VALVE B14DE2031	MOS					18-SEP-1997		
28.390	494 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281486	TANK PRESSURIZATION AUTOMATIC DRAIN P177-526	MOS					18-SEP-1997		
28.400	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281491	WING TANK PRESSURIZATION AUTOMATIC DRAIN P177-526	MOS					18-SEP-1997		
28.400	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281526	LH FEEDER TANK VACUUM PRESSURE RELIEF VALVE B42LA1040	MOS					18-SEP-1997		
28.430	699 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281531	RH FEEDER TANK VACUUM PRESSURE RELIEF VALVE								
28.430	B42LA1040 698 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
281536	LH VALVE BOX								
28.440	2415-1010 979 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			07-DEC-2015 7015 4577		
281541	RH VALVE BOX								
28.440	2415-1010 1648 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			07-DEC-2015 7015 4577		
281601	LH FEEDER TANK SOLENOID/TRANSFER VALVE HOSE								
28.470	71029-380A 69457 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0	-234		10-MAY-2010 5668.9 3540		
281606	CENTER FEEDER TANK SOLENOID/TRANSFER VALVE HOSE								
28.475	71029-420A 72300 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0	-234		10-MAY-2010 5668.9 3540		
281611	RH FEEDER TANK SOLENOID/TRANSFER VALVE HOSE								
28.470	71029-380A 73940 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0	-234		10-MAY-2010 5668.9 3540		
281616	LH FEEDER TANK REGULATION VALVE SUPPLY HOSE								
28.480	71029-1020A 73662 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0	-234		10-MAY-2010 5668.9 3540		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281621	CENTER FEEDER TANK REGULATION/TRANSFER VALVE SPLY HOSE								
28.490	71029-560A 72713 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0		-234	10-MAY-2010 5668.9 3540		
281626	CENTER FEEDER TANK REGULATION VALVE SUPPLY HOSE								
28.485	71029-450A 73016 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0		-234	10-MAY-2010 5668.9 3540		
281631	RH FEEDER TANK REGULATION VALVE SUPPLY HOSE								
28.480	71029-1020A 70989 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0		-234	10-MAY-2010 5668.9 3540		
281636	LH FEEDER TANK HIGH LEVEL/SOLENOID VALVE HOSE								
28.500	71028-610A 72232 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0		-234	10-MAY-2010 5668.9 3540		
281641	RH FEEDER TANK HIGH LEVEL/SOLENOID VALVE HOSE								
28.500	71028-610A 73819 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0		-234	10-MAY-2010 5668.9 3540		
281646	LH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE								
28.510	71028-1290A 72827 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0		-234	10-MAY-2010 5668.9 3540		
281651	CENTER FEEDER TANK LEVEL/VALVE SUPPLY HOSE								
28.515	71028-2460A 72388 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0		-234	10-MAY-2010 5668.9 3540		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281656	RH FEEDER TANK HIGH LEVEL/VALVE SUPPLY HOSE								
28.510	71028-1290A 72828 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0	-234		10-MAY-2010 5668.9 3540		
282011	ENGINE 1 SHUT-OFF VALVE INTEGRATED IN BP 1 MANIFOLD (L14Q)								
28.570	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
282031	ENGINE 2 SHUT-OFF VALVE INTEGRATED IN BP 2 MANIFOLD (M14QD)								
28.580	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
282051	ENGINE 3 SHUT-OFF VALVE INTEGRATED IN BP 3 MANIFOLD (R14QD)								
28.590	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
282191	LH LOW PRESSURE PUMP BELL HOUSING								
28.630	2061J 928 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
282201	CENTRAL LOW PRESSURE PUMP BELL HOUSING								
28.630	2061J 927 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
282211	RH LOW PRESSURE PUMP BELL HOUSING								
28.630	2061J 926 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282221	NO. 1 FIRE SHUT-OFF HANDLE 4161174	MOS					18-SEP-1997		
28.640	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
282226	NO. 2 FIRE SHUT-OFF HANDLE 4161181	MOS					18-SEP-1997		
28.640	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
282231	NO. 3 FIRE SHUT-OFF HANDLE 4161197	MOS					18-SEP-1997		
28.640	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
282311	NO. 1 ENGINE PRESSURIZATION AIR FILTER CG0080503448N00	MOS					25-JUL-2011		
28.680	NA REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			5870.4 3679		
282321	NO. 2 ENGINE PRESSURIZATION AIR FILTER CG0080503448N00	MOS					25-JUL-2011		
28.680	NA REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:65 TSR:0 TSN:1740.4 TSR:0 TSN:953 TSR:0			5870.4 3679		
282601	LH FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE 71030-496A	MOS					10-MAY-2010		
28.520	69392 REF: See Workcard	HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0	-234		5668.9 3540		
282606	CENTER FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE 71030-676A	MOS					10-MAY-2010		
28.525	73430 REF: See Workcard	HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0	-234		5668.9 3540		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282611	RH FEEDER TANK CK VALVE/HI-LEVEL VALVE RETURN HOSE								
28.520	71030-496A 69809 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0	-234		10-MAY-2010 5668.9 3540		
284101	LH LOW TRANSFER PRESSURE SWITCH								
28.690	16344-1 1761 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2015 7015 4577		
284106	CENTER LOW TRANSFER PRESSURE SWITCH								
28.690	1G344-1 552 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
284111	RH LOW TRANSFER PRESSURE SWITCH								
28.690	1G344-1 1014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-APR-2005 3522 2428		
284116	LH LOW PRESSURE SWITCH								
28.700	8G1256 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
284121	CENTER LOW PRESSURE SWITCH								
28.700	8G1256 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
284126	RH LOW PRESSURE SWITCH								
28.700	8G1256 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284196	LH QUANTITY INDICATOR SYSTEM AMPLIFIER								
28.760	706-719-1 775 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
284201	CENTER QUANTITY INDICATOR SYSTEM AMPLIFIER								
28.760	706-719-1 774 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
284206	RH QUANTITY INDICATOR SYSTEM AMPLIFIER								
28.760	706-720-1 453 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-DEC-1997 28 14		
284211	FUEL TANK LOW LEVEL PRINTED CIRCUIT CARD								
28.770	CI815A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
284221	FUEL TEST VALVE								
28.780	B97M13-201 22179 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
284231	FUEL TEMPERATURE PROBE								
28.850	1122506 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
CHAPTER 29	HYDRAULIC POWER								
29-00-00-610-802-01	REPLACEMENT OF HYDRAULIC FLUID FOLLOWING FAILURE OF HYDRAULIC POWER SYSTEM COMPONENT								
		MOS HRS/MSC AFL	A/R				18-SEP-1997 0 0		
	REF: See Workcard								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE NO. 1 MAIN HYDRAULIC SYSTEMS PKG 24 REF: See Workcard	MOS HRS/MSC AFL	6000	+30			PKG 25-JUL-2011 5870.4 3679		
29-10-00-720-801-02 (s)	FUNCTIONAL TEST OF THE NO. 2 MAIN HYDRAULIC SYSTEMS PKG 24 REF: See Workcard	MOS HRS/MSC AFL	6000	+30			PKG 25-JUL-2011 5870.4 3679		
29-11-01-350-801-01 29.030 OVERHAUL	RESTORATION NO. 1 HYDRAULIC PUMP (OVERHAUL) 314470 MX381333H REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			05-AUG-2017 7451.3 4900	11451.3	11571.3
29-11-01-350-801-02 29.040 OVERHAUL	RESTORATION NO. 2 HYDRAULIC PUMP (OVERHAUL) 314470 MX-570050H REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			05-AUG-2017 7451.3 4900	11451.3	11571.3
29-11-01-350-801-03 29.050 OVERHAUL	RESTORATION NO. 3 HYDRAULIC PUMP (OVERHAUL) 314470 MX-585763H REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			05-AUG-2017 7451.3 4900	11451.3	11571.3
29-11-01-900-801-01 29.030	NO. 1 HYDRAULIC PUMP 314470 MX381333H REF: See Workcard	MOS HRS/MSC AFL	H/T		TSO:0 TSO:0 TSO:0		05-AUG-2017 7451.3 4900		
29-11-01-900-801-02 29.040	NO. 2 HYDRAULIC PUMP 314470 MX-570050H REF: See Workcard	MOS HRS/MSC AFL	H/T		TSO:0 TSO:0 TSO:0		05-AUG-2017 7451.3 4900		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-01-900-801-03	NO. 3 HYDRAULIC PUMP								
29.050	314470 MX-585763H REF: See Workcard	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			05-AUG-2017 7451.3 4900		
+ 29-11-21-230-801-01	SPECIAL DETAILED INSPECTION NO. 1 SYSTEM NO.1 PRESSURE RELIEF VALVE INTERNAL PART OF THE BODY								
29.250	A24518001(A) FM01740 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 29-11-21-230-801-02	SPECIAL DETAILED INSPECTION NO. 1 SYSTEM NO.2 PRESSURE RELIEF VALVE INTERNAL PART OF THE BODY								
29.250	A24518001(A) FM01741 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 29-11-21-230-801-03	SPECIAL DETAILED INSPECTION NO. 2 SYSTEM PRESSURE RELIEF VALVE INTERNAL PART OF THE BODY								
29.260	A24518001(A) FM01742 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
29-11-21-900-801-01	NO. 1 SYSTEM NO.1 PRESSURE RELIEF VALVE								
29.250	A24518001(A) FM01740 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
29-11-21-900-801-02	NO. 1 SYSTEM NO.2 PRESSURE RELIEF VALVE								
29.250	A24518001(A) FM01741 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
29-11-21-900-801-03	NO. 2 SYSTEM PRESSURE RELIEF VALVE								
29.260	A24518001(A) FM01742 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-25-900-801-01	NO. 1 HYDRAULIC PUMP PRESSURE SWITCH 15H0089PH 0533 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:27 TSN:0 TSN:0			03-JUN-2014 6664 4295		
29-11-25-900-801-02	NO. 2 HYDRAULIC PUMP PRESSURE SWITCH 90G229 752 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-JUL-2004 2981 2139		
29-11-25-900-801-03	NO. 3 HYDRAULIC PUMP PRESSURE SWITCH 90G229 1094 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
29-11-25-900-801-04	NO. 1 HYDRAULIC SYSTEM STANDBY PUMP PRESSURE SWITCH 90G196-2 2048 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
29-11-25-900-801-05	NO. 2 HYDRAULIC SYSTEM STANDBY PUMP PRESSURE SWITCH 90G196-2 2047 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
29-11-25-960-801-01	DISCARD NO. 1 HYDRAULIC PUMP PRESSURE SWITCH 15H0089PH 0533 REF: See Workcard	MOS HRS/MSC AFL	O/C				03-JUN-2014 6664 4295		
29-11-25-960-801-02	DISCARD NO. 2 HYDRAULIC PUMP PRESSURE SWITCH 90G229 752 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			15-JUL-2004 2981 2139		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-25-960-801-03	DISCARD NO. 3 HYDRAULIC PUMP PRESSURE SWITCH 90G229 1094 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0			18-SEP-1997 0 0		
29-13-09-100-801-01	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 1 RETURN FILTER (L200ML) 285695 H1360 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3
29-13-09-100-801-02	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 2 RETURN FILTER (M200ML) 285695 H1361 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3
29-13-09-100-801-03	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 3 RETURN FILTER (R200ML) 285695 H1362 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3
29-13-09-100-801-04	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 1 DELIVERY FILTER (L350ML) C24636000 H0190 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3
29-13-09-100-801-05	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 2 DELIVERY FILTER (M350ML) C24636000 H0191 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3
29-13-09-100-801-06	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - HYDRAULIC PUMP 3 DELIVERY FILTER (R350ML) C24636000 H0192 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-13-09-100-801-07	CLEANING OF THE HYDRAULIC PUMP FILTERING ELEMENTS - STANDBY PUMP FILTER (14ML)								
29.330	C24561000 H0200 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3
29-14-01-220-801-01	DETAILED INSPECTION NO. 1 SYSTEM HYDRAULIC RESERVOIR								
29.060	C24304-002 H0132 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
29-14-01-220-801-02	DETAILED INSPECTION NO. 2 SYSTEM HYDRAULIC RESERVOIR								
29.060	CH913010148/1800 632350 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
29-14-01-900-801-01	NO. 1 SYSTEM HYDRAULIC RESERVOIR								
29.060	C24304-002 H0132 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
29-14-01-900-801-02	NO. 2 SYSTEM HYDRAULIC RESERVOIR								
29.060	CH913010148/1800 632350 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-SEP-2001 1605 1379		
29-14-11-900-801-01	NO. 1 HYDRAULIC SYSTEM ACCUMULATOR								
29.190	60967-1 3256 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
29-14-11-900-801-02	NO. 2 HYDRAULIC SYSTEM ACCUMULATOR								
29.190	60967-1 3254 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-14-33-960-801-01	REPLACE NO. 1 SYSTEM HYDRAULIC RESERVOIR FILTER ELEMENT C24304-002 H0132 REF: See Workcard	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3
29-14-33-960-801-02	REPLACE NO. 2 SYSTEM HYDRAULIC RESERVOIR FILTER ELEMENT CH913010148/1800 632350 REF: See Workcard	MOS HRS/MSC AFL	1200	+30			15-APR-2018 7651.3 5046	8851.3	8881.3
29-14-33-960-802-01	REPLACEMENT OF THE CHLORINE RETAINING ELEMENT SYSTEM 1 HYDRAULIC RESERVOIR REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
29-14-33-960-802-02	REPLACEMENT OF THE CHLORINE RETAINING ELEMENT SYSTEM 2 HYDRAULIC RESERVOIR REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
+ 29-15-00-720-801-01 (s)	FUNCTIONAL TEST OF THE HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - HYDRAULIC SYSTEM 1 PKG 24 REF: See Workcard	MOS HRS/MSC AFL	6000	+30			PKG 25-JUL-2011 5870.4 3679		
+ 29-15-00-720-801-02 (s)	FUNCTIONAL TEST OF THE HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM - HYDRAULIC SYSTEM 2 PKG 24 REF: See Workcard	MOS HRS/MSC AFL	6000	+30			PKG 25-JUL-2011 5870.4 3679		
29-15-05-100-801-01	CLEAN HYDRAULIC RESERVOIR PRESSURE REDUCER VALVE FILTER 2407ZR4EQ10 1568 REF: See Workcard	MOS HRS/MSC AFL	48				29-JUL-2016	29-JUL-2020	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-15-05-350-801-01	RESTORATION HYDRAULIC RESERVOIR PRESSURE REDUCER VALVE (FUNCTIONAL TEST AND DIAPHRAGM REPLACEMENT) 2407ZR4EQ10 1568 REF: See Workcard	MOS HRS/MSC AFL	72				29-JUL-2016	29-JUL-2022	
29-15-05-900-801-01	HYDRAULIC RESERVOIR PRESSURE REDUCER VALVE 2407ZR4EQ10 1568 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			05-MAR-2017 7347.9 4822		
+ 29-20-00-720-801-01	FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - TEST ON HYDRAULIC SYSTEM 2 REF: See Workcard	MOS HRS/MSC AFL	4800	+30			20-FEB-2007 4780 3071	9580	9610
29-20-01-900-801-01	STANDBY ELECTRIC PUMP EP110 19 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 29-20-03-220-801-01	CHECK HYDRAULIC ELECTRO- PUMP-MOTOR BRUSHES 1153-1 2202 REF: See Workcard	MOS HRS/MSC AFL	4800	+3%			19-APR-2011 5818.3 3646	10618.3	10762.3
29-20-05-900-801-01	AUXILIARY MAINTENANCE HYDRAULIC SELECTOR B94A13-205 20462 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
29-20-07-960-801-01	DISCARD NO. 1 HYDRAULIC SYSTEM STANDBY PUMP PRESSURE SWITCH 90G196-2 2048 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-20-07-960-801-02	DISCARD NO. 2 HYDRAULIC SYSTEM STANDBY PUMP PRESSURE SWITCH								
29.320	90G196-2 2047 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0			18-SEP-1997 0 0		
290801	#2 ENGINE HYDRAULIC QUICK DISCONNECT COUPLING								
	MFR-SDE34 1575950 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JUN-2011 5854.2 3662		
291161	HYDRAULIC PRESSURIZATION VALVE ASSEMBLY								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
291166	NO. 1 CIRCUIT NO.1 RETURN REGULATION FILTER								
29.070	285695 H1360 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291176	NO. 1 CIRCUIT NO.2 RETURN REGULATION FILTER								
29.070	285695 H1361 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291186	NO. 2 CIRCUIT NO.3 RETURN REGULATION FILTER								
29.080	285695 H1362 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291226	NO. 1 PUMP RETURN CHECK VALVE								
29.100	A24515-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291231	NO. 2 PUMP RETURN CHECK VALVE A24515-1	MOS					18-SEP-1997		
29.100	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291236	NO. 3 PUMP RETURN CHECK VALVE A24515-1	MOS					18-SEP-1997		
29.100	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291241	NO. 1 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING 405-20402-13300	MOS					18-SEP-1997		
29.110	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291246	NO. 2 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING 405-20402-13300	MOS					18-SEP-1997		
29.110	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291251	NO. 3 PUMP SUCTION FIXED-HALF QUICK DISCONNECT COUPLING 405-20402-13300	MOS					18-SEP-1997		
29.110	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291256	NO. 1 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING 405-20403-13200	MOS					18-SEP-1997		
29.120	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291261	NO. 2 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING 405-20403-13200	MOS					18-SEP-1997		
29.120	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291266	NO. 3 PUMP SUCTION COUPLER QUICK DISCONNECT COUPLING 405-20403-13200	MOS					18-SEP-1997		
29.120	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291271	NO. 1 PUMP DISCHARGE QUICK DISCONNECT VALVE AE99113H	MOS					18-SEP-1997		
29.130	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291276	NO. 2 PUMP DISCHARGE QUICK DISCONNECT VALVE AE99113H	MOS					18-SEP-1997		
29.130	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291281	NO. 3 PUMP DISCHARGE QUICK DISCONNECT VALVE AE99113H	MOS					18-SEP-1997		
29.130	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291286	NO. 1 HP HYDRAULIC FILTER C24636000	MOS					18-SEP-1997		
29.140	H0190 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291296	NO. 2 HP HYDRAULIC FILTER C24636000	MOS					18-SEP-1997		
29.150	H0191 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291306	NO. 3 HP HYDRAULIC FILTER C24636000	MOS					18-SEP-1997		
29.160	H0192 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291316	NO. 1 HYDRAULIC SYSTEM LEFT GROUND RETURN CONNECTION								
29.170	B3005S4-12D SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291321	NO. 2 HYDRAULIC SYSTEM RIGHT GROUND RETURN CONNECTION								
29.170	B3005S4-12D SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291326	NO. 1 HYDRAULIC SYSTEM LEFT GROUND PRESSURE CONNECTION								
29.180	TB3005S4-8D SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291331	NO. 2 HYDRAULIC SYSTEM RIGHT GROUND PRESSURE CONNECTION								
29.180	TB3005S4-8D SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291356	NO. 1 PRESSURE INDICATOR								
29.200	18040100 36954C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291366	NO. 2 PRESSURE INDICATOR								
29.200	18040100 36955C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291376	NO. 1 HYDRAULIC SYSTEM ACCUMULATOR FILLER VALVE								
29.210	MS28889-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291381	NO. 2 HYDRAULIC SYSTEM ACCUMULATOR FILLER VALVE								
29.210	MS28889-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291386	PARKING BRAKE ACCUMULATOR FILLER VALVE								
29.220	MS28889-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291391	THRUST REVERSER ACCUMULATOR FILLER VALVE								
29.220	MS28889-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291396	NO. 1 PUMP SUCTION CHECK VALVE								
29.230	A24517 FM4534 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291401	NO. 2 PUMP SUCTION CHECK VALVE								
29.230	A24517 FM4535 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291406	NO. 3 PUMP SUCTION CHECK VALVE								
29.230	A24517 FM4527 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291411	NO. 1 SYSTEM SUCTION CHECK VALVE GROUND CONNECTION								
29.240	A24517 FM4536 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291416	NO. 2 SYSTEM SUCTION CHECK VALVE GROUND CONNECTION								
29.240	A24517 FM4537 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291436	NO. 1 SYSTEM ELECTRO PUMP DISTRIBUTOR CHECK VALVE								
29.270	A24516 FM3603 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291441	NO. 2 SYSTEM ELECTRO PUMP DISTRIBUTOR CHECK VALVE								
29.270	A24516 FM3709 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
291446	HYDRAULIC PRESSURIZATION CHECK VALVE								
29.280	2504CD01 802 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
292121	HYDRAULIC ELECTRO- PUMP-MOTOR								
29.300	1153-1 2202 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			01-APR-2005 3466 2396		
292156	AUXILIARY HYDRAULIC SYSTEM FILTER								
29.330	C24561000 H0200 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
293101	NO. 1 CIRCUIT PRESSURE TRANSMITTER								
29.340	8107-134-00-12 350 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293106	NO. 2 CIRCUIT PRESSURE TRANSMITTER								
29.340	8107-134-00-12 305 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
293111	NO. 1 CIRCUIT DUAL INDICATOR PRESSURE LEVEL								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
293116	NO. 2 CIRCUIT DUAL INDICATOR PRESSURE LEVEL								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
293141	NO. 1 HYDRAULIC RESERVOIR PRESSURIZATION LOW PRESSURE SWITCH								
29.370	8A1206-1 509 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
293146	NO. 2 HYDRAULIC RESERVOIR PRESSURIZATION LOW PRESSURE SWITCH								
29.370	8A1206-1 510 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
293801	NO. 1 HYDRAULIC RESERVOIR PRESSURE VALVE								
	C24265 AP3041 REF:	MOS HRS/MSC AFL	O/C	TSR:3 TSR:0 TSR:0			25-JUN-2012 6097.1 3850		
293802	NO. 2 HYDRAULIC RESERVOIR PRESSURE VALVE								
	C24265 M161 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			05-DEC-2003 2487 1891		

CHAPTER 30 ICE AND RAIN PROTECTION

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-11-00-350-801-01	RESTORATION LH INBOARD SLAT TELESCOPIC DUCT (OVERHAUL)								
30.030	5041-200 562 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:0 TSI:0 TSI:0			01-SEP-2010 5687.4 3553		
30-11-00-350-801-02	RESTORATION RH INBOARD SLAT TELESCOPIC DUCT (OVERHAUL)								
30.030	5041-100 586 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:5633.8			21-JUL-2009 5633.8 3518		
30-11-00-350-801-03	RESTORATION LH OUTBOARD SLAT TELESCOPIC DUCT (OVERHAUL)								
30.020	5040-000 598 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:5633.8			21-JUL-2009 5633.8 3518		
30-11-00-350-801-04	RESTORATION RH OUTBOARD SLAT TELESCOPIC DUCT (OVERHAUL)								
30.020	5040-100 594 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:5633.8			21-JUL-2009 5633.8 3518		
30-11-00-720-801-01	FUNCTIONAL TEST LH INBOARD SLAT TELESCOPIC DUCT								
30.030	5041-200 562 REF: See Workcard	MOS HRS/MSC AFL	2500 2000	+3% +3%			11-APR-2016 7065.7 4612	9565.7 6612	9640.7 6672
30-11-00-720-801-02	FUNCTIONAL TEST RH INBOARD SLAT TELESCOPIC DUCT								
30.030	5041-100 586 REF: See Workcard	MOS HRS/MSC AFL	2500 2000	+3% +3%			11-APR-2016 7065.7 4612	9565.7 6612	9640.7 6672
30-11-00-720-801-03	FUNCTIONAL TEST LH OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5040-000 598 REF: See Workcard	MOS HRS/MSC AFL	2500 2000	+3% +3%			11-APR-2016 7065.7 4612	9565.7 6612	9640.7 6672



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-11-00-720-801-04	FUNCTIONAL TEST RH OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5040-100 594 REF: See Workcard	MOS HRS/MSC AFL	2500 +3% 2000 +3%				11-APR-2016 7065.7 4612	9565.7 6612	9640.7 6672
30-11-00-900-801-01	LH OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5040-000 598 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:5633.8			21-JUL-2009 5633.8 3518		
30-11-00-900-801-02	LH INBOARD SLAT TELESCOPIC DUCT								
30.030	5041-200 562 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0		09/01/2011	01-SEP-2010 5687.4 3553		
30-11-00-900-801-03	RH INBOARD SLAT TELESCOPIC DUCT								
30.030	5041-100 586 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:5633.8			21-JUL-2009 5633.8 3518		
30-11-00-900-801-04	RH OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5040-100 594 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:5633.8			21-JUL-2009 5633.8 3518		
30-12-13-900-801-01	LH WING ANTI-ICING PRESSURE SWITCH								
30.040	8G1199-4 760 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
30-12-13-900-801-02	RH WING ANTI-ICING PRESSURE SWITCH								
30.040	8G1199-4 761 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-20-01-700-801-01	FUNCTIONAL TEST NO. 1 ENGINE AIR INTAKE ANTI-ICING VALVE 327945-2 0028 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 30-20-01-700-801-02	FUNCTIONAL TEST NO. 2 ENGINE AIR INTAKE ANTI-ICING VALVE 327945-2 0045 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 30-20-01-700-801-03	FUNCTIONAL TEST NO. 3 ENGINE AIR INTAKE ANTI-ICING VALVE 327945-2 0172 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
30-20-01-900-801-01 30.070	NO. 1 ENGINE AIR INTAKE ANTI-ICING VALVE 327945-2 0028 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:11			22-DEC-1997 28 14		
30-20-01-900-801-02 30.060	NO. 2 ENGINE AIR INTAKE ANTI-ICING VALVE 327945-2 0045 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:11			22-DEC-1997 28 14		
30-20-01-900-801-03 30.070	NO. 3 ENGINE AIR INTAKE ANTI-ICING VALVE 327945-2 0172 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-JAN-2000 979 801		
30-20-09-900-801-01 30.080	NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH 8G1199-4 1109 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-20-09-900-801-02	NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH 8G1199-4 889 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
30-20-09-900-801-03	NO. 3 ENGINE AIR INTAKE ANTI-ICING PRESSURE SWITCH 8G1199-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
30-20-09-900-801-04	S-DUCT ANTI-ICING PRESSURE SWITCH 8G1199-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
30-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 23-MAY-2017 7416.5 4869		
30-41-00-710-801-01 (s)	OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM PKG 24 REF: See Workcard	MOS HRS/MSC AFL	6000	+30			PKG 25-JUL-2011 5870.4 3679		
+ 30-42-00-200-801-01	INSPECTION LH DESSICANT BOTTLE 210-90-17-68601 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 30-42-00-200-801-02	INSPECTION RH DESSICANT BOTTLE 210-90-17-68601 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-43-09-220-801-01	CHECK PILOT WINDSHIELD WIPER MOTOR BRUSHES								
30.110	XW23827G1 00112 REF: See Workcard	MOS HRS/MSC AFL	10000				18-SEP-1997 0 0	10000	
+ 30-43-09-220-801-02	CHECK COPILOT WINDSHIELD WIPER MOTOR BRUSHES								
30.110	XW23827G1 00114 REF: See Workcard	MOS HRS/MSC AFL	10000				18-SEP-1997 0 0	10000	
+ 30-60-01-720-801-01	FUNCTIONAL TEST NO. 2 ENGINE "S" DUCT ANTI-ICING VALVE								
301050	3137-100 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
30.210	AIRFOIL ANTI-ICING VALVE BYLB52642 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
301091	AIRFRAME NORMAL ANTI-ICING VALVE								
30.010	1263-00-12 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
301101	AIRFRAME EMERGENCY ANTI-ICING VALVE								
301101	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
302111	S-DUCT ANTI-ICING VALVE								
30.220	BYLB52643 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302116	NO. 1 ANTI-ICE TEMPERATURE PROBE								
30.230	RP493-00 DAAB02727 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			29-JUL-2017 7448 4897		
302121	BLD AIR ENG #2 THERMOSTAT								
	RP161-00 2276 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-SEP-2004 3101 2205		
302126	NO. 3 ANTI-ICE TEMPERATURE PROBE								
30.240	RP161-00 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			0 0		
302131	NO. 2 ENGINE "S" DUCT ANTI-ICING VALVE								
30.060	3137-100 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
303001	LH PITOT HEAT INDICATOR PRINTED CIRCUIT BOARD								
30.100	24-250 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
303106	RH PITOT HEAT INDICATOR PRINTED CIRCUIT BOARD								
30.100	24-250 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304101	PILOT WINDSHIELD WIPER MOTOR								
30.110	XW23827G1 00112 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304111	COPILOT WINDSHIELD WIPER MOTOR								
30.110	XW23827G1 00114 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304121	PILOT WINDSHIELD WIPER CONVERTER								
30.120	XW203453421082L 02006 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304126	COPILOT WINDSHIELD WIPER CONVERTER								
30.130	XW203453421082R 02015 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304131	PILOT WINDSHIELD FLEXIBLE DRIVE								
30.120	4172396 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304136	COPILOT WINDSHIELD FLEXIBLE DRIVE								
30.130	4172396 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304141	PILOT WINDSHIELD WIPER ARM								
30.120	4011316 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304146	COPILOT WINDSHIELD WIPER ARM								
30.130	4011323 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304156	PILOT FRONT WINDSHIELD HEATER REGULATOR								
30.140	HYLZ50426-1 934D REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-JUN-2001 1531 1302		
304161	COPILOT FRONT WINDSHIELD HEATER REGULATOR								
30.140	AV30559060030-1 299 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304166	PILOT SIDE WINDSHIELD HEATER REGULATOR								
30.150	AV30564060030 298 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304171	COPILOT SIDE WINDSHIELD HEATER REGULATOR								
30.150	AV30564060030 262 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304181	LH WIPER PARKING POSITION RESISTOR								
30.170	24-450 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304186	WINDSHIELD DE-MIST BLOWER								
30.170	125XS01-62-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304191	DE-MIST CIRCUIT THERMAL FUSE								
30.170	4257A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304196	DE-MIST CIRCUIT RESISTOR								
30.180	505-0087 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304201	DE-MIST CIRCUIT THERMOSTAT								
30.180	M1-140-120-182 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304209	DE-MIST CIRCUIT SPEED SELECTOR								
30.180	319-100-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304211	LH DESSICANT BOTTLE								
30.190	210-90-17-68601 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304221	RH DESSICANT BOTTLE								
30.190	210-90-17-68601 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
304241	OUTSIDE AIR TEMPERATURE PROBE								
30.200	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-21-05-960-801-01	REPLACEMENT PILOT CLOCK BATTERY								
31.010	811-BATT-1 NSN REF: See Workcard	MOS HRS/MSC AFL	25				06-MAR-2017 7347.9 4822	06-APR-2019	
SCRAP									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-21-05-960-801-02	REPLACEMENT COPILOT CLOCK BATTERY								
31.010	811-BATT-1	MOS	25				06-MAR-2017	06-APR-2019	
SCRAP	NSN	HRS/MSC					7347.9		
	REF: See Workcard	AFL					4822		
+ 31-31-00-710-802-01 (s)	OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) SYSTEM						PKG		
31.090	PKG 17	MOS	36	+1m			24-MAY-2010		
	REF: See Workcard	HRS/MSC					5673.4		
		AFL					3543		
31-31-00-720-803-01	FUNCTIONAL TEST FLIGHT DATA RECORDER 32-PARAMETER								
	980-4700-027	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
31-31-00-970-801-01	DOWNLOAD FLIGHT DATA RECORDER								
31.190	980-4700-027	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
+ 31-31-09-710-801-01	OPERATIONAL TEST COCKPIT VOICE RECORDER ACCELERATION CONTACT								
31.120	400-10B	MOS	240	+3%	-49		26-OCT-2009	07-SEP-2029	13-APR-2030
	5511	HRS/MSC					5647.7		
	REF: See Workcard	AFL					3527		
+ 31-31-09-710-801-02	OPERATIONAL TEST DIGITAL FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT								
NOT INSTALLED	PN	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
31-31-09-900-801-01	COCKPIT VOICE RECORDER ACCELERATION CONTACT								
31.120	400-10B	MOS				TSN:0	07-SEP-2007		
	5511	HRS/MSC	O/C			TSN:0	5141		
	REF: See Workcard	AFL				TSN:0	3245		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-09-900-801-02	DIGITAL FLIGHT DATA RECORDER (FDR) ACCELERATION CONTACT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
+ 31-31-50-710-801-01 (s)	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) SYSTEM - CVR (10FZ) PKG 17 31.080 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			15-APR-2018 7651.3 5046		
31-31-50-970-801-01	DOWNLOAD COCKPIT VOICE RECORDER 980-6020-011 1257 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
31-32-00-970-801-01	DOWNLOAD QUICK ACCESS (QAR) RECORDER DATA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
31-32-05-960-801-01	REPLACEMENT QUICK ACCESS (QAR) RECORDER BATTERY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
31-52-00-710-801-01	OPERATIONAL TEST OF THE WARNING PANEL DUAL POWER SUPPLY - WARNING PANEL (32W) REF: See Workcard	MOS HRS/MSC AFL	2400	+30			15-APR-2018 7651.3 5046	10051.3	10081.3

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-54-00-720-802-01 (s)	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: LOGIC TEST - ALARM TEST						PKG		
31.040	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			29-MAY-2017 7416.5 4869		
31-54-00-720-802-02 (s)	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: LOGIC TEST - TEST OF INDICATION LOGIC						PKG		
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
+ 31-55-00-720-801-01 (s)	FUNCTIONAL TEST OF THE LANDING SAFETIES						PKG		
31.050	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
+ 31-60-00-710-801-01 (s)	OPERATIONAL TEST OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED)						PKG		
31.180	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			02-JUN-2017 7416.5 4869		
+ 31-60-00-710-801-01A	OPERATIONAL TEST OF THE ENGINE INDICATOR ELECTRONIC DISPLAY (EIED) (MANDATORY 5-40)								
31.180 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	1530				02-JUN-2017 7416.5 4869	8946.5	
31-60-51-900-801-01	ENGINE INDICATION ELECTRONIC TOP DISPLAY								
31.170	C14155BB04 286 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		10-MAY-2010 5668.9 3540		
31-60-51-900-801-02	ENGINE INDICATION ELECTRONIC MIDDLE DISPLAY								
31.170	C14155BB04 119 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		21-MAY-2007 4970 3157		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-60-51-900-801-03	ENGINE INDICATION ELECTRONIC BOTTOM DISPLAY								
31.170	C14155BB04 269 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:1398 TSR:0 TSN:968 TSR:0			15-SEP-2014 6727.3 4344		
310001	WARNING PANEL								
39.010	FE925-1 44 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			16-SEP-1998 369 333		
310006	ELECTRONIC PANEL								
39.010	203TS04Y01 146 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAY-2001 1513 1289		
310009	HYDRAULIC PANEL								
39.010	694TS03Y01SE SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
311098	PILOTS CLOCK								
	811BFTR24HR 32422 REF:	MOS HRS/MSC AFL	O/C				22-DEC-1997 28 14		
312001	PILOT CLOCK BATTERY								
31.010	811-BATT-1 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			06-MAR-2017 7347.9 4822		
312003	COPILOTS CLOCK								
	811BFTR24HR 36109 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2003 2475 1887		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
312006	COPILOT CLOCK BATTERY								
31.010	811-BATT-1 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			06-MAR-2017 7347.9 4822		
312011	GROUND PROXIMITY WARNING SYSTEM DISPLAY UNIT								
31.150	965-0976-212-212 17038 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874		
312016	GROUND PROXIMITY WARNING SYSTEM INVERTER								
31.160	1A501B1 1112607 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
315101	AUDIO WARNING UNIT								
31.020	244ZS01 431 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			24-OCT-2005 3926 2618		
315111	TAKE OFF WARNING PRINTED CARD								
31.030	CI820A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
316001	COCKPIT VOICE RECORDER								
31.080	980-6020-011 1257 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
316008	COCKPIT VOICE RECORDER CONTROL								
31.070	980-6117-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316018	CVR MICROPHONE 980-6113-001 0494 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
316051	FLIGHT DATA RECORDER 980-4700-027 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
CHAPTER 32 LANDING GEAR									
32-00-00-700-801-01 (s)	CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13G) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 31-MAY-2017 7416.5 4869		
32-00-00-700-801-02 (s)	CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (7G1) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 31-MAY-2017 7416.5 4869		
32-00-00-700-801-03 (s)	CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (7G2) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 30-MAY-2017 7416.5 4869		
32-10-00-640-801-01	LUBRICATION OF THE LH MAIN LANDING GEAR (MLG) AND MLG DOORS REF: See Workcard	MOS HRS/MSC AFL	6 400	+1m			27-SEP-2018 7790.4 5152	27-MAR-2019	27-APR-2019 5552
32-10-00-640-801-02	LUBRICATION OF THE RH MAIN LANDING GEAR (MLG) AND MLG DOORS REF: See Workcard	MOS HRS/MSC AFL	6 400	+1m			27-SEP-2018 7790.4 5152	27-MAR-2019	27-APR-2019 5552

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-00-220-801-01	DETAILED INSPECTION LH MAIN LANDING GEAR (MLG) LEG								
32.930	C23791-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	72	+8m			04-APR-2016 7065.7 4612	04-APR-2022	04-DEC-2022
32-11-00-220-801-01C	DETAILED INSPECTION LH MLG LEG (CPCP)								
32.015 CPCP	REF: See Workcard	MOS HRS/MSC AFL	80				04-APR-2016 7065.7 4612	04-DEC-2022	
+ 32-11-00-220-801-02	DETAILED INSPECTION RH MAIN LANDING GEAR (MLG) LEG								
32.930	C23792-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	72	+8m			04-APR-2016 7065.7 4612	04-APR-2022	04-DEC-2022
32-11-00-220-801-02C	DETAILED INSPECTION RH MLG LEG (CPCP)								
32.015 CPCP	REF: See Workcard	MOS HRS/MSC AFL	80				04-APR-2016 7065.7 4612	04-DEC-2022	
32-11-00-350-801-01	RESTORATION LH MAIN LANDING GEAR (MLG) LEG (OVERHAUL)								
OVERHAUL	C23791-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	TSI:0		10-MAY-2010 5668.9 3540	10-MAY-2022 9540	10-OCT-2022
32-11-00-350-801-02	RESTORATION RH MAIN LANDING GEAR (MLG) LEG (OVERHAUL)								
OVERHAUL	C23792-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	TSI:0		10-MAY-2010 5668.9 3540	10-MAY-2022 9540	10-OCT-2022
32-11-00-700-801-01	CHECK LEFT MAIN LANDING GEAR (MLG) LEG GRAVITY OSCILLATIONS								
32.130	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-700-801-02	CHECK RIGHT MAIN LANDING GEAR (MLG) LEG GRAVITY OSCILLATIONS								
32.130	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
32-11-00-900-801-01	LH MAIN LANDING GEAR (MLG) LEG								
32.010	C23791-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:3540			10-MAY-2010 5668.9 3540		
32-11-00-900-801-02	RH MAIN LANDING GEAR (MLG) LEG								
32.010	C23792-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:3540			10-MAY-2010 5668.9 3540		
32-11-00-960-801-01	REPLACEMENT LH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)								
32.010 LIFE LIMIT	C23791-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:3540			10-MAY-2010 5668.9 3540		20000
32-11-00-960-801-01A	REPLACEMENT LH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)								
MANDATORY 5-40	C23791-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:3540			10-MAY-2010 5668.9 3540		20000
32-11-00-960-801-02	REPLACEMENT RH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)								
32.010 LIFE LIMIT	C23792-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:3540			10-MAY-2010 5668.9 3540		20000
32-11-00-960-801-02A	REPLACEMENT RH MAIN LANDING GEAR (MLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)								
MANDATORY 5-40	C23792-1009 B31 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:3540			10-MAY-2010 5668.9 3540		20000

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-03-960-801-01	DISCARD LH REAR MAIN LANDING GEAR (MLG) PINTLE PIN D52554-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	18670				18-SEP-1997 0 0		18670
32.060 LIFE LIMIT									
32-11-03-960-801-01A	DISCARD LH REAR MAIN LANDING GEAR (MLG) PINTLE PIN (MANDATORY 5-40) D52554-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	18670				18-SEP-1997 0 0		18670
32-11-03-960-801-01A									
32-11-03-960-801-02	DISCARD RH REAR MAIN LANDING GEAR (MLG) PINTLE PIN D52554-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	18670				18-SEP-1997 0 0		18670
32.060 LIFE LIMIT									
32-11-03-960-801-02A	DISCARD RH REAR MAIN LANDING GEAR (MLG) PINTLE PIN (MANDATORY 5-40) D52554-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	18670				18-SEP-1997 0 0		18670
32-11-03-960-801-02A									
32-11-05-350-801-01	RESTORATION LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING (DISCARD) D50493 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0		20000
32-11-05-350-801-01									
32-11-05-350-801-01A	RESTORATION LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING (DISCARD) (MANDATORY 5-40) D50493 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0		20000
32.020 LIFE LIMIT									
32-11-05-350-801-02	RESTORATION RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING (DISCARD) D50493 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0		20000
32-11-05-350-801-02									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-05-350-801-02A	RESTORATION RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING (DISCARD) (MANDATORY 5-40)								
	D50493	MOS					18-SEP-1997		
32.030	SN-UNKNOWN	HRS/MSC					0		
LIFE LIMIT	REF: See Workcard	AFL	20000				0		20000
+ 32-11-05-780-801-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)						PKG		
	PKG 21	MOS					31-MAY-2017		
32.020		HRS/MSC	1500	+30			7416.5		
	REF: See Workcard	AFL					4869		
+ 32-11-05-780-801-02 (s)	CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)						PKG		
	PKG 21	MOS					31-MAY-2017		
32.030		HRS/MSC	1500	+30			7416.5		
	REF: See Workcard	AFL					4869		
32-11-05-900-801-01	LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER								
	C23795-1004	MOS					10-MAY-2010		
32.020	SN-UNKNOWN	HRS/MSC	O/C			-234	5668.9		
	REF: See Workcard	AFL					3540		
				TSN:152 TSO:0					
				TSO:0					
				TSN:3540 TSO:0					
32-11-05-900-801-02	RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER								
	C23796-1004	MOS					10-MAY-2010		
32.030	SN-UNKNOWN	HRS/MSC	O/C			-234	5668.9		
	REF: See Workcard	AFL					3540		
				TSN:152 TSO:0					
				TSO:0					
				TSN:3540 TSO:0					
32-11-21-350-801-01	RESTORATION LH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE (DISCARD)								
	D52369	MOS					18-SEP-1997		
32.040	SN-UNKNOWN	HRS/MSC					0		
LIFE LIMIT	REF: See Workcard	AFL	20000				0		20000
32-11-21-350-801-01A	RESTORATION LH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE (DISCARD)(MANDATORY 5-40)								
	D52369	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-21-350-801-02	RESTORATION RH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE (DISCARD)								
	D52369	MOS					18-SEP-1997		
32.050	SN-UNKNOWN	HRS/MSC					0		
LIFE LIMIT	REF: See Workcard	AFL	20000				0		20000
32-11-21-350-801-02A	RESTORATION RH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE (DISCARD)(MANDATORY 5-40)								
	D52369	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		
32-11-21-900-801-01	LH MAIN LANDING GEAR (MLG) BRACE STRUT ACTUATOR								
	D23609000	MOS					18-SEP-1997		
32.040	B12	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
32-11-21-900-801-02	RH MAIN LANDING GEAR (MLG) BRACE STRUT ACTUATOR								
	D23610000	MOS					18-SEP-1997		
32.050	B12	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
32-11-25-220-801-01 (s)	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)						PKG		
	PKG 31	MOS	72				18-SEP-1997		
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
32-11-25-220-801-02 (s)	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)						PKG		
	PKG 31	MOS	72				18-SEP-1997		
		HRS/MSC					0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-25-220-801-03 (s)	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)						PKG		
	PKG 31	MOS	72				18-SEP-1997		
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
32-11-25-220-801-04 (s)	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)						PKG		
	PKG 31	MOS	72				18-SEP-1997		
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
32-11-25-900-801-01	LH MAIN LANDING GEAR (MLG) FRONT BALL-JOINT BEARING								
	BRS50RTGSP6	MOS					18-SEP-1997		
32.120	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
32-11-25-900-801-02	LH MAIN LANDING GEAR (MLG) REAR BALL-JOINT BEARING								
	BRS55TAGSP2	MOS					18-SEP-1997		
32.060	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
32-11-25-900-801-03	RH MAIN LANDING GEAR (MLG) FRONT BALL-JOINT BEARING								
	BRS50RTGSP6	MOS					18-SEP-1997		
32.120	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
32-11-25-900-801-04	RH MAIN LANDING GEAR (MLG) REAR BALL-JOINT BEARING								
	BRS55TAGSP2	MOS					18-SEP-1997		
32.070	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
32-12-17-900-801-01	LH MAIN LANDING GEAR (MLG) UPLOCK								
	C24244-0-1	MOS					18-SEP-1997		
32.310	H500	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-12-17-900-801-02	RH MAIN LANDING GEAR (MLG) UPLOCK C24245-0-1 H959 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:6193.9 TSR:0			24-SEP-2012 6193.9 3935		
32-12-25-900-801-01	LH MAIN LANDING GEAR (MLG) MAIN DOOR ACTUATOR C23735-1101 U44 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0		03/02/2009	02-MAR-2007 4811 3079		
32-12-25-900-801-02	RH MAIN LANDING GEAR (MLG) MAIN DOOR ACTUATOR C23736-1101 H245V REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			12-FEB-1999 525 473		
32-12-29-900-801-01	LH MAIN LANDING GEAR (MLG) DOOR UPLOCK C24257-1-4 H1134 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSN:4839 TSN:3092			16-MAR-2007 4839 3092		
32-12-29-900-801-02	RH MAIN LANDING GEAR (MLG) DOOR UPLOCK C24257-1-4 H324 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0		03/19/2009	19-MAR-2007 4842 3094		
32-20-00-640-801-01	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS REF: See Workcard	MOS HRS/MSC AFL	6 400	+1m			27-SEP-2018 7790.4 5152	27-MAR-2019	27-APR-2019 5552
32-20-00-640-801-02	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS SLIDING ROD LOWER BEARING REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-21-00-220-801-01	DETAILED INSPECTION NOSE LANDING GEAR (NLG) LEG								
32.920	C23787-1007 B10 REF: See Workcard	MOS HRS/MSC AFL	72	+8m			04-APR-2016 7065.7 4612	04-APR-2022	04-DEC-2022
32-21-00-220-801-01C	DETAILED INSPECTION NLG LEG (CPCP)								
32.025 CPCP	REF: See Workcard	MOS HRS/MSC AFL	80				04-APR-2016 7065.7 4612	04-DEC-2022	
32-21-00-350-801-01	RESTORATION NOSE LANDING GEAR (NLG) LEG (OVERHAUL)								
OVERHAUL	C23787-1007 B10 REF: See Workcard	MOS HRS/MSC AFL	144	+5m	TSI:0		10-MAY-2010 5668.9 3540	10-MAY-2022	10-OCT-2022
32-21-00-700-801-01	CHECK NOSE LANDING GEAR (NLG) LEG GRAVITY OSCILLATIONS								
32.270	REF: See Workcard	MOS HRS/MSC AFL	O/C				30-JUN-1999 737 612		
32-21-00-900-801-01	NOSE LANDING GEAR (NLG) LEG								
32.180	C23787-1007 B10 REF: See Workcard	MOS HRS/MSC AFL	H/T		TSN:5603.9 TSN:3489		10-MAY-2010 5668.9 3540		
32-21-00-960-801-01	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD OF LIFE LIMITED PARTS)								
32.180 LIFE LIMIT	C23787-1007 B10 REF: See Workcard	MOS HRS/MSC AFL	20000		TSI:5603.9 TSI:3489		10-MAY-2010 5668.9 3540	20051	
32-21-00-960-801-01A	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD OF LIFE LIMITED PARTS)(MANDATORY 5-40)								
MANDATORY 5-40	C23787-1007 B10 REF: See Workcard	MOS HRS/MSC AFL	20000		TSI:5603.9 TSI:3489		10-MAY-2010 5668.9 3540	20051	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-01-610-801-01	SERVICING NOSE LANDING GEAR (NLG) SHOCK ABSORBER C23789-1002 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
32-21-01-610-802-01	CHARGING NOSE LANDING GEAR (NLG) SHOCK ABSORBER C23789-1002 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 32-21-01-780-801-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 31-MAY-2017 7416.5 4869		
32-21-01-900-801-01	NOSE LANDING GEAR (NLG) SHOCK ABSORBER C23789-1002 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C			TSN:152 TSO:0 TSO:0 TSN:3540 TSO:0	-234 10-MAY-2010 5668.9 3540		
32-21-09-220-801-01 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72				18-SEP-1997 0 0		
32-21-09-220-801-02 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-09-220-801-03 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING						PKG		
	PKG 31	MOS	72				18-SEP-1997		
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
32-21-09-220-801-04 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING						PKG		
	PKG 31	MOS	72				18-SEP-1997		
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
32-21-09-900-801-01	LH NLG DRAG BRACE BALL-JOINT BEARING								
32.250	BRS35TAGSP5 SN-UNKNOWN	MOS	O/C	TSN:0			18-SEP-1997		
	REF: See Workcard	HRS/MSC					0		
		AFL					0		
32-21-09-900-801-02	RH NLG DRAG BRACE BALL-JOINT BEARING								
	PN SN-UNKNOWN	MOS	O/C	TSN:0			18-SEP-1997		
	REF: See Workcard	HRS/MSC		TSN:0			0		
		AFL		TSN:0			0		
32-21-09-900-801-03	LH NLG LEG BALL-JOINT BEARING								
32.240	BRS40TAGSP2 SN-UNKNOWN	MOS	O/C	TSN:0			30-JUN-1999		
	REF: See Workcard	HRS/MSC		TSN:0			737		
		AFL		TSN:0			612		
32-21-09-900-801-04	RH NLG LEG BALL-JOINT BEARING								
32.240	BRS40TAGSP2 SN-UNKNOWN	MOS	O/C	TSN:0			30-JUN-1999		
	REF: See Workcard	HRS/MSC		TSN:0			737		
		AFL		TSN:0			612		
32-22-01-350-801-01	RESTORATION NOSE LANDING GEAR TELESCOPIC STRUT YOKE ASSEMBLY (OVERHAUL)								
32.210	GA62269 B16-624	MOS	144	+5m			10-MAY-2010	10-MAY-2022	10-OCT-2022
OVERHAUL	REF: See Workcard	HRS/MSC			TSI:0		5668.9		
		AFL	6000				3540	9540	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-22-01-900-801-01	NOSE LANDING GEAR (NLG) DRAG BRACE C23811-12 B51 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-22-13-900-801-01	NOSE LANDING GEAR (NLG) ACTUATOR C23810-10-1 B63 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-22-17-900-801-01	NOSE LANDING GEAR (NLG) UPLOCK C24245-4-1 H0965 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-30-00-720-801-01 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEAR AND DOORS - NORMAL OPERATION PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
32-30-00-720-801-02 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEAR AND DOORS - HYDRAULIC EMERGENCY OPERATION PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
32-30-00-720-801-03 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEAR AND DOORS - MECHANICAL EMERGENCY OPERATION PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
32-30-13-900-801-01	LANDING GEAR NORMAL/EMERGENCY SELECTOR VALVE B94B09-202-1 20343 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-31-00-700-801-01 (s)	CHECK OF THE LANDING GEAR RETRACTION INHIBITION ON THE GROUND						PKG		
32.450	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
32-31-01-900-801-01	LANDING GEAR SELECTOR VALVE								
32.360	12-337-37 111 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 32-31-13-790-801-01 (s)	INTERNAL LEAK CHECK OF THE LANDING GEAR SOLENOID SELECTOR VALVE						PKG		
32.910	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
32-32-00-640-801-01 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE NLG CONTROL						PKG		
32.430	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
32-32-00-640-801-02 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE NLG CONTROL ACTUATION FORCE						PKG		
32.430	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
32-32-00-640-801-03 (s)	LUBRICATION OF THE MAIN LANDING GEAR (MLG) CONTROLS						PKG		
32.420	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
+ 32-32-00-640-801-04 (s)	CHECK OF THE MAIN LANDING GEAR (MLG) CONTROL ACTUATION FORCE						PKG		
32.420	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-32-00-700-801-01	TEST TO BE PERFORMED FOLLOWING EMERGENCY LANDING GEAR EXTENSION	MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC AFL	A/R				0 0		
32-32-05-900-801-01	LH MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY EXTENSION CONTROL CABLE	MOS					18-SEP-1997		
32.420	F50B796001A2 SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
32-32-05-900-801-02	RH MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY EXTENSION CONTROL CABLE	MOS					18-SEP-1997		
32.420	F50B796001A2 SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
32-32-17-640-801-01 (s)	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - LUBRICATION OF THE L/G HYDRAULIC EMERGENCY EXTENTION CONTROL	MOS	24	+1m			15-APR-2018		
32.350	PKG 16 REF: See Workcard	HRS/MSC AFL					7651.3 5046		
+ 32-32-17-640-801-02 (s)	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - CHECK OF CONTROL ACTUATION LOADS	MOS	24	+1m			15-APR-2018		
32.350	PKG 16 REF: See Workcard	HRS/MSC AFL					7651.3 5046		
32-32-17-900-801-01	L/G HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE	MOS					18-SEP-1997		
32.350	F50B793001A2 SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
+ 32-40-00-780-801-01 (s)	CHECK NORMAL BRAKING SYSTEM PRESSURE	MOS					25-JUL-2011		
32.710	PKG 22 REF: See Workcard	HRS/MSC AFL	3000	+30			5870.4 3679		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40-00-780-801-02 (s)	CHECK EMERGENCY BRAKING SYSTEM PRESSURE						PKG		
32.710	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000	+30			25-JUL-2011 5870.4 3679		
+ 32-40-00-780-801-03 (s)	CHECK PARKING BRAKE SYSTEM PRESSURE						PKG		
32.710	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000	+30			25-JUL-2011 5870.4 3679		
+ 32-41-00-720-802-01 (s)	FUNCTIONAL TEST OF THE ANTI-SKID SYSTEM						PKG		
32.730	PKG 23 REF: See Workcard	MOS HRS/MSC AFL	4500	+30			31-MAY-2017 7416.5 4869		
32-41-23-900-801-01	NORMAL/EMERGENCY BRAKE SELECTOR VALVE								
32.490	65670-1 2184 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
32-41-37-960-801-01 (s)	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - LH MLG BRAKE FILTER (L580GC)						PKG		
32.670	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
32-41-37-960-801-02 (s)	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - RH MLG BRAKE FILTER (R580GC)						PKG		
32.670	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			31-MAY-2017 7416.5 4869		
32-41-45-900-801-01	ANTI SKID AMPLIFIER								
32.620	6002614-3 JAN03-0588 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		18-MAR-2008 5462 3404		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-49-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER GENERATOR 9542653-1 3070 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-41-49-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER GENERATOR 9542653-1 3072 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-41-49-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER GENERATOR 9542653-1 3073 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-41-49-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL TACHOMETER GENERATOR 9542653-1 MAY75-342 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			27-SEP-2006 4554 2945		
32-41-57-350-801-01	RESTORATION LH MAIN LANDING GEAR (MLG) BRAKE SERVOVALVE (OVERHAUL) 9542732-2 2342D REF: See Workcard	MOS HRS/MSC AFL	300	+3%	TSI:0		18-SEP-1997 0 0	18-SEP-2022	18-JUN-2023
32-41-57-350-801-02	RESTORATION RH MAIN LANDING GEAR (MLG) BRAKE SERVOVALVE (OVERHAUL) 9542732-2 NOV79-1520D REF: See Workcard	MOS HRS/MSC AFL	300	+3%	TSI:0 TSI:0		03-MAR-2008 5456 3400	03-MAR-2033	03-DEC-2033
32-41-57-900-801-01	LH MAIN LANDING GEAR (MLG) BRAKE SERVOVALVE 9542732-2 2342D REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-57-900-801-02	RH MAIN LANDING GEAR (MLG) BRAKE SERVOVALVE 9542732-2 NOV79-1520D REF: See Workcard	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0			03-MAR-2008 5456 3400		
32-41-57-960-801-01 (s)	REPLACEMENT OF THE FILTER AND SEAL OF THE BRAKE SERVOVALVES - LH MLG BRAKE SERVOVALVE (57G1) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 31-MAY-2017 7416.5 4869		
32-41-57-960-801-02 (s)	REPLACEMENT OF THE FILTER AND SEAL OF THE BRAKE SERVOVALVES - RH MLG BRAKE SERVOVALVE (57G2) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 31-MAY-2017 7416.5 4869		
32-42-00-610-801-01	SERVICE PARKING BRAKE CONTROL CABLE F50B794001A1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
32-42-01-900-801-01	PARKING BRAKE SELECTOR VALVE A24522-1 FM349 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 32-42-05-720-801-01 (s)	FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			PKG 15-APR-2018 7651.3 5046		
32-42-05-780-801-01	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE REF: See Workcard	MOS HRS/MSC AFL	600	+30			15-APR-2018 7651.3 5046	8251.3	8281.3

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-42-05-900-801-01	PARKING BRAKE ACCUMULATOR								
32.530	60967-1 TRS-2664 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-JUL-2004 2981 2139		
32-42-13-900-801-01	PARKING BRAKE CONTROL CABLE								
32.590	F50B794001A1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-42-17-900-801-01	PARKING BRAKE BLINKER PRESSURE SWITCH								
32.540	90G198-1 425 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES								
32.260	REF: See Workcard	MOS HRS/MSC AFL	2				05-JUN-2018 7685.2 5077	05-AUG-2018	
32-44-00-780-801-01	CHECK PRESSURE OF MLG AND NLG WHEEL TIRES								
	REF: See Workcard	MOS HRS/MSC AFL	2				27-SEP-2018 7790.4 5152	27-NOV-2018	
+ 32-44-01-280-801-01	SPECIAL DETAILED INSPECTION LH NOSE LANDING GEAR (NLG) WHEEL								
32.560	9543426 JAN81-1941/JUL74-651 REF: See Workcard	MOS HRS/MSC AFL	500	+3%			25-JAN-2017 7340.7 4816	5316	5331
+ 32-44-01-280-801-02	SPECIAL DETAILED INSPECTION RH NOSE LANDING GEAR (NLG) WHEEL								
32.565	9543426 JAN06-3938 REF: See Workcard	MOS HRS/MSC AFL	500	+3%			25-JAN-2017 7340.7 4816	5316	5331

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-01-900-801-01	LH NOSE LANDING GEAR (NLG) WHEEL 9543426 JAN81-1941/JUL74-651 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			25-JAN-2017 7340.7 4816		
32-44-01-900-801-02	RH NOSE LANDING GEAR (NLG) WHEEL 9543426 JAN06-3938 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			25-JAN-2017 7340.7 4816		
32-44-05-900-801-01	LH NOSE LANDING GEAR (NLG) TIRE M08301 5281S199 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			25-JAN-2017 7340.7 4816		
32-44-05-900-801-02	RH NOSE LANDING GEAR (NLG) TIRE M08301 5281S171 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			25-JAN-2017 7340.7 4816		
32-44-09-280-801-01	SPECIAL DETAILED INSPECTION LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL 5003279-3 SEP96-1815 REF: See Workcard	MOS HRS/MSC AFL	400	+3%			05-DEC-2017 7581.7 4993	5393	5405
32-44-09-280-801-02	SPECIAL DETAILED INSPECTION LH INBOARD MAIN LANDING GEAR (MLG) WHEEL 5003279-3 NOV91-1594 REF: See Workcard	MOS HRS/MSC AFL	400	+3%			05-DEC-2017 7581.7 4993	5393	5405
32-44-09-280-801-03	SPECIAL DETAILED INSPECTION RH INBOARD MAIN LANDING GEAR (MLG) WHEEL 5003279-3 JAN98-1911 REF: See Workcard	MOS HRS/MSC AFL	400	+3%			05-DEC-2017 7581.7 4993	5393	5405

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-09-280-801-04	SPECIAL DETAILED INSPECTION RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL 5003279-3 MAR98-1932 REF: See Workcard	MOS HRS/MSC AFL	400	+3%			05-DEC-2017 7581.7 4993	5393	5405
32-44-09-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL 5003279-3 SEP96-1815 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:8 TSO:0 TSO:0		05-DEC-2017 7581.7 4993		
32-44-09-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) WHEEL 5003279-3 NOV91-1594 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:8 TSO:0 TSO:0		05-DEC-2017 7581.7 4993		
32-44-09-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) WHEEL 5003279-3 JAN98-1911 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		05-DEC-2017 7581.7 4993		
32-44-09-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) WHEEL 5003279-3 MAR98-1932 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		05-DEC-2017 7581.7 4993		
32-44-13-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) TIRE M15101-01 5262J120 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:18 TSN:0 TSN:0		05-DEC-2017 7581.7 4993		
32-44-13-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) TIRE M15101-01 5339J108 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:20 TSN:0 TSN:0		05-DEC-2017 7581.7 4993		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-13-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) TIRE M15101-01 7200J103 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			05-DEC-2017 7581.7 4993		
32-44-13-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) TIRE M15101-01 7198J107 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			05-DEC-2017 7581.7 4993		
32-44-17-900-801-01	LH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE 5003280-5 SEP76-22 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-MAR-2017 7347.9 4822		
32-44-17-900-801-02	LH INBOARD MAIN LANDING GEAR (MLG) BRAKE 5003280-5 FEB98-1610 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-APR-2017 7374 4841		
32-44-17-900-801-03	RH INBOARD MAIN LANDING GEAR (MLG) BRAKE 5003280-5 APR77-984 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-APR-2017 7374 4841		
32-44-17-900-801-04	RH OUTBOARD MAIN LANDING GEAR (MLG) BRAKE 5003280-5 SEP80-197 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-MAR-2017 7347.9 4822		
32-50-01-900-801-01	STEERING REPEATER BOX C24166-1 H0542 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-50-05-900-801-01	STEERING HYDRAULIC UNIT								
32.780	C24248-1 H0644 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-50-13-900-801-01	STEERING SERVO VALVE								
32.790	A25455 055 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-50-17-960-801-01 (s)	REPLACEMENT OF THE STEERING SYSTEM FILTERING ELEMENT - STEERING SYSTEM FILTER (511GH)								
32.760	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 26-MAY-2017 7416.5 4869		
32-61-37-900-801-01	LH MAIN LANDING GEAR (MLG) PROXIMITY SWITCH								
32.850	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-37-900-801-02	RH MAIN LANDING GEAR (MLG) PROXIMITY SWITCH								
32.850	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-37-900-801-03	LH MAIN LANDING GEAR (MLG) DRAG BRACE PROXIMITY SWITCH								
32.860	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-37-900-801-04	RH MAIN LANDING GEAR (MLG) DRAG BRACE PROXIMITY SWITCH								
32.860	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-37-900-801-05	LH MAIN LANDING GEAR (MLG) UPLOCK PROXIMITY SWITCH								
32.870	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-37-900-801-06	RH MAIN LANDING GEAR (MLG) UPLOCK PROXIMITY SWITCH								
32.870	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-37-900-801-07	LH MAIN LANDING GEAR (MLG) MAIN DOOR UPLOCK BOX PROXIMITY SWITCH								
32.880	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-37-900-801-08	RH MAIN LANDING GEAR (MLG) MAIN DOOR UPLOCK BOX PROXIMITY SWITCH								
32.890	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-37-900-801-09	LH MAIN LANDING GEAR (MLG) DOOR ACTUATOR PROXIMITY SWITCH								
32.880	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-37-900-801-10	RH MAIN LANDING GEAR (MLG) DOOR ACTUATOR PROXIMITY SWITCH								
32.890	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-41-900-801-01	NOSE LANDIGN GEAR (NLG) UPLOCK BOX SWITCH								
32.820	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-41-900-801-02	NOSE LANDING GEAR (NLG) PROXIMITY SWITCH								
32.820	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
32-61-41-900-801-03	NOSE LANDING GEAR (NLG) DRAG BRACE PROXIMITY SWITCH								
32.830	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
321102	LH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING								
32.020	D50493 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:152 TSN:3540			10-MAY-2010 5668.9 3540		
321104	LH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE								
32.040	D52369 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
321107	RH MAIN LANDING GEAR (MLG) SHOCK ABSORBER END-FITTING								
32.030	D50493 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:152 TSN:3540			10-MAY-2010 5668.9 3540		
321109	RH MAIN LANDING GEAR (MLG) ACTUATOR STRUT DASH-POT SLEEVE								
32.050	D52369 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
321117	LH REAR MAIN LANDING GEAR (MLG) PINTLE PIN								
32.060	D52554-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321118	RH REAR MAIN LANDING GEAR (MLG) PINTLE PIN D52554-1	MOS					18-SEP-1997		
32.070	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	H/T	TSN:0			0 0		
321119	LH MAIN LANDING GEAR (MLG) BARREL C23793-10	MOS		TSN:152 TSO:0	-234		10-MAY-2010		
32.020	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSO:0 TSN:3540 TSO:0			5668.9 3540		
321120	RH MAIN LANDING GEAR (MLG) BARREL C23794-10	MOS		TSN:152 TSO:0	-234		10-MAY-2010		
32.030	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSO:0 TSN:3540 TSO:0			5668.9 3540		
321121	LH MAIN LANDING GEAR (MLG) BRAKE RESTRICTOR VALVE A24506-5200	MOS					13-FEB-2007		
32.080	H0537 REF: GENERIC NO REF	HRS/MSC AFL	O/C				4780.3 3071		
321126	RH MAIN LANDING GEAR (MLG) BRAKE RESTRICTOR VALVE A24506-5200	MOS					18-SEP-1997		
32.080	H337 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
321141	LH MAIN LANDING GEAR (MLG) (ACTUATOR SIDE) SHAFT C23929-01	MOS					18-SEP-1997		
32.100	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
321146	RH MAIN LANDING GEAR (MLG) (ACTUATOR SIDE) SHAFT C23929-01	MOS					18-SEP-1997		
32.100	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321151	LH MAIN LANDING GEAR (MLG) (STRUCTURE SIDE) SHAFT								
32.110	C23321 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
321156	RH MAIN LANDING GEAR (MLG) (STRUCTURE SIDE) SHAFT								
32.110	C23321 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
322104	NOSE LANDING GEAR BARREL								
32.190	C23788-10 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:152 TSO:0 TSO:0 TSN:3540 TSO:0	-234		10-MAY-2010 5668.9 3540		
322112	NOSE LANDING GEAR TELESCOPIC STRUT YOKE ASSEMBLY								
32.210	GA62269 B16-624 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:0 TSO:0 TSO:0	-234		10-MAY-2010 5668.9 3540		
322131	NOSE LANDING GEAR RETRACTION STRUT RIGHT BALL-JOINT BEARING								
32.250	BRS35TAGSP5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
322136	NOSE LANDING GEAR RETRACTION STRUT (STRUCTURE SIDE) SHAFT								
32.220	C23807 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
322141	NOSE LANDING GEAR SWIVEL COUPLING								
32.230	C24266 U384 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-JAN-2002 1666 1420		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323106	NOSE LANDING GEAR "UP" RESTRICTOR VALVE A24508-5150	MOS					18-SEP-1997		
32.340	H1728 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323111	NOSE LANDING GEAR RESTRICTOR VALVE A24508-A5060	MOS		TSN:0			26-DEC-2002		
32.080	H1992 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			1862.9 1540		
323121	LANDING GEAR CIRCUIT SHUTTLE VALVE A25493-1	MOS					18-SEP-1997		
32.360	722 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323126	LANDING GEAR DOORS CIRCUIT SHUTTLE VALVE A25493-1	MOS					18-SEP-1997		
32.360	723 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323146	LANDING GEAR SOLENOID DIRECTIONAL VALVE A24520-2	MOS					18-SEP-1997		
32.380	FM340 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323151	LANDING GEAR DOORS SOLENOID DIRECTIONAL VALVE A24521-102	MOS					18-SEP-1997		
32.380	FM1081 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323158	LH MAIN LANDING GEAR (MLG) DOOR MANUAL UNLOCKING CONTROL PIN F50B793600180	MOS					18-SEP-1997		
32.330	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323163	RH MAIN LANDING GEAR (MLG) DOOR MANUAL UNLOCKING CONTROL PIN F50B793600180	MOS					18-SEP-1997		
32.330	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323166	LH MAIN LANDING GEAR (MLG) DOOR RESTRICTOR VALVE A5150-24506	MOS					13-FEB-2007		
32.390	H0543 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:4780.3			4780.3 3071		
323171	RH MAIN LANDING GEAR (MLG) DOOR RESTRICTOR VALVE A5150-24506	MOS					13-FEB-2007		
32.400	H0542 REF: GENERIC NO REF	HRS/MSC AFL	O/C				4781 3071		
323176	LH MAIN LANDING GEAR (MLG) DOWN RESTRICTOR VALVE A24508-5120	MOS					26-DEC-2002		
32.390	H2363 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			1862.9 1540		
323181	RH MAIN LANDING GEAR (MLG) DOWN RESTRICTOR VALVE A24508-5120	MOS					26-DEC-2002		
32.400	H2374 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			1862.9 1540		
323186	LH MAIN LANDING GEAR (MLG) UP RESTRICTOR VALVE A24510-5220	MOS					18-SEP-1997		
32.390	H167 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323191	RH MAIN LANDING GEAR (MLG) UP RESTRICTOR VALVE A24510-5220	MOS					18-SEP-1997		
32.400	H168 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323196	MAIN LANDING GEAR SUPPLY CHECK VALVE								
32.410	A24516 3682 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
323201	MAIN LANDING GEAR RETURN CHECK VALVE								
32.410	A24516 3604 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
323206	GEAR DOOR ELECTRO DISTRIBUTOR CIRCUIT RESTRICTOR VALVE								
32.410	A5040-24510 H0330 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			12-FEB-1999 525 473		
323221	NOSE LANDING GEAR/DOOR MANUAL/EMERGENCY CONTROL CABLE								
32.430	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324141	NORMAL/EMERGENCY BRAKE DISTRIBUTOR								
32.480	57530-2 298 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324151	NORMAL/BRAKE DISTRIBUTOR VALVE								
32.490	65660 380 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324161	LH BRAKE CIRCUIT SHUTTLE VALVE								
32.500	CN100 358 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324166	RH BRAKE CIRCUIT SHUTTLE VALVE								
32.500	CN100 359 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324171	CENTER PARKING BRAKE CIRCUIT OVERPRESSURE VALVE								
32.520	A24519001 FM1148 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324176	PARKING BRAKE ACCUMULATOR SUPPLY CHECK VALVE								
32.520	A24515 FM02488 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-AUG-1998 295 296		
324181	EMERGENCY BRAKE DISTRIBUTOR CHECK VALVE								
32.510	A24515 FM2368 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324186	LH BRAKE CIRCUIT SWIVEL CONNECTOR								
32.515	A100-24660 H448 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324191	RH BRAKE CIRCUIT SWIVEL CONNECTOR								
32.515	A101-24660 H0473 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324201	PARKING BRAKE ACCUMULATOR GAUGE								
32.530	18040100 36953C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324211	PARKING BRAKE ACCUMULATOR FILLER VALVE								
32.530	MS28889-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324216	LH PARKING BRAKE PRESSURE SWITCH								
32.540	7G1090 063 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324221	RH PARKING BRAKE PRESSURE SWITCH								
32.540	7G1090 064 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324231	NORMAL BRAKING DISTRIBUTOR RETURN CIRCUIT CHECK VALVE								
32.510	A24516 FM3605 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324236	PARKING BRAKE CONTROL HANDLE								
32.550	4183907 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324341	NO. 1 DRIVING CAP								
32.650	6002597 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324346	NO. 2 DRIVING CAP								
32.650	6002597 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324351	NO. 3 DRIVING CAP 6002597	MOS					18-SEP-1997		
32.660	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
324356	NO. 4 DRIVING CAP 6002597	MOS					18-SEP-1997		
32.660	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
324361	LH ANTI-SKID PRESSURE SWITCH 7G1089	MOS					24-AUG-2006		
32.610	646 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			4453 2908		
324366	RH ANTI-SKID PRESSURE SWITCH 7G1089	MOS					26-FEB-2008		
32.610	771 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			5456 3400		
324371	LH BRAKE CIRCUIT FILTER 285697	MOS					25-JUL-2011		
32.670	H2161 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSR:0 TSN:5870.4 TSR:0 TSR:0			5870.4 3679		
324381	RH BRAKE CIRCUIT FILTER 285697	MOS					25-JUL-2011		
32.670	H2160 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSR:0 TSN:5870.4 TSR:0 TSR:0			5870.4 3679		
324391	LH BRAKE SERVO VALVE RETURN CIRCUIT CHECK VALVE A24516	MOS					18-SEP-1997		
32.680	FM3705 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324396	RH BRAKE SERVO VALVE RETURN CIRCUIT CHECK VALVE								
32.680	A24516 FM3706 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324401	LH BRAKE SERVO VALVE SUPPLY CIRCUIT CHECK VALVE								
32.690	A5140-24508 H1755 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
324406	RH BRAKE SERVO VALVE SUPPLY CIRCUIT CHECK VALVE								
32.690	A5140-24508 H1754 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
325106	STEERING DIRECTIONAL VALVE								
32.750	65670-1 2185 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
325111	STEERING CONTROL UNIT								
32.750	287837-1 H0966 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
325116	STEERING FILTER								
32.760	285697 H2154 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
325126	STEERING AMPLIFIER								
32.770	C24242 H455 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
326006	L/G CONTROL PRINTED CIRCUIT BOARD								
32.800	CI823A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
326011	NA-BLANK PRINTED CIRCUIT								
32.800	CI846A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
326026	LH MAIN LANDING GEAR (MLG) LEG DUAL PROXIMITY SWITCH								
32.840	C23844-11 HO758 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			14-FEB-2014 6601.2 4252		
326031	RH MAIN LANDING GEAR (MLG) LEG DUAL PROXIMITY SWITCH								
32.840	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
326076	NOSE GEAR LEG DUAL PROXIMITY SWITCH								
32.830	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
326101	LANDING GEAR UP IAS INDICATOR SWITCH								
32.810	4219G010201 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
CHAPTER 33 LIGHTS									
33-20-00-200-801-01	INSPECTION OF "ALC" LIGHTING TUBES								
33.230	REF: See Workcard	MOS HRS/MSC AFL	N/A				05-AUG-2003 2285 1800		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-40-01-900-801-01	LH WING NAVIGATION LIGHT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
33-40-01-900-801-02	RH WING NAVIGATION LIGHT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
33-40-09-900-802-01 33.140	UPPER ANTI-COLLISION LIGHT 30-1136-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
33-40-33-900-802-01	LH UPPER LOGO LIGHT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
33-40-33-900-802-02	RH UPPER LOGO LIGHT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
33-40-33-900-802-03	LH LOWER LOGO LIGHT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
33-40-33-900-802-04	RH LOWER LOGO LIGHT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-40-33-960-801-01	REPLACE LH UPPER LOGO LIGHT LAMP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
33-40-33-960-801-02	REPLACE RH UPPER LOGO LIGHT LAMP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
33-40-33-960-801-03	REPLACE LH LOWER LOGO LIGHT LAMP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
33-40-33-960-801-04	REPLACE RH LOWER LOGO LIGHT LAMP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
33-40-37-900-801-01	LH LANDING LIGHT 4160818 75033 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
33-40-37-900-801-02	RH LANDING LIGHT 4160818 75019 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
33-40-41-900-801-01	TAXI LIGHT 4060622 97045 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-40-41-900-802-01	PROXIMITY TAXI LIGHT CIRCUIT PROXIMITY SENSOR PROXIMITY SWITCH								
33.170	8-240-02 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 33-50-00-710-804-01 (s)	OPERATIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM						PKG		
	PKG 23 REF: AMM 33-50-00-710-804	MOS HRS/MSC AFL	4500				18-SEP-1997 0 0		
+ 33-50-00-720-801-01	FUNCTIONAL TEST NO. 1 (113L) EMERGENCY (EPS 1) POWER SUPPLY								
33.100	D734-02-001 2202/08-2004 REF: AMM 33-50-00-720-801	MOS HRS/MSC AFL	O/C				11-OCT-2017 7500.2 4933		
33-50-00-720-801-02	FUNCTIONAL TEST NO. 2 (114L1) EMERGENCY (EPS 2) POWER SUPPLY								
33.110	D734-02-001 286 REF: AMM 33-50-00-720-801	MOS HRS/MSC AFL	O/C				11-OCT-2017 7500.2 4933		
33-50-00-720-801-03	FUNCTIONAL TEST NO. 3 (114L2) EMERGENCY (EPS 3) POWER SUPPLY								
33.120	D734-02-001 304 REF: AMM 33-50-00-720-801	MOS HRS/MSC AFL	O/C				11-OCT-2017 7500.2 4933		
33-50-33-610-801-01	SERVICING NO. 1 (113L) EMERGENCY (EPS 1) POWER SUPPLY								
33.100	D734-02-001 2202/08-2004 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			11-OCT-2017 7500.2 4933	11-OCT-2018	22-OCT-2018
33-50-33-610-801-02	SERVICING NO. 2 (114L1) EMERGENCY (EPS 2) POWER SUPPLY								
33.110	D734-02-001 286 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			11-OCT-2017 7500.2 4933	11-OCT-2018	22-OCT-2018

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-33-610-801-03	SERVICING NO. 3 (114L2) EMERGENCY (EPS 3) POWER SUPPLY								
33.120	D734-02-001 304 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			11-OCT-2017 7500.2 4933	11-OCT-2018	22-OCT-2018
33-50-33-900-801-01	NO. 1 (113L) EMERGENCY (EPS 1) POWER SUPPLY								
33.100	D734-02-001 2202/08-2004 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		11-OCT-2017 7500.2 4933		
33-50-33-900-801-02	NO. 2 (114L1) EMERGENCY (EPS 2) POWER SUPPLY								
33.110	D734-02-001 286 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		11-OCT-2017 7500.2 4933		
33-50-33-900-801-03	NO. 3 (114L2) EMERGENCY (EPS 3) POWER SUPPLY								
33.120	D734-02-001 304 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		11-OCT-2017 7500.2 4933		
33-50-37-960-802-01	DISCARD NO. 1 (113L) EMERGENCY (EPS 1) POWER SUPPLY BATTERY PACK								
33.100	D734-02-001 2202/08-2004 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-SEP-2016 7240 4743		
33-50-37-960-802-02	DISCARD NO. 2 (114L1) EMERGENCY (EPS 2) POWER SUPPLY BATTERY PACK								
33.110	D734-02-001 286 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2016		
33-50-37-960-802-03	DISCARD NO. 3 (114L2) EMERGENCY (EPS 3) POWER SUPPLY BATTERY PACK								
33.120	D734-02-001 304 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-OCT-2017 7500.2 4933		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331101	FLIGHT COMPARTMENT LEFT READING LIGHT 10-0027-1	MOS					18-SEP-1997		
33.010	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
331106	FLIGHT COMPARTMENT RIGHT READING LIGHT 10-0027-1	MOS					18-SEP-1997		
33.020	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
331111	LH SPOT LIGHT 4X650	MOS					18-SEP-1997		
33.010	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
331113	LOWER LIGHT ASSEMBLY 10-50B	MOS					18-SEP-1997		
33.010	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
331116	RH SPOT LIGHT 4X650	MOS					18-SEP-1997		
33.020	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
331118	UPPER LIGHT ASSEMBLY 10-50T	MOS					18-SEP-1997		
33.020	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
331121	GLARE SHIELD LIGHTING POWER SUPPLY 17-3019-1	MOS					18-SEP-1997		
33.030	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331126	PILOT LIGHTING UNIT POWER SUPPLY								
33.040	24-54 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
331131	COPILOT LIGHTING UNIT POWER SUPPLY								
33.040	24-54 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
331136	LH CONSOLE UNIT POWER SUPPLY								
33.050	24-54 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
331141	RH CONSOLE UNIT POWER SUPPLY								
33.050	24-54 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
331146	OVERHEAD PANEL POWER SUPPLY								
33.030	24-014 381 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
331151	LH SEGMENTS UNIT POWER SUPPLY								
33.060	24-52-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
331156	RH SEGMENTS UNIT POWER SUPPLY								
33.060	24-52-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332101	LH EMERGENCY EXIT LIGHT								
33.080	30-1358-17 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
332106	RH EMERGENCY EXIT LIGHT								
33.080	30-1358-17 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
334106	LOWER ANTI-COLLISION LIGHT								
33.140	30-1136-9 3016 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
334116	UPPER ANTI-COLLISION LIGHTS UNIT POWER SUPPLY								
33.070	60-2667-3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
334121	LOWER ANTI-COLLISION LIGHTS UNIT POWER SUPPLY								
33.070	60-2667-3 3161 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:6 TSO:0 TSO:0			08-DEC-2015 7015 4577		
334123	PULSELITE, LANDING LIGHT								
33.180	2400-25-4-4 K01336 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
334146	LH WING STROBE LIGHT								
33.180	39-28-21 981 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334151	RIGHT WING STROBE LIGHT								
33.180	39-28-21 982 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
334156	LH WING STROBE UNIT POWER SUPPLY								
33.190	39-42-1 873 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
334161	RH WING STROBE UNIT POWER SUPPLY								
33.190	39-42-1 879 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
334171	TAIL NAVIGATION LIGHT								
33.200	39-54-21 1316 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-SEP-2006 4512 2935		
335121	LH EVACUATION LIGHT								
33.090	30-0424-9 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
335126	RH EVACUATION LIGHT								
33.090	30-0424-9 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
335301	LEFT EMERGENCY LIGHTING UNIT BATTERY PACK								
	NCS734-01-030 0521 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-JAN-2014 6581.6 4235		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335303	RIGHT EMERGENCY LIGHTING UNIT BATTERY PACK NCS734-01-030 0193 REF:	MOS HRS/MSC AFL	O/C	TSN:24 TSN:610.5 TSN:484			16-APR-2014 6627.3 4274		
335306	FRONT EMERGENCY LIGHTING UNIT BATTERY PACK NCS734-01-030 1871 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-OCT-2017 7500.2 4933		
338001	830LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338002	831LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338003	832LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338004	833LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338005	834LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
338006	835LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338007	837LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338008	838LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338009	839LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338010	840LP CABIN LIGHTING POWER SUPPLY AL-2004 27308 REF:	MOS HRS/MSC AFL	O/C					26-JAN-2005 3338 2332	
338011	841LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338012	842LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
338013	843LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338014	844LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338015	R840LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338016	R841LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338017	R842LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338018	L840LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338019	L841LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
338020	L842LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338021	R843LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338022	R844LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338023	R845LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338024	R846LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338025	L843LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338026	L844LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
338027	L845LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338028	L846LP CABIN LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338029	890LP GALLEY LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338030	897LP GALLEY LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338031	903LP LAVATORY LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338032	904LP LAVATORY LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338033	917LP LAVATORY LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
338034	918LP LAVATORY LIGHTING POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
338035	731LP ENTRANCE LIGHT POWER SUPPLY AL-2004 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
CHAPTER 34 NAVIGATION									
34-01-00-720-801-01 (s)	FUNCTIONAL TEST OF THE EFIS SYSTEM						PKG		
34.640	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			11-AUG-2008 5539.2 3454		
34-01-13-900-801-01	LH PRIMARY FLIGHT DISPLAY 622-9978-122 3GVJ REF: See Workcard	MOS HRS/MSC AFL	O/C				09-NOV-2017 7542.6		
34-01-13-900-801-02	RH PRIMARY FLIGHT DISPLAY 622-9978-122 1515 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-JUN-2010 5679.9 3551		
34-01-13-900-801-03	LH MULTIFUNCTION DISPLAY 622-9978-122 1361 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874		
34-01-13-900-801-04	RH MULTIFUNCTION DISPLAY 622-9978-122 1429 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-01-25-710-801-07 (s)	OPERATIONAL TEST OF THE EFIS FANS						PKG		
34.630	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			26-MAY-2017 7416.5 4869		
+ 34-10-00-700-881-01	TEST PILOT AIR DATA (ADC) DISPLAY UNIT (FAR 91.411)								
34.510 MANDATORY	822-1036-467 1FBM REF: GENERIC NO REF	MOS HRS/MSC AFL	24				07-MAR-2017	07-MAR-2019	
+ 34-10-00-700-881-02	TEST COPILOT AIR DATA (ADC) DISPLAY UNIT (FAR 91.411)								
34.520 MANDATORY	822-1036-467 4633 REF: GENERIC NO REF	MOS HRS/MSC AFL	24				07-MAR-2017	07-MAR-2019	
+ 34-10-00-700-881-03	TEST STAND BY ALTIMETER (FAR 91.411)								
34.530 MANDATORY	64141-530-1 3648 REF: GENERIC NO REF	MOS HRS/MSC AFL	24				07-MAR-2017	07-MAR-2019	
34-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE AIR DATA SYSTEM						PKG		
34.105 RVSM	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
34-10-00-720-802-01	FUNCTIONAL TEST PILOT AIR DATA (ADC) DISPLAY UNIT								
34.510	822-1036-467 1FBM REF: See Workcard	MOS HRS/MSC AFL	24	+3%			07-MAR-2017	07-MAR-2019	29-MAR-2019
34-10-00-720-802-02	FUNCTIONAL TEST COPILOT AIR DATA (ADC) DISPLAY UNIT								
34.520	822-1036-467 4633 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			07-MAR-2017	07-MAR-2019	29-MAR-2019

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-10-00-720-802-03	FUNCTIONAL TEST STAND BY ALTIMETER 64141-530-1 3648 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			07-MAR-2017	07-MAR-2019	29-MAR-2019
34.530									
34-10-00-720-802-04	FUNCTIONAL TEST STANDBY MACH-AIRSPEED INDICATOR 64032-229-1 1607 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			10-MAR-2017 7343.9 4822	10-MAR-2019	01-APR-2019
34.535									
+ 34-10-01-700-881-01	TEST STANDBY AIR DATA UNIT (FAR 91.411) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
34-10-01-900-801-01	REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE AIR TEMPERATURE PROBE (185F) 102AU1CK A12978 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:120 TSN:4793 TSN:3048		23-MAR-2007 4852 3100		
34.100									
34-10-11-720-801-01 (s)	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - LH AOA SENSOR (52F1) PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
34-10-11-720-801-02 (s)	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - RH AOA SENSOR (52F2) PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
34-10-11-900-801-01	LH ANGLE-OF-ATTACK (AOA) SENSOR 2551A11P GST02065 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
30.200									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-10-11-900-801-02	RH ANGLE-OF-ATTACK (AOA) SENSOR 2551A12P 221-22 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-JUL-2003 2220 1756		
34-11-00-680-801-01 (s)	DRAINING OF THE TOTAL / STATIC PRESSURE SYSTEM PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
+ 34-11-00-790-801-01	LEAK TEST OF THE PILOT STATIC AIR PRESSURE SYSTEM REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2013 6435.4 4113		
34-11-00-790-801-02	LEAK TEST PILOT TOTAL AIR PRESSURE SYSTEM REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2013 6435.4 4113		
34-11-00-790-801-03	LEAK TEST COPILOT STATIC AIR PRESSURE SYSTEM REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2013 6435.4 4113		
34-11-00-790-801-04	LEAK TEST COPILOT TOTAL AIR PRESSURE SYSTEM REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2013 6435.4 4113		
34-11-00-790-801-05	LEAK TEST STAND-BY STATIC AIR PRESSURE SYSTEM REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2013 6435.4 4113		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-01-200-801-01	CHECK LH TOTAL PRESSURE PROBE DRAIN HOLE FOR CLOGGING								
		MOS	12	+1m			15-APR-2018	15-APR-2019	15-MAY-2019
		HRS/MSC	300	+30			7651.3	7951.3	7981.3
	REF: See Workcard	AFL					5046		
34-11-01-200-801-02	CHECK RH TOTAL PRESSURE PROBE DRAIN HOLE FOR CLOGGING								
		MOS	12	+1m			15-APR-2018	15-APR-2019	15-MAY-2019
		HRS/MSC	300	+30			7651.3	7951.3	7981.3
	REF: See Workcard	AFL					5046		
34-11-01-900-801-01	LH PITOT PROBE								
34.080	50520	MOS					18-SEP-1997		
	1598	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
34-11-01-900-801-02	RH PITOT PROBE								
34.080	50520	MOS					18-SEP-1997		
	1597	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
34-11-05-900-801-01	LH STATIC PRESSURE PROBE								
34.090	F50B220130D1	MOS					14-JUL-2006		
	1302	HRS/MSC	O/C	TSN:0			4400		
	REF: See Workcard	AFL		TSN:0			2874		
34-11-05-900-801-02	RH STATIC PRESSURE PROBE								
34.090	F50B220130D1	MOS					14-JUL-2006		
	1300	HRS/MSC	O/C	TSN:0			4400		
	REF: See Workcard	AFL		TSN:0			2874		
+ 34-14-01-710-802-01	OPERATIONAL TEST PILOT AIR DATA (ADC) DISPLAY UNIT								
34.510	822-1036-467	MOS					10-MAR-2017		
	1FBM	HRS/MSC	O/C				7343.9		
	REF: See Workcard	AFL					4822		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-14-01-710-803-01	OPERATIONAL TEST COPILOT AIR DATA (ADC) DISPLAY UNIT								
34.520	822-1036-467 4633 REF: See Workcard	MOS HRS/MSC AFL	O/C				10-MAR-2017 7343.9 4822		
34-14-01-900-801-01	PILOT AIR DATA (ADC) DISPLAY UNIT								
34.510	822-1036-467 1FBM REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			09-AUG-2012 6150.5 3901		
34-14-01-900-801-02	COPILOT AIR DATA (ADC) DISPLAY UNIT								
34.520	822-1036-467 4633 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-AUG-2011 5895 3706		
34-15-00-720-801-01	FUNCTIONAL TEST OF THE ALTITUDE ALERTER SYSTEM								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
34-16-09-900-801-01	STAND BY ALTIMETER								
34.530	64141-530-1 3648 REF: See Workcard	MOS HRS/MSC AFL	O/C				03-OCT-2007 5218.2 3285		
34-21-01-900-801-01	NO. 1 INERTIAL REFERENCE (IRU 1) UNIT								
34.900	HG2001GC03 94090406 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-JUN-2005 3662 2490		
34-21-01-900-801-02	NO. 2 INERTIAL REFERENCE (IRU2) UNIT								
34.900	HG2001GC03 99011589 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			17-JUL-2009 5628 3514		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21-01-900-801-03	NO. 3 INERTIAL REFERENCE (IRU 3) UNIT NOT INSTALLED REMOVED REF: See Workcard	MOS HRS/MSC AFL	O/C						
34.900									
34-21-13-100-801-01 (s)	CLEANING/REPLACEMENT OF THE IRU 1 FAN FILTER PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000				PKG 15-APR-2018 7651.3 5046		
34.975									
34-21-13-100-801-02 (s)	CLEANING/REPLACEMENT OF THE IRU 2 FAN FILTER PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000				PKG 15-APR-2018 7651.3 5046		
34.975									
+ 34-21-13-100-801-03 (s)	CLEANING/REPLACEMENT OF THE IRU 3 FAN FILTER PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3000				PKG 18-SEP-1997 0 0		
34-22-00-710-801-01	OPERATIONAL TEST OF THE ATTITUDE AND HEADING REFERENCE SYSTEM (AHRS) REF: See Workcard	MOS HRS/MSC AFL	2000				15-APR-2018 7651.3 5046	9651.3	
34.980									
+ 34-23-00-720-801-01	FUNCTIONAL TEST OF THE SECONDARY FLIGHT DISPLAY (SFD) AND AIR DATA UNIT (ADU) - ADU (29F) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
34-23-00-720-801-02	FUNCTIONAL TEST OF THE SECONDARY FLIGHT DISPLAY (SFD) AND AIR DATA UNIT (ADU) - SFD (4F1) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-23-01-900-801-01	SECONDARY FLIGHT DISPLAY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
34-23-05-900-801-01	STANDBY AIR DATA UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
34-41-01-900-801-01 34.380	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA 622-8441-003 930 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-MAY-2018 7674.3 5065		
34-41-05-900-801-01 34.750	WEATHER RADAR ANTENNA PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
34-42-00-710-801-01	OPERATIONAL TEST NO. 1 RADIO ALTIMETER SYSTEM REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
34-42-00-710-801-02	OPERATIONAL TEST NO. 2 RADIO ALTIMETER SYSTEM REF: See Workcard	MOS HRS/MSC AFL	N/A				18-SEP-1997 0 0		
34-42-01-900-801-01 34.010	NO. 1 RADIO ALTIMETER RECEIVER/TRANSMITTER 622-2855-011 10837 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-42-01-900-801-02	NO. 2 RADIO ALTIMETER RECEIVER/TRANSMITTER								
34.015	622-2855-011 11553 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			21-JUL-1998 266 263		
34-44-01-900-801-01	TCAS TRANSCEIVER								
34.400	822-3075-001 4RK45 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-MAR-2016 7065.7 4612		
+ 34-51-01-820-801-01	CALIBRATION NO. 1 VOR/ILS/MKR RECEIVER								
34.700	622-7194-201 5053 REF: See Workcard	MOS HRS/MSC AFL	25	+3%			15-SEP-2009 5644.4 3525	15-OCT-2011	07-NOV-2011
+ 34-51-01-820-801-02	CALIBRATION NO. 2 VOR/ILS/MKR RECEIVER								
34.700	622-7194-201 3601 REF: See Workcard	MOS HRS/MSC AFL	25	+3%			06-OCT-2005 3891 2599	06-NOV-2007	28-NOV-2007
34-51-05-900-801-01	LH VOR/LOC ANTENNA								
34.720	DMN4-45-3 6461 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
34-51-05-900-801-02	RH VOR/LOC ANTENNA								
34.720	DMN4-45-3 6465 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 34-54-00-700-881-01	TEST NO. 1 ATC TRANSPONDER (FAR 91.413)								
34.820 MANDATORY	622-92100-501 7691 REF: GENERIC NO REF	MOS HRS/MSC AFL	24				07-MAR-2017	07-MAR-2019	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-54-00-700-881-02	TEST NO. 2 ATC TRANSPONDER (FAR 91.413)								
34.820	622-92100-501	MOS	24				07-MAR-2017	07-MAR-2019	
MANDATORY	5467 REF: GENERIC NO REF	HRS/MSC AFL							
34-54-00-720-802-01	FUNCTIONAL TEST NO. 1 ATC TRANSPONDER								
34.820	622-92100-501	MOS	24	+3%			07-MAR-2017	07-MAR-2019	29-MAR-2019
	7691 REF: See Workcard	HRS/MSC AFL							
34-54-00-720-802-02	FUNCTIONAL TEST NO. 2 ATC TRANSPONDER								
34.820	622-92100-501	MOS	24	+3%			07-MAR-2017	07-MAR-2019	29-MAR-2019
	5467 REF: See Workcard	HRS/MSC AFL							
34-58-01-710-881-01	CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)								
34.725		DAYS					11-AUG-2008		
	REF: GENERIC NO REF	HRS/MSC AFL	A/R				5539.2 3454		
34-61-01-900-801-01	NO. 1 FMS DISPLAY UNIT								
	PN	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
34-61-01-900-801-02	NO. 2 FMS DISPLAY UNIT								
	PN	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
341008	NO.1 ANALOGIC/DIGITAL CONVERTER								
34.990	622-7209-002	MOS					18-SEP-1997		
	1843	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341009	NO.2 ANALOGIC/DIGITAL CONVERTER								
34.020	622-7209-002 2141 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			21-JUL-1998 266 263		
341011	NO. 1 RADIO ALTIMETER INDICATOR								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
341014	NO. 2 RADIO ALTIMETER INDICATOR								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
341015	NO.1 RADIO ALTIMETER RECEIVER ANTENNA								
34.030	S67-2002-13 759 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
341016	NO.2 RADIO ALTIMETER RECEIVER ANTENNA								
34.030	S67-2002-13 971 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			21-JUL-1998 266 263		
341017	NO.1 RADIO ALTIMETER TRANSMITTER ANTENNA								
34.040	S67-2002-13 760 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
341018	NO.2 RADIO ALTIMETER TRANSMITTER ANTENNA								
34.040	S67-2002-13 970 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			21-JUL-1998 266 263		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341021	RADIO ALTIMETER ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
341041	STANDBY MACH-AIRSPEED INDICATOR 64032-229-1 1607 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
341191	STATIC PRESSURE SELECTOR VALVE 919ZEQ4 1140 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
341193	DUAL CUT-OFF VALVE 914A01 733 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
341196	ALTITUDE ALERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
341236	PILOT AIR DATA COMPUTER REFERENCE PANEL 822-0326-002 997 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-DEC-1997 28 14		
341241	COPILOT AIR DATA COMPUTER REFERENCE PANEL 822-0326-002 948 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342001	STAND-BY COMPASS								
34.340	WL1001KCA1 AJ2671096 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
342037	STAND-BY HORIZON								
34.370	501-1197-25 6227 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-MAR-2017 7348.1 4823		
342041	NO. 1 HEADING REFERENCE SYSTEM (HDG 1) FLUX VALVE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342051	NO. 2 HEADING REFERENCE SYSTEM (HDG 2) FLUX VALVE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342061	LH COMPASS COUPLER								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342066	RH COMPASS COUPLER								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342301	PILOT UPPER ELECTRONIC ATITUDE DIRECTOR INDICATOR (EADI) DISPLAY								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342311	PILOT LOWER ELECTRONIC HORIZONTAL SITUATION INDICATOR (EHSI) DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342321	PILOT DISPLAY (DPU) PROCESSOR UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342331	PILOT DISPLAY (DCP) CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342341	COPILOT UPPER ELECTRONIC ATITUDE DIRECTOR INDICATOR (EADI) DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342351	COPILOT LOWER ELECTRONIC HORIZONTAL SITUATION INDICATOR (EHSI) DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342361	COPILOT DISPLAY PROCESSOR (DPU) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342371	COPILOT DISPLAY CONTROL (DCP) PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342381	MULTIFUNCTION CATHODE RAY TUBE (MFD) DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342391	MULTIFUNCTION PROCESSOR (MPU) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342401	COURSE HEADING PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342411	WEATHER RADAR CONTROL (WXP) PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342451	PILOT REVERSION SWITCH (RSP) PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342461	COPILOT REVERSION SWITCH (RSP) PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342501	PILOT F/D INDIC./SITUATION INDIC. (EADI/EHSI) BLOWER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342506	COPILOT F/D INDIC./SITUATION INDIC. (EADI/EHSI) BLOWER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342511	MULTIFUNCTION CATHODE RAY TUBE DISPLAY (MFB) BLOWER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342516	PILOT DISPLAY PROCESSOR UNIT (DPU) BLOWER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342521	COPILOT DISPLAY PROCESSOR UNIT (DPU) BLOWER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342526	MULTIFUNCTION DISPLAY PROCESSOR UNIT (MPU) BLOWER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342601	LONGITUDINAL ACCELEROMETER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
342901	LH CONFIGURATION (CSU) MODULE 822-0049-002 1345 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
34.170									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342902	RH CONFIGURATION (CSU) MODULE								
34.170	822-0049-002 1360 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
342905	INTERGRATED AVIONICS SYSTEM PROCESSOR								
34.180	822-1407-001 280FN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874		
342911	LH UPPER INPUT/OUTPUT CONCENTRATOR								
34.190	622-9814-634 2196 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-APR-2007 4899 3115		
342912	LH LOWER INPUT/OUTPUT CONCENTRATOR								
34.190	622-9814-634 2195 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-APR-2007 4899 3115		
342913	RH UPPER INPUT/OUTPUT CONCENTRATOR								
34.200	622-9814-634 2197 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-APR-2007 4899 3115		
342914	RH LOWER INPUT/OUTPUT CONCENTRATOR								
34.200	622-9814-634 DYRJ REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-APR-2007 4899 3115		
342921	EFIS INPUT/OUTPUT CONCENTRATOR								
34.210	822-0320-011 241 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342945	PILOT REVERSIONARY CONTROL								
34.250	822-0273-002 272 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
342946	COPILOT REVERSIONARY CONTROL								
34.250	822-0273-002 289 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				22-DEC-1997 28 14		
342947	PILOT DISPLAY CONTROL								
34.260	822-0321-008 1043 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874		
342948	COPILOT DISPLAY CONTROL								
34.260	822-0321-008 1044 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874		
343001	NO. 1 VOR/ILS/MKR RECEIVER								
34.700	622-7194-201 5053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-SEP-2009 5644.4 3525		
343011	NO. 2 VOR/ILS/MKR RECEIVER								
34.700	622-7194-201 3601 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:38			22-DEC-1997 28 14		
343021	VOR/ILS/MKR1/DME1/VHF1 CONTROL								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
343023	VOR/ILS/MKR2/DME2/ATC1/ATC2 CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
343041 34.730	MARKER ANTENNA DMN27-1A 9051 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
343051 34.730	GLIDESLOPE ANTENNA DMN25-2 4198 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
344001	RADAR TRANSCEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
344003 34.390	WEATHER RADAR CONTROL 622-9932-002 744 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
344011	RADAR INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
344067	WEATHER RADAR #2 CONTROL 622-9932-002 636 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344076	LOWER TCAS ANTENNA								
34.410	622-8973-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
344081	UPPER TCAS ANTENNA								
34.410	622-8973-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
344086	NO.1 ATC UPPER ANTENNA								
34.430	DMNI50-2-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
344087	NO.2 ATC UPPER ANTENNA								
34.430	DMNI50-2-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
344088	NO.1 ATC LOWER ANTENNA								
34.440	DMNI50-2-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
344089	NO.2 ATC LOWER ANTENNA								
34.440	DMNI50-2-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
345066	BEARNG DISTANCE INDICATOR								
	520-3020-005 16487 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345086	NO. 1 ADF RECEIVER 622-7382-101 4338 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-JAN-2006 4042 2678		
345096	NO. 2 ADF RECEIVER 622-7382-101 4337 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-JAN-2006 4042 2678		
345106	ADF1/ADF2 CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
345126	NO. 1 ADF ANTENNA 622-7383-001 2857 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
345136	NO. 2 ADF ANTENNA 622-7383-001 2858 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
345181	NO. 1 ATC TRANSPONDER 622-92100-501 7691 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-MAR-2017		
345196	NO. 1 ATC ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345206	NO. 2 ATC TRANSPONDER 622-92100-501 5467 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-MAR-2017		
345221	NO. 2 ATC ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
345231	NO. 1 DME TRANSCEIVER 622-7309-101 3306 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-SEP-1998 374 336		
345241	NO. 2 DME TRANSCEIVER 622-7309-101 3227 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
345251	NO. 1 DME ANTENNA DMNI50-2-2 63639 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
345261	NO. 2 DME ANTENNA DMNI50-2-2 63640 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
346006	MODE SELECTOR (MSU) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346008	NO. 1 FMS DISPLAY UNIT 822-0868-057 26VLH REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-MAY-2018 7674.3 5065		
346010	NO. 2 FMS DISPLAY UNIT 822-0868-057 930 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-MAY-2018 7674.3 5065		
346011	CONTROL DISPLAY (CDU) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
346045 34.510	DATA TRANSFER UNIT 822-0014-008 28FRK REF:	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874		
346058	GPS #1 SENSOR 822-2189-010 26WRL REF:	MOS HRS/MSC AFL	O/C				30-MAR-2016 7065.7 4612		
346060	GPS #2 SENSOR 822-2189-010 26WRN REF:	MOS HRS/MSC AFL	O/C				30-MAR-2016 7065.7 4612		
346061	AFIS DATA MANAGEMENT UNIT 400-045500-0003 1732 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346066	CONFIG AFIS MODULE 31990-1 6236 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
346081	ATT HEADING-AHRS DISPLAY UNIT 622-9336-400 2893 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
346083	INTERNAL-AHRS COMPENSATOR 622-6189-002 2700 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
346085	FLUX-AHRS DETECTOR 622-8154-001 15161 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
346087	COURSE DEV-AHRS INDICATOR 50-0003-11 485 REF:	MOS HRS/MSC AFL	O/C	TSN:0			22-DEC-1997 28 14		
346097	LASER TRACK CDU CG1230AC10 038 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			18-DEC-2007 5394 3370		
346103	SERVICE AHRS BATTERY AD-3120 135592 REF:	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046	15-APR-2019	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346106	NO. 1 IRS MODE SELECTOR (MSU 1) UNIT CG1042AB03 96091965 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
346116	NO. 2 IRS MODE SELECTOR (MSU 2) UNIT CG1042AB03 96122031 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
346126	NO. 3 IRS MODE SELECTOR (MSU 3) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
346131	IRS CONTROL DISPLAY (ISDU) PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
346151	NO. 1 IRS BLOWER 26006881-201 7930 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-OCT-2005 3891 2599		
346156	NO. 1 IRS BLOWER FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
346166	NO. 2 IRS BLOWER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346171	NO. 2 IRS BLOWER FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
346181 34.930	NO. 3 IRS BLOWER NOT INSTALLED SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
346186	NO. 3 IRS BLOWER FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
346208	SERVICE NO. 1 INERTIAL REFERENCE SYSTEM BATTERY REF:	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046	15-APR-2019	
346218	SERVICE NO. 2 INERTIAL REFERENCE SYSTEM BATTERY REF:	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046	15-APR-2019	
346241 34.530	NO.1 GLOBAL POSISTIONING SENSING ANTENNA S67-1575-137 773-4293 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-MAR-2016 7065.7 4612		
346246 34.530	NO.2 GLOBAL POSISTIONING SENSING ANTENNA S67-1575-137 773-4294 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-MAR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346306	NO. 1 FMS CONTROL DISPLAY UNIT 822-1354-104 273JG REF:	MOS HRS/MSC AFL	O/C				11-JUL-2006 4400 2874		
346313	REPLACEMENT FMC 2 (FLIGHT MANAGEMENT COMPUTER) BATTERY REF:	MOS HRS/MSC AFL	36				10-MAY-2018 7674.3 5056	10-MAY-2021	
346316	NO. 2 FMS CONTROL DISPLAY UNIT 822-1354-104 100FT REF:	MOS HRS/MSC AFL	O/C				09-NOV-2017 7542.6		
346831	RH LIGHTNING/HIGH INTENSITY RADIATED FIELD PROTECTOR 822-0287-201 29VMD REF:	MOS HRS/MSC AFL	O/C				14-JUL-2006 4400 2874		
346832	LH LIGHTNING/HIGH INTENSITY RADIATED FIELD PROTECTOR 822-0332-201 28P4M REF:	MOS HRS/MSC AFL	O/C				14-JUL-2006 4400 2874		
346841	IAPS NO. 1 (2A) POWER SUPPLY 622-9945-021 2704 REF:	MOS HRS/MSC AFL	O/C				14-JUL-2006 4400 2874		
346842	IAPS NO. 2 (2B) POWER SUPPLY 622-9945-021 2703 REF:	MOS HRS/MSC AFL	O/C				14-JUL-2006 4400 2874		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346843	IAPS NO. 3 (1A) POWER SUPPLY 622-9945-021 2705 REF:	MOS HRS/MSC AFL	O/C				14-JUL-2006 4400 2874		
346844	IAPS NO. 4 (1B) POWER SUPPLY 622-9945-021 2699 REF:	MOS HRS/MSC AFL	O/C				14-JUL-2006 4400 2874		
346A01	AHRS BATTERY AD-3120 135592 REF:	MOS HRS/MSC AFL	O/C	TSN:57 TSR:24			15-APR-2018 7651.3 5046		
34R125	#2 AHS BATT TEST (#2 IRU B/UP BATT) SWITCH 2004080632329 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-APR-2005 3466 2396		
CHAPTER 34-00 NAVIGATION									
34R115	#1 AHS BATT TEST (#1 IRU B/UP BATT) SWITCH 2004080632329 NONE REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-DEC-1997 28 14		
CHAPTER 35 OXYGEN									
35-10-05-350-801-01	RESTORATION PILOT OXYGEN MASK (OVERHAUL) MA10-12-00 4732 REF: See Workcard	MOS HRS/MSC AFL	72	+3%			05-NOV-2014	05-NOV-2020	09-JAN-2021
35-10-05-350-801-02	RESTORATION COPILOT OXYGEN MASK (OVERHAUL) MA1012-00 70540 REF: See Workcard	MOS HRS/MSC AFL	72	+3%			28-FEB-2014	29-FEB-2020	04-MAY-2020

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10-05-350-801-03	RESTORATION THIRD CREW MEMBER OXYGEN MASK (OVERHAUL)								
35.180	MA10-12-00 66116 REF: See Workcard	MOS HRS/MSC AFL	72	+3%			22-NOV-2011 5939.3 3734	22-NOV-2017	26-JAN-2018
+ 35-10-05-710-801-01 (s)	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)						PKG		
35.080	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			15-APR-2018 7651.3 5046		
35-10-05-710-801-02 (s)	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)						PKG		
35.080	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			15-APR-2018 7651.3 5046		
35-10-05-710-801-03 (s)	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)						PKG		
35.180	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			15-APR-2018 7651.3 5046		
35-10-05-900-801-01	PILOT OXYGEN MASK								
35.080	MA10-12-00 4732 REF: See Workcard	MOS HRS/MSC AFL	H/T				17-NOV-2014 6786.9 4388		
35-10-05-900-801-02	COPILOT OXYGEN MASK								
35.080	MA1012-00 70540 REF: See Workcard	MOS HRS/MSC AFL	H/T				16-OCT-2014 6755.9 4365		
35-10-05-900-801-03	THIRD CREW MEMBER OXYGEN MASK								
35.180	MA10-12-00 66116 REF: See Workcard	MOS HRS/MSC AFL	H/T				22-NOV-2011 5939.3 3734		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS						PKG		
35.205	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
+ 35-20-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM						PKG		
35.010	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			15-APR-2018 7651.3 5046		
35-20-01-350-801-01	RESTORATION PASSENGER OXYGEN CONTROLLER (OVERHAUL)								
35.100 OVERHAUL	RCA70 1069 REF: See Workcard	MOS HRS/MSC AFL	72	+3%			11-DEC-2014 6796.6 4395	11-DEC-2020	15-FEB-2021
35-20-01-900-801-01	PASSENGER OXYGEN CONTROLLER								
35.100	RCA70 1069 REF: See Workcard	MOS HRS/MSC AFL	H/T		TSO:2 TSO:0 TSO:0		11-DEC-2014 6796.6 4395		
35-20-09-900-801-01	NO. 1 PASSENGER OXYGEN MASK								
35.110	289-601-228 1Q12 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUN-2012 6097.1 3850		
35-20-09-900-801-02	NO. 2 PASSENGER OXYGEN MASK								
35.110	289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0	-199	10-MAY-2010 5668.9 3540		
35-20-09-900-801-03	NO. 3 PASSENGER OXYGEN MASK								
35.110	289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0	-199	10-MAY-2010 5668.9 3540		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-04	NO. 4 PASSENGER OXYGEN MASK 289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0	-199		10-MAY-2010 5668.9 3540		
35-20-09-900-801-05	NO. 5 PASSENGER OXYGEN MASK 289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0	-199		10-MAY-2010 5668.9 3540		
35-20-09-900-801-06	NO. 6 PASSENGER OXYGEN MASK 289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0	-199		10-MAY-2010 5668.9 3540		
35-20-09-900-801-07	NO. 7 PASSENGER OXYGEN MASK 289-601-228 4Q08 REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0	-199		10-MAY-2010 5668.9 3540		
35-20-09-900-801-08	NO. 8 PASSENGER OXYGEN MASK 289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0	-199		10-MAY-2010 5668.9 3540		
35-20-09-900-801-09	NO. 9 PASSENGER OXYGEN MASK 289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0	-199		10-MAY-2010 5668.9 3540		
35-20-09-900-801-10	NO. 10 PASSENGER OXYGEN MASK 289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0	-199		10-MAY-2010 5668.9 3540		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-11	NO. 11 PASSENGER OXYGEN MASK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
35-20-09-900-801-12	NO. 12 PASSENGER OXYGEN MASK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
+ 35-20-09-900-801-13	THERAPEUTIC OXYGEN MASK PN SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
35-20-09-900-801-14 35.150	TOILET OXYGEN MASK 289-601-228 4Q08 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0	-199		10-MAY-2010 5668.9 3540		
35-30-01-960-801-01 35.190	DISCARD SMOKE HOOD PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C						
35-30-05-210-801-01 35.170	GENERAL VISUAL INSPECTION PORTABLE OXYGEN BOTTLE AND MASKS 289-601-228 N/A REF: See Workcard	MOS HRS/MSC AFL	12	+3%			15-APR-2018 7651.3 5046	15-APR-2019	25-APR-2019
35-30-05-350-801-01 OVERHAUL	RESTORATION PORTABLE OXYGEN BOTTLE (OVERHAUL) 289-601-228 N/A REF: See Workcard	MOS HRS/MSC AFL	60	+3%			09-MAY-2016	09-MAY-2021	03-JUL-2021

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-30-05-960-801-01	DISCARD PORTABLE OXYGEN BOTTLE 289-601-228 35.030 LIFE LIMIT	MOS HRS/MSC AFL	60				01-MAR-2016	01-MAR-2021	
35-30-09-100-801-01	CLEANING PORTABLE OXYGEN BOTTLE MASK 289-601-228 35.030 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			15-APR-2018 7651.3 5046	15-APR-2019	25-APR-2019
+ 35-40-01-790-801-01	HYDROSTATIC TEST OXYGEN CYLINDER 89723015 ALT282-33076 MANDATORY REF: See Workcard	MOS HRS/MSC AFL	60				15-APR-2018	15-APR-2023	
35-40-01-900-801-01	OXYGEN CYLINDER 89723015 ALT282-33076 REF: See Workcard	MOS HRS/MSC AFL	H/T		TSN:35 TSN:767.8 TSN:587		15-APR-2018 7651.3 5046		
35-40-01-960-801-01	DISCARD OXYGEN CYLINDER 89723015 ALT282-33076 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	180				01-JUN-2014	01-JUN-2029	
35-40-05-350-801-01	RESTORATION OXYGEN PRESSURE REDUCING VALVE (OVERHAUL) RDN1000 536 OVERHAUL REF: See Workcard	MOS HRS/MSC AFL	72	+3%			28-MAY-2013	28-MAY-2019	01-AUG-2019
35-40-05-900-801-01	OXYGEN PRESSURE REDUCING VALVE RDN1000 536 REF: See Workcard	MOS HRS/MSC AFL	H/T		TSO:0 TSO:0 TSO:0		06-FEB-2014 6590 4244		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350116	FILLER VALVE								
35.050	DKR130 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-APR-2012 6016.8 3790		
350131	OXYGEN BOTTLE HP INDICATOR								
35.070	CMT10-1 1685 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
350141	COPILOT OXYGEN HP INDICATOR								
35.070	CMT10-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
351096	JUMPSEAT OXYGEN MASK								
REPLACE	289-601-228 N/A REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			07-MAR-2017 7347.9 4822	07-MAR-2023	
351099	FUNCTIONAL CHECK JUMPSEAT OXYGEN MASK								
	REF:	MOS HRS/MSC AFL	36				11-APR-2016 7065.7 4612	11-APR-2019	
351111	PILOT OXYGEN CONNECTOR								
35.090	DPB179 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
351131	COPILOT OXYGEN CONNECTOR								
35.090	DPB179 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352033	FN CK #1 PAX OXY MASK	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352043	FN CK #2 PAX OXY MASK	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352053	FN CK #3 PAX OXY MASK	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352063	FN CK #4 PAX OXY MASK	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352073	FN CK #5 PAX OXY MASK	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352083	FN CK #6 PAX OXY MASK	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352093	FN CK #7 PAX OXY MASK	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352103	FN CK #8 PAX OXY MASK REF:	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352113	FN CK #9 PAX OXY MASK REF:	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352123	FN CK #10 PAX OXY MASK REF:	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352162	FN CK TOILET OXY MASK REF:	MOS HRS/MSC AFL	36				15-APR-2018 7651.3 5046	15-APR-2021	
352817	TOILET #2 OXYGEN MASK 289-601-228 N/A REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			07-MAR-2017 7347.9 4822	07-MAR-2023	
352819	FN CK TOILET #2 OXY MASK REF:	MOS HRS/MSC AFL	36				04-APR-2016 7065.7 4612	04-APR-2019	
353101 35.160	FIRST AID OXYGEN CYLINDER 894-20330 601124 REF:	MOS HRS/MSC AFL	O/C	TSN:239 TSO:0 TSO:0 TSO:0			30-MAY-2017 7416.5 4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 353106	OVERHAUL FIRST AID OXYGEN CYLINDER								
35.160	894-20330	MOS	60				26-MAY-2017	26-MAY-2022	
OVERHAUL	601124	HRS/MSC							
	REF:	AFL							
353111	PORTABLE OXYGEN BOTTLE								
35.030	289-601-228	MOS		TSN:0			05-MAR-2017		
	N/A	HRS/MSC	H/T	TSN:0			7347.9		
	REF: GENERIC NO REF	AFL		TSN:0			4822		
353121	SMOKE HOOD								
	PN	MOS		TSN:0			18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	H/T	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 36 PNEUMATIC									
36-10-00-790-801-01 (s)	LEAK CHECK OF THE BLEED AIR SYSTEM AT THE APU						PKG		
	PKG 21	MOS					26-MAY-2017		
		HRS/MSC	1500	+30			7416.5		
	REF: See Workcard	AFL					4869		
36-10-00-790-801-02 (s)	LEAK CHECK OF THE BLEED AIR SYSTEM AT THE NO. 1 ENGINE						PKG		
	PKG 21	MOS					26-MAY-2017		
		HRS/MSC	1500	+30			7416.5		
	REF: See Workcard	AFL					4869		
36-10-00-790-801-03 (s)	LEAK CHECK OF THE BLEED AIR SYSTEM AT THE NO. 2 ENGINE						PKG		
	PKG 21	MOS					26-MAY-2017		
		HRS/MSC	1500	+30			7416.5		
	REF: See Workcard	AFL					4869		
36-10-00-790-801-04 (s)	LEAK CHECK OF THE BLEED AIR SYSTEM AT THE NO. 3 ENGINE						PKG		
	PKG 21	MOS					26-MAY-2017		
		HRS/MSC	1500	+30			7416.5		
	REF: See Workcard	AFL					4869		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-10-02-900-801-01	NO. 1 ENGINE HP BLEED AIR SHUTOFF VALVE 6038A040002 00719 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:7 TSR:0 TSR:0			01-OCT-2014 6741.4 4355		
36-10-02-900-801-02	NO. 2 ENGINE HP BLEED AIR SHUTOFF VALVE 6038A030002 00784 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-AUG-2004 3048 2174		
36-10-02-900-801-03	NO. 3 ENGINE HP BLEED AIR SHUTOFF VALVE 6038A040002 00592 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:211 TSR:0 TSR:0 TSR:0			05-AUG-2017 7451.3 4900		
+ 36-10-05-200-801-01	INSPECTION NO. 1 ENGINE ENGINE LP BLEED AIR CHECK VALVE CYLB50419-1H 1953 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 36-10-05-200-801-02	INSPECTION NO. 2 ENGINE ENGINE LP BLEED AIR CHECK VALVE CYLB50419-1H 1952 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 36-10-05-200-801-03	INSPECTION NO. 3 ENGINE ENGINE LP BLEED AIR CHECK VALVE CYLB50419-1H 1954 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 36-10-05-200-801-04	INSPECTION NO. 1 ENGINE ENGINE HP BLEED AIR CHECK VALVE CYLB50419-1H 1949 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 36-10-05-200-801-05	INSPECTION NO. 2 ENGINE ENGINE HP BLEED AIR CHECK VALVE CYLB50419-1H 1948 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 36-10-05-200-801-06	INSPECTION NO. 3 ENGINE ENGINE HP BLEED AIR CHECK VALVE CYLB50419-1H 1972 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 36-10-05-200-801-07	INSPECTION APU BLEED AIR CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
36-10-05-900-801-01	NO. 1 ENGINE ENGINE LP BLEED AIR CHECK VALVE CYLB50419-1H 1953 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
36-10-05-900-801-02	NO. 2 ENGINE ENGINE LP BLEED AIR CHECK VALVE CYLB50419-1H 1952 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
36-10-05-900-801-03	NO. 3 ENGINE ENGINE LP BLEED AIR CHECK VALVE CYLB50419-1H 1954 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
36-10-05-900-801-04	NO. 1 ENGINE ENGINE HP BLEED AIR CHECK VALVE CYLB50419-1H 1949 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-10-05-900-801-05	NO. 2 ENGINE ENGINE HP BLEED AIR CHECK VALVE CYLB50419-1H 1948 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
36-10-05-900-801-06	NO. 3 ENGINE ENGINE HP BLEED AIR CHECK VALVE CYLB50419-1H 1972 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
36-10-05-900-801-07	APU BLEED AIR CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
36-10-05-900-801-11	APU BLEED AIR CHECK VALVE CYLB50419-1H 2005 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 36-10-21-710-801-01	OPERATIONAL TEST BLEED AIR SHUTOFF VALVE BYLB52232 121 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
361101	NO. 1 ENGINE EXPANSION PIPE B45CB1042 T818 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
361106	NO. 2 ENGINE EXPANSION PIPE B45CB1042 T818 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361111	NO. 3 ENGINE EXPANSION PIPE B45CB1042	MOS					18-SEP-1997		
36.010	T818 REF:	HRS/MSC AFL	O/C	TSN:0			0 0		
361161	PRESSURE REGULATING VALVE PN	MOS					18-SEP-1997		
36.060	NOT INSTALLED REF:	HRS/MSC AFL	O/C	TSN:0			0 0		
361201	BLEED AIR SHUTOFF VALVE BYLB52232	MOS					18-SEP-1997		
36.070	121 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
361206	NO. 1 ENGINE BLEED VENTURI CHECK VALVE AR88-02-00-03	MOS					18-SEP-1997		
36.130	819 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
361211	NO. 2 ENGINE BLEED VENTURI CHECK VALVE AR88-02-00-03	MOS					18-SEP-1997		
36.130	846 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
361251	APU BLEED VENTURI CHECK VALVE PN	MOS					18-SEP-1997		
36.130	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0			0 0		
362101	NO. 1 ENGINE BLEED AIR THERMOSTAT PN	MOS					18-SEP-1997		
	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
362106	NO. 1 ENGINE BLEED AIR (THERMOSTAT 25H1) TEMPERATURE PROBE								
36.190	RP161-00 184 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			14-MAY-2004 2866 2076		
362111	NO. 2 ENGINE BLEED AIR THERMOSTAT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
362116	NO. 2 ENGINE BLEED AIR (THERMOSTAT 25H2) TEMPERATURE PROBE								
36.200	RP129-02 2859 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
362121	NO. 3 ENGINE BLEED AIR THERMOSTAT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
362126	NO. 3 ENGINE BLEED AIR (THERMOSTAT 25H3) TEMPERATURE PROBE								
36.210	RP129-02 3175 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			08-AUG-2001 1579 1354		
362131	CABIN AIR CONDITIONING THERMOSTAT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
362136	BLEED AIR SYSTEM DISPLAY UNIT								
36.220	92138C030800 0242 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:222 TSR:0 TSR:0 TSR:0			05-AUG-2017 7451.3 4900		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
362141	COCKPIT AIR CONDITIONING THERMOSTAT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
362144	NO.1 AND NO.3 ENGINE PRESSURE TRANSDUCER ZRA233-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			0 0		
362146	NO. 2 ENGINE PRESSURE TRANSDUCER ZRA233-01 3586 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-AUG-2017 7451.3 4900		
362151	AIR BLEED INDICATOR PRINTED CIRCUIT CI999A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
362156	AIR BLEED INDICATOR PRINTED CIRCUIT CI999A SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
CHAPTER 38 WATER/WASTE									
38-00-00-610-801-01 (s)	SERVICING OF THE WATER SYSTEM PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
38-10-00-670-801-01	STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION REF: See Workcard	MOS HRS/MSC AFL	6	+1m	-3		18-OCT-2018 7806.6 5159	15-APR-2019	15-MAY-2019

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
380106	SERVICE WATER SYSTEM-SEMI-ANNUALLY	MOS	6				18-OCT-2018 7806.6 5159	18-APR-2019	
	REF:	HRS/MSC AFL							
380111	SERVICE WATER SYSTEM-ANNUALLY	MOS	12				15-APR-2018 7651.3 5046	15-APR-2019	
	REF:	HRS/MSC AFL							
380116 (s)	INSPECT/CHECK WATER SYSTEM COMPONENTS						PKG		
	PKG 31	MOS	72				01-APR-2016 7065.7 4612		
	REF:	HRS/MSC AFL							
380201	TEST BELLY DRAIN SYSTEM	MOS	6				18-OCT-2018 7806.6 5159	18-APR-2019 8106.6	
	REF:	HRS/MSC AFL	300						
380211	FORWARD GALLEY HEATED DRAIN MAST								
	115677-111	MOS					24-AUG-2016		
	355	HRS/MSC	O/C				7230.5		
	REF:	AFL					4734		
		TSN:0							
		TSN:0							
		TSN:0							
383803	TOILET ASSY (MONOGRAM)								
	15900-300	MOS					10-MAY-2010		
	46212	HRS/MSC	O/C				5668.9		
	REF:	AFL					3540		
CHAPTER 39 ELECTRICAL PANELS, PARTS AND INSTRUMENTS									
390805	ENGINE NO. 1 AND NO.2 START (431J) PC BOARD								
	FE422	MOS					11-JAN-2008		
	9872	HRS/MSC	O/C				5415		
	REF:	AFL					3380		
		TSR:0							
		TSR:0							
		TSR:0							

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
390810	(100 JE) PRINTED CIRCUIT CARD FE424 266 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		06/13/2004	13-JUN-2003 2181 1731		
CHAPTER 45		CENTRAL MAINT SYSTEM							
45-10-02-900-801-01	MAINTENANCE DIAGNOSTIC COMPUTER (MDC) MODULE 622-9818-213 1010 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-MAY-2018 7674.3 5065		
CHAPTER 49		AIRBORNE AUXILIARY POWER							
49-50-01-900-801-01	AIR INTAKE DOOR ACTUATOR MA11A1061B SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C						
+ 49-60-00-710-801-01 (s)	OPERATIONAL TEST OF THE APU FUEL SHUT-OFF ELECTRIC VALVE AND FIRE DETECTION CIRCUIT - APU SHUT-OFF VALVE (189H) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 26-MAY-2017 7416.5 4869		
490113	APU DOOR MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
490213	APU DOOR MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493041	APU FUEL SHUT-OFF SOLENOID VALVE 656690	MOS					18-SEP-1997		
49.110	SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
49APU1	APU 3800016-3	MOS							
49.APU1	P375 REF: See Workcard	HRS/MSC AFL	E/C						
APU Model : GTCP36-100(A) Serial # P375 Part # 3800016-3									
490010	APU - OPERATIONAL CHECK	MOS					16-FEB-2007		
	REF: MM 49-20-00	HRS/MSC APUS	C/C				2741		
491010	APU - TURBINE ROTOR 3615880-1	MOS					05-OCT-2001		
LIFE LIMIT	9-01345-7093C REF: GENERIC NO REF	HRS/MSC APUS	10000	TSN:880			880		10000
491020	APU - COMPRESSOR ROTOR 3822101-1	MOS					02-JUN-1997		
LIFE LIMIT	03501022908 REF: GENERIC NO REF	HRS/MSC APUS	100000	TSN:0 TSN:0			0 0		100000
+ 491030	APU - HOT SECTION INSPECTION	MOS					14-FEB-2007		
	REF: MM 49-20-00	HRS/MSC APUS	2100	+45			2741		4841 4886
491080	APU - COMBUSTOR UNIT 3830077-9	MOS					05-NOV-2007		
	SN-UNKNOWN REF: See Workcard	HRS/MSC APUS	O/C	TSR:0 TSR:0			3035		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 491110 (s)	APU - INSPECT COMBUSTOR UNIT 3830077-9 PKG 1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	300	+10%			PKG 23-MAR-2016 3809.6		
491115	APU - COMBUSTOR CAP 3615086-2 61013-133852R REF:	MOS HRS/MSC APUS	O/C		TSO:0 TSO:0		05-NOV-2007 3035		
+ 491120	APU - VISUAL CHECK COMPRESSOR ROTOR 3822101-1 03501022908 REF: MM 49-20-00	MOS HRS/MSC APUS	2100	+45			17-FEB-2007 2741	4841	4886
491801	APU - COMBUSTION LINER 3830077-9 61013-129582R REF:	MOS HRS/MSC APUS	O/C		TSO:0 TSO:0 TSO:0		07-JUL-2006 2520		
491805	APU - TURBINE DESWIRLER DEFLECTOR 3826174-2 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C				08-AUG-2013 3566.3		
493010	APU - FUEL CONTROL 3882600-8 A335C REF: See Workcard	MOS HRS/MSC APUS	O/C		TSR:0 TSR:0 TSR:0		10-APR-2008 3135		
493020 (s)	APU - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 1 REF: See Workcard	MOS HRS/MSC APUS	300	+10%			PKG 23-MAR-2016 3809.6		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493040	APU - FUEL SHUTOFF VALVE 65690 679 REF: See Workcard	MOS HRS/MSC APUS	O/C	TSN:0			02-JUN-1997 0 0		
493060	APU - CONTROLLER 2117406-6 56-A0120 REF: MM 49-60-42	MOS HRS/MSC APUS	O/C	TSN:0			02-JUN-1997 0 0		
493070	APU - AIR LOAD CONTROL VALVE 109776-3-2 724 REF: MM 49-50-31	MOS HRS/MSC APUS	O/C	TSN:0			02-JUN-1997 0 0		
493110	APU - FUEL NOZZLE 37791-5 1AFL1368 REF: See Workcard	MOS HRS/MSC APUS	O/C	TSO:0 TSO:0			23-MAR-2016 3809.6		
493120 (s)	APU - CLEAN FUEL NOZZLE 37791-5 PKG 1 1AFL1368 REF: See Workcard	MOS HRS/MSC APUS	300	+10%			PKG 23-MAR-2016 3809.6		
493130	APU - COMBUSTOR DRAIN/ORIFICE FITTING VALVE 968214-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	O/C	TSN:0			02-JUN-1997 0 0		
+ 493140 (s)	APU - CLEAN/INSPECT COMBUSTOR DRAIN/ORIFICE FITTING VALVE 968214-1 PKG 1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	300	+10%			PKG 23-MAR-2016 3809.6		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
494010	APU - IGNITION UNIT 3888000-2 96322967 REF: See Workcard	MOS HRS/MSC APUS	O/C	TSN:0			02-JUN-1997 0 0		
494020	APU - IGNITER PLUG 3888366-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			05-NOV-2007 3035		
+ 494030 (s)	APU - CLEAN/INSPECT IGNITER PLUG 3888366-1 PKG 1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	300	+10%			PKG 23-MAR-2016 3809.6		
495206	APU - SURGE SHUTOFF VALVE 978668-3-1 3438 REF: MM 49-50-32	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			02-JUN-1997 0 0		
497010	APU - MOTION PICK UP TRANSDUCER 3876000-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	O/C	TSN:0			02-JUN-1997 0 0		
497020	APU - THERMOCOUPLE 3876003-1 727 REF: See Workcard	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0			24-AUG-1999 402 0		
497030	APU - HOURMETER 15007-15 NONE REF: See Workcard	MOS HRS/MSC APUS	O/C	TSN:0			22-DEC-1997 5 20		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499030	APU - DRAIN AND REFILL OIL PKG 1 REF: See Workcard	MOS HRS/MSC APUS	12 300	+10% +10%		-28	05-APR-2018 3950	08-MAR-2019 4250	14-APR-2019 4280
499040	APU - REMOVE/INSPECT/REPLACE OIL FILTER ELEMENT PKG 1 REF: MM 49-90-47	MOS HRS/MSC APUS	12 300	+10% +10%			08-MAR-2017 3898.3	08-MAR-2018 4198.3	14-APR-2018 4228.3
499070	APU - LOW PRESSURE SWITCH 3876001-8 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	O/C		TSN:0 TSN:0 TSN:0		01-FEB-2008 3109 3143		
499110	APU - SOAP CHECK OIL REF: GENERIC NO REF	MOS HRS/MSC APUS	O/C				23-MAR-2016 3809.6		
CHAPTER 51 STD PRACTICES AND STRUCT-GENRL									
+ 51-00-00-210-801-01	GENERAL VISUAL INSPECTION OF THE CONTROL SURFACES AND EXPOSED AREAS OF THE AIRCRAFT SKIN								
51.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
CHAPTER 52 DOORS									
52-00-00-640-802-01 (s)	LUBRICATION OF THE VISIBLE DOOR HINGES								
52.010	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			15-APR-2018 7651.3 5046		
52-10-00-200-803-01 (s)	INSPECTION CHECK AND SERVICING OF THE PASSENGER DOOR - PASSENGER DOOR (900MA)								
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-00-610-801-01 (s)	SERVICING OF THE PASSENGER DOOR - CHECK OF STRUCTURE AND LATCHES PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
52-10-00-610-801-02 (s)	SERVICING OF THE PASSENGER DOOR - CHECK OF OPENING AND CLOSING MECHANISM PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
52-10-00-610-801-03 (s)	SERVICING OF THE PASSENGER DOOR - GREASING / LUBRICATION PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
52-10-00-610-801-04 (s)	SERVICING OF THE PASSENGER DOOR - CHECK OF THE DOOR COUNTERBALANCING SYSTEM PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
52-10-00-610-801-05 52.020	SERVICING OF THE PASSENGER DOOR - CHECK OF DOOR LOCKED INDICATION REF: See Workcard	MOS HRS/MSC AFL	6	+1m		-3	18-OCT-2018 7806.6 5159	15-APR-2019	15-MAY-2019
+ 52-10-00-610-801-05A MANDATORY 5-40	SERVICING OF THE PASSENGER DOOR - CHECK OF THE DOOR LOCKED INDICATION (MANDATORY 5-40) REF: See Workcard	MOS HRS/MSC AFL	800				18-OCT-2018 7806.6 5159	8606.6	
52-10-01-900-801-01 52.020	PASSENGER DOOR F50B295 SFA12 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-03-900-801-01	PASSENGER DOOR PNEUMATIC ACTUATOR								
52.030	107-15-0 946 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-DEC-2004 3269 2298		
+ 52-10-07-220-801-01	DETAILED INSPECTION OF THE PASSENGER DOOR LOCKING HOOKS								
53.160	REF: See Workcard	MOS HRS/MSC AFL	5995				18-SEP-1997 0 0	5995	
52-10-07-220-801-01A	DETAILED INSPECTION OF THE PASSENGER DOOR LOCKING HOOKS (MANDATORY 5-40)								
53.290 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	5995				18-SEP-1997 0 0	5995	
+ 52-20-00-610-801-01 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - SERVICING OF THE LH EMERGENCY EXIT DOOR								
52.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
+ 52-20-00-610-801-02 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - SERVICING OF THE RH EMERGENCY EXIT DOOR								
52.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
+ 52-20-00-610-801-03 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE LH EMERGENCY EXIT DOOR								
52.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24				PKG 15-APR-2018 7651.3 5046		
+ 52-20-00-610-801-03A	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE LH EMERGENCY EXIT DOOR (MANDATORY 5-40)								
52.040 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	24				15-APR-2018 7651.3 5046	15-APR-2020	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-20-00-610-801-04 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE RH EMERGENCY EXIT DOOR						PKG		
52.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24				15-APR-2018 7651.3 5046		
+ 52-20-00-610-801-04A	SERVICING OF THE EMERGENCY EXIT DOOR - UNLOCKING TEST FROM INSIDE OF THE RH EMERGENCY EXIT DOOR (MANDATORY 5-40)								
52.040 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	24				15-APR-2018 7651.3 5046	15-APR-2020	
+ 52-20-00-710-801-03 (s)	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE - UNLOCKING TEST FROM OUTSIDE OF LH EXIT						PKG		
52.040	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			26-MAY-2017 7416.5 4869		
+ 52-20-00-710-801-04 (s)	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE - UNLOCKING TEST FROM OUTSIDE OF RH EXIT						PKG		
52.040	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			26-MAY-2017 7416.5 4869		
52-20-01-960-801-01	DISCARD LH EMERGENCY EXIT F50B296001 017H7	MOS HRS/MSC AFL					18-SEP-1997 0		
52.040 LIFE LIMIT	REF: See Workcard		26718		TSl:0		0	26718	
52-20-01-960-801-01A	DISCARD LH EMERGENCY EXIT (MANDATORY 5-40) F50B296001 017H7	MOS HRS/MSC AFL					18-SEP-1997 0		
MANDATORY 5-40	REF: See Workcard		26718				0	26718	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20-01-960-801-02	DISCARD RH EMERGENCY EXIT F50B296001 018H7 REF: See Workcard	MOS HRS/MSC AFL	26718	TSI:0			18-SEP-1997 0 0		26718
52.040	LIFE LIMIT								
52-20-01-960-801-02A	DISCARD RH EMERGENCY EXIT (MANDATORY 5-40) F50B296001 018H7 REF: See Workcard	MOS HRS/MSC AFL	26718				18-SEP-1997 0 0		26718
	MANDATORY 5-40								
52-20-17-640-801-01	LUBRICATION LH EMERGENCY EXIT (DOOR MECHANISM) F50B296001 017H7 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2013 6435.4 4113		
52-20-17-640-801-02	LUBRICATION RH EMERGENCY EXIT (DOOR MECHANISM) F50B296001 018H7 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUN-2012 6097.1 3850		
52-30-00-200-801-01A	VISUAL INSPECTION BAGGAGE COMPARTMENT DOOR (MANDATORY 5-40) REF: See Workcard	MOS HRS/MSC AFL	26299				18-SEP-1997 0 0		26299
53.370	MANDATORY 5-40								
+ 52-30-00-200-802-01	INSPECTION OF THE BAGGAGE COMPARTMENT DOOR FORWARD SIDE FOLD REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
52-30-00-200-802-01A	INSPECTION OF THE BAGGAGE COMPARTMENT DOOR FORWARD SIDE FOLD (MANDATORY 5-40) REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
53.285									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30-00-610-801-01 (s)	SERVICING OF THE BAGGAGE COMPARTMENT DOOR PKG 16	MOS	24	+1m			PKG 15-APR-2018 7651.3 5046		
	REF: See Workcard	HRS/MSC AFL							
52-30-01-900-801-01	BAGGAGE COMPARTMENT DOOR F50B299	MOS					18-SEP-1997		
52.050	SFA17	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
52-40-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE SERVICE DOORS PKG 16	MOS	24	+1m			PKG 15-APR-2018 7651.3 5046		
52.070	REF: See Workcard	HRS/MSC AFL							
52-50-00-710-801-01 (s)	INSPECTION/TEST OF THE BLOWOUT DOORS/PANELS PKG 31	MOS	72	+2m			PKG 01-APR-2016 7065.7 4612		
	REF: See Workcard	HRS/MSC AFL							
52-60-09-610-801-01 (s)	SERVICING OF THE REAR COMPARTMENT DOOR - GREASING/LUBRICATION PKG 17	MOS	36	+1m			PKG 15-APR-2018 7651.3 5046		
52.060	REF: See Workcard	HRS/MSC AFL							
+ 52-60-09-610-801-02 (s)	SERVICING OF THE REAR COMPARTMENT DOOR - INSPECTION/CHECK PKG 17	MOS	36	+1m			PKG 15-APR-2018 7651.3 5046		
52.060	REF: See Workcard	HRS/MSC AFL							
52-60-09-900-801-01	REAR COMPARTMENT DOOR F50B297	MOS					18-SEP-1997		
52.060	SFA10	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-70-11-710-801-01 (s)	OPERATIONAL TEST OF THE S-DUCT DOOR POSITION INDICATING MICROSWITCH						PKG		
52.080	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
52-70-11-710-801-01A	OPERATIONAL TEST OF THE S-DUCT DOOR POSITION INDICATING MICROSWITCH (MANDATORY 5-40)								
52.080 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	10000				15-APR-2018 7651.3 5046	17651.3	
522101	LH EMERGENCY EXIT								
52.040	F50B296001 017H7 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0			18-SEP-1997 0 0		
522121	RH EMERGENCY EXIT								
52.040	F50B296001 018H7 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0			18-SEP-1997 0 0		
528001	FORWARD BAGGAGE DOOR ASSIST CABLE								
	F50299300320 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
528003	AFT BAGGAGE DOOR ASSIST CABLE								
	F50B299300310A1 030825042 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-JAN-2005 3331 2328		
528005	BAGGAGE DOOR SUPPORT CABLE								
	F50B299300400 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-FEB-2006 4130 2726		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
529001	FRAME ZERO DOOR SEAL F50B291600003 NSN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-FEB-2007 4780 3071		
CHAPTER 53 FUSELAGE									
+ 53-00-00-200-801-01 (s)	INSPECTION OF THE FUSELAGE EXTERIOR						PKG		
53.025	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
53-00-00-200-801-01C	INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)						15-APR-2018 7651.3 5046	15-MAY-2020	
53.035 CPCP	REF: See Workcard	MOS HRS/MSC AFL	25						
53-00-00-200-802-01A	VISUAL INSPECTION OF THE SKIN PANELS - FRAME 7 TO FRAME 31 (MANDATORY 5-40)						18-SEP-1997 0 0		20000
53.310 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000						
+ 53-00-00-210-802-01	GENERAL VISUAL INSPECTION OF THE COCKPIT WINDOW FAIRING						15-APR-2018 7651.3 5046		
53.020	REF: AMM 53-00-00-210-802	MOS HRS/MSC AFL	O/C						
53-00-00-210-802-01C	GENERAL VISUAL INSPECTION OF THE COCKPIT WINDOW FAIRING (CPCP)						15-APR-2018 7651.3 5046		
53.035 CPCP	REF: AMM 53-00-00-210-802	MOS HRS/MSC AFL	O/C						
+ 53-00-00-220-801-01	DETAILED INSPECTION OF THE FUSELAGE FRAMES IN PRESSURIZED AREA						18-SEP-1997 0 0		
53.250	REF: See Workcard	MOS HRS/MSC AFL	N/A						

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00-00-250-802-01A	NON DESTRUCTIVE TEST OF THE FUSELAGE FRAMEWORK AROUND THE WINDOWS IN T2 AND T3 SECTIONS (LONGITUDINAL CRACKS) (MANDATORY 5-40)								
53.330		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	31250				0		31250
53-04-01-220-801-01A	VISUAL INSPECTION FLOOR OMEGAS AT FRAMES 18-19 (MANDATORY 5-40)								
53.145		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	27500				0		27500
53-04-05-250-801-01A	EDDY CURRENT INSPECTION OF FLOOR PANEL STIFFENERS BETWEEN FRAMES 31 AND 35 (MANDATORY 5-40)								
53.195		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-10-00-200-808-01 (s)	INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY						PKG		
32.2801	PKG 15	MOS	12	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
53-10-00-200-808-01C	INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY (CPCP)								
		MOS	12				15-APR-2018		15-APR-2019
CPCP	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
+ 53-10-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT						PKG		
53.0401	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
53-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE STATIC PRESSURE PROBE AND OF THE FUSELAGE SKIN IN PROBE AREA						PKG		
53.030	PKG 16	MOS	24	+1m			15-APR-2018		
RVSM	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT						PKG		
53.0402	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			11-APR-2016 7065.7 4612		
53-10-00-220-802-01C	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)								
53.055 CPCP	REF: See Workcard	MOS HRS/MSC AFL	74				11-APR-2016 7065.7 4612	11-JUN-2022	
+ 53-10-00-220-803-01 (s)	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY						PKG		
32.2802	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
53-10-00-220-803-01C	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY (CPCP)								
53.065 CPCP	REF: See Workcard	MOS HRS/MSC AFL	25				15-APR-2018 7651.3 5046	15-MAY-2020	
53-10-03-250-802-01A	EDDY CURRENT INSPECTION OF THE PASSENGER DOOR FRAME CORNERS (MANDATORY 5-40)								
53.320 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	31250				18-SEP-1997 0 0	31250	
53-10-05-250-801-01A	EDDY CURRENT INSPECTION OF FRAME 12 AROUND PAX DOOR TELESCOPIC ROD FITTING (MANDATORY 5-40)								
53.215 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0	20000	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-31-220-801-01A	DETAILED INSPECTION OF COCKPIT UPPER SKIN JUNCTION WITH WINDSHIELD AND WINDOW FRAMES (MANDATORY 5-40)								
53.152		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-10-39-220-801-01 (s)	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES						PKG		
53.210	PKG 31	MOS	72	+2m			01-APR-2016		
	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
+ 53-10-39-220-801-01A	INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (MANDATORY 5-40)								
		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
53-10-39-220-801-01C	INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (CPCP)								
53.075		MOS	74				01-APR-2016	01-JUN-2022	
CPCP	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
+ 53-10-39-220-803-01	DETAILED INSPECTION OF THE SCREWS ATTACHING THE WINDSHIELD FRAMES TO FRAME 0								
53.090		MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC					0		
		AFL	10525				0		10525
53-10-39-220-803-01A	DETAILED INSPECTION OF THE ATTACHING SCREW OF COCKPIT WINDSHIELD FRAMES TO FRAME 0 (MANDATORY 5-40)								
53.235		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	6674				0		6674
+ 53-10-39-220-804-01	DETAILED INSPECTION OF THE FRAME OF THE LH SIDE REAR COCKPIT WINDOWS								
53.140		MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-39-220-804-01A	DETAILED INSPECTION OF THE FRAME OF THE LH SIDE REAR COCKPIT WINDOWS (MANDATORY 5-40)								
53.265	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 53-10-39-220-804-02	INSPECTION OF THE FRAME OF THE RH SIDE REAR COCKPIT WINDOWS								
53.140	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
53-10-39-220-804-02A	INSPECTION RIGHT REAR WINDOW FRAME (MADATORY 5-40)								
53.275	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
+ 53-10-39-220-805-01	DETAILED INSPECTION OF THE FRAME OF THE RH COCKPIT LATERAL WINDOW								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
53-10-39-220-805-01A	DETAILED INSPECTION OF THE FRAME OF THE RH COCKPIT LATERAL WINDOW (MANDATORY 5-40)								
53.110	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
53-10-39-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE LOWER RECESSES OF THE COCKPIT WINDSHIELD/WINDOW FRAMES						PKG		
53.420	REF: See Workcard	PKG 32 MOS HRS/MSC AFL	144				10-MAY-2010 5668.9 3540		
53-10-39-250-801-01C	EDDY CURRENT INSPECTION OF THE LOWER RECESSES OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (CPCP)								
53.095 CPCP	REF: See Workcard	MOS HRS/MSC AFL	148				10-MAY-2010 5668.9 3540	10-SEP-2022	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-39-250-802-01A	EDDY CURRENT INSPECTION OF THE COCKPIT WINDSHIELD/WINDOW FRAMES (MANDATORY 5-40)	MOS					18-SEP-1997		
53.300		HRS/MSC					0		
MANDATORY 5-40	REF: See Workcard	AFL	20000				0		20000
53-10-39-270-801-01 (s)	ULTRASONIC CHECK OF THE LOWER PART OF THE FRAMES OF THE COCKPIT WINDSHIELDS AND WINDOWS	MOS	288	+2m			18-SEP-1997		
53.420		HRS/MSC					0		
	REF: See Workcard	AFL					0		
53-10-39-270-801-01C	ULTRASONIC CHECK OF THE LOWER PART OF FRAMES OF COCKPIT WINDSHIELD AND WINDOWS (CPCP)	MOS	296				18-SEP-1997	18-MAY-2022	
53.115		HRS/MSC					0		
CPCP	REF: See Workcard	AFL					0		
+ 53-10-39-270-802-01 (s)	ULTRASONIC CHECK OF THE VERTICAL POSTS OF THE COCKPIT WINDSHIELDS AND WINDOWS	MOS	72	+2m			01-APR-2016		
53.270		HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		
53-10-39-270-802-01A	ULTRASONIC CHECK OF THE VERTICAL POSTS OF THE COCKPIT WINDSHIELDS AND WINDOWS (MANDATORY 5-40)	MOS					01-APR-2016		
53.270		HRS/MSC					7065.7		
MANDATORY 5-40	REF: See Workcard	AFL	20000				4612		20000 M
53-10-39-270-802-01C	ULTRASONIC CHECK OF THE VERTICAL POSTS OF COCKPIT WINDSHIELD AND WINDOWS (CPCP)	MOS	74				01-APR-2016	01-JUN-2022	
53.120		HRS/MSC					7065.7		
CPCP	REF: See Workcard	AFL					4612		
53-10-41-220-801-01	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR	MOS					18-SEP-1997		
53.228		HRS/MSC					0		
	REF: See Workcard	AFL	10000				0		10000

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-41-220-801-01A	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR (MANDATORY 5-40)								
53.228		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	10000				0		10000
53-10-45-250-801-01A	EDDY CURRENT INSPECTION OF THE NLG BAY SKIN PANEL AND DOOR FRAME AT FRAME 7 (MANDATORY 5-40)								
53.340		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	31250				0		31250
+ 53-11-00-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA						PKG		
53.0301	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
53-11-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)								
53.130		MOS	25				15-APR-2018		15-MAY-2020
CPCP	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
+ 53-11-00-220-801-01 (s)	DETAILED INSPECTION OF THE NOSE CONE AREA						PKG		
53.0302	PKG 31	MOS	72	+2m			11-APR-2016		
	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
53-11-00-220-801-01C	DETAILED INSPECTION OF THE NOSE CONE AREA (CPCP)								
53.135		MOS	74				11-APR-2016		11-JUN-2022
CPCP	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
53-11-00-760-801-01	CHECK OF THE NOSE CONE ELECTRICAL BONDING								
53.380		MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN						PKG		
53.0501	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
+ 53-30-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN						PKG		
53.0502	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			11-APR-2016 7065.7 4612		
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN (CPCP)								
53.230 CPCP	REF: See Workcard	MOS HRS/MSC AFL	74				11-APR-2016 7065.7 4612	11-JUN-2022	
+ 53-30-00-220-802-01	INSPECTION OF THE CENTER FLOOR ANGLE PIECE, RH SIDE BETWEEN FRAME 19 AND FRAME 26								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
53-30-00-220-802-01A	INSPECTION OF THE CENTER FLOOR ANGLE PIECE, RH SIDE BETWEEN FRAME 19 AND FRAME 26 (MANDATORY 5-40)								
53.302 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	16192				18-SEP-1997 0 0	16192	
53-30-00-220-803-01	DETAILED INSPECTION OF THE FLOOR PICK-UP ANGLE AT FRAME 27 AND OF THE FLOOR PANEL BETWEEN FRAME 26 AND FRAME 29								
53.305	REF: See Workcard	MOS HRS/MSC AFL	10000				18-SEP-1997 0 0	10000	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-220-803-01A	DETAILED INSPECTION OF THE FLOOR PICKUP ANGLE AT FRAME 27 AND OF THE FLOOR PANEL BETWEEN FRAME 26 AND FRAME 29 (MANDATORY 5-40)	MOS					18-SEP-1997		
53.360		HRS/MSC					0		
MANDATORY 5-40	REF: See Workcard	AFL	10000				0		10000
+ 53-30-00-220-805-01A	DETAILED INSPECTION OF FUSELAGE SKIN IN SPLICE AREA AT STRINGER 13 BETWEEN FRAME 13 AND 18 (MANDATORY 5-40)	MOS					18-SEP-1997		
		HRS/MSC					0		
MANDATORY 5-40	REF: See Workcard	AFL	30000				0		30000
53-30-00-250-801-01A	EDDY CURRENT INSPECTION OF THE PASSENGER CABIN SKIN PANEL AROUND EMERGENCY EXIT DOOR ROUNDED ANGLES (MANDATORY 5-40)	MOS					18-SEP-1997		
53.175		HRS/MSC					0		
MANDATORY 5-40	REF: See Workcard	AFL	20000				0		20000
53-30-00-250-803-01A	EDDY CURRENT INSPECTION OF THE FINGER PLATE OF CIRCUMFERENTIAL SPLICE AT FRAMES 19 AND 26 (MANDATORY 5-40)	MOS					18-SEP-1997		
53.180		HRS/MSC					0		
MANDATORY 5-40	REF: See Workcard	AFL	20000				0		20000
+ 53-30-01-220-801-01 (s)	DETAILED INSPECTION OF THE FEEDER TANKS						PKG		
53.010	PKG 31	MOS	72	+2m			01-APR-2016		
		HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		
53-30-01-220-801-01A	DETAILED INSPECTION OF THE FEEDER TANKS (MANDATORY 5-40)	MOS	74				01-APR-2016	01-JUN-2022	
53.225		HRS/MSC					7065.7		
MANDATORY 5-40	REF: See Workcard	AFL					4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-01-220-801-01C	DETAILED INSPECTION OF THE FEEDER TANKS (CPCP)	MOS	74				01-APR-2016	01-JUN-2022	
53.240		HRS/MSC					7065.7		
CPCP	REF: See Workcard	AFL					4612		
53-30-01-790-801-01 (s)	LEAK TEST OF THE FEEDER TANK	MOS					PKG		
53.260	PKG 21	HRS/MSC	1500	+30			26-MAY-2017		
	REF: See Workcard	AFL					7416.5		
							4869		
53-30-01-790-801-01A	LEAK TEST OF THE FEEDER TANK (MANDATORY 5-40)	MOS					26-MAY-2017		
53.280		HRS/MSC	N/A				7416.5		
	REF: See Workcard	AFL					4869		
53-30-03-960-801-01	REPLACE OF ALUMINUM LIGHTNING DIVERTER STRIPS ON REAR TANK	MOS					18-SEP-1997		
		HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
+ 53-40-00-200-804-01 (s)	INSPECTION OF THE LH MAIN LANDING GEAR (MLG) BAY	MOS	12	+1m			PKG		
32.1401	PKG 15	HRS/MSC					15-APR-2018		
	REF: See Workcard	AFL					7651.3		
							5046		
53-40-00-200-804-01C	INSPECTION OF THE LH MAIN LANDING GEAR (MLG) BAY (CPCP)	MOS	12				15-APR-2018	15-APR-2019	
53.245		HRS/MSC					7651.3		
CPCP	REF: See Workcard	AFL					5046		
+ 53-40-00-200-804-02 (s)	INSPECTION OF THE RH MAIN LANDING GEAR (MLG) BAY	MOS	12	+1m			PKG		
32.1401	PKG 15	HRS/MSC					15-APR-2018		
	REF: See Workcard	AFL					7651.3		
							5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-40-00-200-804-02C	INSPECTION OF THE RH MAIN LANDING GEAR (MLG) BAY (CPCP)	MOS	12				15-APR-2018	15-APR-2019	
53.245 CPCP	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
+ 53-40-00-210-803-02 (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE FEEDER TANKS						PKG		
53.0601	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
53-40-00-210-803-02C	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS (CPCP)	MOS	25				15-APR-2018	15-MAY-2020	
53.255 CPCP	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
53-40-00-220-802-01 (s)	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS						PKG		
53.450	PKG 31	MOS	72	+2m			01-APR-2016		
	REF: See Workcard	HRS/MSC AFL					7065.7 4612		
53-40-00-220-802-01A	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (MANDATORY 5-40)	MOS	74				01-APR-2016	01-JUN-2022	
	REF: See Workcard	HRS/MSC AFL					7065.7 4612		
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)	MOS	74				01-APR-2016	01-JUN-2022	
CPCP	REF: See Workcard	HRS/MSC AFL					7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-40-00-220-803-01 (s)	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE FEEDER TANKS						PKG		
53.0602	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			11-APR-2016 7065.7 4612		
53-40-00-220-803-01C	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS AND OF THE COMPARTMENTS ABOVE THE FEEDER TANKS (CPCP)								
53.295 CPCP	REF: See Workcard	MOS HRS/MSC AFL	74				11-APR-2016 7065.7 4612	11-JUN-2022	
+ 53-40-00-220-804-01 (s)	DETAILED INSPECTION LH LEFT MAIN LANDING GEAR OF THE LH MAIN LANDING GEAR (MLG) BAY						PKG		
32.1402	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
53-40-00-220-804-01C	DETAILED INSPECTION LH OF THE MAIN LANDING GEAR (MLG) BAY (CPCP)								
53.315 CPCP	REF: See Workcard	MOS HRS/MSC AFL	25				15-APR-2018 7651.3 5046	15-MAY-2020	
+ 53-40-00-220-804-02 (s)	DETAILED INSPECTION RH RIGHT MAIN LANDING GEAR OF THE RH MAIN LANDING GEAR (MLG) BAY						PKG		
32.1402	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
53-40-00-220-804-02C	DETAILED INSPECTION RH OF THE MAIN LANDING GEAR (MLG) BAY (CPCP)								
53.315 CPCP	REF: See Workcard	MOS HRS/MSC AFL	25				15-APR-2018 7651.3 5046	15-MAY-2020	
53-40-07-220-801-01A	DETAILED INSPECTION OF THE CENTERWING TANK LOWER PANELS (MANDATORY 5-40)								
53.165 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0	20000	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-40-07-250-801-01A	EDDY CURRENT INSPECTION OF CENTERWING TANK LOWER PANEL SPLICE (MANDATORY 5-40)								
53.172		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
53-40-07-280-801-01	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS								
53.400		PKG 35					18-SEP-1997		
		MOS					0		
	REF: See Workcard	HRS/MSC					0		20000
		AFL	20000				0		
53-40-07-280-801-01A	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS (MANDATORY 5-40)								
53.155		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
53-40-07-280-801-01C	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF CENTERWING TANK LOWER PANELS AND MAPPING OF REWORKED AREAS (CPCP)								
53.325		MOS	384				18-SEP-1997		18-SEP-2029
CPCP	REF: See Workcard	HRS/MSC					0		
		AFL					0		
+ 53-40-07-960-801-01A	DISCARD CENTRAL WING SECTION OF THE CENTERWING TANK LOWER PANELS (MANDATORY 5-40)								
	PN	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	O/C				0		
LIFE LIMIT	REF: See Workcard	AFL					0		
53-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE LH UPPER WING ROOT BOLT RECESSES						PKG		
	PKG 31	MOS	72	+2m			11-APR-2016		
		HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-220-801-01C	DETAILED INSPECTION OF THE LH UPPER WING ROOT BOLT RECESSES (CPCP)	MOS	74				11-APR-2016 7065.7 4612	11-JUN-2022	
53.335 CPCP	REF: See Workcard	HRS/MSC AFL							
53-41-00-220-801-02 (s)	DETAILED INSPECTION OF THE RH UPPER WING ROOT BOLT RECESSES	MOS	72	+2m			11-APR-2016 7065.7 4612		
	PKG 31	HRS/MSC AFL							
	REF: See Workcard								
53-41-00-220-801-02C	DETAILED INSPECTION OF THE RH UPPER WING ROOT BOLT RECESSES (CPCP)	MOS	74				11-APR-2016 7065.7 4612	11-JUN-2022	
53.335 CPCP	REF: See Workcard	HRS/MSC AFL							
53-41-00-620-802-01	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH UPPER WING ROOT BOLT RECESSES	MOS					18-SEP-1997 0 0		
57.170	REF: See Workcard	HRS/MSC AFL	N/A						
53-41-00-620-802-01C	RENEWAL OF THE TEMPORARY PROTECTION OF LH UPPER WING ROOT BOLT RECESSES (CPCP)	MOS					18-SEP-1997 0 0		
53.345 CPCP	REF: See Workcard	HRS/MSC AFL	N/A						
53-41-00-620-802-02	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH UPPER WING ROOT BOLT RECESSES	MOS					18-SEP-1997 0 0		
57.180	REF: See Workcard	HRS/MSC AFL	N/A						
53-41-00-620-802-02C	RENEW OF THE TEMPORARY PROTECTION OF RH UPPER WING ROOT BOLT RECESSES (CPCP)	MOS					18-SEP-1997 0 0		
53.345 CPCP	REF: See Workcard	HRS/MSC AFL	N/A						

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-620-802-03	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH LOWER WING ROOT BOLT RECESSES								
57.170	REF: See Workcard	MOS HRS/MSC AFL	N/A						
53-41-00-620-802-03C	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH LOWER WING ROOT BOLT RECESSES (CPCP)						18-SEP-1997		
	REF: See Workcard	MOS HRS/MSC AFL	N/A				0		0
53-41-00-620-802-04	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH LOWER WING ROOT BOLT RECESSES						18-SEP-1997		
57.180	REF: See Workcard	MOS HRS/MSC AFL	N/A				0		0
53-41-00-620-802-04C	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH LOWER WING ROOT BOLT RECESSES (CPCP)						18-SEP-1997		
	REF: See Workcard	MOS HRS/MSC AFL	N/A				0		0
53-41-01-640-801-01 (s)	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - LH LINK ROD						PKG		
57.040	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
53-41-01-640-801-02 (s)	LUBRICATE RH WING TO FUSELAGE CONNECTING AT FRAME 29 ROD						PKG		
57.040	PN PKG 31 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
53-41-01-900-801-01	LH WING TO FUSELAGE CONNECTING AT FRAME 29 ROD						18-SEP-1997		
57.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-01-900-801-02	RH WING TO FUSELAGE CONNECTING AT FRAME 29 ROD								
57.040	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 53-50-00-210-804-02 (s)	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT						PKG		
53.0801	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			15-APR-2018 7651.3 5046		
53-50-00-210-804-02C	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)								
53.350 CPCP	REF: See Workcard	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046	15-APR-2019	
+ 53-50-00-210-806-02 (s)	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT						PKG		
53.0701	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
53-50-00-210-806-02C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)								
53.355 CPCP	REF: See Workcard	MOS HRS/MSC AFL	25				15-APR-2018 7651.3 5046	15-MAY-2020	
+ 53-50-00-210-807-02 (s)	GENERAL VISUAL INSPECTION OF THE APU AREA						PKG		
49.124	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			15-APR-2018 7651.3 5046		
+ 53-50-00-220-803-02 (s)	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT						PKG		
53.0702	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			11-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-00-220-803-02C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)	MOS	74				11-APR-2016	11-JUN-2022	
53.375		HRS/MSC					7065.7		
CPCP	REF: See Workcard	AFL					4612		
+ 53-50-00-220-805-01 (s)	DETAILED INSPECTION OF THE REAR COMPARTMENT						PKG		
53.0802	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
53-50-00-220-805-01C	DETAILED INSPECTION OF THE REAR COMPARTMENT (CPCP)	MOS	25				15-APR-2018	15-MAY-2020	
53.385		HRS/MSC					7651.3		
CPCP	REF: See Workcard	AFL					5046		
+ 53-50-00-220-806-01	DETAILED INSPECTION OF APU EXHAUST PIPE AND OUTER DUCT								
49.119		MOS					15-APR-2018		
	REF: AMM 53-50-00-220-806	HRS/MSC	O/C				7651.3		
		AFL					5046		
53-50-34-220-801-01A	DETAILED INSPECTION OF THE FRAME 34 UPPER AND LOWER SECTIONS (MANDATORY 5-40)								
53.142		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-50-35-220-801-01	DETAILED INSPECTION OF THE FRAME 35 LOWER SECTION								
53.100		MOS					18-SEP-1997		
	REF: See Workcard	HRS/MSC	O/C				0		
		AFL					0		
53-50-35-220-802-01A	DETAILED INSPECTION OF THE FRAME 35 UPPER AND LOWER SECTIONS (MANDATORY 5-40)								
		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-35-250-801-01A	EDDY CURRENT INSPECTION OF THE FRAME 35 VERTICAL BEAMS (MANDATORY 5-40)								
53.185		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
53-50-44-220-801-01A	DETAILED INSPECTION OF THE FIN STUB FRONT SPAR (MANDATORY REF 5-40)								
53.205		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
+ 53-80-00-200-801-01 (s)	CHECK OF THE CONDENSATION AND STREAM WATER DRAINS						PKG		
51.040	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
+ 53-80-09-710-801-01 (s)	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS						PKG		
51.050	PKG 31	MOS	72	+2m			01-APR-2016		
	REF: See Workcard	HRS/MSC AFL					7065.7 4612		
530321	FLIGHT COMPARTMENT REMOVABLE WINDOW FAIRING								
53.210	PN	MOS					18-SEP-1997		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL					0		
CHAPTER 54 NACELLES/PYLONS									
+ 54-00-00-210-810-03	GENERAL VISUAL INSPECTION NO. 1 ENGINE OF THE ENGINE 1 NACELLES AND PYLONS								
54.0101		MOS	19				18-OCT-2018		18-MAY-2020
	REF: See Workcard	HRS/MSC AFL	800				7806.6 5159		8606.6
54-00-00-210-810-03C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 NACELLE AND PYLON (CPCP)								
54.085		MOS	19				18-OCT-2018		18-MAY-2020
CPCP	REF: See Workcard	HRS/MSC AFL	800				7806.6 5159		8606.6

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-00-00-210-810-04	GENERAL VISUAL INSPECTION NO. 3 ENGINE OF THE ENGINE 3 NACELLES AND PYLONS								
54.0101	REF: See Workcard	MOS HRS/MSC AFL	19 800				18-OCT-2018 7806.6 5159	18-MAY-2020 8606.6	
54-00-00-210-810-04C	GENERAL VISUAL INSPECTION OF THE ENGINE 3 NACELLE AND PYLON (CPCP)								
54.055 CPCP	REF: See Workcard	MOS HRS/MSC AFL	19 800				18-OCT-2018 7806.6 5159	18-MAY-2020 8606.6	
+ 54-00-00-210-811-02	GENERAL VISUAL INSPECTION NO. 2 ENGINE OF THE ENGINE 2 NACELLE								
54.0201	REF: See Workcard	MOS HRS/MSC AFL	19 800				18-OCT-2018 7806.6 5159	18-MAY-2020 8606.6	
54-00-00-210-811-02C	GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE (CPCP)								
54.065 CPCP	REF: See Workcard	MOS HRS/MSC AFL	19 800				18-OCT-2018 7806.6 5159	18-MAY-2020 8606.6	
54-00-00-220-801-01	DETAILED INSPECTION/CHECK NO. 1 ENGINE OF THE ENGINE 1 NACELLES, PYLONS AND FORWARD MOUNTS								
54.0102	REF: AMM 54-00-00-220-801	MOS HRS/MSC AFL	O/C				10-MAY-2010 5668.9 3540		
54-00-00-220-801-01C	DETAILED INSPECTION OF THE ENGINE 1 NACELLE/PYLON/FORWARD MOUNTS (CPCP)								
54.035 CPCP	REF: AMM 54-00-00-220-801	MOS HRS/MSC AFL	O/C				01-APR-2016 7065.7 4612		
54-00-00-220-801-02	DETAILED INSPECTION NO. 3 ENGINE OF THE ENGINE 3 NACELLES, PYLONS AND FORWARD MOUNTS								
54.0102	REF: AMM 54-00-00-220-801	MOS HRS/MSC AFL	O/C				10-MAY-2010 5668.9 3540		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-00-00-220-801-02C	DETAILED INSPECTION OF THE ENGINE 3 NACELLE/PYLON/FORWARD MOUNTS (CPCP)								
54.035		MOS					01-APR-2016		
CPCP	REF: AMM 54-00-00-220-801	HRS/MSC	O/C				7065.7		
		AFL					4612		
+ 54-00-00-220-802-01 (s)	DETAILED INSPECTION NO. 2 ENGINE OF THE ENGINE 2 NACELLE						PKG		
54.0202	PKG 32	MOS	144	+2m			10-MAY-2010		
	REF: See Workcard	HRS/MSC					5668.9		
		AFL					3540		
54-00-00-220-802-01C	DETAILED INSPECTION OF THE ENGINE 2 NACELLE (CPCP)								
54.095		MOS	148				01-APR-2016	01-AUG-2028	
CPCP	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
54-11-00-610-801-01 (s)	SERVICING OF THE ENGINE 1 COWLINGS						PKG		
54.030	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
54-11-00-610-801-02 (s)	SERVICING OF THE ENGINE 2 COWLINGS						PKG		
54.030	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
54-11-00-610-801-03 (s)	SERVICING OF THE ENGINE 3 COWLINGS						PKG		
54.030	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
54-14-00-210-801-01	GENERAL VISUAL INSPECTION OF ENGINE 1 CORE COWL ASSEMBLY								
		MOS					05-JUN-2018		
	REF: See Workcard	HRS/MSC	300				7685.2	7985.2	
		AFL					5077		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-14-00-210-801-02	GENERAL VISUAL INSPECTION OF ENGINE 2 CORE COWL ASSEMBLY	MOS					05-JUN-2018		
	REF: See Workcard	HRS/MSC	300				7685.2		7985.2
		AFL					5077		
54-14-00-210-801-03	GENERAL VISUAL INSPECTION OF ENGINE 3 CORE COWL ASSEMBLY	MOS					05-JUN-2018		
	REF: See Workcard	HRS/MSC	300				7685.2		7985.2
		AFL					5077		
+ 54-42-17-200-801-01	CHECK FOR NON-LOOSENING OF SCREWS OF S-DUCT SECTIONS 2 AND 3 COUPLING FLANGES	MOS					15-APR-2018		
54.070	REF: See Workcard	HRS/MSC	600	+30			7651.3		8251.3
		AFL					5046		8281.3
54-50-00-220-802-01A	DETAILED INSPECTION OF PYLON UPPER FLANGE RIBS AT FRAME 32 (MANDATORY 5-40)	MOS					18-SEP-1997		
53.222	REF: See Workcard	HRS/MSC					0		
MANDATORY 5-40		AFL	20000				0		20000
540171	NO. 1 ENGINE REAR ATTACH FITTING	MOS					18-SEP-1997		
54.040	F50B581106400	HRS/MSC	O/C				0		
	SN-UNKNOWN	AFL			TSN:0		0		
	REF: GENERIC NO REF								
540173	NO. 1 ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT	MOS					18-SEP-1997		
54.040	3073361-1	HRS/MSC	O/C				0		
	NOT INST.	AFL			TSN:0		0		
	REF:								
540176	NO. 1 ENGINE MAIN ATTACH FITTING	MOS					18-SEP-1997		
54.040	F10A5B10555	HRS/MSC	O/C				0		
	SN-UNKNOWN	AFL			TSN:0		0		
	REF: GENERIC NO REF								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
540181	NO. 2 ENGINE REAR ATTACH FITTING F50B25520	MOS					18-SEP-1997		
54.050	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
540186	NO. 2 ENGINE REAR ATTACH LINK F50B255520110	MOS					18-SEP-1997		
54.050	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
540191	NO. 3 ENGINE REAR ATTACH FITTING F50B581106400	MOS					18-SEP-1997		
54.060	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
540193	NO. 3 ENGINE REAR ATTACHMENT AUXILIARY FITTING BOLT 3073361-1	MOS					18-SEP-1997		
54.060	NOT INST. REF:	HRS/MSC AFL	O/C	TSN:0			0 0		
540196	NO. 3 ENGINE MAIN ATTACH FITTING F10A5B10555	MOS					18-SEP-1997		
54.060	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

CHAPTER 55		STABILIZERS							
+ 55-00-00-210-801-01 (s)		GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT						PKG	
55.0101	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)								
55.025 CPCP	REF: See Workcard	MOS HRS/MSC AFL	25				15-APR-2018 7651.3 5046	15-MAY-2020	
+ 55-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT						PKG		
55.0102	REF: See Workcard	MOS HRS/MSC AFL	72	+2m			11-APR-2016 7065.7 4612		
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)								
55.035 CPCP	REF: See Workcard	MOS HRS/MSC AFL	74				11-APR-2016 7065.7 4612	11-JUN-2022	
55-00-00-270-801-01 (s)	ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES						PKG		
55.070	REF: See Workcard	MOS HRS/MSC AFL	288	+2m			18-SEP-1997 0 0		
55-00-00-270-801-01A	ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES (MANDATORY 5-40)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0	20000	
55-00-00-270-801-01C	ULTRASONIC INSPECTION FOR STRESS CORROSION IN STABILIZER HINGES (CPCP)								
55.060 CPCP	REF: See Workcard	MOS HRS/MSC AFL	296				18-SEP-1997 0 0	18-MAY-2022	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-00-00-760-801-01 (s) 55.080	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING RUDDER PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
55-00-00-760-801-02 (s) 55.080	CHECK LH OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING ELEVATOR PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
55-00-00-760-801-03 (s) 55.080	CHECK RH OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING ELEVATOR PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
55-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 01-APR-2016 7065.7 4612		
55-10-00-220-801-01C CPCP	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE (CPCP) REF: See Workcard	MOS HRS/MSC AFL	148				01-APR-2016 7065.7 4612	01-AUG-2028	
55-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 01-APR-2016 7065.7 4612		
55-10-00-220-802-01C CPCP	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS (CPCP) REF: See Workcard	MOS HRS/MSC AFL	148				01-APR-2016 7065.7 4612	01-AUG-2028	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-220-803-01A	DETAILED INSPECTION OF HORIZONTAL STABILIZER UPPER PANELS BETWEEN ROOT AND RIB2 (MANDATORY 5-40)								
55.045		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
55-10-00-640-803-01 (s)	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK, ACTUATOR UPPER HINGE, AND ELEVATOR U-JOINTS-LINKAGE U-JOINTS AND ELEVATOR BEARINGS						PKG		
27.380		MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
55-10-00-640-803-02 (s)	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK, ACTUATOR UPPER HINGE, AND ELEVATOR U-JOINTS-HORIZONTAL STABILIZER FRONT HING POINTS						PKG		
27.440		MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
55-10-03-640-801-01 (s)	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM						PKG		
27.440		MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC AFL					7651.3 5046		
+ 55-10-31-220-801-01	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS								
55.040		MOS					11-APR-2016		
	REF: See Workcard	HRS/MSC AFL	3750				7065.7 4612		8362
+ 55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY 5-40)								
55.040		MOS					11-APR-2016		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	3750				7065.7 4612		8362



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-33-640-801-01	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS								
27.430		MOS	12	+1m			15-APR-2018	15-APR-2019	15-MAY-2019
	REF: See Workcard	HRS/MSC	600	+30			7651.3	8251.3	8281.3
		AFL					5046		
55-10-39-220-801-01A	DETAILED INSPECTION OF HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS (MANDATORY 5-40)								
55.065		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0	20000	
55-20-00-220-801-01A	DETAILED INSPECTION OF THE ELEVATORS SKIN AND HINGE FITTINGS (MANDATORY 5-40)								
55.050		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0	20000	
55-20-01-900-801-01	LH ELEVATOR								
55.020	F50B341	MOS					18-SEP-1997		
	138BZ/511	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
55-20-01-900-801-02	RH ELEVATOR								
55.020	F50B342	MOS					18-SEP-1997		
	139BZ/512	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
55-20-03-640-801-01 (s)	LUBRICATION OF THE ELEVATOR BEARINGS - LH ELEVATOR						PKG		
55.020	PKG 31	MOS	72	+2m			01-APR-2016		
	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
55-20-03-640-801-02 (s)	LUBRICATION OF THE ELEVATOR BEARINGS - RH ELEVATOR						PKG		
55.020	PKG 31	MOS	72	+2m			01-APR-2016		
	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-03-640-802-01 (s) 27.370	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
55-40-00-220-801-01A 55.055 MANDATORY 5-40	DETAILED INSPECTION OF THE RUDDER SKIN AND HINGE FITTINGS (MANDATORY 5-40) REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0	20000	
55-40-01-900-801-01 55.030	RUDDER F50B321 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		
55-40-05-640-801-01 (s) 55.030	LUBRICATION OF THE RUDDER BEARINGS PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
55-40-05-640-802-01 (s) 27.280	LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
CHAPTER 56 WINDOWS									
56-00-00-910-801-01	PERFORM ACCEPTANCE CRITERIA FOR DAMAGE TO WINDOWS AND WINDSHIELDS, CABIN WINDOWS AND TRANSPARENCIES REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
56-10-01-900-801-01 56.010	PILOT WINDSHIELD ASSY, (LH) MY20267-10-8 2999 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-01-900-801-02	COPILOT WINDSHIELD ASSY, (LH) MY20268-10-8 3136 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-JAN-1998 43 28		
56-10-01-900-801-03	FRONT WINDSHIELD ASSY, (LH) MY20261-10-8 2990 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-10-07-900-801-01	RH LATERAL WINDOW MY20263-10-6 4724 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 56-10-09-640-801-01 (s)	LUBRICATION OF THE OPENING WINDOW MECHANISM - LH SLIDING WINDOW (145H1) PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
56-10-09-900-801-01	OPENING WINDOW MY20264-10-5 4705 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-10-11-900-801-01	LH REAR WINDOW F50B265001001B5 69 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			05-NOV-2012 6214 3950		
56-10-11-900-801-02	RH REAR WINDOW F50B266001001B5 796 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-01	NO. 1 LEFT PASSENGER CABIN WINDOW F50B228100A4 7163 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-02	NO. 2 LEFT PASSENGER CABIN WINDOW F50B228100A4 7138 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-03	NO. 3 LEFT PASSENGER CABIN WINDOW F50B228100A4 7160 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-04	NO. 4 LEFT PASSENGER CABIN WINDOW F50B228100A4 7135 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-05	NO. 5 LEFT PASSENGER CABIN WINDOW F50B228100A4 7162 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-06	NO. 6 LEFT PASSENGER CABIN WINDOW F50B228100A4 7137 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-07	NO. 7 LEFT PASSENGER CABIN WINDOW F50B228100A4 7150 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-08	NO. 1 RIGHT PASSENGER CABIN WINDOW F50B228100A4 7152 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-09	NO. 2 RIGHT PASSENGER CABIN WINDOW F50B228100A4 7134 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-10	NO. 3 RIGHT PASSENGER CABIN WINDOW F50B228100A4 7151 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-11	NO. 4 RIGHT PASSENGER CABIN WINDOW F50B228100A4 7136 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-12	NO. 5 RIGHT PASSENGER CABIN WINDOW F50B228100A4 7159 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-13	NO. 6 RIGHT PASSENGER CABIN WINDOW F50B228100A4 7286 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
56-20-05-900-801-14	NO. 7 RIGHT PASSENGER CABIN WINDOW F50B228100A4 7290 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561136	LH DEFOGGING VALVE								
56.050	L95-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
561141	RH DEFOGGING VALVE								
56.050	L95-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
CHAPTER 57 WINGS									
+ 57-00-00-210-801-03 (s)	GENERAL VISUAL INSPECTION OF THE LH WING						PKG		
57.0101	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
57-00-00-210-801-03C	GENERAL VISUAL INSPECTION OF THE LH WING (CPCP)								
57.035	REF: See Workcard	MOS HRS/MSC AFL	25				15-APR-2018 7651.3 5046	15-MAY-2020	
CPCP									
+ 57-00-00-210-801-04 (s)	GENERAL VISUAL INSPECTION OF THE RH WING						PKG		
57.0101	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			15-APR-2018 7651.3 5046		
57-00-00-210-801-04C	GENERAL VISUAL INSPECTION OF THE RH WING (CPCP)								
57.035	REF: See Workcard	MOS HRS/MSC AFL	25				15-APR-2018 7651.3 5046	15-MAY-2020	
CPCP									
+ 57-00-00-220-802-01 (s)	DETAILED INSPECTION LH OF THE WINGS						PKG		
57.0102	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			24-FEB-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-00-220-802-01C	DETAILED INSPECTION LH OF THE WING (CPCP)								
57.045		MOS	74				24-FEB-2016	24-APR-2022	
CPCP	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
+ 57-00-00-220-802-02 (s)	DETAILED INSPECTION RH OF THE WINGS						PKG		
57.0102	PKG 31	MOS	72	+2m			24-FEB-2016		
	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
57-00-00-220-802-02C	DETAILED INSPECTION RH OF THE WING (CPCP)								
57.045		MOS	74				24-FEB-2016	24-APR-2022	
CPCP	REF: See Workcard	HRS/MSC					7065.7		
		AFL					4612		
57-00-00-760-801-01 (s)	CHECK ELECTRICAL BONDING OF THE WING MOVABLE SURFACE (LH AILERON)						PKG		
57.240	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
57-00-00-760-801-02 (s)	CHECK RH ELECTRICAL BONDING OF THE WING MOVABLE SURFACE (RH AILERON)						PKG		
57.240	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
57-00-00-760-801-03 (s)	CHECK ELECTRICAL BONDING OF THE WING MOVABLE SURFACE (LH FLAPS)						PKG		
57.250	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		
57-00-00-760-801-04 (s)	CHECK ELECTRICAL BONDING OF THE WING MOVABLE SURFACE (RH FLAPS)						PKG		
57.250	PKG 16	MOS	24	+1m			15-APR-2018		
	REF: See Workcard	HRS/MSC					7651.3		
		AFL					5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-00-760-801-05 (s) 57.260	CHECK ELECTRICAL BONDING OF THE WING MOVABLE SURFACE (LH SLATS) PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
57-00-00-760-801-06 (s) 57.260	CHECK ELECTRICAL BONDING OF THE WING MOVABLE SURFACE (RH SLATS) PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
57-00-00-760-801-07 (s) 57.270	CHECK ELECTRICAL BONDING OF THE WING MOVABLE SURFACE (LH AIRBRAKES) PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
57-00-00-760-801-08 (s) 57.270	CHECK ELECTRICAL BONDING OF THE WING MOVABLE SURFACE (RH AIRBRAKES) PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 15-APR-2018 7651.3 5046		
57-00-01-900-801-01	LH WING PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		18-SEP-1997 0 0		
57-00-01-900-801-02	RH WING PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		18-SEP-1997 0 0		
+ 57-10-00-220-801-01 57.150	DETAILED INSPECTION LEFT MAIN LANDING GEAR OF THE MLG WHEEL WELL GAP SEALING BRUSHES REF: See Workcard	MOS HRS/MSC AFL	O/C				23-OCT-2003 2404.2 1853		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-00-220-801-02	DETAILED INSPECTION RIGHT MAIN LANDING GEAR OF THE MLG WHEEL WELL GAP SEALING BRUSHES								
57.150	REF: See Workcard	MOS HRS/MSC AFL	O/C				23-OCT-2003 2404.2 1853		
+ 57-10-00-290-801-01 (s)	BORESCOPE INSPECTION OF THE WING TANKS						PKG		
57.030	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			11-APR-2016 7065.7 4612		
57-10-00-290-801-01A	BORESCOPE INSPECTION OF THE WING TANKS (MANDATORY 5-40)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	74				11-APR-2016 7065.7 4612	11-JUN-2022	
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP)								
57.057 CPCP	REF: See Workcard	MOS HRS/MSC AFL	74				11-APR-2016 7065.7 4612	11-JUN-2022	
57-10-01-220-801-01A	DETAILED INSPECTION OF LOWER WING PANELS (MANDATORY 5-40)								
57.172 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0	20000	
57-10-01-270-801-01	ULTRASONIC INSPECTION OF THE WING LOWER SURFACE PANEL STIFFENERS BETWEEN RIBS 13 AND 17								
57.290	REF: See Workcard	MOS HRS/MSC AFL	14200				18-SEP-1997 0 0	14200	
+ 57-10-01-270-801-01A	ULTRASONIC INSPECTION OF THE WING LOWER SURFACE PANEL STIFFENERS BETWEEN RIBS 13 AND 17 (MANDATORY 5-40)								
57.295 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	14200				18-SEP-1997 0 0	14200	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-01-280-801-01	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS PKG 35	MOS					18-SEP-1997		
57.280	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
57-10-01-280-801-01A	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS (MANDATORY 5-40)	MOS					18-SEP-1997		
57.165 MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
57-10-01-280-801-01C	SPECIAL DETAILED INSPECTION (ULTRASONIC) OF LOWER WING PANELS AND MAPPING OF REWORKED AREAS (CPCP)	MOS	384				18-SEP-1997	18-SEP-2029	
57.065 CPCP	REF: See Workcard	HRS/MSC AFL					0 0		
57-10-14-200-801-01A	INSPECTION OF WING FRONT SPAR FROM ROOT TO RIB 8 AND FROM RIB 9 TO RIB 17 (MANDATORY 5-40)	MOS					18-SEP-1997		
57.175 MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
57-10-14-200-802-01A	INSPECTION OF WING FRONT SPAR FROM RIB 8 TO RIB 9 (MANDATORY 5-40)	MOS					18-SEP-1997		
57.182 MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
57-10-15-200-801-01A	INSPECTION OF WING REAR SPAR 1 FROM ROOT TO RIB 3 (MANDATORY 5-40)	MOS					18-SEP-1997		
57.192 MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
57-10-15-200-802-01A	INSPECTION OF WING REAR SPAR 2 FROM RIB 3 TO RIB 17 (MANDATORY 5-40)	MOS					18-SEP-1997		
57.185 MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-15-250-801-01A	EDDY CURRENT INSPECTION OF WING REAR SPAR RIB 8 SPLICE (MANDATORY 5-40)								
57.195		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
57-45-01-900-801-01	LH INBOARD LEFT INBOARD MOVABLE SLAT								
57.110	F50B133	MOS					18-SEP-1997		
	478R1	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
57-45-01-900-801-02	RH INBOARD RIGHT INBOARD MOVABLE SLAT								
57.110	F50B143	MOS					18-SEP-1997		
	479RA	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
57-45-13-900-801-01	LH OUTBOARD LEFT OUTBOARD MOVABLE SLAT								
57.120	F50B134	MOS					18-SEP-1997		
	535R1	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
57-45-13-900-801-02	RH OUTBOARD RIGHT OUTBOARD MOVABLE SLAT								
57.120	F50B144	MOS					18-SEP-1997		
	533RA	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		
57-45-25-250-801-01A	EDDY CURRENT INSPECTION OF SLAT TRACKS (MANDATORY 5-40)								
57.225		MOS					18-SEP-1997		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
57-55-00-700-801-01 (s)	CHECK LH OF THE FLAP LATERAL CLEARANCE						PKG		
57.235	PKG 31	MOS	72	+2m			01-APR-2016		
		HRS/MSC					7065.7		
	REF: See Workcard	AFL					4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-55-00-700-801-02 (s)	CHECK RH OF THE FLAP LATERAL CLEARANCE						PKG		
57.235	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
57-55-01-900-801-01	LH INBOARD FLAP								
57.070	F50B161 LE266 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57-55-01-900-801-02	RH INBOARD FLAP								
57.070	F50B162 LE266 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57-55-05-900-801-01	LH OUTBOARD FLAP								
57.080	F50B163 LE253 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57-55-05-900-801-02	RH OUTBOARD FLAP								
57.080	F50B164 LE253 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 57-55-07-220-801-01 (s)	DETAILED INSPECTION OF THE PROTECTION ON LH WING INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG		
57.130	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
+ 57-55-07-220-801-02 (s)	DETAILED INSPECTION OF THE PROTECTION ON RH WING INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG		
57.130	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-55-07-900-801-01	INBOARD / OUTBOARD FLAP JUNCTION FAIRING								
57.130	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
+ 57-55-11-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE LH WING FORE FLAP BRACKETS						PKG		
57.140	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
+ 57-55-11-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE RH WING FORE FLAP BRACKETS						PKG		
57.140	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
57-55-13-640-801-01	GREASING/LUBRICATION OF THE LH WING FLAP ROLLERS AND TRACKS								
	REF: See Workcard	MOS HRS/MSC AFL	24 800	+1m +30			15-APR-2018 7651.3 5046	15-APR-2020 8451.3	15-MAY-2020 8481.3
57-55-13-640-801-02	GREASING/LUBRICATION OF THE RH WING FLAP ROLLERS AND TRACKS								
	REF: See Workcard	MOS HRS/MSC AFL	24 800	+1m +30			15-APR-2018 7651.3 5046	15-APR-2020 8451.3	15-MAY-2020 8481.3
57-55-21-250-801-01	EDDY CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5								
57.310	REF: See Workcard	MOS HRS/MSC AFL	7900				18-SEP-1997 0 0	7900	
57-55-21-250-801-01A	EDDY CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5 (MANDATORY 5-40)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	7900				18-SEP-1997 0 0	7900	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-00-220-801-01A	DETAILED INSPECTION OF THE AILERON SKIN AND HINGE FITTINGS (MANDATORY 5-40)								
57.210 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0	20000	
57-60-01-900-801-01	LH AILERON								
57.020	F50B-151B5 111A0100 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			20-JUL-2010 5686.9 3551		
57-60-01-900-801-02	RH AILERON								
57.020	F50B152B5 111A0100 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-JUL-2010 5686.9 3551		
57-60-05-640-801-01 (s)	PRESSURE LUBRICATION OF THE AILERON BEARINGS - LH AILERON BEARINGS								
57.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
57-60-05-640-801-02 (s)	PRESSURE LUBRICATION OF THE AILERON BEARINGS - RH AILERON BEARINGS								
57.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-APR-2016 7065.7 4612		
57-60-05-640-802-01 (s)	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - LH AILERON								
	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
57-60-05-640-802-02 (s)	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - RH AILERON								
	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-09-270-801-01	ULTRASONIC INSPECTION OF THE COMPOSITE MATERIAL AILERONS - LH AILERON F50B153A1								
57.020	REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUL-2010		
57-60-09-270-801-02	ULTRASONIC INSPECTION OF THE COMPOSITE MATERIAL AILERONS - RH AILERON F50B154A1								
57.020	REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
57-70-01-900-801-01	LH OUTBOARD LEFT OUTBOARD AIRBRAKE FGFB165 516LE	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57.090	REF: See Workcard								
57-70-01-900-801-02	LH MIDDLE LEFT CENTRAL AIRBRAKE FGFB169 1019LE	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57.090	REF: See Workcard								
57-70-01-900-801-03	LH INBOARD LEFT INBOARD AIRBRAKE FGFB167 508LE	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57.090	REF: See Workcard								
57-70-01-900-801-04	RIGHT INBOARD AIRBRAKE FGFB168 511LE	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57.100	REF: See Workcard								
57-70-01-900-801-05	RH MIDDLE RIGHT CENTRAL AIRBRAKE FGFB169 1020LE	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57.100	REF: See Workcard								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-01-900-801-06	RH OUTBOARD RIGHT OUTBOARD AIRBRAKE								
57.100	FGFB166 509LE REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
57-70-03-640-801-01 (s)	LUBRICATION OF THE AIRBRAKE HINGES								
	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 15-APR-2018 7651.3 5046		
57-70-03-960-801-01	DISCARD LH OUTBOARD AIRBRAKE CENTRAL HINGE								
57.230 LIFE LIMIT	F50B165003001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	20000		TSI:0 TSI:0		18-SEP-1997 0 0		20000
57-70-03-960-801-01A	DISCARD LH OUTBOARD AIRBRAKE CENTRAL HINGE (MANDATORY 5-40)								
MANDATORY 5-40	F50B165003001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0		20000
57-70-03-960-801-02	DISCARD RH OUTBOARD AIRBRAKE CENTRAL HINGE								
57.230 LIFE LIMIT	F50B165003001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	20000		TSI:0 TSI:0		18-SEP-1997 0 0		20000
57-70-03-960-801-02A	DISCARD RH OUTBOARD AIRBRAKE CENTRAL HINGE (MANDATORY 5-40)								
MANDATORY 5-40	F50B165003001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0		20000
570701	CENTRAL WING SECTION								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575151	LINKING FAIRING-INBOARD FLAP-LEFT OUTBOARD FLAP ASSEMBLY								
57.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
575181	LH OUTBOARD AIRBRAKE CENTRAL HINGE								
57.230	F50B165003001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
575186	RH OUTBOARD AIRBRAKE CENTRAL HINGE								
57.230	F50B165003001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
CHAPTER 71 POWER PLANT									
71-00-00-910-802-01	PERFORM NO. 1 ENGINE INSPECTION RUN-UP								
	REF: See Workcard	MOS HRS/MSC AFL	C/C				18-SEP-1997 0 0		
71-00-00-910-802-02	PERFORM NO. 2 ENGINE INSPECTION RUN-UP								
	REF: See Workcard	MOS HRS/MSC AFL	C/C				18-SEP-1997 0 0		
71-00-00-910-802-03	PERFORM NO. 3 ENGINE INSPECTION RUN-UP								
	REF: See Workcard	MOS HRS/MSC AFL	C/C				18-SEP-1997 0 0		
71-20-01-220-801-01A	DETAILED INSPECTION OF ENGINE 1 AND 3 FRONT AND REAR MOUNTS (MANDATORY 5-40)								
54.075 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0	20000	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-02-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE NO. 1 ENGINE FRONT MOUNTS REF: See Workcard	MOS HRS/MSC AFL					18-SEP-1997 0 0		11250
71-20-02-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE NO. 3 ENGINE FRONT MOUNTS REF: See Workcard	MOS HRS/MSC AFL					18-SEP-1997 0 0		11250
71-20-02-250-801-03	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE NO. 1 ENGINE FAIL SAFE ATTACHMENTS REF: See Workcard	MOS HRS/MSC AFL					18-SEP-1997 0 0		11250
71-20-02-250-801-04	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE NO. 3 ENGINE FAIL SAFE ATTACHMENTS REF: See Workcard	MOS HRS/MSC AFL					18-SEP-1997 0 0		11250
71-20-05-350-801-01	RESTORATION NO. 1 ENGINE UPPER FRONT MOUNT (OVERHAUL) LM-833-SA20-6 LK0159 REF: See Workcard	MOS HRS/MSC AFL	6000	+200			15-FEB-2007 4781 3071		10781 10981
71-20-05-350-801-02	RESTORATION NO. 1 ENGINE LOWER FRONT MOUNT (OVERHAUL) LM-833-SA20-6 LK0214 REF: See Workcard	MOS HRS/MSC AFL	6000	+200			15-FEB-2007 4781 3071		10781 10981
71-20-05-350-801-03	RESTORATION NO. 3 ENGINE UPPER FRONT MOUNT (OVERHAUL) LM-833-SA20-6 LK5814 REF: See Workcard	MOS HRS/MSC AFL	6000	+200			23-APR-2007 4899 3115		10899 11099

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-05-350-801-04	RESTORATION NO. 3 ENGINE LOWER FRONT MOUNT (OVERHAUL)								
	LM-833-SA20-6	MOS					23-APR-2007		
	LK5807	HRS/MSC	6000	+200			4899	10899	11099
OVERHAUL	REF: See Workcard	AFL					3115		
71-20-05-900-801-01	NO. 1 ENGINE UPPER FRONT MOUNT								
	LM-833-SA20-6	MOS		TSO:0			15-FEB-2007		
71.050	LK0159	HRS/MSC	O/C	TSO:0			4781		
	REF: See Workcard	AFL		TSO:0			3071		
71-20-05-900-801-02	NO. 1 ENGINE LOWER FRONT MOUNT								
	LM-833-SA20-6	MOS					15-FEB-2007		
71.050	LK0214	HRS/MSC	O/C				4781		
	REF: See Workcard	AFL					3071		
71-20-05-900-801-03	NO. 3 ENGINE UPPER FRONT MOUNT								
	LM-833-SA20-6	MOS		TSN:0			20-APR-2007		
71.055	LK5814	HRS/MSC	O/C	TSN:0			4899		
	REF: See Workcard	AFL		TSN:0			3115		
71-20-05-900-801-04	NO. 3 ENGINE LOWER FRONT MOUNT								
	LM-833-SA20-6	MOS		TSN:0			20-APR-2007		
71.055	LK5807	HRS/MSC	O/C	TSN:0			4899		
	REF: See Workcard	AFL		TSN:0			3115		
71-20-07-250-801-01	SPECIAL DETAILED INSPECTION (NDT) OF THE ENGINE 1 REAR MOUNTS								
		MOS					18-SEP-1997		
54.100		HRS/MSC					0		
	REF: See Workcard	AFL	11250				0	11250	
71-20-07-250-801-02	SPECIAL DETAILED INSPECTION (NDT) OF THE ENGINE 3 REAR MOUNTS								
		MOS					18-SEP-1997		
54.100		HRS/MSC					0		
	REF: See Workcard	AFL	11250				0	11250	



Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-09-350-801-01	RESTORATION NO. 1 ENGINE AFT MOUNT (OVERHAUL) LM-833-SA18-1 LK1371 REF: See Workcard	MOS HRS/MSC AFL	6000	+200			15-FEB-2007 4781 3071	10781	10981
OVERHAUL									
71-20-09-350-801-02	RESTORATION NO. 3 ENGINE AFT MOUNT (OVERHAUL) LM-833-SA18-1 LK1355 REF: See Workcard	MOS HRS/MSC AFL	6000	+200			23-APR-2007 4899 3115	10899	11099
OVERHAUL									
71-20-09-900-801-01	NO. 1 ENGINE AFT MOUNT LM-833-SA18-1 LK1371 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		15-FEB-2007 4781 3071		
71.070									
71-20-09-900-801-02	NO. 3 ENGINE AFT MOUNT LM-833-SA18-1 LK1355 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		20-APR-2007 4899 3115		
71.080									
71-20-11-220-801-01A	DETAILED INSPECTION OF ENGINE 2 HOISTING PLATE AND MOUNTS (MANDATORY 5-40) MANDATORY 5-40	MOS HRS/MSC AFL	20000				18-SEP-1997 0 0	20000	
54.082									
71-20-11-900-801-01	NO. 2 ENGINE LEFT FRONT SHOCK MOUNT LM833SA21 LK0314 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-FEB-2007 4781 3071		
71.045									
71-20-11-900-801-02	NO. 2 ENGINE RIGHT FRONT SHOCK MOUNT LM833SA21 LK0317 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-FEB-2007 4781 3071		
71.046									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-11-900-801-03	NO. 2 ENGINE REAR SHOCK MOUNT LM-833-SA22 LK0120 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-FEB-2007 4781 3071		
71.047									
71-20-17-230-801-01	SPECIAL DETAILED INSPECTION NO. 2 ENGINE LEFT FRONT SHOCK MOUNT AND REPLACEMENT OF RUBBER CORES LM833SA21 LK0314 REF: See Workcard	MOS HRS/MSC AFL	6000	+200			15-FEB-2007 4781 3071	10781	10981
71-20-17-230-801-02	SPECIAL DETAILED INSPECTION NO. 2 ENGINE RIGHT FRONT SHOCK MOUNT AND REPLACEMENT OF RUBBER CORES LM833SA21 LK0317 REF: See Workcard	MOS HRS/MSC AFL	6000	+200			15-FEB-2007 4781 3071	10781	10981
71-20-21-960-801-01	DISCARD NO. 2 ENGINE REAR SHOCK MOUNT VIBRATION ISOLATOR LM-833-SA22 LK0120 REF: See Workcard	MOS HRS/MSC AFL	6000				15-FEB-2007 4781 3071	10781	
71.065 LIFE LIMIT									
71-20-23-900-801-01	NO. 2 ENGINE HOIST PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
71EN1	NO. 1 ENGINE 3060050-1 P115150 REF: See Workcard	MOS HRS/MSC AFL	E/C			TSN:7076.3	04-MAR-2017 7347.9 4822		
71.EN1									
71EN2	NO. 2 ENGINE 3060050-1 P115154 REF: See Workcard	MOS HRS/MSC AFL	E/C			TSN:7229.3	04-MAR-2017 7347.9 4822		
71.EN2									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN3	NO. 3 ENGINE								
71.EN3	3060050-1 P115153 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:7229.3			04-MAR-2017 7347.9 4822		

ENGINE NO. 1 Model : TFE731-40-1C Serial # P115150 Part # 3060050-1

+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)	MOS HRS/MSC ENC	3000	+100			04-MAR-2017 7076.5 4684	(10076.5) 10348.1	10176.5
	REF: LMM 72-00-00								
+ 710130 (s)	NO. 1 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY						PKG		
	PKG 3	MOS HRS/MSC ENC	800	+50			04-MAR-2017 7076.5 4684		
	REF: LMM 72-50-04								
+ 710140 (s)	NO. 1 ENGINE - INSPECT INLET/FAN AREA						PKG		
	PKG 3	MOS HRS/MSC ENC	800	+50			04-MAR-2017 7076.5 4684		
	REF: LMM 72-00-00								
+ 714010 (s)	NO. 1 ENGINE - VISUALLY INSPECT ELECTRICAL WIRES AND CONNECTIONS						PKG		
	PKG 3	MOS HRS/MSC ENC	800	+50			04-MAR-2017 7076.5 4684		
	REF: LMM 70-00-00								
+ 715010 (s)	NO. 1 ENGINE - VISUALLY INSPECT PLUMBING LINES AND CONNECTIONS						PKG		
	PKG 3	MOS HRS/MSC ENC	800	+50			04-MAR-2017 7076.5 4684		
	REF: LMM 70-00-00								

ENGINE NO. 2 Model : TFE731-40-1C Serial # P115154 Part # 3060050-1

+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								
		MOS HRS/MSC ENC	3000	+100			03-MAR-2017 7229.5 4787	(10229.5) 10348.1	10329.5
	REF: LMM 72-00-00								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710130 (s)	NO. 2 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY PKG 3 REF: LMM 72-50-04	MOS HRS/MSC ENC	800	+50			PKG 03-MAR-2017 7229.5 4787		
+ 710140 (s)	NO. 2 ENGINE - INSPECT INLET/FAN AREA PKG 3 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50			PKG 03-MAR-2017 7229.5 4787		
+ 714010 (s)	NO. 2 ENGINE - VISUALLY INSPECT ELECTRICAL WIRES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 03-MAR-2017 7229.5 4787		
+ 715010 (s)	NO. 2 ENGINE - VISUALLY INSPECT PLUMBING LINES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 03-MAR-2017 7229.5 4787		
ENGINE NO. 3 Model : TFE731-40-1C Serial # P115153 Part # 3060050-1									
+ 710120	NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI) REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100			03-MAR-2017 7229.5 4787	(10229.5) 10348.1	10329.5
+ 710130 (s)	NO. 3 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY PKG 3 REF: LMM 72-50-04	MOS HRS/MSC ENC	800	+50			PKG 03-MAR-2017 7229.5 4787		
+ 710140 (s)	NO. 3 ENGINE - INSPECT INLET/FAN AREA PKG 3 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50			PKG 03-MAR-2017 7229.5 4787		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 714010 (s)	NO. 3 ENGINE - VISUALLY INSPECT PKG 3 REF: LMM 70-00-00	ELECTRICAL WIRES AND CONNECTIONS MOS HRS/MSC ENC	800	+50			PKG 03-MAR-2017 7229.5 4787		
+ 715010 (s)	NO. 3 ENGINE - VISUALLY INSPECT PKG 3 REF: LMM 70-00-00	PLUMBING LINES AND CONNECTIONS MOS HRS/MSC ENC	800	+50			PKG 03-MAR-2017 7229.5 4787		

CHAPTER 72 ENGINE
ENGINE NO. 1 Model : TFE731-40-1C Serial # P115150 Part # 3060050-1

720110	NO. 1 ENGINE - ACCESSORY GEARBOX 3060827-3 S284 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
720210	NO. 1 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				28-SEP-2001 1607		
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				18-SEP-1997 0 0		
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				18-SEP-1997 0 0		
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723010	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH REF: LMM 72-00-00	MOS HRS/MSC ENC	1500	+150			10-MAR-2017 7076.5 4684	(8576.5) 8848.1	8726.5
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 3060625-1 960322902230 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			01-MAR-1997 0 0	(12000) 12136	
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3060611-1 960322902508 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			01-MAR-1997 0 0	(12000) 12136	
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3060671-2 960322902082 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			01-MAR-1997 0 0	(12000) 12136	
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC 3060841-1 031217200102 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			14-JUL-2003 2155.8 1706	(11706) 11842	
725050	NO. 1 ENGINE - FAN DISC 3060287-1 950322905386 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			01-MAR-1997 0 0	(20000) 20136	
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 020316001694 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			14-JUL-2003 2155.8 1706	(11706) 11842	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 960316003229 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			01-MAR-1997 0 0	(10000) 10136	
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 960316001935 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			01-MAR-1997 0 0	(20000) 20136	
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 031365101143 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			14-JUL-2003 2155.8 1706	(21706) 21842	
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 961119500200 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			14-JUL-2003 2155.8 1706		
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 020322902588 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000	TSN:0 TSN:0 TSN:0			14-JUL-2003 2155.8 1706	(9706) 9842	
725130	NO. 1 ENGINE - FAN SPINNER 3060156-2 970811400130 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			01-MAR-1997 0 0	(20000) 20136	
725140	NO. 1 ENGINE - FAN DRIVE SHAFT 3060180-1 950339000388 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725160	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1 951903300921	MOS HRS/MSC ENC		TSN:2155.8 TSR:0 TSN:1706 TSR:0			14-JUL-2003 2155.8 1706		(7000) 7136
LIFE LIMIT	REF: GENERIC NO REF		7000						
725170	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-3 02P20013	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2003 2155.8 1706		
725180	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-3 97P00413	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
725210	NO. 1 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1 95032293149	MOS HRS/MSC ENC		TSN:0 TSN:0			01-MAR-1997 0 0		(10000) 10136
LIFE LIMIT	REF: GENERIC NO REF		10000						
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-4 96P09146	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1 96P19276	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-7 96P17307	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
LIFE LIMIT	REF: LMM 05-10-01								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725250	NO. 1 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 96P21041 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 96P21152 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
725270	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 96P19174 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
+ 726010	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI) REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			18-APR-2007 4627.3 2965	(10627.3) 10898.9	10827.3
726020	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
726801	NO. 1 ENGINE - ACCESSORY GEARBOX GENERATOR CARBON SEAL 3072784-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			13-DEC-2007 5113.3		
727010 (s)	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY PKG 4 REF: See Workcard	MOS HRS/MSC ENC	1200	+100			PKG 04-MAR-2017 7076.5 4684		

ENGINE NO. 2 Model : TFE731-40-1C Serial # P115154 Part # 3060050-1

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720110	NO. 2 ENGINE - ACCESSORY GEARBOX 3060827-3 S293 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		
720210	NO. 2 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				28-SEP-2001 1607		
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				18-SEP-1997 0 0		
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				18-SEP-1997 0 0		
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				18-SEP-1997 0 0		
+ 723010	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH REF: LMM 72-00-00	MOS HRS/MSC ENC	1500	+150			17-FEB-2017 7229.5 4787	(8729.5) 8848.1	8879.5
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 3060625-1 960322902783 LIFE LIMIT	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			06-MAR-1997 0 0	(12000) 12033	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3060611-1 960322903386	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			06-MAR-1997 0 0		(12000) 12033
LIFE LIMIT	REF: GENERIC NO REF								
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3060671-2 960322902068	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			06-MAR-1997 0 0		(12000) 12033
LIFE LIMIT	REF: GENERIC NO REF								
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC 3060841-1 031217200101	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			03-APR-2007 4783 3071		(13071) 13104
LIFE LIMIT	REF: GENERIC NO REF								
725050	NO. 2 ENGINE - FAN DISC 3060287-1 960322904682	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			06-MAR-1997 0 0		(20000) 20033
LIFE LIMIT	REF: GENERIC NO REF								
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 960316003911	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			06-MAR-1997 0 0		(10000) 10033
LIFE LIMIT	REF: GENERIC NO REF								
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 960316003238	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			06-MAR-1997 0 0		(10000) 10033
LIFE LIMIT	REF: GENERIC NO REF								
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 960316003634	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			06-MAR-1997 0 0		(20000) 20033
LIFE LIMIT	REF: GENERIC NO REF								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 960350102202 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			06-MAR-1997 0 0	(20000) 20033	
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 97P01479 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				02-OCT-2003 2404.2 1853		
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 965332201306 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000	TSN:0 TSN:0			06-MAR-1997 0 0	(8000) 8033	
725130	NO. 2 ENGINE - FAN SPINNER 3060156-2 970811400141 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			06-MAR-1997 0 0	(20000) 20033	
725140	NO. 2 ENGINE - FAN DRIVE SHAFT 3060180-1 960339000113 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		
725160	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1 961903300125 REF: GENERIC NO REF	MOS HRS/MSC ENC	7000	TSN:0 TSN:0			06-MAR-1997 0 0	(7000) 7033	
725170	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-1 97P00909 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725180	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-3 97P01144 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		
725210	NO. 2 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1 960322900904 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			06-MAR-1997 0 0	(10000) 10033	
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-4 96P14756 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1 03P05832 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				02-OCT-2003 2404.2 1853		
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-7 97P00553 REF: LMM 05-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		
725250	NO. 2 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 97P00537 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 97P02081 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725270	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 96P20377	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		
LIFE LIMIT	REF: GENERIC NO REF								
+ 726010	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI) REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			10-APR-2007 4780.3 3071	(10780.3) 10898.9	10980.3
726020	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
726801	NO. 2 ENGINE - ACCESSORY GEARBOX GENERATOR CARBON SEAL PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C						
727010 (s)	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY PKG 4 REF: See Workcard	MOS HRS/MSC ENC	1200	+100			PKG 03-MAR-2017 7229.5 4787		
ENGINE NO. 3 Model : TFE731-40-1C Serial # P115153 Part # 3060050-1									
720110	NO. 3 ENGINE - ACCESSORY GEARBOX 3060827-3 S291 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			12-FEB-1997 0 0		
720210	NO. 3 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				28-SEP-2001 1607		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721001	NO. 3 ENGINE - PRESERVATION OF ENGINE	MOS					18-SEP-1997		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
721002	NO. 3 ENGINE - PERFORM ENGINE PRESERVATION CHECK	MOS					18-SEP-1997		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
721003	NO. 3 ENGINE - DE-PRESERVATION OF ENGINE	MOS					18-SEP-1997		
	REF: LMM 72-00-00	HRS/MSC O/C					0		
		ENC					0		
+ 723010	NO. 3 ENGINE - CHECK CARBON SEAL HEALTH	MOS					17-FEB-2017		
	REF: LMM 72-00-00	HRS/MSC 1500	+150				7229.5	(8729.5) 8848.1	8879.5
		ENC					4787		
725010	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC	MOS					12-FEB-1997		
	3060625-1	HRS/MSC		TSN:0			0		
	960322902241	ENC	12000	TSN:0			0	(12000) 12033	
LIFE LIMIT	REF: GENERIC NO REF								
725020	NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC	MOS					12-FEB-1997		
	3060611-1	HRS/MSC		TSN:0			0		
	950322904403	ENC	12000	TSN:0			0	(12000) 12033	
LIFE LIMIT	REF: GENERIC NO REF								
725030	NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC	MOS					12-FEB-1997		
	3060671-2	HRS/MSC		TSN:0			0		
	960322902100	ENC	12000	TSN:0			0	(12000) 12033	
LIFE LIMIT	REF: GENERIC NO REF								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC 3060841-1 061217200773 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			18-APR-2007 4780 3071	(13071) 13104	
725050	NO. 3 ENGINE - FAN DISC 3060287-1 960322902635 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			12-FEB-1997 0 0	(20000) 20033	
725060	NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 960316003924 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			12-FEB-1997 0 0	(10000) 10033	
725070	NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 960316003228 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			12-FEB-1997 0 0	(10000) 10033	
725080	NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 960316004393 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			12-FEB-1997 0 0	(20000) 20033	
725090	NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 960350102267 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			12-FEB-1997 0 0	(20000) 20033	
725110	NO. 3 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 981119500373 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				02-OCT-2003 2404.2 1853		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725120	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 965332201321	MOS HRS/MSC ENC					12-FEB-1997 0 0		
LIFE LIMIT	REF: GENERIC NO REF		8000	TSN:0 TSN:0					(8000) 8033
725130	NO. 3 ENGINE - FAN SPINNER 3060156-2 970811400391	MOS HRS/MSC ENC					12-FEB-1997 0 0		
LIFE LIMIT	REF: GENERIC NO REF		20000	TSN:0 TSN:0					(20000) 20033
725140	NO. 3 ENGINE - FAN DRIVE SHAFT 3060180-1 960339000139	MOS HRS/MSC ENC				O/C	12-FEB-1997 0 0		
LIFE LIMIT	REF: GENERIC NO REF			TSN:0 TSN:0					
725160	NO. 3 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1 961903300127	MOS HRS/MSC ENC					12-FEB-1997 0 0		
LIFE LIMIT	REF: GENERIC NO REF		7000	TSN:0 TSN:0					(7000) 7033
725170	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-1 97P00904	MOS HRS/MSC ENC				O/C	12-FEB-1997 0 0		
LIFE LIMIT	REF: GENERIC NO REF			TSN:0 TSN:0					
725180	NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-3 97P00360	MOS HRS/MSC ENC				O/C	12-FEB-1997 0 0		
LIFE LIMIT	REF: GENERIC NO REF			TSN:0 TSN:0					
725210	NO. 3 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1 960322900899	MOS HRS/MSC ENC					12-FEB-1997 0 0		
LIFE LIMIT	REF: GENERIC NO REF		10000	TSN:0 TSN:0					(10000) 10033

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725220	NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-4 96P03983 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			12-FEB-1997 0 0		
725230	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1 02P20026 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				02-OCT-2003 2404.2 1853		
725240	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-7 02P20514 REF: LMM 05-10-01	MOS HRS/MSC ENC	O/C				02-OCT-2003 2404.2 1853		
725250	NO. 3 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 97P00533 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			12-FEB-1997 0 0		
725260	NO. 3 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 96P14606 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			12-FEB-1997 0 0		
725270	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 02P19802 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				02-OCT-2003 2404.2 1853		
+ 726010	NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI) REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			18-APR-2007 4780.3 3071	(10780.3) 10898.9	10980.3

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726020	NO. 3 ENGINE - TRANSFER GEARBOX ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
726801	NO. 3 ENGINE - ACCESSORY GEARBOX GENERATOR CARBON SEAL 3072784-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			05-NOV-2007 5191		
727010 (s)	NO. 3 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY PKG 4 REF: See Workcard	MOS HRS/MSC ENC	1200	+100			PKG 03-MAR-2017 7229.5 4787		
CHAPTER 73 ENGINE FUEL AND CONTROL									
+ 73-20-01-710-802-01 (s)	OPERATIONAL TEST OF THE ENGINE 1 DIGITAL ELECTRONIC COMPUTER (DEEC 1) DUAL POWER SUPPLY PKG 21 76.040 REF: See Workcard	MOS HRS/MSC AFL	1500	+30			PKG 26-MAY-2017 7416.5 4869		
+ 73-20-01-710-802-01A	OPERATIONAL TEST OF THE ENGINE 1 DIGITAL ELECTRONIC COMPUTER (DEEC 1) DUAL POWER SUPPLY (MANDATORY 5-40) 76.040 MANDATORY 5-40 REF: See Workcard	MOS HRS/MSC AFL	1530				26-MAY-2017 7416.5 4869	8946.5	
73-20-01-900-801-01	NO. 1 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 1) DISPLAY UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
73-20-01-900-801-02	NO. 2 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 2) DISPLAY UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-20-01-900-801-03	NO. 3 ENGINE DIGITAL ELECTRONIC ENGINE CONTROL (DEEC 3) DISPLAY UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
73-30-09-900-801-01 73.090	NO. 1 ENGINE FUEL FLOW TRANSMITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
73-30-09-900-801-02 73.090	NO. 2 ENGINE FUEL FLOW TRANSMITTER 9-231-32 6264 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			20-APR-2007 4899 3115		
73-30-09-900-801-03 73.090	NO. 3 ENGINE FUEL FLOW TRANSMITTER 9-231-32 6550 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-OCT-2005 3891 2599		
733801	NO. 1 ENGINE FUEL BYPASS INDICATOR 5911442-2 1567 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-SEP-2006 4520 2941		
733802	NO. 2 ENGINE FUEL BYPASS INDICATOR 5909244-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
733803	NO. 3 ENGINE FUEL BYPASS INDICATOR 5911442-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		

ENGINE NO. 1 Model : TFE731-40-1C Serial # P115150 Part # 3060050-1

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
730110	NO. 1 ENGINE - FUEL CONTROL UNIT 3070800-30 A3487PTC REF: See Workcard	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0			07-JUL-1999 737		
730120 (s)	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: LMM 73-21-02	MOS HRS/MSC ENC	600	+50			PKG 04-MAR-2017 7076.5 4684		
730130	NO. 1 ENGINE - ENGINE FUEL PUMP 3060719-10 0223 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			01-MAR-1997 0 0		
732120	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: LMM 73-21-04	MOS HRS/MSC ENC	N/A				18-SEP-1997 0 0		

ENGINE NO. 2 Model : TFE731-40-1C Serial # P115154 Part # 3060050-1

730110	NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-39 20275 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			08-FEB-2013 6200.6 3977		
730120 (s)	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: LMM 73-21-02	MOS HRS/MSC ENC	600	+50			PKG 03-MAR-2017 7229.5 4787		
730130	NO. 2 ENGINE - ENGINE FUEL PUMP 3060719-10 0188 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			06-MAR-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732120	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE	MOS					18-SEP-1997		
	REF: LMM 73-21-04	HRS/MSC	N/A				0		
		ENC					0		
ENGINE NO. 3 Model : TFE731-40-1C Serial # P115153 Part # 3060050-1									
730110	NO. 3 ENGINE - FUEL CONTROL UNIT	MOS					23-JAN-2013		
	3070800-39	HRS/MSC	O/C	TSR:0			6185.6		
	18337	ENC		TSR:0			3968		
	REF: See Workcard			TSR:0					
730120 (s)	NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT	MOS					PKG		
	PKG 2	HRS/MSC	600	+50			03-MAR-2017		
	REF: LMM 73-21-02	ENC					7229.5		
							4787		
730130	NO. 3 ENGINE - ENGINE FUEL PUMP	MOS					12-FEB-1997		
	3060719-10	HRS/MSC	O/C	TSN:0			0		
	0229	ENC		TSN:0			0		
	REF: See Workcard								
732120	NO. 3 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE	MOS					18-SEP-1997		
	REF: LMM 73-21-04	HRS/MSC	N/A				0		
		ENC					0		
CHAPTER 74 IGNITION									
ENGINE NO. 1 Model : TFE731-40-1C Serial # P115150 Part # 3060050-1									
740110	NO. 1 ENGINE - IGNITION UNIT	MOS					01-MAR-1997		
	3073914-7	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: LMM 74-00-01								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 NSN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				07-SEP-2007 4869.3		
+ 740140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 04-MAR-2017 7076.5 4684		
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 NONE REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				07-SEP-2007 4869.3		
+ 740160 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 04-MAR-2017 7076.5 4684		
+ 740210 (s)	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 2 REF: LMM 74-00-01	MOS HRS/MSC ENC	600	+50			PKG 04-MAR-2017 7076.5 4684		
ENGINE NO. 2 Model : TFE731-40-1C Serial # P115154 Part # 3060050-1									
740110	NO. 2 ENGINE - IGNITION UNIT 3073914-7 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C			TSN:0 TSN:0	06-MAR-1997 0 0		
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 NONE REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				07-SEP-2007 5022.3		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1500	+150			PKG 03-MAR-2017 7229.5 4787		
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 NONE REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				07-SEP-2007 5022.3		
+ 740160 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1500	+150			PKG 03-MAR-2017 7229.5 4787		
+ 740210 (s)	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 2 REF: LMM 74-00-01	MOS HRS/MSC ENC	600	+50			PKG 03-MAR-2017 7229.5 4787		
ENGINE NO. 3 Model : TFE731-40-1C Serial # P115153 Part # 3060050-1									
740110	NO. 3 ENGINE - IGNITION UNIT 3073914-7 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C			TSN:0 TSN:0	12-FEB-1997 0 0		
740130	NO. 3 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 NONE REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				07-SEP-2007 5032		
+ 740140 (s)	NO. 3 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 03-MAR-2017 7229.5 4787		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740150	NO. 3 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 NONE REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				07-SEP-2007 5032		
+ 740160 (s)	NO. 3 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 03-MAR-2017 7229.5 4787		
+ 740210 (s)	NO. 3 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 2 REF: LMM 74-00-01	MOS HRS/MSC ENC	600	+50			PKG 03-MAR-2017 7229.5 4787		
CHAPTER 75 AIR									
77-20-09-900-801-01	NO. 1 ENGINE INLET PRESSURE/TEMPERATURE SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 18-SEP-1997 0 0		
77-20-09-900-801-02	NO. 2 ENGINE INLET PRESSURE/TEMPERATURE SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 18-SEP-1997 0 0		
77-20-09-900-801-03	NO. 3 ENGINE INLET PRESSURE/TEMPERATURE SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 18-SEP-1997 0 0		
CHAPTER 76 ENGINE CONTROLS									
+ 76-10-00-220-801-01	CHECK LH ENGINE TELEFLEX CONTROL CABLE THROTTLE LEVER FOR FRICTION POINTS 7-43497-1 0326 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-10-00-220-801-02	CHECK CENTER ENGINE TELEFLEX CONTROL CABLE THROTTLE LEVER FOR FRICTION POINTS								
76.030	7-43497-2 0302 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
+ 76-10-00-220-801-03	CHECK RH ENGINE TELEFLEX CONTROL CABLE THROTTLE LEVER FOR FRICTION POINTS								
76.020	7-43497-3 291 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2018 7651.3 5046		
76-10-00-220-802-01	MEASURE LH ENGINE TELEFLEX CONTROL CABLE THROTTLE LEVER OPERATING FORCES								
76.020	7-43497-1 0326 REF: See Workcard	MOS HRS/MSC AFL	O/C				20-APR-2007 4899 3115		
76-10-00-220-802-02	MEASURE CENTER ENGINE TELEFLEX CONTROL CABLE THROTTLE LEVER OPERATING FORCES								
76.030	7-43497-2 0302 REF: See Workcard	MOS HRS/MSC AFL	O/C				20-APR-2007 4899 3115		
76-10-00-220-802-03	MEASURE RH ENGINE TELEFLEX CONTROL CABLE THROTTLE LEVER OPERATING FORCES								
76.020	7-43497-3 291 REF: See Workcard	MOS HRS/MSC AFL	O/C				20-APR-2007 4899 3115		
76-10-21-640-801-01	LUBRICATION LH ENGINE TELEFLEX CONTROL CABLE								
76.020	7-43497-1 0326 REF: See Workcard	MOS HRS/MSC AFL	74 E/C				11-APR-2016 7065.7 4612	11-JUN-2022	
76-10-21-640-801-02	LUBRICATION CENTER ENGINE TELEFLEX CONTROL CABLE								
76.030	7-43497-2 0302 REF: See Workcard	MOS HRS/MSC AFL	74 E/C				11-APR-2016 7065.7 4612	11-JUN-2022	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-10-21-640-801-03	LUBRICATION RH ENGINE TELEFLEX CONTROL CABLE								
76.020	7-43497-3 291 REF: See Workcard	MOS HRS/MSC AFL	74 E/C				11-APR-2016 7065.7 4612	11-JUN-2022	
76-10-21-640-801-04	LUBRICATION LH ENGINE TELEFLEX CONTROL CABLE (AND CONTROL UNIT)								
76.020	7-43497-1 0326 REF: See Workcard	MOS HRS/MSC AFL	74 E/C				11-APR-2016 7065.7 4612	11-JUN-2022	
76-10-21-640-801-05	LUBRICATION CENTER ENGINE TELEFLEX CONTROL CABLE (AND CONTROL UNIT)								
76.030	7-43497-2 0302 REF: See Workcard	MOS HRS/MSC AFL	74 E/C				11-APR-2016 7065.7 4612	11-JUN-2022	
76-10-21-640-801-06	LUBRICATION RH ENGINE TELEFLEX CONTROL CABLE (AND CONTROL UNIT)								
76.020	7-43497-3 291 REF: See Workcard	MOS HRS/MSC AFL	74 E/C				11-APR-2016 7065.7 4612	11-JUN-2022	
76-10-21-900-801-01	LH ENGINE TELEFLEX CONTROL CABLE								
76.020	7-43497-1 0326 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
76-10-21-900-801-02	RH ENGINE TELEFLEX CONTROL CABLE								
76.020	7-43497-3 291 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
76-10-21-900-802-01	CENTER ENGINE TELEFLEX CONTROL CABLE								
76.030	7-43497-2 0302 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-10-33-820-801-01 (s)	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 1 CONTROL CABLE (L501EC)						PKG		
76.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
76-10-33-820-801-02 (s)	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 2 CONTROL CABLE (M501EC)						PKG		
76.030	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
76-10-33-820-801-03 (s)	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 3 CONTROL CABLE (R501EC)						PKG		
76.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-APR-2016 7065.7 4612		
761101	THROTTLE CONTROL UNIT								
76.010	F50B771100A-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
ENGINE NO. 1 Model : TFE731-40-1C Serial # P115150 Part # 3060050-1									
761210	NO. 1 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM								
76.010	2118882-4005 17H0051 REF: See Workcard	MOS HRS/MSC ENC	50				27-SEP-2018 7588.4 5016	(7638.4) 7910	
761330	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL								
76.040	2118882-4005 17H0051 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSO:462			22-NOV-1999 918		
ENGINE NO. 2 Model : TFE731-40-1C Serial # P115154 Part # 3060050-1									
761210	NO. 2 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM								
76.010	2118882-4006 126H0041 REF: See Workcard	MOS HRS/MSC ENC	50				27-SEP-2018 7741.4 5119	(7791.4) 7910	

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761330	NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL								
76.040	2118882-4006 126H0041 REF: See Workcard	MOS HRS/MSC ENC	O/C				14-AUG-2003 2305 1810		
ENGINE NO. 3 Model : TFE731-40-1C Serial # P115153 Part # 3060050-1									
761210	NO. 3 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM								
76.010	2118882-4006 57T0001 REF: See Workcard	MOS HRS/MSC ENC	50				27-SEP-2018 7741.4 5119	(7791.4) 7910	
761330	NO. 3 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL								
76.040	2118882-4006 57T0001 REF: See Workcard	MOS HRS/MSC ENC	O/C				14-AUG-2003 2305 1810		
CHAPTER 77 ENGINE INDICATING									
771121	NO. 1 ENGINE N2 MONOPOLE								
	3070722-7 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
771122	NO. 2 ENGINE N2 MONOPOLE								
	3070722-7 981936000190 REF:	MOS HRS/MSC AFL	O/C				10-JUN-2003 2176 1727		
771123	NO. 3 ENGINE N2 MONOPOLE								
	3070722-7 041936039055 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		12-DEC-2004 3260 2294		
771141	NO. 1 ENGINE DATA DISPLAY UNIT								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771142	NO. 2 ENGINE DATA DISPLAY UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
771143	NO. 3 ENGINE DATA DISPLAY UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
773011	NO.2 ENGINE VIBRATION DISPLAY UNIT C12438AB01 267 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-JUN-2004 2950 2127		
CHAPTER 78 EXHAUST									
78-30-00-910-809-01	PERFORM INHIBITION/ACTIVATION OF THE THRUST REVERSER FOR FLIGHT	MOS HRS/MSC AFL	O/C				18-SEP-1997 0 0		
78-31-00-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE LEFT THRUST REVERSER DOOR HINGE FITTING	MOS HRS/MSC AFL	O/C				25-MAY-2014 6664 4295		
78-31-00-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE RIGHT THRUST REVERSER DOOR HINGE FITTING	MOS HRS/MSC AFL	O/C				25-MAY-2014 6664 4295		
78-31-00-250-802-01 (s)	SPECIAL DETAILED INSPECTION (FLOURESCENT PENETRANT) OF THE LH THRUST REVERSER DOOR HINGE FITTINGS	MOS HRS/MSC AFL		12			15-APR-2018 7651.3 5046		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-00-250-802-01A	SPECIAL DETAILED INSPECTION (FLOURESCENT PENETRANT) OF THE LH THRUST REVERSER DOOR HINGE FITTINGS (MANDATORY 5-40)	MOS HRS/MSC AFL	1155				15-APR-2018 7651.3 5046		6201
MANDATORY 5-40	REF: See Workcard								
78-31-00-250-802-02 (s)	SPECIAL DETAILED INSPECTION (FLOURESCENT PENETRANT) OF THE RH THRUST REVERSER DOOR HINGE FITTINGS	MOS HRS/MSC AFL	12				15-APR-2018 7651.3 5046		
	PKG 15								
	REF: See Workcard								
78-31-00-250-802-02A	SPECIAL DETAILED INSPECTION (FLOURESCENT PENETRANT) OF THE RH THRUST REVERSER DOOR HINGE FITTINGS (MANDATORY 5-40)	MOS HRS/MSC AFL	1155				15-APR-2018 7651.3 5046		6201
MANDATORY 5-40	REF: See Workcard								
78-31-00-640-801-01 (s)	GREASING OF THE THRUST REVERSER ASSEMBLY	MOS HRS/MSC AFL	12	+1m			15-APR-2018 7651.3 5046		
	PKG 15								
78.020	REF: See Workcard								
78-31-01-900-801-01	LH THRUST-REVERSER DOOR	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		18-SEP-1997 0 0		
	PN								
	SN-UNKNOWN								
	REF: See Workcard								
78-31-01-900-801-02	RH THRUST-REVERSER DOOR	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		18-SEP-1997 0 0		
	PN								
	SN-UNKNOWN								
	REF: See Workcard								

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-13-900-801-01	THRUST REVERSER DOOR ACTUATOR								
78.080	F10A5SCH203-4 0258 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-AUG-2003 2337 1828		
783101	THRUST REVERSER SOLENOID VALVE								
78.050	A24521-102 FM1082 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
783106	THRUST REVERSER ACCUMULATOR								
78.010	60909-1 3051 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
783121	THRUST REVERSER PRESSURE INDICATOR								
78.040	18040100 36956C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
783126	THRUST REVERSER FILLER VALVE								
78.050	MS28889-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
783131	LH THRUST REVERSER DISCHARGE VALVE								
78.060	3300-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		02/17/2009	17-FEB-2007 4781 3071		
783136	RH THRUST REVERSER DISCHARGE VALVE								
78.060	3300-6 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783141	LH THRUST REVERSER CHECK VALVE								
78.070	A24515 FM2357 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
783146	RH THRUST REVERSER CHECK VALVE								
78.070	A24515 FM2365 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
783151	THRUST REVERSER LATCHING SOLENOID								
78.030	A861TS4RF50 1602 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-FEB-2006 4130 2726		
783156	THRUST REVERSER LOCKING SOLENOID								
78.030	A861TS4RF50 1181 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
783166	THRUST REVERSER JUNCTION ACTUATOR								
78.080	JEFX0500250AA SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
783201	THRUST REVERSER LOCKING SOLENOID								
78.030	F10A-5-SCAV200-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0 0		
CHAPTER 79 OIL									
79-30-05-900-801-01	NO. 1 ENGINE OIL PRESSURE TRANSMITTER								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-30-05-900-801-02	NO. 2 ENGINE OIL PRESSURE TRANSMITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
79-30-05-900-801-03	NO. 3 ENGINE OIL PRESSURE TRANSMITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
79-30-09-900-801-01	NO. 1 ENGINE OIL PRESSURE SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
79-30-09-900-801-02	NO. 2 ENGINE OIL PRESSURE SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
79-30-09-900-801-03	NO. 3 ENGINE OIL PRESSURE SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
79-30-13-900-801-01	NO. 1 ENGINE OIL TEMPERATURE PROBE MS28034-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0		
79.120									
79-30-13-900-801-02	NO. 2 ENGINE OIL TEMPERATURE PROBE MS28034-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0		
79.120									

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-30-13-900-801-03	NO. 3 ENGINE OIL TEMPERATURE PROBE MS28034-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-SEP-1997 0		
793A61	NO. 2 ENGINE OIL (M4E) PRESSURE SWITCH 1103P0969 0083 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-JUN-2003 2180 1731		
ENGINE NO. 1 Model : TFE731-40-1C Serial # P115150 Part # 3060050-1									
790110	NO. 1 ENGINE - OIL PUMP 3060785-2 011405700159 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			14-JUL-2003 2155.8 1706		
+ 790130	NO. 1 ENGINE - ANALYZE ENGINE OIL AND FILTER PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			05-APR-2018 7379.7 4910	(7529.7) 7801.3	7629.7
790140 (s)	NO. 1 ENGINE - CHANGE OIL PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			PKG 04-MAR-2017 7076.5 4684		
+ 790150 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			04-MAR-2017 7076.5 4684		
790160 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 1 REF: See Workcard	MOS HRS/MSC ENC	150	+100			PKG 05-APR-2018 7379.7 4910		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792205	NO. 1 ENGINE - UPPER OIL COOLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-SEP-1997 0 0		
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE 3060782-2 050645104965 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-MAR-2006 4061		
+ 793315 (s)	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH 3060782-2 PKG 2 050645104965 REF: LMM 79-30-01	DAYS HRS/MSC ENC	600	+50 +50			PKG 31-MAY-2017 7144.9 4730		
ENGINE NO. 2 Model : TFE731-40-1C Serial # P115154 Part # 3060050-1									
790110	NO. 2 ENGINE - OIL PUMP 3060785-2 011405700165 REF: See Workcard	MOS HRS/MSC ENC	O/C				02-OCT-2003 2404.2 1853		
+ 790130	NO. 2 ENGINE - ANALYZE ENGINE OIL AND FILTER PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			05-APR-2018 7532.7 5013	(7682.7) 7801.3	7782.7
790140 (s)	NO. 2 ENGINE - CHANGE OIL PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			PKG 03-MAR-2017 7229.5 4787		
+ 790150 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			PKG 03-MAR-2017 7229.5 4787		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790160 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION						PKG		
79.040	PKG 1 REF: See Workcard	MOS HRS/MSC ENC	150	+100			05-APR-2018 7532.7 5013		
792205	NO. 2 ENGINE - UPPER OIL COOLER								
	160506-4 2479 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSO:0 TSO:0 TSO:0		19-APR-2017 7268.7 4813		
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE								
79.110	3060782-2 030645100725 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		17-MAY-2005 3592 2465		
+ 793315 (s)	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH						PKG		
79.110	3060782-2 PKG 2 030645100725 REF: LMM 79-30-01	DAYS HRS/MSC ENC	600	+50 +50			31-MAY-2017 7297.9 4833		
ENGINE NO. 3 Model : TFE731-40-1C Serial # P115153 Part # 3060050-1									
790110	NO. 3 ENGINE - OIL PUMP								
79.010	3060785-2 95-14057-0060 REF: See Workcard	MOS HRS/MSC ENC	O/C				02-OCT-2003 2404.2 1853		
+ 790130	NO. 3 ENGINE - ANALYZE ENGINE OIL AND FILTER								
79.020	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			05-APR-2018 7532.7 5013	(7682.7) 7801.3	7782.7
790140 (s)	NO. 3 ENGINE - CHANGE OIL						PKG		
79.030	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			03-MAR-2017 7229.5 4787		

Status Report

FALCON 50EX S/N 265 (N868DB): 7927.2 HRS, 5240 AFL as of 26-Feb-2019

Owner/Operator: ALEDO SUB LLC, JLB PARTNERS, LP

Report Date: 26-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 790150 (s)	NO. 3 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK						PKG		
79.040	PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			03-MAR-2017 7229.5 4787		
790160 (s)	NO. 3 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION						PKG		
79.040	PKG 1 REF: See Workcard	MOS HRS/MSC ENC	250				05-APR-2018 7532.7 5013		
792205	NO. 3 ENGINE - UPPER OIL COOLER								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		18-SEP-1997 0 0		
793310	NO. 3 ENGINE - OIL FILTER BYPASS VALVE								
79.110	PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		18-SEP-1997 0 0		
+ 793315 (s)	NO. 3 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH						PKG		
79.110	PN PKG 2 SN-UNKNOWN REF: LMM 79-30-01	DAYS HRS/MSC ENC	600	+50 +50			31-MAY-2017 7297.9 4833		