



VAZEY DRILL PRESS TABLE
INITIAL SET UP.

WITH THE MOUNTING BOLTS LOOSE AND THE CTR. MARK FACING
 TOWARDS THE COLUMN AND THE DRILL-BIT ABOVE HOLE IN "V"
 GROOVE ADJUST TABLE TO FIND CENTRE OF THE V GROOVE THEN
 TIGHTEN BOLTS