
RAIN GUARDING FOR MODERNISING LATEX HARVEST





PROBLEMS

- PANEL GUARDS BECOME LEAKY.
- AFTER 5 MONTHS 50% RAIN GUARDSBECOME LEAKY