

4DX Quality

Wildly Important Goal (WIG):

- Complete every job under budget and ahead of schedule without any quality deficiencies

Lead Measures:

- QMPs
- P6 Schedule
- WIP Inspections
- Procurement
- Material Management

Accountability:

- Track each project team's performance across key metrics

Scorecard:

- Weekly scorecards: NCRs, COPQ

