

FINISHER'S CHOICE

SUBSTRATE MANAGEMENT SYSTEM

TOOL RA REFERENCE SHEET



PREPARATION ZONE



Ra: 700>



Ra: 700 - 601



Ra: 600 - 501



Ra: 500 - 401



Ra: 400 - 251

POLISHING ZONE



Metal Bonds

Hybrids

Ra: 250 - 200

Ra: 200 - 165

Ra: 165 - 145

Ra: 145 - 120


Ra: 85 - 65

Ra: 65 - 45

Ra: 45 - 25

Ra: 20 - 15

Ceramics



MAINTENANCE ZONE

