
THE SAILING MAGAZINE FOR THE REST OF US! www.goodoldboat.com Issue 83 March/April 2012





Speaking seriously

Sailboats 101

14 Hoses 101

There's safety in (specification) numbers by Don Launer

Cruising designs

16 Idiosyncracies of the IOR

How rating-rule number crunchers shaped sailboats by Robert Perry

Dinghy transport

26 Chameleon: a tender in two parts

A nesting hard dinghy that's enduring and endearing by Leslie Linkkila and Philip DiNuovo

Safe sailing

56 Night vision

How we see in the dark, or not by Robert Fisher

Safety first

60 UV exposed

It's invisible, insidious, and destructive by Bill Sandifer

Electronic wizardry

62 Boat, phone home

Have your boat text you when it's in trouble by Van Taiariol

CONTENTS

MARCH/APRIL 2012

For the love of sailboats

Review boat

10 C&C 35 Mk II

A true cruiser/racer, with emphasis on the latter by Allen Penticoff

20 Pearson 26

A perky pocket cruiser built in great numbers by Tom Wells

Refit boat

24 From weekender to months-on-ender

Minor modifications add up to a major improvement by Dan Cripe

Feature boat

49 A well-loved Morgan 42 Mk II

She's seen a lifetime of devotion by David VanDenburgh

Boat comparison

53 The Morgan 42 Mk II ...

... meets veterans designed for similar goals by Ted Brewer

Spotlight on ...

Maintenance tasks

34 Do it right the first time


It takes more thought but saves time (and face) by Bob Norson

37 Holding tank essentials

Practical ways to comply with the law by Gregg Nestor

41 The boat painter's apprentice

A novice learns some tricks from the pros by Barbara Hart



MARCH/APRIL 2012

CONTENTS









What's more

Web sightings

5 What's to see and download on Good Old Boat's websites

The view from here

7 A little relief from winter

Warm up those earbuds and chill . . . by Karen Larson

Mail buoy

8 GPS precursor, pinstripes, and hitchhikers

Cruising memories

31 Deferred maintenance meets microburst

Mother Nature has no respect for job schedules by Scott Gordon

Sailing life

44 Sabres and Scorpions

Classic classes are given new life by Durkee Richards

Simple solutions

64 Scarfing made easy

Using a radial-arm saw and a simple jig by Gordon Otto

Quick and easy

65 Halyard replacement

Do it in a jiffy with a tape splice by Jim Hildinger

66 Homemade clamps

A woodworker sometimes has to extemporize by Connie McBride

67 Temporary diesel tank

A work-around keeps the boat in service by Larry Schremmer

68 Good old classifieds

Reflections

77 Good Old Boat has lost a friend

by Karen Larson



About the cover ...

Wish you were here? *K-Aloha*, Brett Pruitt's 1977 Cal 20 doesn't get to vacation in Hawaii, she *lives* in Hawaii all year. Brett says she had quite a racing history with her first owner. These days, with Brett, she sails the windward side of Oahu and is shown here a mile offshore from Kaneohe.

3



We briefly considered a roll-up inflatable, but its poor performance when rowed in windy conditions concerned us. Also, better-quality Hypalon inflatable sport boats were expensive and subject to UV degradation. This choice also seemed to mandate the purchase of a large, heavy outboard engine that would dictate carrying significant quantities of gasoline when going offshore. A large outboard would also necessitate some sort of lifting

term service, it would resist degradation

in the elements when used every day and

would be easy to maintain and repair.

sailing rig, we had differing opinions.

As to the benefit of a dinghy with a

Next we considered folding-dinghy options (such as the Porta-Bote or the

apparatus, a further deterrent.

26

German Banana Boot), but the long dimension when folded would dictate that it be stowed along the lifelines. This would pose a safety hazard in rough seas and create something to trip over when going forward; we discarded this option.

A solution in two parts

About this time (this was 1996), we became aware of nesting dinghies in general and Danny Greene's designs in particular while reading two of Dan Spurr's books: *Upgrading the Cruising Sailboat* and his biographical tale, *Steered by the Falling Stars:* A Father's Journey. A nesting dinghy is made in two or three separate sections that are bolted or clamped together to form the entire boat. For stowing

aboard (or for transport), the sections are separated and nested together to take up minimal space.

The nesting hard dinghy seemed to us at the time, and in fact still does, like the perfect solution to the tender dilemma, particularly for smaller-sized cruising yachts. Eventually, we found an address for Danny Greene (a naval architect and nesting dinghy pioneer) and requested plans for Two Bits or For Pete's Sake. We learned these plans were no longer available. His designs had evolved over 20 years into the pram he called Chameleon.

Chameleon is a nesting pram, 10-feet 4-inches long when assembled, with a gracefully angled bow transom and hard chines but with a pleasing sheerline.

Good Old Boat March/April 2012 www.goodoldboat.com


a tender in two parts

It's designed to be made of marine plywood, fiberglass cloth, and epoxy and has many desirable, and some unique, features: aft buoyancy tanks, a forward storage compartment, removable fore-and-aft oriented seats to allow for adjusting trim under power, and curved mating bulkheads defined by laminated beams. The sections are simply bolted together in three places to form the complete dinghy. Design options include a sliding rowing seat and a sprit-type sailing rig.

To quote the designer: "Over the years, I experimented with ... {nesting dinghy} dimensions, hull shapes and construction details. I tried boats up to 16 feet in length and with two and three nesting pieces. Some towed beautifully, some sailed very well, some towed well, some were stable, some handled rough weather easily, some were light and compact to stow, and some were very easy to build. None, however, combined these qualities in a way that satisfied me, until Chameleon."

We bought the plans and the optional full-sized patterns for cutting the panels and built our first Chameleon, Diva, as a full-sized rowing version. Because it was our first boatbuilding project, and also our first try at stitch-and-glue construction, we worked slowly and methodically for about a year in our unheated garage on nights and weekends. We followed the plans carefully and made no substitutions or changes. We inevitably made mistakes, but soon learned our way with epoxy resins, filleting blends, and fiberglass cloth as Diva became a reality.

As promised, she stowed compactly, rowed effortlessly with 7½-foot oars, and towed like a dream. Importantly, when stowed securely behind the mast she did not interfere with sail handling. When assembled and under way, she was solid, and it was impossible to tell that she was joined at the mating



The full-sized Chameleon was too long to nest behind *Carina*'s mast, so Philip and Leslie modified Danny Greene's plans to make *Bacio*, above, which has the same freeboard and beam but is only 8 feet long. *Bacio* has been used nearly every day for almost eight years and has proved to be a rugged, reliable, and stable tender, below. Plus she's a pretty boat with a graceful sheerline.



bulkheads. In short, we were thrilled with her, except for one problem. When we sold our Hallberg Mistral sloop, Aria, and acquired Carina, a Mason 33 cutter, we found Diva's nested length was just a trifle too long. It interfered with the use of a reefing winch mounted on the mast beneath the boom.

Chameleon reduced

To solve that problem, we decided to construct *Bacio*, a shorter version of the Chameleon. (Note: The purchase of Danny Greene's plans allows for construction of *one* dinghy; additional boats require a small royalty payment to the designer.) We did not know it at the time, but others had reduced the size of the Chameleon as we had done ... with mixed results.

One version we learned about, called the Gecko, was cut down by reducing all Chameleon dimensions proportionally, yielding an 8-foot 6 inch Chameleon. Though seemingly logical and appropriate on paper, the result was a dinghy with unacceptably low freeboard and insufficient clearance for oars when rowing. In the end, after devoting much labor to adding freeboard, the builder was very pleased with the boat.

Our strategy, done solely by instinct, was to maintain the Chameleon's freeboard and beam but to essentially chop it off at both ends to reduce the overall length to an even 8 feet. We hoped this would allow us to retain most of the Chameleon's carrying capacity and stability but make it fit the available space on Carina when nested. Concerned about modifiving individual panels, and particularly the size and configuration of the transom, we photocopied Danny's plans so we could make a few small models out of lightweight cardboard and masking tape. Eventually, we became confident enough in our design modifications to cut

Dinghy transport

plywood. In the end, we preserved the bow dimensions but made the transom slightly bigger than on the original.

Another change we made when constructing Bacio was to use 4mm okoume plywood. Okoume plywood is made from the African hardwood Aucoumea klaineana and is used in aircraft, kayaks, and acoustic guitars. We used this in place of the specified thicker 1/4-inch marine plywood for all the panels with the exception of the bulkheads, bow, and transom. We chose okoume because of its very high strength-to-weight ratio and a desire to reduce weight. though we did so at the expense of rot resistance. Because we used this type of plywood, we sealed every surface of Bacio with epoxy and fiberglass, except for the insides of the flotation chambers. Failing to seal the flotation chambers proved to be a bad decision; eventually, water incursion in the chambers allowed fungus to attack the wood.

For inwales and outwales, we chose ash, which is light, knot-free, and strong. We stitched the panels together with monofilament line instead of copper wire to save time. We cut curved knees for aesthetic reasons and through-bolted pad-eyes at all four corners of both halves (eight in total) to facilitate lifting and launch. Also, during construction, we placed a thick piece of corrugated cardboard of the exact dimensions of the mating bulkheads between them before we screwed the bulkheads together. This helped create a "soft" center space to guide our saw and prevent damage to the bulkheads when cutting the boat in two, a problem we had had when building Diva.

When building *Bacio*, we eliminated the forward seat, since we rarely used it in *Diva* and often removed it for carrying provisions or jerry cans of water or fuel. We installed Wichard folding pad-eyes on the aft section to which we attach stainless-steel lifeline turnbuckles via large snap hooks. This allows us to lash *Bacio* very tightly onto pads on deck. The forward dinghy section is held captive by the aft section and needs no pad-eyes. We estimate *Bacio*'s weight to be 80 pounds or less.

28

Practical in practice

To launch *Bacio* from her nested position on deck, we flip over the aft half and, using a lift bridle and our main halyard, lift and hang this section outboard and out of the way. Next, we flip over the forward section and lay it athwartships of *Carina* with its mating bulkhead outboard. We then swing the aft section in and mate the bulkheads



To launch *Bacio*, Philip and Leslie first turn her aft half upright and hoist it with a halyard.



With Bacio's stern suspended, they flip her bow half and turn it so the bulkhead faces outboard.



Once the two halves are mated, they switch the forward bridle legs to the bow for launching.

with the three ½-inch bolts. We use wingnuts that we tighten onto stainless-steel fender washers and also nitrile rubber washers to help seal out water. Once the dinghy is assembled, we move the forward lines of the lifting bridle to the dinghy's bow and lift the entire dinghy up and over the lifelines and lower it to the water. It takes us about 15 minutes to assemble or disassemble

Bacio. (With Diva, we would put both halves overboard in the water and one of us would climb in the aft half, align the two half boats, and bolt them together.)


We can also hang *Bacio* from a main halyard (resting against a fender slung parallel to *Carina*'s toerail) for security and to minimize fouling of the bottom and the outboard motor. We use no antifouling paint on her bottom.

For propulsion, we outfitted Bacio with 7-foot oars and a small 3.3-hp two-stroke outboard, the latter still easily purchased outside the U.S. Though she will not quite get up on plane (most likely due to our amateur design modifications), she still moves along at 5 knots or so under power. By shortening her waterline, we also sacrificed some performance in short choppy seas. We wouldn't recommend it, but we have transported almost 675 pounds, though only for a short, flat-water passage. She'll easily carry 450 pounds.

We have used *Bacio* nearly every day for almost eight years while cruising from our home port in Puget Sound, Washington, through Mexico, Central and South America, and the South Pacific. She has required periodic maintenance but has been a rugged, reliable, and stable tender. Plus she's a pretty boat with a graceful sheerline. One of us still pines for a sailing rig, especially when she sees a Chameleon under sail, but she still does not have it.

Bacio's fine finish has degraded some as we have had to do repairs without fiberglass tape or the best epoxies, but she is as tough as ever and still going strong. She's a working boat, she's held up well to the elements, and her rugged construction probably saved Philip's life when he was hit

Good Old Boat March/April 2012 www.goodoldboat.com



Bacio's rugged construction probably saved Philip's life when he was hit broadside by a speeding powerboat in Nuku Hiva, above. The collision stove in the starboard aft hull panel, leaving the forward half of the boat undamaged. When repairing Bacio, three photos at right, Philip and Leslie made do with the limited supplies they had on board together with what was available in their remote location. She was afloat again in a week.

broadside by a speeding powerboat in the Marquesas.

Periodic maintenance

Maintaining our Chameleon has primarily involved keeping her painted, which prevents UV degradation of the epoxy resin. Any spot exposed for even a few months in the tropical sun is subject to delamination. Single-part paints have not proven hard enough for everyday use on the hull, so we've resorted to two-part paints with epoxy seeming to be better than polyurethane for durability. For the inside, rubber roof paint seems to hold up best to standing water while single-part paints quickly peel off where rainwater or dew accumulates. A layer or two of fiberglass cloth tape along the keel did not prove to be substantial enough for frequent landings on sand and rocky shores. To mitigate wear, we added an 8-inch-wide strip of 24-ounce coarse woven roving to the keel to strengthen it for impact and to serve as a chafe guard. The surface is not fair but it's hardly noticeable and does the job.

We have had some problems with rot, though much less than you might expect. The first serious case was due to a crack that developed in the seam of one of the flotation chambers in the aft section. Water quickly accumulated during a long wet Central American summer. While doing routine maintenance, Leslie noticed a softness in the

panel, began tapping with a screwdriver, and found a large area of rot. With a borrowed Fein tool, we quickly excised the rotten piece (the inner side had not been coated with epoxy) and constructed a replacement, stripped the adjacent paint, and used a filleting blend to install the replacement. Strips of fiberglass cloth reinforced the fix and *Bacio* was watertight once more.

The other instance of rot involved the forward storage area. Due to ingress around the seal of the commercial hatch we had chosen to install (rather than the hatch suggested by the designer), water accumulated inside. This led to fungus growth that eventually attacked the okoume hull panels of the forward section despite their coatings of epoxy and fiberglass. While in the boatyard for routine maintenance, we stripped the paint from the outside of the hull using a heat gun, dried out the storage area, and re-epoxied and reinforced the fiberglass of the entire forward section. (We also installed a strip of wood forward of the hatch to which we snap a Sunbrella cover that helps minimize leakage.)

Repairable construction

As for major repairs, the collision in the Marquesas crushed in the starboard section of the aft half, shattered one oar, popped the knee, and caused *Bacio* to capsize and nearly sink. The flotation chambers kept her afloat. (Philip was







Resources

References:

Spectre, Peter, 100 Boat Designs Reviewed, WoodenBoat Publications, 1997 Spurr, Daniel, Steered by the Falling Stars: A Father's Journey, Henry Holt & Co, 1995 Spurr, Daniel, Upgrading the Cruising Sailboat, International Marine/Ragged Mountain Press; 2nd ed., 1993

Websites:

www.duckworksmagazine.com www.yachtvalhalla.net/gecko/gecko.html www.bebi-electronics.com/rtt.html

Dinghy transport

plucked from the water, unharmed, by the stunned crew of the offending vessel.)

Even though we had limited supplies, we stripped all the paint from the crushed section and gently re-assembled the remaining bits, like a jigsaw puzzle, against a piece of sacrificial plywood, screwing the brace to the damaged piece. We sealed the ragged edges with a liberal application of the locally available epoxy filler (Epi-Fill by International), then faired the surface and glassed both sides with 2:1 no-name epoxy we had purchased in Panama. The bits of knee and gunwale we still had fit together in another puzzle and we built up and sculpted thickened epoxy to fill the gaps left by lost pieces. After a week of work in a hot parking lot on Nuku Hiva, under the watchful eves of nearly everyone on the island, she was back afloat. We could see her minor scars but no one else seemed able to see the repair.

Nesting dinghy enthusiasts are a small club but we find many Chameleons (and other designs) as primary or secondary tenders in active use by cruising yachts in far-flung ports.

In Fiji, we tied up each day next to a Chameleon, made of aluminum, named *Rin Tin Twin*. This is a well-loved family vehicle for liveaboards who commute to their business ashore.

The two Chameleons we have built and used have proved their worth and we encourage any slightly-resourceful sailor looking for an economical solution to the tender dilemma to consider the Chameleon. With a little skill and a small amount of concentrated effort, anyone can build and maintain a Chameleon that will be joy to own (and sail) while providing years of reliable service. Δ

Philip DiNuovo and Leslie Linkkila came to cruising and boat ownership as adults and quickly developed a passion for small-boat travel. In 2003, they quit their professional jobs and left the Pacific Northwest behind and are now in the South Pacific.




A Chameleon nesting dinghy can be assembled or disassembled with both sections in the water.

PerfectPitch Props

For Auxiliary Diesel & Gas to 40-hp

Atomic 4
Westerbeke
Universal
Yanmar
Most others




30

Performance Propellers

44 James St., Homer, NY 13077 Phone 607-749-3165 • Fax 607-749-4604

performance.props@verizon.net www.performancepropellers.com



Good Old Boat March/April 2012 www.goodoldboat.com