


DRILL TEMPLATE

2019+ MERCEDES SPRINTER

DRIVER SIDE

FRONT CYLINDER



CUT OUTER SHAPE



269-483-9636 (fax)
800-952-9815 (phone)
B.Slack > 6-12-19

SCALE 1 : 0.96