### **WENGER**<sub>®</sub>



# WeSpeed For small parts and fast cycle times

### Highlights

Workpiece storage: 2 x 400 x 600 mm drawers A slide guard allows uninterrupted pallet change.



The decoupling of the machine loading and the handling within the cell, through the surface gantry, enables the shortest cycle times for complex applications, with multiple process stations.

Room for process stations, such as measurement, deburring and more.

WeSpeed

SPC/NOK drawer

Safe loading hatch. Safe separation of loader and machine compartment

### **WENGER**

### WeSpeed product description



WeSpeed fills the void wherever the standard robot cell fails to meet the required cycle times because, in addition to machine loading, additional processes must be operated.

Due to the decoupling of machine loading and part handling for process stations and workpiece storage, very short cycle times can also be realised for complex match grinding tasks.

The workpiece storage consists of 2 400 x 600 mm drawers.

#### Features:


- A sliding guard above the drawer enables the pallet to be changed during machining.
- A controller for every function. All processes are developed by us in-house, and are integrated in the loader control system.
- Industry 4.0: All methods of retrieving relevant operating and process data are available with our preconfigured OPC-UA interfaces for all common systems and our WeConnect software tool.

## WeSpeed technical specifications

Technical specifications	WeSpeed
Number of drawers	2 + 1xSPC/NOK
Autonomy example Chuck part Ø 10 L60:	500 pcs
Number of pallets/sizes	4 x 300 x 400 mm 2 x 400 x 600 mm
Chuck part max. dimension: Shaft part max. dimension: *Larger dimensions also possible if required with geometric analysis	Ø 140 L100 (to 2 kg) Ø 100 L200 (to 2 kg)
Workpiece changeover time Without machine clamping times, depending on part weight	< 4-6s
Traversing speeds	up to 4m/s
Dimensions Floor plan: Height of casing: Height of Z axis top:	1660 x 1560 mm 2300 mm 2740 mm
Weight	Approx. 1.5t
Consumption information Air pressure: Air consumption: Voltage: Backup fuse: Max. power consumption:	6 bar 50 l/min 3 x 400 VAC (3LNPE 50 Hz) 25 A 5 kW

#### Footprint

(WeSpeed only without machine tool)



### Successful WeSpeed projects







### **WENGER**。

#### Wenger Automation & Engineering AG

Sandgrubenstrasse 14 8409 Winterthur Switzerland

+41 52 245 19 20 automation@wenger-ag.ch

### www.wenger-ag.ch

#### UK AGENT

1

K

1

П

ISH DRI N

DF Precision Machinery Ltd Bridgemere Farm, Mowsley lane,Walton, Lutterworth LE17 5RE England

+44(0) 116 201 3000 sales@dfpmach.com www.dfpmach.com