



**SUMMARY**  
4121 Ragen Dr, Charlotte, NC 28273  
Mary King  
February 19, 2022

Steve Rogers 5297  
Impact Home Inspections LLC  
Steve Rogers  
704-691-3161  
[steve@impacthomeinspectionsllc.com](mailto:steve@impacthomeinspectionsllc.com)



74

ITEMS INSPECTED

1

RECOMMENDATION

7.5.1 Fuel Storage & Distribution Systems

**CORROSION**

ATTIC

Gas fitting/shut off to furnace was corroded. Overtime this can lead to gas leaks. Recommend contacting a qualified contractor to evaluation and repair.

Recommendation  
Contact a qualified professional.

 Recommendation

