



Spring service requests must be received TWO WEEKS prior or sooner to the requested launch date! If you would like to guarantee your spot sooner, please send paperwork by May 1st.

Dates will be approved by the office on a first come, first serve basis.

Please do NOT send payment with spring paperwork. Payment is due upon receipt prior to launch.

Spring start/ DE-winterize approximately \$150.00 (ALL boats receive spring start)

- Removal of shrink wrap (IF APPLICABLE) and/or boat removed from storage.
- Charge and test battery.
- Check fluids, check boat systems, run engine to check for run quality and proper cooling, check and inspect throttle and shift functions, check and inspect steering system.
- Safety systems will be repaired if needed Example: Navigation lights, bilge pump and blower motor.
- Boats will also receive courtesy fluff inside and out (this is not a detail)

Replace battery: Single \$195.00 Dual \$390.00 Trolling motor \$210.00.

Battery replacement is recommended every 4 seasons to ensure trouble-free boating.

Engine tune up: Inboard engine \$200.00 Outboard engine \$110.00

- Fuel system service included in tune up
- Replacement of all ignition components (spark plugs, ignition cap and rotor)
- Replacement of all fuel filters, fuel system cleaner added to fuel tank. Service should be performed no later than 100 hours or 3 years. For the best results we recommend this as an annual service for an avid boater or biannual for all others. Price is labor only. Parts are extra.

Water pump impeller replacement:

Outboard \$265.00 Volvo Penta \$195.00 Alpha \$320.00 Bravo \$375.00

The water pump impeller is the main component in your engine's cooling system. Service should not exceed 100 hours or 3 years of service. For Volvo Penta and Mercruiser Bravo we recommend biannual service. Price is labor only parts are extra cost.

Engine oil and filter: Outboard \$95.00 (parts extra) Inboard \$200.00(parts included)

Normally a fall service, however available in the spring as well. An oil and filter change are recommended annually.

Gear oil change: Outboard \$90.00 Sterndrive \$120.00 Prop(s) removal \$45.00

Recommended in the fall, however available in the spring. Drain gearcase lubricant, replace drain screw gaskets and refill with high performance gearcase lubricant. If prop(s) need to be removed to drain, there will be inspection and lubrication of prop shaft splines as well as propeller hub. Recommended as an annual service.

___ Complete pontoon boat detail; interior and exterior (Request quote)

Carpet cleaning, excessive mildew, sap and stains will be charged by the hour.

___ Complete fiberglass boat detail; interior and exterior (Request quote)

Machine polish and wax (heavy oxidation, scratch removal and sap will be charged by the hour)

___ Canvas clean and waterproof \$150.00

Battery switch installation: ___ Single ___ Dual with battery (Request Quote)

It is recommended to have a battery switch installed. When away from your boat you can turn off all the power to eliminate your battery from drawing down. We can also install a dual battery switch and extra batteries for even extra security. Onboard charger or solar charger available and recommended.

Additional repairs requested:

Requested launch dates: _____

Location: _____

___ Dockside Delivery \$250/HR ___ Out-of-town delivery \$200/HR

Name/Date: _____