

RM Products Ltd

Case Study - HWY #407 Maintenance Brampton ON

HWY# 407 Maintenance Department required a building to park service vehicles, contain electronic testing equipment and needed to be out of the elements of winter weather.

The building had to be large enough to house the vehicle, maintain an above freezing temperature and there had to be minimal site work.

RM Products provided a 20' x 40' fiberglass unit with an interior ceiling of 14'.

The building was mounted directly to the Customers existing asphalt surface.



14' ceiling provides clearance for large vehicles & equipment.



RM Products Ltd

1-800-363-0867

sales@rmfiberglass.com

www.rmfiberglass.com

