

7817 N Dale Mabry Hwy Tampa, FL 33614 813.588.0905 europeanexoticcenter.com MV-90977

SERVICE INVOICE

	SERVICE INVOIC			
00208 ZA9RU31B3WLA12866	0.9	DATE IN 5/12/2025		
R MAKE MODEL COLOR		TIME IN		
1998 LAMBORGHIN DIABLO SV O		16:41 CLOSE 15:22		
43079 43082 00/00/00 FT.	0.9	3/30/2025		
00/00/00		WRITER		
	W: () -	NICK\01		
) COURTESY VEHICLE HEALTH CHECK	CUSTOMER TO PICKUP			
MULTIPOINT INSPECTION COMPLETE	Labor T04	.00		
(04- MARTIN-) A	Total Repair (Customer)	.00		
) CUSTOMER REQUESTS ENGINE OIL CHANGE		460.00		
SERVICE WITH LIGHT RESET	Labor T04	460.00		
DRAINED OIL, CHANGED FILTER, FILLED WITH NEW	LM2043 (LIQUI MOLY 5L) 3	184.38		
OIL.	1505914	113.00		
	(OIL FILTER - DIABLO)	460 00		
	Total Labor			
VERSE / 77-4	Total Parts			
(04- MARTIN-) A	Total Repair (Customer)	757.38		
) DOOR HANDLE REPLACEMENT - CUST HAS PARTS IN				
CAR.	Labor T04	460.00		
NO WARRANTY ON CUST SUPPLIED PARTS	9921011 (DOOR CABLE) 1	132.80		
	PONOMERS OF THE CONTROL OF THE PONOME AND THE PONOM			
REMOVED DOOR PANEL, DISASSEMBLED CABLE/LATCH	FREIGHT 00208	35.00		
CUST ORDERED INCORRECT DOOR CABLE.	Total Labor			
ORDERED AND INSTALLED CORRECT CABLE AND CUST	Total Parts	132.80		
SUPPLIED DOOR HANDLE.	Total Sublet/Fees	35.00		
(04- MARTIN-) A	Total Repair (Customer)	627.80		
) REPLACE RUBBER PIECES ON PEDALS - CUST HAS				
PARTS IN CAR.	Labor T04	46.00		
NO WARRANTY ON CUST SUPPLIED PARTS	Total Labor	46.00		
COMPLETE (04- MARTIN-) A	Total Repair (Customer)	46.00		
) CAR IS DIFFICULT TO GET INTO FIRST AND REVERE				
CHECK/ADJUST.	Labor T04	.00		
COMPARED TO DIABO IN SHOWROOM, FEEL IS VERY				
SIMILAR, NO ISSUE FOUND, SHIFTER IS WORKING S	Microsophy			
AS DESIGNED.				
(04- MARTIN-) A	Total Repair (Customer)	.00		
A GUAR DEGUERARA NO AD TIAM DETURNA ATRE VIDADI TAM				
) CUST REQUESTS TO ADJUST DRIVERS SIDE HEADLIGT	Labor T04	220 00		
REMOVED WHEEL AND FENDER LINER, ADJUSTED		230.00		
HEADLIGHT LEVEL TO OTHER SIDE.	Total Labor	230.00		
(04- MARTIN-) A	Total Repair (Customer)	230.00		
	Il parts are new or factory rebuilt unless specified otherwise. Replaced par			
	nless specified otherwise. Parts replaced under the manufacturers warranty a ealer for inspection by the manufacturer.	are retained by f		
	W/C INT.	CUSTOMER		
	MER OF WARRANTIES Ties on the product sold			
hereby at manufacture	e those made by the er. The seller hereby expressly			
hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not disclaims all	I warrantes either expressed			
or any delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to	ncluding any implied warranty ntability of fitness for a			
person me change along the along the shore which is secure the amount of the shore the person of the shore along the shore which is secure the amount of transits thereto. PLEASE SEE particular pu	urpose, and neither assumes			
E. only working	ics any person to assume for ly in connection with the sale			
CUSTOMER'S SIGNATURE of said produ	ucis.			
Page 1 of 2 Joh	00208			
		1		
00208 Customer	Copy			
00200				
	1 1 1			



7817 N Dale Mabry Hwy Tampa, FL 33614 813.588.0905 europeanexoticcenter.com MV-90977

SERVICE INVOICE

R/O VN				DATE IN
00208 ZA9RU31B3W	LA12866		0	\$/12/2025
YEAR MAKE MODEL	COLOR			TIME IN
1998 LAMBORGHIN DIABLO SV	0			16:41
MILES IN MILES OUT FIRST USE	LISC.			CLOSE 15:22
43079 43082 00/00/00	FL		0	\$/30/2025
SEE ALSO				WRITER
ALSO		i: ()	_	NICK\01
(7) CUST STATES FRONT LIFT IS IN	NOP - CHECK AND AD	Labor	T04	690.00
CHECKED FLUID LEVELS, LINES AKS PRESENT AT THIS TIME. RI SOLE, SWITCH GETTING POWER. NEED ADDITIONTAL DIAGNOSIS A CUST DECLINED ADDITIONAL DIA	EMOVED CENTER CONO AT THIS TIME	Total Labor		690.00
(04- MARTIN-) A		Total Repair (Customer).		690.00

THANK YOU FOR YOUR BUSINESS!



SHOP SUPPLIES AND HAZARDOUS WASTE DISPOSAL CHARGES

This charge represents costs and profits to the motor vehicle repair facility for items such as miscellaneous shop supplies and/or waste disposal. [s.559.904(4)]

All parts are new or factory rebuilt unless specified otherwise. Replaced parts will be returned unless specified otherwise. Parts replaced under the manufacturers warranty are retained by the dealer for inspection by the manufacturer.

Thereby authorize the repair work hereinafter set forth to be done along responsible for loss or damage to vehicle or articles left in vehicle in case for any delays in parts shipment by the supplier or transporter. I here oncerts the vehicle bears in described on extracts, brickwars or offers.	of fire, theft or any other cause beyondour control or	DISCLAIMER OF WARRANTIES Any warranties on the product solid hereby are those made by the manufacture. The selder hereby expressivy disclaims at warranties either oppressed of merchenisbility of liness for a	.00 .00 .00 .00	Labor Parts Sublet/Fees Shp. Sup. Oil/Grease	1886.00 430.18 35.00 50.01
operate the which betten dearthed on streets, highways or elsewhs operate the which betten dearthed on streets, highways or elsewhs oppress mechanic size is hereby acknowledged on the above vehicle the Versite SIDE FORADDITIONAL INFORMATION. CUSTOMER'S SIGNATU		particular purpose, and neither assumes nor authorises any person to assume for it any liability in connection with the sale of said produces.	.00	Sub Total Tax Total (Due)	2401.19 153.79 2554.98
00208	Customer Copy				