
# LATERAL AND UPLIFT DESIGN/INSPECTION CONSIDERATIONS

Joe Polder Simpson Strong-Tie <u>jpolder@strongtie.com</u> 714-493-3388

# LATERAL AND UPLIFT DESIGN/INSPECTION CONSIDERATIONS

- Overview of continuous load path
- Overview of different systems
- Different design considerations
- Pre-construction activities
- Construction concerns
- Post-construction

# **CONTINUOUS LOAD PATH**



# DIFFERENT LATERAL RESISTANCE SYSTEMS

- Site-Built Shear Wall
- Pre-Fabricated narrow Shear Panels
- Multi-Story Rod Systems
  - Wind and Seismic
- Moment Frames

#### TYPICAL SITE BUILT SHEAR WALL

- Cast-in-place anchor bolts <u>or</u> cast-in-place strap hold downs
- Reinforcement by EOR/Designer
- Attached hold downs with proper fasteners
- Attached sheathing and nailing per shear wall schedule

# TEMPLATED PRE-FABRICATED HOLD DOWN AND ANCHOR BOLTS



# POST TENSION CABLES AND HOLD DOWN STRAPS READY FOR POUR







# COMPLETED SITE-BUILT SHEAR WALLS



### SHEAR WALL NAILING SCHEDULE


	SHEAR WALL SCHEDULE												
SHEAR	THICKNESS	PLYWOOD	NO. OF	NAILING		SPACING		ALLOWABLE	SILL PLATE			TOP PLATE CONNECTION W/SIMPSON 'A35' (SEE NOTE 3 & 6 BELOW)	
MARK NO.	ILICKNESS	TYPE	SIDES	SIZES	BLK'G	EDGE	INTERM	SHEAR WALL VALUE	SIZE	CONNECTION TO FOOTING INTERIOR NON RATED WALLS	CONNECTION TO FOOTING EXTERIOR RATED WALLS	INTERIOR NON RATED WALLS	EXTERIOR RATED WALLS
1	15/32"	STRUCTURAL I	ONE	10d COMMON	YES	6"	12"	340 PLF	3X	5/8"ø ANCHOR BOLTS AT 48" OC	5∕g"ø ANCHOR BOLTS AT 40" OC	'A35' AT 16" OC	'A35' AT 16" OC
2	15/32"	STRUCTURAL I	ONE	10d COMMON	YES	4'	12"	510 PLF	3X	56"ø ANCHOR BOLTS AT 40" OC	5∕8″ø ANCHOR BOLTS AT 32″ OC	'A35' AT 8" O.C.	'A35' AT 8" O.C.
3	15/32"	STRUCTURAL I	ONE	10d COMMON	YES	3"	12"	665 PLF	3X	5∕8″ø ANCHOR BOLTS AT 32″ OC	%″ø ANCHOR BOLTS AT 24″ OC	'A35' AT 8" O.C.	'A35' AT 8" O.C.
4	15/32"	STRUCTURAL I	ONE	10d COMMON	YES	2"	12"	870 PLF	3X	56"ø ANCHOR BOLTS AT 24" OC	5∕8″ø ANCHOR BOLTS AT 16″ OC	'A35' AT 8" OC	2-'A35' AT 12" OC
5	15/32"	STRUCTURAL I	вотн	10d COMMON	YES	4'	12"	1020 PLF	3X	5/8"ø ANCHOR BOLTS AT 16" OC	5∕g"ø ANCHOR BOLTS AT 16" OC	'A35' AT 8" O.C.	2-'A35' AT 10" OC
6	15/32"	STRUCTURAL I	вотн	10d COMMON	YES	3"	12"	1330 PLF	3X	5/8"ø ANCHOR BOLTS AT 16" OC	5⁄8"ø ANCHOR BOLTS AT 8" OC	2-'A35' AT 12" O.C.	2-'A35' AT 8" OC
<u></u>	15/32"	STRUCTURAL I	вотн	10d COMMON	YES	2"	12"	1740 PLF	3X	5%"Ø ANCHOR BOLTS AT 8" OC	%"ø ANCHOR BOLTS AT 8" OC	2-'A35' AT 8" O.C.	2-'A35' AT 8" OC

- 1. FOR ADDITIONAL INFORMATION SEE GENERAL NOTES
- 2. FOR SHEAR WALL NOTES SEE DETAIL 8 ON SHEET S1.2
- 3. 'A35' INSTALLED BY SIMPSON SPECIFICATIONS and AS ALTERNATE USE DETAIL 20 ON SHEET S8.0
- 4. SCREWS 'SDWS' INSTALLED BY SIMPSON SPECIFICATIONS.
- FASTENERS IN CONTACT WITH PRESSURE TREATED SILL PLATE SHALL BE HOT DIPPED ZINC COATED GALVANIZED or STAINLESS STEEL OR SILICON BRONZE OR COPPER
- 6. WHEN REQUIRED 2 CLIP ANGLES, PROVIDE ONE AT ONE SIDE & OTHER AT OTHER SIDE
- STAGGERED. AS ALTERNATE ONE 'A35' AND OTHER SIDE ONE 'LTP4' STAGGERED.
- 7. RATED WALLS MEAN FIRE RATED WALLS.SEE PLANS.
- 8. EDGE NAILING ARE BOUNDARIES, PANEL EDGES, TOP and BOTTOM PLATE ATTACHMENT

SHEAR WALLS SCHEDULE

SCALE: 1/8"=1'-0"





# FLOOR TO FLOOR TRANSFER AND LATERAL RESISTANCE OF SECOND FLOOR





# PRE-FABRICATED SHEAR WALLS










# PRE-FABRICATED PLATED TRUSS




# TRANSFER TOP PLATE TO TRUSS







# INTERIOR UPLIFT



### NEW APPROACH TO UPLIFT...







# SDWC & QUIK STICK



# **COLD FORMED STEEL CONSTRUCTION**



# **COLD FORMED STEEL CONSTRUCTION**



# TYPICAL MID-RISE WOOD FRAMED BUILDIING




# MULTI-STORY OVERTURNING AND UPLIFT

- Overturning (Lateral)
- When a building weight cannot stabilize a structure under a lateral force, it causes the structure to rotate off its foundation.




- As wind flows over the roof the wind creates a strong lifting effect, much like that of air flowing over an airplane wing.
- Different Forces = Different Systems






### TWO DIFFERENT TYPES OF SYSTEMS



#### **Key Differences:**

- Rod location
- Load direction
- Framing Requirements
- Load path
- Shrinkage/ compression location



# OVERTURNING (HOLD DOWNS & ROD SYSTEMS)






# **ROD SYSTEMS**








# FAST BUILD AND MOVE...





# HOW DID IT DO?



# TYPICAL MID-RISE IN CONSTRUCTION




#### **DESIGN PHASE**

- Arch/Engineer communication
  - Manufacture spec vs. generic load call-out
- Manufacturer responsibility
- RFIs
- Mis-step of ordering too early in design process

### **SUBMITTALS**

- Deferred submittals vs. hard spec
- Final construction docs review by manufacturer
- Document prep
  - -Calculations
  - -Installation details
  - -Overlays and laminated cards



#### COSEMBORUM SOCO

- INTER-DESCRIPTION OF SHEARING STREET THE R. LEWIS CO. LEWIS CO., LANSING, MICH.
- THE STATE OF
- THE PARTY INVESTIGATION PARTY INVESTIGATION IN THE COMMUNICATION CONTRACTOR IN THE PARTY INC.
- A SEE SENS ENGINEERING
- A STREET STREET OF THE STREET
- LANGE CONTRACTOR OF THE PARTY O
- A MODERN THE SALES OF THE SALES OF THE SALES OF THE SALES
- TO THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY.

ILTER DE UN Control of the contro

#### DIESE SCHWILTER STEE

- LUMB ON BUTCHE BOLLOD.
- L page (see 4. Marrier 14 recent of rest of
- A ALBERT CHERT CHARGE VALUE CONTROL
- Here the or two to the state of the state of

- A THE MEAN PER PERSON OF THE MEAN PERSON.

  A COMPANY OF THE MEAN PERSON OF THE MEAN PERSO
- A THE RESIDENCE WAS READ AS
- A PROPERTY OF BUILDING
- Zимеников съ със
- NAMES OF THE OWNERS OF TAXABLE
- STRAIGHT
- THE PERSON NAMED IN COLUMN



#### ANCHOR TIEDOWN SYSTEM REQUEST FOR INFORMATION (RFI)

Homewood Suites - Aliso Viejo, CA DATE CREATED: 09/08/2014

IMPORTANCE: SENT VIA: [] HIGH [X] MEDIUM [] LOW

[] FAX [X] EMAIL


PROJECT INFORMATION:

DATEOF PLANS: 07/02/2014

	Company	CONTACT	Pho Ne Number
Engineer:	DCI ENGINEERS		(949)892-4950
Авсинтест:	Gене Foнo Associates		(310) 209-7520


	QUESTIONS	Responses
the tie down a our concerns	ed a few locations in the contract documents in regards with cystem which we would like clarification on. We have listed in the attached mark-up sheet. Please reution and prouide ormation if changes are required.	

Anbwer Company:	AMSWERED BY (NAME):	
DATE Andwered:	SIGNATURE:	



Form: ES-ATSRFI

Project #: ES-140431B





SIMPSON STRONG-TIE COMPANY INC.

5996 W. Las Positas Blud., Reasonion, CA 94522. (200) 559-5059

www.strongtie.com

#### Anchor Tiedown System

Composest capacities for Homewood Suites

110 Vantis Drive Aliso Viejo, CA

Prepared for

DCI Engineers

Structural Date of Plans

Aug 25, 2014

Airch feicht rail Date of Pitans

Jul 28, 2014


Date of hip it


Nov 12, 2014

Inputby

H.DA

Version: 3.21.0.0 Page 1 or 20





### PRE-CONSTRUCTION CONSIDERATIONS

- Anchorage issues
  - -Inconsistent callouts
  - -Responsibility
- Sub coordination
  - -HVAC
  - -Utilities
  - -Plumber
  - -Concrete
  - -Framer
    - -System termination (bridge block/top plate)

#### **SHIPMENT**


- Coordination with GC and sub
- Ship by floors
  - -Stage shipments
  - -Minimize potential missing parts
- Check in shipments with subs
  - -Ongoing throughout the job
- Missing parts
- Inspection
  - -Ensure understandings of jurisdiction inspector, EOR job walk and GC
- Post assessment of system with EOR, GC and subs

### SHIPPING PALLETS



### **ANCHORAGE**







### **OVERTURNING COMPONENTS**




## TERMINATION (OVERTURNING)


**Top Plate** 




#### **Bridge Block**




#### **UPLIFT RESTRAINT SYSTEMS**





# UPLIFT RESTRAINT SYSTEMS COMPONENTS



# UPLIFT RESTRAINT SYSTEMS COMPONENTS

Strong-Drive® SDWC TRUSS Screw








Strong-Drive® SDWC TRUSS Screws







# MULTI FAMILY AND PRE-FAB WALLS AND MOMENT FRAMES






#### MOMENT FRAME DOCUMENTS







# THANK YOU

Questions?

