

E-GLASS SURFACE PREP FOR FIELD PAINTING

(WARNING !) SURFACE PREPARATION SHOULD BE DONE IN A WELL VENTILATED SPACE WITH NO OPEN SOURCE OF IGNITION IN THE AREA. FOLLOW ALL SAFETY INSTRUCTIONS OF CLEANING AGENTS.

1. CLEAN SURFACE TO BE PAINTED WITH DENATURED ALCOHOL.

2. SAND SURFACE WITH MEDIUM STEEL WOOL.
SURFACE FINISH SHOULD APPEAR DULL AFTER SANDING.

3. CLEAN SURFACE WITH ACETONE.

4. PAINT WITH HIGH ADHESIVE PAINT.



Email: Info@essiacoustical.com
WWW.essiacoustical.com
(216)-251-7888
FAX: (216)-251-9933