

# E-GLASS SURFACE PREP FOR FIELD PAINTING

## ( WARNING ! )

- SURFACE PREPARATION SHOULD BE DONE IN A WELL VENTILATED SPACE WITH NO OPEN SOURCE OF IGNITION IN THE AREA.
- FOLLOW ALL SAFETY INSTRUCTIONS OF CLEANING AGENTS.
- 1. CLEAN SURFACE TO BE PAINTED WITH DENATURED ALCOHOL.
- 2. SAND SURFACE WITH MEDIUM STEEL WOOL.  
SURFACE FINISH SHOULD APPEAR DULL AFTER SANDING.
- 3. CLEAN SURFACE WITH ACETONE.
- 4. PAINT WITH HIGH ADHESIVE PAINT.

