

Time is history. So Let me help tell your familys history for many more decades to come.

# Time to Watch - The Qualified Clock and Watch repair experts

Owner- Peter Ronan,  
BA (Hons), MBHI.



BRITISH  
HOROLOGICAL  
INSTITUTE



[www.timetowatch.co.uk](http://www.timetowatch.co.uk)

Customer name, number  
& address

**T.Fugit**  
**Hancox Street**  
**West Midlands**  
**B68**  
**07508 937 255**

## Estimate

Reference: **10016**

Estimated repair cost	£ 325.00
Full service+ 1 x mainspring + 1 x ratchet wheel	
Collection/delivery costs (£1.25 per mile)	£ 25.00
	£

This estimate of repair/service is based on the initial inspection, condition, style and model of the clock and is not a final invoice or contract. Once the clock has been disassembled and fully inspected then an accurate price can be given for work needed. Until then please only refer to this estimate as a guide price. Set prices below are for the most common works needed on clocks including services, rebushing and replacement mainsprings. Upon confirmation to proceed with work, further notes and photographic evidence can be found on my website [Timetowatch.co.uk](http://Timetowatch.co.uk) by quoting the reference at the top right of the page.

Initial checks	
1 - Working / None working	Works for a few minutes
2 - Any damage, knocks, falls	None known
3 - Service history	none known
4 - Case condition	Scratched and faded
5 - Condition of dial & hands	no dial hands aged but
6 - Is key present?	NO
7 - Do clock springs have tension?	NO
8 - Any other customer information?	

Clock Service Price List	None Striking	Striking
Quartz new movement	£90	£120
mechanical	£175	£195
Pendulum movement	£230	£290
None pendulum	£200	£260
Fusee	£260	£360
Pre 1870 longcase 8 day	£310	£410

Set Price Parts	Cost
Pendulum suspension each	£8
Bronze/brass re bushing each	£10
Bush for barrels each	£18
Mainspring each	£30
	£30

Extras	cost
Dial clean/replace	£ T.B.A.
Case clean/polish	£ T.B.A.
New pendulum	£ T.B.A.
Screw replacement and blueing	£ T.B.A.
Ratchet wheel each	£ 5

**Notes about clock**

- Upon initial inspection in customers home I found the clock was not working as it should. It did wind and tick but would stop after 10 minutes or so and mainspring would "bang" and spin out under more tension.
- There was no dial present and key was also missing.
- Main glass appeared in ok condition and no visible scratches.
- Upon opening the case, the hammer arm was twisted out of shape but did operate when clock went into warning.
- the chime was present .
- As the dial was missing i could have a closer look at the front of the movement which showed damage to ratchet wheels, several teeth bent over on the mainspring wheel, several screws crushed and incorrect wire holding a lot of parts in place.
- The damage through the movement is possibly caused from a broken outer hooking on the mainspring and or broken ratchet teeth so they will need repairing or replacing.
- I recommend a full service so we can fully inspect the movement and give an accurate cost of any extra repairs that may be needed to get the clock working as it was intended.
- The customer has agreed to a full service but also asked me to supply a new key and not to replace the dial but to polish certain parts of the front of the movement purely for asthetics.
- Photos of initial inspection can be found on the website and any further damage we find will also be posted on the website.

TOTAL ESTIMATE COST	£ 350.00	-
TOTAL ACTUAL COST	£	-
TOTAL DIFFERENCE PAYABLE	£	-

- A full service includes initial inspection, complete strippdown, professional clean, damage inspection, costing of part repair vs replace, correct strike train and pendulum setting, final clean, oil and grease, reassemble and ful 7 day test.  
- Not included in a service = Replacement parts, polishing, case repair, case lacquering, blueing of hands or screws.

All work is guareneteed for 12 months.

While we take every care to protect and preserve your watches or clocks while they are in our care we are still fully insured up to £1,000,000.00 for cover, damage and theft. We are also insured to transport horological items and from our place of business to the value of £500,000.00.