

## CLARIFICATION NO. 1

---

Commercial Township

### Municipal Building Interior Renovations

#### CLARIFICATION NO. 1

#### **ARCHITECTURAL:**

1. Transaction window glazing shall be UL rated level 3 ballistic glazing as indicated in specification section 062023 Interior Finish Carpentry.
2. Door EX1 is a pair of doors with one Adams Rite mortise exit device on the active leaf. The electric strike shall be installed on the inactive leaf. The set in the hardware specification is correct as specified with the addition of one power transfer TSB-C by Securitron.
3. When the drawings call for ceilings to be replaced it is meant to include ceiling tile and grid.
4. The CFO office has an existing gwb ceiling. This should be repainted and not replaced.
5. New openings in existing masonry walls would require lintels.