

- Before upgrade the firmware into your device, please go **UPDATE YOUR “SOYAL Device Tools”** software **FIRST**.
- There are two firmware upgrade software included in SOYAL Device Tools named “ISP Tools” and “UDP Updater”

ISP Tools applies to the model no. (Via COM Port Only)

- H series:
321H / 327H / 331H / 721H / 723H / 725H / 737H(Mifare) / 727H(V3) / 747H(V3) / 757H / 888H / 721E
- WG series (Mostly Mifare Only):
725UB / 737UB / 331KD / 331UD / 721KD / 721UD / 725KD / 725UD
- Old E series (V3 version):
716E / 732M / 821EF(V3/V9) / 829E (V3)
- Others:
323D / 321W / 401E / 401DI16 / 401RO16 / MIF chip module for 727H(V3), 747H(V3), 821EF(V3/V9), 829E(V3)

UDP Updater applies to the model no. (Via COM port or TCP/IP port)

- E-V2 / E-V5 series:
721E-V2 / 725E-V2 / 727H-V5 / 821EF-V5 / 829E-V5 / 837E / 837EF / 881EF
- TCP/IP Converter:
727CM (V2/V3) / 727CM-IO / 727iV3 (TCP/IP module inserted on 716E)

- **Cautions:**

If your upgrade on ISP Tools has popped out following message **“File Type didn’t Match the Target CPU”**, please contact your Supplier or SOYAL to get correct firmware and match with your device.

