

Certificate of Compliance

Certificate Number:

[E540092]

Report Reference:

E540092-20240401

Issue Date:

2025-SEP-01

Issued to:

INDUSTRONIC US INC

530 S 8th St, Las Vegas, NV 89101-7003 US

This certificate confirms that representative samples of:

Uninterruptible Power-supply Equipment

See Addendum Page

Has been evaluated by UL LLC in accordance with Standard(s) for Safety:

[See Addendum Page]

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch

UL Mark Certification Program Owner



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

Certificate of Compliance

Certificate Number: E540092
Report Reference: E540092-20240401
Issue Date: 2025-SEP-01

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.]

Standard No. & Title

Standard for Uninterruptible Power Systems, UL 1778.

Certificate of Compliance

Certificate Number: E540092
Report Reference: E540092-20240401
Issue Date: 2025-SEP-01

Uninterruptible power supplies:

UPS-IND HF 1310 M1, UPS-IND HFL 1310 M1, UPS-IND HF 1320 M1, UPS-IND HFL 1320 M1, UPS-IND HF 1330 M1, UPS-IND HFL 1330 M1.

Models –

UPS-IND HF 1380 M1, UPS-IND HF 13100 M1, UPS-IND HF 13135 M1, UPS-IND HF 13160 M1, UPS-IND HF 13200 M1.