

BMW Coverage 17.10

<u>Model</u>	<u>Location</u>									
Last 3 digits of Bosch CDR adapter /cable number shown		<u>2012</u>	<u>2013</u>	<u>2014</u>	<u>2015</u>	<u>2016</u>	<u>2017</u>	<u>2018</u>	<u>2019</u>	
BMW	All BMW require 387 Adapter for DTM									
1 Series					not covered - Europe Only					
2 Series	Driver side, behind IP, rt of strg			796						
3 Series	Driver side, behind IP, rt of strg		796							
Active Hybrid 3	Passenger side, behind the glove box		796							
4 Series	Driver side, behind IP, rt of strg			796						
5 Series	Passenger side, behind the glove box		796					500/822		
6 Series	Passenger side, behind the glove box		796							
6 Series GT	See Service Manual								500/822	
7 Series	Passenger side, behind the glove box		796				500/796	500/822		
8 Series	Passenger side, behind the glove box								500/822	
X3 xDrive	Passenger side, behind the glove box		796							
X5	Center Tunnel, Between Seats			796						
X1, X2	Center Tunnel, Between Seats				798	500/798	500/807	also X2		
X3, X4	See Help File - Various				796				500/822	
X6	Center Tunnel, Between Seats				796					
X7	See Service Manual								500/822	
Z4	Center Tunnel, Under Dash				798				500/822	
i3, i8	See Service Manual			500/807						
The source data for this chart is the Bosch CDR help file for Version 17.10										
Always consult the latest help file for the most accurate coverage										
Copyright Ruth Consulting LLC 2018 - Authorized for distribution by UNF-IPTM,										
SAE, IATAI, PSP & MATAI										