

Home Inspection Report



, SC

Inspection prepared for: Sample Report
Date of Inspection: 12/12/2018 Time: 12:30pm

Age of Home: 27 years Size: 2045 Weather: Partly cloudy, 43 degrees

Inspector: Jeffrey J Triska

License #49339 200 Poore Rd., Piedmont, SC 29673 Phone: 864-556-3306

Email: jthandyman1@sbcglobal.net

INTRODUCTION:

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process.

Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFCI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific non-code, non-cosmetic concerns that the inspector feels may need further investigation or repair.

For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

What We Inspect:

A Home Inspection is a non-invasive visual examination of a residential dwelling, performed for a fee, which is designed to identify observed material defects within specific components of said dwelling. Components may include any combination of mechanical, structural, electrical, plumbing, or other essential systems or portions of the home, as identified and agreed to by the Client and Inspector, prior to the inspection process.

A home inspection is intended to assist in evaluation of the overall condition of the dwelling. The inspection is based on observation of the visible and apparent condition of the structure and its components on the date of the inspection and not the prediction of future conditions.

A home inspection will not reveal every concern that exists or ever could exist, but only those material defects observed on the day of the inspection.

A material defect is a condition with a residential real property or any portion of it that would have a significant adverse impact on the value of the real property or that involves an unreasonable risk to people on the property. The fact that a structural element, system or subsystem is near, at or beyond the end of the normal useful life of such a structural element, system or subsystem is not by itself a material defect.

An Inspection report shall describe and identify in written format the inspected systems, structures, and components of the dwelling and shall identify material defects observed. Inspection reports may contain recommendations regarding conditions reported or recommendations for correction, monitoring or further evaluation by professionals, but this is not required.

Report Summary

Roof		
Page 8 Item: 7	Chimney	Chimney cap is crack, possible water intrusion.
Page 9 Item: 8	Gutter Condition	Rusting screws on some gutters. Recommend painting or replacing screws with corrosion resistant screws
Exterior		
Page 11 Item: 6	Exterior Doors	 Rear door of house swings open. Door is out of level. It does have a good seal.
Page 11 Item: 7	Storm Doors, Windows	 In the inspectors opinion the rear screen door is near the end of their useful life. It is sagging towards the latch side.
Page 12 Item: 11	Deck Condition	 Improper deck piers. Support posts are not secured to piers, support posts have direct contact with soil. Missing baluster, install new one. Deck stair railings are loose and are not graspable.
Page 15 Item: 16	Electrical Conditions	 Extension cord running to pond. Cords are not to be buried. Recommend moving security light away from roof to avoid fire when bulb is installed. All outside outlets need to be GFCI protected. 2 front porch outlets and one rear out need to be GFCI protected.
Page 16 Item: 17	Door Bell Condition	The doorbell is damaged at the rear of the house.
Page 16 Item: 19	Walkway Conditions	 Possible trip hazard. This is a safety concern. Suggest repair/replacement as needed to ensure safety.
Page 18 Item: 22	Lot Grade and Drainage Conditions	• Area under deck is pitched word house and forms a pool along the foundation. Area should be re-graded to slope away from house. Recommend 6" drop in 10 feet.
Garage		
Page 21 Item: 11	Fire Door Conditions	 No self closer. Recommend installation of self closer to protect against fume entry.
Basement		
Page 23 Item: 4	Foundation Walls Condition	 Active leaks observed at the time of inspection. This area is directly inside of the poor grading under the deck.
Page 24 Item: 7	Support Post Comments	Posts are finished or concealed, unable to inspect.
Attic		
Page 27 Item: 8	Electrical Conditions	 Open junction boxes were observed, which is a safety concern. Recommend installing proper covers, as needed, for safety.
Page 28 Item: 11	Attic Comments	bathroom vent fans are improperly venting into attic. Recommend extending fan exhaust to the exterior to prevent damage and/or deterioration from moisture and/or condensation.
Water Heater		
Page 31 Item: 3	Supply lines Condition	 There is a shut off valve on the hot water side. This is not allowed. Must be removed. Hot/cold water lines are reversed, this condition will cause the water heater to function improperly. Corrections are needed by a licensed plumbing contractor.

Page 32 Item: 4	TPR	There is no discharge line pipe installed. Must have TPR dishcharge pipe.
Electrical		
1 0	Main Electrical Panel	Panel cover removal is restricted due to soffit framing
Bathroom 2		
Page 54 Item: 11	Tub Surround Condition	Broken hand grip.
Other Interior Area	as	
Page 59 Item: 8	Stair Conditions	Basement door opens over stairs, should have a 3'x3' landing.

General Information

1. Inspector

Jeffrey J. Triska

2. Persons in Attendance

Buyers

3. Occupancy

The Property is occupied

4. Property Information

This is a single family home • This is a raised ranch.

5. Levels

Bungalow

6. Estimated Age

This home is approximately 20 to 30 years old.

7. Weather conditions

Cloudy • Cold

Roof

1. Methods Used to Inspect Roof

How Inspected: Roof mounted.

2. Style

Materials: Cross Gable.

3. Roof Condition


Inspect Not None ed Inspect ed

Materials: Architectural asphalt shingles.

Observations:

- Roof appeared serviceable at time of inspection. No prediction of future performance or warranties can be offered.
- The roof shows normal wear for its age and type.
- No **Drip edge** installed.







No Drip edge.

4. Roof Flashing Condition

Inspect Not Nor ed Inspect

Materials: Aluminum.

X

Observations:

• No step flashing get on chimney, existing flashing looks in good condition.



No Step flashing.

5. Skylights

Inspect Not Inspect ed Inspect ed

6. Penetrations

Not Inspect ed

Materials: Fireplace chimney. • Kitchen range vent. • 3 Plumbing vent stacks noted. Observations:

• Exposed nails on vent flashing, should be sealed with roof cement.











7. Chimney

Materials: Masonry Fireplace Chimney.
Observations:
• Spark arrestor present.
• Chimney cap is crack, possible water intrusion.



8. Gutter Condition

Inspect	Not	
ėd	Inspect	
	ed	
		- 17

Materials: Gutters are present. • Aluminum.

Observations:

• Suggest cleaning gutters now, and as a normal part maintenance.

• Rusting screws on some gutters. Recommend painting or replacing screws with corrosion resistant screws





Exterior

1. Facia/ Eaves

Inspect Inspec



2. Trim Conditions

Note ed Inspect ed Materials: Aluminum.

3. Exterior Wall Cladding Condition

nspect Not None ed Materials: Brick.

Observations:

• Brick to earth contact noted. This can result in brick "spalling" or deterioration over time. Re-grading or other protection of brick is recommended.



1 Daint/C	audhina
4. Paint/ C	auikinu

Inspect Not None ed Inspect ed

5. Window/Frame Conditions

Materials: Doors.

Inspect Not N ed Inspect ed

Materials: Double Hung. • Thermopane. • Vinyl Frame.







6. Exterior Doors

Inspect Not Nor ed Inspect ed

Materials: Front of house. • Back of house.



Materials: Wood. Observations:

• Rear door of house swings open. Door is out of level. It does have a good seal.

7. Storm Doors, Windows

Inspect Not None ed Inspect ed

Materials: No front entrance storm door. • Rear entry storm Door. Observations:



• In the inspectors opinion the rear screen door is near the end of their useful life. It is sagging towards the latch side.



_		_	
Q	Balconv	Conc	titi∧n
O.	Daicully	COLIC	มเนษเ

	_		
I	nspect ed	Not Inspect ed	None
		ea	
ı			

9. Patio Conditions

Inspect ed	Not Inspect ed	None
		X

10. Porch Condition

Inspect Not ed Inspect ed	None	Materials: Brick. • Concret	
X		Observations: • Covered front porch.	





11. Deck Condition

ed Inspect	Materials: Wood.
	Observations:
X	 Peeling paint observed, suggest scraping and p
	 Improper deck piere. Support poete are not each

- Improper deck piers. Support posts are not secured to piers, support posts have direct contact with soil.
 Missing beliefer in the
- Missing baluster, install new one.
- Deck stair railings are loose and are not graspable.









12. Foundation Conditions

Type: Basement.
Observations:
• Block foundation, with water proofing noted were visible.

13. Electric Meter Condition

Location: Rear of house.







14. Gas Meter Condition

Inspect Not None ed Inspect ed

Location: Rear of house.

□ □ □ Observations:

· Main fuel shutoff was located at the meter.

· Should have bush trimmed back from meter to allow access



15. Exterior Faucets

Inspect Not None ed Inspect ed

, ed

Materials: Front of house. • Rear of house. • Left side of house. • Right Side of house. Materials: Hose Bib.

Observations:


- Recommend installation of screw-on anti-siphon valve to prevent backflow of water.
- Recommend installing frost covers on all hose bibs for winter to prevent freezing.
- · Winterized, unable to test.

16. Electrical Conditions

Inspect Not None ed Inspect ed

Observations:

- Security lights on all 4 corners of house. Not tested due to photo cell activated.
- Extension cord running to pond. Cords are not to be buried.
- Recommend moving security light away from roof to avoid fire when bulb is installed.
- All outside outlets need to be GFCI protected. 2 front porch outlets and one rear out need to be GFCI protected.



Missing bulb, recommend moving fixture so bulb will not over hang roof and possibly cause a fire.

Missing bulb



17. Door Bell Condition

Inspect Not None ed Inspect ed

Location: Front of house. • Rear of house.

¬ Observations:

• The doorbell is damaged at the rear of the house.

18. Driveway Condition

Inspect Not None ed Inspect ed

Materials: Asphalt.

Observations:

Common cracks noted.

• Evidence of ponding observed.



19. Walkway Conditions

Inspect Not None ed Inspect ed

Materials: Concrete. • Stone.

Observations:

• Common cracks and heaved/settled areas observed.

• Possible trip hazard. This is a safety concern. Suggest repair/replacement as needed to ensure safety.



20. Stairs/ Railings

Materials: Brick Materials: Vinyl





21. Fence Condition

Not Inspect ed

Materials: Chain Link.

Observations:

• Peeling paint observed, suggest scraping and painting as necessary.

22. Lot Grade and Drainage Conditions

Inspect Not None ed Inspect ed

Observations:

- Moderate Slope
- While performance of lot drainage and water handling systems may appear serviceable at the time of inspection, the inspector CANNOT always accurately predict this performance as conditions constantly change. Furthermore, items such as leakage in downspout/gutter systems are very difficult to detect during dry weather. Inspection of foundation performance and water handling systems, therefore, is limited to visible conditions and evidence of past problems. Buyer is advised to refer to Disclosure Statement for further information about drainage failure.
- Area under deck is pitched word house and forms a pool along the foundation. Area should be re-graded to slope away from house. Recommend 6" drop in 10 feet.



23. Retaining Wall Conditions

Inspect Not None ed Inspect ed

Materials: Block. Observations:

 $\overline{\chi}$

• Appeared serviceable at time of inspection. Structural assembly inaccessible.





24. General Exterior Comments

ed	Inspect ed	140110
X		

Observations:

- An effective water management program is required for all homes. This includes maintenance of all wooden components, caulking of all openings and ongoing vigilance of water handling systems, roof and flashing. Buyer is advised that while there may not be evidence of water intrusion into structure at time of inspection, NO STATEMENT referring to future performance can be made due to changing weather and structure conditions.
- Barn/shed/outbuilding observed but not inspected.

Garage

1.	Garage	Type
		Ty

Type: Two car drive under.

2. Garage Roof Condition

Inspect Not None Inspect ed

Materials: Same roofing material as attached house.

X

3. Gutter/ Downspout Conditions

Inspect Not No

Materials: Same gutter system as attached house.

X

4. Wall Cladding

nspect Not N ed Inspect ed

Materials: Same as attached house.

X

5. Garage Floor Condition

Inspect Not Noned Inspect ed

Materials: Concrete.

Observations:

Common cracks noted.

• Dry at the time of the inspection.

6. Garage Door Condition

Inspect Not None ed Inspect ed

X

Materials: Metal, Insulated 8' doors. • Roll-up Panel.

Observations:

• Bottom weatherstrip is deteriorated, recommend review for repair or replacement, as necessary.



7. Garage Door Hardware Condition

Inspect Not No ed Inspect ed

Observations:

Door hardware is operable.

8. Door Openers
Materials: Chain drive. Materials: Overhead Door Observations: Door opener is operable.
9. Garage Window Conditions
Inspect Not None ed Inspect ed X
10. Exterior Man Door Condition
Inspect Not None ed Inspect ed X
11. Fire Door Conditions
Materials: Metal/Metal Clad. Observations: No self closer. Recommend installation of self closer to protect against fume entry.
12. Firewalls
Inspect Not None ed Inspect ed Inspect of the Inspe
13. Garage Wall Condition
Inspect Not None ed Inspect Materials: Block.
Observations: Painted block.
14. Garage Ceiling Condition
Inspect Not None ed Materials: Drywall.

1	5	Garage	Electrical	Condition
ш	J.	Garage	Licultai	COHUME

Inspect ed	Not Inspect ed	None
X		

16. Garage Comments Inspect Not Inspect Observation

cu	 ed		
Х			

Observations:
• Garage was inspected and is operational.

Basement
1. Basement observations
Inspect Inspect Not Inspect None ed Inspect No
2. Basement Access
Basement stairway inside house.
3. Basement Stairs Condition
Inspect Not None ed Inspect ed X None Ed N
4. Foundation Walls Condition
Materials: Block. Observations: • Efflorescence observed; this is a mineral deposit left behind from exterior water infiltration. • Active leaks observed at the time of inspection. This area is directly inside of the poor grading under the deck.
5. Basement Floor Condition
Materials: Concrete. • Carpet. Not ed Inspect None ed
6. Joist Condition
Materials: Conventional 2 x 10 Framing. • Steel I Beam.

7. Support Post Comments
Inspect Not None ed Inspect Materials: Metal.
Observations:
Posts are finished or concealed, unable to inspect.
8. Beams Condition
Inspect Not None ed Inspect ed In
X C
9. Subfloor Condition
Inspect Not None ed Inspect ed ed
10. Basement Ceilings Condition
Inspect Not None ed Inspect Set Office Offic
Observations: • Acoustic tiles are all yellowed.
Acoustic tiles are all yellowed.
11. Exterior Doors Condition
Inspect Not None ed Inspect Materials: Metal.
X D
12. Window Condition
Inspect Not None ed Inspect ed ed
13. Electrical Conditions
Inspect Not None ed Inspect Observations:
• All electric above drop ceiling, limited access.
14. Visible Plumbing Condition
Materials: Copper.
15. Insulation Condition
Inspect Not None Materials: Fiberglass.
Observations: • Insulation is in floor joists. Basement is not heated.
16. Distribution/Ducts Inspect Not None
ed Inspect Ducts
Observations:

	_	_
17	Cum	a Diima
1/.	Sulli	o Pump

Inspect Not None ed Inspect ed

X

18. Basement Comments

Inspect Not None ed Inspect ed

X

Attic

1. Access

Not None Inspect ed

Materials: Drop down stair case. Observations:
• No insulation on attic access.



2. Methods Used to Inspect

How Inspected: Entered attic and inspected.

3. Framing Condition

Inspect Not ed Inspect ed

Style: Truss.



4. Sheathing Condition

Not Inspect ed

Materials: Plywood. Observations:

• Mild staining at nail penetrations noted.

5. Insulation Condition
Inspect Not Inspec
Observations: • 4-6" of insulation present.
7 4-0 of institution present.
6. Ventilation Conditions
Inspect Not Inspect of Style: Attic Fan. • Gable Vents. • Ridge Vents.
Observations: • Attic fan appears to be controlled by a thermostat; no operational test was
performed. Suggest verification of performance prior to closing.
7. Window Conditions
Inspect Not None ed Inspect
ed ed
8. Electrical Conditions
Inspect Not None ed Inspect Observations:
• Open junction boxes were observed, which is a safety concern. Recommend
installing proper covers, as needed, for safety.
9. Distribution/Ducting Conditions
Inspect Not None ed Inspect ed ed
10. Evidence of leaking
Inspect Not None Observations:
• Dry at the time of the inspection.

11. Attic Comments

Inspect ed	Not Inspect ed	None
Х		

Observations:

- Attic should be reviewed at least twice per year to ensure ventilation openings are clear and to ensure development of mould is kept in check. While there may be very little or no evidence of mould build-up in the attic at time of inspection, it can reproduce and spread rapidly should conditions allow it to. Mould can be potentially hazardous and will spread when moisture enters the attic cavity and is not vented to the exterior. Any area of suspected mould should be reviewed by a qualified contractor for analysis and removal.
- bathroom vent fans are improperly venting into attic. Recommend extending fan exhaust to the exterior to prevent damage and/or deterioration from moisture and/or condensation.

Plumbing

1. Water Source

Materials: City water.

2. Main Shutoff Location

Inspect Not None ed Inspect ed

X

Materials: Brass ball valve

Observations:

· Basement, left side of house.



3. Water pressure

Inspect Not Inspect ed

Observations:

Water Pressure was 62 PSI

4. Water Flow Volume

Inspect Not None ed Inspect ed

Observations:

• Functional water flow with 2 devices open.

5. Supply Line Condition

Inspect Not ed Inspect ed

None

Materials: Pex

Observations:

No leaks observed at the time of the inspection.

Limited inspection, main waterline below ground.

6. Waste Line Conditions

Inspect Not None ed Inspect ed

Materials: Septic System.

Observations:

• Septic tanks, leach tanks and other private sewage systems are outside the scope of this report and are not inspected. We recommend review by a qualified professional to assess the functionality and condition of the system, prior to close.

• Septic tanks and leach lines are buried and are not visible to the inspector. Should you desire a more thorough inspection of all septic components, further review by a licensed septic contractor is recommended prior to closing to ensure the system is functioning properly.

7. Waste Line Condition
Materials: PVC. Observations: Tested by running water, no leaks apparent at time of inspection. Limited visibility, some lines viewable above drop ceiling in basement.
8. Ejector Pump Conditions
Inspect Not None ed Inspect
9. Venting Conditions
Observations: Noted vent stack in attic, through roof. All other vents are not visible.
10. Plumbing Comments
Comments: • All plumbing components tested well at time of inspection unless otherwise noted.

Water Heater

1. Brand

Materials: Bradford white

2. Water heater

Inspect Not None ed Inspect ed

Materials: Tank.

Materials: Natural Gas.

Observations:

· Water heater is located outside on back of house in a stainless steel enclosure









3. Supply lines Condition

Inspect Not None ed Inspect ed

Materials: PEX. Observations:

X

- There is a shut off valve on the hot water side. This is not allowed. Must be removed.
- Hot/cold water lines are reversed, this condition will cause the water heater to function improperly. Corrections are needed by a licensed plumbing contractor.

4. TPR	
Inspect Not None ed Inspect ed	Materials: IPR valve is noted. Observations: • Unable to access TPR valve due to location. • There is no discharge line pipe installed. Must have TPR dishcharge pipe.
5. Combusti	on Chamber Conditions
Inspect Not None ed Inspect ed X	Observations: • Inaccessible
6. Flue Vent	ing Conditions
6. Flue Vent Inspect None ed Inspect ed	ing Conditions Materials: Metal.
Inspect Not None ed Inspect ed	•

Electrical

1. Service Comments
Materials: Main Service Drop is underground. Materials: 240 volt.
2. Main Electrical Panel
Materials: Breakers. • Service Entrance cables are aluminium. Materials: Basement. Observations: • Panel cover removal is restricted due to soffit framing
3. Main Panel Comments
Observations: Main disconnects are present. Main Circuit breaker amp rating 200 amp
4. Sub Panel
Inspect ed Inspect ed None ed No
5. Branch circuit wiring
Inspect Not Inspect ed Inspect ed Materials: Copper. Materials: Copper.
6. Grounding
Inspect Not Inspect ed Inspect ed Materials: Ground stake. Materials: Ground stake.

	_		
7	Smaka	detector	comments

Inspect Not Inspect In

8. Electrical Comments

Inspect Not None ed Inspect ed

Heating

1. Heating Type

Materials: Gas Forced Air.

Materials: Heil

2. Btu/ HR rating

Materials: Outside

3. Operating Comments

Inspect Not ed Inspect ed

Observations:

Temperature at Register...112 degreesTemperature at cold air return...71 degrees





Gas shut off for furnace.

4. Burner Chamber Comments

Observations:

Closed System, not visible

5. Exhaust Venting Conditions

Not Inspect ed

Materials: Metal. Observations:

· Vents directly to open air



6 Humidifier Comments

o. Hamidilei Comments						
Observations: No humidifier installed						
7. Air Filter Condition						
Observations:						
8. Thermostat Condition						
Programmable thermostat. • Located in hallway.						
9. Distribution Ducting Condition						
Type: Ducts and Registers. • Most ducting is inaccessible, above drop ceiling in basement.						
10. Other Heat Source						
Inspect Not None ed Inspect ed ed						
11. Heating Comments						
Observations: Garage has electric space heater mounted to ceiling.						

Fireplace

1. Fireplace Location

Location: The fireplace is located in the Family Room. • The fireplace is located in the Basement Family Room. • Fireplace damper is operational.

2. Fireplace Style

Style: Masonry

3. Fireplace Comments

Inspect Not ed Inspect ed

Observations:

X

• Recommend further review and cleaning by a qualified professional prior to use.





Air Conditioning

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Air Conditioning Comments							
Inspect Not None ed laspect No							
2. Brand Name							
Materials: Heil							
3. Compressor							
Materials: Outside, back of house. Materials: Clean and visible good							
4. Operating Comments							
Inspect Not None ed Inspect ed							
5. Other Cooling							

6. Comments

Materials: Air conditioning could not be inspected due to outside temperature. Activating air conditioning during cool/cold weather can cause serious damage to the system. Buyer is advised to verify satisfactory operation prior to close.

Laundry Area

1. Laundry Area Location

Location: Main Floor.

2	00	
/	\mathbf{o}	118

Inspect

Materials: Sheet Vinyl.

Observations:

• Minor damage noted.



Inspect Not None ed Inspect ed

Materials: Drywall/Plaster.

4. Ceiling Condition

Inspect Not ed Inspect ed

Materials: Drywall/Plaster.

5. Door Condition

Not Inspect ed

Materials: Bi-fold. • Hollow Core.

6. Window Condition

Not Inspect ed



7. Cabinet Condition

Inspect Not None ed Inspect ed



8. Laundry Tub/Sink Condition
Inspect Not None ed Inspect ed ed
9. Laundry Faucets
Inspect Not None ed Inspect ed ed
10. Electrical Conditions
Inspect Not None Observations:
• GFCI needs to be installed
11. Washer Hook-ups
Inspect Not None od Inspect ed In
• Washer hook ups observed. We do not disconnect the supply hoses to the washer, nor do we operate the valves. These can leak at any time and should be considered
a part of normal maintenance.
12. Dryer Hook-ups
Inspect Not None Observations:
x Gas
13. Exhaust Fan Condition
Inspect Not None ed Inspect
éd The Control of the
14. Laundry Comments
Inspect Not None ed Inspect ed ed
X D
15 Weeher/ Druge Comments

15. Washer/ Dryer Comments

Materials: Beyond scope of inspection. • Operational at time of inspection.

Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

stove, dishwasher, sink and other appliances.
1. Kitchen Floor Condition
Inspect Not Inspect lospect ed Materials: Wood. X
2. Kitchen Walls Condition
Inspect Not Inspect None ed In
3. Ceiling Conditions
Inspect Inspect Inspect ed Inspec
4. Kitchen Doors Condition
Inspect Inspect of the sed of the
5. Kitchen Windows Condition
Style: Screens are noted. • Double Hung. Observations: • Some spots between glass of thermopanes.

6. Kitchen Cabinet Condition

ed	Ins	spect ed	140110	Observations:					
	Г			Cabinets are in	good condition,	some minor	scratches a	nd blemishes no	ted.
X									

7. Kitchen Counter Top Condition
Observations: Granite counters
8. Kitchen Sink Condition
Inspect Not Inspect None ed In
9. Kitchen Faucets
Inspect Not None ed Inspect ed ed
X
10. Traps/Drains/Supply Condition Inspect Not None ed Inspect
× ed
11. Kitchen Electrical Condition
Inspect Not None ed Inspect of GFCI in place Observations:
12. Stove Cooktop Conditions
Inspect Not naspect None ed Style: Electric.



Frigidaire

40 /	~	<u></u>	1:1:
1.5 (Jven	Conc	litions

Inspect Not Inspect ed Inspect ed Style: Electric.

14. Garbage Disposal

Inspect Not None ed Inspect ed

15. Dishwasher Condition

Observations:

Observations:

Operated a rinse cycle, operated as should, no apparent leaks.



16. Hood Fan Condition

Inspect Inspect ed Inspect ed Observations:

**None ed Observations:*

Operational.

17. Microwave

X

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

Master Bedroom

4	-	_		\sim			:4:	_	
1	П	O	or	C	or	าต	IITI	О	n

Not Inspect ed Inspect ed

Observations:

Carpet shows wear as expected for age of home.

2. Wall Condition

Not Inspect ed







3. Ceiling Conditions

Inspect Not ed Inspect ed

Γ	
П	V
н	\sim 1



4. Door Conditions

Not Inspect ed






5. Window Condition

Not Inspect ed





Spots inside glass.

6. Electrical Conditions

Inspect Not ed Inspect ed

Observations:



• Ceiling fan noted. Fan is operational at time of inspection.

• AFCI Outlets not present

Master Bathroom

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring.

1. Bathroom Location

Location: Main Floor. • Ensuite to Master bedroom.

Inspect ed	Not Inspect ed	None	Materials: Ceramic Tile
X			

6. Bathroom Windows Condition

Style: Screens noted. • Double Hung.



3. Bathroom Wall Condition
Inspect Not None ed Inspect Materials: Drywall/Plaster.
4. Bathroom Ceiling Condition
Inspect Not None ed Inspect ed
5. Bathroom Doors Condition
Inspect Not None ed Inspect Not None ed Inspect Not None Materials: Bi-fold. • Hollow Core.

7. Electrical Condition
Inspect Not Inspect of
8. Heat Source Condition
Inspect Not None ed Inspect No
9. Bathroom Exhaust Fan Condition
Observations: Exhaust fan is operational
10. Tub/Whirlpool Condition
Inspect Not None ed Inspect ed Variable Variable
11. Tub Surround Condition
Inspect Not None ed Inspect ed X
12. Tub Doors Condition
Inspect None ed Inspect ed X
13. Tub Faucet Condition
Inspect Not None ed Inspect ed Value Va
14. Shower Base Condition
Inspect Not None ed Inspect None ed Materials: Fiberglass.
15. Shower Surround Condition
Inspect Not Inspect None ed In
16. Shower Door Condition
Inspect Not Inspect of

17. Shower Faucet Condition
Inspect Not None ed Inspect ed
X
18. Sink Condition
Inspect Not None ed Inspect Materials: China. 2 sinks
19. Sink Faucet Condition
Inspect Not None ed Inspect ed
20. Traps/Drains/Supply Condition
Inspect Not None ed Inspect ed
21. Toilet Condition
Inspect Not None ed Inspect ed
22. Counters/Cabinets Condition
Inspect Not None ed Inspect ed

Bedroom 1

1. Floor Condition
Observations: Carpet shows wear as expected for age of home.
2. Wall Condition
Inspect Not None ed Inspect ed
3. Ceiling Conditions
Inspect Not None ed Inspect ed ed
x S
4. Door Conditions
Inspect None ed Inspect ed e
5. Window Condition
Inspect Not None ed Inspect Observations:
 Screens noted. Spots inside glass.
6. Electrical Conditions
Inspect Not None Observations:
 Ceiling fan noted. Fan is operational at time of inspection. AFCI Outlets not present.

6. Electrical Conditions

Inspect	Not	None
ėd	Inspect	
	ed	

Observations:
• Ceiling fan noted. Fan is operational at time of inspection.

Bedroom 3

1. Floor Condition
Observations: Carpet shows wear as expected for age of home.
2. Wall Condition
Inspect Not None ed Inspect
X ed
3. Ceiling Conditions
Inspect Not None ed Inspect
X ed
4. Door Conditions
Inspect Not None ed Inspect ed ed
X
5. Window Condition
Inspect Not None Observations:
Screens noted. Spots inside glass.
6. Electrical Conditions
Observations: Ceiling fan noted. Fan is operational at time of inspection. Open ground on 2 outlets. AFCI Outlets not present.

Bathroom 2

1. Bathroom Location
Location: Main Floor.
2. Bath Floor Conditions
Inspect Not Inspect ed
3. Bathroom Wall Condition
Inspect Not Inspect None ed In
4. Bathroom Ceiling Condition
Inspect Not Inspect ed
5. Bathroom Doors Condition
Inspect Not None ed Inspect ed Unspect ed Un
6. Bathroom Windows Condition
Inspect Not None ed Inspect ed None N
7. Electrical Condition
Observations: GFCI in place and operational
8. Heat Source Condition
Inspect Not None ed Inspect ed None ed None None
9. Bathroom Exhaust Fan Condition
Observations: Exhaust fan is operable.
10. Tub/Whirlpool Condition
Inspect Not Inspect ed

11. Tub Surround Condition
Materials: Fiberglass Observations: Broken hand grip.
12. Tub Doors Condition
Inspect Not None ed Inspect ed X
13. Tub Faucet Condition
Inspect Not Inspect of
14. Shower Base Condition
Inspect Not None ed Inspect ed X
15. Shower Surround Condition
Inspect Not None ed Inspect ed X
16. Shower Door Condition
Inspect Not None ed Inspect ed X
17. Shower Faucet Condition

18. Sink Condition
Inspect Not None ed Inspect Materials: China.
19. Sink Faucet Condition
Inspect Not None ed Inspect ed
20. Traps/Drains/Supply Condition
Inspect Not None ed Inspect ed
21. Toilet Condition
Inspect Not None ed Inspect ed
22. Counters/Cabinets Condition
Inspect Not None ed Inspect ed

Bathroom 3
1. Bathroom Location
Location: Basement.
2. Bath Floor Conditions
Inspect Not None ed Inspect ed Materials: Vinyl Tile.
3. Bathroom Wall Condition
Inspect Not None ed Inspect Materials: Drywall/Plaster.
4. Bathroom Ceiling Condition
Materials: Drop Tile. Observations: Drop ceiling has water stain
5. Bathroom Doors Condition
Inspect Not None ed Inspect None ed Inspect Not Not Not Not Not Not Not Not Not No
6. Bathroom Windows Condition
Inspect Not None ed Inspect ed X
7. Electrical Condition
Observations: GFCI in place and operational

8. Heat Source Condition
Inspect Not None ed Inspect ed
9. Bathroom Exhaust Fan Condition Inspect Not None
ed Inspect
10. Tub/Whirlpool Condition
Inspect Not None ed Inspected
11. Tub Surround Condition
Inspect Not None ed Inspect ed e
12. Tub Doors Condition
Inspect Not None ed Inspect ed o
13. Tub Faucet Condition
Inspect Not None ed Inspected
14. Shower Base Condition
Inspect Note None Materials: Fiberglass.
45. Chausan Cumanund Candition
15. Shower Surround Condition Inspect Not None Materials: Fiberglass.
16. Shower Door Condition
Inspect Not None ed Inspect ed
17. Shower Faucet Condition
Inspect Not None ed Inspect Observations:
• Unable to test. Items stored in shower

18. Sink Condition
Inspect Not None ed Inspect Materials: China.
19. Sink Faucet Condition
Inspect Not None ed Inspect ed
X O
20. Traps/Drains/Supply Condition
Inspect Not None ed Inspect ed
X O
21. Toilet Condition
Inspect Not None ed Inspect ed
22. Counters/Cabinets Condition
Inspect Not None ed Inspect ed ed

Other Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Floor Condition
Inspect None ed Inspect ed ed
X S
2. Wall Condition
Inspect Not None ed Inspect ed ed
3. Ceiling Conditions
Inspect Not None ed Inspect
X ed
4. Door Conditions
Inspect Not None ed Inspect ed ed
5. Window Condition
Inspect Not None ed Inspect Observations:
• Screens noted.
6. Electrical Conditions
Inspect Not None ed Inspect ed ed
7. Wet Bar Conditions
Inspect Not None ed Inspect eded
8. Stair Conditions
Inspect Not None ed Inspect Observations:
• Basement door opens over stairs, should have a 3'x3' landing.

Jeff's Home Inspections, LLC.	, SC
9. Stair Railings	
Inspect Not Inspect Inspect ed Inspect ed Inspect Nood. Materials: Wood.	
10. Other Interior Area Comments	
Inspect Not None ed Inspect ed	
X	

Glossary

Term	Definition
AFCI	Arc-fault circuit interrupter: A device intended to provide protection from the effects of arc faults by recognizing characteristics unique to arcing and by functioning to de-energize the circuit when an arc fault is detected.
Drip Edge	Drip edge is a metal flashing applied to the edges of a roof deck before the roofing material is applied. The metal may be galvanized steel, aluminum (painted or not), copper and possibly others.
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.
PVC	Polyvinyl chloride, which is used in the manufacture of white plastic pipe typically used for water supply lines.
TPR Valve	The thermostat in a water heater shuts off the heating source when the set temperature is reached. If the thermostat fails, the water heater could have a continuous rise in temperature and pressure (from expansion of the water). The temperature and pressure could continue to rise until the pressure exceeds the pressure capacity of the tank (300 psi). If this should happen, the super-heated water would boil and expand with explosive force, and the tank would burst. The super-heated water turns to steam and turns the water heater into an unguided missile. To prevent these catastrophic failures, water heaters are required to be protected for both excess temperature and pressure. Usually, the means of protection is a combination temperature- and pressure-relief valve (variously abbreviated as T&P, TPV, TPR, etc.). Most of these devices are set to operate at a water temperature above 200° F and/or a pressure above 150 psi. Do not attempt to test the TPR valve yourself! Most water heating systems should be serviced once a year as a part of an annual preventive maintenance inspection by a professional heating and cooling contractor. From Plumbing: Water Heater TPR Valves