

LCA ROADWAY DAMAGE ASSESSMENT

Rev: 12/04/2020 jt

AREA 1

Street	Pole #/Street	Quan	Description
Kupono	3-4 to 8-9 3	1	Repave entire stretch 1,000 Ft Single narrow crack
Moku	1 to 6-7 9	4	Repave entire stretch 1,100' Single narrow cracks
Malama	38-41 Near Kupono	Several 4	Repave cracks, offsets, separations 650' Single narrow cracks
S. Nohea	4.5-5.5 3-4	3 4	Single narrow cracks Deformations on E. side

Repair Notes:

1. Single narrow cracks to require hot tar patch
2. Large cracks require existing pavement cut-back, bed compaction, and pavement restored
3. Vertical offset cracks will require existing pavement cut-back sufficient to restore grade, restore bed, and repave
4. Moku & Kupono and areas of Malama will require pavement cut-back, bed restoration, and complete repaving
5. Roadway paving to be 20' wide plus 5' wide gravel/cinder shoulders

Repairs include:

Patching 9 single narrow cracks

Repaving 1,750 feet of roadway