

///safe.lone.working

ATV / SbS operators are often required to work alone in remote locations. In the event of an incident or accident, timely help and assistance can literally be the difference between life and death. Identifying and explaining your exact location can be extremely difficult and in many cases almost impossible.

Consider the following safety precautions when working alone.

- Always wear the appropriate PPE
- Avoid wearing loose fitting clothing which could get caught in machinery
- Plan the ride and ride the plan.
 - Let others know your plan and timings.
 - Agree periodic checkins with family / colleagues
- Carry a means of communication - upper chest/ jacket pocket
- Consider monitoring systems / Apps
- Utilise what3words to pin point your location
- Carry emergency 1st aid kit

