
Mount Shasta Pickleball courts

Mount Shasta Resort

Overview

This project consisted of resurfacing four pickleball courts at Mount Shasta Resort. Services included crack repair, surface preparation, and a complete color refresh. The courts were updated from dark blue to light blue kitchen areas, creating a brighter and more modern appearance. The completed work restored the court surfaces, improved overall aesthetics, and extended the service life of the playing areas.

Before



Jun 8, 2026, 8:45 AM

Patching Cracks


Cracks were ground out, patched and buffed smooth.




Jun 10, 2026, 1:18 PM

Directional coating cracks.


After buffing smooth cracks were coated with acrylic for a smoother finish. After drying it was buffed smooth.



Jun 10, 2026, 3:37 PM




Jun 10, 2026, 3:37 PM



Jun 10, 2026, 3:37 PM

First coat of green.


Our crew put down a coat of green over the entire surface to give the best result.




Jun 11, 2026, 10:39 AM

Putting down playing areas.

After the green was put down, crews moved to playing areas where dark green with light blue kitchens was applied.




Jun 12, 2026, 3:54 PM




Jun 12, 2026, 3:54 PM

Finished product.


After all color was down it was time to stripe. Once that was done the result spoke for itself.




Jun 13, 2026, 2:45 PM




Jun 13, 2026, 2:43 PM




Jun 13, 2026, 2:43 PM



Jun 13, 2026, 2:38 PM



Jun 13, 2026, 2:38 PM



Jun 13, 2026, 2:38 PM