

Notes:

Relief angle should be round the whole bevel length

50° For plater faces, shallow bowl & square platers

55° For most bowl sizes

60° For deeper bowls - 65° to 70° is the highest working angles and only suitable for very deep narrow bowls