

MAINTENANCE GUIDELINES FOR SOLID PHENOLIC

WARNING:

- AVOID using cleaners that contain Sulfuric, Nitric, Oxalic, Muriatic
 or Hydrochloric acid. Such cleaners will cause discoloration and
 corrosion to all metals. When used in an enclosed area such as
 a public restroom, the fumes can cause corrosion and
 discoloration even if the acid is not in direct contact with the
 metal.
- AVOID using bleaches, sodium hydroxide, and sodium hypochlorite.

MAINTENANCE:

CLEAN BY WIPING WITH NON-ABRASIVE DETERGENT AND DAMP CLOTH OR SPONGE. DIFFICULT STAINS CAN BE REMOVED USING A MILD SOAP AND DETERGENT AND A SOFT-BRISTLED BRUSH.

DIFFICULT STAINS THAT RESIST ANY OF THE ABOVE CLEANING METHODS MAY REQUIRE THE USE OF LACQUER THINNER. DISCONTINUE APPLYING THINNER IF THE STAIN PERSISTS AND IF COLOR OF THE LAMINATE HAS BEEN ALTERED. EXTENDED CONTACT OF THE LAMINATE TO THE THINNER MAY CAUSE DISCOLORATION.