


VW3391 Camshaft Alignment Tool

Used to hold both camshafts at TDC position when replacing timing belt on Audi models with V-6 engine (5 valves per cylinder and 2.7 bi-turbo).



VW3243 Camshaft Alignment Tool

Used to hold both camshafts at TDC position when replacing timing belt. Used in conjunction with VW3242 on Audi models with V-6 engine (2 valves per cylinder)



T10252 Camshaft Locking Tool

For 2006-2008 VW-Audi 2.0L Turbo Engines (BPY). Used in conjunction with Vw5220, T10115 and H2587-2



T40001 VW-Audi Camshaft Drive Belt Pulley Puller Kit

Extractor for the camshaft phasing gear with 5 and 6 spokes. Pulling arms 17 and 23 mm. This cam sprocket puller is the 3rd essential tool required when replacing the timing belt in the Audi V6 and V8 engines. Applicable: 1992-1994 Audi 100s with the 12 valve AFC or AAH V6 engine, 1995-1997 Audi A6 12 valve AAH V6 engine, and similar engines used in A4s, A8s during the 1990's and later



T40046 Camshaft Alignment Tool (4.2L)

For locking camshafts when checking valve timing on Audi A6, A8, 4.2L engines. Engine model: V8 BAT 4.2



T40005 Camshaft Alignment Tool

Used to hold both camshafts at TDC position when replacing timing belt on Audi models with 40 valve, V8 motors (5 valve per cylinder). Used in conjunction with W3242



T40030 Cam Holding Alignment Fixture

Used to align and hold camshaft on Audi 3.0L V6 5-valve. Used in conjunction with T40011, T40026, T40028





TTS1471 / T40133 Audi Camshaft Clamp

For securing camshafts when adjusting timing on 2009+ A6 with 3.0L Supercharged V6 4v (CCAA) Q5 3.2L V6 4v (CALB), A5 3.2L V6 4v (CALA)



T40047 Engine Timing Tool Set (4.2L)

For installing Hall sender screens into crankshaft adjuster when setting the crankshaft timing on Audi A6, A8, 4.2 L (V8 BAT 4.2)



T40028 Camshaft Adjustment Socket



T40070 Cam Lock Clamp Pair

for VW-Audi Fits audi 3.2 L V6 (BKH) 4.2 L V8 (4v) (BAR, BNS, BVJ, BYH and CAUA) 5.2 L V10 (4v) (BXA AND BSM) VW2.5 L 5 cylinder Fits 2005 and newer vw/audi models with motors listed above

