

Vermillion Township  
Spring Road Tour Meeting Minutes  
May 7, 2022

Attendance:

Supervisor Chairman Larry Ring  
Supervisor Audrey Felty

Additional Attendance:

Resident James Sathra

Observations:

1. Dubarry Trail – Extra gravel needed at the intersection of Dubarry Trail & 210<sup>th</sup> Street.
2. 170<sup>th</sup> Street – Concrete culvert located half mile east of Goodwin Avenue needs repair. The Road & Bridge Contractor will look into this and give the board suggestions.  
180<sup>th</sup> Street – Guardrail on northeast side of bridge a quarter mile west of Goodwin Avenue needs repair. The Road & Bridge Contractor will look into this and give the board suggestions.
3. Hogan Avenue – Improved drainage and erosion control is needed a half mile north of 220<sup>th</sup> Street. The Road & Bridge Contractor will look into this and give the board suggestions.

Cynthia Ladzun  
Vermillion Township Clerk